DEUTSCHE AIRCRAFT

Dornier 328-100

# PUBLICATION INDEX

The technical content of this document is approved
under the authority of the DOA ref. EASA.21J.438

**IM-PI-081093-ALL**

**Issue: Oct 08/93**
**Revised: May 30/23, Revision 348**

For the Copyright of Deutsche Aircraft GmbH refer to the back of this Title Page.

© Deutsche Aircraft GmbH 2006-2023

The information contained in this Publication Index in connection with Aircraft types Dornier 328-100 and Dornier 328-300 (collectively defined as “Dornier 328”) are Technical Documents and Data as defined in the Technical Data Agreement concluded separately between Deutsche Aircraft GmbH and the Customer. Therefore, any Technical Documents and Data contained in this Publication Index can only be used in accordance with the license provided in the Technical Data Agreement. Technical Documents and Data must be kept confidential and can only be disclosed as provided in the Technical Data Agreement.

Deutsche Aircraft GmbH - Technical Publications – Oberpfaffenhofen Airport, D-82234 Wessling, Germany, E-Mail: techpub@deutscheaircraft.com

## RECORD OF REVISIONS

| REV. NO. | ISSUE DATE | DATE INCORPORATED | INCORPORATED BY |
|---|---|---|---|
| 1 | Jan 21/94 | | |
| 2 | Apr 14/94 | | |
| 3 | May 30/94 | | |
| 4 | Jun 30/94 | | |
| 5 | Jul 29/94 | | |
| 6 | Aug 31/94 | | |
| 7 | Sep 30/94 | | |
| 8 | Oct 31/94 | | |
| 9 | Nov 30/94 | | |
| 10 | Dec 23/94 | | |
| 11 | Jan 31/95 | | |
| 12 | Feb 28/95 | | |
| 13 | Mar 31/95 | | |
| 14 | Apr 28/95 | | |
| 15 | May 31/95 | | |
| 16 | Jun 30/95 | | |
| 17 | Jul 31/95 | | |
| 18 | Sep 08/95 | | |
| 19 | Sep 29/95 | | |
| 20 | Oct 31/95 | | |
| 21 | Nov 27/95 | | |
| 22 | Dec 22/95 | | |
| 23 | Jan 31/96 | | |
| 24 | Feb 29/96 | | |
| 25 | Mar 28/96 | | |
| 26 | April 30/96 | | |
| 27 | May 29/96 | | |
| 28 | Jun 26/96 | | |
| 29 | Jul 30/96 | | |
| 30 | Aug 30/96 | | |
| 31 | Sep 30/96 | | |
| 32 | Oct 31/96 | | |
| 33 | Nov 29/96 | | |
| 34 | Dec 20/96 | | |
| 35 | Jan 31/97 | | |
| 36 | Feb 28/97 | | |
| 37 | Mar 27/97 | | |
| 38 | Apr 30/97 | | |
| 39 | May 30/97 | | |
| 40 | June 30/97 | | |
| 41 | Jul 31/97 | | |
| 42 | Aug 29/97 | | |
| 43 | Sep 30/97 | | |
| 44 | Oct 31/97 | | |
| 45 | Dec 31/97 | | |
| 46 | Jan 30/98 | | |

# RECORD OF REVISIONS

## RECORD OF REVISIONS

| REV. NO. | ISSUE DATE | DATE INCORPORATED | INCORPORATED BY |
|---|---|---|---|
| 47 | Feb 27/98 | | |
| 48 | Mar 31/98 | | |
| 49 | Apr 30/98 | | |
| 50 | May 29/98 | | |
| 51 | Jun 30/98 | | |
| 52 | Jul 31/98 | | |
| 53 | Aug 31/98 | | |
| 54 | Sep 30/98 | | |
| 55 | Oct 31/98 | | |
| 56 | Nov 30/98 | | |
| 57 | Dec 31/98 | | |
| 58 | Jan 29/99 | | |
| 59 | Feb 26/99 | | |
| 60 | Apr 30/99 | | |
| 61 | May 31/99 | | |
| 62 | Jun 30/99 | | |
| 63 | Jul 30/99 | | |
| 64 | Aug 30/99 | | |
| 65 | Sep 30/99 | | |
| 66 | Oct 29/99 | | |
| 67 | Nov 30/99 | | |
| 68 | Dec 30/99 | | |
| 69 | Jan 31/00 | | |
| 70 | Feb 15/00 | | |
| 71 | Mar 15/00 | | |
| 72 | Apr 28/00 | | |
| 73 | May 31/00 | | |
| 74 | Jun 30/00 | | |
| 75 | Jul 31/00 | | |
| 76 | Aug 31/00 | | |
| 77 | Sep 30/00 | | |
| 78 | Oct 31/00 | | |
| 79 | Nov 30/00 | | |
| 80 | Dec 31/00 | | |
| 81 | Jan 31/01 | | |
| 82 | Feb 28/01 | | |
| 83 | Mar 30/01 | | |
| 84 | Apr 30/01 | | |
| 85 | May 31/01 | | |
| 86 | Jun 30/01 | | |
| 87 | Jul 31/01 | | |
| 88 | Aug 31/01 | | |
| 89 | Sep 30/01 | | |
| 90 | Oct 31/01 | | |
| 91 | Nov 30/01 | | |
| 92 | Dec 31/01 | | |
| 93 | Jan 31/02 | | |

# RECORD OF REVISIONS

## RECORD OF REVISIONS

| REV. NO. | ISSUE DATE | DATE INCORPORATED | INCORPORATED BY |
|---|---|---|---|
| 94 | Feb 28/02 | | |
| 95 | Mar 31/02 | | |
| 96 | Apr 30/02 | | |
| 97 | May 31/02 | | |
| 98 | Jun 30/02 | | |
| 99 | Jul 30/02 | | |
| 100 | Aug 31/02 | | |
| 101 | Sep 30/02 | | |
| 102 | Oct 31/02 | | |
| 103 | Nov 30/02 | | |
| 104 | Dec 31/02 | | |
| 105 | Jan 31/03 | | |
| 106 | Feb 28/03 | | |
| 107 | Mar 31/03 | | |
| 108 | Apr 30/03 | | |
| 109 | May 28/03 | | |
| 110 | Jun 30/03 | | |
| 111 | Jul 31/03 | | |
| 112 | Aug 29/03 | | |
| 113 | Sep 30/03 | | |
| 114 | Oct 31/03 | | |
| 115 | Nov 28/03 | | |
| 116 | Dec 31/03 | | |
| 117 | Jan 31/04 | | |
| 118 | Feb 27/04 | | |
| 119 | Mar 29/04 | | |
| 120 | Apr 30/04 | | |
| 121 | May 31/04 | | |
| 122 | Jun 30/04 | | |
| 123 | Jul 31/04 | | |
| 124 | Aug 31/04 | | |
| 125 | Sep 30/04 | | |
| 126 | Oct 31/04 | | |
| 127 | Nov 30/04 | | |
| 128 | Dec 31/04 | | |
| 129 | Jan 31/05 | | |
| 130 | Feb 28/05 | | |
| 131 | Mar 31/05 | | |
| 132 | Apr 30/05 | | |
| 133 | May 31/05 | | |
| 134 | Jun 30/05 | | |
| 135 | Jul 31/05 | | |
| 136 | Aug 31/05 | | |
| 137 | Sep 30/05 | | |
| 138 | Oct 31/05 | | |
| 139 | Nov 30/05 | | |

# RECORD OF REVISIONS

## RECORD OF REVISIONS

| REV. NO. | ISSUE DATE | DATE INCORPORATED | INCORPORATED BY |
|---|---|---|---|
| 140 | Dec 31/05 | | |
| 141 | Jan 31/06 | | |
| 142 | Feb 28/06 | | |
| 143 | Mar 31/06 | | |
| 144 | Apr 30/06 | | |
| 145 | May 31/06 | | |
| 146 | Jun 30/06 | | |
| 147 | Jul 31/06 | | |
| 148 | Aug 31/06 | | |
| 149 | Sep 30/06 | | |
| 150 | Oct 31/06 | | |
| 151 | Nov 30/06 | | |
| 152 | Dec 31/06 | | |
| 153 | Jan 31/07 | | |
| 154 | Feb 28/07 | | |
| 155 | Mar 31/07 | | |
| 156 | Apr 30/07 | | |
| 157 | Jun 31/07 | | |
| 158 | Jul 31/07 | | |
| 159 | Aug 31/07 | | |
| 160 | Sep 30/07 | | |
| 161 | Oct 31/07 | | |
| 162 | Nov 30/07 | | |
| 163 | Dec 31/07 | | |
| 164 | Jan 31/08 | | |
| 165 | Feb 29/08 | | |
| 166 | Mar 31/08 | | |
| 167 | Apr 30/08 | | |
| 168 | May 31/08 | | |
| 169 | Jun 30/08 | | |
| 170 | Jul 31/08 | | |
| 171 | Aug 31/08 | | |
| 172 | Sep 30/08 | | |
| 173 | Oct 31/08 | | |
| 174 | Nov 30/08 | | |
| 175 | Dec 31/08 | | |
| 176 | Jan 31/09 | | |
| 177 | Feb 28/09 | | |
| 178 | Mar 31/09 | | |
| 179 | Apr 30/09 | | |
| 180 | May 31/09 | | |
| 181 | Jun 30/09 | | |
| 182 | Jul 31/09 | | |
| 183 | Aug 31/09 | | |
| 184 | Sep 30/09 | | |
| 185 | Oct 31/09 | | |
| 186 | Nov 30/09 | | |

# RECORD OF REVISIONS

## RECORD OF REVISIONS

| REV. NO. | ISSUE DATE | DATE INCORPORATED | INCORPORATED BY |
|---|---|---|---|
| 187 | Dec 31/09 | | |
| 188 | Jan 31/10 | | |
| 189 | Feb 28/10 | | |
| 190 | Mar 31/10 | | |
| 191 | Apr 30/10 | | |
| 192 | May 31/10 | | |
| 193 | Jun 30/10 | | |
| 194 | Jul 31/10 | | |
| 195 | Aug 31/10 | | |
| 196 | Sep 30/10 | | |
| 197 | Oct 31/10 | | |
| 198 | Nov 30/10 | | |
| 199 | Dec 31/10 | | |
| 200 | Jan 31/11 | | |
| 201 | Feb 28/11 | | |
| 202 | Mar 31/11 | | |
| 203 | Apr 30/11 | | |
| 204 | May 31/11 | | |
| 205 | Jun 30/11 | | |
| 206 | Jul 31/11 | | |
| 207 | Aug 31/11 | | |
| 208 | Sep 30/11 | | |
| 209 | Oct 31/11 | | |
| 210 | Nov 30/11 | | |
| 211 | Dec 31/11 | | |
| 212 | Jan 31/12 | | |
| 213 | Feb 29/12 | | |
| 214 | Mar 30/12 | | |
| 215 | Apr 30/12 | | |
| 216 | May 31/12 | | |
| 217 | Jun 29/12 | | |
| 218 | Jul 31/12 | | |
| 219 | Aug 31/12 | | |
| 220 | Sep 28/12 | | |
| 221 | Oct 31/12 | | |
| 222 | Nov 30/12 | | |
| 223 | Dec 31/12 | | |
| 224 | Jan 31/13 | | |
| 225 | Feb 28/13 | | |
| 226 | Mar 28/13 | | |
| 227 | Apr 30/13 | | |
| 228 | May 29/13 | | |
| 229 | Jun 28/13 | | |
| 230 | Jul 31/13 | | |
| 231 | Aug 29/13 | | |
| 232 | Sep 30/13 | | |

# RECORD OF REVISIONS

## RECORD OF REVISIONS

| REV. NO. | ISSUE DATE | DATE INCORPORATED | INCORPORATED BY |
|---|---|---|---|
| 233 | Oct 31/13 | | |
| 234 | Nov 29/13 | | |
| 235 | Dec 23/13 | | |
| 236 | Jan 31/14 | | |
| 237 | Feb 28/14 | | |
| 238 | Mar 31/14 | | |
| 239 | Apr 30/14 | | |
| 240 | May 28/14 | | |
| 241 | Jun 30/14 | | |
| 242 | Jul 31/14 | | |
| 243 | Aug 29/14 | | |
| 244 | Sep 30/14 | | |
| 245 | Oct 31/14 | | |
| 246 | Nov 28/14 | | |
| 247 | Dec 30/14 | | |
| 248 | Jan 30/15 | | |
| 249 | Feb 27/15 | | |
| 250 | Mar 27/15 | | |
| 251 | Apr 30/15 | | |
| 252 | May 29/15 | | |
| 253 | Jun 30/15 | | |
| 254 | Jul 31/15 | | |
| 255 | Aug 31/15 | | |
| 256 | Sep 30/15 | | |
| 257 | Oct 30/15 | | |
| 258 | Nov 30/15 | | |
| 259 | Dec 18/15 | | |
| 260 | Jan 29/16 | | |
| 261 | Feb 29/16 | | |
| 262 | Mar 31/16 | | |
| 263 | Apr 29/16 | | |
| 264 | May 31/16 | | |
| 265 | Jul 04/16 | | |
| 266 | Jul 29/16 | | |
| 267 | Aug 31/16 | | |
| 268 | Sep 30/16 | | |
| 269 | Oct 31/16 | | |
| 270 | Nov 30/16 | | |
| 271 | Dec 23/16 | | |
| 272 | Jan 31/17 | | |
| 273 | Feb 28/17 | | |
| 274 | Mar 30/17 | | |
| 275 | Apr 28/17 | | |
| 276 | May 31/17 | | |
| 277 | Jun 30/17 | | |
| 278 | Jul 31/17 | | |
| 279 | Aug 31/17 | | |

# RECORD OF REVISIONS

## RECORD OF REVISIONS

| REV. NO. | ISSUE DATE | DATE INCORPORATED | INCORPORATED BY |
|---|---|---|---|
| 280 | Sep 29/17 | | |
| 281 | Oct 27/17 | | |
| 282 | Nov 30/17 | | |
| 283 | Dec 22/17 | | |
| 284 | Jan 31/18 | | |
| 285 | Feb 28/18 | | |
| 286 | Mar 29/18 | | |
| 287 | Apr 30/18 | | |
| 288 | May 30/18 | | |
| 289 | Jun 29/18 | | |
| 290 | Jul 31/18 | | |
| 291 | Aug 30/18 | | |
| 292 | Sep 27/18 | | |
| 293 | Oct 31/18 | | |
| 294 | Nov 28/18 | | |
| 295 | Dec 21/18 | | |
| 296 | Jan 31/19 | | |
| 297 | Feb 28/19 | | |
| 298 | Mar 29/19 | | |
| 299 | Apr 30/19 | | |
| 300 | May 29/19 | | |
| 301 | Jun 28/19 | | |
| 302 | Jul 31/19 | | |
| 303 | Aug 30/19 | | |
| 304 | Sep 30/19 | | |
| 305 | Oct 31/19 | | |
| 306 | Nov 29/19 | | |
| 307 | Dec 19/19 | | |
| 308 | Jan 30/20 | | |
| 309 | Feb 28/20 | | |
| 310 | Mar 30/20 | | |
| 311 | Apr 30/20 | | |
| 312 | May 27/20 | | |
| 313 | Jun 29/20 | | |
| 314 | Jul 29/20 | | |
| 315 | Aug 31/20 | | |
| 316 | Sep 30/20 | | |
| 317 | Oct 29/20 | | |
| 318 | Nov 27/20 | | |
| 319 | Dec 18/20 | | |
| 320 | Jan 29/21 | | |
| 321 | Feb 26/21 | | |
| 322 | Mar 31/21 | | |
| 323 | Apr 29/21 | | |
| 324 | May 31/21 | | |
| 325 | Jun 30/21 | | |

# RECORD OF REVISIONS

## RECORD OF REVISIONS

| REV. NO. | ISSUE DATE | DATE INCORPORATED | INCORPORATED BY |
|---|---|---|---|
| 326 | Jul 27/21 | | |
| 327 | Aug 30/21 | | |
| 328 | Sep 30/21 | | |
| 329 | Oct 29/21 | | |
| 330 | Nov 29/21 | | |
| 331 | Dec 23/21 | | |
| 332 | Jan 28/22 | | |
| 333 | Feb 28/22 | | |
| 334 | Mar 31/22 | | |
| 335 | May 02/22 | | |
| 336 | May 31/22 | | |
| 337 | Jun 30/22 | | |
| 338 | Jul 29/22 | | |
| 339 | Aug 31/22 | | |
| 340 | Sep 30/22 | | |
| 341 | Oct 28/22 | | |
| 342 | Nov 30/22 | | |
| 343 | Dec 21/22 | | |
| 344 | Jan 31/23 | | |
| 345 | Feb 28/23 | | |
| 346 | Mar 31/23 | | |
| 347 | Apr 27/23 | | |
| 348 | May 30/23 | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

# RECORD OF REVISIONS

## LIST OF EFFECTIVE PAGES

| CAPTER/SECTION/SUBJECT | TOTAL PAGES | DATE | EFFECTIVITY |
|---|---|---|---|
| TITEL | 1 | May 30/23 | |
| RECORD OF REVISIONS | 8 | May 30/23 | |
| LIST OF EFFECTIVE PAGES | 2 | May 30/23 | |
| TABLE OF CONTENT | 2 | May 30/23 | |
| INTRODUCTION | 8 | Mar 03/23 | ALL |
| CHAPTER 1 – A/C MFR PUBLICATIONS | 45 | May 30/23 | ALL |
| CHAPTER 2 – VENDOR PUBLICATIONS | | | |
| CHAPTER 2 – Sort: Vendor alphabetical | 24 | May 30/23 | ALL |
| CHAPTER 2 – Sort: ATA–Chapter Code | 25 | May 30/23 | ALL |
| CHAPTER 2 – Sort: Part Number | 25 | May 30/23 | ALL |
| CHAPTER 3 – SERVICE PUBLICATIONS | 134 | May 30/23 | ALL |
| ANNEX A – Publication in Work | 1 | May 30/23 | ALL |

# LIST OF EFFECTIVE PAGES

## LIST OF EFFECTIVE PAGES

INTENTIONALLY LEFT BLANK

## TABLE OF CONTENTS


| SUBJECT | CHAPTER | PAGE |
|---|---|---|
| **TITLE** | | |
| **RECORD OF REVISIONS** | | 1 |
| **LIST OF EFFECTIVE PAGES** | | 1 |
| **TABLE OF CONTENTS** | | 1 |
| **INTRODUCTION** | | 1 |
| **A/C MFR PUBLICATIONS** | 1 | 1-45 |
| **VENDOR PUBLICATIONS – SORT: VENDOR ALPHABETICAL** | 2 | 1-24 |
| **VENDOR PUBLICATIONS – SORT: ATA–CHAPTER CODE** | 2 | 1-25 |
| **VENDOR PUBLICATIONS – SORT: PART NUMBER** | 2 | 1-25 |
| **SERVICE PUBLICATIONS** | 3 | 1-134 |
| **PUBLICATION IN WORK** | ANNEX A | 1 |


# TABLE OF CONTENTS

**TABLE OF CONTENTS**

INTENTIONALLY LEFT BLANK

# TABLE OF CONTENT

# INTRODUCTION

## 1. General

This PUBLICATIONS INDEX (PI) contains all documents available for the operation and maintenance of the Dornier 328 - 100 aircraft and its installed equipment.

The documents not delivered as either standard aircraft documentation or standard vendor documentation but required for trouble shooting, test, repair or maintenance can be ordered, through Deutsche Aircraft GmbH or through the concerning vendor, as necessary.

Certain documents are only available to those operators who have been certified to repair and/or overhaul by the individual vendor.

Documents currently in work are listed in ANNEX A.

The PI will be published monthly.

## 2. Validity of Documents

Make sure, to have the valid issue of the manual and all relevant TRs available before using the manual. This Publications Index shows the latest issue and the revision status of the documents issued by the aircraft manufacturer. Only those aircraft manufacturer manuals/documents are valid which have the same issue date/ revision date as given in the PI. Vendor manuals listed in the Publications Index is valid of this issue which is available at the concerning vendor support.

NOTE: If a manual/document is available with an issue date /revision date higher than the date given in the Publications Index, the higher issue date has priority. The reason for this difference can be that the Publications Index has a monthly update and therefore the gap between the delivery of documentation and the delivery of the updated PI can be up to one month. In this case please check the next issue of the PI.

Manuals and TRs in the A/C MFR PUBLICATIONS part of the Publications Index can have the following extensions of the document numbers:

| | |
|---|---|
| –**ALL** | These manuals are non–customized manuals and valid for all users |
| –**ENV** | These manuals or TRs are envelope issues |
| –**Customer ID** | These manuals or TRs are customized for a specific fleet, see 6. Customer Identification |
| –**Aircraft S/N** | These manuals or TRs are valid for a single aircraft serial number (e.g. 3095) |
| –**X** | These TRs have to be observed in addition to the envelope manuals and all customer manuals |

Example: The holder of the Aircraft Maintenance Manual TM–AMM–190793–ENV has to observe in addition to this manual all TRs with the extension –ENV and –X.

## INTRODUCTION

SB's, EO's, RO's, SI's, CI's, AOT's and AD's have the same extensions as manuals and TRs:

–**Customer ID** These service bulletins are customized for a specific fleet, see 5. Customer Identification
–**X** These service bulletins are valid for all customers

The document–number of these bulletins is shown in the column Doc.–Title.

The valid contents of a manual can be identified by comparison of the pages with the List of Effective Pages (LEP) which is a part of the front matter of each manual.
To introduce and register Temporary Revisions into a manual always follow the insertion instructions.

3. Chapter 1 Remarks

| | |
|---|---|
| –**CD-ROM** | These documents are distributed on CD-ROM |
| –**DISKETTE** | These documents are distributed on diskette |
| –**Edition: dd.mm.yyyy** | These "Edition" dates shows the date when the (PDF) document was changed by TechPub |
| –**MFR Overh. Only** | These documents are distributed to manufacturer approved overhaul facilities only |
| –**Outdated** | These documents are no longer valid and must not be used |
| –**S/N** | These documents are valid for the listed aircraft serial number |

4. Component Maintenance Manuals from Vendors

The Publications Index shows the latest issue and the revision status of the vendor documentations to the best of our knowledge.

5. Technical Publications on CD–ROM

Deutsche Aircraft GmbH provides the envelope issues of the AMM, AIPC, FIM, PPBM and CML also on CD–ROM. Before you use the CD–ROM you must read the Revision Transmittal Letter which was provided with the CD–ROM.

TEMPORARY REVISIONS ARE NOT COVERED BY THE CD–ROM. THEREFORE TEMPORARY REVISIONS MUST BE KEPT AS HARD COPIES IN ADDITION TO THE CD–ROM.

You must check the Publications Index (PI) to ensure that you have the valid issue of the CD–ROM available and to ensure that you are informed about the Temporary Revisions which must be observed.

## INTRODUCTION

The PI lists the effective issues of the manuals which are available on the CD–ROM. Please compare the issue written on the CD–ROM label with the issue for the manuals given in the PI. Finally please read the OPERATING INSTRUCTIONS for the use of the CD–ROM before you start reading, copying or printing of CD–ROM data.

6. Index Breakdown

The general breakdown of the PI is:

– A/C MFR PUBLICATIONS
– VENDOR PUBLICATIONS
- Sort Vendor alphabetical
- Sort ATA–Chapter Code
- Sort Part Number

– SERVICE PUBLICATIONS
- SB's, EO's, RO's, SI's, CI's, AOT's, AD's etc.

7. Customer Identification

| | | | |
|---|---|---|---|
| –ADA | Aerolinea de Antioquia | –GLR | Central Mountain Air |
| –ADNB | Mediterranean Aviation | –PEARL | Pearl Aviation |
| –AFEX | Afrimex (DANA) | –SAY | Loganair (Suckling Airways) |
| –AWI | Air Wisconsin Airlines | –SNCORP | Sierra Nevada Corporation |
| –DANA | Dornier Aviation Nigeria | –SUS | Sun–Air of Scandinavia |
| –EAGLE | Eagle Air | –TAA | Tyrol Air Ambulance / Welcome Air |
| –EASPA | EASP Air BV | | |
| –EXECU | Execu Jet Aviaiton | | |

## INTRODUCTION

8. Instructions for Continued Airworthiness

Following Manuals contain ICA in accordance with EASA Part 21.A.7(a):

NOTE: Refer to the following Sections for the current revision and temporary revision status for the manual.

| Manual Name | Abbreviated | A/C-Type | Documentnumber | Initial Issue | Remarks |
|---|---|---|---|---|---|
| Weight and Balance Manual | WBM | 328-100 | TM-WBM-190793-ENV | 10.10.1995 | |
| | | | | | |
| Airworthiness Limitations Document | ALD | 328-100 | TM-ALD-010693-ALL | 01.06.1993 | |
| | | | | | |
| Certification Maintenance Requirements Document | CMR | 328-100 | TM-CMR-010793-ALL | 01.07.1993 | |
| | | | | | |
| Maintentance Review Board Report | MRB | 328-100 | TM-MRB-010693-ALL | 30.09.1993 | |
| | | | | | |
| Maintenance Planning Document | MPD | 328-100 | TM-MPD-300994-ALL | 30.09.1994 | |
| | | | | | |
| EWIS Source Documents | SB | 328-100 | SB-328-90-482 | 10.12.2009 | |
| | | | | | |
| Aircraft Maintenance Manual - Job Instruction Cards | AMM - JIC | 328-100 | TM-AMM-190793-ENV | 19.07.1993 | |
| Aircraft Maintenance Manual - Description and Operation | AMM - D&O | 328-100 | TM-AMM-190793-ENV | 19.07.1993 | |
| | | | | | |
| Corrosion Prevention and Control Program Manual | CPCP | 328-100 | TM-CPCP-200897-ALL | 20.08.1997 | |
| | | | | | |
| System Schematics Manual | SSM | 328-100 | TM-SSM-010693-ENV | 15.02.1994 | |
| | | | | | |

## INTRODUCTION

| Manual Name | Abbreviated | A/C-Type | Documentnumber | Initial Issue | Remarks |
|---|---|---|---|---|---|
| Fault Isolation Manual | FIM | 328-100 | TM-FIM-300493-ENV | 10.12.1993 | |
| | | | | | |
| Wiring Manual | WM | 328-100 | TM-WM-300493-ENV | 30.04.1993 | |
| | | | | | |
| Structural Repair Manual | SRM | 328-100 | TM-SRM-300493-ALL | 30.04.1993 | |
| | | | | | |
| Component Maintenance Manual Manufacturer | CMMM | 328-ALL | TM-CMMM-010598-ALL | 05.02.2001 | Topic: Inlet Header Tank Assy |
| Component Maintenance Manual Manufacturer | CMMM | 328-ALL | TM-CMMM-010917-ALL | 01.09.2017 | Topic: Insulation Kit |
| Component Maintenance Manual Manufacturer | CMMM | 328-100 | TM-CMMM-120698-ALL | 12.06.1998 | Topic: Engine Control Box |
| Component Maintenance Manual Manufacturer | CMMM | 328-ALL | TM-CMMM-101097-ALL | 10.10.1997 | Topic: NWS Hand Control Unit |
| Component Maintenance Manual Manufacturer | CMMM | 328-100 | TM-CMMM-011204-100 | 01.12.2004 | Topic: Hydraulic Main Reservoir |
| Component Maintenance Manual Manufacturer | CMMM | 328-ALL | TM-CMMM-300198-ALL-1 | 05.02.2001 | Topic: S-Duct Assy |
| Component Maintenance Manual Manufacturer | CMMM | 328-ALL | TM-CMMM-300198-ALL-2 | 15.11.2004 | Topic: Outlet Deflector S-Duct/Heat Exchanger |
| Component Maintenance Manual Manufacturer | CMMM | 328-ALL | TM-CMMM-300493-ALL-1 | 30.04.1993 | Topic: Passenger/Crew Door |
| Component Maintenance Manual Manufacturer | CMMM | 328-ALL | TM-CMMM-300493-ALL-2 | 30.04.1993 | Topic: Cargo Door |
| Component Maintenance Manual Manufacturer | CMMM | 328-ALL | TM-CMMM-300493-ALL-3 | 30.04.1993 | Topic: Service Door |
| Component Maintenance Manual Manufacturer | CMMM | 328-ALL | TM-CMMM-301116-ALL | 30.11.2016 | Topic: Roll- & Flightspoiler (MFR Overhaul Only ->no distribution to customers) |
| Component Maintenance Manual Manufacturer | CMMM | 328-100 | TM-CMMM-150798-ALL | 15.07.1998 | Topic: Tail Cone with Exhaust Duct (MFR Overhaul Only ->no distribution to customers) |

## INTRODUCTION

| Manual Name | Abbreviated | A/C-Type | Documentnumber | Initial Issue | Remarks |
|---|---|---|---|---|---|
| Component Maintenance Manual Manufacturer | CMMM | 328-100 | TM-CMMM-240316-ALL | 24.03.2016 | Topic: NWS Feedback Potentiometer Harness (MFR Overhaul Only ->no distribution to customers) |
| Component Maintenance Manual Manufacturer | CMMM | 328-100 | TM-CMMM-300198-ALL | 30.01.1998 | Topic: Air Inlet Duct (MFR Overhaul Only ->no distribution to customers) |
| | | | | | |
| Component Maintenance Manual - Vendor | CMM-V | - | - | - | |
| System Maintenance Manual | SMM | - | - | - | |
| | | | | | |
| Illustrated Tool and Equipment Manual | ITEM | 328-ALL | TM-ITEM-010914-ALL | 01.09.2014 | Supersedes TM-ITEM-300493-ALL & TM-ITEM-010699-ALL. |
| | | | | | |
| Nondestructive Testing Manual | NTM | 328-100 | TM-NTM-300493-ALL | 30.04.1993 | |
| | | | | | |
| Fatigue Critical Baseline/ Alteration Structure Manual | FCB/ASM | 328-100 | TM-FCB/ASM-010709-100-ALL | 01.07.2009 | |
| | | | | | |
| Repair Evaluation Guidelines | REG | 328-100 | TM-REG-010909-100-ALL | 01.09.2009 | |
| | | | | | |
| Aircraft Illustrated Parts Catalog | AIPC | 328-100 | TM-AIPC-170993-ENV | 10.04.1995 | |
| | | | | | |
| In Service Technical Information (ASB, SB, SI, CI, AOT) | ISTI | 328-100 | - | - | |
| | | | | | |
| Aircraft Maintenance Manual - Cold Weather Operation | AMMC | 328-100 | TM-AMMC-151195-ALL | 15.11.1995 | |

## INTRODUCTION

9. User Comments

Your partner for further inquiries concerning this Publications Index:

Deutsche Aircraft GmbH
Technical Publications
Oberpaffenhofen Airport
D-82234 Wessling
Germany
E-Mail: techpub@deutscheaircraft.com

## INTRODUCTION

INTENTIONALLY LEFT BLANK

# CHAPTER

# 1

# A/C MFR PUBLICATIONS

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. | / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Version 2.4 | Adaptions Software for ECTM | 328 SSG | WinRGBS | 01.10.96 | | | IM-RGBS-011096-ALL | O | | DISKETTE | 3P |
| | AIPC Cable Harness Listing (ACHL) | 328 SSG | ACHL | 16.10.98 | | | TM-ACHL-161098-ALL | S | | | 3P |
| | Aircr. Maint. Man. (AMM - D&O) | 328 SSG | AMM | 01.03.11 | 9 | 01.03.19 | TM-AMM-190793-ADA | S | | Outdated | 3P |
| | Aircr. Maint. Man. (AMM - D&O) | 328 SSG | AMM | 19.07.93 | 53 | 01.03.23 | TM-AMM-190793-ENV | S | | | 3P |
| | Aircr. Maint. Man. (AMM - D&O) | 328 SSG | AMM | 01.03.08 | 5 | 01.09.11 | TM-AMM-190793-EXECU | S | | Outdated | 3P |
| | Aircr. Maint. Man. (AMM - D&O) | 328 SSG | AMM | 02.09.04 | 28 | 01.03.22 | TM-AMM-190793-PEARL | S | | Outdated | 3P |
| | Aircr. Maint. Man. (AMM - JIC) | 328 SSG | AMM | 01.03.11 | 10 | 01.03.19 | TM-AMM-190793-ADA | S | | Outdated | 3P |
| | Aircr. Maint. Man. (AMM - JIC) | 328 SSG | AMM | 19.07.93 | 55 | 01.03.23 | TM-AMM-190793-ENV | S | | | 3P |
| | Aircr. Maint. Man. (AMM - JIC) | 328 SSG | AMM | 19.07.93 | 55 | 01.03.23 | TM-AMM-190793-ENV (PDF) | S | | | 3P |
| | Aircr. Maint. Man. (AMM - JIC) | 328 SSG | AMM | 01.03.08 | 6 | 01.09.11 | TM-AMM-190793-EXECU | S | | Outdated | 3P |
| | Aircr. Maint. Man. (AMM - JIC) | 328 SSG | AMM | 02.09.04 | 30 | 01.03.22 | TM-AMM-190793-PEARL | S | | Outdated | 3P |
| | Aircr. Maint. Man. (AMM - JIC) | 328 SSG | TR 05-268 | 13.01.12 | | | TM-AMM-190793-X | S | | | 3P |
| | Aircr. Maint. Man. (AMM - JIC) | 328 SSG | TR 05-268 | 13.01.12 | | | TM-AMM-190793-X (PDF) | S | | | 3P |
| | Aircr. Maint. Man. Storage (AMMS) | 328 SSG | AMMS | 01.04.04 | 3 | 01.03.19 | TM-AMMS-010404-ALL | O | | | 3P |
| | Aircraft Ill. Parts Catalog (AIPC) | 328 SSG | AIPC | 01.03.11 | 10 | 01.03.19 | TM-AIPC-170993-ADA | S | | Outdated | 3P |
| | Aircraft Ill. Parts Catalog (AIPC) | 328 SSG | AIPC | 10.04.95 | 53 | 01.03.23 | TM-AIPC-170993-ENV | S | | | 3P |
| | Aircraft Logbook (ALB) | 328 SSG | Service Tech. | | | | 348 | S | | | 3A |
| | Aircraft Recovery Manual (ARM) | 328 SSG | ARM | 01.08.00 | 1 | 25.07.16 | TM-ARM-010800-ALL-100 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.05.08 | | 01.10.18 | AM-AFM-050893-3005 | S | | Outdated | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | | 01.10.10 | AM-AFM-050893-3005 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | | 01.10.10 | AM-AFM-050893-3005 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | | 01.10.18 | AM-AFM-050893-3005 | S | | Outdated | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | | 31.10.19 | AM-AFM-050893-3005 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | | AM-AFM-050893-3005 | S | | | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | | 01.10.18 | AM-AFM-050893-3005 | S | | | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | | 29.05.13 | AM-AFM-050893-3005 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | | 30.03.17 | AM-AFM-050893-3005 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 18-003 | 31.12.18 | | | AM-AFM-050893-3005 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 18-005 | 31.12.18 | | | AM-AFM-050893-3005 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 19-006 | 15.10.19 | | | AM-AFM-050893-3005 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 29.04.08 | | 28.02.21 | AM-AFM-050893-3006 (PDF) | S | | Edition: 12.01.2022 | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | | 01.10.10 | AM-AFM-050893-3006 (PDF) | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | | 01.10.10 | AM-AFM-050893-3006 (PDF) | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | | 28.02.21 | AM-AFM-050893-3006 (PDF) | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | | 31.10.19 | AM-AFM-050893-3006 (PDF) | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | | AM-AFM-050893-3006 (PDF) | S | | | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | | 01.10.18 | AM-AFM-050893-3006 (PDF) | S | | | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | | 29.05.13 | AM-AFM-050893-3006 (PDF) | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | | 01.04.20 | AM-AFM-050893-3006 (PDF) | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | | 30.03.17 | AM-AFM-050893-3006 (PDF) | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.06.03 | | 01.01.14 | AM-AFM-050893-3010 | S | | Outdated | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | | 01.10.10 | AM-AFM-050893-3010 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | | 01.10.10 | AM-AFM-050893-3010 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| FAA-Suppl TCAS | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.01.95 | | AM-AFM-050893-3010 | S | | Outdated | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.01.14 | AM-AFM-050893-3010 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 15-008 | 15.10.15 | | AM-AFM-050893-3010 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 15-013 | 30.10.15 | | AM-AFM-050893-3010 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 16-001 | 08.02.16 | | AM-AFM-050893-3010 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 03.11.14 | 28.02.21 | AM-AFM-050893-3013 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3013 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3013 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3013 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3013 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3013 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3013 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3013 | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-3013 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.05.17 | 01.05.20 | AM-AFM-050893-3013 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3013 | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3013 | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3013 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3013 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3013 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.05.08 | 01.01.14 | AM-AFM-050893-3014 | S | | Outdated | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3014 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3014 | S | | | 3P |
| FAA-Suppl TCAS | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.01.95 | | AM-AFM-050893-3014 | S | | Outdated | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.01.14 | AM-AFM-050893-3014 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 15-013 | 30.10.15 | | AM-AFM-050893-3014 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 16-001 | 08.02.16 | | AM-AFM-050893-3014 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 16-007 | 15.09.16 | | AM-AFM-050893-3014 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 16-009 | 01.12.16 | | AM-AFM-050893-3014 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.21 | 28.02.21 | AM-AFM-050893-3015 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3015 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3015 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3015 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3015 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3015 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3015 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-3015 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3015 | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3015 | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-3015 | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3015 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3015 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3015 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 02.11.11 | 28.02.21 | AM-AFM-050893-3016 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3016 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3016 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3016 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3016 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3016 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3016 | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3016 | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3016 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3016 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3016 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3016 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3016 | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-3016 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-3016 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3016 | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3016 | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-3016 | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3016 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3016 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3016 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.02.15 | 01.01.14 | AM-AFM-050893-3018 | S | | Outdated | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3018 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3018 | S | | | 3P |
| FAA-Suppl TCAS | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.01.95 | | AM-AFM-050893-3018 | S | | Outdated | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 01.01.14 | AM-AFM-050893-3018 | S | | Outdated | 3P |
| Supplement 008 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.95 | 01.10.10 | AM-AFM-050893-3018 | S | | | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.01.14 | AM-AFM-050893-3018 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 15-001 | 30.01.15 | | AM-AFM-050893-3018 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 15-008 | 15.10.15 | | AM-AFM-050893-3018 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 15-013 | 30.10.15 | | AM-AFM-050893-3018 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 16-001 | 08.02.16 | | AM-AFM-050893-3018 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 16-007 | 15.09.16 | | AM-AFM-050893-3018 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.08.11 | 28.02.21 | AM-AFM-050893-3019 (PDF) | S | | Edition: 12.01.2022 | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3019 (PDF) | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3019 (PDF) | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3019 (PDF) | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3019 (PDF) | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3019 (PDF) | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3019 (PDF) | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3019 (PDF) | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3019 (PDF) | S | | | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.10.18 | AM-AFM-050893-3019 (PDF) | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3019 (PDF) | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3019 (PDF) | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.16 | 28.02.21 | AM-AFM-050893-3020 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3020 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3020 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3020 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3020 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3020 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.06.94 | 28.02.21 | AM-AFM-050893-3020 | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3020 | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3020 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3020 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3020 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3020 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3020 | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-3020 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-3020 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3020 | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3020 | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-3020 | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3020 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3020 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3020 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.02.04 | 01.01.14 | AM-AFM-050893-3021 | S | | Outdated | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3021 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3021 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 01.10.15 | AM-AFM-050893-3021 | S | | Outdated | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 01.01.14 | AM-AFM-050893-3021 | S | | Outdated | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | 01.10.10 | AM-AFM-050893-3021 | S | | Outdated | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3021 | S | | | 3P |
| Supplement 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 24.11.94 | 01.10.10 | AM-AFM-050893-3021 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | | AM-AFM-050893-3021 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 15-001 | 30.01.15 | | AM-AFM-050893-3021 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 15-009 | 30.10.15 | | AM-AFM-050893-3021 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 15-013 | 30.10.15 | | AM-AFM-050893-3021 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 16-001 | 08.02.16 | | AM-AFM-050893-3021 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 16-009 | 01.12.16 | | AM-AFM-050893-3021 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 12.11.96 | 28.02.21 | AM-AFM-050893-3022 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3022 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3022 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3022 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3022 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3022 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | 01.10.18 | AM-AFM-050893-3022 | S | | | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3022 | S | | | 3P |
| Supplement 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 24.11.94 | 01.10.10 | AM-AFM-050893-3022 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3022 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.03.97 | 28.02.21 | AM-AFM-050893-3023 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3023 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3023 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3023 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3023 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3023 | S | | | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | 01.10.18 | AM-AFM-050893-3023 | S | | | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3023 | S | | | 3P |
| Supplement 008 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.95 | 01.10.10 | AM-AFM-050893-3023 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3023 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 14.03.97 | 01.01.14 | AM-AFM-050893-3024 | S | | Outdated | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3024 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3024 | S | | | 3P |
| FAA-Suppl TCAS | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.01.95 | | AM-AFM-050893-3024 | S | | Outdated | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 01.01.14 | AM-AFM-050893-3024 | S | | Outdated | 3P |
| Supplement 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.11.94 | 01.10.10 | AM-AFM-050893-3024 | S | | Outdated | 3P |
| Supplement 007 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.95 | 01.10.10 | AM-AFM-050893-3024 | S | | Outdated | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.06.15 | AM-AFM-050893-3024 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 15-001 | 30.01.15 | | AM-AFM-050893-3024 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 15-013 | 30.10.15 | | AM-AFM-050893-3024 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 16-001 | 08.02.16 | | AM-AFM-050893-3024 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 17-006 | 30.05.17 | | AM-AFM-050893-3024 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 14.10.16 | 28.02.21 | AM-AFM-050893-3025 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3025 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3025 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3025 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3025 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3025 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3025 | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3025 | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3025 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3025 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3025 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3025 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3025 | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-3025 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-3025 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3025 | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3025 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-3025 | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3025 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3025 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3025 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 16.08.11 | 28.02.21 | AM-AFM-050893-3026 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3026 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3026 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3026 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3026 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3026 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3026 | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3026 | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3026 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3026 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3026 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3026 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3026 | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-3026 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-3026 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3026 | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3026 | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-3026 | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3026 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3026 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3026 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.03.20 | 02.10.18 | AM-AFM-050893-3027 | S | | Outdated | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3027 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3027 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3027 | S | | | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | 01.10.18 | AM-AFM-050893-3027 | S | | | 3P |
| Supplement 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 24.11.94 | 01.10.10 | AM-AFM-050893-3027 | S | | | 3P |
| Supplement 007 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.95 | 01.10.18 | AM-AFM-050893-3027 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3027 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 18-004 | 31.12.18 | | AM-AFM-050893-3027 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 16.08.11 | 28.02.21 | AM-AFM-050893-3031 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3031 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3031 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3031 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3031 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3031 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3031 | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3031 | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3031 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3031 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3031 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3031 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3031 | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-3031 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-3031 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3031 | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3031 | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-3031 | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3031 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3031 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3031 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.11 | 01.10.10 | AM-AFM-050893-3033 | S | | Outdated | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.09.11 | 01.10.10 | AM-AFM-050893-3033 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.09.11 | 01.10.10 | AM-AFM-050893-3033 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.09.11 | 01.10.10 | AM-AFM-050893-3033 | S | | Outdated | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.09.11 | 01.10.10 | AM-AFM-050893-3033 | S | | Outdated | 3P |
| Supplement 013 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.09.98 | 01.10.10 | AM-AFM-050893-3033 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 14.03.97 | 01.01.14 | AM-AFM-050893-3034 | S | | Outdated | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3034 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3034 | S | | | 3P |
| FAA-Suppl TCAS | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.01.95 | | AM-AFM-050893-3034 | S | | Outdated | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 01.01.14 | AM-AFM-050893-3034 | S | | Outdated | 3P |
| Supplement 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.11.94 | 01.10.10 | AM-AFM-050893-3034 | S | | Outdated | 3P |
| Supplement 007 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.95 | 01.10.10 | AM-AFM-050893-3034 | S | | Outdated | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.06.15 | AM-AFM-050893-3034 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 15-001 | 30.01.15 | | AM-AFM-050893-3034 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 15-013 | 30.10.15 | | AM-AFM-050893-3034 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 16-001 | 08.02.16 | | AM-AFM-050893-3034 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 17-006 | 30.05.17 | | AM-AFM-050893-3034 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.07.08 | 28.02.21 | AM-AFM-050893-3035 (PDF) | S | | Edition: 12.01.2022 | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3035 (PDF) | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3035 (PDF) | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3035 (PDF) | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3035 (PDF) | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3035 (PDF) | S | | | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3035 (PDF) | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3035 (PDF) | S | | | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.10.18 | AM-AFM-050893-3035 (PDF) | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3035 (PDF) | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 12.09.96 | 01.01.14 | AM-AFM-050893-3036 | S | | Outdated | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3036 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3036 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 01.10.10 | AM-AFM-050893-3036 | S | | Outdated | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | 01.10.10 | AM-AFM-050893-3036 | S | | Outdated | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3036 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 26.06.13 | 01.01.14 | AM-AFM-050893-3039 | S | | Outdated | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3039 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3039 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 01.01.14 | AM-AFM-050893-3039 | S | | Outdated | 3P |
| Supplement 008 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.95 | 01.10.10 | AM-AFM-050893-3039 | S | | | 3P |
| Supplement 019 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 22.05.00 | 01.10.10 | AM-AFM-050893-3039 | S | | Outdated | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.01.14 | AM-AFM-050893-3039 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 15-001 | 30.01.15 | | AM-AFM-050893-3039 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 15-008 | 15.10.15 | | AM-AFM-050893-3039 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 15-013 | 30.10.15 | | AM-AFM-050893-3039 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 16-001 | 08.02.16 | | AM-AFM-050893-3039 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 16-007 | 15.09.16 | | AM-AFM-050893-3039 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.08.12 | 28.02.21 | AM-AFM-050893-3040 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3040 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3040 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3040 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3040 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3040 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3040 | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3040 | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3040 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3040 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3040 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3040 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3040 | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-3040 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-3040 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3040 | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3040 | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-3040 | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3040 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3040 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3040 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 23.04.13 | 28.02.21 | AM-AFM-050893-3047 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3047 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3047 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3047 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3047 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3047 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3047 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3047 | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3047 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3047 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3047 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3047 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3047 | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-3047 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-3047 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3047 | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3047 | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-3047 | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3047 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3047 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3047 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.03.13 | 28.02.21 | AM-AFM-050893-3050 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3050 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3050 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3050 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3050 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3050 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3050 | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3050 | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3050 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3050 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3050 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3050 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3050 | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-3050 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-3050 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3050 | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3050 | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-3050 | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3050 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3050 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3050 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.03.06 | 28.02.21 | AM-AFM-050893-3051 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3051 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3051 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3051 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3051 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3051 | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3051 | S | | | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.10.18 | AM-AFM-050893-3051 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3051 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.03.06 | 28.02.21 | AM-AFM-050893-3052 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3052 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3052 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3052 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3052 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3052 | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3052 | S | | | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.10.18 | AM-AFM-050893-3052 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3052 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 16.12.04 | 28.02.21 | AM-AFM-050893-3053 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3053 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3053 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3053 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3053 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3053 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3053 | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3053 | S | | | 3P |
| Supplement 018 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.12.99 | 28.02.21 | AM-AFM-050893-3053 | S | | | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.10.18 | AM-AFM-050893-3053 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3053 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3053 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.14 | 28.02.21 | AM-AFM-050893-3055 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3055 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3055 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3055 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3055 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3055 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3055 | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3055 | S | | | 3P |
| Supplement 019 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 22.05.00 | 28.02.21 | AM-AFM-050893-3055 | S | | | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.10.18 | AM-AFM-050893-3055 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 03.11.11 | 01.01.14 | AM-AFM-050893-3056 | S | | Outdated | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3056 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3056 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 01.10.15 | AM-AFM-050893-3056 | S | | Outdated | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 01.01.14 | AM-AFM-050893-3056 | S | | Outdated | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3056 | S | | | 3P |
| Supplement 008 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.95 | 01.10.10 | AM-AFM-050893-3056 | S | | | 3P |
| Supplement 019 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 22.05.00 | 01.10.10 | AM-AFM-050893-3056 | S | | Outdated | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3056 | S | | | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.01.14 | AM-AFM-050893-3056 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 15-001 | 30.01.15 | | AM-AFM-050893-3056 | S | | Outdated | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 15-013 | 30.10.15 | | AM-AFM-050893-3056 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 16-001 | 08.02.16 | | AM-AFM-050893-3056 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 16-007 | 15.09.16 | | AM-AFM-050893-3056 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 17-006 | 30.05.17 | | AM-AFM-050893-3056 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.03.06 | 28.02.21 | AM-AFM-050893-3057 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3057 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3057 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3057 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3057 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3057 | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3057 | S | | | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.10.18 | AM-AFM-050893-3057 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3057 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.12.10 | 28.02.21 | AM-AFM-050893-3058 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3058 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3058 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3058 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3058 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3058 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3058 | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3058 | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3058 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3058 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3058 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3058 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3058 | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-3058 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-3058 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3058 | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3058 | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-3058 | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3058 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3058 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3058 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.03.06 | 28.02.21 | AM-AFM-050893-3059 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3059 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3059 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3059 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3059 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3059 | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3059 | S | | | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.10.18 | AM-AFM-050893-3059 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3059 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3059 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.08.12 | 28.02.21 | AM-AFM-050893-3060 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3060 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3060 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3060 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3060 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3060 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3060 | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3060 | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3060 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3060 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3060 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3060 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3060 | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-3060 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-3060 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3060 | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3060 | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-3060 | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3060 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3060 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3060 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.10.04 | 28.02.21 | AM-AFM-050893-3061 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3061 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3061 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3061 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3061 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3061 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3061 | S | | | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3061 | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3061 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3061 | S | | | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.10.18 | AM-AFM-050893-3061 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3061 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3061 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.04.15 | 28.02.21 | AM-AFM-050893-3063 (PDF) | S | R | Edition: 09.05.2023 | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3063 (PDF) | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3063 (PDF) | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3063 (PDF) | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3063 (PDF) | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3063 (PDF) | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3063 (PDF) | S | | | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | 01.10.18 | AM-AFM-050893-3063 (PDF) | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3063 (PDF) | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3063 (PDF) | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3063 (PDF) | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3063 (PDF) | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3063 (PDF) | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 02.04.04 | 01.01.14 | AM-AFM-050893-3066 (PDF) | S | | Outdated / Edition: 02.11.2018 | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3066 (PDF) | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3066 (PDF) | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 30.03.17 | AM-AFM-050893-3066 (PDF) | S | | Outdated | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | | AM-AFM-050893-3066 (PDF) | S | | Outdated | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 31.01.17 | AM-AFM-050893-3066 (PDF) | S | | Outdated | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | 01.10.10 | AM-AFM-050893-3066 (PDF) | S | | Outdated | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3066 (PDF) | S | | | 3P |
| Supplement 007 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.95 | 01.10.10 | AM-AFM-050893-3066 (PDF) | S | | Outdated | 3P |
| Supplement 008 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.95 | 01.10.10 | AM-AFM-050893-3066 (PDF) | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3066 (PDF) | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 15-009 | 30.10.15 | | AM-AFM-050893-3066 (PDF) | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 15-013 | 30.10.15 | | AM-AFM-050893-3066 (PDF) | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 16-001 | 08.02.16 | | AM-AFM-050893-3066 (PDF) | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 17-001 | 31.01.17 | | AM-AFM-050893-3066 (PDF) | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 17-006 | 30.05.17 | | AM-AFM-050893-3066 (PDF) | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.07.11 | 28.02.21 | AM-AFM-050893-3068 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3068 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3068 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3068 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3068 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3068 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3068 | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3068 | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3068 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3068 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3068 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3068 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3068 | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-3068 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-3068 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3068 | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3068 | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-3068 | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3068 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3068 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3068 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.10.04 | 01.10.18 | AM-AFM-050893-3070 | S | | Outdated | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3070 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3070 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 01.10.18 | AM-AFM-050893-3070 | S | | Outdated | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | | AM-AFM-050893-3070 | S | | Outdated | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 31.01.17 | AM-AFM-050893-3070 | S | | Outdated | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3070 | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 15.03.18 | AM-AFM-050893-3070 | S | | Outdated | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.10.18 | AM-AFM-050893-3070 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3070 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 18-003 | 31.12.18 | | AM-AFM-050893-3070 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 18-005 | 31.12.18 | | AM-AFM-050893-3070 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 09.12.14 | 28.02.21 | AM-AFM-050893-3072 (PDF) | S | | Edition: 12.01.2022 | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3072 (PDF) | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3072 (PDF) | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3072 (PDF) | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3072 (PDF) | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3072 (PDF) | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3072 (PDF) | S | | | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | 01.10.18 | AM-AFM-050893-3072 (PDF) | S | | | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 02.03.98 | 29.05.13 | AM-AFM-050893-3072 (PDF) | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3072 (PDF) | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3072 (PDF) | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3072 (PDF) | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3072 (PDF) | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.02.99 | 28.02.21 | AM-AFM-050893-3073 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3073 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3073 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3073 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3073 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3073 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3073 | S | | | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | 01.10.18 | AM-AFM-050893-3073 | S | | | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3073 | S | | | 3P |
| Supplement 008 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.95 | 01.10.10 | AM-AFM-050893-3073 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3073 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.12.11 | 28.02.21 | AM-AFM-050893-3075 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3075 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3075 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3075 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3075 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3075 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3075 | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3075 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3075 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3075 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3075 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3075 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3075 | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-3075 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-3075 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3075 | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3075 | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-3075 | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3075 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3075 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3075 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.09.11 | 28.02.21 | AM-AFM-050893-3077 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3077 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3077 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3077 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3077 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3077 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3077 | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3077 | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3077 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3077 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3077 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3077 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3077 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3077 | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-3077 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-3077 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3077 | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3077 | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-3077 | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3077 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3077 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3077 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 09.10.96 | 28.02.21 | AM-AFM-050893-3078 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3078 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3078 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3078 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3078 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3078 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3078 | S | | | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3078 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Supplement 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.11.94 | 01.10.18 | AM-AFM-050893-3078 | S | | | 3P |
| Supplement 007 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.95 | 01.10.18 | AM-AFM-050893-3078 | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3078 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3078 | S | | | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.10.18 | AM-AFM-050893-3078 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3078 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 16.06.08 | 28.02.21 | AM-AFM-050893-3083 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3083 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3083 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3083 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3083 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3083 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3083 | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3083 | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3083 | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3083 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3083 | S | | | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.10.18 | AM-AFM-050893-3083 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3083 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3083 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.07.00 | 01.10.18 | AM-AFM-050893-3084 | S | | Outdated | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3084 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3084 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | | AM-AFM-050893-3084 | S | | Outdated | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 31.01.17 | AM-AFM-050893-3084 | S | | Outdated | 3P |
| Supplement 008 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.95 | 01.10.10 | AM-AFM-050893-3084 | S | | | 3P |
| Supplement 019 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 22.05.00 | 01.10.10 | AM-AFM-050893-3084 | S | | Outdated | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.10.18 | AM-AFM-050893-3084 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 18-003 | 31.12.18 | | AM-AFM-050893-3084 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 18-007 | 31.12.18 | | AM-AFM-050893-3084 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.08.12 | 28.02.21 | AM-AFM-050893-3085 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3085 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3085 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3085 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3085 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3085 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3085 | S | | | 3P |
| Supplement 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.11.94 | 01.10.18 | AM-AFM-050893-3085 | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3085 | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3085 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3085 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3085 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3085 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3085 | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-3085 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-3085 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3085 | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3085 | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-3085 | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3085 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3085 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3085 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.06.15 | 28.02.21 | AM-AFM-050893-3086 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3086 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3086 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3086 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3086 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3086 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3086 | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3086 | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3086 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3086 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3086 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3086 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3086 | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-3086 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-3086 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3086 | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3086 | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-3086 | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3086 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3086 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3086 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 17.05.06 | 28.02.21 | AM-AFM-050893-3087 (PDF) | S | | Edition: 12.01.2022 | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3087 (PDF) | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3087 (PDF) | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3087 (PDF) | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3087 (PDF) | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3087 (PDF) | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3087 (PDF) | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3087 (PDF) | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3087 (PDF) | S | | | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.10.18 | AM-AFM-050893-3087 (PDF) | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3087 (PDF) | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3087 (PDF) | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 11.03.96 | 28.02.21 | AM-AFM-050893-3088 (PDF) | S | | Edition: 10.11.2022 | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3088 (PDF) | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3088 (PDF) | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3088 (PDF) | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3088 (PDF) | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3088 (PDF) | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3088 (PDF) | S | | | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | 01.10.18 | AM-AFM-050893-3088 (PDF) | S | | | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3088 (PDF) | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3088 (PDF) | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3088 (PDF) | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3088 (PDF) | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.11.99 | 28.02.21 | AM-AFM-050893-3089 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3089 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3089 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3089 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3089 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3089 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3089 | S | | | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | 01.10.18 | AM-AFM-050893-3089 | S | | | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3089 | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3089 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3089 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 13.08.07 | 28.02.21 | AM-AFM-050893-3090 (PDF) | S | | Edition: 12.01.2022 | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3090 (PDF) | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3090 (PDF) | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3090 (PDF) | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3090 (PDF) | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3090 (PDF) | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3090 (PDF) | S | | | 3P |
| Supplement 007 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.95 | 01.10.18 | AM-AFM-050893-3090 (PDF) | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3090 (PDF) | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3090 (PDF) | S | | | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.10.18 | AM-AFM-050893-3090 (PDF) | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3090 (PDF) | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3090 (PDF) | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.10.09 | 28.02.21 | AM-AFM-050893-3091 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3091 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3091 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3091 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3091 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3091 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3091 | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3091 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3091 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3091 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3091 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3091 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3091 | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-3091 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-3091 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3091 | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3091 | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-3091 | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3091 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3091 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3091 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 17.03.15 | 01.10.18 | AM-AFM-050893-3092 | S | | Outdated | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3092 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3092 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | | AM-AFM-050893-3092 | S | | Outdated | 3P |
| FAA-Suppl TCAS | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.01.95 | | AM-AFM-050893-3092 | S | | Outdated | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 31.01.17 | AM-AFM-050893-3092 | S | | Outdated | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | 01.10.18 | AM-AFM-050893-3092 | S | | | 3P |
| Supplement 008 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.95 | 01.10.10 | AM-AFM-050893-3092 | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3092 | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3092 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 18-003 | 31.12.18 | | AM-AFM-050893-3092 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 18-007 | 31.12.18 | | AM-AFM-050893-3092 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 02.11.10 | 28.02.21 | AM-AFM-050893-3093 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3093 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3093 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3093 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3093 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3093 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3093 | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3093 | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3093 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3093 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3093 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3093 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3093 | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-3093 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-3093 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3093 | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3093 | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-3093 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3093 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3093 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3093 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 07.10.08 | 28.02.21 | AM-AFM-050893-3094 (PDF) | S | | Edition: 12.01.2022 | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3094 (PDF) | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3094 (PDF) | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3094 (PDF) | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3094 (PDF) | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3094 (PDF) | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3094 (PDF) | S | | | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | 01.10.18 | AM-AFM-050893-3094 (PDF) | S | | | 3P |
| Supplement 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.11.94 | 01.10.18 | AM-AFM-050893-3094 (PDF) | S | | | 3P |
| Supplement 007 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.95 | 01.10.18 | AM-AFM-050893-3094 (PDF) | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3094 (PDF) | S | | | 3P |
| Supplement 019 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 22.05.00 | 28.02.21 | AM-AFM-050893-3094 (PDF) | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.05 | 28.02.21 | AM-AFM-050893-3096 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3096 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3096 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3096 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3096 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3096 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3096 | S | | | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | 01.10.18 | AM-AFM-050893-3096 | S | | | 3P |
| Supplement 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.11.94 | 01.10.18 | AM-AFM-050893-3096 | S | | | 3P |
| Supplement 007 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.95 | 01.10.18 | AM-AFM-050893-3096 | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3096 | S | | | 3P |
| Supplement 019 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 22.05.00 | 28.02.21 | AM-AFM-050893-3096 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.05.05 | 28.02.21 | AM-AFM-050893-3097 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3097 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3097 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3097 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3097 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3097 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3097 | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3097 | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3097 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3097 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3097 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3097 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3097 | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-3097 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-3097 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3097 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3097 | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-3097 | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3097 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3097 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3097 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 26.03.99 | 28.02.21 | AM-AFM-050893-3098 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3098 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3098 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3098 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.10.19 | 31.10.19 | AM-AFM-050893-3098 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3098 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3098 | S | | | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | 01.10.18 | AM-AFM-050893-3098 | S | | | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3098 | S | | | 3P |
| Supplement 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 16.04.98 | 01.10.10 | AM-AFM-050893-3098 | S | | | 3P |
| Supplement 007 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.95 | 01.10.18 | AM-AFM-050893-3098 | S | | | 3P |
| Supplement 008 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.95 | 01.10.10 | AM-AFM-050893-3098 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3098 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3098 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.11.12 | 01.01.14 | AM-AFM-050893-3100 | S | | Outdated | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3100 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3100 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 30.03.17 | AM-AFM-050893-3100 | S | | Outdated | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | | AM-AFM-050893-3100 | S | | Outdated | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 31.01.17 | AM-AFM-050893-3100 | S | | Outdated | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 15.03.18 | AM-AFM-050893-3100 | S | | Outdated | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.01.14 | AM-AFM-050893-3100 | S | | Outdated | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3100 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 15-013 | 30.10.15 | | AM-AFM-050893-3100 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 16-002 | 08.02.16 | | AM-AFM-050893-3100 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 16-008 | 15.09.16 | | AM-AFM-050893-3100 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 17-001 | 31.01.17 | | AM-AFM-050893-3100 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 17-006 | 30.05.17 | | AM-AFM-050893-3100 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.05 | 28.02.21 | AM-AFM-050893-3101 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3101 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3101 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3101 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3101 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3101 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3101 | S | | | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | 01.10.18 | AM-AFM-050893-3101 | S | | | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3101 | S | | | 3P |
| Supplement 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 16.04.98 | 01.10.10 | AM-AFM-050893-3101 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Supplement 007 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.95 | 01.10.18 | AM-AFM-050893-3101 | S | | | 3P |
| Supplement 008 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.95 | 01.10.10 | AM-AFM-050893-3101 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3101 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3101 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.06.11 | 28.02.21 | AM-AFM-050893-3104 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3104 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3104 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3104 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3104 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3104 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3104 | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3104 | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3104 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3104 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3104 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3104 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3104 | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-3104 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-3104 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3104 | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3104 | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.03.19 | AM-AFM-050893-3104 | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3104 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3104 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3104 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 02.08.10 | 28.02.21 | AM-AFM-050893-3106 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3106 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3106 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3106 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3106 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3106 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3106 | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-3106 | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-3106 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3106 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3106 | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-3106 | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3106 | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-3106 | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-3106 | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-3106 | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3106 | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-3106 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-3106 | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-3106 | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-3106 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 22.05.17 | 28.02.21 | AM-AFM-050893-3109 | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3109 | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3109 | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3109 | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3109 | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3109 | S | | | 3P |
| Supplement 018 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.12.99 | 28.02.21 | AM-AFM-050893-3109 | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3109 | S | | | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.10.18 | AM-AFM-050893-3109 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3109 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 02.04.15 | 28.02.21 | AM-AFM-050893-3110 (PDF) | S | | Edition: 12.01.2022 | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3110 (PDF) | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3110 (PDF) | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3110 (PDF) | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3110 (PDF) | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3110 (PDF) | S | | | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | 01.10.18 | AM-AFM-050893-3110 (PDF) | S | | | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3110 (PDF) | S | | | 3P |
| Supplement 007 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.95 | 01.10.18 | AM-AFM-050893-3110 (PDF) | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3110 (PDF) | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3110 (PDF) | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.99 | 28.02.21 | AM-AFM-050893-3112 (PDF) | S | | Edition: 12.01.2022 | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3112 (PDF) | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3112 (PDF) | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3112 (PDF) | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3112 (PDF) | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3112 (PDF) | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3112 (PDF) | S | | | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3112 (PDF) | S | | | 3P |
| Supplement 007 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.95 | 01.10.18 | AM-AFM-050893-3112 (PDF) | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3112 (PDF) | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3112 (PDF) | S | | | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.10.18 | AM-AFM-050893-3112 (PDF) | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3112 (PDF) | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3112 (PDF) | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 16.02.04 | 28.02.21 | AM-AFM-050893-3113 (PDF) | S | | Edition: 12.01.2022 | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3113 (PDF) | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3113 (PDF) | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3113 (PDF) | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3113 (PDF) | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3113 (PDF) | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3113 (PDF) | S | | | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3113 (PDF) | S | | | 3P |
| Supplement 007 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.95 | 01.10.18 | AM-AFM-050893-3113 (PDF) | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3113 (PDF) | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3113 (PDF) | S | | | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.10.18 | AM-AFM-050893-3113 (PDF) | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3113 (PDF) | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3113 (PDF) | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 12.04.00 | 01.10.18 | AM-AFM-050893-3115 | S | | Outdated | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3115 | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3115 | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 01.10.18 | AM-AFM-050893-3115 | S | | Outdated | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | | AM-AFM-050893-3115 | S | | Outdated | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 31.01.17 | AM-AFM-050893-3115 | S | | Outdated | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3115 | S | | | 3P |
| Supplement 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.11.94 | 01.10.18 | AM-AFM-050893-3115 | S | | | 3P |
| Supplement 007 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.95 | 01.10.18 | AM-AFM-050893-3115 | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 15.03.18 | AM-AFM-050893-3115 | S | | Outdated | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.10.18 | AM-AFM-050893-3115 | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3115 | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 18-003 | 31.12.18 | | AM-AFM-050893-3115 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 18-005 | 31.12.18 | | AM-AFM-050893-3115 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | TR 19-001 | 30.05.19 | | AM-AFM-050893-3115 | S | | Outdated | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 28.02.21 | AM-AFM-050893-3117 (PDF) | S | | Edition: 26.01.2023 | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3117 (PDF) | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3117 (PDF) | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3117 (PDF) | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3117 (PDF) | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3117 (PDF) | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-3117 (PDF) | S | | | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3117 (PDF) | S | | | 3P |
| Supplement 007 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.95 | 01.10.18 | AM-AFM-050893-3117 (PDF) | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3117 (PDF) | S | | | 3P |
| Supplement 018 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.12.99 | 28.02.21 | AM-AFM-050893-3117 (PDF) | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3117 (PDF) | S | | | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.10.18 | AM-AFM-050893-3117 (PDF) | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3117 (PDF) | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3117 (PDF) | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 12.09.96 | 28.02.21 | AM-AFM-050893-3119 (PDF) | S | | Edition: 12.01.2022 | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-3119 (PDF) | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-3119 (PDF) | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-3119 (PDF) | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-3119 (PDF) | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-3119 (PDF) | S | | | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | 01.10.18 | AM-AFM-050893-3119 (PDF) | S | | | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-3119 (PDF) | S | | | 3P |
| Supplement 007 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.95 | 01.10.18 | AM-AFM-050893-3119 (PDF) | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-3119 (PDF) | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-3119 (PDF) | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-3119 (PDF) | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-3119 (PDF) | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 28.02.21 | AM-AFM-050893-ENV | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-ENV | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-ENV | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-ENV | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-ENV | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-ENV | S | | | 3P |
| FAA-Suppl TCAS | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.01.95 | 28.02.21 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | 01.10.18 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 16.04.98 | 01.10.10 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.11.94 | 01.10.18 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 24.11.94 | 01.10.10 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 007 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.95 | 01.10.18 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 008 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.95 | 01.10.10 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 011 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.96 | 01.10.10 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 013 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.09.98 | 28.02.21 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 016 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 23.09.99 | 01.10.18 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 017 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.10.99 | 01.10.10 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 018 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.12.99 | 28.02.21 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 019 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 22.05.00 | 28.02.21 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.01.18 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 023 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 13.04.12 | 01.01.14 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 024 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.06.15 | | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-ENV | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 034 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.11.18 | | AM-AFM-050893-ENV | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-ENV | S | | | 3P |
| | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 28.02.21 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Appendix 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.09.93 | 01.10.10 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Appendix 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 21.09.99 | 01.10.10 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Appendix 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 18.01.95 | 28.02.21 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Appendix 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.10.17 | 31.10.19 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Appendix 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.02.20 | | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| FAA-Suppl TCAS | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.01.95 | 28.02.21 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 001 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.07.94 | 28.02.21 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 002 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 06.04.94 | 01.10.18 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 003 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.97 | 29.05.13 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 004 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 16.04.98 | 01.10.10 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 005 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.11.94 | 01.10.18 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 006 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 24.11.94 | 01.10.10 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 007 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.07.95 | 01.10.18 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 008 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.95 | 01.10.10 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 011 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.96 | 01.10.10 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 012 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 08.10.96 | 01.10.18 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 013 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.09.98 | 28.02.21 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 014 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 05.11.96 | 01.04.20 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 015 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.11.97 | 01.10.10 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 016 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 23.09.99 | 01.10.18 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 017 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 28.10.99 | 01.10.10 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 018 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 10.12.99 | 28.02.21 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 019 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 22.05.00 | 28.02.21 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 020 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 19.11.01 | 01.10.10 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 021 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 20.09.04 | 01.01.18 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 022 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 25.03.12 | 30.03.17 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 023 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 13.04.12 | 01.01.14 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 024 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.06.15 | | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 025 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 01.03.17 | | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 026 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.09.15 | 01.10.18 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 027 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 31.01.17 | 01.04.20 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 028 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.05.20 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 029 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 28.02.21 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 030 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 031 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 27.10.17 | 30.05.19 | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 032 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | 01.04.20 | AM-AFM-050893-ENV (PDF) | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| Supplement 033 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 30.03.17 | | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 034 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.11.18 | | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| Supplement 035 | Airpl. Flight Manual (AFM) | 328 SSG | AFM | 15.03.19 | | AM-AFM-050893-ENV (PDF) | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 28.05.08 | 01.02.20 | AM-AOM-150793-3005 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 01-033 | 28.02.20 | | AM-AOM-150793-3005 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-196 | 15.11.19 | | AM-AOM-150793-3005 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 09-136 | 15.11.19 | | AM-AOM-150793-3005 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 20.07.07 | 30.04.21 | AM-AOM-150793-3006 (PDF) | S | | Edition: 28.06.2021 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 05.02.13 | 07.01.14 | AM-AOM-150793-3010 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 01-018 | 29.02.16 | | AM-AOM-150793-3010 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 02-127 | 15.04.15 | | AM-AOM-150793-3010 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 02-136 | 04.09.15 | | AM-AOM-150793-3010 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-108 | 15.10.15 | | AM-AOM-150793-3010 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-119 | 16.11.15 | | AM-AOM-150793-3010 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-124 | 08.02.16 | | AM-AOM-150793-3010 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 06-047 | 02.03.15 | | AM-AOM-150793-3010 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 06-054 | 31.03.16 | | AM-AOM-150793-3010 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 09-088 | 15.10.15 | | AM-AOM-150793-3010 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 09-096 | 08.02.16 | | AM-AOM-150793-3010 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 03.11.14 | 30.04.21 | AM-AOM-150793-3013 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 05.05.08 | 01.11.16 | AM-AOM-150793-3014 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 04-106 | 15.09.16 | | AM-AOM-150793-3014 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-132 | 01.12.16 | | AM-AOM-150793-3014 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 20.09.21 | 30.04.21 | AM-AOM-150793-3015 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 01.12.11 | 30.04.21 | AM-AOM-150793-3016 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 18.02.15 | 01.11.16 | AM-AOM-150793-3018 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 04-106 | 15.09.16 | | AM-AOM-150793-3018 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-136 | 01.12.16 | | AM-AOM-150793-3018 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 01.08.11 | 30.04.21 | AM-AOM-150793-3019 (PDF) | S | | Edition: 28.06.2021 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 18.01.16 | 30.04.21 | AM-AOM-150793-3020 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 30.11.12 | 01.11.16 | AM-AOM-150793-3021 (PDF) | S | | Outdated / Edition: 15.02.2017 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 04-101 | 30.10.15 | | AM-AOM-150793-3021 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-135 | 01.12.16 | | AM-AOM-150793-3021 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 01.02.06 | 01.02.20 | AM-AOM-150793-3022 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 01-033 | 28.02.20 | | AM-AOM-150793-3022 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 03-077 | 15.11.19 | | AM-AOM-150793-3022 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-196 | 15.11.19 | | AM-AOM-150793-3022 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 09-136 | 15.11.19 | | AM-AOM-150793-3022 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 01.02.06 | 01.02.20 | AM-AOM-150793-3023 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 01-033 | 28.02.20 | | AM-AOM-150793-3023 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 03-077 | 15.11.19 | | AM-AOM-150793-3023 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-196 | 15.11.19 | | AM-AOM-150793-3023 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 09-136 | 15.11.19 | | AM-AOM-150793-3023 | S | | Outdated | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 31.03.06 | 01.11.16 | AM-AOM-150793-3024 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-152 | 30.05.17 | | AM-AOM-150793-3024 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 10-021 | 01.03.17 | | AM-AOM-150793-3024 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 14.10.16 | 30.04.21 | AM-AOM-150793-3025 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 16.08.11 | 30.04.21 | AM-AOM-150793-3026 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 27.03.20 | 01.02.20 | AM-AOM-150793-3027 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 01-033 | 28.02.20 | | AM-AOM-150793-3027 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 16.08.11 | 30.04.21 | AM-AOM-150793-3031 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 15.09.11 | 01.03.11 | AM-AOM-150793-3033 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 31.03.06 | 01.11.16 | AM-AOM-150793-3034 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-152 | 30.05.17 | | AM-AOM-150793-3034 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 10-021 | 01.03.17 | | AM-AOM-150793-3034 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 28.07.08 | 30.04.21 | AM-AOM-150793-3035 (PDF) | S | | Edition: 28.06.2021 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 10.08.07 | 07.01.14 | AM-AOM-150793-3036 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 06-046 | 02.03.15 | | AM-AOM-150793-3036 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 09-085 | 03.06.14 | | AM-AOM-150793-3036 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 26.06.13 | 01.11.16 | AM-AOM-150793-3039 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 04-106 | 15.09.16 | | AM-AOM-150793-3039 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-136 | 01.12.16 | | AM-AOM-150793-3039 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 01.09.12 | 30.04.21 | AM-AOM-150793-3040 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 23.04.13 | 30.04.21 | AM-AOM-150793-3047 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 28.03.13 | 30.04.21 | AM-AOM-150793-3050 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 20.03.06 | 01.02.20 | AM-AOM-150793-3051 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 01-033 | 28.02.20 | | AM-AOM-150793-3051 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 03-077 | 15.11.19 | | AM-AOM-150793-3051 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-200 | 15.11.19 | | AM-AOM-150793-3051 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 09-139 | 15.11.19 | | AM-AOM-150793-3051 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 20.03.06 | 01.02.20 | AM-AOM-150793-3052 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 01-033 | 28.02.20 | | AM-AOM-150793-3052 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 03-077 | 15.11.19 | | AM-AOM-150793-3052 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-200 | 15.11.19 | | AM-AOM-150793-3052 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 09-139 | 15.11.19 | | AM-AOM-150793-3052 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 22.06.07 | 30.04.21 | AM-AOM-150793-3053 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 25.07.14 | 30.04.21 | AM-AOM-150793-3055 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 30.11.12 | 01.11.16 | AM-AOM-150793-3056 (PDF) | S | | Outdated / Edition: 27.10.2017 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 04-106 | 15.09.16 | | AM-AOM-150793-3056 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-151 | 30.05.17 | | AM-AOM-150793-3056 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 10-021 | 01.03.17 | | AM-AOM-150793-3056 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 20.03.06 | 01.02.20 | AM-AOM-150793-3057 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 01-033 | 28.02.20 | | AM-AOM-150793-3057 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 03-077 | 15.11.19 | | AM-AOM-150793-3057 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-200 | 15.11.19 | | AM-AOM-150793-3057 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 09-139 | 15.11.19 | | AM-AOM-150793-3057 | S | | Outdated | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 06.12.10 | 30.04.21 | AM-AOM-150793-3058 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 20.03.06 | 30.04.21 | AM-AOM-150793-3059 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 01.09.12 | 30.04.21 | AM-AOM-150793-3060 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 30.11.12 | 30.04.21 | AM-AOM-150793-3061 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 27.04.15 | 30.04.21 | AM-AOM-150793-3063 (PDF) | S | R | Edition: 08.05.2023 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 30.11.12 | 01.11.16 | AM-AOM-150793-3066 (PDF) | S | | Outdated / Edition: 02.11.2018 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 04-101 | 30.10.15 | | AM-AOM-150793-3066 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-151 | 30.05.17 | | AM-AOM-150793-3066 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 10-021 | 01.03.17 | | AM-AOM-150793-3066 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 15.07.11 | 30.04.21 | AM-AOM-150793-3068 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 20.07.07 | 01.11.16 | AM-AOM-150793-3070 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 01-024 | 31.01.18 | | AM-AOM-150793-3070 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 01-026 | 31.01.18 | | AM-AOM-150793-3070 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 02-164 | 15.11.18 | | AM-AOM-150793-3070 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 03-065 | 25.02.19 | | AM-AOM-150793-3070 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 04-106 | 15.09.16 | | AM-AOM-150793-3070 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 04-113 | 31.01.18 | | AM-AOM-150793-3070 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 04-124 | 30.04.18 | | AM-AOM-150793-3070 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-139 | 31.01.17 | | AM-AOM-150793-3070 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-151 | 30.05.17 | | AM-AOM-150793-3070 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 07-002 | 30.09.18 | | AM-AOM-150793-3070 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 09-111 | 31.01.17 | | AM-AOM-150793-3070 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 10-021 | 01.03.17 | | AM-AOM-150793-3070 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 09.12.14 | 30.04.21 | AM-AOM-150793-3072 (PDF) | S | | Edition: 28.06.2021 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 01.11.11 | 30.04.21 | AM-AOM-150793-3073 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 01.12.11 | 30.04.21 | AM-AOM-150793-3075 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 28.09.11 | 30.04.21 | AM-AOM-150793-3077 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 22.06.07 | 30.04.21 | AM-AOM-150793-3078 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 20.07.07 | 30.04.21 | AM-AOM-150793-3083 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 26.06.13 | 01.11.16 | AM-AOM-150793-3084 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 01-025 | 31.01.18 | | AM-AOM-150793-3084 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 02-163 | 15.11.18 | | AM-AOM-150793-3084 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 03-065 | 25.02.19 | | AM-AOM-150793-3084 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 04-106 | 15.09.16 | | AM-AOM-150793-3084 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-152 | 30.05.17 | | AM-AOM-150793-3084 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 07-003 | 30.09.18 | | AM-AOM-150793-3084 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 10-021 | 01.03.17 | | AM-AOM-150793-3084 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 01.09.12 | 30.04.21 | AM-AOM-150793-3085 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 25.06.15 | 30.04.21 | AM-AOM-150793-3086 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 17.05.06 | 30.04.21 | AM-AOM-150793-3087 (PDF) | S | | Edition: 28.06.2021 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 01.02.06 | 30.04.21 | AM-AOM-150793-3088 (PDF) | S | | Edition: 27.10.2022 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 01.11.11 | 30.04.21 | AM-AOM-150793-3089 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 13.08.07 | 30.04.21 | AM-AOM-150793-3090 (PDF) | S | | Edition: 28.06.2021 | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 06.10.09 | 30.04.21 | AM-AOM-150793-3091 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 17.03.15 | 01.11.16 | AM-AOM-150793-3092 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 01-025 | 31.01.18 | | AM-AOM-150793-3092 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 02-166 | 15.11.18 | | AM-AOM-150793-3092 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 03-048 | 31.01.17 | | AM-AOM-150793-3092 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 03-060 | 25.02.19 | | AM-AOM-150793-3092 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 04-101 | 30.10.15 | | AM-AOM-150793-3092 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-143 | 30.05.17 | | AM-AOM-150793-3092 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 07-003 | 30.09.18 | | AM-AOM-150793-3092 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 10-021 | 01.03.17 | | AM-AOM-150793-3092 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 02.11.10 | 30.04.21 | AM-AOM-150793-3093 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 07.10.08 | 30.04.21 | AM-AOM-150793-3094 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 10.08.07 | 30.04.21 | AM-AOM-150793-3096 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 29.02.12 | 30.04.21 | AM-AOM-150793-3097 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 01.02.06 | 30.04.21 | AM-AOM-150793-3098 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 20.11.12 | 01.11.16 | AM-AOM-150793-3100 (PDF) | S | | Outdated / Edition: 20.08.2016 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 04-107 | 15.09.16 | | AM-AOM-150793-3100 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-150 | 01.12.16 | | AM-AOM-150793-3100 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 10-022 | 01.03.17 | | AM-AOM-150793-3100 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 01.02.06 | 30.04.21 | AM-AOM-150793-3101 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 15.06.11 | 30.04.21 | AM-AOM-150793-3104 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 02.08.10 | 30.04.21 | AM-AOM-150793-3106 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 22.05.17 | 30.04.21 | AM-AOM-150793-3109 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 02.04.15 | 30.04.21 | AM-AOM-150793-3110 (PDF) | S | | Edition: 28.06.2021 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 15.07.11 | 30.04.21 | AM-AOM-150793-3112 (PDF) | S | | Edition: 28.06.2021 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 06.12.11 | 30.04.21 | AM-AOM-150793-3113 (PDF) | S | | Edition: 28.06.2021 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 22.06.07 | 01.11.16 | AM-AOM-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 01-024 | 31.01.18 | | AM-AOM-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 01-027 | 31.01.18 | | AM-AOM-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 02-164 | 15.11.18 | | AM-AOM-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 03-065 | 25.02.19 | | AM-AOM-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 04-106 | 15.09.16 | | AM-AOM-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 04-110 | 31.01.17 | | AM-AOM-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 04-113 | 31.01.18 | | AM-AOM-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 04-124 | 30.04.18 | | AM-AOM-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-139 | 31.01.17 | | AM-AOM-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 05-151 | 30.05.17 | | AM-AOM-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 07-002 | 30.09.18 | | AM-AOM-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 09-111 | 31.01.17 | | AM-AOM-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 10-021 | 01.03.17 | | AM-AOM-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 22.06.07 | 30.04.21 | AM-AOM-150793-3117 (PDF) | S | | Edition: 19.01.2023 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 06.12.10 | 30.04.21 | AM-AOM-150793-3119 (PDF) | S | | Edition: 28.06.2021 | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 06.09.10 | 30.04.21 | AM-AOM-150793-AeroRescue (PDF) | S | | Edition: 28.06.2021 / S/N 3051, 3052, 3053, 3057, 3059 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 01.09.94 | 30.04.21 | AM-AOM-150793-ENV | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 02-167 | 15.11.18 | | AM-AOM-150793-ENV | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 02-168 | 15.11.18 | | AM-AOM-150793-ENV | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 02-169 | 15.11.18 | | AM-AOM-150793-ENV | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 02-170 | 15.11.18 | | AM-AOM-150793-ENV | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | AOM | 01.09.94 | 30.04.21 | AM-AOM-150793-ENV (PDF) | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 02-167 | 15.11.18 | | AM-AOM-150793-ENV (PDF) | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 02-168 | 15.11.18 | | AM-AOM-150793-ENV (PDF) | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 02-169 | 15.11.18 | | AM-AOM-150793-ENV (PDF) | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.1 | 328 SSG | TR 02-170 | 15.11.18 | | AM-AOM-150793-ENV (PDF) | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 01.09.94 | 01.09.12 | AM-AOM-150793-3036 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 01.09.94 | 01.12.21 | AM-AOM-150793-3073 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 17-002 | 31.05.22 | | AM-AOM-150793-3073 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 17.03.15 | 01.09.12 | AM-AOM-150793-3092 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 01.09.94 | 01.12.21 | AM-AOM-150793-ENV | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 01.09.94 | 01.12.21 | AM-AOM-150793-ENV (PDF) | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 17-002 | 31.05.22 | | AM-AOM-150793-X | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 17-002 | 31.05.22 | | AM-AOM-150793-X (PDF) | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 28.05.08 | 28.02.17 | AM-AOM-2-150793-3005 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 02-010 | 15.11.18 | | AM-AOM-2-150793-3005 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 20.07.07 | 30.07.21 | AM-AOM-2-150793-3006 (PDF) | S | | Edition: 16.09.2022 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 05.02.13 | 01.12.12 | AM-AOM-2-150793-3010 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 01-002 | 29.02.16 | | AM-AOM-2-150793-3010 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 13-007 | 16.11.15 | | AM-AOM-2-150793-3010 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-014 | 30.09.15 | | AM-AOM-2-150793-3010 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 03.11.14 | 30.07.21 | AM-AOM-2-150793-3013 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 05.05.08 | 01.12.12 | AM-AOM-2-150793-3014 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 01-002 | 29.02.16 | | AM-AOM-2-150793-3014 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 13-007 | 16.11.15 | | AM-AOM-2-150793-3014 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-017 | 30.10.15 | | AM-AOM-2-150793-3014 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 30.09.21 | 30.07.21 | AM-AOM-2-150793-3015 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 01.12.11 | 30.07.21 | AM-AOM-2-150793-3016 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 18.02.15 | 01.12.12 | AM-AOM-2-150793-3018 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 13-007 | 16.11.15 | | AM-AOM-2-150793-3018 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-017 | 30.10.15 | | AM-AOM-2-150793-3018 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 01.08.11 | 30.07.21 | AM-AOM-2-150793-3019 (PDF) | S | | Edition: 16.09.2022 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 18.01.16 | 30.07.21 | AM-AOM-2-150793-3020 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 30.11.12 | 01.12.12 | AM-AOM-2-150793-3021 (PDF) | S | | Outdated / Edition: 18.04.2017 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 01-002 | 29.02.16 | | AM-AOM-2-150793-3021 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 13-008 | 16.11.15 | | AM-AOM-2-150793-3021 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-010 | 25.03.12 | | AM-AOM-2-150793-3021 (PDF) | S | | Outdated | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-016 | 30.10.15 | | AM-AOM-2-150793-3021 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-024 | 30.09.16 | | AM-AOM-2-150793-3021 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 25.10.99 | 28.02.17 | AM-AOM-2-150793-3022 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 02-010 | 15.11.18 | | AM-AOM-2-150793-3022 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 25.10.99 | 28.02.17 | AM-AOM-2-150793-3023 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 02-010 | 15.11.18 | | AM-AOM-2-150793-3023 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 25.10.99 | 01.12.12 | AM-AOM-2-150793-3024 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 01-002 | 29.02.16 | | AM-AOM-2-150793-3024 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 13-007 | 16.11.15 | | AM-AOM-2-150793-3024 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-013 | 30.06.15 | | AM-AOM-2-150793-3024 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-014 | 30.09.15 | | AM-AOM-2-150793-3024 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-016 | 30.10.15 | | AM-AOM-2-150793-3024 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 14.10.16 | 30.07.21 | AM-AOM-2-150793-3025 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 16.08.11 | 30.07.21 | AM-AOM-2-150793-3026 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 27.03.20 | 28.02.17 | AM-AOM-2-150793-3027 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 02-010 | 15.11.18 | | AM-AOM-2-150793-3027 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-028 | 28.02.20 | | AM-AOM-2-150793-3027 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 16.08.11 | 30.07.21 | AM-AOM-2-150793-3031 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 15.09.11 | 29.04.05 | AM-AOM-2-150793-3033 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 06-001 | 12.03.09 | | AM-AOM-2-150793-3033 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 20-010 | 12.03.09 | | AM-AOM-2-150793-3033 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 25.10.99 | 01.12.12 | AM-AOM-2-150793-3034 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 01-002 | 29.02.16 | | AM-AOM-2-150793-3034 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 13-007 | 16.11.15 | | AM-AOM-2-150793-3034 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-013 | 30.06.15 | | AM-AOM-2-150793-3034 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-014 | 30.09.15 | | AM-AOM-2-150793-3034 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-016 | 30.10.15 | | AM-AOM-2-150793-3034 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 28.07.08 | 30.07.21 | AM-AOM-2-150793-3035 (PDF) | S | | Edition: 16.09.2022 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 26.06.13 | 01.12.12 | AM-AOM-2-150793-3039 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 13-007 | 16.11.15 | | AM-AOM-2-150793-3039 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-017 | 30.10.15 | | AM-AOM-2-150793-3039 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 01.09.12 | 30.07.21 | AM-AOM-2-150793-3040 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 23.04.13 | 30.07.21 | AM-AOM-2-150793-3047 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 28.03.13 | 30.07.21 | AM-AOM-2-150793-3050 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 20.03.06 | 28.02.17 | AM-AOM-2-150793-3051 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 02-011 | 15.11.18 | | AM-AOM-2-150793-3051 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 20.03.06 | 28.02.17 | AM-AOM-2-150793-3052 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 02-011 | 15.11.18 | | AM-AOM-2-150793-3052 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 25.10.99 | 30.07.21 | AM-AOM-2-150793-3053 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 25.07.14 | 28.02.17 | AM-AOM-2-150793-3055 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 02-011 | 15.11.18 | | AM-AOM-2-150793-3055 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 30.11.12 | 01.12.12 | AM-AOM-2-150793-3056 (PDF) | S | | Outdated / Edition: 18.04.2017 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 01-002 | 29.02.16 | | AM-AOM-2-150793-3056 (PDF) | S | | Outdated | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 13-007 | 16.11.15 | | AM-AOM-2-150793-3056 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-017 | 30.10.15 | | AM-AOM-2-150793-3056 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-024 | 30.09.16 | | AM-AOM-2-150793-3056 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 20.03.06 | 28.02.17 | AM-AOM-2-150793-3057 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 02-011 | 15.11.18 | | AM-AOM-2-150793-3057 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 06.12.10 | 30.07.21 | AM-AOM-2-150793-3058 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 20.03.06 | 30.07.21 | AM-AOM-2-150793-3059 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 01.09.12 | 30.07.21 | AM-AOM-2-150793-3060 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 30.11.12 | 30.07.21 | AM-AOM-2-150793-3061 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 27.04.15 | 30.07.21 | AM-AOM-2-150793-3063 (PDF) | S | | Edition: 16.09.2022 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 30.11.12 | 01.12.12 | AM-AOM-2-150793-3066 (PDF) | S | | Outdated / Edition: 02.11.2018 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 01-002 | 29.02.16 | | AM-AOM-2-150793-3066 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 13-007 | 16.11.15 | | AM-AOM-2-150793-3066 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-010 | 25.03.12 | | AM-AOM-2-150793-3066 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-016 | 30.10.15 | | AM-AOM-2-150793-3066 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-024 | 30.09.16 | | AM-AOM-2-150793-3066 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 15.07.11 | 30.07.21 | AM-AOM-2-150793-3068 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 30.04.13 | 01.12.12 | AM-AOM-2-150793-3070 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 01-002 | 29.02.16 | | AM-AOM-2-150793-3070 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 13-007 | 16.11.15 | | AM-AOM-2-150793-3070 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-010 | 25.03.12 | | AM-AOM-2-150793-3070 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-013 | 30.06.15 | | AM-AOM-2-150793-3070 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-014 | 30.09.15 | | AM-AOM-2-150793-3070 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-017 | 30.10.15 | | AM-AOM-2-150793-3070 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-024 | 30.09.16 | | AM-AOM-2-150793-3070 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 09.12.14 | 30.07.21 | AM-AOM-2-150793-3072 (PDF) | S | | Edition: 16.09.2022 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 01.12.11 | 30.07.21 | AM-AOM-2-150793-3075 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 28.09.11 | 30.07.21 | AM-AOM-2-150793-3077 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 25.10.99 | 30.07.21 | AM-AOM-2-150793-3078 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 25.10.99 | 30.07.21 | AM-AOM-2-150793-3083 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 26.06.13 | 01.12.12 | AM-AOM-2-150793-3084 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 13-007 | 16.11.15 | | AM-AOM-2-150793-3084 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-017 | 30.10.15 | | AM-AOM-2-150793-3084 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 25.01.11 | 30.07.21 | AM-AOM-2-150793-3085 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 25.06.15 | 30.07.21 | AM-AOM-2-150793-3086 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 17.05.06 | 30.07.21 | AM-AOM-2-150793-3087 (PDF) | S | | Edition: 16.09.2022 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 25.10.99 | 30.07.21 | AM-AOM-2-150793-3088 (PDF) | S | | Edition: 27.10.2022 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 30.04.13 | 30.07.21 | AM-AOM-2-150793-3089 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 13.08.07 | 30.07.21 | AM-AOM-2-150793-3090 (PDF) | S | | Edition: 16.09.2022 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 06.10.09 | 30.07.21 | AM-AOM-2-150793-3091 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 02.11.10 | 30.07.21 | AM-AOM-2-150793-3093 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 07.10.08 | 30.07.21 | AM-AOM-2-150793-3094 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 25.10.99 | 30.07.21 | AM-AOM-2-150793-3096 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 23.06.05 | 30.07.21 | AM-AOM-2-150793-3097 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 25.10.99 | 30.07.21 | AM-AOM-2-150793-3098 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 20.11.12 | 01.12.12 | AM-AOM-2-150793-3100 (PDF) | S | | Outdated / Edition: 18.04.2017 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 01-002 | 29.02.16 | | AM-AOM-2-150793-3100 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-010 | 25.03.12 | | AM-AOM-2-150793-3100 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-014 | 30.09.15 | | AM-AOM-2-150793-3100 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-017 | 25.03.12 | | AM-AOM-2-150793-3100 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-024 | 30.09.16 | | AM-AOM-2-150793-3100 (PDF) | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 25.10.99 | 30.07.21 | AM-AOM-2-150793-3101 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 15.06.11 | 30.07.21 | AM-AOM-2-150793-3104 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 02.08.10 | 30.07.21 | AM-AOM-2-150793-3106 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 22.05.17 | 30.07.21 | AM-AOM-2-150793-3109 | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 02.04.15 | 30.07.21 | AM-AOM-2-150793-3110 (PDF) | S | | Edition: 16.09.2022 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 15.07.11 | 30.07.21 | AM-AOM-2-150793-3112 (PDF) | S | | Edition: 16.09.2022 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 25.10.99 | 30.07.21 | AM-AOM-2-150793-3113 (PDF) | S | | Edition: 16.09.2022 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 25.10.99 | 01.12.12 | AM-AOM-2-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 01-002 | 29.02.16 | | AM-AOM-2-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 13-007 | 16.11.15 | | AM-AOM-2-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-010 | 25.03.12 | | AM-AOM-2-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-013 | 30.06.15 | | AM-AOM-2-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-014 | 30.09.15 | | AM-AOM-2-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-017 | 30.10.15 | | AM-AOM-2-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 16-024 | 30.09.16 | | AM-AOM-2-150793-3115 | S | | Outdated | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 22.07.07 | 30.07.21 | AM-AOM-2-150793-3117 (PDF) | S | | Edition: 16.09.2022 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 06.12.10 | 30.07.21 | AM-AOM-2-150793-3119 (PDF) | S | | Edition: 16.09.2022 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 06.09.10 | 30.07.21 | AM-AOM-2-150793-AeroRescue (PDF) | S | | Edition: 26.09.2022 / S/N 3053 | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 25.10.99 | 30.07.21 | AM-AOM-2-150793-ENV | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | AOM | 25.10.99 | 30.07.21 | AM-AOM-2-150793-ENV (PDF) | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 17-002 | 31.05.22 | | AM-AOM-2-150793-X | S | | | 3P |
| | Airpl. Operat. Manual (AOM) Vol.2 | 328 SSG | TR 17-002 | 31.05.22 | | AM-AOM-2-150793-X (PDF) | S | | | 3P |
| | Airworthiness Limit. Doc. (ALD) | 328 SSG | ALD | 01.06.93 | 17 31.07.19 | TM-ALD-010693-ALL | S | | | 3P |
| | Airworthiness Limit. Doc. (ALD) | 328 SSG | TR ALD-126 | 10.12.18 | | TM-ALD-010693-ALL | S | | | 3P |
| | Airworthiness Limit. Doc. (ALD) | 328 SSG | TR ALD-138 | 12.05.22 | | TM-ALD-010693-ALL | | | | 3P |
| | Airworthiness Limit. Doc. (ALD) | 328 SSG | TR ALD-139 | 12.05.22 | | TM-ALD-010693-ALL | | | | 3P |
| | AMM Cold Weather Operat. (AMMC) | 328 SSG | AMMC | 15.11.95 | 1 01.03.19 | TM-AMMC-151195-ALL | O | | | 3P |
| | APU Logbook | 328 SSG | Service Tech. | | | 348-3 | S | | | 3A |
| | CAMSIS 3 CD-ROM DO328 | 328 SSG | CAMSIS | 01.03.23 | | IM-COM-301098-ENV | O | | CD-ROM | 3P |
| | CAMSIS 3 Operating Manual | 328 SSG | COM | 04.03.04 | 4 01.03.23 | TM-COM-040304-ALL | O | | | 3A |
| | Certific.Maint.Require.Doc. (CMR) | 328 SSG | CMR | 01.07.93 | 13 30.04.07 | TM-CMR-010793-ALL | S | | | 3P |
| Inlet Header Tank Assy | Comp. Maint. Man. Manuf. (CMMM) | 328 SSG | CMMM | 05.02.01 | 1 15.03.04 | TM-CMMM-010598-ALL | S | | | 3A |
| Insulation Kit | Comp. Maint. Man. Manuf. (CMMM) | 328 SSG | CMMM | 01.09.17 | | TM-CMMM-010917-ALL | S | | | 3A |
| Hyd.Main Reserv. | Comp. Maint. Man. Manuf. (CMMM) | 328 SSG | CMMM | 01.12.04 | 1 15.03.17 | TM-CMMM-011204-100 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. | / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Hand Ctr. Unit | Comp. Maint. Man. Manuf. (CMMM) | 328 SSG | CMMM | 10.10.97 | 4 | 01.06.16 | TM-CMMM-101097-ALL | S | | | 3A |
| Eng. Contr. Box | Comp. Maint. Man. Manuf. (CMMM) | 328 SSG | CMMM | 12.06.98 | 3 | 01.10.19 | TM-CMMM-120698-ALL | S | | | 3P |
| Tail Co.w.Ex.Du | Comp. Maint. Man. Manuf. (CMMM) | 328 SSG | CMMM | 15.07.98 | | | TM-CMMM-150798-ALL | O | | MFR Overh. Only | 3P |
| NWS Harness | Comp. Maint. Man. Manuf. (CMMM) | 328 SSG | CMMM | 24.03.16 | | | TM-CMMM-240316-ALL | O | | MFR Overh. Only | 3P |
| Air inlet duct | Comp. Maint. Man. Manuf. (CMMM) | 328 SSG | CMMM | 30.01.98 | | | TM-CMMM-300198-ALL | O | | MFR Overh. Only | 3P |
| S-Duct Assy | Comp. Maint. Man. Manuf. (CMMM) | 328 SSG | CMMM | 05.02.01 | 1 | 15.03.04 | TM-CMMM-300198-ALL-1 | S | | | 3A |
| Outlet Deflector | Comp. Maint. Man. Manuf. (CMMM) | 328 SSG | CMMM | 15.11.04 | | | TM-CMMM-300198-ALL-2 | S | | | 3A |
| Pass./Crew Door | Comp. Maint. Man. Manuf. (CMMM) | 328 SSG | CMMM | 30.04.93 | 5 | 28.04.23 | TM-CMMM-300493-ALL-1 | S | R | | 3A |
| Cargo Door | Comp. Maint. Man. Manuf. (CMMM) | 328 SSG | CMMM | 30.04.93 | 5 | 01.10.21 | TM-CMMM-300493-ALL-2 | S | | | 3A |
| Service Door | Comp. Maint. Man. Manuf. (CMMM) | 328 SSG | CMMM | 30.04.93 | 5 | 01.10.21 | TM-CMMM-300493-ALL-3 | S | | | 3A |
| Roll- & Flightspoiler | Comp. Maint. Man. Manuf. (CMMM) | 328 SSG | CMMM | 30.11.16 | | | TM-CMMM-301116-ALL | O | | MFR Overh. Only | 3A |
| | Comp.Configuration Manual (CM) | 328 SSG | CM | 01.10.96 | | | TM-CM-011096-ALL | O | | | 3P |
| | Comp.Configuration Manual (CM) | 328 SSG | TR 31-001 | 17.11.97 | | | TM-CM-011096-ALL | O | | | 3P |
| | Comp.Configuration Manual (CM) | 328 SSG | TR 31-002 | 17.11.97 | | | TM-CM-011096-ALL | O | | | 3P |
| | Comp.Configuration Manual (CM) | 328 SSG | TR 31-003 | 04.02.98 | | | TM-CM-011096-ALL | O | | | 3P |
| | Comp.Configuration Manual (CM) | 328 SSG | TR 31-004 | 02.03.98 | | | TM-CM-011096-ALL | O | | | 3P |
| | Comp.Configuration Manual (CM) | 328 SSG | TR 31-005 | 02.03.98 | | | TM-CM-011096-ALL | O | | | 3P |
| | Comp.Configuration Manual (CM) | 328 SSG | TR 31-006 | 24.06.98 | | | TM-CM-011096-ALL | O | | | 3P |
| | Component Repair Manual (CRM) | 328 SSG | CRM | 05.10.01 | 2 | 29.10.04 | TM-CRM-051001-ALL | S | | | 3A |
| | Component Repair Manual (CRM) | 328 SSG | TR 25-001 | 01.04.19 | | | TM-CRM-051001-ALL | S | | | 3A |
| | Consumable Material List (CML) | 328 SSG | CML | 30.04.93 | 39 | 01.03.22 | TM-CML-300493-ALL | S | | | 3A |
| | Corr.Prevent.a.Contr.Prog.Man. (CPCP) | 328 SSG | CPCP | 20.08.97 | 5 | 01.09.20 | TM-CPCP-200897-ALL | S | | | 3P |
| | Corr.Prevent.a.Contr.Prog.Man. (CPCP) | 328 SSG | TR 53-033 | 30.01.21 | | | TM-CPCP-200897-ALL | S | | | 3P |
| V 2.4.3.0 | CRETA-Reduced Thrust Takeoff | 328 SSG | CRETA | 04.08.03 | | | CRETA-RTTO | S | | CD-ROM | 3A |
| V 2.4.2.2 | CRETA-Regulated Weight Program | 328 SSG | CRETA | 21.12.98 | | 08.03.02 | CRETA | S | | CD-ROM | 3A |
| | Customer Support Manual (CSM) | 328 SSG | CSM | 30.06.04 | 2019/ 1 | 18.04.19 | IM-CSM-260696-ALL | S | | | 3A |
| | Delivery Record | 328 SSG | Service Tech. | | | | 348-4 | S | | | 3A |
| | Dispatsch Deviation Procedure Guide (DDPG) | 328 SSG | DDPG | 01.09.97 | 1 | 01.03.99 | TM-DDPG-200995-FAA | S | | | 3P |
| | Dispatsch Deviation Procedure Guide (DDPG) | 328 SSG | TR 26-001 | 15.09.00 | | | TM-DDPG-200995-FAA | S | | | 3P |
| | Dispatsch Deviation Procedure Guide (DDPG) | 328 SSG | TR 26-002 | 15.09.00 | | | TM-DDPG-200995-FAA | S | | | 3P |
| | Dispatsch Deviation Procedure Guide (DDPG) | 328 SSG | TR 27-001 | 22.05.00 | | | TM-DDPG-200995-FAA | S | | | 3P |
| | Dispatsch Deviation Procedure Guide (DDPG) | 328 SSG | TR 32-001 | 13.11.00 | | | TM-DDPG-200995-FAA | S | | | 3P |
| | Dispatsch Deviation Procedure Guide (DDPG) | 328 SSG | TR 32-003 | 14.12.01 | | | TM-DDPG-200995-FAA | S | | | 3P |
| | Dispatsch Deviation Procedure Guide (DDPG) | 328 SSG | TR 34-001 | 24.07.01 | | | TM-DDPG-200995-FAA | S | | | 3P |
| | Dispatsch Deviation Procedure Guide (DDPG) | 328 SSG | TR 36-003 | 22.02.02 | | | TM-DDPG-200995-FAA | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. | / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | DOMEX-plus Exchange Order | 328 SSG | Form | | | | 100005 | O | | | 3P |
| | Dornier 328 ASB, SB, SI, CI, AOT | 328 SSG | Service Tech. | | | | ISTI Complete Set DO328 | S | | | 3P |
| | Dornier 328 Standard Specification | 328 SSG | SPEC | 01.08.04 | | | IM-SPEC-010804-PROP | S | | | 3P |
| Version 1.2 | Engine Exceedance Rec.Progr. ELEX 328 | 328 SSG | ELEX | 08.08.98 | | | IM-ELEX-080898-ALL | O | | DISKETTE | 3P |
| | Engine Logbook | 328 SSG | Service Tech. | | | | 348-1 | S | | | 3A |
| | Fatig.Critical Basel./Alt.Struct.Man./Rep.Eval.Guidel. | 328 SSG | FCB/ASM - REG | 28.02.22 | | | IM-COM-010710-100-ALL | O | | CD-ROM | 3P |
| | Fatig.Critical Basel./Alt.Struct.Manual (FCB/ASM) | 328 SSG | FCB/ASM | 01.07.09 | | 28.02.22 | TM-FCB/ASM-010709-100-ALL | S | | | 3P |
| 001U454A3070000 | Fatigue Monitoring Software DOLIMONi | 328 SSG | CMMM | 30.01.01 | 1 | 10.08.01 | TM-CMMM-300101-ALL | S | | | 3A |
| | Fault Isolation Manual (FIM) | 328 SSG | FIM | 01.03.08 | 6 | 01.03.19 | TM-FIM-300493-ADA | S | | Outdated | 3P |
| | Fault Isolation Manual (FIM) | 328 SSG | FIM | 04.03.04 | 5 | 01.09.11 | TM-FIM-300493-ADNB | S | | Outdated | 3P |
| | Fault Isolation Manual (FIM) | 328 SSG | FIM | 01.03.05 | 3 | 01.09.11 | TM-FIM-300493-AWI | S | | Outdated | 3P |
| | Fault Isolation Manual (FIM) | 328 SSG | FIM | 10.12.93 | 17 | 01.03.20 | TM-FIM-300493-ENV | S | | | 3P |
| | Fault Isolation Manual (FIM) | 328 SSG | FIM | 01.03.08 | 1 | 01.09.11 | TM-FIM-300493-EXECU | S | | Outdated | 3P |
| | Fault Isolation Manual (FIM) | 328 SSG | FIM | 15.02.95 | 11 | 01.09.11 | TM-FIM-300493-SAY | S | | Outdated | 3P |
| | Ground Hand.a.Serv. Info. Man. (GHSIM) | 328 SSG | GHSIM | 01.09.11 | 3 | 01.03.22 | TM-GHSIM-301093-ALL | O | | | 3P |
| | Illustrated Tool and Equipment Manual (ITEM) | 328 SSG | ITEM | 01.09.14 | 1 | 01.06.22 | TM-ITEM-010914-ALL | S | | Supersedes TM-ITEM-300493-ALL & TM-ITEM-010699-ALL | 3A |
| | LETTER BINDER & TABS | 328 SSG | BINDER | | | | LETTER BINDER & TABS | O | | | 3A |
| | Low Utilization Maint.Plann.Data (LUMPD) | 328 SSG | LUMPD | 01.08.15 | | | IM-LUMPD-280194-ALL | S | | CD-ROM / Discontinued see CSI-328all-2018-02 | 3P |
| | Low Utilization Maint.Plann.Doc.(LUMPD) | 328 SSG | LUMPD | 28.01.94 | 16 | 01.08.15 | TM-LUMPD-280194-ALL | S | | Discontinued see CSI-328all-2018-02 | 3P |
| | Low Utilization Maint.Plann.Doc.(LUMPD) | 328 SSG | TR LUMPD-115 | 01.03.16 | | | TM-LUMPD-280194-ALL | S | | Discontinued see CSI-328all-2018-02 | 3P |
| | Low Utilization Maint.Plann.Doc.(LUMPD) | 328 SSG | TR LUMPD-117 | 30.04.16 | | | TM-LUMPD-280194-ALL | S | | Discontinued see CSI-328all-2018-02 | 3P |
| | Low Utilization Maint.Plann.Doc.(LUMPD) | 328 SSG | TR LUMPD-118 | 01.06.16 | | | TM-LUMPD-280194-ALL | S | | Discontinued see CSI-328all-2018-02 | 3P |
| | Low Utilization Maint.Plann.Doc.(LUMPD) | 328 SSG | TR LUMPD-120 | 15.07.16 | | | TM-LUMPD-280194-ALL | S | | Discontinued see CSI-328all-2018-02 | 3P |
| | Low Utilization Maint.Plann.Doc.(LUMPD) | 328 SSG | TR LUMPD-121 | 15.07.16 | | | TM-LUMPD-280194-ALL | S | | Discontinued see CSI-328all-2018-02 | 3P |
| | Low Utilization Maint.Plann.Doc.(LUMPD) | 328 SSG | TR LUMPD-124 | 30.11.16 | | | TM-LUMPD-280194-ALL | S | | Discontinued see CSI-328all-2018-02 | 3P |
| | Low Utilization Maint.Plann.Doc.(LUMPD) | 328 SSG | TR LUMPD-125 | 01.01.17 | | | TM-LUMPD-280194-ALL | S | | Discontinued see CSI-328all-2018-02 | 3P |
| | Low Utilization Maint.Plann.Doc.(LUMPD) | 328 SSG | TR LUMPD-127 | 30.09.18 | | | TM-LUMPD-280194-ALL | S | | Discontinued see CSI-328all-2018-02 | 3P |
| | Low Utilization Maint.Plann.Doc.(LUMPD) | 328 SSG | TR LUMPD-128 | 30.09.18 | | | TM-LUMPD-280194-ALL | S | | Discontinued see CSI-328all-2018-02 | 3P |
| | Low Utilization Maint.Plann.Doc.(LUMPD) | 328 SSG | TR LUMPD-129 | 30.09.18 | | | TM-LUMPD-280194-ALL | S | | Discontinued see CSI-328all-2018-02 | 3P |
| | Low Utilization Maint.Plann.Doc.(LUMPD) | 328 SSG | TR LUMPD-130 | 20.05.18 | | | TM-LUMPD-280194-ALL | S | | Discontinued see CSI-328all-2018-02 | 3P |
| | Low Utilization Maint.Plann.Doc.(LUMPD) | 328 SSG | TR LUMPD-131 | 30.09.18 | | | TM-LUMPD-280194-ALL | S | | Discontinued see CSI-328all-2018-02 | 3P |
| | Low Utilization Maint.Plann.Doc.(LUMPD) | 328 SSG | TR LUMPD-132 | 01.11.18 | | | TM-LUMPD-280194-ALL | S | | Discontinued see CSI-328all-2018-02 | 3P |
| | Low Utilization Maint.Plann.Doc.(LUMPD) | 328 SSG | TR LUMPD-134 | 01.11.18 | | | TM-LUMPD-280194-ALL | S | | Discontinued see CSI-328all-2018-02 | 3P |
| | Low Utilization Maint.Plann.Doc.(LUMPD) | 328 SSG | TR LUMPD-136 | 01.01.19 | | | TM-LUMPD-280194-ALL | S | | Discontinued see CSI-328all-2018-02 | 3P |
| | Low Utilization Maint.Plann.Doc.(LUMPD) | 328 SSG | TR LUMPD-137 | 01.01.19 | | | TM-LUMPD-280194-ALL | S | | Discontinued see CSI-328all-2018-02 | 3P |
| | Low Utilization Maint.Plann.Doc.(LUMPD) | 328 SSG | TR LUMPD-138 | 30.04.19 | | | TM-LUMPD-280194-ALL | S | | Discontinued see CSI-328all-2018-02 | 3P |
| | Low Utilization Maint.Plann.Doc.(LUMPD) | 328 SSG | TR LUMPD-139 | 30.04.19 | | | TM-LUMPD-280194-ALL | S | | Discontinued see CSI-328all-2018-02 | 3P |
| | Maint. Requirements Document (MRD) | 328 SSG | MRD | 15.01.02 | 2 | 15.06.08 | TM-MRD-150102-ALL | S | | | 3P |
| | Maint. Review Board Report (MRB) | 328 SSG | MRB | 30.09.93 | 12 | 31.05.19 | TM-MRB-010693-ALL | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. | / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | Maint. Review Board Report (MRB) | 328 SSG | TR MRB-161 | 01.04.20 | | | TM-MRB-010693-ALL | S | | | 3P |
| | Maint. Review Board Report (MRB) | 328 SSG | TR MRB-162 | 02.12.19 | | | TM-MRB-010693-ALL | S | | | 3P |
| | Maint. Review Board Report (MRB) | 328 SSG | TR MRB-163 | 01.04.20 | | | TM-MRB-010693-ALL | S | | | 3P |
| | Maint. Review Board Report (MRB) | 328 SSG | TR MRB-164 | 31.07.20 | | | TM-MRB-010693-ALL | S | | | 3P |
| | Maint. Review Board Report (MRB) | 328 SSG | TR MRB-165 | 26.02.21 | | | TM-MRB-010693-ALL | S | | | 3P |
| | Maint. Review Board Report (MRB) | 328 SSG | TR MRB-166 | 30.09.21 | | | TM-MRB-010693-ALL | S | | | 3P |
| | Maintenance Planning Data (MPD) | 328 SSG | MPD | 01.08.19 | | | IM-MPD-300994-ALL | S | | CD-ROM | 3P |
| | Maintenance Planning Document (MPD) | 328 SSG | MPD | 30.09.94 | 18 | 01.08.19 | TM-MPD-300994-ALL | S | | | 3P |
| | Maintenance Planning Document (MPD) | 328 SSG | TR MPD-158 | 10.12.18 | | | TM-MPD-300994-ALL | S | | | 3P |
| | Maintenance Planning Document (MPD) | 328 SSG | TR MPD-162 | 01.04.20 | | | TM-MPD-300994-ALL | S | | | 3P |
| | Maintenance Planning Document (MPD) | 328 SSG | TR MPD-163 | 02.12.19 | | | TM-MPD-300994-ALL | S | | | 3P |
| | Maintenance Planning Document (MPD) | 328 SSG | TR MPD-164 | 01.04.20 | | | TM-MPD-300994-ALL | S | | | 3P |
| | Maintenance Planning Document (MPD) | 328 SSG | TR MPD-165 | 31.07.20 | | | TM-MPD-300994-ALL | S | | | 3P |
| | Maintenance Planning Document (MPD) | 328 SSG | TR MPD-166 | 20.09.20 | | | TM-MPD-300994-ALL | S | | | 3P |
| | Maintenance Planning Document (MPD) | 328 SSG | TR MPD-167 | 26.02.21 | | | TM-MPD-300994-ALL | S | | | 3P |
| | Maintenance Planning Document (MPD) | 328 SSG | TR MPD-168 | 30.04.21 | | | TM-MPD-300994-ALL | S | | | 3P |
| | Maintenance Planning Document (MPD) | 328 SSG | TR MPD-169 | 30.09.21 | | | TM-MPD-300994-ALL | S | | | 3P |
| | Master Mini. Equip. List (MMEL) | 328 SSG | MMEL | 01.04.10 | 2 | 01.10.13 | AM-MMEL-010410-EASA | S | | replaces AM-MMEL-300993-JAA | 3P |
| | Master Mini. Equip. List (MMEL) | 328 SSG | TR 00-001 | 31.03.14 | | | AM-MMEL-010410-EASA | S | | | 3P |
| | Master Mini. Equip. List (MMEL) | 328 SSG | TR 21-001 | 15.10.19 | | | AM-MMEL-010410-EASA | S | | | 3P |
| | Master Mini. Equip. List (MMEL) | 328 SSG | TR 23-002 | 15.03.19 | | | AM-MMEL-010410-EASA | S | | | 3P |
| | Master Mini. Equip. List (MMEL) | 328 SSG | TR 31-001 | 30.10.17 | | | AM-MMEL-010410-EASA | S | | | 3P |
| | Master Mini. Equip. List (MMEL) | 328 SSG | TR 34-002 | 26.01.16 | | | AM-MMEL-010410-EASA | S | | | 3P |
| | Master Mini. Equip. List (MMEL) | 328 SSG | TR 34-004 | 30.11.17 | | | AM-MMEL-010410-EASA | S | | | 3P |
| | Master Mini. Equip. List (MMEL) | 328 SSG | TR 34-005 | 15.03.19 | | | AM-MMEL-010410-EASA | S | | | 3P |
| | Master Mini. Equip. List MMEL-FAA | 328 SSG | MMEL | 30.09.93 | 4 | 25.11.98 | AM-MMEL-300993-ALL-F | S | | FAA | 3P |
| | Non-Destr. Testing Manual (NTM) | 328 SSG | NTM | 30.04.93 | 3 | 30.07.20 | TM-NTM-300493-ALL | S | | | 3P |
| | Operating Instruction For Ferry Flight (OIFF) | 328 SSG | OIFF | 20.02.95 | | | AM-OIFF-200295-ENV | S | | | 3P |
| | Policy and Procedures Handbook (PPH) | 328 SSG | PPH | 01.07.18 | 2 | 02.11.21 | TM-PPH-010118-ALL | O | | Supersedes TM-PPH-010613-ALL & TM-PPH-150198-ALL & TM-PPH-010191-ALL | 3A |
| | Power Plant Build-up Man. (PPBM) | 328 SSG | PPBM | 30.10.93 | 18 | 01.03.22 | TM-PPBM-300493-ALL | S | | | 3P |
| | Propeller Logbook | 328 SSG | Service Tech. | | | | 348-2 | S | | | 3P |
| | Publications Index DO328 (PI) | 328 SSG | INDEX | 08.10.93 | 348 | 30.05.23 | IM-PI-081093-ALL | S | R | from now on only available on www.deutscheaircraft.com | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 31.05.18 | QRH-328-3005 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.22 | QRH-328-3006 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.22 | QRH-328-3006 (PDF) | S | | Edition: 01.03.2023 | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 29.01.16 | QRH-328-3010 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 03.11.14 | | 30.11.22 | QRH-328-3013 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 29.01.16 | QRH-328-3014 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 20.09.21 | | 30.11.22 | QRH-328-3015 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.22 | QRH-328-3016 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 18.02.15 | 29.01.16 | QRH-328-3018 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 30.11.22 | QRH-328-3019 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 18.01.16 | 30.11.22 | QRH-328-3020 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 29.01.16 | QRH-328-3021 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 30.11.19 | QRH-328-3022 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 30.11.19 | QRH-328-3023 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 29.01.16 | QRH-328-3024 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 14.10.16 | 30.11.22 | QRH-328-3025 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 30.11.22 | QRH-328-3026 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 27.03.20 | 31.05.18 | QRH-328-3027 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 30.11.22 | QRH-328-3031 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 01.07.11 | QRH-328-3033 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 29.01.16 | QRH-328-3034 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 30.11.22 | QRH-328-3035 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 30.11.22 | QRH-328-3035 (PDF) | S | | Edition: 01.03.2023 | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 07.01.14 | QRH-328-3036 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 26.06.13 | 29.01.16 | QRH-328-3039 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 01.09.12 | 30.11.22 | QRH-328-3040 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 23.04.13 | 30.11.22 | QRH-328-3047 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 28.03.13 | 30.11.22 | QRH-328-3050 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 30.11.19 | QRH-328-3051 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 30.11.19 | QRH-328-3052 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 30.11.22 | QRH-328-3053 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 25.07.14 | 30.11.19 | QRH-328-3055 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 29.01.16 | QRH-328-3056 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 30.11.19 | QRH-328-3057 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 30.11.22 | QRH-328-3058 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 30.11.22 | QRH-328-3059 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 01.09.12 | 30.11.22 | QRH-328-3060 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 30.11.22 | QRH-328-3061 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 27.04.15 | 30.11.22 | QRH-328-3063 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 29.01.16 | QRH-328-3066 (PDF) | S | | Outdated / Edition: 02.11.2018 | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 30.11.22 | QRH-328-3068 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 09.12.14 | 30.11.22 | QRH-328-3072 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 30.11.22 | QRH-328-3073 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 30.11.22 | QRH-328-3075 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 30.11.22 | QRH-328-3077 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 30.11.22 | QRH-328-3078 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 30.11.19 | QRH-328-3083 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 26.06.13 | 31.05.18 | QRH-328-3084 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 01.09.12 | 30.11.22 | QRH-328-3085 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 25.06.15 | 30.11.22 | QRH-328-3086 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | 30.11.22 | QRH-328-3087 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. | / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.22 | QRH-328-3088 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.22 | QRH-328-3089 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.22 | QRH-328-3090 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.22 | QRH-328-3091 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 17.03.15 | | 31.05.18 | QRH-328-3092 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.22 | QRH-328-3093 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.22 | QRH-328-3094 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.22 | QRH-328-3096 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 15.03.12 | | 30.11.22 | QRH-328-3097 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.19 | QRH-328-3098 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 30.11.12 | | 29.01.16 | QRH-328-3100 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.19 | QRH-328-3101 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.22 | QRH-328-3104 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.22 | QRH-328-3106 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 22.05.17 | | 30.11.22 | QRH-328-3109 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 02.04.15 | | 30.11.22 | QRH-328-3110 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 02.04.15 | | 30.11.22 | QRH-328-3110 (PDF) | S | | Edition: 01.03.2023 | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.22 | QRH-328-3112 | S | R | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.22 | QRH-328-3112 (PDF) | S | | Edition: 01.03.2023 | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.22 | QRH-328-3113 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 31.05.18 | QRH-328-3115 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.22 | QRH-328-3117 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.22 | QRH-328-3119 | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 29.03.18 | | 29.01.16 | QRH-328-AeronautX | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 31.05.18 | QRH-328-AeroRescue (PDF) | S | | Outdated / Edition: 25.02.2019 / S/N 3051, 3052, 3057, 3059 | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.22 | QRH-328-ENV | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.22 | QRH-328-ENV (PDF) | S | | | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 01.07.11 | QRH-328-SIM PROP | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 01.07.11 | QRH-328-SIM PROP 1 | S | | Outdated | 3P |
| | Quick Reference Handbook (QRH) | 328 SSG | QRH | 04.02.00 | | 30.11.22 | QRH-328-SNCORP | S | | | 3P |
| | Repair Evaluation Guidelines (REG) | 328 SSG | REG | 01.09.09 | | 28.02.22 | TM-REG-010909-100-ALL | S | | | 3P |
| | Rescue Manual (RM) | 328 SSG | RM | 10.08.96 | | | AM-RM-010896-ENV | S | | | 3P |
| | Safety Instruct.Cards DO328/328JET | 328 SSG | SIC | | | | SIC-328JET/PROP | O | | | 3A |
| | Spare Parts Price List (SPPL) | 328 SSG | SPPL | 01.07.00 | | | IM-SPPL-XXXXXX- | S | | | 3A |
| | SPR - Service Problem Report | 328 SSG | Form | | | | 1000032 | S | | | 3A |
| | Structural Repair Manual (SRM) | 328 SSG | SRM | 30.04.93 | 11 | 01.05.20 | TM-SRM-300493-ALL | S | | | 3P |
| | Structural Repair Manual (SRM) | 328 SSG | TR 51-142 | 31.08.20 | | | TM-SRM-300493-ALL | S | | | 3P |
| | Structural Repair Manual (SRM) | 328 SSG | TR 53-125 | 30.01.21 | | | TM-SRM-300493-ALL | S | | | 3P |
| | System Schematics Manual (SSM) | 328 SSG | SSM | 01.03.08 | 6 | 01.03.19 | TM-SSM-010693-ADA | S | | | 3P |
| | System Schematics Manual (SSM) | 328 SSG | SSM | 04.09.04 | 5 | 01.03.19 | TM-SSM-010693-ADNB | S | | | 3P |
| | System Schematics Manual (SSM) | 328 SSG | SSM | 01.09.14 | 3 | 01.03.19 | TM-SSM-010693-AFEX | S | | | 3P |
| | System Schematics Manual (SSM) | 328 SSG | SSM | 01.09.16 | 1 | 01.03.19 | TM-SSM-010693-EAGLE | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | System Schematics Manual (SSM) | 328 SSG | SSM | 15.02.94 | 15 01.03.19 | TM-SSM-010693-ENV | S | | | 3P |
| | System Schematics Manual (SSM) | 328 SSG | SSM | 01.03.08 | 1 01.09.11 | TM-SSM-010693-EXECU | S | | Outdated | 3P |
| | System Schematics Manual (SSM) | 328 SSG | SSM | 04.09.04 | 5 01.03.19 | TM-SSM-010693-PEARL | S | | | 3P |
| | System Schematics Manual (SSM) | 328 SSG | SSM | 01.08.95 | 11 01.03.19 | TM-SSM-010693-SAY | S | | | 3P |
| | System Schematics Manual (SSM) | 328 SSG | SSM | 04.09.04 | 1 01.09.11 | TM-SSM-010693-SUS | S | | Outdated | 3P |
| | System Schematics Manual (SSM) | 328 SSG | SSM | 10.08.96 | 5 01.09.11 | TM-SSM-010693-TAA | S | | Outdated | 3P |
| | Vendor Information Manual (VIM) | 328 SSG | VIM | 31.07.93 | 2 01.10.01 | IM-VIM-310793-ALL | O | | | 3P |
| | Warranty, Exchange, Repair Appl. | 328 SSG | Appl. Form | | | 100004 | S | | | 3A |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 19.07.93 | 5 01.10.18 | TM-WBM-190793-3005 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 12.01.94 | 6 01.10.18 | TM-WBM-190793-3006 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 12.01.94 | 2 30.05.00 | TM-WBM-190793-3010 | S | | Outdated | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 03.11.14 | 1 01.10.18 | TM-WBM-190793-3013 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 12.01.94 | 2 30.05.00 | TM-WBM-190793-3014 | S | | Outdated | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 20.09.21 | 0 01.10.18 | TM-WBM-190793-3015 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 19.07.93 | 4 01.10.18 | TM-WBM-190793-3016 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 15.04.15 | 0 01.03.12 | TM-WBM-190793-3018 | S | | Outdated | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-063 | 01.08.14 | | TM-WBM-190793-3019 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-064 | 01.08.14 | | TM-WBM-190793-3019 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-065 | 01.08.14 | | TM-WBM-190793-3019 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 04.08.14 | 1 01.10.18 | TM-WBM-190793-3019 (PDF) | S | | Edition: 25.03.2022 | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 18.01.16 | 1 01.10.18 | TM-WBM-190793-3020 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 20.02.97 | 4 05.12.04 | TM-WBM-190793-3021 | S | | Outdated | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 11.11.96 | 2 01.10.18 | TM-WBM-190793-3022 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 08.08.95 | 2 01.10.18 | TM-WBM-190793-3023 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 07.11.94 | 1 10.10.06 | TM-WBM-190793-3024 | S | | Outdated | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 14.10.16 | 1 01.10.18 | TM-WBM-190793-3025 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 21.11.94 | 4 01.10.18 | TM-WBM-190793-3026 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 27.03.20 | 0 01.10.18 | TM-WBM-190793-3027 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 06.11.95 | 1 29.05.07 | TM-WBM-190793-3028 | S | | Outdated | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 21.11.94 | 6 01.10.18 | TM-WBM-190793-3031 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 02.11.11 | | TM-WBM-190793-3033 | S | | Outdated | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 07.11.94 | 1 10.10.06 | TM-WBM-190793-3034 | S | | Outdated | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 21.11.94 | 4 01.10.18 | TM-WBM-190793-3035 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 10.10.95 | 2 03.12.01 | TM-WBM-190793-3036 | S | | Outdated | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 06.11.95 | 2 26.06.13 | TM-WBM-190793-3039 | S | | Outdated | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 21.11.94 | 5 01.10.18 | TM-WBM-190793-3040 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 30.09.96 | 1 15.01.01 | TM-WBM-190793-3041 | S | | Outdated | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 06.11.95 | 3 01.10.18 | TM-WBM-190793-3047 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 21.11.94 | 5 01.10.18 | TM-WBM-190793-3050 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-231 | 08.02.19 | | TM-WBM-190793-3051 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 08.08.95 | 2 01.10.18 | TM-WBM-190793-3051 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-231 | 08.02.19 | | TM-WBM-190793-3052 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 08.08.95 | 2 01.10.18 | TM-WBM-190793-3052 | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 06.11.95 | 2 01.10.18 | TM-WBM-190793-3053 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 29.08.14 | 1 01.10.18 | TM-WBM-190793-3055 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 15.08.12 | | TM-WBM-190793-3056 | S | | Outdated | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-231 | 08.02.19 | | TM-WBM-190793-3057 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 08.08.95 | 2 01.10.18 | TM-WBM-190793-3057 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 08.08.95 | 4 01.10.18 | TM-WBM-190793-3058 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-231 | 08.02.18 | | TM-WBM-190793-3059 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 08.08.95 | 2 01.10.18 | TM-WBM-190793-3059 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 08.08.95 | 3 01.10.18 | TM-WBM-190793-3060 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-243 | 11.07.22 | | TM-WBM-190793-3061 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-244 | 11.07.22 | | TM-WBM-190793-3061 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 26.07.96 | 3 01.10.18 | TM-WBM-190793-3061 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-063 | 01.08.14 | | TM-WBM-190793-3063 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-064 | 01.08.14 | | TM-WBM-190793-3063 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-065 | 01.08.14 | | TM-WBM-190793-3063 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 11.05.15 | 1 01.10.18 | TM-WBM-190793-3063 (PDF) | S | R | Edition: 11.05.2023 | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 06.11.95 | 3 20.09.05 | TM-WBM-190793-3064 | S | | Outdated | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 06.11.95 | 3 20.09.05 | TM-WBM-190793-3065 | S | | Outdated | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 06.11.95 | 4 13.08.07 | TM-WBM-190793-3066 | S | | Outdated | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-231 | 08.02.19 | | TM-WBM-190793-3068 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 06.11.95 | 4 01.10.18 | TM-WBM-190793-3068 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 06.11.95 | 2 01.10.18 | TM-WBM-190793-3070 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-063 | 01.08.14 | | TM-WBM-190793-3072 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-064 | 01.08.14 | | TM-WBM-190793-3072 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-065 | 01.08.14 | | TM-WBM-190793-3072 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 09.12.14 | 1 01.10.18 | TM-WBM-190793-3072 (PDF) | S | | Edition: 18.03.2022 | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 01.02.99 | 1 01.10.18 | TM-WBM-190793-3073 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 10.10.95 | 3 01.10.18 | TM-WBM-190793-3075 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 18.06.97 | 3 01.10.18 | TM-WBM-190793-3077 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 15.11.96 | 2 01.10.18 | TM-WBM-190793-3078 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 12.02.97 | 5 01.10.18 | TM-WBM-190793-3083 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 06.06.97 | 2 01.10.18 | TM-WBM-190793-3084 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 02.04.97 | 3 01.10.18 | TM-WBM-190793-3085 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 25.06.15 | 1 01.10.18 | TM-WBM-190793-3086 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-063 | 01.08.14 | | TM-WBM-190793-3087 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-064 | 01.08.14 | | TM-WBM-190793-3087 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-065 | 01.08.14 | | TM-WBM-190793-3087 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 16.07.17 | 1 01.10.18 | TM-WBM-190793-3087 (PDF) | S | | Edition: 30.09.2022 | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 06.06.97 | 2 01.10.18 | TM-WBM-190793-3088 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 01.07.98 | 3 01.10.18 | TM-WBM-190793-3089 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-238 | 27.05.21 | | TM-WBM-190793-3090 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-239 | 27.05.21 | | TM-WBM-190793-3090 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-245 | 15.02.23 | | TM-WBM-190793-3090 (PDF) | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. | / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-246 | 15.02.23 | | | TM-WBM-190793-3090 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-063 | 01.08.14 | | | TM-WBM-190793-3090 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-064 | 01.08.14 | | | TM-WBM-190793-3090 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-065 | 01.08.14 | | | TM-WBM-190793-3090 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 26.11.18 | 3 | 01.10.18 | TM-WBM-190793-3090 (PDF) | S | | Edition: 20.02.2023 | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 06.06.97 | 6 | 01.10.18 | TM-WBM-190793-3091 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 17.03.15 | 1 | 01.10.18 | TM-WBM-190793-3092 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 06.06.97 | 4 | 01.10.18 | TM-WBM-190793-3093 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 10.03.98 | 2 | 01.10.18 | TM-WBM-190793-3094 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 15.06.98 | 1 | 20.10.05 | TM-WBM-190793-3095 | S | | Outdated | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 08.05.98 | 3 | 01.10.18 | TM-WBM-190793-3096 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 06.06.97 | 4 | 01.10.18 | TM-WBM-190793-3097 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 01.07.98 | 2 | 01.10.18 | TM-WBM-190793-3098 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 20.08.01 | | | TM-WBM-190793-3100 | S | | Outdated | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 25.05.98 | 2 | 01.10.18 | TM-WBM-190793-3101 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 01.12.98 | 4 | 01.10.18 | TM-WBM-190793-3104 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 10.03.99 | 5 | 01.10.18 | TM-WBM-190793-3106 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 22.03.17 | 1 | 01.10.18 | TM-WBM-190793-3109 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 02.04.15 | 1 | 01.10.18 | TM-WBM-190793-3110 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-247 | 15.02.23 | | | TM-WBM-190793-3112 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-248 | 15.02.23 | | | TM-WBM-190793-3112 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-063 | 01.08.14 | | | TM-WBM-190793-3112 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-064 | 01.08.14 | | | TM-WBM-190793-3112 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-065 | 01.08.14 | | | TM-WBM-190793-3112 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 01.10.15 | 2 | 01.10.18 | TM-WBM-190793-3112 (PDF) | S | | Edition: 20.02.2023 | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-063 | 01.08.14 | | | TM-WBM-190793-3113 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-064 | 01.08.14 | | | TM-WBM-190793-3113 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-065 | 01.08.14 | | | TM-WBM-190793-3113 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 13.05.16 | 1 | 01.10.18 | TM-WBM-190793-3113 (PDF) | S | | Edition: 04.05.2022 | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 08.05.00 | 1 | 01.10.18 | TM-WBM-190793-3115 | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-236 | 24.07.20 | | | TM-WBM-190793-3117 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-237 | 24.07.20 | | | TM-WBM-190793-3117 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-249 | 15.02.23 | | | TM-WBM-190793-3117 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-250 | 15.02.23 | | | TM-WBM-190793-3117 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-063 | 01.08.14 | | | TM-WBM-190793-3117 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-064 | 01.08.14 | | | TM-WBM-190793-3117 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-065 | 01.08.14 | | | TM-WBM-190793-3117 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 05.06.20 | 2 | 01.10.18 | TM-WBM-190793-3117 (PDF) | S | | Edition: 16.03.2023 | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-063 | 01.08.14 | | | TM-WBM-190793-3119 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-064 | 01.08.14 | | | TM-WBM-190793-3119 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-065 | 01.08.14 | | | TM-WBM-190793-3119 (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 04.09.17 | 1 | 01.10.18 | TM-WBM-190793-3119 (PDF) | S | | Edition: 24.03.2022 | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-231 | 08.02.19 | | | TM-WBM-190793-ENV | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-236 | 24.07.20 | | | TM-WBM-190793-ENV | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-237 | 24.07.20 | | | TM-WBM-190793-ENV | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-238 | 27.05.21 | | | TM-WBM-190793-ENV | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-239 | 27.05.21 | | | TM-WBM-190793-ENV | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-240 | 15.11.21 | | | TM-WBM-190793-ENV | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-243 | 11.07.22 | | | TM-WBM-190793-ENV | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-244 | 11.07.22 | | | TM-WBM-190793-ENV | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-245 | 15.02.23 | | | TM-WBM-190793-ENV | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-246 | 15.02.23 | | | TM-WBM-190793-ENV | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-247 | 15.02.23 | | | TM-WBM-190793-ENV | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-248 | 15.02.23 | | | TM-WBM-190793-ENV | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-249 | 15.02.23 | | | TM-WBM-190793-ENV | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-250 | 15.03.23 | | | TM-WBM-190793-ENV | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-063 | 01.08.14 | | | TM-WBM-190793-ENV | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-064 | 01.08.14 | | | TM-WBM-190793-ENV | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-065 | 01.08.14 | | | TM-WBM-190793-ENV | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-075 | 05.04.19 | | | TM-WBM-190793-ENV | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-076 | 05.04.19 | | | TM-WBM-190793-ENV | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | WBM | 10.10.95 | 16 | 01.10.18 | TM-WBM-190793-ENV | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-232 | 16.09.19 | | | TM-WBM-190793-X | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-079 | 16.09.19 | | | TM-WBM-190793-X | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 01-232 | 16.09.19 | | | TM-WBM-190793-X (PDF) | S | | | 3P |
| | Weight and Balance Manual (WBM) | 328 SSG | TR 02-079 | 16.09.19 | | | TM-WBM-190793-X (PDF) | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 32-001 | 31.03.14 | | | TM-WM-300493-ADA | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 33-005 | 12.04.18 | | | TM-WM-300493-ADA | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-013 | 15.09.17 | | | TM-WM-300493-ADA | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | WM | 02.11.11 | 2 | 01.03.12 | TM-WM-300493-ADA | S | | S/N 3018, 3033, 3039, 3084, 3092 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 21-001 | 04.09.17 | | | TM-WM-300493-DANA | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 33-003 | 29.09.15 | | | TM-WM-300493-DANA | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 33-005 | 12.04.18 | | | TM-WM-300493-DANA | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-012 | 15.09.17 | | | TM-WM-300493-DANA | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-013 | 15.09.17 | | | TM-WM-300493-DANA | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-014 | 31.07.19 | | | TM-WM-300493-DANA | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-015 | 31.07.19 | | | TM-WM-300493-DANA | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-016 | 31.07.19 | | | TM-WM-300493-DANA | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-017 | 31.07.19 | | | TM-WM-300493-DANA | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | WM | 01.03.11 | 3 | 01.03.12 | TM-WM-300493-DANA | S | | S/N 3070, 3073, 3078, 3089, 3109 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 21-001 | 04.09.17 | | | TM-WM-300493-EAGLE | S | | S/N 3088 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 23-017 | 31.07.19 | | | TM-WM-300493-EAGLE | S | | S/N 3088 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 23-018 | 31.07.19 | | | TM-WM-300493-EAGLE | S | | S/N 3088 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 33-003 | 29.09.15 | | | TM-WM-300493-EAGLE | S | | S/N 3088 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 33-005 | 12.04.18 | | | TM-WM-300493-EAGLE | S | | S/N 3088 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-013 | 15.09.17 | | | TM-WM-300493-EAGLE | S | | S/N 3088 | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | Wiring Manual (WM) | 328 SSG | TR 34-019 | 31.07.19 | | TM-WM-300493-EAGLE | S | | S/N 3088 | 3P |
| | Wiring Manual (WM) | 328 SSG | WM | 07.09.18 | 2 01.03.12 | TM-WM-300493-EAGLE | S | | S/N 3088 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 21-001 | 04.09.17 | | TM-WM-300493-EASPA | S | | S/N 3053, 3059 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 23-017 | 31.07.19 | | TM-WM-300493-EASPA | S | | S/N 3053, 3059 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 23-018 | 31.07.19 | | TM-WM-300493-EASPA | S | | S/N 3053, 3059 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 23-021 | 15.10.19 | | TM-WM-300493-EASPA | S | | S/N 3053, 3059 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 33-005 | 12.04.18 | | TM-WM-300493-EASPA | S | | S/N 3053, 3059 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-019 | 31.07.19 | | TM-WM-300493-EASPA | S | | S/N 3053, 3059 | 3P |
| | Wiring Manual (WM) | 328 SSG | WM | 13.02.23 | 0 01.03.12 | TM-WM-300493-EASPA | S | | S/N 3053, 3059 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 21-001 | 04.09.17 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 23-010 | 28.02.14 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 23-011 | 28.02.14 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 23-012 | 28.02.14 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 23-015 | 30.10.17 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 23-016 | 30.10.17 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 23-017 | 31.07.19 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 23-018 | 31.07.19 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 23-019 | 31.07.19 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 23-020 | 16.08.19 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 23-021 | 15.10.19 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 24-003 | 09.09.20 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 24-004 | 09.09.20 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 31-010 | 29.09.15 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 31-012 | 04.09.17 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 31-013 | 04.09.17 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 31-014 | 04.09.17 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 32-001 | 31.03.14 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 32-002 | 31.03.14 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 33-003 | 29.09.15 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 33-004 | 12.04.18 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 33-005 | 12.04.18 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 33-006 | 31.07.19 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-005 | 15.11.15 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-008 | 30.03.17 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-010 | 04.09.17 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-011 | 04.09.17 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-012 | 15.09.17 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-013 | 15.09.17 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-014 | 31.07.19 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-015 | 31.07.19 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-016 | 31.07.19 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-017 | 31.07.19 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-018 | 31.07.19 | | TM-WM-300493-ENV | S | | | 3P |

| PartNr | Nomenclature | Vendor | Doc.-Title | Issue | REV. / Date | Doc.-Nr. | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | Wiring Manual (WM) | 328 SSG | TR 34-019 | 31.07.19 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-020 | 22.10.20 | | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | WM | 30.04.93 | 10 01.03.12 | TM-WM-300493-ENV | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 21-001 | 04.09.17 | | TM-WM-300493-GLR | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 32-002 | 31.03.14 | | TM-WM-300493-GLR | S | | S/N 3055, 3094, 3096 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 33-003 | 29.09.15 | | TM-WM-300493-GLR | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 33-005 | 12.04.18 | | TM-WM-300493-GLR | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-012 | 15.09.17 | | TM-WM-300493-GLR | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-013 | 15.09.17 | | TM-WM-300493-GLR | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-014 | 31.07.19 | | TM-WM-300493-GLR | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-017 | 31.07.19 | | TM-WM-300493-GLR | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | WM | 02.09.04 | 1 01.03.12 | TM-WM-300493-GLR | S | | S/N 3055, 3094, 3096 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 21-001 | 04.09.17 | | TM-WM-300493-PEARL | S | | Outdated / S/N 3053 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 23-017 | 31.07.19 | | TM-WM-300493-PEARL | S | | Outdated / S/N 3053 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 23-018 | 31.07.19 | | TM-WM-300493-PEARL | S | | Outdated / S/N 3053 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 23-021 | 15.10.19 | | TM-WM-300493-PEARL | S | | Outdated / S/N 3053 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 32-001 | 31.03.14 | | TM-WM-300493-PEARL | S | | Outdated / S/N 3053 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 32-002 | 31.03.14 | | TM-WM-300493-PEARL | S | | Outdated / S/N 3053 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 33-005 | 12.04.18 | | TM-WM-300493-PEARL | S | | Outdated / S/N 3053 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-019 | 31.07.19 | | TM-WM-300493-PEARL | S | | Outdated / S/N 3053 | 3P |
| | Wiring Manual (WM) | 328 SSG | WM | 01.03.07 | 3 01.03.12 | TM-WM-300493-PEARL | S | | Outdated / S/N 3053 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 21-001 | 04.09.17 | | TM-WM-300493-PWF | S | | S/N 3117 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 23-017 | 31.07.19 | | TM-WM-300493-PWF | S | | S/N 3117 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 23-018 | 31.07.19 | | TM-WM-300493-PWF | S | | S/N 3117 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 24-003 | 09.09.20 | | TM-WM-300493-PWF | S | | S/N 3117 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 33-003 | 29.09.15 | | TM-WM-300493-PWF | S | | S/N 3117 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 33-005 | 12.04.18 | | TM-WM-300493-PWF | S | | S/N 3117 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-015 | 31.07.19 | | TM-WM-300493-PWF | S | | S/N 3117 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-019 | 31.07.19 | | TM-WM-300493-PWF | S | | S/N 3117 | 3P |
| | Wiring Manual (WM) | 328 SSG | WM | 01.09.04 | 3 01.03.12 | TM-WM-300493-PWF | S | | S/N 3117 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 21-001 | 04.09.17 | | TM-WM-300493-SAY | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 33-005 | 12.04.18 | | TM-WM-300493-SAY | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-015 | 31.07.19 | | TM-WM-300493-SAY | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 34-016 | 31.07.19 | | TM-WM-300493-SAY | S | | | 3P |
| | Wiring Manual (WM) | 328 SSG | WM | 01.08.95 | 10 01.03.12 | TM-WM-300493-SAY | S | | S/N 3098, 3101 | 3P |
| | Wiring Manual (WM) | 328 SSG | TR 31-011 | 18.12.15 | | TM-WM-300493-X | S | | S/N ALL | 3P |

# CHAPTER

# 2

# VENDOR PUBLICATIONS

## Sort Vendor alphabetical

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| DTSP-400L | 24-34-00 | Aircraft Batteries | | OMM | 23.06.97 | 11 09.11.12 | VDN-0455 | S | | | 3A |
| | | Adhesive Transfer Tapes with Adhesive 300 | 3M | SPM | 01.09.02 | | TDS 950 | S | | | 3A |
| | | Epoxy Adhesive 1751 B/A | 3M | SPM | 01.12.09 | | TDS 1751 B-A | S | | Supersedes Messier Dowty DCMP-156 | 3A |
| | | Polyurethane Protective Tape 8672/8672 GB (Gloss black) | 3M | SPM | 01.04.13 | | TDS PPT8672_2013 | S | | | 3A |
| 90002024 | 32-41-34 | Main Wheel Assy | ABSC | CMM w. IPC | 01.06.01 | 1 15.10.03 | AP-857 | S | | P/N 2610701-2 (HALS part) Superseded by P/N 90002024-1 (ABSC now MEGGITT) | 3P |
| 90002024 | 32-41-34 | Main Wheel Assy | ABSC | TR 32-2 | 26.10.04 | | AP-857 | S | | | 3P |
| 90002024 | 32-41-34 | Main Wheel Assy | ABSC | TR 32-3 | 08.03.06 | | AP-857 | S | | | 3P |
| 90002024 | 32-41-34 | Main Wheel Assy | ABSC | TR 32-4 | 03.01.07 | | AP-857 | S | | | 3P |
| | 32-42-03 | Nondestructive Testing Manual with Procedures | ABSC | NTM | 18.03.94 | 1 01.03.05 | AP-763 | S | | | 3A |
| | 32-42-03 | Nondestructive Testing Manual with Procedures | ABSC | TR 32-2 | 16.05.11 | | AP-763 | S | | | 3A |
| 90002021 /-1, (2610485-1) | 32-46-37 | Nose Wheel Assy | ABSC | CMM w. IPC | 01.06.01 | 2 08.11.14 | AP-859 | S | | | 3P |
| AR9592-X/9608-X | 38-30-06 | DRAIN VALVE ASSEMBLY | ADAMS RITE | CMM w. IPC | 20.05.14 | 3 25.10.16 | VDN-0488 | S | | | 3A |
| 70428 Series | 38-10-61 | Electricla Box Assembly | ADAMS RITE | CMM w. IPC | 09.08.06 | 1 18.11.08 | VDN-0487 | S | | | 3A |
| 70290 | 38-10-37 | Faucet Assembly | ADAMS RITE | CMM w. IPC | 16.04.07 | 3 29.01.19 | VDN-0486 | S | | | 3A |
| 9696 Series | 38-12-34 | Faucet Assembly | ADAMS RITE | CMM w. IPC | 15.10.03 | | VDN-0489 | S | | | 3A |
| 9776-15-1 | 38-20-09 | Hands Free Electronic Faucet Assy | ADAMS RITE | CMM w. IPC | 30.12.91 | 1 22.12.97 | 9776 | S | | | 3P |
| AR9874-3 + AR9877 Series | | Installation AR9874-3 + AR9877 Series Water System | ADAMS RITE | OM | 04.04.03 | 1 14.05.08 | AR9895-38-01 | S | | | 3A |
| AR2518 | 52-50-11 | Latch Assembly | ADAMS RITE | CMM w. IPC | 16.11.70 | 2 05.07.07 | AR2518 | S | | | 3A |
| | 52-51-04 | Latch Assembly | ADAMS RITE | CMM w. IPC | 29.06.90 | 6 21.01.05 | VDN-0446 | S | | | 3A |
| 400500-1 | 38-11-06 | Manual Shutoff Valve | ADAMS RITE | CMM w. IPC | 01.04.73 | 7 23.03.04 | 400500 | S | | | 3A |
| 1606670/-80 | 76-10-08 | Control Assembly Throttle Quadrant Engine | AERO CONTROLEX | CMM w. IPC | 24.01.02 | 1 19.06.12 | VDN-0384 | S | | Now Allsafe Jungfalk | 3P |
| C-5184 | 61-21-16 | Hydraulic and Electrical Motor Assy | AERO CONTROLEX | CMM w. IPC | 15.05.97 | 3 12.08.02 | 4122-006005 | S | | | 3P |
| 4100-849048 | 29-12-01 | Motor Driven Hydraulic Pump Assy | AERO CONTROLEX | CMM w. IPC | 15.08.94 | 3 15.10.02 | VDN-0003 | S | | | 3A |
| 4100-849049 | 28-09-04 | Motor Driven Hydraulic Pump Assy | AERO CONTROLEX | CMM w. IPC | 17.07.97 | 3 30.05.01 | VDN-0380 | S | | | 3A |
| AL-EX15-200E-1 | 25-34-02 | AL-EX15-200E-1 Espresso Coffee Maker | AEROLUX | CMM w. IPC | 30.01.10 | 1 30.08.10 | VDN-0493 | S | | | 3A |
| AL-EX15-200E-1 | 25-34-20 | Configuration for the AL-EX15-200E Espresso Coffee Maker | AEROLUX | CMM w. IPC | 30.01.00 | 2 30.10.04 | VDN-0464 | S | | Superseded by 25-34-02 | 3A |
| AL-EX15-200E-1 | 25-34-02 | New Parts Catallog | AEROLUX | TR25-34-02-03 | 06.09.12 | | VDN-0497 | S | | | 3A |
| AL-EX15-200E-1 | 25-34-02 | New Parts Catalogue | AEROLUX | TR25-34-02-04 | 12.02.13 | | VDN-0496 | S | | | 3A |
| AL-EX15-200E-1 | 25-34-02 | PCB Test Procedures | AEROLUX | TR25-34-02-01 | 30.03.10 | | VDN-0494 | S | | | 3A |
| AL-EX15-200E-1 | 25-34-02 | Proof Pressure Test | AEROLUX | TR25-34-02-02 | 15.11.11 | | VDN-0495 | S | | | 3A |
| AL-RA15-001 | 25-34-00 | Rail Assembly | AEROLUX | CMM w. IPC | 30.03.97 | 3 30.04.04 | VDN-0465 | S | | | 3A |
| ELT96/97A2560000000 | 25-61-02 | ELT 96 / 97 Installation Manual | AIR PRECISION | INSTAL. M | 01.04.01 | 8 01.04.15 | VDN-0442 | O | | SOCATA | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| ELT96/97 | 25-61-02 | ELT96/ELT97 User's Manual | AIR PRECISION | USER M | 01.04.01 | 4 01.10.07 | VDN-0453 | S | Repl. single manual of ELT96 & 97 | 3A |
| ELT96/97A2560000000 | 25-61-02 | Emergency Locator Transmitter ELT 96/97 | AIR PRECISION | CMM w. IPC | 01.05.97 | 10 01.09.16 | VDN-0275 | S | SOCATA | 3A |
| 2610702-2/-3 | 32-46-01 | Brake Assembly | ALLIEDSIGNAL | CMM w. IPC | 31.08.92 | 8 31.01.98 | FORM 12-597 | S | | 3P |
| 109812-7-1/-13 | 49-50-73 | Butterfly Shutoff Valve | ALLIEDSIGNAL | CMM w. IPC | 15.03.83 | 7 11.08.20 | VDN-0008 | S | HONEYWELL | 3A |
| 965-0676-021 | 34-45-30 | Ground Proximity Warning Computer | ALLIEDSIGNAL | CMM w. IPC | 17.07.91 | 10 27.01.06 | 012-0618-001 | S | HONEYWELL | 3P |
| 965-0676-021 | 34-45-30 | Ground Proximity Warning Computer | ALLIEDSIGNAL | TR 34-14 | 27.10.06 | | 012-0618-001 | S | HONEYWELL | 3P |
| 965-0676-021 | 34-45-30 | Ground Proximity Warning Computer | ALLIEDSIGNAL | TR 34-15 | 13.12.06 | | 012-0618-001 | S | HONEYWELL | 3P |
| 965-0676-021 | 34-45-30 | Ground Proximity Warning Computer | ALLIEDSIGNAL | TR 34-16 | 22.01.07 | | 012-0618-001 | S | | 3P |
| | | KHF950/990 Pilot´s Guide for HF | ALLIEDSIGNAL | PG | 01.12.96 | | 006-18038-0000 | O | | 3A |
| | | KLN 900 Pilot´s Guide GPS | ALLIEDSIGNAL | PG | 02.01.99 | 2 | 006-08796-0000 | O | | 3A |
| 980-6117-005 | 23-70-43 | Microphone Monitor | ALLIEDSIGNAL | CMM w. IPC | 15.09.93 | 7 23.08.02 | 012-0666-001 | S | HONEYWELL | 3P |
| 965-0976-0XX | | MK V Enhanced Ground Proximity Warning System<br>Enhanced Ground Proximity Warning System | ALLIEDSIGNAL | IDG | 01.10.99 | | 060-4199-125 | S | HONEYWELL | 3A |
| 3888134-5 | 49-30-93 | Normally Closed Solenoid Valve | ALLIEDSIGNAL | CMM w. IPC | 30.05.85 | 3 21.11.95 | VDN-0004 | S | | 3P |
| 2610485-1 | 32-46-03 | Nose Wheel Assembly | ALLIEDSIGNAL | CMM w. IPC | 31.08.92 | 1 30.05.97 | FORM 12-599 | S | | 3P |
| 064-1015-01 | 23-20-08 | Receiver/Exciter KTR 953 | ALLIEDSIGNAL | CMM w. IPC | 30.04.95 | | 006-05381-0000 | S | Bendix King | 3A |
| 064-1015-01 | 23-20-08 | Receiver/Exciter KTR 953 | ALLIEDSIGNAL | TR 23-1 | 20.11.08 | | 006-05381-0000 | S | Bendix King | 3A |
| 064-1015-01 | 23-20-08 | Receiver/Exciter KTR 953 | ALLIEDSIGNAL | TR 23-2 | 02.03.09 | | 006-05381-0000 | S | Bendix King | 3A |
| 110022-10 | | Baggage Net Door | ALLSAFE | CMM w. IPC | 03.07.96 | E 18.01.18 | BST-641/96 | S | | 3A |
| 76021 | | Baggage Net Freight Compartment | ALLSAFE | CMM w. IPC | 03.07.96 | F 18.01.18 | BST-639/96 | S | | 3A |
| 3001-01-100 | 31-33-15 | Accelerometer | AMETEK | CMM w. IPC | 01.07.86 | 6 12.12.15 | VDN-0012 | S | PATRIOT | 3A |
| 011390-500 | 21-22-01 | Recirculation Fan | AMETEK | CMM w. IPC | 22.05.95 | 5 30.04.14 | VDN-0232 | S | ROTRON | 3A |
| 2060-5AC | 25-25-60 | Attendant Seats Model 2060 | AMI | CMM w. IPC | 15.10.93 | 5 01.05.01 | VDN-0333 | S | | 3A |
| 1112-1AA | 25-11-12 | Observer Seat Model 1112 | AMI | CMM w. IPC | 01.10.93 | | VDN-0013 | S | | 3A |
| 502745-Series | 25-24-01 | Lap Belt Assembly | AM-SAFE | CMM w. IPC | 15.05.96 | 7 12.06.12 | 502745 | S | | 3A |
| 502879-Series | 25-22-08 | Restraint System Assembly | AM-SAFE | CMM w. IPC | 20.11.98 | 3 20.01.03 | 502879 | S | | 3A |
| 503321-Series | 25-23-05 | Restraint System Assembly | AM-SAFE | CMM w. IPC | 27.11.98 | 3 17.01.03 | 503321 | S | | 3A |
| 503693 Series | 25-11-16 | Restraint System Assembly | AM-SAFE | CMM w. IPC | 13.09.96 | 4 19.12.02 | 503693 | S | | 3A |
| 504109-Series | 25-12-18 | Restraint System Assembly | AM-SAFE | CMM w. IPC | 07.06.98 | 3 09.01.03 | 504109 | S | | 3A |
| 1180002-Series | 25-10-32 | Restraint System Assembly | AM-SAFE | ACMM w. IPC | 12.10.10 | | VDN-5030 | S | | 3A |
| SD9422-01 | 26-15-01 | Ambient Smoke Detector | AOA | CMM w. IPC | 05.02.92 | 1 20.12.99 | VDN-0015 | S | | 3A |
| VD3870 | | Mixed Flow Fan | AOA | CMM w. IPC | 15.01.91 | 3 21.10.91 | VD3870 | S | | 3A |
| SD9470-22 | 26-15-02 | Smoke Detector | AOA | CMM w. IPC | 20.12.99 | 2 05.05.04 | VDN-0014 | S | | 3A |
| WT228 | 31-50-01 | Warning/Caution Panel | AOA | CMM w. IPC | 01.03.86 | 6 09.11.98 | WT228 | S | | 3A |
| 453-0150 | | Emergency Locator Transmitters | ARTEX | DOIMM | 26.04.96 | G 29.08.06 | 570-1015 | S | ELT 110-4 | 3A |
| 110-337 | | Emergency Locator Transmitters 406MHz | ARTEX | DOIMM | 10.12.02 | B 25.08.08 | 570-5000 | S | ELT C406-2, C406-2HM | 3A |
| 30ZF108 | 79-40-20 | Flap Actuator for Oil Cooler | ASG | CMM w. IPC | 01.08.96 | 1 14.04.97 | VDN-0018 | S | AEG | 3P |
| 30VR1107 | 79-40-10 | Thermal Valve | ASG | CMM w. IPC | 01.08.96 | | VDN-0017 | S | AEG | 3P |
| AT6421R1 | 31-20-00 | Digital Chronometer Model LC-60 | ASTROTECH | CMM w. IPC | 16.11.95 | 0 17.11.99 | VDN-0019 | S | TRANSICOIL | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| 20040 | 24-22-66 | AC Generator | AUXILEC | CMM w. IPC | 01.10.92 | 1 02.05.00 | VDN-0023 | S | THALES | 3P |
| 106-000-3 | 24-22-68 | DC Bus Power Control Unit | AUXILEC | CMM w. IPC | 30.05.94 | 1 15.01.95 | VDN-0025 | S | THALES | 3P |
| 106-000-4 | 24-22-71 | DC Bus Power Control Unit | AUXILEC | CMM w. IPC | 15.09.99 | | VDN-0028 | S | THALES | 3A |
| 20736 | 24-22-15 | Differential Protection Current Transformer | AUXILEC | TCMS | 01.06.92 | 1 16.11.92 | VDN-0448 | O | THALES | 3P |
| 2438 | 24-22-67 | Generator Control Unit | AUXILEC | CMM w. IPC | 30.07.92 | | VDN-0020 | S | THALES | 3P |
| 118-000-1 | 24-35-33 | Generator Control Unit for Starter Generator | AUXILEC | CMM w. IPC | 15.11.95 | | VDN-0022 | S | THALES | 3A |
| 947 | 24-35-34 | Ground Power Protection Unit | AUXILEC | CMM w. IPC | 15.08.92 | | VDN-0024 | S | THALES | 3A |
| 118-000-2 | 24-35-30 | Generator Control Unit for Starter Generator | AUXILEC (THALES) | CMM w. IPC | 22.12.04 | | VDN-0430 | S | AUXILEC | 3A |
| 4328-2 | 27-11-07 | Aileron Disconnect Unit | AVIAC | CMM w. IPC | 01.06.94 | 1 15.09.99 | VDN-0037 | S | SAGEM | 3A |
| 4327-4 | 27-31-09 | Disconnect Unit Elevator | AVIAC | CMM w. IPC | 01.06.94 | 1 01.09.99 | VDN-0038 | S | SAGEM | 3A |
| 8428-1/-2/-3/-4 | 27-23-04 | Limiter Actuator | AVIAC | CMM w. IPC | 31.01.94 | 6 01.02.11 | VDN-0032 | S | SAGEM | 3A |
| 8409/-1/-2/-3 | 27-32-01 | Pitch Trim Actuator | AVIAC | CMM w. IPC | 31.12.94 | 7 09.11.11 | VDN-0034 | S | SAGEM | 3A |
| 4330 | 27-33-02 | Stick Shaker | AVIAC | CMM w. IPC | 20.10.92 | 1 10.06.07 | VDN-0036 | S | SAGEM | 3A |
| PC251() Series | 24-20-32 | 300 VA Static Inverter | Avionic Instruments | CMM w. IPC | 30.04.95 | 2 14.09.07 | VDN-0642 | S | | 3A |
| 5483-1 | 23-30-08 | Interphone Handset/Cradle | AVTECH | CMM w. IPC | 28.02.92 | 2 01.07.05 | VDN-0041 | S | | 3A |
| 5382-1 | 23-30-11 | Passenger Address Amplifier | AVTECH | CMM w. IPC | 14.10.93 | 1 16.08.04 | VDN-0039 | S | | 3A |
| 2524-520 | 25-20-98 | Fixed Dynamic Double Seat Series 1300 | B/E AERO AMP | MM w. IPL | 01.03.97 | | 4M52001 | S | B/E AERO | 3A |
| 2524-519 | 25-20-97 | Fixed Dynamic Single Seat Series 1300 | B/E AERO AMP | MM w. IPL | 01.02.97 | | 4M51901 | S | B/E AERO | 3A |
| 87064XXX,87065XXX | 25-27-78 | JB6 SERIES COMMUTER CLASS PASSENGER SEATS FOR USAIR EXPRESS/DORNIER 328 AIRCRAFT | B/E AERO BURNS | CMM w. IPC | 13.05.96 | 1 30.09.02 | 25-27-078-2063 | S | | 3A |
| 87064XXX,87065XXX | 25-27-78 | JB6 SERIES COMMUTER CLASS PASSENGER SEATS FOR USAIR EXPRESS/DORNIER 328 AIRCRAFT | B/E AERO BURNS | TR 2.0 | 01.11.02 | | 25-27-078-2063 | S | | 3A |
| 87064XXX,87065XXX | 25-27-78 | JB6 SERIES COMMUTER CLASS PASSENGER SEATS FOR USAIR EXPRESS/DORNIER 328 AIRCRAFT | B/E AERO BURNS | TR 2.01 | 17.11.08 | | 25-27-078-2063 | S | | 3A |
| 87064XXX,87065XXX | 25-27-78 | JB6 SERIES COMMUTER CLASS PASSENGER SEATS FOR USAIR EXPRESS/DORNIER 328 AIRCRAFT | B/E AERO BURNS | TR 2.02 | 14.04.16 | | 25-27-078-2063 | S | | 3A |
| 87064/5XXX | 25-25-83 | Passenger Seat | B/E AERO BURNS | CMM w. IPC | 25.01.93 | | 25-25-083 | S | | 3A |
| 8706XXXX | 25-40-48 | Passenger Seat (ACA) | B/E AERO BURNS | CMM w. IPC | 02.06.00 | | VDN-0042 | S | ACA | 3A |
| 87064/5XXX | 25-27-13 | Passenger Seat (AFRIMEX) | B/E AERO BURNS | CMM w. IPC | 15.04.94 | | 25-27-013 | S | AFRIMEX | 3P |
| 87064/5XXX | 25-27-32 | Passenger Seat (ENGADINA II) | B/E AERO BURNS | CMM w. IPC | 03.02.95 | | VDN-0064 | S | ENGADINA II | 3P |
| 87064/5XXX | 25-27-08 | Passenger Seat (ENGADINA) | B/E AERO BURNS | CMM w. IPC | 15.04.94 | | 25-27-008 | S | ENGADINA | 3P |
| 8788XXXX | 25-41-51 | Passenger Seat (GROSSMANN) | B/E AERO BURNS | CMM w. IPC | 16.03.01 | | VDN-0086 | S | GROSSMANN | 3A |
| 8706XXXX | 25-40-57 | Passenger Seat (HAINAN) | B/E AERO BURNS | CMM w. IPC | 26.05.00 | | VDN-0063 | S | HAINAN | 3A |
| 8718900X; 8719000X | 25-27-04 | Passenger Seat (HORIZON) | B/E AERO BURNS | CMM w. IPC | 08.04.94 | | VDN-0060 | S | HORIZON | 3P |
| 8706XXXX | 25-40-63 | Passenger Seat (OZARK) | B/E AERO BURNS | CMM w. IPC | 09.06.00 | | VDN-0043 | S | OZARK | 3A |
| 8788XXXX | 25-41-78 | Passenger Seat (PHILLIP MORRIS) | B/E AERO BURNS | CMM w. IPC | 03.08.01 | | VDN-0338 | S | PHILLIP MORRIS | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 8788XXXX | 25-40-59 | Passenger Seat (SKYWAYS) | B/E AERO BURNS | CMM w. IPC | 17.04.00 | | VDN-0339 | S | | SKYWAYS | 3A |
| 8788XXXX | 25-40-59 | Passenger Seat (SKYWAYS) | B/E AERO BURNS | TR 1.0 | 03.10.01 | | VDN-0339 | S | | SKYWAYS | 3A |
| 72184002B | 25-33-40 | Water Heater DR40 Series | B/E AERO INVENTUM | CMM w. IPC | 01.07.91 | 17 03.06.16 | VDN-0285 | S | | B/E AERO | 3A |
| 115102 | 35-22-88 | Emergency Oxygen Container Assembly | B/E AERO PURITAN | CMM w. IPC | 13.11.09 | | VDN-0474 | S | | PURITAN BENNETT | 3A |
| 176200-Series/-219/-250 | 35-22-02 | Oxygen Cylinder Assembly | B/E AERO PURITAN | CMM w. IPC | 27.06.03 | 2 26.06.06 | VDN-0045 | S | | PURITAN BENNETT | 3A |
| 176226-Series | 35-22-18 | Oxygen Cylinder Assembly | B/E AERO PURITAN | CMM w. IPC | 15.03.10 | | VDN-0475 | S | | PURITAN BENNETT | 3A |
| 170080-Series | 35-01-01 | Oxygen Fill Valve | B/E AERO PURITAN | CMM w. IPC | 17.12.82 | 2 20.04.05 | VDN-0438 | S | | PURITAN BENNETT | 3A |
| 174097-88 | 35-24-04 | Oxygen Mask Assembly | B/E AERO PURITAN | CMM w. IPC | 01.11.00 | 4 02.05.23 | VDN-0110 | S | R | PURITAN BENNETT | 3A |
| | 35-20-96 | Oxygen Mask Assembly | B/E AERO PURITAN | TR 3A | 12.08.13 | | VDN-0590 | S | | PURITAN BENNETT | 3A |
| 174080 Series | 35-20-96 | Oxygen Mask Assembly 174080 Series | B/E AERO PURITAN | CMM w. IPC | 31.05.99 | 2 16.07.13 | VDN-0552 | O | | PURITAN BENNETT | 3A |
| 170017/-18/-33 | 35-10-52 | Oxygen Outlet Valve Assembly | B/E AERO PURITAN | CMM w. IPC | 15.08.86 | 3 08.05.14 | VDN-0182 | S | | PURITAN BENNET | 3A |
| 4441019-002 | 35-22-11 | Oxygen Pressure Regulator | B/E AERO PURITAN | CMM w. IPC | 06.01.02 | | VDN-0451 | S | | PURITAN BENNETT | 3P |
| 172234-02 | 35-22-10 | Oxygen Pressure Regulator | B/E AERO PURITAN | CMM w. IPC | 15.05.04 | 1 15.05.06 | VDN-0452 | S | | PURITAN BENNETT | 3A |
| 119003, 119063, 4401005 | | Protective Breathing Equipment | B/E AERO PURITAN | GUIDE | 06.04.90 | 13 21.09.21 | 2499-200 | O | | PURITAN BENNETT | 3A |
| 174260-Series | 35-10-60 | Sweep-On 2000 and Fullface Crew Mask Assembly | B/E AERO PURITAN | CMM w. IPC | 30.12.96 | 4 01.09.09 | VDN-0439 | S | | PURITAN BENNETT | 3A |
| 174260-XX | 35-11-78 | Sweep-on 2000 Crew Mask Assembly | B/E AERO PURITAN | CMM w. IPC | 05.02.13 | | VDN-0490 | S | | | 3A |
| 174260-XX | 35-11-78 | Sweep-on 2000 Crew Mask Assembly | B/E AERO PURITAN | TR-1A | 13.02.14 | | VDN-0490 | S | | | 3A |
| 101013-01 | 35-21-55 | Valve Assembly, Solenoid | B/E AERO PURITAN | CMM w. IPC | 01.06.93 | | VDN-0440 | S | | PURITAN BENNETT | 3A |
| 03-1805-2001-2 | 33-49-03 | ACL-1000 Light Assy, Model 1805 | B/E Aerospace | CMM w. IPC | | 1 02.08.16 | VDN-0612 | S | | | 3A |
| 04-1604-1429 | 33-49-04 | ACL-1000 Power Supply Model 1604 | B/E Aerospace | CMM w. IPC | 04.11.99 | 4 09.02.16 | VDN-0087 | S | | FLIGHT COMP. | 3A |
| K9321060A04, K9321062A01 | | DU-875 Display Unit | BARCO | CMM w. IPC | 15.12.09 | | K5920116-02 | S | | | 3A |
| 95218-Series | 71-20-34 | Engine Vibration Isolation System | BARRY CONTROLS | CMM w. IPC | 01.08.92 | 4 15.07.04 | VDN-0047 | S | | | 3P |
| 0543-284-925 | 23-30-06 | Cardsetup Software Version 1.0 for Digital Player DP 4100 | BECKER | IOM | 01.11.02 | | VDN-0329 | O | | | 3A |
| 0543-284-925 | 23-30-06 | Digital Player DP 4100 | BECKER | CMM w. IPC | 15.04.05 | | VDN-0327 | S | | Supersedes TP300 | 3A |
| 0543-284-925 | 23-30-06 | Digital Player DP 4100 | BECKER | AMM | 15.06.01 | 2 15.04.05 | VDN-0328 | O | | | 3A |
| 0543-284-925 | 23-30-06 | DP 4100 Operating Instructions | BECKER | OI | 01.04.05 | | VDN-0466 | O | | | 3A |
| 779.407.925 | 23-30-03 | Tape Player | BECKER | MR | 01.09.90 | | DV 32001.04 | S | | | 3A |
| 854-301-925 | 23-30-03 | Tape Player | BECKER | CMM w. IPC | 15.01.93 | | VDN-0048 | S | | | 3A |
| 397.326-925/802.157-925 | 23-30-03 | Tape player TP 3100 | BECKER | IOM | 01.02.89 | | DV 32002.03 | O | | OBSOLETED | 3A |
| 37-035-23-000-2/-4 | 79-20-01 | Oil Cooler Assembly | BEHR | CMM w. IPC | 25.01.96 | 1 31.07.14 | VDN-0049 | S | | MAHLE | 3P |
| 064-1015-01 | | KHF 950 HF/SSB Communication System | BENDIX | MM w. IPL | 01.05.82 | 4 04.05.83 | 006-05190-0004 | S | | Bendix King | 3A |
| | 30-10-31 | Black Standard Pneumatic De-Icer Installation, Maintenance and Repair Manual | BFG ICE | IM | 15.11.96 | 5 06.06.12 | VDN-0055 | S | | | 3A |
| 3D3555-01 | 30-10-47 | Check Valve | BFG ICE | CMM w. IPC | 30.03.99 | 1 14.01.20 | VDN-0226 | S | | | 3A |
| 74-451-XX | 30-10-25 | De-Icer Patch Instructions | BFG ICE | INSTR.M | 17.10.97 | 16.05.02 | VDN-0053 | O | | | 3P |
| 5E2546/5E2547 | 30-10-19 | Elevator a. Rudder Horn Anti-Icer | BFG ICE | INSTAL.M | 07.03.06 | | VDN-0052 | O | | | 3A |
| 74-451-AC | 30-10-27 | Erosion Repair Kit | BFG ICE | AMR | 12.04.99 | 2 25.03.02 | VDN-0054 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | 30-10-70 | FASTboot Pneumatic De-Icer | BFG ICE | INSTR.M | 10.04.00 | 6 13.04.18 | VDN-0274 | S | 74-451-XX | 3A |
| | 30-10-76 | FASTboot Silver Estane Pneumatic De-Icer | BFG ICE | INSTAL.M | 07.12.99 | 8 17.10.12 | VDN-0551 | S | | 3A |
| | 30-10-66 | FASTboot Silver Urethane Pneumatic De-Icer | BFG ICE | INSTAL.M | 05.03.09 | 3 11.01.19 | VDN-0550 | S | Now is UTC Aerospace | 3A |
| 3D3554-02 | 30-10-46 | Isolation Valve, De-Icing | BFG ICE | CMM w. IPC | 15.01.99 | | VDN-0425 | S | | 3P |
| 4D2185-01 | 30-10-42 | Pre-Cooler | BFG ICE | CMM w. IPC | 15.04.99 | | VDN-0120 | S | | 3P |
| 3D3573-01/-02 | 30-10-55 | PRESSURE RELIEF VALVE | BFG ICE | CMM w. IPC | 01.12.99 | | VDN-0409 | S | | 3P |
| 3D3557-01 | 30-10-45 | Pressure Switch | BFG ICE | CMM w. IPC | 15.12.00 | | VDN-0140 | S | | 3A |
| 3E2459-1 | 24-09-01 | Temperature Controller | BFG ICE | CMM w. IPC | 15.05.92 | | 92-32-019 | S | | 3A |
| 3D3190-1-2 | 30-10-73 | Temperature Switch | BFG ICE | CMM w. IPC | 15.04.99 | | VDN-0282 | S | | 3A |
| 4E2947-3 | 30-60-12 | Timer/Monitor | BFG ICE | ACMM | 01.02.01 | 1 02.09.08 | VDN-0556 | S | | 3A |
| 3D3553-01 | 30-10-44 | Water Seperator | BFG ICE | CMM w. IPC | 01.02.02 | 1 25.11.19 | VDN-0426 | S | | 3A |
| 30005-0000-41/-53/-57 | 73-20-06 | Torque Signal Conditioner Vol. I | BFG SIMMONDS | CMM w. IPC | 15.10.93 | C 30.03.99 | VDN-0441 | S | IPC P&WC | 3P |
| 30005-0000-41/-53/-57 | 73-20-06 | Torque Signal Conditioner Vol. II | BFG SIMMONDS | IPC | 30.03.99 | | VDN-0441 | S | IPC P&WC | 3P |
| 580-291-XXX | 76-10-63 | CONTROL CABLE ASSEMBLIES, COCKPIT AND NACELLE | Cablecraft Motion | CMM w. IPC | 20.08.15 | 1 20.08.15 | VDN-0560 | S | | 3A |
| | | Aero-M/I Antenna TT-5006A | CHELTON ANTENNAS | IM | 04.02.05 | | 677-A00022_IM | S | COBHAM | 3A |
| 802-10-0010 | | SwiftBroadband Intermediate Gain Antenna IGA-5001 | CHELTON ANTENNAS | IM | 20.03.09 | 7 10.04.14 | 677-A0181_IM | S | COBHAM | 3A |
| ZCV193-4 | 27-60-06 | Valve-Double Shuttle | CIRCLE SEAL | CMM w. IPC | 17.08.94 | | ZTP-220 | S | ZEVCO | 3P |
| 328-0020/21 | 31-11-05 | AC/DC Panel | COBHAM | CMM w. IPC | 01.10.93 | 1 30.06.95 | VDN-0166 | S | NEC AERO | 3A |
| 328-0040/41 | 49-32-10 | APU Panel | COBHAM | CMM w. IPC | 01.10.93 | 1 30.06.95 | VDN-0168 | S | NEC AERO | 3A |
| 328-0050/51/52 | 23-41-03 | Calls Panel | COBHAM | CMM w. IPC | 01.10.93 | 1 30.06.95 | VDN-0172 | S | NEC AERO | 3A |
| 328-0180 | 26-10-02 | Distribution Box | COBHAM | CMM w. IPC | 07.03.00 | | VDN-0162 | S | NEC AERO | 3A |
| 328-0170 | 26-10-01 | Fire Panel For Cargo Compartment | COBHAM | CMM w. IPC | 19.03.00 | 1 04.04.01 | VDN-0161 | S | NEC AERO | 3A |
| 328-0100 | 31-12-15 | Flight Attendant Panel | COBHAM | CMM w. IPC | 01.10.93 | 4 31.07.07 | VDN-0163 | S | NEC AERO | 3A |
| 328-0030/-31 | 31-12-11 | Forward Combined Panel | COBHAM | CMM w. IPC | 01.10.93 | 2 30.04.99 | VDN-0169 | S | NEC AERO | 3P |
| 328-3150 | 27-60-01 | Ground Spoiler Test Panel | COBHAM | CMM w. IPC | 28.01.98 | 1 01.07.99 | VDN-0524 | S | NEC AERO | 3A |
| 328-0010 | 31-12-13 | Ice - Fuel - Hydro Panel | COBHAM | CMM w. IPC | 01.10.93 | 1 30.06.95 | VDN-0170 | S | NEC AERO | 3P |
| 328-007XAmdtB/C /-3074 | 31-12-12 | OXYGEN/ECS Panel | COBHAM | CMM w. IPC | 01.10.93 | 2 25.06.99 | VDN-0165 | S | NEC AERO | 3A |
| 328-0090 | 31-25-01 | Reversionnary Panel | COBHAM | CMM w. IPC | 01.10.93 | 1 30.06.95 | VDN-0160 | S | NEC AERO | 3A |
| | | SwiftBroadband HLD-7260 | COBHAM | IM | 16.11.07 | 2 11.03.14 | 862-A0101_IM | S | | 3A |
| 328-0140/0160 | 27-20-11 | The Reds Test Panel 34VE | COBHAM | CMM w. IPC | 14.10.97 | 1 20.11.98 | VDN-0525 | S | NEC AERO | 3A |
| 328-0080 | 27-32-20 | Trim Panel | COBHAM | CMM w. IPC | 01.10.93 | 3 06.09.10 | VDN-0164 | S | NEC AERO | 3A |
| 8-700-04/-05 | 31-41-09 | Proximity Sensor Electronic Unit | CRANE | CMM w. IPC | 01.09.96 | 5 17.02.21 | 011-2910-616 | S | was ELDEC | 3P |
| 3253-10 | 33-24-99 | Ballast Unit | DIEHL | CMM w. IPC | 20.02.95 | 2 28.09.01 | VDN-0415 | S | | 3A |
| 3214-30 | 33-51-07 | Battery | DIEHL | CMM w. IPC | 15.02.83 | 5 04.02.98 | VDN-0073 | S | | 3A |
| 3214-31 | 33-51-17 | Battery | DIEHL | CMM w. IPC | 08.07.02 | 12 13.07.21 | VDN-0422 | S | | 3A |
| 07-110-9200 | | Battery Adapter P/N 07-110-9200 | DIEHL | UG | 06.12.04 | 6 18.09.17 | 0432401 | O | | 3A |
| | | Capability List (Management Manual - Appendix I) | DIEHL | CL | 19.02.10 | 23 22.07.22 | MH-000-0006 | S | | 3A |
| 3285-50 | 30-42-03 | Control Unit, Window Heat | DIEHL | CMM w. IPC | 10.04.00 | | VDN-0229 | S | | 3A |
| 3214-73 | 33-51-99 | Emergency Power Supply Unit | DIEHL | CMM w. IPC | 01.09.94 | 2 02.07.10 | VDN-0071 | S | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 3296-30/-40 | 33-13-11 | Lighting Dimmer | DIEHL | CMM w. IPC | 15.07.96 | 3 11.03.08 | VDN-0072 | S | | | 3A |
| 3274-10 | 31-50-99 | Red Warning Panel | DIEHL | TR 001 | 20.11.03 | | 31-50-99_001 | S | | | 3A |
| 3274-10 | 31-50-99 | Red Warning Panel | DIEHL | CMM w. IPC | 20.03.95 | | VDN-0070 | S | | | 3A |
| 3285-10 | 30-42-02 | Windscreen Heater Control Unit | DIEHL | CMM w. IPC | 25.07.94 | 1 30.06.00 | VDN-0068 | S | | | 3P |
| 261000B | 24-23-30 | Transformer Rectifier Unit TRU - 150A1 | DITTEL | CMM w. IPC | 17.11.00 | | TRU 150 A1 | S | | | 3A |
| DLH 294 | 25-36-10 | Atlas Container | DRIESSEN | CMM w. IPC | 03.04.96 | E 17.06.14 | VDN-0270 | S | | | 3A |
| DLH 294 | 25-36-10 | Atlas Container | DRIESSEN | IPC | 03.04.96 | F 17.06.14 | VDN-0610 | S | | | 3A |
| TB001016 | 25-37-63 | Atlas Trolley Assy | DRIESSEN | CMM w. IPC | 11.05.98 | | VDN-0271 | S | | | 3A |
| DLH 3072 | 25-37-63 | Bar Trolley Assy | DRIESSEN | CMM w. IPC | 09.03.94 | B 17.03.05 | VDN-0443 | S | | | 3P |
| DLH 3072 | 25-37-63 | Bar Trolley Assy | DRIESSEN | IPC | 09.03.94 | A 29.08.03 | VDN-0443 | S | | | 3P |
| JA010001 | 25-35-36 | Hot Jug | DRIESSEN | CMM w. IPC | 26.06.95 | E 31.01.12 | VDN-0269 | S | | | 3P |
| DLH 105-210 | 25-38-26 | Hot Jug | DRIESSEN | CMM w. IPC | 05.12.97 | D 29.06.10 | VDN-0272 | S | | | 3A |
| DLH 105-210 | 25-38-26 | Hot Jug | DRIESSEN | IPC | 14.08.96 | D 29.06.10 | VDN-0272 | S | | | 3A |
| DLH 105-211 | 25-38-66 | Hot Jug | DRIESSEN | CMM w. IPC | 06.07.98 | A 05.03.04 | VDN-0273 | S | | | 3P |
| DLH 105-211 | 25-38-66 | Hot Jug | DRIESSEN | IPC | 06.07.98 | A 05.03.04 | VDN-0273 | S | | | 3P |
| JA010001 | 25-35-36 | Hot Jug | DRIESSEN | IPC | 26.06.95 | F 31.01.12 | VDN-0600 | S | | | 3P |
| DLH 1085-017 | 25-32-31 | Meal Trolley Assy | DRIESSEN | CMM w. IPC | 09.08.89 | A 16.01.04 | VDN-0268 | S | | | 3A |
| DLH 1085-017 | 25-32-31 | Meal Trolley Assy | DRIESSEN | IPC | 09.08.89 | A 16.01.04 | VDN-0268 | S | | | 3A |
| ACM30488 | 32-43-31 | Aircraft Applicability | DUNLOP | AEM | 27.06.94 | | DM1443-47 | O | | | 3P |
| | | Aircraft Tyres and Tubes | DUNLOP | GPM | 02.01.08 | | DM1172 | S | | Supersedes GSI DM1172 | 3A |
| | 32-41-00 | Aircraft Tyres and Tubes | DUNLOP | ACMM | | 4 01.02.17 | VDN-0553 | S | | Tire Care & Maintenace Manual | 3A |
| | 20-00-02 | Aircraft Wheel Bearings | DUNLOP | GPM | 31.01.91 | | VDN-0316 | S | | | 3A |
| AE20462 | | Anti - Skid Test Set | DUNLOP | GEM | 15.04.93 | | DM1636-00 | S | | | 3A |
| AC69895/69963 | 32-42-03 | Brake Metering Unit | DUNLOP | CMM w. IPC | 31.03.99 | | VDN-0315 | S | | | 3P |
| AE20462 | | Interface for Anti - Skid Test Set | DUNLOP | GEM | 15.04.93 | | DM1636-01 | S | | | 3A |
| | 20-00-01 | NDT of Aircraft Wheels | DUNLOP | GPM | 21.05.84 | | VDN-0317 | S | | | 3A |
| P0723E105P-VARIANT | 25-60-12 | Adult/Child Life Preserver | EAM | CMM w. IPC | 26.04.88 | 10 14.12.11 | KSE-35L8 | S | | | 3A |
| P01400-2XX | 25-60-58 | AIC-35 LIFE PRESERVER | EAM | CMM | 15.09.15 | | AIC-35 | S | | | 3A |
| R0101A( ) | 25-60-17 | EAM-T4 LIFE RAFT | EAM | CMM | 01.09.11 | 8 01.05.14 | VDN-0570 | O | | | 3A |
| P0640-103 | 25-60-15 | Infant Life Preserver | EAM | CMM w. IPC | 20.03.87 | 9 23.05.13 | IN-V20L8 | S | | | 3A |
| P01074-1XX | 25-60-30 | XF-35 LIFE PRESERVER | EAM | CMM | 12.02.16 | | XF-35 | S | | | 3A |
| 717801-1 | 32-31-01 | Landing Gear Control Assembly | EATON | CMM w. IPC | 01.12.92 | A 01.07.95 | VDN-0081 | S | | | 3A |
| 330/335GA01Y01 | 24-29-55 | AC Junction Box | ECE | CMM w. IPC | 15.06.94 | 3 24.09.13 | VDN-0083 | S | | ZODIAC | 3A |
| 440/441TS08Y01 | 26-24-15 | Fire Panel | ECE | CMM w. IPC | 15.05.93 | 3 30.04.98 | VDN-0084 | S | | INTERTECHNIQUE | 3A |
| 8-700 | | Failure Indication - Quick Reference Guide | ELDEC | QRG | 16.10.00 | | QRG8-700 | S | | Now is CRANE | 3A |
| 9-231-29 | 73-35-31 | Fuel Flow Transmitter | ELDEC | CMM w. IPC | 15.05.92 | 2 23.10.17 | 011-4910-702 | S | | Now is CRANE | 3P |
| 8-700 | 31-41-00 | Proximity Sensor Electr. Unit | ELDEC | ITEM | 15.03.94 | | 011-2921-002 | O | | Now is CRANE | 3P |
| DP3113 (A) | | Crewmember Protective Breathing Equipment (PBE) | ESSEX | GUIDE | | 24 24.02.17 | PRM-01 | O | | | 3A |
| BA24320D-1 | 26-25-36 | 0.12kg AUTO EUTECTIC FIRE EXTINGUISHER | FIRE FIGHTING ENTERP | CMM w. IPC | 01.10.02 | 8 01.03.17 | VDN-0554 | S | | PERCIVAL | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | | Doc.-No | S=Standard O=optional | R= Revision REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| BA23177-1 | 26-25-12 | Automatic Fire Extinguisher 0,12kg | FIRE FIGHTING ENTERP | CMM w. IPC | 01.03.93 | 8 | 01.01.19 | VDN-0181 | S | PERCIVAL | 3A |
| BA21741GR-2 | 26-20-29 | Hand Fire Extinguisher 1,2kg BCF | FIRE FIGHTING ENTERP | CMM w. IPC | 01.11.92 | 6 | 01.01.19 | VDN-0180 | S | PERCIVAL | 3A |
| 02-1510-8011 | 33-49-02 | ACL-1000 Cable Assy, Model 1510 | FLIGHT COMP. | CMM w. IPC | 15.04.94 | | | VDN-0092 | S | | 3P |
| 07-2700-2000 | 33-49-07 | ACL-1000 Electronic Switch, Model 2700 | FLIGHT COMP. | CMM w. IPC | 11.03.03 | | | VDN-0611 | S | | 3A |
| 03-1805-2001 | 33-49-03 | ACL-1000 Light Assy, Model 1805 | FLIGHT COMP. | CMM w. IPC | 15.04.94 | 2 | 07.11.02 | VDN-0091 | S | | 3A |
| 03-2100-2003/4 | 33-49-03 | ACL-1000 Light Assy, Model 2100 | FLIGHT COMP. | CMM w. IPC | 15.04.94 | 3 | 07.07.08 | VDN-0093 | S | | 3P |
| 03-2103-2003/4 | 33-49-03 | ACL-1000 Light Assy, Model 2103 | FLIGHT COMP. | CMM w. IPC | 15.04.99 | 2 | 07.07.08 | VDN-0393 | S | | 3P |
| 03-2700-2006 | 33-49-03 | ACL-1000 Light Assy, Model 2700 | FLIGHT COMP. | CMM w. IPC | 04.12.98 | | | VDN-0089 | S | | 3A |
| 03-2901-2003/4 | 33-49-03 | ACL-1000 Light Assy, Model 2901 | FLIGHT COMP. | CMM w. IPC | 20.03.99 | 2 | 07.07.08 | VDN-0088 | S | | 3A |
| 04-1504-1429 | 33-49-04 | ACL-1000 Power Supply Model 1504 | FLIGHT COMP. | CMM w. IPC | 15.04.94 | 3 | 23.08.04 | VDN-0090 | S | | 3P |
| 001A251A4400 | | Head-Up Guidance System Model 2700 | FLIGHT DYNAMICS | PG | 01.11.94 | 1 | 01.05.96 | 523-0809568 | S | ROCKWELL COLLINS | 3A |
| DC24/50/1 | | Operating Instruction for Mini.Vacuum Pump | FUERGUT | OI | 26.08.02 | | | VDN-0421 | O | | 3A |
| S4-3402000-1 | 32-43-02 | Emergency Park / Brake Valve | FWM | CMM w. IPC | 20.07.92 | 1 | 29.04.93 | VDN-0138 | S | | 3P |
| 6033-01/02-1/2/03-1 | 28-48-04 | Signal Processor and Refueling Panel Volume 1 | GE AVIATION | CMM w. IPC | 15.07.97 | 3 | 24.09.10 | GEK 118086 | S | Formlerly Smiths Aerospace, then GE Aviationn, now ONTIC | 3A |
| 6033-01/02-1/2/03-1 | 28-48-04 | Signal Processor and Refueling Panel Volume 2 | GE AVIATION | CMM w. IPC | 15.07.97 | 3 | 24.09.10 | GEK 118101 | S | Formlerly Smiths Aerospace, then GE Aviationn, now ONTIC | 3A |
| 001A716E1000 | 71-60-00 | Air Intake | GKN WESTL.AERO. | CMMM | 31.01.96 | 5 | 31.03.02 | VDN-0057 | S | | 3P |
| 001A716E1000 | 71-60-00 | Air Intake | GKN WESTL.AERO. | OVMM | 31.01.96 | 1 | 31.07.98 | VDN-0336 | O | | 3P |
| 001A717A2000 | 71-70-00 | Drain Assy, Lower Cowling | GKN WESTL.AERO. | CMMM | 31.01.96 | 4 | 31.03.02 | VDN-0058 | S | | 3P |
| 001A712A0000 | 71-20-00 | Engine Mounting Structure | GKN WESTL.AERO. | CMMM | 31.01.96 | 3 | 31.03.02 | VDN-0056 | S | | 3P |
| 001A711E0000 | 71-10-00 | Nacelle Assembly | GKN WESTL.AERO. | CMMM | 31.01.96 | 6 | 31.03.02 | VDN-0051 | S | | 3P |
| A06 - Series | 24-09-02 | Actuator Assembly | GKN WESTL.SITEC | CMM w. IPC | 01.08.91 | 6 | 21.12.18 | A06000-07 | S | | 3A |
| H019 Series | 76-10-01 | Adjustable Cam Switch Assembly | GKN WESTL.SITEC | CMM w. IPC | 01.01.00 | | | VDN-0096 | S | | 3P |
| B49 - Series | 28-10-03 | Fuel Drain Valve Assy | GKN WESTL.SITEC | CMS | 01.09.92 | | | VDN-0050 | S | | 3A |
| B14000 | 28-29-14 | Fuel Shut - Off Valve | GKN WESTL.SITEC | CMM w. IPC | 01.09.92 | | | VDN-0095 | S | | 3A |
| | 32-41-00 | Aircraft Tire Care and Maintenance | GOOD YEAR | GUIDE | 01.06.16 | | | 700-862-931-538 | S | | 3A |
| | | Aircraft Tire Data Book | GOOD YEAR | DB | 01.10.02 | | | 700-862-931-522 | S | | 3A |
| 811099-1/-3 | 73-21-74 | Drain Pressure Sensitivity Test | HAMILTON SUND | AI | 15.06.98 | | | D3282-AI97166 | S | IPC P&WC | 3A |
| 811180-X-0X,PWC3118888-0X | 73-21-71 | Electronic Engine Control EEC118-15 | HAMILTON SUND | CMM w. IPC | 01.12.92 | 13 | 29.07.17 | EEC118-15 | S | IPC P&WC | 3P |
| | 20-00-02 | Electronic Standard Practices Manual | HAMILTON SUND | SPM | 26.04.07 | 29 | 15.11.19 | VDN-5027 | O | UTC Aerospace Systems | 3A |
| 811099-X/3117036-0X | 73-21-74 | Fuel Control | HAMILTON SUND | CMM w. IPC | 15.12.85 | 8 | 12.09.18 | JFC118-15 | S | IPC P&WC | 3P |
| | 24-10-00 | GENERATOR DRIVES AND RELATED EQUIPMENT | HAMILTON SUND | SPM | 01.12.72 | 80 | 29.10.19 | SPM 24-10-00 | O | UTC Aerospace Systems | 3P |
| | 20-00-01 | Mechanical Standard Practices | HAMILTON SUND | SPM | 26.04.07 | 18 | 04.02.19 | VDN-5026 | O | UTC Aerospace Systems | 3A |
| | 20-00-04 | Warnings Registry (Long Version) | HAMILTON SUND | SPM | 28.10.13 | 12 | 05.10.18 | VDN-5025 | O | UTC Aerospace Systems | 3A |
| HD-E6C-3XX-XX | 61-02-59 | Application Guide | HARTZELL | AG | 01.07.02 | 82 | 01.11.22 | 159 | O | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | 61-13-35 | Composite Propeller Blade | HARTZELL | MM | 02.06.97 | 44 01.11.22 | 135F | S | | | 3P |
| | 61-13-70 | Composite Propeller Blade Field Maintenance and Minor Repair Manual | HARTZELL | FMRM | 01.10.13 | 18 01.09.22 | 170 | S | | | 3P |
| | 61-10-73 | Composite Spinner Field Maintenance and Minor Repair Manual | HARTZELL | FMRM | 01.09.14 | 8 01.11.19 | 173 | S | | | 3P |
| | 61-16-48 | Composite Spinner Maintenance Manual | HARTZELL | MM | 01.10.93 | 22 01.12.21 | 148 | S | | | 3P |
| A-5659-2 | 61-20-03 | Constant Speed Propeller Governor | HARTZELL | CMM w. IPC | 31.08.93 | 3 19.08.03 | WG 60064 | S | | WOODWARD | 3P |
| | 61-00-60 | Dual Acting Prop./Prop. Control Syst. | HARTZELL | OLMM | 01.09.93 | 4 01.02.97 | 160 | S | | | 3P |
| | 61-00-60 | Dual Acting Prop./Prop. Control Syst. | HARTZELL | TR-022 | 01.03.97 | | 160 | S | | | 3P |
| | 61-00-60 | Dual Acting Prop./Prop. Control Syst. | HARTZELL | TR-023 | 01.05.97 | | 160 | S | | | 3P |
| | 61-00-60 | Dual Acting Prop./Prop. Control Syst. | HARTZELL | TR-029 | 01.10.06 | | 160 | S | | | 3P |
| | 61-00-60 | Dual Acting Prop./Prop. Control Syst. | HARTZELL | TR-030 | 01.05.09 | | 160 | S | | | 3P |
| | 61-00-60 | Dual Acting Prop./Prop. Control Syst. | HARTZELL | TR-031 | 01.11.16 | | 160 | S | | | 3P |
| | 61-00-60 | Dual Acting Prop./Prop. Control Syst. | HARTZELL | TR-032 | 01.03.17 | | 160 | S | | | 3P |
| A-5656 | 61-20-01 | Gear Pump Assy | HARTZELL | CMM w. IPC | 30.06.93 | 2 14.11.07 | WG 60063 | S | | WOODWARD | 3P |
| | 61-00-65 | Illustrated Tool and Equipment Manual | HARTZELL | ITEM | 01.11.95 | 30 01.11.22 | 165A | S | | | 3P |
| | 61-00-64 | IPC for Dual Acting Propeller and Propeller Control System | HARTZELL | IPC | 01.12.94 | 9 01.08.11 | 164B | S | | | 3P |
| | 61-00-64 | IPC for Dual Acting Propeller and Propeller Control System | HARTZELL | TR-007 | 01.08.14 | | 164B | S | | | 3P |
| | 61-00-64 | IPC for Dual Acting Propeller and Propeller Control System | HARTZELL | TR-008 | 01.01.17 | | 164B | S | | | 3P |
| | | Manual Revision Status | HARTZELL | PI | 13.11.09 | 337 02.12.14 | VDN-0472 | O | | | 3P |
| A-5651 | 61-20-02 | Overspeed Governor Assy | HARTZELL | CMM w. IPC | 30.06.93 | 1 15.01.97 | WG 60062 | S | | WOODWARD | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | MM | 01.08.93 | 26 01.10.06 | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-027 | 01.12.06 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-029 | 01.12.07 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-030 | 01.05.11 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-031 | 01.08.11 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-032 | 01.08.11 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-033 | 01.04.12 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-034 | 01.06.13 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-035 | 01.07.15 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-036 | 01.01.17 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-038 | 01.04.18 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-039 | 01.11.20 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-20-62 | Propeller Control Unit | HARTZELL | MM | 01.08.93 | 15 01.01.19 | 162 | S | | | 3P |
| | 30-61-80 | Propeller Ice Protection System Manual | HARTZELL | SMM | 01.07.06 | 38 01.06.22 | 180 | S | | Manual 181 & 182 & 183 included with Rev 27 | 3P |
| | 61-00-63 | Propeller Log Book | HARTZELL | LB | 01.08.93 | 2 01.06.97 | 163A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 1 | HARTZELL | SPM | 01.03.93 | 61 01.11.21 | 202A | S | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | 61-01-02 | Standard Practices Manual Vol. 1 | HARTZELL | TR-045 | 01.06.22 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 1 | HARTZELL | TR-046 | 01.06.22 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 1 | HARTZELL | TR-047 | 01.08.22 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 1 | HARTZELL | TR-048 | 01.08.22 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 10 | HARTZELL | SPM | 01.03.93 | 37 01.11.21 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 10 | HARTZELL | TR-010 | 01.12.21 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 11 | HARTZELL | SPM | 01.03.93 | 37 01.02.22 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 2 | HARTZELL | SPM | 01.03.93 | 32 01.04.20 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 3 | HARTZELL | SPM | 01.03.93 | 42 01.12.21 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 4 | HARTZELL | SPM | 01.03.93 | 34 01.06.22 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 5 | HARTZELL | SPM | 01.03.93 | 34 01.06.22 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 6 | HARTZELL | SPM | 01.03.93 | 36 01.06.20 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 7 | HARTZELL | SPM | 01.03.93 | 53 01.06.22 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 7 | HARTZELL | TR-022 | 01.09.22 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 8 | HARTZELL | SPM | 01.10.22 | 36 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 9 | HARTZELL | SPM | 01.03.93 | 32 01.04.21 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manuel Vol. 7 | HARTZELL | TR-023 | 01.10.22 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manuel Vol. 7 | HARTZELL | TR-024 | 01.10.22 | | 202A | S | | | 3P |
| F20/40 / F20/27 H1CT70 | | Aircraft Battery | HAWKER | OVMM | 01.01.01 | | VDN-0325 | S | | | 3A |
| 2LA005109-Serie | 33-20-06 | Cargo Compartment Light | HELLA | CMM w. IPC | 10.05.88 | 1 18.05.95 | VDN-0107 | S | | GOODRICH HELLA | 3P |
| 2LA006823-01 | 33-31-13 | Cargo Compartment Light | HELLA | CMM w. IPC | 01.03.00 | 2 19.03.14 | VDN-0482 | S | | GOODRICH HELLA | 3A |
| 2LA006633-00/-01 | 33-12-06 | Dome Light | HELLA | CMM w. IPC | 29.04.94 | | VDN-0102 | S | | GOODRICH HELLA | 3A |
| 2LA006729-00 | 33-52-03 | Emergency Light | HELLA | CMM w. IPC | 15.11.92 | | VDN-0101 | S | | GOODRICH HELLA | 3A |
| 2LA006729-00 | 33-52-03 | Emergency Light | HELLA | IPL | 26.06.01 | | VDN-0101 | S | | GOODRICH HELLA | 3A |
| 2LA005163-30 | 33-11-22 | Flight Crew Reading Light | HELLA | CMM w. IPC | 08.07.91 | 5 01.03.16 | VDN-0098 | S | | GOODRICH HELLA | 3A |
| 2LA004626-05 | 33-11-09 | Flight Crew Reading Light | HELLA | CMM w. IPC | 10.10.95 | 1 22.01.02 | VDN-0108 | S | | GOODRICH HELLA | 3A |
| 2LA005113-00 | 33-26-41 | Indicator Light | HELLA | CMM w. IPC | 10.05.88 | 1 18.11.94 | VDN-0103 | S | | GOODRICH HELLA | 3A |
| 2LA006778-00 | 33-11-44 | Instrument Panel Light | HELLA | CMM w. IPC | 29.04.94 | 1 06.06.01 | VDN-0173 | S | | GOODRICH HELLA | 3A |
| 1X4004429-00 | 33-40-14 | Landing Light | HELLA | CMM w. IPC | 01.03.94 | 1 22.09.99 | VDN-0106 | S | | GOODRICH HELLA | 3A |
| 2LA002428-00 | 33-32-01 | Light | HELLA | CMM w. IPC | 15.07.82 | 5 19.03.14 | VDN-0183 | S | | GOODRICH HELLA | 3A |
| 1X0006678-00 | 33-40-23 | Logo Light | HELLA | CMM w. IPC | 15.11.92 | | VDN-0100 | S | | GOODRICH HELLA | 3A |
| 1X0006678-00 | 33-40-23 | Logo Light | HELLA | IPL | 10.02.01 | | VDN-0100 | S | | GOODRICH HELLA | 3A |
| 2LA00661X-Serie | 33-22-09 | Passenger Service Units | HELLA | CMM w. IPC | 15.02.94 | 1 20.07.00 | VDN-0104 | S | | GOODRICH HELLA | 3A |
| 2LA006672-00 | 33-11-48 | Pedestal Light, Observer Light | HELLA | CMM w. IPC | 29.04.94 | | VDN-0105 | S | | GOODRICH HELLA | 3A |
| 2LA005171-55/-60 | 33-22-08 | Reading Light | HELLA | CMM w. IPC | 01.05.95 | 1 08.08.96 | VDN-0188 | S | | GOODRICH HELLA | 3A |
| 2LA004186-00 | 33-41-12 | Tail Light | HELLA | CMM w. IPC | 11.05.00 | | VDN-0187 | S | | GOODRICH HELLA | 3P |
| 1X0004427-05 | 33-40-19 | Taxi Light | HELLA | CMM w. IPC | 01.01.94 | | VDN-0097 | S | | GOODRICH HELLA | 3A |
| 1XA006726/7-00 | 33-40-22 | Wing Inspection Light | HELLA | CMM w. IPC | 15.11.92 | | VDN-0099 | S | | GOODRICH HELLA | 3A |
| 1XA006726/7-00 | 33-40-22 | Wing Inspection Light | HELLA | IPL | 08.02.01 | | VDN-0099 | S | | GOODRICH HELLA | 3A |
| 7021450-601/-801 | 34-42-12 | PRIMUS 660/880 Digital Weather Radar | HOL3NEYWELL | SDIM | 20.05.96 | 9 13.10.10 | D199605000036 | S | | A09-3944-001 | 3A |
| 7001840-922/-932 | | AA-300 Radio Altimeter System | HONEYWELL | SDIM | 15.08.80 | 12 15.01.09 | A15-3321-006 | S | | consists RT-300 | 3A |
| 964-0465-001 | 23-20-33 | Airplane Personality Module | HONEYWELL | CMM w. IPC | 31.10.02 | | 012-0733-001 | S | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 3800498-1/-3 | 49-24-11 | APU GTCP36-150[DD] | HONEYWELL | MM | 24.02.95 | 4 28.08.15 | VDN-0005 | S | | | 3A |
| 3800498-1/-3 | 49-24-10 | APU GTCP36-150[DD] | HONEYWELL | IPC | 18.05.92 | 5 07.10.11 | VDN-0007 | S | | | 3A |
| 3800498-1/-3 | 49-24-12 | APU GTCP36-150[DD] | HONEYWELL | CMM w. IPC | 18.05.92 | 4 28.08.15 | VDN-0009 | S | | | 3A |
| 3800498-1/-3 | 49-24-12 | APU GTCP36-150[DD] | HONEYWELL | TR 49-2 | 25.10.01 | | VDN-0009 | S | | | 3A |
| 3800498-1/-3 | 49-24-12 | APU GTCP36-150[DD] | HONEYWELL | TR 49-3 | 25.10.01 | | VDN-0009 | S | | | 3A |
| 7510300-901 | 34-51-14 | AT-860 ADF Antenna Vol. I | HONEYWELL | CMM w. IPC | 15.03.88 | 5 14.09.06 | A09-3800-012 | S | | Volume I | 3A |
| 7510300-901 | 34-51-14 | AT-860 ADF Antenna Vol. II | HONEYWELL | CMM w. IPC | 30.08.00 | 2 14.09.06 | A09-3800-012 | S | | Volume II | 3A |
| 7510300-901 | 34-51-14 | AT-860 ADF Antenna Vol. II | HONEYWELL | TR 1 | 11.12.07 | | A09-3800-012 | S | | Volume II | 3A |
| HG2010AC02, AC01, AC03 | 34-26-14 | Attitude Heading Reference Unit | HONEYWELL | CMM w. IPC | 15.09.95 | 1 17.06.14 | M15-3324-002 | S | | | 3A |
| 7511001-912 | 23-81-08 | AV-850A Audio Panel | HONEYWELL | CMM w. IPC | 20.10.89 | 12 08.07.21 | A09-3800-021 | S | | Supersedes Vol. I - III | 3A |
| 7014700-XXX | 34-16-17 | AZ-840 Micro Air Data Computer | HONEYWELL | CMM w. IPC | 01.02.91 | 8 10.09.19 | A09-3435-010 | S | | formerly A09-3735-10 | 3P |
| 7014332-902 | 34-24-38 | BL-870/871 Bezel Controller | HONEYWELL | CMM w. IPC | 15.05.93 | 7 29.06.20 | A09-1147-038 | S | | | 3A |
| 7007549-906 | 34-64-02 | CD-810 Control Display Unit | HONEYWELL | CMM w. IPC | 01.02.91 | 6 28.07.15 | A09-1147-040 | S | | Supersedes A09-1147-40 Vol. I + II | 3A |
| 7022360-901/-902 | 34-63-03 | CD-815 Control Display Unit | HONEYWELL | CMM w. IPC | 30.08.99 | 1 01.09.02 | A09-1147-081 | S | | | 3A |
| 7513000-802/ -836 | 23-81-07 | CD-850 Clearance Delivery Control Head | HONEYWELL | CMM w. IPC | 01.09.88 | 3 21.09.20 | A32-3800-002 | S | | | 3A |
| 7510733-6XX | 23-81-15 | Communication Unit ADS-B Assembly | HONEYWELL | CMM w. IPC | 02.05.12 | | D201110000060 | S | | | 3A |
| 965-0758-00X | 23-20-13 | Communications Management Unit (MK II) | HONEYWELL | CMM w. IPC | 21.02.97 | 14 15.05.20 | 012-0690-001 | S | | | 3P |
| G7830-() | | Control Display Unit CD-830 | HONEYWELL | IM | 09.12.14 | 3 05.06.15 | IST.G7830-() | S | | GABLES | 3A |
| G7830-02/-03 | 34-62-01 | Control Display Unit CD-830 | HONEYWELL | CMM w. IPC | 02.10.15 | | VDN-0011 | S | | GABLES | 3A |
| 7013348-9XX | 31-40-01 | DA-800 Data Acquisition Unit | HONEYWELL | CMM w. IPC | 01.11.93 | 10 24.02.20 | M15-1147-042 | S | | | 3A |
| G7228-01 | | Data Loader 1000 | HONEYWELL | IM | 30.06.09 | | IST.G7228-01 | S | | GABLES | 3A |
| G7228-01/-02 | 34-60-04 | Data Loader Model No. DL-1000 | HONEYWELL | CMM w. IPC | 01.03.10 | | VDN-0010 | S | | GABLES | 3A |
| 7510114-855/7510300-901/2 | 34-51-26 | DF-855 ADF Module and AT-860 Antenna Assy | HONEYWELL | CMM w. IPC | 30.12.01 | 2 27.07.20 | A09-3800-036 | S | | | 3P |
| 7016600-901/-902 | 34-24-43 | DL-900 Data Loader | HONEYWELL | CMM w. IPC | 15.06.92 | 4 15.10.15 | A09-1147-062 | S | | | 3A |
| 7014300-902 | 34-24-39 | DU-870 Display Unit | HONEYWELL | CMM w. IPC | 15.08.93 | 7 08.02.19 | A09-1147-043 | S | | merged into a single-volume | 3A |
| 996-5106-XXX | | Equalizer-MH/C - Digital Audio Equalizer | HONEYWELL | MM | 02.12.03 | A 19.02.04 | 763-1014-001 | S | | | 3P |
| FMZ Series | | Flight Management System Vers.4.1 | HONEYWELL | PM | 01.07.96 | | A28-1146-113 | O | | | 3P |
| FMZ Series | | Flight Management System Vers.4.8 | HONEYWELL | PM | 01.08.97 | 1 01.01.00 | A28-1146-122 | O | | | 3P |
| HG2021GB01/HG2021GDX X | 34-58-04 | Global Navigation Satellite Sensor Unit | HONEYWELL | CMM w. IPC | 15.07.94 | 4 27.04.11 | M15-3819-003 | S | | | 3A |
| HG2012GB, HG2021GD | 34-58-04 | Global Navigation Satellite Sensor Unit | HONEYWELL | TR 34-2 | 13.08.15 | | M15-3819-003 | S | | | 3A |
| HG2021GD04 | | Global Navigation System Sensor Unit | HONEYWELL | SIM | 21.11.08 | | D200809000030 | S | | Esterline (CMC Electronics) | 3A |
| 7015327-901/-905 | 22-18-70 | GP-300 Guidance Panel Controller | HONEYWELL | CMM w. IPC | 01.08.91 | 4 01.12.05 | A09-1147-044 | S | | | 3A |
| | | Handling, Storage, Shipping Avion.Equip. | HONEYWELL | INSTR. M | 10.03.78 | 14 01.08.06 | A09-1100-001 | S | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| HG2001 GD03/GD20/GD40 | | HOLDERS OF THE HG2001GD03/GD20/GD40 INERTIAL REFERENCE UNIT PILOT'S GUIDE | HONEYWELL | PM | 01.09.98 | 1 01.08.10 | M28-3343-003 | O | | | 3P |
| | | Honeywell Flight Management Systems (FMS) NZ-2000 | HONEYWELL | SIL | 10.11.10 | 2 08.08.11 | D201010000079 | O | | | 3A |
| 7017300-XXXXX | 22-11-95 | IC-800 Intergrated Avionics Computer | HONEYWELL | CMM w. IPC | 01.10.92 | 6 26.08.19 | A09-1147-075 | S | | Supersedes Vol. I - III | 3A |
| 7014940-902 | 22-12-79 | IM-803 Installation Module | HONEYWELL | CMM w. IPC | 15.12.98 | 2 | A09-1147-073 | S | | Reissue | 3A |
| | | Index of Publications | HONEYWELL | INDEX | 15.05.98 | 42 01.07.07 | A01-9000-006 | O | | | 3A |
| | | Index Service Bulletins/Technical Newsletter | HONEYWELL | INDEX | 08.06.98 | 34 01.07.07 | A21-9000-002 | O | | | 3A |
| HG2001AC02 | 34-26-18 | Inertial Reference Unit | HONEYWELL | CMM w. IPC | 15.06.95 | 3 14.01.00 | M15-3343-012 | S | | | 3A |
| HG2001AC02 | 34-26-18 | Inertial Reference Unit | HONEYWELL | TR 4 | 15.03.00 | | M15-3343-012 | S | | | 3A |
| HG2001AC02 | 34-26-18 | Inertial Reference Unit | HONEYWELL | TR 6 | 07.05.02 | | M15-3343-012 | S | | | 3A |
| 064-01073-0102 | 23-10-09 | KHF 1050 HF Communication System | HONEYWELL | SIM | 01.03.03 | 6 01.11.07 | 006-10640-0006 | S | | Bendix King | 3A |
| | 23-10-09 | KHF 1050 HF Communication System | HONEYWELL | TR 23-1 | 01.03.11 | | 006-10640-0006 | S | | | 3A |
| | 23-10-09 | KHF 1050 HF Communication System | HONEYWELL | TR 23-3 | 07.03.13 | | 006-10640-0006 | S | | | 3A |
| | 23-10-09 | KHF 1050 HF Communication System | HONEYWELL | TR 23-4 | 17.07.13 | | 006-10640-0006 | S | | | 3A |
| 7026240-90X | 23-05-04 | Mini Cabinet Assembly | HONEYWELL | CMM w. IPC | 20.12.02 | 3 24.08.11 | A09-3855-002 | S | | | 3P |
| 6900094X | | MKV-A EGPWS | HONEYWELL | IM | 14.10.13 | D 20.04.16 | PDS69000940-501 | O | | | 3P |
| 69000941-10X | 34-45-72 | MKV-A Enhanced Ground Proximity Warning System | HONEYWELL | CMM w. IPL | 24.01.14 | 9 10.12.20 | D201304000065 | S | | | 3P |
| 7510600-801 | 34-52-05 | ML-850 MLS Receiver Vol. I | HONEYWELL | CMM w. IPC | 01.09.89 | 1 15.11.00 | A09-3800-014 | S | | Volume I | 3A |
| 7510600-801 | 34-52-05 | ML-850 MLS Receiver Vol. II | HONEYWELL | CMM w. IPC | 15.11.00 | | A09-3800-014 | S | | Volume II | 3A |
| CG1042AB04 | 34-26-15 | Mode Select Unit | HONEYWELL | CMM w. IPC | 20.11.87 | 7 18.07.08 | M15-3349-006 | S | | | 3A |
| 5682C000 | 36-11-05 | Over Pressure Switch | HONEYWELL | MM | 27.04.92 | 2 11.11.15 | 2373 | S | | was NGL | 3A |
| | | PM-CPDLC MK2 CMU | HONEYWELL | PM | 16.11.11 | A | 69001561-001 | O | | | 3P |
| | 22-05-04 | PRIMUS 2000 Integr.Avi. Syst.Vol I | HONEYWELL | SMM | 01.11.93 | 1 15.03.95 | A15-1146-054 | S | | Volume I | 3P |
| | 22-05-34 | PRIMUS 2000 Integr.Avi. Syst.Vol I (GAU) | HONEYWELL | SMM | 15.07.98 | | A15-1146-085 | S | | for DO328 GAU | 3P |
| | 22-05-04 | PRIMUS 2000 Integr.Avi. Syst.Vol II | HONEYWELL | SMM | 01.11.93 | 1 15.03.95 | A15-1146-054 | S | | Volume II | 3P |
| | 22-05-34 | PRIMUS 2000 Integr.Avi. Syst.Vol II (GAU) | HONEYWELL | SMM | 15.07.98 | | A15-1146-085 | S | | for DO328 GAU | 3P |
| | 22-05-04 | PRIMUS 2000 Integr.Avi. Syst.Vol III | HONEYWELL | SMM | 15.03.95 | | A15-1146-054 | S | | Volume III | 3P |
| | 22-05-34 | PRIMUS 2000 Integr.Avi. Syst.Vol III (GAU) | HONEYWELL | SMM | 15.07.98 | | A15-1146-085 | S | | for DO328 GAU | 3P |
| | | PRIMUS 2000 Integr.Avionics Syst.w.GAU | HONEYWELL | PM | 01.03.00 | | A28-1146-139 | O | | | 3P |
| | | PRIMUS 2000 Integr.Avionics System | HONEYWELL | PM | 01.08.93 | 1 01.11.93 | A28-1146-086 | O | | | 3P |
| | | PRIMUS 2000 Integr.Avionics System | HONEYWELL | TR 1 | 01.10.94 | | A28-1146-086 | O | | | 3P |
| | | PRIMUS 660 Digital Weather Radar | HONEYWELL | PM | 01.02.98 | 3 01.08.03 | A28-1146-111 | O | | | 3A |
| | | PRIMUS 880 Digital Weather Radar | HONEYWELL | PM | 01.09.96 | 3 01.01.06 | A28-1146-102 | O | | | 3A |
| | | PRIMUS II Integr.Radio Syst.RM-855 RMU | HONEYWELL | PM | 01.02.99 | 3 01.10.11 | A28-1146-121 | O | | | 3A |
| | | PRIMUS II Integr.Radio System | HONEYWELL | EC | 01.06.91 | | A04-3800-01-00 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | PRIMUS II Integr.Radio System | HONEYWELL | PM | 01.11.87 | 7 | 01.08.00 | A28-1146-050 | O | | | 3A |
| SRZ-85X | | PRIMUS II SRZ-85X Integr.Radio Syst. | HONEYWELL | OIM | 10.10.87 | 16 | 27.07.20 | D198710000004 | O | | Supersedes A15-3800-001 | 3A |
| | | RCZ-850 Instal./Removal Instructions | HONEYWELL | IRI | 01.09.95 | 4 | 01.03.99 | A62-0097-000 | O | | | 3P |
| 7510700-8XX | 23-81-01 | RCZ-8XX Integrated Comm.Unit | HONEYWELL | CMM w. IPC | 15.12.87 | 15 | 24.08.20 | A09-3800-015 | S | | | 3A |
| 7021450-601 | 34-42-11 | Receiver Transmitter Antenna | HONEYWELL | CMM w. IPC | 15.04.97 | 3 | 15.05.07 | A09-3944-002 | S | | | 3A |
| 7021450-601 | 34-42-11 | Receiver Transmitter Antenna | HONEYWELL | IPC | 15.04.97 | 3 | 15.05.07 | A09-3944-002 | S | | | 3A |
| 7013270-93X/-966 thru-988 | 34-51-24 | RM-855 Radio Management Unit | HONEYWELL | CMM w. IPC | 15.07.93 | 13 | 01.06.20 | A09-3800-028 | S | | | 3A |
| | | RNZ-850 Instal./Removal Instructions | HONEYWELL | IRI | 01.02.92 | 8 | 01.06.04 | A62-0096-000 | O | | | 3P |
| 7510100-8XX | 34-51-17 | RNZ-851 Integrated Navigation Unit | HONEYWELL | CMM w. IPC | 15.02.92 | 4 | 15.08.05 | A09-3800-030 | S | | | 3A |
| 7001840-932/922 | 34-42-10 | RT-300 Radio Alti. Rec.Transm. | HONEYWELL | CMM w. IPC | 01.09.10 | 9 | 29.03.19 | A09-3531-010 | S | | Supersedes Vol. I - III | 3A |
| 4005842 | 22-11-51 | SB-201 Servo Drum/Housing Assy | HONEYWELL | CMM w. IPC | 15.10.73 | 6 | 30.08.99 | A09-1146-005 | S | | | 3A |
| 4006719-906/-910 | 22-11-50 | SM-200 Servo Drive | HONEYWELL | CMM w. IPC | 05.12.73 | 13 | 07.04.15 | A09-1146-004 | S | | | 3A |
| | | Stand.Rep.Procedures Avionic Equipment | HONEYWELL | SRM | 01.04.94 | 7 | 01.02.08 | A09-1100-004 | O | | | 3A |
| 3800498-1/-3 | | Standard Practices Manual | HONEYWELL | SPM | 28.10.77 | 22 | 11.12.19 | 20-00-02-70-00-01 | S | | | 3A |
| 7517900-10001/3 | 34-43-10 | TCAS 2000 | HONEYWELL | SDIM | 20.10.97 | 3 | 15.11.02 | A09-3841-001 | S | | ACSS-L3 | 3A |
| | | Tech. Pub. Index for Commercial Aviation | HONEYWELL | INDEX | 29.12.03 | | | CA-INDEX | O | | | 3A |
| | | Tech.Pub.Index for General Aviation | HONEYWELL | INDEX | 29.12.03 | | | GA-INDEX | O | | | 3A |
| 7510114-811/901/855 | | Test Software Revision M for the DF-850/855 ADF Assembly | HONEYWELL | TB | 19.08.11 | | | A45-3818-2463 | O | | | 3P |
| | | TNL8100 GPS Navigation System ARINC CDU | HONEYWELL | PG | 29.02.96 | D | 25.06.99 | 81803-01 | O | | TRIMBLE | 3P |
| | 34-40-01 | TRA-45A / Terrain Display Unit / Radio Altimeter Indicator | HONEYWELL | IM | 01.02.00 | 6 | 01.04.10 | VDN-0478 | S | | for use with the EGPWS | 3P |
| | | TRA-45A Pilot Guide / Terrain Awareness and Display System | HONEYWELL | PG | 01.03.04 | 2 | | PG80-5145 | O | | EGPWS | 3P |
| 7026201-8XX | 23-12-03 | Very High Frequency Data Radio Assembly | HONEYWELL | CMM w. IPC | 20.12.02 | 8 | 27.04.18 | A09-3829-002 | S | | | 3P |
| 7008470-922 | 34-40-30 | WU-650 Receiver Transm.Antenna Vol. I | HONEYWELL | CMM w. IPC | 01.05.86 | 5 | 15.12.02 | A09-3941-002 | S | | Supersedes A09-3941-02 | 3P |
| 7008470-922 | 34-40-30 | WU-650 Receiver Transm.Antenna Vol. II | HONEYWELL | CMM w. IPC | 15.12.02 | | | A09-3941-002 | S | | Supersedes A09-3941-02 | 3P |
| 7008470-922 | 34-40-30 | WU-650 Receiver Transm.Antenna Vol. IIIA | HONEYWELL | CMM w. IPC | 01.10.92 | 1 | 15.12.02 | A09-3941-002 | S | | Supersedes A09-3941-02 | 3P |
| 7008470-922 | 34-40-30 | WU-650 Receiver Transm.Antenna Vol. IIIB | HONEYWELL | CMM w. IPC | 01.10.92 | 1 | 15.12.02 | A09-3941-002 | S | | Supersedes A09-3941-02 | 3P |
| 980-6020-001 | 23-70-44 | Solid State Cockpit Voice Recorder | HONEYWELL ASIG | CMM w. IPC | 31.01.94 | 19 | 01.12.11 | 012-0667-001 | S | | ALLIEDSIGNAL | 3P |
| | | CMM, SB, SIL Landing Gear Equipm. | HONEYWELL ASIG | INDEX | 01.03.98 | 18 | 31.01.06 | FORM 12-536 | O | | ALLIEDSIGNAL | 3A |
| 965-1180-/-1190-020 | 34-45-40 | Enhanced Ground Proximity Warning System EGPWS | HONEYWELL ASIG | CMM w. IPC | 09.05.00 | 19 | 21.09.06 | 012-0709-001 | S | | | 3P |
| 980-4700-XXX | 31-30-40 | FA2100CVR Solid State Flight Data Recorder | HONEYWELL ASIG | CMM w. IPC | 01.12.92 | 27 | 18.05.11 | 012-0650-001 | S | | ALLIEDSIGNAL | 3P |
| 3800498-1 | 49-30-91 | Fuel Control Assembly | HONEYWELL ASIG | CMM w. IPC | 01.05.86 | 8 | 31.07.10 | D200402000036 | S | | ALLIEDSIGNAL | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| 3800498-1/-3 | 49-24-09 | Pneum.a.Shaft Power Gas Turbine GTCP36-150 Series | HONEYWELL ASIG | IRM | 02.01.88 | 33 20.02.18 | D200701000028 | S | ALLIEDSIGNAL | 3A |
| 980-6113-001 | 23-70-41 | Remote Microphone | HONEYWELL ASIG | CMM w. IPC | 10.03.89 | 3 14.04.98 | 012-0552-001 | S | ALLIEDSIGNAL | 3P |
| 980-6113-001 | 23-70-41 | Remote Microphone | HONEYWELL ASIG | TR 23-01 | 01.05.00 | | 012-0552-001 | S | ALLIEDSIGNAL | 3P |
| 980-6113-001 | 23-70-41 | Remote Microphone | HONEYWELL ASIG | TR 23-02 | 21.08.00 | | 012-0552-001 | S | ALLIEDSIGNAL | 3P |
| | 32-49-01 | Standard Practices Manual | HONEYWELL ASIG | SPM | 31.12.98 | 3 30.04.00 | FORM 12-622 | S | ALLIEDSIGNAL | 3A |
| | | Workscope Planning Guide for 36-150 APU | HONEYWELL ASIG | WPG | 25.04.03 | | 31-16647-15 | O | ALLIEDSIGNAL | 3A |
| 064-01074-0101 | 23-10-07 | KAC 1052 Antenna Coupler | HONEYWELL BENDIX | CMM w. IPC | 26.01.04 | 1 | 006-15640-0001 | S | Bendix King | 3A |
| 064-01073-0102 | | KHF 1050/PS440 Pilot's Guide | HONEYWELL BENDIX | PG | | 1 01.05.03 | 006-18289-0000 | O | Bendix King | 3A |
| 064-1015-01 | 23-20-03 | KHF 950 HF/SSB Communication System | HONEYWELL BENDIX | SIM | 01.02.94 | 2 28.04.06 | 006-05389-0002 | S | Bendix King | 3A |
| 064-01072-0101 | 23-10-08 | KPA 1052 Power Amplifier | HONEYWELL BENDIX | CMM w. IPC | 30.09.03 | | 006-15641-0000 | S | Bendix King | 3A |
| 064-01073-0102 | 23-10-06 | KRX 1053 Receiver/Exciter | HONEYWELL BENDIX | CMM w. IPC | 30.09.03 | 2 06.05.11 | 006-15642-0001 | S | Bendix King | 3A |
| 7517900-10001/3 | 34-43-11 | TCAS 2000 Computer Unit Vol. I | HONEYWELL L3 | CMM w. IPC | 30.10.97 | 6 15.08.06 | A09-3841-002 | S | ACSS-L3 | 3A |
| 7517900-10001/3 | 34-43-11 | TCAS 2000 Computer Unit Vol. II | HONEYWELL L3 | CMM w. IPC | 30.10.97 | 7 15.08.06 | A09-3841-002 | S | ACSS-L3 | 3A |
| 7517900-10001/3 | 34-43-11 | TCAS 2000 Computer Unit Vol. III | HONEYWELL L3 | CMM w. IPC | 30.10.97 | 9 15.08.06 | A09-3841-002 | S | ACSS-L3 | 3A |
| 4066010-904 | 34-43-04 | Traff. Alert a. Collision Avoid.System Vol. 1 | HONEYWELL L3 | CMM w. IPC | 01.07.90 | 11 15.12.05 | C15-3841-007 | S | ACSS-L3; supersedes 15-3841-07; ATA change in to 34-45-04 | 3P |
| 4066010-904 | 34-43-04 | Traff. Alert a. Collision Avoid.System Vol. 2 | HONEYWELL L3 | CMM w. IPC | 01.04.94 | 5 15.12.05 | C15-3841-007 | S | ACSS-L3; supersedes 15-3841-07; ATA change in to 34-45-04 | 3P |
| 4066010-904 | 34-43-04 | Traff. Alert a. Collision Avoid.System Vol. 3 | HONEYWELL L3 | CMM w. IPC | 01.07.90 | 10 15.12.05 | C15-3841-007 | S | ACSS-L3; supersedes 15-3841-07; ATA change in to 34-45-04 | 3P |
| | | Traffic Alert Collision Avoid.Syst. (TCAS) | HONEYWELL L3 | PM | 01.10.90 | 4 01.09.00 | A28-1146-070 | O | L3 | 3P |
| | | Traffic Collision Avoidance System 2000 | HONEYWELL L3 | PG | 01.09.99 | | C28-3841-005 | O | ACCS-L3 | 3A |
| Suppl.for PG C28-3841-005 | | Traffic Collision Avoidance System 2000 | HONEYWELL L3 | SUPPL | 01.05.00 | 1 01.08.00 | C28-3841-006 | O | ACCS-L3 | 3A |
| 1716D000-002 | 21-51-11 | Cold Air Unit | HONEYWELL NGL | CMM w. IPC | 26.05.94 | 9 06.12.16 | 2516 | S | NGL | 3A |
| 4069B000-002 | 36-11-10 | Cross Feed Valve | HONEYWELL NGL | CMM w. IPC | 12.12.95 | 6 09.02.11 | 2383 | S | | 3A |
| 8554C000 | 21-51-12 | Dual Heat Exchanger | HONEYWELL NGL | CMM w. IPC | 27.06.92 | 8 19.01.04 | 2389 | S | NGL | 3A |
| 5729C000/-002 | 21-51-10 | Environmental Control Unit | HONEYWELL NGL | CMM w. IPC | 14.06.94 | 6 06.12.16 | 2511 | S | NGL | 3A |
| 6038C000-001 | 21-51-95 | Environmt.Contr.Sys.Comp.Insul.Jacket Kit | HONEYWELL NGL | CMM w. IPC | 18.10.01 | | 2780 | S | NGL | 3A |
| 4040B000 | 36-11-11 | Non Return Valve 63,5 mm (2.5 inch) | HONEYWELL NGL | CMM w. IPC | 10.10.95 | 5 09.12.14 | 2406S | S | NGL | 3A |
| 3907B000 | 21-51-22 | Non-Return Valve | HONEYWELL NGL | CMM w. IPC | 21.10.92 | 4 01.07.10 | 2376 | S | NGL | 3A |
| 4066B000 | 36-11-02 | Non-Return Valve 2 inch (50,8 mm) | HONEYWELL NGL | MM | 10.07.92 | 1 01.07.10 | 2371 | O | | 3P |
| 4066B000/-002 | 36-11-02 | Non-Return Valve 2 inch (50,8 mm) | HONEYWELL NGL | CMM w. IPC | 09.01.96 | 4 09.02.15 | 2372 | S | | 3A |
| 5658C000 | 36-11-08 | Over Temperature Switch | HONEYWELL NGL | MM | 29.04.92 | 2 10.11.15 | 2374 | S | | 3P |
| 5677C000/-002 | 21-51-16 | Pneumatic Temperature Sensor | HONEYWELL NGL | CMM w. IPC | 23.01.96 | 5 15.09.03 | 2400 | S | NGL | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| 4067B000-002/3/4/5/6 | 36-11-03 | Pressure Reducing and Shut Off Valve | HONEYWELL NGL | CMM w. IPC | 15.03.96 | 12 07.11.16 | 2385 | S | NGL | 3A |
| 4031B000 | 21-51-02 | Solenoid Valve | HONEYWELL NGL | CMM w. IPC | 04.02.92 | 5 11.03.11 | 2369 | S | NGL | 3A |
| 5413C000 | 21-61-08 | Temperature Control Valve | HONEYWELL NGL | CMM w. IPC | 10.08.95 | 7 12.08.10 | 2395 | S | NGL | 3A |
| 5406C000 | 21-61-03 | Temperature Controller | HONEYWELL NGL | CMM w. IPC | 17.01.96 | 4 12.10.01 | 2405 | S | NGL | 3A |
| 5732C000 | 21-51-15 | Turbine Inlet Control Valve | HONEYWELL NGL | CMM w. IPC | 23.05.94 | 2 19.08.04 | 2514 | S | NGL | 3A |
| 5556C000 | 21-51-21 | Water Injector | HONEYWELL NGL | CMM w. IPC | 09.01.96 | 2 01.11.01 | 2396 | S | NGL | 3A |
| 4068B000-002/-003 | 21-51-03 | Flow Control and Shut Off Valve | HONEYWELL NGL GL | CMM w. IPC | 18.12.95 | 9 09.08.06 | 2379 | S | NGL | 3A |
| 2500-205RB | 25-60-10 | Air Aspirated Life Rafts | HOOVER INDUSTRIES | CMM w. IPC | 07.08.98 | 1 07.08.98 | VDN-0112 | S | Models FR-25 | 3P |
| 500-12, 16, 27 | | MULTI FUNCTION PERSONAL LOCATOR BEACON (PLB) PERSONAL LOCATOR BEACON (PLB) | HR-SMITH | MM | | 15 20.10.14 | HRS1002-5-00 | O | | 3A |
| Model RH0802 | | Hydraulic Axle Jack Mod. RH0802 | HYDRO | TH | 01.09.99 | | VDN-0114 | O | | 3A |
| Model SG103 | | Hydraulic Axle Jack Mod. SG103 | HYDRO | TH | 01.03.00 | | VDN-0113 | O | | 3A |
| AA-02-A | 25-34-68 | Coffee Maker | IACOBUCCI | CMM w. IPC | 22.05.00 | | 1683 | S | | 3A |
| HFE96-28 | 25-34-52 | Coffee Maker | IACOBUCCI | CMM w. IPC | 31.12.97 | B 01.09.08 | 1713 | S | | 3A |
| HFE96-28 | 25-34-52 | Operating Instructions for the HFE96-28 Coffe Maker | IACOBUCCI | OI | 31.12.97 | | VDN-0470 | O | | 3A |
| CA-01 | 25-34-69 | Rail | IACOBUCCI | CMM w. IPC | 14.09.00 | | 1739 | S | | 3A |
| AA-8 | 25-34-70 | Water Tank | IACOBUCCI | CMM w. IPC | 21.09.00 | | 1738 | S | | 3A |
| 5577 | 25-10-09 | Cockpit Sliding Door Lock | INDRAÉRO SIREN | CMM w. IPC | 25.09.00 | 1 01.02.06 | VDN-0449 | S | | 3A |
| 5574 | 25-10-10 | Hatrack Latch | INDRAÉRO SIREN | CMM w. IPC | 01.02.01 | 1 01.02.06 | VDN-0450 | S | | 3A |
| 785841-1 | 36-11-82 | Detection Box | INTERTECHNIQUE | CMM w. IPC | 15.01.96 | | VDN-0200 | S | ZODIAC | 3P |
| 219335-3/219336-2 | 28-20-06 | Fuel Jet Pumps | INTERTECHNIQUE | CMM w. IPC | 15.04.92 | 4 28.10.13 | VDN-0118 | S | ZODIAC | 3A |
| L98B621/-2/-6/-7 | 28-41-14 | Fuel Level Indicator | INTERTECHNIQUE | CMM w. IPC | 15.04.92 | 1 01.10.94 | VDN-0201 | S | ZENITH-AVIATION | 3A |
| L94E31-651 | 28-19-86 | Re- and Defuelling Valve | INTERTECHNIQUE | CMM w. IPC | 15.04.92 | 2 16.07.12 | VDN-0115 | S | ZENITH-AVIATION | 3A |
| K97-63-603P2 | 28-19-87 | Refuelling Adapter | INTERTECHNIQUE | CMM w. IPC | 15.04.92 | 2 01.10.94 | VDN-0119 | S | ZENITH-AVIATION | 3A |
| GC205CR | 25-20-17 | Aircraft Oven Types | IPECO | CMM w. IPC | 30.07.99 | 13 24.11.22 | VDN-0331 | S | AMC INDUSTRIES | 3A |
| GC204/5(-) | 25-20-04 | Aircraft Oven Types | IPECO | CMM w. IPC | 26.07.98 | 3 23.09.02 | VDN-0429 | S | Supersedes 25-20-01 | 3A |
| 3A165-0007/8-01-1 | 25-11-15 | Crew Seat | IPECO | CMM w. IPC | 05.02.07 | 4 28.08.12 | SM628 | S | Repl. CMM 25-10-72 | 3P |
| 3A165-0007/8-01-2 | 25-11-03 | Crew Seat Assembly | IPECO | CMM w. IPC | 22.03.96 | 12 28.08.14 | SM615 | S | | 3A |
| 2651-311-5 | 38-37-01 | Lavatory Drain Valve Assy | KAISER | CMM w. IPC | 09.09.85 | 6 15.01.90 | VDN-0121 | S | | 3P |
| 0016-0015-3 | 38-32-09 | Lever Cap Assemblies | KAISER | CMM w. IPC | 01.06.84 | 5 01.02.94 | VDN-0122 | S | | 3P |
| 35XXX-XXX-XXX | | Cont.Fire a.Overheat Detection Sys. | KIDDE-DEUGRA | INSTR.M | 01.11.80 | 4 15.08.96 | 505 | S | HAMILTON SUNDSTRAND | 3A |
| 51653-151-01 | 26-11-84 | Fire Detection Control Unit | KIDDE-DEUGRA | CMM w. IPC | 01.03.95 | | VDN-0385 | S | HAMILTON SUNDSTRAND | 3A |
| 51653-151 | 26-11-89 | Fire Detection Control Unit | KIDDE-DEUGRA | CMM w. IPC | 03.08.05 | 1 25.07.11 | VDN-0499 | S | HAMILTON SUNDSTRAND | 3A |
| 355XX-2 | 26-14-12 | Sensing Elements | KIDDE-DEUGRA | CMM w. IPC | 17.05.06 | 12 27.05.14 | 512 | S | HAMILTON SUNDSTRAND | 3A |
| 512XX-XXX | 26-16-10 | Terminal Lug Firewire and Accessoires | KIDDE-DEUGRA | CMM w. IPC | 04.08.93 | 09.08.11 | VDN-0381 | S | HAMILTON SUNDSTRAND | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| 35303-XXX | 26-14-14 | Wire End Fittings | KIDDE-DEUGRA | CMM w. IPC | 12.02.96 | 3 03.01.13 | 514 | S | HAMILTON SUNDSTRAND | 3A |
| | | Low Oil Pressure Switch | KULITE | ATP | 08.07.93 | E 20.05.96 | 3104 | O | APS-3D-1000-1000A | 3A |
| | | Oil Pressure Sensor | KULITE | ATP | 09.10.90 | G 24.04.96 | 2953 | O | IPTE-75GF-1000-70D | 3P |
| | | Pressure Transducer | KULITE | ATP | 06.09.90 | E 10.03.99 | 2952 | O | APTE-133-1000-XXX | 3P |
| | | Pressure Transducer | KULITE | ATP | 28.03.91 | D 24.04.96 | 2982 | O | APTE-137-1000-200 | 3P |
| | | Underwater Locator Beacon | L3 | IOIM | 03.11.16 | | 165E5542-10 | S | FA2100 | 3P |
| 7517900-10001/3 | 34-43-10 | TCAS 2000 | L3 ACSS | TR 3 | 03.12.09 | | A09-3841-001 | S | ACSS-L3 | 3A |
| 7517900-10001/3 | 34-43-10 | TCAS 2000 | L3 ACSS | TR 4 | 15.12.09 | | A09-3841-001 | S | ACSS-L3 | 3A |
| 7517900-10001/3 | 34-43-10 | TCAS 2000 | L3 ACSS | TR 6 | 15.07.11 | | A09-3841-001 | S | ACSS-L3 | 3A |
| | | TCAS 2000/3000 Pilot's Guide | L3 ACSS | PG | 16.08.07 | | 8006773-001 | O | ACSS-L3 | 3A |
| | | TCAS II / TCAS 2000 (Change 7.1) Pilot's Guide Supplement | L3 ACSS | PG | 31.10.09 | 1 15.01.12 | 8008110-001 | O | ACSS-L3 | 3P |
| 4066010-904/-910 | 34-43-00 | TCAS II RT-910 | L3 ACSS | SDIM | 01.06.89 | 5 06.08.14 | C15-3841-005 | S | ACSS-L3 | 3P |
| 4066010-XXX | 34-45-04 | Traffic Alert and Collision Avoidance System - Volume I | L3 ACSS | CMM w. IPC | 01.07.90 | 13 15.08.18 | C15-3841-007 | S | ACSS-L3 | 3A |
| 4066010-XXX | 34-45-04 | Traffic Alert and Collision Avoidance System - Volume II | L3 ACSS | CMM w. IPC | 01.07.90 | 7 15.08.18 | C15-3841-007 | S | ACSS-L3 | 3A |
| 4066010-XXX | 34-45-04 | Traffic Alert and Collision Avoidance System - Volume III | L3 ACSS | CMM w. IPC | 01.07.90 | 12 15.08.18 | C15-3841-007 | S | ACSS-L3 | 3A |
| S00-0003-() | | A200S Solid State Cockpit Voice Recorder - Notification of Obsolescense | L3 AVIATION RECORDER | SIL | 20.07.06 | 1 23.08.06 | A200S SCVR 003 | O | Model A200S | 3A |
| 93A100-XX | 23-70-01 | Cockpit Voice Recorder | L3 AVIATION RECORDER | CMM w. IPC | 01.05.91 | 3 01.03.04 | 165E0101-00 | S | Model A100X | 3P |
| 2100-1020-00 | 23-70-04 | Cockpit Voice Recorder | L3 AVIATION RECORDER | CMM w. IPC | 01.11.98 | 17 07.03.19 | 165E1689-00 | S | Model FA2100 | 3A |
| 93AXXXXX | | Cockpit Voice Recorder | L3 AVIATION RECORDER | IOIM | | 2 01.07.02 | 165E2807-00 | S | Supersedes FAR02213189 | 3A |
| 93A151-XX | 23-70-01 | CVR Control Units | L3 AVIATION RECORDER | CMM w. IPC | 01.05.91 | 3 01.03.04 | 165E0101-00 | S | Model A15X | 3P |
| 93A055-XX | 23-70-01 | CVR MIC Modules | L3 AVIATION RECORDER | CMM w. IPC | 01.05.91 | 3 01.03.04 | 165E0101-00 | S | Model A55X | 3P |
| 17M800-261 | 31-30-01 | Digital Flight Recorder | L3 AVIATION RECORDER | CMM w. IPC | 01.08.88 | 2 31.01.94 | 165E0049-00 | S | Model F800 | 3P |
| 17-M800-(XXX) | 31-30-01 | Digital Flight Recorder Model F800 | L3 AVIATION RECORDER | IOIM | 01.10.03 | 1 | 165E3359-00 | S | Supersedes FAR02283174 | 3P |
| S151-0060-00 | 23-70-05 | ED-56A Control Unit, Preamplifier Module and Microphone Module | L3 AVIATION RECORDER | CMM w. IPC | 01.09.00 | 9 06.05.14 | 165E0101-00 | S | | 3P |
| 17TES0423 | | FA2100CVR Audio & Data Link Player Software | L3 AVIATION RECORDER | IOIM | 01.06.04 | 1 01.04.07 | 165E3596-00 | S | | 3P |
| | | FA2100CVR Audio & Data Link Player Software | L3 AVIATION RECORDER | IOIM | 01.06.04 | 1 11.06.10 | 165E3596-01 | S | | 3P |
| | | FA2100CVR Audio & Data Link Player Software Operator's Manual (v3.3) | L3 AVIATION RECORDER | OM | 14.08.14 | | 165E3596-03 | S | Model FA2100 | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | | Doc.-No | S=Standard O=optional | R= Revision REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| S100-0080-00 | 23-70-02 | FA2100CVR Solid State Cockpit Voice Recorder | L3 AVIATION RECORDER | CMM w. IPC | 01.02.93 | 3 | 01.07.05 | 165E0948-00 | S | Model A100S | 3P |
| S800-2000/3000-00 | 31-30-02 | FA2100CVR Solid State Flight Data Recorder | L3 AVIATION RECORDER | CMM w. IPC | 01.08.91 | 5 | 01.03.04 | 165E0503-00 | S | Model F1000 | 3P |
| 2100-4043-00 | 31-30-03 | Flight Data Recorder | L3 AVIATION RECORDER | CMM w. IPC | 01.10.98 | 14 | 12.04.19 | 165E1688-00 | S | Model FA2100 | 3A |
| 2100-4043-00 | 31-30-03 | Flight Data Recorder | L3 AVIATION RECORDER | CMM w. IPC | 01.10.98 | 12 | 19.02.18 | 165E1688-00 | S | Model FA2100 | 3A |
| | 25-62-01 | L3AP UNDERWATER LOCATOR BEACON | L3 AVIATION RECORDER | CMM w. IPC | 24.04.15 | 5 | 15.05.17 | 165E5542-00 | S | FA2100 | 3P |
| QAR2XX-XX-XX | 31-30-20 | microQAR (Quick ACCESS RECORDER) | L3 AVIATION RECORDER | CMM w. OIM | 31.03.03 | 7 | 01.02.11 | 165E2810-0 | S | L3 | 3A |
| | | Model A100S Fairchild Solid State Cockpit Voice Recorder System | L3 AVIATION RECORDER | IOIM | 01.08.93 | | | FAR04611238 | S | | 3P |
| 046E0828-05 | | Model A200S Memory Test EPROM | L3 AVIATION RECORDER | IOIM | 13.07.01 | | | 165E2652-00 | S | | 3P |
| 147E1616-00 | | Model A200S Profiler Kit | L3 AVIATION RECORDER | IOIM | 18.07.01 | B | 27.06.01 | 165E1616-00 | S | | 3P |
| S200-0003-00/0003/90/12 | | Model A200S Solid State Cockpit Voice Recorder System | L3 AVIATION RECORDER | IOIM | 19.09.94 | 4 | 01.02.03 | 165E2685-00 | S | | 3P |
| 165E1630-00 | | Portable Interface | L3 AVIATION RECORDER | OM | 01.10.98 | 1 | 01.05.99 | VDN-0294 | S | | 3A |
| 165E1696-01 | | Read-Out Support Equipment RI | L3 AVIATION RECORDER | OM | 01.12.99 | | | VDN-0293 | S | | 3A |
| 93A055-XX / 93A151-XX | 23-70-02 | SOLID–STATE COCKPIT VOICE RECORDER (SSCVR) | L3 AVIATION RECORDER | CMM w. IPC | 01.02.93 | 3 | 01.07.05 | 165E0948-00 | S | Model A55X / Model A15X | 3P |
| S200-0012-00 | 23-70-03 | A200S Solid State Cockpit Voice Recorder | L3 COMMUNICATIONS | CMM w. IPC | 15.02.96 | 5 | 01.03.05 | 165E1233-00 | S | Model A200S | 3P |
| 501-1568-10 | 34-20-51 | AI-330 Attitude Indicator | L3 COMMUNICATIONS | IOM | 31.03.00 | C | 05.02.18 | TP-454 | S | BFG AVIONICS | 3A |
| 501-1568-() | | AI-330 Standby Attitude Indicator | L3 COMMUNICATIONS | PG | | D | 05.02.18 | TP-573 | O | | 3A |
| 2100-1220-xx | | Cockpit Voice Recorder | L3 COMMUNICATIONS | IOIM | 15.03.99 | 19 | 04.08.15 | 165E1846-00 | O | Model FA2100 | 3A |
| 501-1228-() | 24-30-04 | Emergency Power Supply JET Model PS-835 | L3 COMMUNICATIONS | IM | 01.07.94 | P | 20.03.17 | TP-336 | S | | 3A |
| 501-1228-03 | 24-30-02 | PS-835 Emergency Power Supply | L3 COMMUNICATIONS | CMM w. IPC | 01.09.95 | C, Chng4 | 25.07.19 | TP-329 | S | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | PS-835 Troubleshooting Guide | L3 COMMUNICATIONS | GUIDE | 06.06.08 | | | TP-607 | S | BFG AVIONICS | 3A |
| | | Cleaning Recommendations | LANTAL | CR | 01.11.12 | | | VDN-0123 | S | | 3A |
| | | Synthetics | LANTAL | CARE INSTR. | 13.04.01 | | | VDN-0297 | S | | 3A |
| | | Wool and Wool Blends | LANTAL | CARE INSTR. | 17.11.99 | | | VDN-0298 | S | | 3A |
| 407A0104 | 21-33-05 | Air Jet Pump | LIEBHERR | CMM w. IPC | 30.06.92 | 2 | 31.12.12 | VDN-0132 | S | ABG-SEMCA | 3A |
| 22260A/E010101 | 21-34-01 | Cabin Pressure Controller | LIEBHERR | CMM w. IPC | 15.12.92 | 5 | 15.06.99 | VDN-0127 | S | ABG-SEMCA | 3A |
| 2097H020900;2097P011400 | 21-34-03 | Electropneumatic Valve | LIEBHERR | CMM w. IPC | 20.11.92 | 6 | 15.01.06 | VDN-0125 | S | ABG-SEMCA | 3A |
| 234A0101 | 21-30-05 | Filter | LIEBHERR | CMM w. IPC | 21.01.85 | 2 | 01.06.11 | VDN-0476 | S | ABG-SEMCA | 3A |
| 1048A0000-02/-04 | 27-50-22 | Flap Actuator | LIEBHERR | CMM w. IPC | 30.10.95 | 2 | 20.10.00 | VDN-0135 | S | | 3A |
| 1053A0000-02 | 27-52-18 | Flap Control Switch | LIEBHERR | CMM w. IPC | 11.12.95 | 1 | 30.01.98 | VDN-0131 | S | | 3P |
| 1050A0000-XX | 27-52-10 | Flap Control Unit | LIEBHERR | CMM w. IPC | 30.01.98 | 2 | 26.09.04 | VDN-0133 | S | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1049A0000-02 | 27-52-12 | Flap Valve Block | LIEBHERR | CMM w. IPC | 30.06.93 | 1 | 30.01.98 | VDN-0130 | S | | | 3A |
| 1059A0000-02 | 27-62-10 | Ground Spoiler Actuator | LIEBHERR | CMM w. IPC | 30.09.93 | 1 | 30.12.99 | VDN-0116 | S | | | 3P |
| 1059A0000-03 | 27-62-11 | Ground Spoiler Actuator | LIEBHERR | CMM w. IPC | 09.09.98 | 1 | 15.07.14 | VDN-0117 | S | | | 3A |
| 1060A0000-06 | 27-62-12 | Ground Spoiler Valve Block | LIEBHERR | CMM w. IPC | 30.06.93 | 1 | 30.01.98 | VDN-0137 | S | | | 3P |
| 912V0201 | 21-34-02 | Manual Controller | LIEBHERR | CMM w. IPC | 01.09.92 | 3 | 24.11.08 | VDN-0134 | S | | ABG-SEMCA | 3P |
| 92105A010100 | 21-34-06 | Manual Indicator Module | LIEBHERR | CMM w. IPC | 02.11.92 | 1 | 04.03.98 | VDN-0124 | S | | ABG-SEMCA | 3A |
| 2099J020900;2099R011400 | 21-34-04 | Pneumatic Valve | LIEBHERR | CMM w. IPC | 01.12.92 | 6 | 30.05.13 | VDN-0129 | S | | | 3A |
| 1058A0000-03 | 27-62-16 | Roll Spoiler Actuator | LIEBHERR | CMM w. IPC | 30.09.93 | 2 | 28.08.19 | VDN-0136 | S | | | 3A |
| 1234A0000-01 | 27-72-01 | Rudder Gust Damper | LIEBHERR | CMM w. IPC | 28.11.96 | | | VDN-0335 | S | | | 3P |
| 1111C0000-01 | 27-09-50 | Solenoid Valve | LIEBHERR | CMM w. IPC | 30.09.93 | 1 | 02.02.18 | VDN-0469 | S | | | 3A |
| | 20-00-10 | Standard Practices Manual | LIEBHERR | SPM | 30.03.88 | 3 | 09.12.15 | VDN-0467 | S | | LIEBHERR | 3A |
| 234A0101 | 21-30-05 | Filter, Air | LIEBHERR TOUL | TCMS | 21.01.85 | 1 | 03.10.95 | VDN-0002 | S | | ABG-SEMCA | 3A |
| | 33-50-02 | Emergency Egress Lighting Syst. | LUMINESCENT | IPC | 01.05.99 | | | VDN-0139 | S | | | 3A |
| | 33-50-01 | Emergency Egress Lighting Syst. | LUMINESCENT | SMIM | 30.01.88 | 6 | 01.05.99 | VDN-0139 | S | | | 3A |
| AE20824 | 32-43-46 | Anti-Skid Conrol Unit | MABS | CMM w. IPC | 31.01.99 | 4 | 12.03.15 | AP-2129 | S | | | 3P |
| AE20464 / AE20768 | 32-43-36 | Anti-Skid Control Unit | MABS | CMM w. IPC | 09.10.92 | 4 | 12.03.15 | AP-2124 | S | | | 3P |
| 90002030 | 32-44-26 | Brake Assy | MABS | CMM w. IPC | 01.06.01 | 2 | 12.06.08 | AP-858 | S | | ABSC | 3P |
| AC70071 | 32-42-04 | Brake Metering Unit | MABS | CMM w. IPC | 15.06.01 | 4 | 12.03.15 | AP-2082 | S | | | 3P |
| AC69965, AC69965-2/-3 | 32-43-02 | Emergency/Park Brake Valve | MABS | CMM w. IPC | 31.10.97 | 8 | 12.03.15 | AP-2113 | S | | | 3P |
| ACM30488 | 32-43-31 | Hydraulic Fuse | MABS | CMM w. IPC | 20.04.93 | 6 | 12.03.15 | AP-2122 | S | | | 3P |
| ACM30492 | 32-43-30 | Master Cylinder | MABS | CMM w. IPC | 25.02.93 | 2 | 18.04.13 | AP-2121 | S | | | 3P |
| | 32-46-35 | Standard Practices Manual | MABS | SPM | 02.07.01 | 7 | 16.04.21 | AP-842 | S | | ABSC | 3A |
| ACM30496/30662 | 32-43-32 | Wheel Speed Transducer Installation | MABS | CMM w. IPC | 22.10.92 | 6 | 12.03.15 | AP-2123 | S | | | 3P |
| PC125 | 24-20-02 | 125 VA Static Inverter | MARATHON | CMM w. IPC | 01.08.78 | 2 | 02.08.95 | VDN-0141 | S | | | 3P |
| PC251 | 24-20-07 | 250 VA Static Inverter | MARATHON | CMM w. IPC | 01.07.81 | 2 | 26.09.89 | VDN-0142 | S | | | 3A |
| 30874-001 | 24-34-02 | Ni-Cad-Batterie Typ SP-747 | MARATHON | CMM w. IPC | 31.03.02 | 2 | 07.05.04 | VDN-0428 | S | | | 3A |
| DTSP-400L | 24-34-00 | Nickel-Cadmium Aircraft Batteries | MARATHON | OMM | 23.06.97 | 18 | 17.06.20 | DCR60741 | S | | | 3A |
| 24125-000-00 | 32-31-06 | Actuating Cylinder | MESSIER-DOWTY | CMM w. IPC | 31.03.92 | 4 | 15.07.06 | VDN-0145 | S | | | 3A |
| | | Air Drying Epoxide Paint Scheme | MESSIER-DOWTY | SPM | 05.05.14 | | | M-DLPS618 | S | | | 3A |
| | | Air Dryling Polyurethane Paint Scheme | MESSIER-DOWTY | SPM | 02.08.14 | | | M-DLPS615 | S | | | 3A |
| | | Anodising of Aluminium and Aluminium Alloys | MESSIER-DOWTY | SPM | 02.07.14 | | | M-DLPS102 | S | | | 3A |
| | | Anti-Stone Chip Polysulphide Coating | MESSIER-DOWTY | SPM | 30.03.05 | 4 | 30.06.14 | PCS-7204 | S | | | 3A |
| | | Application of Tungsten Carbide Cobalt Chromium (4%) Coatings on Metallic Parts by High Velocity Oxygen/Fuel Process | MESSIER-DOWTY | SPM | 01.08.02 | 5 | 17.09.14 | PCS-2560 | S | | | 3A |
| | | Application of Loctite | MESSIER-DOWTY | SPM | 25.10.07 | 3 | 19.09.13 | PCS-5303 | S | | SAFRAN | 3A |
| | | Approval of Personnel for NON-Destructive Testing | MESSIER-DOWTY | SPM | 06.08.08 | 15 | 11.01.14 | M-DLNDT10 | S | | | 3A |
| | | Assembly of Bushes Using Primer Paint | MESSIER-DOWTY | SPM | 26.07.06 | 2 | 15.10.14 | PCS-5120 | S | | | 3A |
| 24260-000-00/-01/-02 | 32-11-12 | Brace Assy | MESSIER-DOWTY | CMM w. IPC | 15.09.93 | 5 | 31.12.12 | VDN-0147 | S | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 23200-000-01/02 | 32-21-16 | Brace Assy | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0347 | S | | | 3P |
| | | Brush Plating | MESSIER-DOWTY | SPM | 01.03.63 | 7 08.12.14 | M-DLPS118 | S | | | 3A |
| | | Cleaning and Preparation of Steel for Plating | MESSIER-DOWTY | SPM | 30.05.08 | 8 18.09.13 | M-DLPS207 | S | | | 3A |
| | | CONSUMABLE MATERIALS LIST | MESSIER-DOWTY | CML | 10.11.14 | 1 19.12.14 | MBD-CML | S | | SAFRAN | 3A |
| | | Controlled Areas for Assembly and Test | MESSIER-DOWTY | SPM | 10.12.09 | 5 04.09.13 | M-DLPS927 | S | | | 3A |
| | | Corrosion Protection of Parts by Application of Corrosion Inhibiting Compounds | MESSIER-DOWTY | SPM | 01.03.12 | 3 12.06.14 | PCS-2831 | S | | | 3A |
| | | Decarburisation & Carburisation Control of Heat Treated Steel Parts | MESSIER-DOWTY | SPM | 14.04.14 | | PCS-1150 | S | | | 3A |
| 22910-000-01 | 32-07-15 | Electrical Harness | MESSIER-DOWTY | CMM w. IPC | 31.07.98 | 1 15.07.06 | VDN-0289 | S | | | 3P |
| 22915-000-01 | 32-07-16 | Electrical Harness | MESSIER-DOWTY | CMM w. IPC | 31.07.98 | 1 15.07.06 | VDN-0290 | S | | | 3P |
| 22760/22765-000-00 | 32-07-17 | Electrical Harness | MESSIER-DOWTY | CMM w. IPC | 31.07.98 | 1 15.07.06 | VDN-0318 | S | | | 3P |
| | | Electrolytic Hard Chromium Plating os Steels | MESSIER-DOWTY | SPM | 23.11.05 | 5 09.07.13 | PCS-2110 | S | | SAFRAN | 3A |
| 23180-000-01/-02 | 32-51-08 | Electronic Control Unit | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0352 | S | | | 3A |
| | | Glass and Ceramic Bead Peening | MESSIER-DOWTY | SPM | 11.12.07 | 5 30.10.13 | M-DLPS134 | S | | | 3A |
| | | Guide for On-Line Appl. of a Repair Design Solution | MESSIER-DOWTY | SPM | 01.10.11 | 2 12.12.13 | GUIDE-CS-001 | S | | SAFRAN | 3A |
| Index Pub. | | History of the CMM | MESSIER-DOWTY | CMM w. IPC | 15.04.97 | 6 01.07.13 | 20269 | S | | | 3A |
| | | Inspection of Titanium Alloy Parts | MESSIER-DOWTY | SPM | 25.06.07 | 5 11.02.14 | PCS-3601 | S | | | 3A |
| | | List of Cutting Fluids for Machinig of Metallic Parts and Coatings | MESSIER-DOWTY | SPM | 04.11.12 | 2 04.07.13 | PCS-4002 | S | | | 3A |
| | | Low Temperature Stoving Paint Scheme for Magnesium Alloys | MESSIER-DOWTY | SPM | 01.04.63 | 7 28.10.14 | M-DLPS602 | S | | | 3A |
| 22730/22731-000-XX | 32-11-01 | Main - Leg | MESSIER-DOWTY | CMM w. IPC | 31.05.92 | 9 31.12.12 | VDN-0353 | S | | | 3P |
| 22515/6-000-00 | 32-11-00 | Main Landing Gear | MESSIER-DOWTY | IPC | 01.05.93 | 4 29.05.09 | VDN-0419 | O | | ERAM | 3A |
| | | Mechanical Finishing of HVOF Sprayed Thungsten Carbide Cobalt Chromium Coatings | MESSIER-DOWTY | SPM | 30.05.02 | 4 24.09.13 | PCS-4102 | S | | | 3A |
| | | Metal Spraying | MESSIER-DOWTY | SPM | 13.11.70 | 3 18.03.14 | M-DLPS503 | S | | | 3A |
| 22455-000-00/-1 | 32-32-00 | MLG - Assist Actuator | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0153 | S | | Supersedes 22455-000-00 | 3A |
| 22730/22731-000-XX | 32-00-01 | MLG - Operating Instructions | MESSIER-DOWTY | T. LEAFL. | 01.04.91 | 2 01.09.93 | VDN-0144 | O | | | 3P |
| 23200-300-00/-01/-2 | 32-21-32 | NLG - Brace Assembly | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0350 | S | | Supersedes Rev.1 May 15/1999 | 3A |
| 23285-000-00 | 32-07-22 | NLG - Electrical Control Harness | MESSIER-DOWTY | CMM w. IPC | 05.11.01 | 1 15.07.06 | VDN-0354 | S | | | 3P |
| 23425-000-00 | 32-07-24 | NLG - Electrical Power Harness | MESSIER-DOWTY | CMM w. IPC | 05.11.01 | 1 15.07.06 | VDN-0356 | S | | | 3P |
| 23055-000-00 | 32-07-21 | NLG - Feedback Potentiometer Harness | MESSIER-DOWTY | CMM w. IPC | 05.11.01 | 1 15.07.06 | VDN-0375 | S | | | 3A |
| 23415-000-00 | 32-07-23 | NLG - Main Electrical Harness | MESSIER-DOWTY | CMM w. IPC | 05.11.01 | 1 15.07.06 | VDN-0355 | S | | | 3P |
| 23100-000-00 /-1/-2/-3 | 32-00-02 | NLG - Operating Instructions | MESSIER-DOWTY | T. LEAFL. | 30.09.92 | 2 07.03.95 | VDN-0152 | O | | | 3P |
| 23100-300-00-/-1-4 | 32-21-30 | NLG - Shock Strut Assembly | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0155 | S | | Supersedes 23100-300-00 | 3A |
| 23100-000-00 /-1/-2/-3 | 32-21-00 | NLG - Shock Strut Assembly | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0481 | S | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 22495-000-01 | 32-31-04 | NLG - Unlock Actuator | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0279 | S | | Supersedes 22495-000-00 | 3A |
| 23265-000-00 | 32-07-28 | NLG - Uplock Electrical Harness | MESSIER-DOWTY | CMM w. IPC | 05.11.01 | 1 15.07.06 | VDN-0377 | S | | | 3P |
| | | Penetrant Inspection of Ground Chrome Plated Parts | MESSIER-DOWTY | SPM | 25.06.09 | 2 10.04.14 | PCS-3002 | S | | | 3A |
| | | Processing requirements for Ultra High Strength Steels | MESSIER-DOWTY | SPM | 12.09.67 | 4 30.09.14 | M-DLPS914 | S | | SAFRAN | 3A |
| 22890-000-01 | 32-31-09 | Restrictor Check Valve | MESSIER-DOWTY | TDS | 31.05.93 | 1 31.01.95 | VDN-0148 | S | | | 3A |
| 22895-000-01 | 32-31-10 | Restrictor Check Valve | MESSIER-DOWTY | TDS | 31.05.93 | 1 31.01.95 | VDN-0149 | S | | | 3A |
| 24120-000-00 | 32-31-11 | Restrictor Check Valve | MESSIER-DOWTY | TDS | 31.05.93 | 1 31.01.95 | VDN-0151 | S | | | 3A |
| 23110-000-01 | 32-21-01 | Shock Absorber | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0156 | S | | | 3P |
| 22420-000-XX | 32-11-04 | Shock Absorber | MESSIER-DOWTY | CMM w. IPC | 31.03.92 | 8 31.12.12 | VDN-0348 | S | | | 3P |
| 23110-300-00 | 32-21-31 | Shock Absorber | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0351 | S | | | 3A |
| | | Silver Brazing | MESSIER-DOWTY | SPM | 29.11.06 | 7 25.09.13 | M-DLPS303 | S | | | 3A |
| | 20-00-10 | Standard Practices Manual | MESSIER-DOWTY | SPM | 15.10.08 | 9 15.01.12 | VDN-0460 | S | | Supersedes CMM 31-09-01 | 3A |
| 23040-000-01 | 32-51-07 | Steering Control Valve | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0143 | S | | | 3A |
| | | Surface Compr. Stressing and Bushing Instl. | MESSIER-DOWTY | SPM | 27.03.09 | 2 30.05.12 | PCS-7500 | S | | SAFRAN | 3A |
| | | The Chromate Treatment of Magnesium Alloys | MESSIER-DOWTY | SPM | 01.08.06 | 6 08.01.14 | M-DLPS103 | S | | | 3A |
| | | The Chromium Plating of Aluminium Alloys | MESSIER-DOWTY | SPM | 01.02.63 | 4 08.12.14 | M-DLPS119 | S | | | 3A |
| | | Top - Cot Colours of Low Voc Paint as Per PCS-2530 | MESSIER-DOWTY | SPM | 28.07.10 | 4 08.04.13 | PCS-2531 | S | | | 3A |
| | | Traceability and Identification of Material | MESSIER-DOWTY | SPM | 06.09.13 | 1 17.09.13 | PCD-MBD-102 | S | | | 3A |
| 22445-000-00 | 32-31-07 | Unlocking Cylinder | MESSIER-DOWTY | CMM w. IPC | 30.04.92 | 3 15.07.06 | VDN-0418 | S | | ERAM | 3A |
| 22405-000-02/03/04 | 32-31-05 | Uplock Assembly | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0154 | S | | | 3P |
| 026-675-0 | 32-45-01 | Aircraft Tire Care & Service Manual | MICHELIN | CSM | 01.01.01 | 15.12.11 | VDN-0360 | S | | | 3P |
| 14328-001/-002 | 38-35-03 | Toilet Assembly | MONOGRAM | CMM w. IPC | 30.09.91 | 3 15.02.96 | VDN-0157 | S | | | 3A |
| 190755-XXX | 76-10-61 | Engine Control Cable Assembly | MORSE | CMM w. IPC | 01.02.93 | 1 01.01.94 | 190755 | S | | | 3P |
| 250205/001-004 | 76-10-62 | Engine Control Cable Assembly | MORSE | CMM w. IPC | 01.01.94 | | VDN-0159 | S | | | 3P |
| 251174 | 27-70-01 | Gust Lock Control | MORSE | CMM w. IPC | 01.05.95 | 1 01.11.96 | VDN-0158 | S | | | 3P |
| 106098/106098A | 25-30-39 | AFT Galley R/H | MÜHLENBERG | CMM w. IPC | 25.06.93 | C 19.03.96 | VDN-0258 | S | | | 3P |
| 106100/A/B/C | 25-30-40 | AFT Galley R/H | MÜHLENBERG | CMM w. IPC | 25.06.93 | B 15.04.96 | VDN-0259 | S | | | 3A |
| 106100D, 106100L | 25-30-82 | AFT Galley R/H | MÜHLENBERG | CMM w. IPC | 15.02.00 | 2 10.10.01 | VDN-0262 | S | | | 3A |
| 106100F | 25-30-84 | AFT Galley R/H | MÜHLENBERG | CMM w. IPC | 15.02.00 | 2 12.12.07 | VDN-0264 | S | | | 3A |
| 105146 | 25-28-20 | Foldable Trolley Stowage | MÜHLENBERG | CMM w. IPC | 25.07.95 | | VDN-0251 | S | | | 3A |
| 105148 | 25-28-40 | Galley | MÜHLENBERG | CMM w. IPC | 30.11.96 | | VDN-0253 | S | | | 3P |
| 106100E | 25-30-83 | Galley AFT R/H | MÜHLENBERG | CMM w. IPC | 15.02.00 | 1 10.03.00 | VDN-0263 | S | | | 3A |
| 113218 | 25-29-21 | Music Entertainment Cabinet | MÜHLENBERG | CMM w. IPC | 29.12.00 | 1 12.04.01 | VDN-0256 | S | | | 3A |
| 103141 | 25-28-44 | QC - Wardrobe | MÜHLENBERG | CMM w. IPC | 30.01.97 | | VDN-0254 | S | | | 3A |
| 106101 | 25-30-42 | Small Galley | MÜHLENBERG | CMM w. IPC | 01.08.94 | B 15.04.96 | VDN-0260 | S | | | 3A |
| 106101A | 25-30-47 | Small Galley | MÜHLENBERG | CMM w. IPC | 30.09.96 | | VDN-0261 | S | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 113197/113198 | 25-28-38 | Stowages | MÜHLENBERG | CMM w. IPC | 30.08.96 | | VDN-0252 | S | | | 3A |
| 3029B000-002 | 21-30-21 | 1/4" Non Return Valve | NGL | CMM w. IPC | 10.12.74 | 1 12.05.99 | 1372 | S | | | 3P |
| 5409C000 | 21-61-05 | Bay Temperature Sensor | NGL | MM | 12.05.92 | 1 07.07.08 | 2393 | S | | | 3A |
| 1716D000-002 | 21-51-11 | Cold Air Unit | NGL | MM | 25.05.94 | 1 26.05.98 | 2515 | O | | | 3A |
| 8555C000 | 21-51-13 | Condenser/Water Extractor | NGL | CMM w. IPC | 21.05.96 | 2 07.01.11 | 2390 | S | | | 3A |
| 8563C000 | 21-51-13 | Condenser/Water Extractor | NGL | CMM w. IPC | 21.05.96 | 3 22.09.00 | 2512 | S | | | 3A |
| 8554C000 | 21-51-12 | Dual Heat Exchanger | NGL | MM | 08.05.92 | 2 10.04.95 | 2388 | O | | | 3A |
| 5403C000 | 21-61-06 | Duct Temperature Limiter | NGL | CMM w. IPC | 13.06.92 | | 2403 | S | | | 3A |
| 5410C000 | 21-61-04 | Duct Temperature Sensor | NGL | MM | 06.05.92 | 1 04.03.11 | 2381 | S | | | 3A |
| 5729C000,-002,-003 | 21-51-10 | Environmental Control Unit | NGL | MM with IPL | 14.06.94 | 1 10.01.10 | 2510 | O | | | 3P |
| 4053B000 | 21-21-04 | Non-Return Valve 165 mm (6.5 in) | NGL | MM | 23.06.92 | | 2397 | O | | | 3A |
| 4053B000 | 21-21-04 | Non-Return Valve 165 mm (6.5 in) | NGL | CMM w. IPC | 11.11.92 | 1 12.12.95 | 2398 | S | | | 3A |
| 4040B000 | 36-11-11 | Non-Return Valve 2.5 inch (6,3 50 mm) | NGL | MM | 22.04.92 | 1 01.07.10 | 2370 | O | | | 3A |
| 3907B000 | 21-51-22 | Non-Return Valve 63,5 mm (2.5 in) | NGL | MM | 29.04.92 | | 2375 | O | | | 3A |
| 4066B000-002 | 36-11-41 | Non-Return Valve, 2 inch (50.8 mm) | NGL | MM | 23.02.99 | | 2705 | O | | | 3A |
| 4066B000-002 | 36-11-41 | Non-Return Valve, 2 inch (50.8 mm) | NGL | CMM w. IPC | 04.03.99 | | 2706 | S | | | 3A |
| 5586C000 | 21-51-14 | Over Temperature Switch | NGL | MM | 05.05.92 | 1 24.03.99 | 2380 | S | | | 3A |
| 5584C000 | 36-11-04 | Over Temperature Switch | NGL | MM | 23.08.91 | | 2407 | S | | | 3A |
| 5677C000 | 21-51-16 | Pneumatic Temperature Sensor | NGL | MM | 09.06.92 | | 2399 | O | | | 3A |
| 4067B000-004 | 36-11-42 | Press.Reduc. And Shut-Off Valve | NGL | MM | 23.02.99 | | 2707 | O | | | 3A |
| 4067B000-004 | 36-11-42 | Press.Reduc. And Shut-Off Valve | NGL | CMM w. IPC | 23.02.99 | | 2708 | S | | | 3A |
| 4067B000-002 | 36-11-03 | Pressure Reducing a.Shut Off Valve | NGL | MM | 07.05.92 | 2 01.07.10 | 2384 | O | | | 3P |
| 5623C000 | 21-51-15 | Turbine Inlet Control Valve | NGL | CMM w. IPC | 20.10.92 | 1 17.01.96 | 2387 | S | | | 3A |
| 5732C000 | 21-51-15 | Turbine Inlet Control Valve | NGL | MM | 24.05.94 | | 2513 | O | | | 3A |
| WL101AMS1 | 34-11-41 | Altimeter/Airspeed Indicator | ONTIC | CMM w. IPC | 20.11.01 | 4 02.09.16 | VDN-0420 | S | | was GE Aviation | 3A |
| 35001016-1 | 26-20-10 | Discharge Indicator Assy | PACIFIC SCIENTIFIC | CMM w. IPC | 01.02.76 | 1 15.02.94 | VDN-0175 | S | | | 3A |
| 33500012-1/13-1 | 26-22-54 | Fire Extinguisher | PACIFIC SCIENTIFIC | CMM w. IPC | 15.06.99 | 1 15.01.05 | VDN-0281 | S | | | 3A |
| 33100016-1/33600042-1 | 26-22-37 | Single Outlet Fire Extinguishers | PACIFIC SCIENTIFIC | CMM w. IPC | 15.02.94 | 4 15.06.04 | VDN-0174 | S | | | 3A |
| 34200408-1 | 26-23-50 | Single Outlet Metering Fire Extinguisher | PACIFIC SCIENTIFIC | CMM w. IPC | 15.11.00 | | VDN-0280 | S | | | 3A |
| QB0471 | 21-02-71 | Filter Element | PALL | CMS | 27.05.94 | | VDN-0176 | S | | | 3A |
| QB0470 | 21-02-70 | Filter Element | PALL | CMS | 27.05.94 | | VDN-0177 | S | | | 3A |
| QA07390 / QA07704 | 29-11-07 | Main Filter Package | PALL | CMM w. IPC | 31.01.95 | 3 12.12.16 | VDN-0006 | S | | | 3P |
| QA07376-01 / QA07770 | 29-10-76 | Pressure Sensing Valve | PALL | CMM w. IPC | 31.01.95 | 2 14.01.20 | VDN-0199 | S | | | 3P |
| QA07770 | 29-10-78 | Pressure Sensing Valve | PALL | CMM w. IPC | 09.07.14 | | VDN-0498 | S | | | 3A |
| 3900001-101 to -109 | 29-10-29 | 3000 PSI Ribbed Shell Accumulator | PARKER | CMM w. IPC | 12.09.91 | 8 07.03.14 | VDN-0178 | S | | 3900001-101/-105/-107/-108/-109 | 3A |
| 1C12-42 | | Centrifugal Fuel Boost Pump | PARKER | CMM w. IPC | 21.09.10 | | CM1C12-42 | S | | | 3A |
| 1C12-42 | 28-21-12 | Centrifugal Fuel Boost Pump | PARKER | CMM w. IPC | 23.05.00 | | VDN-0179 | S | | | 3P |
| 42086/4208601 | 29-10-50 | Electric Motor Driven Variable Delivery Hydraulic Pump | PARKER | CMM w. IPC | 01.09.93 | 1 01.03.03 | VDN-0433 | S | | | 3P |
| 4208601 | 29-10-50 | Insert facing page 118 | PARKER | TR-29-410 | 28.09.11 | | VDN-0433 | S | | | 3A |
| 4208601 | 29-10-50 | Introduction of P/N 4208601 | PARKER | TR-29-409 | 28.09.11 | | VDN-0433 | S | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 41590-200 | | Pressure compensated elbow bellows joint | PERKINELMER | GRS | 30.11.01 | | GR-0021C | O | | | 3P |
| 3360 | 29-21-02 | Relief Valve and Pressure Dump | PneuDraulics | CMM w. IPC | 24.09.09 | | 06177-3360 | S | | | 3P |
| 3040346 | | Airworthiness Limitations PW119B/C | PWC | ALM | 01.02.93 | 8 22.06.09 | 3040346 | S | | | 3P |
| 3041330 | 79-30-02 | Chip Detectors/Collectors a.Valves | PWC | CMM w. IPC | 18.01.95 | | 3041330 | S | | | 3P |
| 3053125 | 79-31-02 | Chip Detectors/Collectors and Valves | PWC | CMM w. IPC | 01.07.99 | 5 11.09.15 | 3053125 | S | | | 3A |
| 3043340 | | CONSUMABLE MATERIALS LIST | PWC | CML | 01.03.96 | 16 02.05.06 | 3043340 | S | | | 3P |
| 3041321 | 71-50-10 | Electrical Wiring Harness | PWC | ACMM | 16.08.93 | 6 24.07.15 | 3041321 | S | | | 3P |
| | | Engine Condition Trend Monitoring Sys. | PWC | SIL INDEX | 05.05.89 | 3 31.03.97 | | O | | | 3P |
| 3038533 | 72-XX-XX | Engine Manual PW119B / 119C | PWC | EM | 26.04.93 | 20 04.09.17 | 3038533 | O | | CD-ROM only | 3P |
| 3038533 | 72-XX-XX | Engine Manual PW119B / 119C | PWC | TR 72-5 | 12.01.18 | | 3038533 | O | | | 3P |
| 3038533 | 72-XX-XX | Engine Manual PW119B / 119C | PWC | TR 72-6 | 20.02.18 | | 3038533 | O | | | 3P |
| 3040589 | | Engine Module Sampling Program | PWC | MANUAL | 19.03.93 | | 3040589 | O | | | 3P |
| 3040878 | | Facility Equipment and Planning Manual | PWC | FEPM | 30.06.96 | 7 13.08.07 | 3040878 | O | | | 3A |
| 3040878 | | Facility Planning Manual | PWC | FPM | 13.08.07 | | 3040878 | O | | CD-ROM only | 3A |
| | 73-11-40 | Flexible Fuel Manifold | PWC | ACMM | 01.07.99 | 6 09.04.15 | 3043611 | S | | | 3P |
| 3037038 | 73-10-03 | Fuel Manifold Adapter | PWC | CMM w. IPC | 27.09.89 | 8 18.07.97 | 3037038 | S | | | 3P |
| 3037326 | 73-10-04 | Fuel Manifold Adapter | PWC | CMM w. IPC | 09.11.89 | 8 18.07.97 | 3037326 | S | | | 3P |
| 3056640 | 73-10-05 | Fuel Manifold Adapter | PWC | CMM w. IPC | 01.03.03 | 7 22.01.16 | 3056640 | S | | | 3P |
| 3040598 | 72-03-00 | Hot Section Inspection PW119B/C | PWC | HSIM | 01.10.93 | 21 06.10.06 | 3040598 | O | | CD-ROM only | 3P |
| 3036423 | 74-20-01 | Ignition Cables | PWC | CMM w. IPC | 30.01.87 | 3 10.12.09 | 3036423 | S | | | 3P |
| 3041332 | 77-20-02 | Immersion Thermocouples | PWC | CMM w. IPC | 15.02.96 | 3 21.07.15 | 3041332 | S | | | 3P |
| | | Index of Publ. For Engine Model PW119 | PWC | INDEX | 30.04.98 | | AIP (PW119) | O | | | 3P |
| 3036422 | 75-30-02 | Intercompressor Bleed Valve Assy | PWC | CMM | 30.05.96 | 7 30.10.15 | 3036422 | S | | | 3P |
| 3036422 | 75-30-02 | Intercompressor Bleed Valve Assy | PWC | CMM w. IPC | 30.01.87 | 5 18.02.10 | 3036422 | S | | | 3P |
| 3038534 | 72-00-00 | IPC for PW119B/119C | PWC | IPC | 26.04.93 | 54 18.07.22 | 3038534 | O | | | 3P |
| 3072152 | 72-XX-XX | Maintenance Manual PW119B / PW119C | PWC | MM | 30.06.14 | 17 27.05.22 | 3072152 | O | | | 3P |
| 3045331 | 77-21-08 | MOT Sonsor a/o T6 Trim Thermocouple | PWC | CMM w. IPC | 01.07.99 | 1 01.09.00 | 3045331 | S | | | 3A |
| | | Num. Index of Service Tool Bulletins | PWC | INDEX | 01.09.00 | | VDN-0206 | O | | | 3A |
| | | Num. Index PW100 Engine SB | PWC | INDEX | 31.10.01 | | ABX (PW100) SB | O | | | 3P |
| | | Num. Index PW100 Engine SPB | PWC | INDEX | 30.04.01 | | ABX (PW100) SPB | O | | | 3P |
| | | Num. Index PW119B/C Engine SB | PWC | INDEX | 30.09.02 | | ABO (PW119B/C) SB | O | | | 3P |
| | | Num. Index PW119B/C Engine SPB | PWC | INDEX | 30.09.02 | | ABO (PW119B/C) SPB | O | | | 3P |
| | | Numerical Index of SIL | PWC | INDEX | 17.02.03 | | COB SIL | O | | | 3A |
| 3041329 | 79-30-01 | Oil Press.Differential Switch or Indicator | PWC | CMM w. IPC | 16.09.93 | 4 26.08.16 | 3041329 | S | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Omnibus Index PW100Engine SB/SPB | PWC | INDEX | 30.01.98 | | VDN-0202 | O | | | 3P |
| 3036421 | 75-30-01 | P2.5 Check Valve | PWC | CMM w. IPC | 30.01.87 | 4 05.09.08 | 3036421 | S | | | 3P |
| | | Publications Status Report | PWC | INDEX | 10.09.09 | | VDN-0473 | O | | | 3A |
| 3033125 | | PW100 S Facility Planning Manual | PWC | MANUAL | 25.01.85 | 8 28.09.95 | 3033125 | O | | | 3P |
| 3040879 | | PW100 Workscope Planning Guide | PWC | WPG | 04.06.99 | 23 30.06.19 | 3040879 | O | | | 3P |
| 3039739 | | Specific Operating Instr. PW119A | PWC | SOI | 27.01.92 | 1 03.04.92 | BSN 792 | O | | | 3P |
| 3040588 | | Specific Operating Instr. PW119B/C | PWC | SOI | 26.02.93 | 5 15.11.96 | BSN 824/878 | O | | | 3P |
| 3043640 | 77-11-06 | Speed Sensors | PWC | CMM w. IPC | 01.07.99 | 4 13.06.14 | 3043640 | S | | Replaces 77-10-01/-02 | 3A |
| 585005 | 72-XX-XX | Standard Practices Manual | PWC | SPM | 01.10.66 | 130 01.12.11 | 52A138 | O | | CD-ROM only | 3A |
| 3041323 | 77-20-01 | T6 Trim Cable | PWC | CMM w. IPC | 16.08.93 | | 3041323 | S | | | 3P |
| 3041327 | 77-20-05 | T6 Trim Thermocouple Electrical Cable | PWC | CMM w. IPC | 16.08.93 | 3 09.02.10 | 3041327 | S | | | 3P |
| 3041328 | 77-20-06 | Temperature Sensor | PWC | CMM w. IPC | 16.08.93 | 3 26.08.16 | 3041328 | S | | | 3P |
| 3040888 | | Test Facility Planning Manual | PWC | TFPM | 13.05.99 | 5 15.10.05 | 3040888 | O | | CD-ROM only | 3A |
| | 77-11-04 | Torque Probe and/or Torque Sensor | PWC | CMM w. IPC | 01.07.99 | 5 20.11.15 | 3045330 | O | | | 3P |
| 3041331 | 77-10-04 | Torque Sensor | PWC | CMM w. IPC | 16.08.93 | | 3041331 | S | | | 3P |
| FE255-000/-001 | 27-70-06 | Rudder Damper Assembly | RATIER FIGEAC | CMM w. IPC | 15.01.96 | 4 02.06.20 | VDN-0210 | S | | | 3A |
| FE217-004 | 27-70-05 | Rudder Damper Assembly | RATIER FIGEAC | CMM w. IPC | 25.03.92 | 4 28.02.03 | VDN-0212 | S | | | 3P |
| FE211-002/-003/-004/-005 | 27-20-01 | Rudder Pedals Assembly | RATIER FIGEAC | CMM w. IPC | 20.12.91 | 1 03.06.96 | VDN-0211 | S | | | 3P |
| FE309000000 | 27-20-03 | Rudder Pedals Assembly | RATIER FIGEAC | CMM w. IPC | 15.06.98 | 2 16.02.21 | VDN-0230 | S | | | 3A |
| 4990DO-2 | 30-13-12 | Air Pressure Regulator Valve | ROGERSON | CMM w. IPC | 01.07.95 | | VDN-0219 | S | | | 3P |
| 84400-3 | 30-13-01 | Check Valve | ROGERSON | CMM w. IPC | 01.07.95 | | VDN-0221 | S | | | 3A |
| 85100-3 | 30-13-06 | Ejector Flow Valve | ROGERSON | CMM w. IPC | 01.07.95 | | VDN-0223 | S | | | 3P |
| 5150DO-1 | 30-13-09 | Isolation Valve | ROGERSON | CMM w. IPC | 01.07.95 | | VDN-0220 | S | | | 3P |
| 83900-1 | 36-11-09 | Pre-Cooler | ROGERSON | CMM w. IPC | 01.07.95 | | VDN-0225 | S | | | 3P |
| 85000-5 | 30-13-10 | Pressure Switch | ROGERSON | CMM w. IPC | 01.07.95 | | VDN-0222 | S | | | 3P |
| 30013 | 28-42-03 | Sensor, Fuel Level | ROGERSON | CMM w. IPC | 15.07.95 | | VDN-0217 | S | | | 3A |
| 30011-4 | 28-41-04 | Sensor, Tank Unit, Feeder Tank | ROGERSON | CMM w. IPC | 15.07.95 | | VDN-0216 | S | | | 3A |
| 30011-1 | 28-41-01 | Sensor, Tank Unit, Innertank | ROGERSON | CMM w. IPC | 15.07.95 | | VDN-0224 | S | | | 3A |
| 30011-3 | 28-41-03 | Sensor, Tank Unit, Outertank | ROGERSON | CMM w. IPC | 15.07.95 | | VDN-0214 | S | | | 3A |
| 30011-2 | 28-41-02 | Sensor, Tank Unit, Outertank | ROGERSON | CMM w. IPC | 15.07.95 | | VDN-0215 | S | | | 3A |
| 40006 | 28-23-10 | Signal Processing /Refueling Panel | ROGERSON | CMM w. IPC | 15.07.95 | 1 17.11.09 | 9967-0246 | S | | | 3P |
| 5570DO-3 | 30-13-11 | Water Separator | ROGERSON | CMM w. IPC | 01.07.95 | | VDN-0213 | S | | | 3P |
| 0861EF1 | 34-12-27 | Angle Of Attack Sensor | ROSEMOUNT | CMM w. IPC | 15.02.92 | | VDN-0231 | S | | | 3A |
| 0871DW1 | 30-81-17 | ICE Detector | ROSEMOUNT | CMM w. IPC | 01.11.90 | | VDN-0209 | S | | | 3A |
| 1060K | 73-21-50 | Immersion Temperatur Sensor Assembly | ROSEMOUNT | CMM w. IPC | 01.01.99 | | VDN-0190 | S | | | 3A |
| 0851GW / 0851GW-1 | 34-10-73 | Pitot Tube | ROSEMOUNT | CMM w. IPC | 01.09.98 | 1 15.03.00 | VDN-0085 | S | | | 3A |
| 011291-500 | 21-25-03 | Avionics Aft Fan | ROTRON | CMM w. IPC | 22.05.95 | 1 22.09.97 | VDN-0233 | S | | AMETEK | 3A |
| 011292-500 | 21-25-01 | EFIS Fan | ROTRON | CMM w. IPC | 01.04.95 | | VDN-0235 | S | | AMETEK | 3A |
| 011389-502 | 21-51-23 | Ground Cooling Fan | ROTRON | CMM w. IPC | 15.11.94 | 2 29.04.10 | VDN-0234 | S | | AMETEK | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| 717801-1 | 32-31-01 | LANDING GEAR CONTROL ASSEMBLY | SAFRAN | CMM w. IPC | 01.07.95 | 1 22.06.16 | VDN-0408 | S | SAGEM | 3A |
| 4337122/38 | 30-41-03 | Motor-Converter | SAFRAN | CMM w. IPC | 31.12.91 | 5 22.08.19 | VDN-0246 | S | Ex ZODIAC | 3A |
| 8410/-1 | 27-12-03 | Roll Trim Actuator | SAFRAN | CMM w. IPC | 30.12.94 | 6 29.04.11 | VDN-0033 | S | AVIAC | 3A |
| 8408/-1 | 27-22-03 | Yaw Trim Actuator | SAFRAN | CMM w. IPC | 31.01.94 | 5 09.11.11 | VDN-0035 | S | SAGEM/AVIAC | 3A |
| 3759-2 | 24-30-00 | Aircraft Battery | SAFT | CMM w. IPC | 01.09.94 | | VDN-0322 | S | | 3A |
| 2778-1 | 24-30-00 | Aircraft Battery | SAFT | CMM w. IPC | 01.04.95 | 1 24.04.18 | VDN-0323 | S | | 3A |
| 4078-4 | 24-31-16 | Aircraft Battery | SAFT | CMM w. IPC | 01.02.91 | | VDN-0324 | S | | 3A |
| | | Allowed Temperature Tolerance during Testing | SAFT | TN | 01.01.09 | 1 01.11.18 | TN10 | O | | 3A |
| | | End of life cells | SAFT | TN | 01.03.08 | | TN7 | O | | 3A |
| | | Insulation Check | SAFT | TN | | 5 01.04.20 | TN2 | O | | 3A |
| | | MEMO / Dangerous Goods Transortation repuirements | SAFT | TN | 06.05.19 | | SQ-19-0166_A1_PhB | O | | 3A |
| | | O-ring on cells terminals | SAFT | TN | | 3 01.04.20 | TN13 | O | | 3A |
| | | Placing a battery in service | SAFT | TN | 01.10.08 | | TN8 | O | | 3A |
| | | Preparation before storage batteries | SAFT | TN | | 4 01.04.20 | TN3 | O | | 3A |
| | | Saft and NiCd aircraft battery maintenance | SAFT | TN | | 3 01.08.15 | TN5 | O | | 3A |
| | | Saft Ni-Cd Aviation Battery life | SAFT | TN | 01.03.08 | 3 01.04.20 | TN6 | O | | 3A |
| | | Saft Ni-Cd aviation battery storage recommendations | SAFT | TN | | 11 01.10.20 | TN1 | O | | 3A |
| | | Torque Check | SAFT | TN | 01.03.09 | | TN9 | O | | 3A |
| | | Transport Requirements | SAFT | TN | | 4 09.12.09 | CM\TranspReqs | O | | 3A |
| | | Various calibrated methods to test thermistors and thermostats | SAFT | TN | 01.11.15 | | TN11 | O | | 3A |
| 8432-1 | 27-33-03 | Stick Pusher Actuator | SAGEM | CMM w. IPC | 15.03.94 | 6 08.04.19 | VDN-0031 | S | AVIAC | 3A |
| 328300-1M02/3 | 27-11-02 | Cable Tension Regulator (Aileron Contr.) | SARMA | CMM w. IPC | 10.07.95 | 1 29.12.00 | VDN-0198 | S | | 3A |
| 328300-2M02/3 | 27-11-02 | Cable Tension Regulator (Aileron Contr.) | SARMA | CMM w. IPC | 10.07.95 | 1 29.12.00 | VDN-0236 | S | | 3A |
| 328100-2M03AMDT-A | 27-31-02 | Cable Tension Regulator (Elevator Contr.) | SARMA | CMM w. IPC | 10.07.95 | 2 29.12.00 | VDN-0195 | S | | 3A |
| 328100-1M03AMDT-A | 27-31-02 | Cable Tension Regulator (Elevator Contr.) | SARMA | CMM w. IPC | 10.07.95 | 2 29.12.00 | VDN-0197 | S | | 3A |
| 328600 M02 | 27-31-11 | Force Detector Rod | SARMA | CMM w. IPC | 20.04.95 | 1 28.02.01 | VDN-0312 | S | | 3A |
| 488-221 | | Pressure Fuel Servicing Cap | SHAW | SM | 08.05.98 | | ILS-033 | S | | 3A |
| 331-0001-01 | 38-30-08 | Waste Drain Valve | SHAW | CMM w. IPC | 15.06.95 | | 331-0001-01 | S | | 3A |
| WL1001KCA1 | 34-25-21 | Standby Compasses | SIRS NAVIGATION | CMM w. IPC | 10.04.03 | 11 | VDN-0431 | S | former Smiths Ind. Aero | 3A |
| 10839X | 73-10-08 | Fuel Heater | STEWART WARNER | CMM w. IPC | 15.06.92 | 6 19.01.00 | 10839 | S | IPC P&WC | 3P |
| SPSDO328-1/2-X-X | 56-11-81 | Front Windshield LH/RH | SULLY | CMM w. IPC | 01.01.95 | 1 01.02.01 | VDN-0241 | S | SPS.Do328.211 | 3A |
| 001A561A0000214 | 56-13-83 | Glass Side Cockpit Window LH/RH | SULLY | CMM w. IPC | 01.10.99 | 1 01.05.01 | VDN-0240 | S | SPS.Do328.4.1.1 | 3A |
| 001A562A0015002 | 56-21-84 | Passenger Window LH/RH | SULLY | CMM w. IPC | 01.01.95 | 1 01.10.99 | VDN-0239 | S | SPS.Do328.6.1.0 | 3A |
| HP1594100-1 | 29-20-01 | Dual Stage Hydraulic Hand Pump | TACTAIR | CMM w. IPC | 15.12.95 | | VDN-0243 | S | | 3P |
| HP848800-4 | 32-30-02 | Landing Gear Control Valve | TACTAIR | CMM w. IPC | 01.08.95 | | VDN-0242 | S | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| HP848800 | 32-30-02 | Landing Gear Control Valve | TACTAIR | TR 32-01 | 24.04.13 | | VDN-0242 | S | | 3A |
| GB2001AA1 | 21-51-24 | Check Valve | TECHNOFAN | CMM w. IPC | 01.09.00 | 1 01.01.01 | VDN-0244 | S | | 3A |
| 600100-00/-10-500 | 30-10-28 | Timer, De-Icing | TELAIR | CMS | 02.12.97 | | VDN-0245 | S | NORD-MICRO | 3A |
| 4298816/-09 | 30-41-04 | Wiper-Arm LH/RH | TELEFLEX | CMS | 01.03.92 | 1 01.07.00 | VDN-0247 | S | ZODIAC | 3A |
| 4298823 | 30-41-05 | Wiper-Blade | TELEFLEX | CMS | 01.03.92 | 1 01.09.94 | VDN-0248 | S | ZODIAC | 3A |
| 40351 | | Application Guide Honeywell Carry-On VXP | TELEMETER ELECTRONIC | AG | 04.02.11 | | TAG-X328 | O | | 3P |
| 40514 | | User Guide for Honeywell Carry-On VXP | TELEMETER ELECTRONIC | UG | 04.03.11 | | TUG-X328 | O | Chapter 1-5 | 3P |
| 177310 | 28-21-11 | Fuel Booster Pump | TEST-FUCHS | CMM w. IPC | 04.04.96 | 2 21.01.11 | VR 1007 | S | | 3P |
| 705000 | 29-12-02 | Hydraulic DC Standby Pump | TEST-FUCHS | CMM w. IPC | 19.09.16 | | 705000 | S | | 3A |
| PVP 5055-00 | | Pump Valve Panel Assy | TEST-FUCHS | OI | 31.01.08 | 2 21.02.08 | VR 1013 | S | | 3A |
| 103-020-0 | 24-32-16 | Hall Effect Current Sensor | THALES | TCMS | 16.11.92 | 4 02.05.13 | VDN-0313 | S | AUXILEC | 3A |
| 8160-121 | 24-35-32 | Starter Generator | THALES | CMM w. IPC | 01.06.92 | 3 26.04.22 | VDN-0027 | S | AUXILEC (THALES) | 3A |
| | | Aviator 200/300/350 | THRANE | UM | 13.03.12 | | 98-127719-D | S | | 3A |
| 74-20 | 26-24-05 | Halon 1/1,2/2,5 | TOTAL FEUERSCHUTZ | CMM w. IPC | 01.07.15 | | J 74/76-00 | S | AIR TOTAL | 3A |
| 25910-1 to -8, 25910-09, | 73-10-08 | Ejector Pump and Tank Assy. | TRW / LUCAS | CMM w. IPC | 15.12.84 | 6 20.12.02 | VDN-0191 | S | P&WC P/N: 3033856, 3039330, 3041468, 3055635-01 | 3P |
| 25910 | 73-10-08 | Ejector Pump and Tank Assy. | TRW / LUCAS | TR 73-1 | 11.02.05 | | VDN-0191 | S | IPC P&WC | 3P |
| 25910 | 73-10-08 | Ejector Pump and Tank Assy. | TRW / LUCAS | TR 73-2 | 31.03.05 | | VDN-0191 | S | IPC P&WC | 3P |
| 26200/260 | 73-10-15 | Flow Divider and Dump Valve | TRW / LUCAS | CMM w. IPC | 31.12.92 | 3 31.05.05 | VDN-0193 | S | IPC P&WC | 3P |
| 3039695/3121593-01 | 74-10-58 | High Energy Ignition Unit | TRW / LUCAS | CMM w. IPC | 06.01.93 | 3 18.10.95 | VDN-0194 | S | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | CMM w. IPC | 01.05.83 | 10 28.06.02 | VDN-0192 | S | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | TR 73-10 | 19.07.00 | | VDN-0192 | S | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | TR 73-11 | 18.06.03 | | VDN-0192 | S | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | TR 73-12 | 20.04.04 | | VDN-0192 | S | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | TR 73-13 | 01.06.05 | | VDN-0192 | S | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | TR 73-14 | 15.09.05 | | VDN-0192 | S | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | TR 73-8 | 15.05.95 | | VDN-0192 | S | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | TR 73-9 | 29.03.96 | | VDN-0192 | S | IPC P&WC | 3P |
| 3D3556-01/-03 | 30-10-48 | Ejector Flow Control Valve | UTC | CMM w. IPC | 01.02.02 | 1 30.01.20 | VDN-0227 | S | Goodrich / BFG ICE | 3A |
| 4D2095-200/220 | 30-10-43 | Pressure Regulator/Reliever | UTC | CMM w. IPC | 01.02.02 | 2 31.08.20 | VDN-0126 | S | Goodrich | 3P |
| 208CC02Y1 | 24-39-59 | SPST NO CONTACTOR | ZODIAC AERO ELECTRIC | ACMM w. IPC | 04.11.15 | | 208CC02Y1 | S | | 3A |
| 220GC02Y01/230GC01/-04 | 24-39-55 | DC Junction Box | ZODIAC AEROSPACE | CMM w. IPC | 15.06.94 | 8 12.05.14 | VDN-0082 | S | | 3A |

# CHAPTER 2

# VENDOR PUBLICATIONS

## Sort ATA–Chapter Code

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Epoxy Adhesive 1751 B/A | 3M | SPM | 01.12.09 | | TDS 1751 B-A | S | | Supersedes Messier Dowty DCMP-156 | 3A |
| | | Adhesive Transfer Tapes with Adhesive 300 | 3M | SPM | 01.09.02 | | TDS 950 | S | | | 3A |
| | | Polyurethane Protective Tape 8672/8672 GB (Gloss black) | 3M | SPM | 01.04.13 | | TDS PPT8672_2013 | S | | | 3A |
| AR9874-3 + AR9877 Series | | Installation AR9874-3 + AR9877 Series Water System | ADAMS RITE | OM | 04.04.03 | 1 14.05.08 | AR9895-38-01 | S | | | 3A |
| | | KLN 900 Pilot´s Guide GPS | ALLIEDSIGNAL | PG | 02.01.99 | 2 | 006-08796-0000 | O | | | 3A |
| | | KHF950/990 Pilot´s Guide for HF | ALLIEDSIGNAL | PG | 01.12.96 | | 006-18038-0000 | O | | | 3A |
| 965-0976-0XX | | MK V Enhanced Ground Proximity Warning System Enhanced Ground Proximity Warning System | ALLIEDSIGNAL | IDG | 01.10.99 | | 060-4199-125 | S | | HONEYWELL | 3A |
| 76021 | | Baggage Net Freight Compartment | ALLSAFE | CMM w. IPC | 03.07.96 | F 18.01.18 | BST-639/96 | S | | | 3A |
| 110022-10 | | Baggage Net Door | ALLSAFE | CMM w. IPC | 03.07.96 | E 18.01.18 | BST-641/96 | S | | | 3A |
| VD3870 | | Mixed Flow Fan | AOA | CMM w. IPC | 15.01.91 | 3 21.10.91 | VD3870 | S | | | 3A |
| 453-0150 | | Emergency Locator Transmitters | ARTEX | DOIMM | 26.04.96 | G 29.08.06 | 570-1015 | S | | ELT 110-4 | 3A |
| 110-337 | | Emergency Locator Transmitters 406MHz | ARTEX | DOIMM | 10.12.02 | B 25.08.08 | 570-5000 | S | | ELT C406-2, C406-2HM | 3A |
| 119003, 119063, 4401005 | | Protective Breathing Equipment | B/E AERO PURITAN | GUIDE | 06.04.90 | 13 21.09.21 | 2499-200 | O | | PURITAN BENNETT | 3A |
| K9321060A04, K9321062A01 | | DU-875 Display Unit | BARCO | CMM w. IPC | 15.12.09 | | K5920116-02 | S | | | 3A |
| 064-1015-01 | | KHF 950 HF/SSB Communication System | BENDIX | MM w. IPL | 01.05.82 | 4 04.05.83 | 006-05190-0004 | S | | Bendix King | 3A |
| | | Aero-M/I Antenna TT-5006A | CHELTON ANTENNAS | IM | 04.02.05 | | 677-A00022_IM | S | | COBHAM | 3A |
| 802-10-0010 | | SwiftBroadband Intermediate Gain Antenna IGA-5001 | CHELTON ANTENNAS | IM | 20.03.09 | 7 10.04.14 | 677-A0181_IM | S | | COBHAM | 3A |
| | | SwiftBroadband HLD-7260 | COBHAM | IM | 16.11.07 | 2 11.03.14 | 862-A0101_IM | S | | | 3A |
| 07-110-9200 | | Battery Adapter P/N 07-110-9200 | DIEHL | UG | 06.12.04 | 6 18.09.17 | 0432401 | O | | | 3A |
| | | Capability List (Management Manual - Appendix I) | DIEHL | CL | 19.02.10 | 23 22.07.22 | MH-000-0006 | S | | | 3A |
| | | Aircraft Tyres and Tubes | DUNLOP | GPM | 02.01.08 | | DM1172 | S | | Supersedes GSI DM1172 | 3A |
| AE20462 | | Anti - Skid Test Set | DUNLOP | GEM | 15.04.93 | | DM1636-00 | S | | | 3A |
| AE20462 | | Interface for Anti - Skid Test Set | DUNLOP | GEM | 15.04.93 | | DM1636-01 | S | | | 3A |
| 8-700 | | Failure Indication - Quick Reference Guide | ELDEC | QRG | 16.10.00 | | QRG8-700 | S | | Now is CRANE | 3A |
| DP3113 (A) | | Crewmember Protective Breathing Equipment (PBE) | ESSEX | GUIDE | | 24 24.02.17 | PRM-01 | O | | | 3A |
| 001A251A4400 | | Head-Up Guidance System Model 2700 | FLIGHT DYNAMICS | PG | 01.11.94 | 1 01.05.96 | 523-0809568 | S | | ROCKWELL COLLINS | 3A |
| DC24/50/1 | | Operating Instruction for Mini.Vacuum Pump | FUERGUT | OI | 26.08.02 | | VDN-0421 | O | | | 3A |
| | | Aircraft Tire Data Book | GOOD YEAR | DB | 01.10.02 | | 700-862-931-522 | S | | | 3A |
| | | Manual Revision Status | HARTZELL | PI | 13.11.09 | 337 02.12.14 | VDN-0472 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| F20/40 / F20/27 H1CT70 | | Aircraft Battery | HAWKER | OVMM | 01.01.01 | | VDN-0325 | S | | | 3A |
| 3800498-1/-3 | | Standard Practices Manual | HONEYWELL | SPM | 28.10.77 | 22 11.12.19 | 20-00-02-70-00-01 | S | | | 3A |
| | | PM-CPDLC MK2 CMU | HONEYWELL | PM | 16.11.11 | A | 69001561-001 | O | | | 3P |
| 996-5106-XXX | | Equalizer-MH/C - Digital Audio Equalizer | HONEYWELL | MM | 02.12.03 | A 19.02.04 | 763-1014-001 | S | | | 3P |
| | | TNL8100 GPS Navigation System ARINC CDU | HONEYWELL | PG | 29.02.96 | D 25.06.99 | 81803-01 | O | | TRIMBLE | 3P |
| | | Index of Publications | HONEYWELL | INDEX | 15.05.98 | 42 01.07.07 | A01-9000-006 | O | | | 3A |
| | | PRIMUS II Integr.Radio System | HONEYWELL | EC | 01.06.91 | | A04-3800-01-00 | O | | | 3P |
| | | Handling, Storage, Shipping Avion.Equip. | HONEYWELL | INSTR. M | 10.03.78 | 14 01.08.06 | A09-1100-001 | S | | | 3A |
| | | Stand.Rep.Procedures Avionic Equipment | HONEYWELL | SRM | 01.04.94 | 7 01.02.08 | A09-1100-004 | O | | | 3A |
| 7001840-922/-932 | | AA-300 Radio Altimeter System | HONEYWELL | SDIM | 15.08.80 | 12 15.01.09 | A15-3321-006 | S | | consists RT-300 | 3A |
| | | Index Service Bulletins/Technical Newsletter | HONEYWELL | INDEX | 08.06.98 | 34 01.07.07 | A21-9000-002 | O | | | 3A |
| | | PRIMUS II Integr.Radio System | HONEYWELL | PM | 01.11.87 | 7 01.08.00 | A28-1146-050 | O | | | 3A |
| | | PRIMUS 2000 Integr.Avionics System | HONEYWELL | TR 1 | 01.10.94 | | A28-1146-086 | O | | | 3P |
| | | PRIMUS 2000 Integr.Avionics System | HONEYWELL | PM | 01.08.93 | 1 01.11.93 | A28-1146-086 | O | | | 3P |
| | | PRIMUS 880 Digital Weather Radar | HONEYWELL | PM | 01.09.96 | 3 01.01.06 | A28-1146-102 | O | | | 3A |
| | | PRIMUS 660 Digital Weather Radar | HONEYWELL | PM | 01.02.98 | 3 01.08.03 | A28-1146-111 | O | | | 3A |
| FMZ Series | | Flight Management System Vers.4.1 | HONEYWELL | PM | 01.07.96 | | A28-1146-113 | O | | | 3P |
| | | PRIMUS II Integr.Radio Syst.RM-855 RMU | HONEYWELL | PM | 01.02.99 | 3 01.10.11 | A28-1146-121 | O | | | 3A |
| FMZ Series | | Flight Management System Vers.4.8 | HONEYWELL | PM | 01.08.97 | 1 01.01.00 | A28-1146-122 | O | | | 3P |
| | | PRIMUS 2000 Integr.Avionics Syst.w.GAU | HONEYWELL | PM | 01.03.00 | | A28-1146-139 | O | | | 3P |
| 7510114-811/901/855 | | Test Software Revision M for the DF-850/855 ADF Assembly | HONEYWELL | TB | 19.08.11 | | A45-3818-2463 | O | | | 3P |
| | | RNZ-850 Instal./Removal Instructions | HONEYWELL | IRI | 01.02.92 | 8 01.06.04 | A62-0096-000 | O | | | 3P |
| | | RCZ-850 Instal./Removal Instructions | HONEYWELL | IRI | 01.09.95 | 4 01.03.99 | A62-0097-000 | O | | | 3P |
| | | Tech. Pub. Index for Commercial Aviation | HONEYWELL | INDEX | 29.12.03 | | CA-INDEX | O | | | 3A |
| SRZ-85X | | PRIMUS II SRZ-85X Integr.Radio Syst. | HONEYWELL | OIM | 10.10.87 | 16 27.07.20 | D198710000004 | O | | Supersedes A15-3800-001 | 3A |
| HG2021GD04 | | Global Navigation System Sensor Unit | HONEYWELL | SIM | 21.11.08 | | D200809000030 | S | | Esterline (CMC Electronics) | 3A |
| | | Honeywell Flight Management Systems (FMS) NZ-2000 | HONEYWELL | SIL | 10.11.10 | 2 08.08.11 | D201010000079 | O | | | 3A |
| | | Tech.Pub.Index for General Aviation | HONEYWELL | INDEX | 29.12.03 | | GA-INDEX | O | | | 3A |
| G7228-01 | | Data Loader 1000 | HONEYWELL | IM | 30.06.09 | | IST.G7228-01 | S | | GABLES | 3A |
| G7830-() | | Control Display Unit CD-830 | HONEYWELL | IM | 09.12.14 | 3 05.06.15 | IST.G7830-() | S | | GABLES | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| HG2001 GD03/GD20/GD40 | | HOLDERS OF THE HG2001GD03/GD20/GD40 INERTIAL REFERENCE UNIT PILOT'S GUIDE | HONEYWELL | PM | 01.09.98 | 1 01.08.10 | M28-3343-003 | O | | 3P |
| 6900094X | | MKV-A EGPWS | HONEYWELL | IM | 14.10.13 | D 20.04.16 | PDS69000940-501 | O | | 3P |
| | | TRA-45A Pilot Guide / Terrain Awareness and Display System | HONEYWELL | PG | 01.03.04 | 2 | PG80-5145 | O | EGPWS | 3P |
| | | Workscope Planning Guide for 36-150 APU | HONEYWELL ASIG | WPG | 25.04.03 | | 31-16647-15 | O | ALLIEDSIGNAL | 3A |
| | | CMM, SB, SIL Landing Gear Equipm. | HONEYWELL ASIG | INDEX | 01.03.98 | 18 31.01.06 | FORM 12-536 | O | ALLIEDSIGNAL | 3A |
| 064-01073-0102 | | KHF 1050/PS440 Pilot's Guide | HONEYWELL BENDIX | PG | | 1 01.05.03 | 006-18289-0000 | O | Bendix King | 3A |
| | | Traffic Alert Collision Avoid.Syst. (TCAS) | HONEYWELL L3 | PM | 01.10.90 | 4 01.09.00 | A28-1146-070 | O | L3 | 3P |
| | | Traffic Collision Avoidance System 2000 | HONEYWELL L3 | PG | 01.09.99 | | C28-3841-005 | O | ACCS-L3 | 3A |
| Suppl.for PG C28-3841-005 | | Traffic Collision Avoidance System 2000 | HONEYWELL L3 | SUPPL | 01.05.00 | 1 01.08.00 | C28-3841-006 | O | ACCS-L3 | 3A |
| 500-12, 16, 27 | | MULTI FUNCTION PERSONAL LOCATOR BEACON (PLB) PERSONAL LOCATOR BEACON (PLB) | HR-SMITH | MM | | 15 20.10.14 | HRS1002-5-00 | O | | 3A |
| Model SG103 | | Hydraulic Axle Jack Mod. SG103 | HYDRO | TH | 01.03.00 | | VDN-0113 | O | | 3A |
| Model RH0802 | | Hydraulic Axle Jack Mod. RH0802 | HYDRO | TH | 01.09.99 | | VDN-0114 | O | | 3A |
| 35XXX-XXX-XXX | | Cont.Fire a.Overheat Detection Sys. | KIDDE-DEUGRA | INSTR.M | 01.11.80 | 4 15.08.96 | 505 | S | HAMILTON SUNDSTRAND | 3A |
| | | Pressure Transducer | KULITE | ATP | 06.09.90 | E 10.03.99 | 2952 | O | APTE-133-1000-XXX | 3P |
| | | Oil Pressure Sensor | KULITE | ATP | 09.10.90 | G 24.04.96 | 2953 | O | IPTE-75GF-1000-70D | 3P |
| | | Pressure Transducer | KULITE | ATP | 28.03.91 | D 24.04.96 | 2982 | O | APTE-137-1000-200 | 3P |
| | | Low Oil Pressure Switch | KULITE | ATP | 08.07.93 | E 20.05.96 | 3104 | O | APS-3D-1000-1000A | 3A |
| | | Underwater Locator Beacon | L3 | IOIM | 03.11.16 | | 165E5542-10 | S | FA2100 | 3P |
| | | TCAS 2000/3000 Pilot's Guide | L3 ACSS | PG | 16.08.07 | | 8006773-001 | O | ACSS-L3 | 3A |
| | | TCAS II / TCAS 2000 (Change 7.1) Pilot's Guide Supplement | L3 ACSS | PG | 31.10.09 | 1 15.01.12 | 8008110-001 | O | ACSS-L3 | 3P |
| 147E1616-00 | | Model A200S Profiler Kit | L3 AVIATION RECORDER | IOIM | 18.07.01 | B 27.06.01 | 165E1616-00 | S | | 3P |
| 046E0828-05 | | Model A200S Memory Test EPROM | L3 AVIATION RECORDER | IOIM | 13.07.01 | | 165E2652-00 | S | | 3P |
| S200-0003-00/0003/90/12 | | Model A200S Solid State Cockpit Voice Recorder System | L3 AVIATION RECORDER | IOIM | 19.09.94 | 4 01.02.03 | 165E2685-00 | S | | 3P |
| 93AXXXXX | | Cockpit Voice Recorder | L3 AVIATION RECORDER | IOIM | | 2 01.07.02 | 165E2807-00 | S | Supersedes FAR02213189 | 3A |
| 17TES0423 | | FA2100CVR Audio & Data Link Player Software | L3 AVIATION RECORDER | IOIM | 01.06.04 | 1 01.04.07 | 165E3596-00 | S | | 3P |
| | | FA2100CVR Audio & Data Link Player Software | L3 AVIATION RECORDER | IOIM | 01.06.04 | 1 11.06.10 | 165E3596-01 | S | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | | FA2100CVR Audio & Data Link Player Software Operator's Manual (v3.3) | L3 AVIATION RECORDER | OM | 14.08.14 | | 165E3596-03 | S | Model FA2100 | 3A |
| S00-0003-() | | A200S Solid State Cockpit Voice Recorder - Notification of Obsolescense | L3 AVIATION RECORDER | SIL | 20.07.06 | 1 23.08.06 | A200S SCVR 003 | O | Model A200S | 3A |
| | | Model A100S Fairchild Solid State Cockpit Voice Recorder System | L3 AVIATION RECORDER | IOIM | 01.08.93 | | FAR04611238 | S | | 3P |
| 165E1696-01 | | Read-Out Support Equipment RI | L3 AVIATION RECORDER | OM | 01.12.99 | | VDN-0293 | S | | 3A |
| 165E1630-00 | | Portable Interface | L3 AVIATION RECORDER | OM | 01.10.98 | 1 01.05.99 | VDN-0294 | S | | 3A |
| 2100-1220-xx | | Cockpit Voice Recorder | L3 COMMUNICATIONS | IOIM | 15.03.99 | 19 04.08.15 | 165E1846-00 | O | Model FA2100 | 3A |
| 501-1568-() | | AI-330 Standby Attitude Indicator | L3 COMMUNICATIONS | PG | | D 05.02.18 | TP-573 | O | | 3A |
| | | Cleaning Recommendations | LANTAL | CR | 01.11.12 | | VDN-0123 | S | | 3A |
| | | Synthetics | LANTAL | CARE INSTR. | 13.04.01 | | VDN-0297 | S | | 3A |
| | | Wool and Wool Blends | LANTAL | CARE INSTR. | 17.11.99 | | VDN-0298 | S | | 3A |
| Index Pub. | | History of the CMM | MESSIER-DOWTY | CMM w. IPC | 15.04.97 | 6 01.07.13 | 20269 | S | | 3A |
| | | Guide for On-Line Appl. of a Repair Design Solution | MESSIER-DOWTY | SPM | 01.10.11 | 2 12.12.13 | GUIDE-CS-001 | S | SAFRAN | 3A |
| | | CONSUMABLE MATERIALS LIST | MESSIER-DOWTY | CML | 10.11.14 | 1 19.12.14 | MBD-CML | S | SAFRAN | 3A |
| | | Approval of Personnel for NON-Destructive Testing | MESSIER-DOWTY | SPM | 06.08.08 | 15 11.01.14 | M-DLNDT10 | S | | 3A |
| | | Anodising of Aluminium and Aluminium Alloys | MESSIER-DOWTY | SPM | 02.07.14 | | M-DLPS102 | S | | 3A |
| | | The Chromate Treatment of Magnesium Alloys | MESSIER-DOWTY | SPM | 01.08.06 | 6 08.01.14 | M-DLPS103 | S | | 3A |
| | | Brush Plating | MESSIER-DOWTY | SPM | 01.03.63 | 7 08.12.14 | M-DLPS118 | S | | 3A |
| | | The Chromium Plating of Aluminium Alloys | MESSIER-DOWTY | SPM | 01.02.63 | 4 08.12.14 | M-DLPS119 | S | | 3A |
| | | Glass and Ceramic Bead Peening | MESSIER-DOWTY | SPM | 11.12.07 | 5 30.10.13 | M-DLPS134 | S | | 3A |
| | | Cleaning and Preparation of Steel for Plating | MESSIER-DOWTY | SPM | 30.05.08 | 8 18.09.13 | M-DLPS207 | S | | 3A |
| | | Silver Brazing | MESSIER-DOWTY | SPM | 29.11.06 | 7 25.09.13 | M-DLPS303 | S | | 3A |
| | | Metal Spraying | MESSIER-DOWTY | SPM | 13.11.70 | 3 18.03.14 | M-DLPS503 | S | | 3A |
| | | Low Temperature Stoving Paint Scheme for Magnesium Alloys | MESSIER-DOWTY | SPM | 01.04.63 | 7 28.10.14 | M-DLPS602 | S | | 3A |
| | | Air Dryling Polyurethane Paint Scheme | MESSIER-DOWTY | SPM | 02.08.14 | | M-DLPS615 | S | | 3A |
| | | Air Drying Epoxide Paint Scheme | MESSIER-DOWTY | SPM | 05.05.14 | | M-DLPS618 | S | | 3A |
| | | Processing requirements for Ultra High Strength Steels | MESSIER-DOWTY | SPM | 12.09.67 | 4 30.09.14 | M-DLPS914 | S | SAFRAN | 3A |
| | | Controlled Areas for Assembly and Test | MESSIER-DOWTY | SPM | 10.12.09 | 5 04.09.13 | M-DLPS927 | S | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Traceability and Identification of Material | MESSIER-DOWTY | SPM | 06.09.13 | 1 17.09.13 | PCD-MBD-102 | S | | 3A |
| | | Decarburisation & Carburisation Control of Heat Treated Steel Parts | MESSIER-DOWTY | SPM | 14.04.14 | | PCS-1150 | S | | 3A |
| | | Electrolytic Hard Chromium Plating os Steels | MESSIER-DOWTY | SPM | 23.11.05 | 5 09.07.13 | PCS-2110 | S | SAFRAN | 3A |
| | | Top - Cot Colours of Low Voc Paint as Per PCS-2530 | MESSIER-DOWTY | SPM | 28.07.10 | 4 08.04.13 | PCS-2531 | S | | 3A |
| | | Application of Tungsten Carbide Cobalt Chromium (4%) Coatings on Metallic Parts by High Velocity Oxygen/Fuel Process | MESSIER-DOWTY | SPM | 01.08.02 | 5 17.09.14 | PCS-2560 | S | | 3A |
| | | Corrosion Protection of Parts by Application of Corrosion Inhibiting Compounds | MESSIER-DOWTY | SPM | 01.03.12 | 3 12.06.14 | PCS-2831 | S | | 3A |
| | | Penetrant Inspection of Ground Chrome Plated Parts | MESSIER-DOWTY | SPM | 25.06.09 | 2 10.04.14 | PCS-3002 | S | | 3A |
| | | Inspection of Titanium Alloy Parts | MESSIER-DOWTY | SPM | 25.06.07 | 5 11.02.14 | PCS-3601 | S | | 3A |
| | | List of Cutting Fluids for Machinig of Metallic Parts and Coatings | MESSIER-DOWTY | SPM | 04.11.12 | 2 04.07.13 | PCS-4002 | S | | 3A |
| | | Mechanical Finishing of HVOF Sprayed Thungsten Carbide Cobalt Chromium Coatings | MESSIER-DOWTY | SPM | 30.05.02 | 4 24.09.13 | PCS-4102 | S | | 3A |
| | | Assembly of Bushes Using Primer Paint | MESSIER-DOWTY | SPM | 26.07.06 | 2 15.10.14 | PCS-5120 | S | | 3A |
| | | Application of Loctite | MESSIER-DOWTY | SPM | 25.10.07 | 3 19.09.13 | PCS-5303 | S | SAFRAN | 3A |
| | | Anti-Stone Chip Polysulphide Coating | MESSIER-DOWTY | SPM | 30.03.05 | 4 30.06.14 | PCS-7204 | S | | 3A |
| | | Surface Compr. Stressing and Bushing Instl. | MESSIER-DOWTY | SPM | 27.03.09 | 2 30.05.12 | PCS-7500 | S | SAFRAN | 3A |
| 1C12-42 | | Centrifugal Fuel Boost Pump | PARKER | CMM w. IPC | 21.09.10 | | CM1C12-42 | S | | 3A |
| 41590-200 | | Pressure compensated elbow bellows joint | PERKINELMER | GRS | 30.11.01 | | GR-0021C | O | | 3P |
| | | Engine Condition Trend Monitoring Sys. | PWC | SIL INDEX | 05.05.89 | 3 31.03.97 | | O | | 3P |
| 3033125 | | PW100 S Facility Planning Manual | PWC | MANUAL | 25.01.85 | 8 28.09.95 | 3033125 | O | | 3P |
| 3040346 | | Airworthiness Limitations PW119B/C | PWC | ALM | 01.02.93 | 8 22.06.09 | 3040346 | S | | 3P |
| 3040589 | | Engine Module Sampling Program | PWC | MANUAL | 19.03.93 | | 3040589 | O | | 3P |
| 3040878 | | Facility Planning Manual | PWC | FPM | 13.08.07 | | 3040878 | O | CD-ROM only | 3A |
| 3040878 | | Facility Equipment and Planning Manual | PWC | FEPM | 30.06.96 | 7 13.08.07 | 3040878 | O | | 3A |
| 3040879 | | PW100 Workscope Planning Guide | PWC | WPG | 04.06.99 | 23 30.06.19 | 3040879 | O | | 3P |
| 3040888 | | Test Facility Planning Manual | PWC | TFPM | 13.05.99 | 5 15.10.05 | 3040888 | O | CD-ROM only | 3A |
| 3043340 | | CONSUMABLE MATERIALS LIST | PWC | CML | 01.03.96 | 16 02.05.06 | 3043340 | S | | 3P |
| | | Num. Index PW119B/C Engine SB | PWC | INDEX | 30.09.02 | | ABO (PW119B/C) SB | O | | 3P |
| | | Num. Index PW119B/C Engine SPB | PWC | INDEX | 30.09.02 | | ABO (PW119B/C) SPB | O | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Num. Index PW100 Engine SB | PWC | INDEX | 31.10.01 | | ABX (PW100) SB | O | | | 3P |
| | | Num. Index PW100 Engine SPB | PWC | INDEX | 30.04.01 | | ABX (PW100) SPB | O | | | 3P |
| | | Index of Publ. For Engine Model PW119 | PWC | INDEX | 30.04.98 | | AIP (PW119) | O | | | 3P |
| 3039739 | | Specific Operating Instr. PW119A | PWC | SOI | 27.01.92 | 1 03.04.92 | BSN 792 | O | | | 3P |
| 3040588 | | Specific Operating Instr. PW119B/C | PWC | SOI | 26.02.93 | 5 15.11.96 | BSN 824/878 | O | | | 3P |
| | | Numerical Index of SIL | PWC | INDEX | 17.02.03 | | COB SIL | O | | | 3A |
| | | Omnibus Index PW100Engine SB/SPB | PWC | INDEX | 30.01.98 | | VDN-0202 | O | | | 3P |
| | | Num. Index of Service Tool Bulletins | PWC | INDEX | 01.09.00 | | VDN-0206 | O | | | 3A |
| | | Publications Status Report | PWC | INDEX | 10.09.09 | | VDN-0473 | O | | | 3A |
| | | Transport Requirements | SAFT | TN | | 4 09.12.09 | CM\TranspReqs | O | | | 3A |
| | | MEMO / Dangerous Goods Transortation repuirements | SAFT | TN | 06.05.19 | | SQ-19-0166_A1_PhB | O | | | 3A |
| | | Saft Ni-Cd aviation battery storage recommendations | SAFT | TN | | 11 01.10.20 | TN1 | O | | | 3A |
| | | Allowed Temperature Tolerance during Testing | SAFT | TN | 01.01.09 | 1 01.11.18 | TN10 | O | | | 3A |
| | | Various calibrated methods to test thermistors and thermostats | SAFT | TN | 01.11.15 | | TN11 | O | | | 3A |
| | | O-ring on cells terminals | SAFT | TN | | 3 01.04.20 | TN13 | O | | | 3A |
| | | Insulation Check | SAFT | TN | | 5 01.04.20 | TN2 | O | | | 3A |
| | | Preparation before storage batteries | SAFT | TN | | 4 01.04.20 | TN3 | O | | | 3A |
| | | Saft and NiCd aircraft battery maintenance | SAFT | TN | | 3 01.08.15 | TN5 | O | | | 3A |
| | | Saft Ni-Cd Aviation Battery life | SAFT | TN | 01.03.08 | 3 01.04.20 | TN6 | O | | | 3A |
| | | End of life cells | SAFT | TN | 01.03.08 | | TN7 | O | | | 3A |
| | | Placing a battery in service | SAFT | TN | 01.10.08 | | TN8 | O | | | 3A |
| | | Torque Check | SAFT | TN | 01.03.09 | | TN9 | O | | | 3A |
| 488-221 | | Pressure Fuel Servicing Cap | SHAW | SM | 08.05.98 | | ILS-033 | S | | | 3A |
| 40351 | | Application Guide Honeywell Carry-On VXP | TELEMETER ELECTRONIC | AG | 04.02.11 | | TAG-X328 | O | | | 3P |
| 40514 | | User Guide for Honeywell Carry-On VXP | TELEMETER ELECTRONIC | UG | 04.03.11 | | TUG-X328 | O | | Chapter 1-5 | 3P |
| PVP 5055-00 | | Pump Valve Panel Assy | TEST-FUCHS | OI | 31.01.08 | 2 21.02.08 | VR 1013 | S | | | 3A |
| | | Aviator 200/300/350 | THRANE | UM | 13.03.12 | | 98-127719-D | S | | | 3A |
| | 20-00-01 | NDT of Aircraft Wheels | DUNLOP | GPM | 21.05.84 | | VDN-0317 | S | | | 3A |
| | 20-00-01 | Mechanical Standard Practices | HAMILTON SUND | SPM | 26.04.07 | 18 04.02.19 | VDN-5026 | O | | UTC Aerospace Systems | 3A |
| | 20-00-02 | Aircraft Wheel Bearings | DUNLOP | GPM | 31.01.91 | | VDN-0316 | S | | | 3A |
| | 20-00-02 | Electronic Standard Practices Manual | HAMILTON SUND | SPM | 26.04.07 | 29 15.11.19 | VDN-5027 | O | | UTC Aerospace Systems | 3A |
| | 20-00-04 | Warnings Registry (Long Version) | HAMILTON SUND | SPM | 28.10.13 | 12 05.10.18 | VDN-5025 | O | | UTC Aerospace Systems | 3A |
| | 20-00-10 | Standard Practices Manual | LIEBHERR | SPM | 30.03.88 | 3 09.12.15 | VDN-0467 | S | | LIEBHERR | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | 20-00-10 | Standard Practices Manual | MESSIER-DOWTY | SPM | 15.10.08 | 9 15.01.12 | VDN-0460 | S | Supersedes CMM 31-09-01 | 3A |
| QB0470 | 21-02-70 | Filter Element | PALL | CMS | 27.05.94 | | VDN-0177 | S | | 3A |
| QB0471 | 21-02-71 | Filter Element | PALL | CMS | 27.05.94 | | VDN-0176 | S | | 3A |
| 4053B000 | 21-21-04 | Non-Return Valve 165 mm (6.5 in) | NGL | MM | 23.06.92 | | 2397 | O | | 3A |
| 4053B000 | 21-21-04 | Non-Return Valve 165 mm (6.5 in) | NGL | CMM w. IPC | 11.11.92 | 1 12.12.95 | 2398 | S | | 3A |
| 011390-500 | 21-22-01 | Recirculation Fan | AMETEK | CMM w. IPC | 22.05.95 | 5 30.04.14 | VDN-0232 | S | ROTRON | 3A |
| 011292-500 | 21-25-01 | EFIS Fan | ROTRON | CMM w. IPC | 01.04.95 | | VDN-0235 | S | AMETEK | 3A |
| 011291-500 | 21-25-03 | Avionics Aft Fan | ROTRON | CMM w. IPC | 22.05.95 | 1 22.09.97 | VDN-0233 | S | AMETEK | 3A |
| 234A0101 | 21-30-05 | Filter | LIEBHERR | CMM w. IPC | 21.01.85 | 2 01.06.11 | VDN-0476 | S | ABG-SEMCA | 3A |
| 234A0101 | 21-30-05 | Filter, Air | LIEBHERR TOUL | TCMS | 21.01.85 | 1 03.10.95 | VDN-0002 | S | ABG-SEMCA | 3A |
| 3029B000-002 | 21-30-21 | 1/4" Non Return Valve | NGL | CMM w. IPC | 10.12.74 | 1 12.05.99 | 1372 | S | | 3P |
| 407A0104 | 21-33-05 | Air Jet Pump | LIEBHERR | CMM w. IPC | 30.06.92 | 2 31.12.12 | VDN-0132 | S | ABG-SEMCA | 3A |
| 22260A/E010101 | 21-34-01 | Cabin Pressure Controller | LIEBHERR | CMM w. IPC | 15.12.92 | 5 15.06.99 | VDN-0127 | S | ABG-SEMCA | 3A |
| 912V0201 | 21-34-02 | Manual Controller | LIEBHERR | CMM w. IPC | 01.09.92 | 3 24.11.08 | VDN-0134 | S | ABG-SEMCA | 3P |
| 2097H020900;2097P011400 | 21-34-03 | Electropneumatic Valve | LIEBHERR | CMM w. IPC | 20.11.92 | 6 15.01.06 | VDN-0125 | S | ABG-SEMCA | 3A |
| 2099J020900;2099R011400 | 21-34-04 | Pneumatic Valve | LIEBHERR | CMM w. IPC | 01.12.92 | 6 30.05.13 | VDN-0129 | S | | 3A |
| 92105A010100 | 21-34-06 | Manual Indicator Module | LIEBHERR | CMM w. IPC | 02.11.92 | 1 04.03.98 | VDN-0124 | S | ABG-SEMCA | 3A |
| 4031B000 | 21-51-02 | Solenoid Valve | HONEYWELL NGL | CMM w. IPC | 04.02.92 | 5 11.03.11 | 2369 | S | NGL | 3A |
| 4068B000-002/-003 | 21-51-03 | Flow Control and Shut Off Valve | HONEYWELL NGL GL | CMM w. IPC | 18.12.95 | 9 09.08.06 | 2379 | S | NGL | 3A |
| 5729C000/-002 | 21-51-10 | Environmental Control Unit | HONEYWELL NGL | CMM w. IPC | 14.06.94 | 6 06.12.16 | 2511 | S | NGL | 3A |
| 5729C000,-002,-003 | 21-51-10 | Environmental Control Unit | NGL | MM with IPL | 14.06.94 | 1 10.01.10 | 2510 | O | | 3P |
| 1716D000-002 | 21-51-11 | Cold Air Unit | HONEYWELL NGL | CMM w. IPC | 26.05.94 | 9 06.12.16 | 2516 | S | NGL | 3A |
| 1716D000-002 | 21-51-11 | Cold Air Unit | NGL | MM | 25.05.94 | 1 26.05.98 | 2515 | O | | 3A |
| 8554C000 | 21-51-12 | Dual Heat Exchanger | HONEYWELL NGL | CMM w. IPC | 27.06.92 | 8 19.01.04 | 2389 | S | NGL | 3A |
| 8554C000 | 21-51-12 | Dual Heat Exchanger | NGL | MM | 08.05.92 | 2 10.04.95 | 2388 | O | | 3A |
| 8555C000 | 21-51-13 | Condenser/Water Extractor | NGL | CMM w. IPC | 21.05.96 | 2 07.01.11 | 2390 | S | | 3A |
| 8563C000 | 21-51-13 | Condenser/Water Extractor | NGL | CMM w. IPC | 21.05.96 | 3 22.09.00 | 2512 | S | | 3A |
| 5586C000 | 21-51-14 | Over Temperature Switch | NGL | MM | 05.05.92 | 1 24.03.99 | 2380 | S | | 3A |
| 5732C000 | 21-51-15 | Turbine Inlet Control Valve | HONEYWELL NGL | CMM w. IPC | 23.05.94 | 2 19.08.04 | 2514 | S | NGL | 3A |
| 5623C000 | 21-51-15 | Turbine Inlet Control Valve | NGL | CMM w. IPC | 20.10.92 | 1 17.01.96 | 2387 | S | | 3A |
| 5732C000 | 21-51-15 | Turbine Inlet Control Valve | NGL | MM | 24.05.94 | | 2513 | O | | 3A |
| 5677C000/-002 | 21-51-16 | Pneumatic Temperature Sensor | HONEYWELL NGL | CMM w. IPC | 23.01.96 | 5 15.09.03 | 2400 | S | NGL | 3A |
| 5677C000 | 21-51-16 | Pneumatic Temperature Sensor | NGL | MM | 09.06.92 | | 2399 | O | | 3A |
| 5556C000 | 21-51-21 | Water Injector | HONEYWELL NGL | CMM w. IPC | 09.01.96 | 2 01.11.01 | 2396 | S | NGL | 3A |
| 3907B000 | 21-51-22 | Non-Return Valve | HONEYWELL NGL | CMM w. IPC | 21.10.92 | 4 01.07.10 | 2376 | S | NGL | 3A |
| 3907B000 | 21-51-22 | Non-Return Valve 63,5 mm (2.5 in) | NGL | MM | 29.04.92 | | 2375 | O | | 3A |
| 011389-502 | 21-51-23 | Ground Cooling Fan | ROTRON | CMM w. IPC | 15.11.94 | 2 29.04.10 | VDN-0234 | S | AMETEK | 3A |
| GB2001AA1 | 21-51-24 | Check Valve | TECHNOFAN | CMM w. IPC | 01.09.00 | 1 01.01.01 | VDN-0244 | S | | 3A |
| 6038C000-001 | 21-51-95 | Environmt.Contr.Sys.Comp.Insul.Jacket Kit | HONEYWELL NGL | CMM w. IPC | 18.10.01 | | 2780 | S | NGL | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| 5406C000 | 21-61-03 | Temperature Controller | HONEYWELL NGL | CMM w. IPC | 17.01.96 | 4 12.10.01 | 2405 | S | NGL | 3A |
| 5410C000 | 21-61-04 | Duct Temperature Sensor | NGL | MM | 06.05.92 | 1 04.03.11 | 2381 | S | | 3A |
| 5409C000 | 21-61-05 | Bay Temperature Sensor | NGL | MM | 12.05.92 | 1 07.07.08 | 2393 | S | | 3A |
| 5403C000 | 21-61-06 | Duct Temperature Limiter | NGL | CMM w. IPC | 13.06.92 | | 2403 | S | | 3A |
| 5413C000 | 21-61-08 | Temperature Control Valve | HONEYWELL NGL | CMM w. IPC | 10.08.95 | 7 12.08.10 | 2395 | S | NGL | 3A |
| | 22-05-04 | PRIMUS 2000 Integr.Avi. Syst.Vol II | HONEYWELL | SMM | 01.11.93 | 1 15.03.95 | A15-1146-054 | S | Volume II | 3P |
| | 22-05-04 | PRIMUS 2000 Integr.Avi. Syst.Vol I | HONEYWELL | SMM | 01.11.93 | 1 15.03.95 | A15-1146-054 | S | Volume I | 3P |
| | 22-05-04 | PRIMUS 2000 Integr.Avi. Syst.Vol III | HONEYWELL | SMM | 15.03.95 | | A15-1146-054 | S | Volume III | 3P |
| | 22-05-34 | PRIMUS 2000 Integr.Avi. Syst.Vol I (GAU) | HONEYWELL | SMM | 15.07.98 | | A15-1146-085 | S | for DO328 GAU | 3P |
| | 22-05-34 | PRIMUS 2000 Integr.Avi. Syst.Vol III (GAU) | HONEYWELL | SMM | 15.07.98 | | A15-1146-085 | S | for DO328 GAU | 3P |
| | 22-05-34 | PRIMUS 2000 Integr.Avi. Syst.Vol II (GAU) | HONEYWELL | SMM | 15.07.98 | | A15-1146-085 | S | for DO328 GAU | 3P |
| 4006719-906/-910 | 22-11-50 | SM-200 Servo Drive | HONEYWELL | CMM w. IPC | 05.12.73 | 13 07.04.15 | A09-1146-004 | S | | 3A |
| 4005842 | 22-11-51 | SB-201 Servo Drum/Housing Assy | HONEYWELL | CMM w. IPC | 15.10.73 | 6 30.08.99 | A09-1146-005 | S | | 3A |
| 7017300-XXXXX | 22-11-95 | IC-800 Intergrated Avionics Computer | HONEYWELL | CMM w. IPC | 01.10.92 | 6 26.08.19 | A09-1147-075 | S | Supersedes Vol. I - III | 3A |
| 7014940-902 | 22-12-79 | IM-803 Installation Module | HONEYWELL | CMM w. IPC | 15.12.98 | 2 | A09-1147-073 | S | Reissue | 3A |
| 7015327-901/-905 | 22-18-70 | GP-300 Guidance Panel Controller | HONEYWELL | CMM w. IPC | 01.08.91 | 4 01.12.05 | A09-1147-044 | S | | 3A |
| 7026240-90X | 23-05-04 | Mini Cabinet Assembly | HONEYWELL | CMM w. IPC | 20.12.02 | 3 24.08.11 | A09-3855-002 | S | | 3P |
| 064-01073-0102 | 23-10-06 | KRX 1053 Receiver/Exciter | HONEYWELL BENDIX | CMM w. IPC | 30.09.03 | 2 06.05.11 | 006-15642-0001 | S | Bendix King | 3A |
| 064-01074-0101 | 23-10-07 | KAC 1052 Antenna Coupler | HONEYWELL BENDIX | CMM w. IPC | 26.01.04 | 1 | 006-15640-0001 | S | Bendix King | 3A |
| 064-01072-0101 | 23-10-08 | KPA 1052 Power Amplifier | HONEYWELL BENDIX | CMM w. IPC | 30.09.03 | | 006-15641-0000 | S | Bendix King | 3A |
| | 23-10-09 | KHF 1050 HF Communication System | HONEYWELL | TR 23-4 | 17.07.13 | | 006-10640-0006 | S | | 3A |
| | 23-10-09 | KHF 1050 HF Communication System | HONEYWELL | TR 23-1 | 01.03.11 | | 006-10640-0006 | S | | 3A |
| | 23-10-09 | KHF 1050 HF Communication System | HONEYWELL | TR 23-3 | 07.03.13 | | 006-10640-0006 | S | | 3A |
| 064-01073-0102 | 23-10-09 | KHF 1050 HF Communication System | HONEYWELL | SIM | 01.03.03 | 6 01.11.07 | 006-10640-0006 | S | Bendix King | 3A |
| 7026201-8XX | 23-12-03 | Very High Frequency Data Radio Assembly | HONEYWELL | CMM w. IPC | 20.12.02 | 8 27.04.18 | A09-3829-002 | S | | 3P |
| 064-1015-01 | 23-20-03 | KHF 950 HF/SSB Communication System | HONEYWELL BENDIX | SIM | 01.02.94 | 2 28.04.06 | 006-05389-0002 | S | Bendix King | 3A |
| 064-1015-01 | 23-20-08 | Receiver/Exciter KTR 953 | ALLIEDSIGNAL | TR 23-1 | 20.11.08 | | 006-05381-0000 | S | Bendix King | 3A |
| 064-1015-01 | 23-20-08 | Receiver/Exciter KTR 953 | ALLIEDSIGNAL | TR 23-2 | 02.03.09 | | 006-05381-0000 | S | Bendix King | 3A |
| 064-1015-01 | 23-20-08 | Receiver/Exciter KTR 953 | ALLIEDSIGNAL | CMM w. IPC | 30.04.95 | | 006-05381-0000 | S | Bendix King | 3A |
| 965-0758-00X | 23-20-13 | Communications Management Unit (MK II) | HONEYWELL | CMM w. IPC | 21.02.97 | 14 15.05.20 | 012-0690-001 | S | | 3P |
| 964-0465-001 | 23-20-33 | Airplane Personality Module | HONEYWELL | CMM w. IPC | 31.10.02 | | 012-0733-001 | S | | 3P |
| 779.407.925 | 23-30-03 | Tape Player | BECKER | MR | 01.09.90 | | DV 32001.04 | S | | 3A |
| 397.326-925/802.157-925 | 23-30-03 | Tape player TP 3100 | BECKER | IOM | 01.02.89 | | DV 32002.03 | O | OBSOLETED | 3A |
| 854-301-925 | 23-30-03 | Tape Player | BECKER | CMM w. IPC | 15.01.93 | | VDN-0048 | S | | 3A |
| 0543-284-925 | 23-30-06 | Digital Player DP 4100 | BECKER | CMM w. IPC | 15.04.05 | | VDN-0327 | S | Supersedes TP300 | 3A |
| 0543-284-925 | 23-30-06 | Digital Player DP 4100 | BECKER | AMM | 15.06.01 | 2 15.04.05 | VDN-0328 | O | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 0543-284-925 | 23-30-06 | Cardsetup Software Version 1.0 for Digital Player DP 4100 | BECKER | IOM | 01.11.02 | | VDN-0329 | O | | | 3A |
| 0543-284-925 | 23-30-06 | DP 4100 Operating Instructions | BECKER | OI | 01.04.05 | | VDN-0466 | O | | | 3A |
| 5483-1 | 23-30-08 | Interphone Handset/Cradle | AVTECH | CMM w. IPC | 28.02.92 | 2 01.07.05 | VDN-0041 | S | | | 3A |
| 5382-1 | 23-30-11 | Passenger Address Amplifier | AVTECH | CMM w. IPC | 14.10.93 | 1 16.08.04 | VDN-0039 | S | | | 3A |
| 328-0050/51/52 | 23-41-03 | Calls Panel | COBHAM | CMM w. IPC | 01.10.93 | 1 30.06.95 | VDN-0172 | S | | NEC AERO | 3A |
| 93A055-XX | 23-70-01 | CVR MIC Modules | L3 AVIATION RECORDER | CMM w. IPC | 01.05.91 | 3 01.03.04 | 165E0101-00 | S | | Model A55X | 3P |
| 93A100-XX | 23-70-01 | Cockpit Voice Recorder | L3 AVIATION RECORDER | CMM w. IPC | 01.05.91 | 3 01.03.04 | 165E0101-00 | S | | Model A100X | 3P |
| 93A151-XX | 23-70-01 | CVR Control Units | L3 AVIATION RECORDER | CMM w. IPC | 01.05.91 | 3 01.03.04 | 165E0101-00 | S | | Model A15X | 3P |
| 93A055-XX / 93A151-XX | 23-70-02 | SOLID–STATE COCKPIT VOICE RECORDER (SSCVR) | L3 AVIATION RECORDER | CMM w. IPC | 01.02.93 | 3 01.07.05 | 165E0948-00 | S | | Model A55X / Model A15X | 3P |
| S100-0080-00 | 23-70-02 | FA2100CVR Solid State Cockpit Voice Recorder | L3 AVIATION RECORDER | CMM w. IPC | 01.02.93 | 3 01.07.05 | 165E0948-00 | S | | Model A100S | 3P |
| S200-0012-00 | 23-70-03 | A200S Solid State Cockpit Voice Recorder | L3 COMMUNICATIONS | CMM w. IPC | 15.02.96 | 5 01.03.05 | 165E1233-00 | S | | Model A200S | 3P |
| 2100-1020-00 | 23-70-04 | Cockpit Voice Recorder | L3 AVIATION RECORDER | CMM w. IPC | 01.11.98 | 17 07.03.19 | 165E1689-00 | S | | Model FA2100 | 3A |
| S151-0060-00 | 23-70-05 | ED-56A Control Unit, Preamplifier Module and Microphone Module | L3 AVIATION RECORDER | CMM w. IPC | 01.09.00 | 9 06.05.14 | 165E0101-00 | S | | | 3P |
| 980-6113-001 | 23-70-41 | Remote Microphone | HONEYWELL ASIG | TR 23-01 | 01.05.00 | | 012-0552-001 | S | | ALLIEDSIGNAL | 3P |
| 980-6113-001 | 23-70-41 | Remote Microphone | HONEYWELL ASIG | CMM w. IPC | 10.03.89 | 3 14.04.98 | 012-0552-001 | S | | ALLIEDSIGNAL | 3P |
| 980-6113-001 | 23-70-41 | Remote Microphone | HONEYWELL ASIG | TR 23-02 | 21.08.00 | | 012-0552-001 | S | | ALLIEDSIGNAL | 3P |
| 980-6117-005 | 23-70-43 | Microphone Monitor | ALLIEDSIGNAL | CMM w. IPC | 15.09.93 | 7 23.08.02 | 012-0666-001 | S | | HONEYWELL | 3P |
| 980-6020-001 | 23-70-44 | Solid State Cockpit Voice Recorder | HONEYWELL ASIG | CMM w. IPC | 31.01.94 | 19 01.12.11 | 012-0667-001 | S | | ALLIEDSIGNAL | 3P |
| 7510700-8XX | 23-81-01 | RCZ-8XX Integrated Comm.Unit | HONEYWELL | CMM w. IPC | 15.12.87 | 15 24.08.20 | A09-3800-015 | S | | | 3A |
| 7513000-802/ -836 | 23-81-07 | CD-850 Clearance Delivery Control Head | HONEYWELL | CMM w. IPC | 01.09.88 | 3 21.09.20 | A32-3800-002 | S | | | 3A |
| 7511001-912 | 23-81-08 | AV-850A Audio Panel | HONEYWELL | CMM w. IPC | 20.10.89 | 12 08.07.21 | A09-3800-021 | S | | Supersedes Vol. I - III | 3A |
| 7510733-6XX | 23-81-15 | Communication Unit ADS-B Assembly | HONEYWELL | CMM w. IPC | 02.05.12 | | D201110000060 | S | | | 3A |
| 3E2459-1 | 24-09-01 | Temperature Controller | BFG ICE | CMM w. IPC | 15.05.92 | | 92-32-019 | S | | | 3A |
| A06 - Series | 24-09-02 | Actuator Assembly | GKN WESTL.SITEC | CMM w. IPC | 01.08.91 | 6 21.12.18 | A06000-07 | S | | | 3A |
| | 24-10-00 | GENERATOR DRIVES AND RELATED EQUIPMENT | HAMILTON SUND | SPM | 01.12.72 | 80 29.10.19 | SPM 24-10-00 | O | | UTC Aerospace Systems | 3P |
| PC125 | 24-20-02 | 125 VA Static Inverter | MARATHON | CMM w. IPC | 01.08.78 | 2 02.08.95 | VDN-0141 | S | | | 3P |
| PC251 | 24-20-07 | 250 VA Static Inverter | MARATHON | CMM w. IPC | 01.07.81 | 2 26.09.89 | VDN-0142 | S | | | 3A |
| PC251() Series | 24-20-32 | 300 VA Static Inverter | Avionic Instruments | CMM w. IPC | 30.04.95 | 2 14.09.07 | VDN-0642 | S | | | 3A |
| 20736 | 24-22-15 | Differential Protection Current Transformer | AUXILEC | TCMS | 01.06.92 | 1 16.11.92 | VDN-0448 | O | | THALES | 3P |
| 20040 | 24-22-66 | AC Generator | AUXILEC | CMM w. IPC | 01.10.92 | 1 02.05.00 | VDN-0023 | S | | THALES | 3P |
| 2438 | 24-22-67 | Generator Control Unit | AUXILEC | CMM w. IPC | 30.07.92 | | VDN-0020 | S | | THALES | 3P |
| 106-000-3 | 24-22-68 | DC Bus Power Control Unit | AUXILEC | CMM w. IPC | 30.05.94 | 1 15.01.95 | VDN-0025 | S | | THALES | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| 106-000-4 | 24-22-71 | DC Bus Power Control Unit | AUXILEC | CMM w. IPC | 15.09.99 | | VDN-0028 | S | THALES | 3A |
| 261000B | 24-23-30 | Transformer Rectifier Unit TRU - 150A1 | DITTEL | CMM w. IPC | 17.11.00 | | TRU 150 A1 | S | | 3A |
| 330/335GA01Y01 | 24-29-55 | AC Junction Box | ECE | CMM w. IPC | 15.06.94 | 3 24.09.13 | VDN-0083 | S | ZODIAC | 3A |
| 3759-2 | 24-30-00 | Aircraft Battery | SAFT | CMM w. IPC | 01.09.94 | | VDN-0322 | S | | 3A |
| 2778-1 | 24-30-00 | Aircraft Battery | SAFT | CMM w. IPC | 01.04.95 | 1 24.04.18 | VDN-0323 | S | | 3A |
| 501-1228-03 | 24-30-02 | PS-835 Emergency Power Supply | L3 COMMUNICATIONS | CMM w. IPC | 01.09.95 | C, Chng4 25.07.19 | TP-329 | S | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | PS-835 Troubleshooting Guide | L3 COMMUNICATIONS | GUIDE | 06.06.08 | | TP-607 | S | BFG AVIONICS | 3A |
| 501-1228-() | 24-30-04 | Emergency Power Supply JET Model PS-835 | L3 COMMUNICATIONS | IM | 01.07.94 | P 20.03.17 | TP-336 | S | | 3A |
| 4078-4 | 24-31-16 | Aircraft Battery | SAFT | CMM w. IPC | 01.02.91 | | VDN-0324 | S | | 3A |
| 103-020-0 | 24-32-16 | Hall Effect Current Sensor | THALES | TCMS | 16.11.92 | 4 02.05.13 | VDN-0313 | S | AUXILEC | 3A |
| DTSP-400L | 24-34-00 | Aircraft Batteries | | OMM | 23.06.97 | 11 09.11.12 | VDN-0455 | S | | 3A |
| DTSP-400L | 24-34-00 | Nickel-Cadmium Aircraft Batteries | MARATHON | OMM | 23.06.97 | 18 17.06.20 | DCR60741 | S | | 3A |
| 30874-001 | 24-34-02 | Ni-Cad-Batterie Typ SP-747 | MARATHON | CMM w. IPC | 31.03.02 | 2 07.05.04 | VDN-0428 | S | | 3A |
| 118-000-2 | 24-35-30 | Generator Control Unit for Starter Generator | AUXILEC (THALES) | CMM w. IPC | 22.12.04 | | VDN-0430 | S | AUXILEC | 3A |
| 8160-121 | 24-35-32 | Starter Generator | THALES | CMM w. IPC | 01.06.92 | 3 26.04.22 | VDN-0027 | S | AUXILEC (THALES) | 3A |
| 118-000-1 | 24-35-33 | Generator Control Unit for Starter Generator | AUXILEC | CMM w. IPC | 15.11.95 | | VDN-0022 | S | THALES | 3A |
| 947 | 24-35-34 | Ground Power Protection Unit | AUXILEC | CMM w. IPC | 15.08.92 | | VDN-0024 | S | THALES | 3A |
| 220GC02Y01/230GC01/-04 | 24-39-55 | DC Junction Box | ZODIAC AEROSPACE | CMM w. IPC | 15.06.94 | 8 12.05.14 | VDN-0082 | S | | 3A |
| 208CC02Y1 | 24-39-59 | SPST NO CONTACTOR | ZODIAC AERO ELECTRIC | ACMM w. IPC | 04.11.15 | | 208CC02Y1 | S | | 3A |
| 5577 | 25-10-09 | Cockpit Sliding Door Lock | INDRAÉRO SIREN | CMM w. IPC | 25.09.00 | 1 01.02.06 | VDN-0449 | S | | 3A |
| 5574 | 25-10-10 | Hatrack Latch | INDRAÉRO SIREN | CMM w. IPC | 01.02.01 | 1 01.02.06 | VDN-0450 | S | | 3A |
| 1180002-Series | 25-10-32 | Restraint System Assembly | AM-SAFE | ACMM w. IPC | 12.10.10 | | VDN-5030 | S | | 3A |
| 3A165-0007/8-01-2 | 25-11-03 | Crew Seat Assembly | IPECO | CMM w. IPC | 22.03.96 | 12 28.08.14 | SM615 | S | | 3A |
| 1112-1AA | 25-11-12 | Observer Seat Model 1112 | AMI | CMM w. IPC | 01.10.93 | | VDN-0013 | S | | 3A |
| 3A165-0007/8-01-1 | 25-11-15 | Crew Seat | IPECO | CMM w. IPC | 05.02.07 | 4 28.08.12 | SM628 | S | Repl. CMM 25-10-72 | 3P |
| 503693 Series | 25-11-16 | Restraint System Assembly | AM-SAFE | CMM w. IPC | 13.09.96 | 4 19.12.02 | 503693 | S | | 3A |
| 504109-Series | 25-12-18 | Restraint System Assembly | AM-SAFE | CMM w. IPC | 07.06.98 | 3 09.01.03 | 504109 | S | | 3A |
| GC204/5(-) | 25-20-04 | Aircraft Oven Types | IPECO | CMM w. IPC | 26.07.98 | 3 23.09.02 | VDN-0429 | S | Supersedes 25-20-01 | 3A |
| GC205CR | 25-20-17 | Aircraft Oven Types | IPECO | CMM w. IPC | 30.07.99 | 13 24.11.22 | VDN-0331 | S | AMC INDUSTRIES | 3A |
| 2524-519 | 25-20-97 | Fixed Dynamic Single Seat Series 1300 | B/E AERO AMP | MM w. IPL | 01.02.97 | | 4M51901 | S | B/E AERO | 3A |
| 2524-520 | 25-20-98 | Fixed Dynamic Double Seat Series 1300 | B/E AERO AMP | MM w. IPL | 01.03.97 | | 4M52001 | S | B/E AERO | 3A |
| 502879-Series | 25-22-08 | Restraint System Assembly | AM-SAFE | CMM w. IPC | 20.11.98 | 3 20.01.03 | 502879 | S | | 3A |
| 503321-Series | 25-23-05 | Restraint System Assembly | AM-SAFE | CMM w. IPC | 27.11.98 | 3 17.01.03 | 503321 | S | | 3A |
| 502745-Series | 25-24-01 | Lap Belt Assembly | AM-SAFE | CMM w. IPC | 15.05.96 | 7 12.06.12 | 502745 | S | | 3A |
| 2060-5AC | 25-25-60 | Attendant Seats Model 2060 | AMI | CMM w. IPC | 15.10.93 | 5 01.05.01 | VDN-0333 | S | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 87064/5XXX | 25-25-83 | Passenger Seat | B/E AERO BURNS | CMM w. IPC | 25.01.93 | | 25-25-083 | S | | | 3A |
| 8718900X; 8719000X | 25-27-04 | Passenger Seat (HORIZON) | B/E AERO BURNS | CMM w. IPC | 08.04.94 | | VDN-0060 | S | | HORIZON | 3P |
| 87064/5XXX | 25-27-08 | Passenger Seat (ENGADINA) | B/E AERO BURNS | CMM w. IPC | 15.04.94 | | 25-27-008 | S | | ENGADINA | 3P |
| 87064/5XXX | 25-27-13 | Passenger Seat (AFRIMEX) | B/E AERO BURNS | CMM w. IPC | 15.04.94 | | 25-27-013 | S | | AFRIMEX | 3P |
| 87064/5XXX | 25-27-32 | Passenger Seat (ENGADINA II) | B/E AERO BURNS | CMM w. IPC | 03.02.95 | | VDN-0064 | S | | ENGADINA II | 3P |
| 87064XXX,87065XXX | 25-27-78 | JB6 SERIES COMMUTER CLASS PASSENGER SEATS FOR USAIR EXPRESS/DORNIER 328 AIRCRAFT | B/E AERO BURNS | TR 2.0 | 01.11.02 | | 25-27-078-2063 | S | | | 3A |
| 87064XXX,87065XXX | 25-27-78 | JB6 SERIES COMMUTER CLASS PASSENGER SEATS FOR USAIR EXPRESS/DORNIER 328 AIRCRAFT | B/E AERO BURNS | TR 2.01 | 17.11.08 | | 25-27-078-2063 | S | | | 3A |
| 87064XXX,87065XXX | 25-27-78 | JB6 SERIES COMMUTER CLASS PASSENGER SEATS FOR USAIR EXPRESS/DORNIER 328 AIRCRAFT | B/E AERO BURNS | CMM w. IPC | 13.05.96 | 1 30.09.02 | 25-27-078-2063 | S | | | 3A |
| 87064XXX,87065XXX | 25-27-78 | JB6 SERIES COMMUTER CLASS PASSENGER SEATS FOR USAIR EXPRESS/DORNIER 328 AIRCRAFT | B/E AERO BURNS | TR 2.02 | 14.04.16 | | 25-27-078-2063 | S | | | 3A |
| 105146 | 25-28-20 | Foldable Trolley Stowage | MÜHLENBERG | CMM w. IPC | 25.07.95 | | VDN-0251 | S | | | 3A |
| 113197/113198 | 25-28-38 | Stowages | MÜHLENBERG | CMM w. IPC | 30.08.96 | | VDN-0252 | S | | | 3A |
| 105148 | 25-28-40 | Galley | MÜHLENBERG | CMM w. IPC | 30.11.96 | | VDN-0253 | S | | | 3P |
| 103141 | 25-28-44 | QC - Wardrobe | MÜHLENBERG | CMM w. IPC | 30.01.97 | | VDN-0254 | S | | | 3A |
| 113218 | 25-29-21 | Music Entertainment Cabinet | MÜHLENBERG | CMM w. IPC | 29.12.00 | 1 12.04.01 | VDN-0256 | S | | | 3A |
| 106098/106098A | 25-30-39 | AFT Galley R/H | MÜHLENBERG | CMM w. IPC | 25.06.93 | C 19.03.96 | VDN-0258 | S | | | 3P |
| 106100/A/B/C | 25-30-40 | AFT Galley R/H | MÜHLENBERG | CMM w. IPC | 25.06.93 | B 15.04.96 | VDN-0259 | S | | | 3A |
| 106101 | 25-30-42 | Small Galley | MÜHLENBERG | CMM w. IPC | 01.08.94 | B 15.04.96 | VDN-0260 | S | | | 3A |
| 106101A | 25-30-47 | Small Galley | MÜHLENBERG | CMM w. IPC | 30.09.96 | | VDN-0261 | S | | | 3A |
| 106100D, 106100L | 25-30-82 | AFT Galley R/H | MÜHLENBERG | CMM w. IPC | 15.02.00 | 2 10.10.01 | VDN-0262 | S | | | 3A |
| 106100E | 25-30-83 | Galley AFT R/H | MÜHLENBERG | CMM w. IPC | 15.02.00 | 1 10.03.00 | VDN-0263 | S | | | 3A |
| 106100F | 25-30-84 | AFT Galley R/H | MÜHLENBERG | CMM w. IPC | 15.02.00 | 2 12.12.07 | VDN-0264 | S | | | 3A |
| DLH 1085-017 | 25-32-31 | Meal Trolley Assy | DRIESSEN | CMM w. IPC | 09.08.89 | A 16.01.04 | VDN-0268 | S | | | 3A |
| DLH 1085-017 | 25-32-31 | Meal Trolley Assy | DRIESSEN | IPC | 09.08.89 | A 16.01.04 | VDN-0268 | S | | | 3A |
| 72184002B | 25-33-40 | Water Heater DR40 Series | B/E AERO INVENTUM | CMM w. IPC | 01.07.91 | 17 03.06.16 | VDN-0285 | S | | B/E AERO | 3A |
| AL-RA15-001 | 25-34-00 | Rail Assembly | AEROLUX | CMM w. IPC | 30.03.97 | 3 30.04.04 | VDN-0465 | S | | | 3A |
| AL-EX15-200E-1 | 25-34-02 | AL-EX15-200E-1 Espresso Coffee Maker | AEROLUX | CMM w. IPC | 30.01.10 | 1 30.08.10 | VDN-0493 | S | | | 3A |
| AL-EX15-200E-1 | 25-34-02 | PCB Test Procedures | AEROLUX | TR25-34-02-01 | 30.03.10 | | VDN-0494 | S | | | 3A |
| AL-EX15-200E-1 | 25-34-02 | Proof Pressure Test | AEROLUX | TR25-34-02-02 | 15.11.11 | | VDN-0495 | S | | | 3A |
| AL-EX15-200E-1 | 25-34-02 | New Parts Catalogue | AEROLUX | TR25-34-02-04 | 12.02.13 | | VDN-0496 | S | | | 3A |
| AL-EX15-200E-1 | 25-34-02 | New Parts Catallog | AEROLUX | TR25-34-02-03 | 06.09.12 | | VDN-0497 | S | | | 3A |
| AL-EX15-200E-1 | 25-34-20 | Configuration for the AL-EX15-200E Espresso Coffee Maker | AEROLUX | CMM w. IPC | 30.01.00 | 2 30.10.04 | VDN-0464 | S | | Superseded by 25-34-02 | 3A |
| HFE96-28 | 25-34-52 | Coffee Maker | IACOBUCCI | CMM w. IPC | 31.12.97 | B 01.09.08 | 1713 | S | | | 3A |
| HFE96-28 | 25-34-52 | Operating Instructions for the HFE96-28 Coffe Maker | IACOBUCCI | OI | 31.12.97 | | VDN-0470 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| AA-02-A | 25-34-68 | Coffee Maker | IACOBUCCI | CMM w. IPC | 22.05.00 | | 1683 | S | | | 3A |
| CA-01 | 25-34-69 | Rail | IACOBUCCI | CMM w. IPC | 14.09.00 | | 1739 | S | | | 3A |
| AA-8 | 25-34-70 | Water Tank | IACOBUCCI | CMM w. IPC | 21.09.00 | | 1738 | S | | | 3A |
| JA010001 | 25-35-36 | Hot Jug | DRIESSEN | CMM w. IPC | 26.06.95 | E 31.01.12 | VDN-0269 | S | | | 3P |
| JA010001 | 25-35-36 | Hot Jug | DRIESSEN | IPC | 26.06.95 | F 31.01.12 | VDN-0600 | S | | | 3P |
| DLH 294 | 25-36-10 | Atlas Container | DRIESSEN | CMM w. IPC | 03.04.96 | E 17.06.14 | VDN-0270 | S | | | 3A |
| DLH 294 | 25-36-10 | Atlas Container | DRIESSEN | IPC | 03.04.96 | F 17.06.14 | VDN-0610 | S | | | 3A |
| TB001016 | 25-37-63 | Atlas Trolley Assy | DRIESSEN | CMM w. IPC | 11.05.98 | | VDN-0271 | S | | | 3A |
| DLH 3072 | 25-37-63 | Bar Trolley Assy | DRIESSEN | IPC | 09.03.94 | A 29.08.03 | VDN-0443 | S | | | 3P |
| DLH 3072 | 25-37-63 | Bar Trolley Assy | DRIESSEN | CMM w. IPC | 09.03.94 | B 17.03.05 | VDN-0443 | S | | | 3P |
| DLH 105-210 | 25-38-26 | Hot Jug | DRIESSEN | IPC | 14.08.96 | D 29.06.10 | VDN-0272 | S | | | 3A |
| DLH 105-210 | 25-38-26 | Hot Jug | DRIESSEN | CMM w. IPC | 05.12.97 | D 29.06.10 | VDN-0272 | S | | | 3A |
| DLH 105-211 | 25-38-66 | Hot Jug | DRIESSEN | IPC | 06.07.98 | A 05.03.04 | VDN-0273 | S | | | 3P |
| DLH 105-211 | 25-38-66 | Hot Jug | DRIESSEN | CMM w. IPC | 06.07.98 | A 05.03.04 | VDN-0273 | S | | | 3P |
| 8706XXXX | 25-40-48 | Passenger Seat (ACA) | B/E AERO BURNS | CMM w. IPC | 02.06.00 | | VDN-0042 | S | | ACA | 3A |
| 8706XXXX | 25-40-57 | Passenger Seat (HAINAN) | B/E AERO BURNS | CMM w. IPC | 26.05.00 | | VDN-0063 | S | | HAINAN | 3A |
| 8788XXXX | 25-40-59 | Passenger Seat (SKYWAYS) | B/E AERO BURNS | CMM w. IPC | 17.04.00 | | VDN-0339 | S | | SKYWAYS | 3A |
| 8788XXXX | 25-40-59 | Passenger Seat (SKYWAYS) | B/E AERO BURNS | TR 1.0 | 03.10.01 | | VDN-0339 | S | | SKYWAYS | 3A |
| 8706XXXX | 25-40-63 | Passenger Seat (OZARK) | B/E AERO BURNS | CMM w. IPC | 09.06.00 | | VDN-0043 | S | | OZARK | 3A |
| 8788XXXX | 25-41-51 | Passenger Seat (GROSSMANN) | B/E AERO BURNS | CMM w. IPC | 16.03.01 | | VDN-0086 | S | | GROSSMANN | 3A |
| 8788XXXX | 25-41-78 | Passenger Seat (PHILLIP MORRIS) | B/E AERO BURNS | CMM w. IPC | 03.08.01 | | VDN-0338 | S | | PHILLIP MORRIS | 3A |
| 2500-205RB | 25-60-10 | Air Aspirated Life Rafts | HOOVER INDUSTRIES | CMM w. IPC | 07.08.98 | 1 07.08.98 | VDN-0112 | S | | Models FR-25 | 3P |
| P0723E105P-VARIANT | 25-60-12 | Adult/Child Life Preserver | EAM | CMM w. IPC | 26.04.88 | 10 14.12.11 | KSE-35L8 | S | | | 3A |
| P0640-103 | 25-60-15 | Infant Life Preserver | EAM | CMM w. IPC | 20.03.87 | 9 23.05.13 | IN-V20L8 | S | | | 3A |
| R0101A( ) | 25-60-17 | EAM-T4 LIFE RAFT | EAM | CMM | 01.09.11 | 8 01.05.14 | VDN-0570 | O | | | 3A |
| P01074-1XX | 25-60-30 | XF-35 LIFE PRESERVER | EAM | CMM | 12.02.16 | | XF-35 | S | | | 3A |
| P01400-2XX | 25-60-58 | AIC-35 LIFE PRESERVER | EAM | CMM | 15.09.15 | | AIC-35 | S | | | 3A |
| ELT96/97A2560000000 | 25-61-02 | Emergency Locator Transmitter ELT 96/97 | AIR PRECISION | CMM w. IPC | 01.05.97 | 10 01.09.16 | VDN-0275 | S | | SOCATA | 3A |
| ELT96/97A2560000000 | 25-61-02 | ELT 96 / 97 Installation Manual | AIR PRECISION | INSTAL. M | 01.04.01 | 8 01.04.15 | VDN-0442 | O | | SOCATA | 3A |
| ELT96/97 | 25-61-02 | ELT96/ELT97 User's Manual | AIR PRECISION | USER M | 01.04.01 | 4 01.10.07 | VDN-0453 | S | | Repl. single manual of ELT96 & 97 | 3A |
| | 25-62-01 | L3AP UNDERWATER LOCATOR BEACON | L3 AVIATION RECORDER | CMM w. IPC | 24.04.15 | 5 15.05.17 | 165E5542-00 | S | | FA2100 | 3P |
| 328-0170 | 26-10-01 | Fire Panel For Cargo Compartment | COBHAM | CMM w. IPC | 19.03.00 | 1 04.04.01 | VDN-0161 | S | | NEC AERO | 3A |
| 328-0180 | 26-10-02 | Distribution Box | COBHAM | CMM w. IPC | 07.03.00 | | VDN-0162 | S | | NEC AERO | 3A |
| 51653-151-01 | 26-11-84 | Fire Detection Control Unit | KIDDE-DEUGRA | CMM w. IPC | 01.03.95 | | VDN-0385 | S | | HAMILTON SUNDSTRAND | 3A |
| 51653-151 | 26-11-89 | Fire Detection Control Unit | KIDDE-DEUGRA | CMM w. IPC | 03.08.05 | 1 25.07.11 | VDN-0499 | S | | HAMILTON SUNDSTRAND | 3A |
| 355XX-2 | 26-14-12 | Sensing Elements | KIDDE-DEUGRA | CMM w. IPC | 17.05.06 | 12 27.05.14 | 512 | S | | HAMILTON SUNDSTRAND | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| 35303-XXX | 26-14-14 | Wire End Fittings | KIDDE-DEUGRA | CMM w. IPC | 12.02.96 | 3 03.01.13 | 514 | S | HAMILTON SUNDSTRAND | 3A |
| SD9422-01 | 26-15-01 | Ambient Smoke Detector | AOA | CMM w. IPC | 05.02.92 | 1 20.12.99 | VDN-0015 | S | | 3A |
| SD9470-22 | 26-15-02 | Smoke Detector | AOA | CMM w. IPC | 20.12.99 | 2 05.05.04 | VDN-0014 | S | | 3A |
| 512XX-XXX | 26-16-10 | Terminal Lug Firewire and Accessoires | KIDDE-DEUGRA | CMM w. IPC | 04.08.93 | 09.08.11 | VDN-0381 | S | HAMILTON SUNDSTRAND | 3A |
| 35001016-1 | 26-20-10 | Discharge Indicator Assy | PACIFIC SCIENTIFIC | CMM w. IPC | 01.02.76 | 1 15.02.94 | VDN-0175 | S | | 3A |
| BA21741GR-2 | 26-20-29 | Hand Fire Extinguisher 1,2kg BCF | FIRE FIGHTING ENTERP | CMM w. IPC | 01.11.92 | 6 01.01.19 | VDN-0180 | S | PERCIVAL | 3A |
| 33100016-1/33600042-1 | 26-22-37 | Single Outlet Fire Extinguishers | PACIFIC SCIENTIFIC | CMM w. IPC | 15.02.94 | 4 15.06.04 | VDN-0174 | S | | 3A |
| 33500012-1/13-1 | 26-22-54 | Fire Extinguisher | PACIFIC SCIENTIFIC | CMM w. IPC | 15.06.99 | 1 15.01.05 | VDN-0281 | S | | 3A |
| 34200408-1 | 26-23-50 | Single Outlet Metering Fire Extinguisher | PACIFIC SCIENTIFIC | CMM w. IPC | 15.11.00 | | VDN-0280 | S | | 3A |
| 74-20 | 26-24-05 | Halon 1/1,2/2,5 | TOTAL FEUERSCHUTZ | CMM w. IPC | 01.07.15 | | J 74/76-00 | S | AIR TOTAL | 3A |
| 440/441TS08Y01 | 26-24-15 | Fire Panel | ECE | CMM w. IPC | 15.05.93 | 3 30.04.98 | VDN-0084 | S | INTERTECHNIQUE | 3A |
| BA23177-1 | 26-25-12 | Automatic Fire Extinguisher 0,12kg | FIRE FIGHTING ENTERP | CMM w. IPC | 01.03.93 | 8 01.01.19 | VDN-0181 | S | PERCIVAL | 3A |
| BA24320D-1 | 26-25-36 | 0.12kg AUTO EUTECTIC FIRE EXTINGUISHER | FIRE FIGHTING ENTERP | CMM w. IPC | 01.10.02 | 8 01.03.17 | VDN-0554 | S | PERCIVAL | 3A |
| 1111C0000-01 | 27-09-50 | Solenoid Valve | LIEBHERR | CMM w. IPC | 30.09.93 | 1 02.02.18 | VDN-0469 | S | | 3A |
| 328300-1M02/3 | 27-11-02 | Cable Tension Regulator (Aileron Contr.) | SARMA | CMM w. IPC | 10.07.95 | 1 29.12.00 | VDN-0198 | S | | 3A |
| 328300-2M02/3 | 27-11-02 | Cable Tension Regulator (Aileron Contr.) | SARMA | CMM w. IPC | 10.07.95 | 1 29.12.00 | VDN-0236 | S | | 3A |
| 4328-2 | 27-11-07 | Aileron Disconnect Unit | AVIAC | CMM w. IPC | 01.06.94 | 1 15.09.99 | VDN-0037 | S | SAGEM | 3A |
| 8410/-1 | 27-12-03 | Roll Trim Actuator | SAFRAN | CMM w. IPC | 30.12.94 | 6 29.04.11 | VDN-0033 | S | AVIAC | 3A |
| FE211-002/-003/-004/-005 | 27-20-01 | Rudder Pedals Assembly | RATIER FIGEAC | CMM w. IPC | 20.12.91 | 1 03.06.96 | VDN-0211 | S | | 3P |
| FE309000000 | 27-20-03 | Rudder Pedals Assembly | RATIER FIGEAC | CMM w. IPC | 15.06.98 | 2 16.02.21 | VDN-0230 | S | | 3A |
| 328-0140/0160 | 27-20-11 | The Reds Test Panel 34VE | COBHAM | CMM w. IPC | 14.10.97 | 1 20.11.98 | VDN-0525 | S | NEC AERO | 3A |
| 8408/-1 | 27-22-03 | Yaw Trim Actuator | SAFRAN | CMM w. IPC | 31.01.94 | 5 09.11.11 | VDN-0035 | S | SAGEM/AVIAC | 3A |
| 8428-1/-2/-3/-4 | 27-23-04 | Limiter Actuator | AVIAC | CMM w. IPC | 31.01.94 | 6 01.02.11 | VDN-0032 | S | SAGEM | 3A |
| 328100-2M03AMDT-A | 27-31-02 | Cable Tension Regulator (Elevator Contr.) | SARMA | CMM w. IPC | 10.07.95 | 2 29.12.00 | VDN-0195 | S | | 3A |
| 328100-1M03AMDT-A | 27-31-02 | Cable Tension Regulator (Elevator Contr.) | SARMA | CMM w. IPC | 10.07.95 | 2 29.12.00 | VDN-0197 | S | | 3A |
| 4327-4 | 27-31-09 | Disconnect Unit Elevator | AVIAC | CMM w. IPC | 01.06.94 | 1 01.09.99 | VDN-0038 | S | SAGEM | 3A |
| 328600 M02 | 27-31-11 | Force Detector Rod | SARMA | CMM w. IPC | 20.04.95 | 1 28.02.01 | VDN-0312 | S | | 3A |
| 8409/-1/-2/-3 | 27-32-01 | Pitch Trim Actuator | AVIAC | CMM w. IPC | 31.12.94 | 7 09.11.11 | VDN-0034 | S | SAGEM | 3A |
| 328-0080 | 27-32-20 | Trim Panel | COBHAM | CMM w. IPC | 01.10.93 | 3 06.09.10 | VDN-0164 | S | NEC AERO | 3A |
| 4330 | 27-33-02 | Stick Shaker | AVIAC | CMM w. IPC | 20.10.92 | 1 10.06.07 | VDN-0036 | S | SAGEM | 3A |
| 8432-1 | 27-33-03 | Stick Pusher Actuator | SAGEM | CMM w. IPC | 15.03.94 | 6 08.04.19 | VDN-0031 | S | AVIAC | 3A |
| 1048A0000-02/-04 | 27-50-22 | Flap Actuator | LIEBHERR | CMM w. IPC | 30.10.95 | 2 20.10.00 | VDN-0135 | S | | 3A |
| 1050A0000-XX | 27-52-10 | Flap Control Unit | LIEBHERR | CMM w. IPC | 30.01.98 | 2 26.09.04 | VDN-0133 | S | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1049A0000-02 | 27-52-12 | Flap Valve Block | LIEBHERR | CMM w. IPC | 30.06.93 | 1 30.01.98 | VDN-0130 | S | | | 3A |
| 1053A0000-02 | 27-52-18 | Flap Control Switch | LIEBHERR | CMM w. IPC | 11.12.95 | 1 30.01.98 | VDN-0131 | S | | | 3P |
| 328-3150 | 27-60-01 | Ground Spoiler Test Panel | COBHAM | CMM w. IPC | 28.01.98 | 1 01.07.99 | VDN-0524 | S | | NEC AERO | 3A |
| ZCV193-4 | 27-60-06 | Valve-Double Shuttle | CIRCLE SEAL | CMM w. IPC | 17.08.94 | | ZTP-220 | S | | ZEVCO | 3P |
| 1059A0000-02 | 27-62-10 | Ground Spoiler Actuator | LIEBHERR | CMM w. IPC | 30.09.93 | 1 30.12.99 | VDN-0116 | S | | | 3P |
| 1059A0000-03 | 27-62-11 | Ground Spoiler Actuator | LIEBHERR | CMM w. IPC | 09.09.98 | 1 15.07.14 | VDN-0117 | S | | | 3A |
| 1060A0000-06 | 27-62-12 | Ground Spoiler Valve Block | LIEBHERR | CMM w. IPC | 30.06.93 | 1 30.01.98 | VDN-0137 | S | | | 3P |
| 1058A0000-03 | 27-62-16 | Roll Spoiler Actuator | LIEBHERR | CMM w. IPC | 30.09.93 | 2 28.08.19 | VDN-0136 | S | | | 3A |
| 251174 | 27-70-01 | Gust Lock Control | MORSE | CMM w. IPC | 01.05.95 | 1 01.11.96 | VDN-0158 | S | | | 3P |
| FE217-004 | 27-70-05 | Rudder Damper Assembly | RATIER FIGEAC | CMM w. IPC | 25.03.92 | 4 28.02.03 | VDN-0212 | S | | | 3P |
| FE255-000/-001 | 27-70-06 | Rudder Damper Assembly | RATIER FIGEAC | CMM w. IPC | 15.01.96 | 4 02.06.20 | VDN-0210 | S | | | 3A |
| 1234A0000-01 | 27-72-01 | Rudder Gust Damper | LIEBHERR | CMM w. IPC | 28.11.96 | | VDN-0335 | S | | | 3P |
| 4100-849049 | 28-09-04 | Motor Driven Hydraulic Pump Assy | AERO CONTROLEX | CMM w. IPC | 17.07.97 | 3 30.05.01 | VDN-0380 | S | | | 3A |
| B49 - Series | 28-10-03 | Fuel Drain Valve Assy | GKN WESTL.SITEC | CMS | 01.09.92 | | VDN-0050 | S | | | 3A |
| L94E31-651 | 28-19-86 | Re- and Defuelling Valve | INTERTECHNIQUE | CMM w. IPC | 15.04.92 | 2 16.07.12 | VDN-0115 | S | | ZENITH-AVIATION | 3A |
| K97-63-603P2 | 28-19-87 | Refuelling Adapter | INTERTECHNIQUE | CMM w. IPC | 15.04.92 | 2 01.10.94 | VDN-0119 | S | | ZENITH-AVIATION | 3A |
| 219335-3/219336-2 | 28-20-06 | Fuel Jet Pumps | INTERTECHNIQUE | CMM w. IPC | 15.04.92 | 4 28.10.13 | VDN-0118 | S | | ZODIAC | 3A |
| 177310 | 28-21-11 | Fuel Booster Pump | TEST-FUCHS | CMM w. IPC | 04.04.96 | 2 21.01.11 | VR 1007 | S | | | 3P |
| 1C12-42 | 28-21-12 | Centrifugal Fuel Boost Pump | PARKER | CMM w. IPC | 23.05.00 | | VDN-0179 | S | | | 3P |
| 40006 | 28-23-10 | Signal Processing /Refueling Panel | ROGERSON | CMM w. IPC | 15.07.95 | 1 17.11.09 | 9967-0246 | S | | | 3P |
| B14000 | 28-29-14 | Fuel Shut - Off Valve | GKN WESTL.SITEC | CMM w. IPC | 01.09.92 | | VDN-0095 | S | | | 3A |
| 30011-1 | 28-41-01 | Sensor, Tank Unit, Innertank | ROGERSON | CMM w. IPC | 15.07.95 | | VDN-0224 | S | | | 3A |
| 30011-2 | 28-41-02 | Sensor, Tank Unit, Outertank | ROGERSON | CMM w. IPC | 15.07.95 | | VDN-0215 | S | | | 3A |
| 30011-3 | 28-41-03 | Sensor, Tank Unit, Outertank | ROGERSON | CMM w. IPC | 15.07.95 | | VDN-0214 | S | | | 3A |
| 30011-4 | 28-41-04 | Sensor, Tank Unit, Feeder Tank | ROGERSON | CMM w. IPC | 15.07.95 | | VDN-0216 | S | | | 3A |
| L98B621/-2/-6/-7 | 28-41-14 | Fuel Level Indicator | INTERTECHNIQUE | CMM w. IPC | 15.04.92 | 1 01.10.94 | VDN-0201 | S | | ZENITH-AVIATION | 3A |
| 30013 | 28-42-03 | Sensor, Fuel Level | ROGERSON | CMM w. IPC | 15.07.95 | | VDN-0217 | S | | | 3A |
| 6033-01/02-1/2/03-1 | 28-48-04 | Signal Processor and Refueling Panel Volume 1 | GE AVIATION | CMM w. IPC | 15.07.97 | 3 24.09.10 | GEK 118086 | S | | Formlerly Smiths Aerospace, then GE Aviationn, now ONTIC | 3A |
| 6033-01/02-1/2/03-1 | 28-48-04 | Signal Processor and Refueling Panel Volume 2 | GE AVIATION | CMM w. IPC | 15.07.97 | 3 24.09.10 | GEK 118101 | S | | Formlerly Smiths Aerospace, then GE Aviationn, now ONTIC | 3A |
| 3900001-101 to -109 | 29-10-29 | 3000 PSI Ribbed Shell Accumulator | PARKER | CMM w. IPC | 12.09.91 | 8 07.03.14 | VDN-0178 | S | | 3900001-101/-105/-107/-108/-109 | 3A |
| 42086/4208601 | 29-10-50 | Electric Motor Driven Variable Delivery Hydraulic Pump | PARKER | CMM w. IPC | 01.09.93 | 1 01.03.03 | VDN-0433 | S | | | 3P |
| 4208601 | 29-10-50 | Introduction of P/N 4208601 | PARKER | TR-29-409 | 28.09.11 | | VDN-0433 | S | | | 3A |
| 4208601 | 29-10-50 | Insert facing page 118 | PARKER | TR-29-410 | 28.09.11 | | VDN-0433 | S | | | 3A |
| QA07376-01 / QA07770 | 29-10-76 | Pressure Sensing Valve | PALL | CMM w. IPC | 31.01.95 | 2 14.01.20 | VDN-0199 | S | | | 3P |
| QA07770 | 29-10-78 | Pressure Sensing Valve | PALL | CMM w. IPC | 09.07.14 | | VDN-0498 | S | | | 3A |
| QA07390 / QA07704 | 29-11-07 | Main Filter Package | PALL | CMM w. IPC | 31.01.95 | 3 12.12.16 | VDN-0006 | S | | | 3P |
| 4100-849048 | 29-12-01 | Motor Driven Hydraulic Pump Assy | AERO CONTROLEX | CMM w. IPC | 15.08.94 | 3 15.10.02 | VDN-0003 | S | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 705000 | 29-12-02 | Hydraulic DC Standby Pump | TEST-FUCHS | CMM w. IPC | 19.09.16 | | 705000 | S | | | 3A |
| HP1594100-1 | 29-20-01 | Dual Stage Hydraulic Hand Pump | TACTAIR | CMM w. IPC | 15.12.95 | | VDN-0243 | S | | | 3P |
| 3360 | 29-21-02 | Relief Valve and Pressure Dump | PneuDraulics | CMM w. IPC | 24.09.09 | | 06177-3360 | S | | | 3P |
| 5E2546/5E2547 | 30-10-19 | Elevator a. Rudder Horn Anti-Icer | BFG ICE | INSTAL.M | 07.03.06 | | VDN-0052 | O | | | 3A |
| 74-451-XX | 30-10-25 | De-Icer Patch Instructions | BFG ICE | INSTR.M | 17.10.97 | 16.05.02 | VDN-0053 | O | | | 3P |
| 74-451-AC | 30-10-27 | Erosion Repair Kit | BFG ICE | AMR | 12.04.99 | 2 25.03.02 | VDN-0054 | O | | | 3P |
| 600100-00/-10-500 | 30-10-28 | Timer, De-Icing | TELAIR | CMS | 02.12.97 | | VDN-0245 | S | | NORD-MICRO | 3A |
| | 30-10-31 | Black Standard Pneumatic De-Icer Installation, Maintenance and Repair Manual | BFG ICE | IM | 15.11.96 | 5 06.06.12 | VDN-0055 | S | | | 3A |
| 4D2185-01 | 30-10-42 | Pre-Cooler | BFG ICE | CMM w. IPC | 15.04.99 | | VDN-0120 | S | | | 3P |
| 4D2095-200/220 | 30-10-43 | Pressure Regulator/Reliever | UTC | CMM w. IPC | 01.02.02 | 2 31.08.20 | VDN-0126 | S | | Goodrich | 3P |
| 3D3553-01 | 30-10-44 | Water Seperator | BFG ICE | CMM w. IPC | 01.02.02 | 1 25.11.19 | VDN-0426 | S | | | 3A |
| 3D3557-01 | 30-10-45 | Pressure Switch | BFG ICE | CMM w. IPC | 15.12.00 | | VDN-0140 | S | | | 3A |
| 3D3554-02 | 30-10-46 | Isolation Valve, De-Icing | BFG ICE | CMM w. IPC | 15.01.99 | | VDN-0425 | S | | | 3P |
| 3D3555-01 | 30-10-47 | Check Valve | BFG ICE | CMM w. IPC | 30.03.99 | 1 14.01.20 | VDN-0226 | S | | | 3A |
| 3D3556-01/-03 | 30-10-48 | Ejector Flow Control Valve | UTC | CMM w. IPC | 01.02.02 | 1 30.01.20 | VDN-0227 | S | | Goodrich / BFG ICE | 3A |
| 3D3573-01/-02 | 30-10-55 | PRESSURE RELIEF VALVE | BFG ICE | CMM w. IPC | 01.12.99 | | VDN-0409 | S | | | 3P |
| | 30-10-66 | FASTboot Silver Urethane Pneumatic De-Icer | BFG ICE | INSTAL.M | 05.03.09 | 3 11.01.19 | VDN-0550 | S | | Now is UTC Aerospace | 3A |
| | 30-10-70 | FASTboot Pneumatic De-Icer | BFG ICE | INSTR.M | 10.04.00 | 6 13.04.18 | VDN-0274 | S | | 74-451-XX | 3A |
| 3D3190-1-2 | 30-10-73 | Temperature Switch | BFG ICE | CMM w. IPC | 15.04.99 | | VDN-0282 | S | | | 3A |
| | 30-10-76 | FASTboot Silver Estane Pneumatic De-Icer | BFG ICE | INSTAL.M | 07.12.99 | 8 17.10.12 | VDN-0551 | S | | | 3A |
| 84400-3 | 30-13-01 | Check Valve | ROGERSON | CMM w. IPC | 01.07.95 | | VDN-0221 | S | | | 3A |
| 85100-3 | 30-13-06 | Ejector Flow Valve | ROGERSON | CMM w. IPC | 01.07.95 | | VDN-0223 | S | | | 3P |
| 5150DO-1 | 30-13-09 | Isolation Valve | ROGERSON | CMM w. IPC | 01.07.95 | | VDN-0220 | S | | | 3P |
| 85000-5 | 30-13-10 | Pressure Switch | ROGERSON | CMM w. IPC | 01.07.95 | | VDN-0222 | S | | | 3P |
| 5570DO-3 | 30-13-11 | Water Separator | ROGERSON | CMM w. IPC | 01.07.95 | | VDN-0213 | S | | | 3P |
| 4990DO-2 | 30-13-12 | Air Pressure Regulator Valve | ROGERSON | CMM w. IPC | 01.07.95 | | VDN-0219 | S | | | 3P |
| 4337122/38 | 30-41-03 | Motor-Converter | SAFRAN | CMM w. IPC | 31.12.91 | 5 22.08.19 | VDN-0246 | S | | Ex ZODIAC | 3A |
| 4298816/-09 | 30-41-04 | Wiper-Arm LH/RH | TELEFLEX | CMS | 01.03.92 | 1 01.07.00 | VDN-0247 | S | | ZODIAC | 3A |
| 4298823 | 30-41-05 | Wiper-Blade | TELEFLEX | CMS | 01.03.92 | 1 01.09.94 | VDN-0248 | S | | ZODIAC | 3A |
| 3285-10 | 30-42-02 | Windscreen Heater Control Unit | DIEHL | CMM w. IPC | 25.07.94 | 1 30.06.00 | VDN-0068 | S | | | 3P |
| 3285-50 | 30-42-03 | Control Unit, Window Heat | DIEHL | CMM w. IPC | 10.04.00 | | VDN-0229 | S | | | 3A |
| 4E2947-3 | 30-60-12 | Timer/Monitor | BFG ICE | ACMM | 01.02.01 | 1 02.09.08 | VDN-0556 | S | | | 3A |
| | 30-61-80 | Propeller Ice Protection System Manual | HARTZELL | SMM | 01.07.06 | 38 01.06.22 | 180 | S | | Manual 181 & 182 & 183 included with Rev 27 | 3P |
| 0871DW1 | 30-81-17 | ICE Detector | ROSEMOUNT | CMM w. IPC | 01.11.90 | | VDN-0209 | S | | | 3A |
| 328-0020/21 | 31-11-05 | AC/DC Panel | COBHAM | CMM w. IPC | 01.10.93 | 1 30.06.95 | VDN-0166 | S | | NEC AERO | 3A |
| 328-0030/-31 | 31-12-11 | Forward Combined Panel | COBHAM | CMM w. IPC | 01.10.93 | 2 30.04.99 | VDN-0169 | S | | NEC AERO | 3P |
| 328-007XAmdtB/C /-3074 | 31-12-12 | OXYGEN/ECS Panel | COBHAM | CMM w. IPC | 01.10.93 | 2 25.06.99 | VDN-0165 | S | | NEC AERO | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| 328-0010 | 31-12-13 | Ice - Fuel - Hydro Panel | COBHAM | CMM w. IPC | 01.10.93 | 1 30.06.95 | VDN-0170 | S | NEC AERO | 3P |
| 328-0100 | 31-12-15 | Flight Attendant Panel | COBHAM | CMM w. IPC | 01.10.93 | 4 31.07.07 | VDN-0163 | S | NEC AERO | 3A |
| AT6421R1 | 31-20-00 | Digital Chronometer Model LC-60 | ASTROTECH | CMM w. IPC | 16.11.95 | 0 17.11.99 | VDN-0019 | S | TRANSICOIL | 3A |
| 328-0090 | 31-25-01 | Reversionnary Panel | COBHAM | CMM w. IPC | 01.10.93 | 1 30.06.95 | VDN-0160 | S | NEC AERO | 3A |
| 17M800-261 | 31-30-01 | Digital Flight Recorder | L3 AVIATION RECORDER | CMM w. IPC | 01.08.88 | 2 31.01.94 | 165E0049-00 | S | Model F800 | 3P |
| 17-M800-(XXX) | 31-30-01 | Digital Flight Recorder Model F800 | L3 AVIATION RECORDER | IOIM | 01.10.03 | 1 | 165E3359-00 | S | Supersedes FAR02283174 | 3P |
| S800-2000/3000-00 | 31-30-02 | FA2100CVR Solid State Flight Data Recorder | L3 AVIATION RECORDER | CMM w. IPC | 01.08.91 | 5 01.03.04 | 165E0503-00 | S | Model F1000 | 3P |
| 2100-4043-00 | 31-30-03 | Flight Data Recorder | L3 AVIATION RECORDER | CMM w. IPC | 01.10.98 | 14 12.04.19 | 165E1688-00 | S | Model FA2100 | 3A |
| 2100-4043-00 | 31-30-03 | Flight Data Recorder | L3 AVIATION RECORDER | CMM w. IPC | 01.10.98 | 12 19.02.18 | 165E1688-00 | S | Model FA2100 | 3A |
| QAR2XX-XX-XX | 31-30-20 | microQAR (Quick ACCESS RECORDER) | L3 AVIATION RECORDER | CMM w. OIM | 31.03.03 | 7 01.02.11 | 165E2810-0 | S | L3 | 3A |
| 980-4700-XXX | 31-30-40 | FA2100CVR Solid State Flight Data Recorder | HONEYWELL ASIG | CMM w. IPC | 01.12.92 | 27 18.05.11 | 012-0650-001 | S | ALLIEDSIGNAL | 3P |
| 3001-01-100 | 31-33-15 | Accelerometer | AMETEK | CMM w. IPC | 01.07.86 | 6 12.12.15 | VDN-0012 | S | PATRIOT | 3A |
| 7013348-9XX | 31-40-01 | DA-800 Data Acquisition Unit | HONEYWELL | CMM w. IPC | 01.11.93 | 10 24.02.20 | M15-1147-042 | S | | 3A |
| 8-700 | 31-41-00 | Proximity Sensor Electr. Unit | ELDEC | ITEM | 15.03.94 | | 011-2921-002 | O | Now is CRANE | 3P |
| 8-700-04/-05 | 31-41-09 | Proximity Sensor Electronic Unit | CRANE | CMM w. IPC | 01.09.96 | 5 17.02.21 | 011-2910-616 | S | was ELDEC | 3P |
| WT228 | 31-50-01 | Warning/Caution Panel | AOA | CMM w. IPC | 01.03.86 | 6 09.11.98 | WT228 | S | | 3A |
| 3274-10 | 31-50-99 | Red Warning Panel | DIEHL | TR 001 | 20.11.03 | | 31-50-99_001 | S | | 3A |
| 3274-10 | 31-50-99 | Red Warning Panel | DIEHL | CMM w. IPC | 20.03.95 | | VDN-0070 | S | | 3A |
| 22730/22731-000-XX | 32-00-01 | MLG - Operating Instructions | MESSIER-DOWTY | T. LEAFL. | 01.04.91 | 2 01.09.93 | VDN-0144 | O | | 3P |
| 23100-000-00 /-1/-2/-3 | 32-00-02 | NLG - Operating Instructions | MESSIER-DOWTY | T. LEAFL. | 30.09.92 | 2 07.03.95 | VDN-0152 | O | | 3P |
| 22910-000-01 | 32-07-15 | Electrical Harness | MESSIER-DOWTY | CMM w. IPC | 31.07.98 | 1 15.07.06 | VDN-0289 | S | | 3P |
| 22915-000-01 | 32-07-16 | Electrical Harness | MESSIER-DOWTY | CMM w. IPC | 31.07.98 | 1 15.07.06 | VDN-0290 | S | | 3P |
| 22760/22765-000-00 | 32-07-17 | Electrical Harness | MESSIER-DOWTY | CMM w. IPC | 31.07.98 | 1 15.07.06 | VDN-0318 | S | | 3P |
| 23055-000-00 | 32-07-21 | NLG - Feedback Potentiometer Harness | MESSIER-DOWTY | CMM w. IPC | 05.11.01 | 1 15.07.06 | VDN-0375 | S | | 3A |
| 23285-000-00 | 32-07-22 | NLG - Electrical Control Harness | MESSIER-DOWTY | CMM w. IPC | 05.11.01 | 1 15.07.06 | VDN-0354 | S | | 3P |
| 23415-000-00 | 32-07-23 | NLG - Main Electrical Harness | MESSIER-DOWTY | CMM w. IPC | 05.11.01 | 1 15.07.06 | VDN-0355 | S | | 3P |
| 23425-000-00 | 32-07-24 | NLG - Electrical Power Harness | MESSIER-DOWTY | CMM w. IPC | 05.11.01 | 1 15.07.06 | VDN-0356 | S | | 3P |
| 23265-000-00 | 32-07-28 | NLG - Uplock Electrical Harness | MESSIER-DOWTY | CMM w. IPC | 05.11.01 | 1 15.07.06 | VDN-0377 | S | | 3P |
| 22515/6-000-00 | 32-11-00 | Main Landing Gear | MESSIER-DOWTY | IPC | 01.05.93 | 4 29.05.09 | VDN-0419 | O | ERAM | 3A |
| 22730/22731-000-XX | 32-11-01 | Main - Leg | MESSIER-DOWTY | CMM w. IPC | 31.05.92 | 9 31.12.12 | VDN-0353 | S | | 3P |
| 22420-000-XX | 32-11-04 | Shock Absorber | MESSIER-DOWTY | CMM w. IPC | 31.03.92 | 8 31.12.12 | VDN-0348 | S | | 3P |
| 24260-000-00/-01/-02 | 32-11-12 | Brace Assy | MESSIER-DOWTY | CMM w. IPC | 15.09.93 | 5 31.12.12 | VDN-0147 | S | | 3P |
| 23100-000-00 /-1/-2/-3 | 32-21-00 | NLG - Shock Strut Assembly | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0481 | S | | 3P |
| 23110-000-01 | 32-21-01 | Shock Absorber | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0156 | S | | 3P |
| 23200-000-01/02 | 32-21-16 | Brace Assy | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0347 | S | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 23100-300-00-/-1-4 | 32-21-30 | NLG - Shock Strut Assembly | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0155 | S | | Supersedes 23100-300-00 | 3A |
| 23110-300-00 | 32-21-31 | Shock Absorber | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0351 | S | | | 3A |
| 23200-300-00/-01/-2 | 32-21-32 | NLG - Brace Assembly | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0350 | S | | Supersedes Rev.1 May 15/1999 | 3A |
| HP848800 | 32-30-02 | Landing Gear Control Valve | TACTAIR | TR 32-01 | 24.04.13 | | VDN-0242 | S | | | 3A |
| HP848800-4 | 32-30-02 | Landing Gear Control Valve | TACTAIR | CMM w. IPC | 01.08.95 | | VDN-0242 | S | | | 3A |
| 717801-1 | 32-31-01 | Landing Gear Control Assembly | EATON | CMM w. IPC | 01.12.92 | A 01.07.95 | VDN-0081 | S | | | 3A |
| 717801-1 | 32-31-01 | LANDING GEAR CONTROL ASSEMBLY | SAFRAN | CMM w. IPC | 01.07.95 | 1 22.06.16 | VDN-0408 | S | | SAGEM | 3A |
| 22495-000-01 | 32-31-04 | NLG - Unlock Actuator | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0279 | S | | Supersedes 22495-000-00 | 3A |
| 22405-000-02/03/04 | 32-31-05 | Uplock Assembly | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0154 | S | | | 3P |
| 24125-000-00 | 32-31-06 | Actuating Cylinder | MESSIER-DOWTY | CMM w. IPC | 31.03.92 | 4 15.07.06 | VDN-0145 | S | | | 3A |
| 22445-000-00 | 32-31-07 | Unlocking Cylinder | MESSIER-DOWTY | CMM w. IPC | 30.04.92 | 3 15.07.06 | VDN-0418 | S | | ERAM | 3A |
| 22890-000-01 | 32-31-09 | Restrictor Check Valve | MESSIER-DOWTY | TDS | 31.05.93 | 1 31.01.95 | VDN-0148 | S | | | 3A |
| 22895-000-01 | 32-31-10 | Restrictor Check Valve | MESSIER-DOWTY | TDS | 31.05.93 | 1 31.01.95 | VDN-0149 | S | | | 3A |
| 24120-000-00 | 32-31-11 | Restrictor Check Valve | MESSIER-DOWTY | TDS | 31.05.93 | 1 31.01.95 | VDN-0151 | S | | | 3A |
| 22455-000-00/-1 | 32-32-00 | MLG - Assist Actuator | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0153 | S | | Supersedes 22455-000-00 | 3A |
| | 32-41-00 | Aircraft Tyres and Tubes | DUNLOP | ACMM | | 4 01.02.17 | VDN-0553 | S | | Tire Care & Maintenace Manual | 3A |
| | 32-41-00 | Aircraft Tire Care and Maintenance | GOOD YEAR | GUIDE | 01.06.16 | | 700-862-931-538 | S | | | 3A |
| 90002024 | 32-41-34 | Main Wheel Assy | ABSC | TR 32-2 | 26.10.04 | | AP-857 | S | | | 3P |
| 90002024 | 32-41-34 | Main Wheel Assy | ABSC | CMM w. IPC | 01.06.01 | 1 15.10.03 | AP-857 | S | | P/N 2610701-2 (HALS part) Superseded by P/N 90002024-1 (ABSC now MEGGITT) | 3P |
| 90002024 | 32-41-34 | Main Wheel Assy | ABSC | TR 32-3 | 08.03.06 | | AP-857 | S | | | 3P |
| 90002024 | 32-41-34 | Main Wheel Assy | ABSC | TR 32-4 | 03.01.07 | | AP-857 | S | | | 3P |
| | 32-42-03 | Nondestructive Testing Manual with Procedures | ABSC | TR 32-2 | 16.05.11 | | AP-763 | S | | | 3A |
| | 32-42-03 | Nondestructive Testing Manual with Procedures | ABSC | NTM | 18.03.94 | 1 01.03.05 | AP-763 | S | | | 3A |
| AC69895/69963 | 32-42-03 | Brake Metering Unit | DUNLOP | CMM w. IPC | 31.03.99 | | VDN-0315 | S | | | 3P |
| AC70071 | 32-42-04 | Brake Metering Unit | MABS | CMM w. IPC | 15.06.01 | 4 12.03.15 | AP-2082 | S | | | 3P |
| S4-3402000-1 | 32-43-02 | Emergency Park / Brake Valve | FWM | CMM w. IPC | 20.07.92 | 1 29.04.93 | VDN-0138 | S | | | 3P |
| AC69965, AC69965-2/-3 | 32-43-02 | Emergency/Park Brake Valve | MABS | CMM w. IPC | 31.10.97 | 8 12.03.15 | AP-2113 | S | | | 3P |
| ACM30492 | 32-43-30 | Master Cylinder | MABS | CMM w. IPC | 25.02.93 | 2 18.04.13 | AP-2121 | S | | | 3P |
| ACM30488 | 32-43-31 | Aircraft Applicability | DUNLOP | AEM | 27.06.94 | | DM1443-47 | O | | | 3P |
| ACM30488 | 32-43-31 | Hydraulic Fuse | MABS | CMM w. IPC | 20.04.93 | 6 12.03.15 | AP-2122 | S | | | 3P |
| ACM30496/30662 | 32-43-32 | Wheel Speed Transducer Installation | MABS | CMM w. IPC | 22.10.92 | 6 12.03.15 | AP-2123 | S | | | 3P |
| AE20464 / AE20768 | 32-43-36 | Anti-Skid Control Unit | MABS | CMM w. IPC | 09.10.92 | 4 12.03.15 | AP-2124 | S | | | 3P |
| AE20824 | 32-43-46 | Anti-Skid Conrol Unit | MABS | CMM w. IPC | 31.01.99 | 4 12.03.15 | AP-2129 | S | | | 3P |
| 90002030 | 32-44-26 | Brake Assy | MABS | CMM w. IPC | 01.06.01 | 2 12.06.08 | AP-858 | S | | ABSC | 3P |
| 026-675-0 | 32-45-01 | Aircraft Tire Care & Service Manual | MICHELIN | CSM | 01.01.01 | 15.12.11 | VDN-0360 | S | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 2610702-2/-3 | 32-46-01 | Brake Assembly | ALLIEDSIGNAL | CMM w. IPC | 31.08.92 | 8 31.01.98 | FORM 12-597 | S | | | 3P |
| 2610485-1 | 32-46-03 | Nose Wheel Assembly | ALLIEDSIGNAL | CMM w. IPC | 31.08.92 | 1 30.05.97 | FORM 12-599 | S | | | 3P |
| | 32-46-35 | Standard Practices Manual | MABS | SPM | 02.07.01 | 7 16.04.21 | AP-842 | S | | ABSC | 3A |
| 90002021 /-1, (2610485-1) | 32-46-37 | Nose Wheel Assy | ABSC | CMM w. IPC | 01.06.01 | 2 08.11.14 | AP-859 | S | | | 3P |
| | 32-49-01 | Standard Practices Manual | HONEYWELL ASIG | SPM | 31.12.98 | 3 30.04.00 | FORM 12-622 | S | | ALLIEDSIGNAL | 3A |
| 23040-000-01 | 32-51-07 | Steering Control Valve | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0143 | S | | | 3A |
| 23180-000-01/-02 | 32-51-08 | Electronic Control Unit | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0352 | S | | | 3A |
| 2LA004626-05 | 33-11-09 | Flight Crew Reading Light | HELLA | CMM w. IPC | 10.10.95 | 1 22.01.02 | VDN-0108 | S | | GOODRICH HELLA | 3A |
| 2LA005163-30 | 33-11-22 | Flight Crew Reading Light | HELLA | CMM w. IPC | 08.07.91 | 5 01.03.16 | VDN-0098 | S | | GOODRICH HELLA | 3A |
| 2LA006778-00 | 33-11-44 | Instrument Panel Light | HELLA | CMM w. IPC | 29.04.94 | 1 06.06.01 | VDN-0173 | S | | GOODRICH HELLA | 3A |
| 2LA006672-00 | 33-11-48 | Pedestal Light, Observer Light | HELLA | CMM w. IPC | 29.04.94 | | VDN-0105 | S | | GOODRICH HELLA | 3A |
| 2LA006633-00/-01 | 33-12-06 | Dome Light | HELLA | CMM w. IPC | 29.04.94 | | VDN-0102 | S | | GOODRICH HELLA | 3A |
| 3296-30/-40 | 33-13-11 | Lighting Dimmer | DIEHL | CMM w. IPC | 15.07.96 | 3 11.03.08 | VDN-0072 | S | | | 3A |
| 2LA005109-Serie | 33-20-06 | Cargo Compartment Light | HELLA | CMM w. IPC | 10.05.88 | 1 18.05.95 | VDN-0107 | S | | GOODRICH HELLA | 3P |
| 2LA005171-55/-60 | 33-22-08 | Reading Light | HELLA | CMM w. IPC | 01.05.95 | 1 08.08.96 | VDN-0188 | S | | GOODRICH HELLA | 3A |
| 2LA00661X-Serie | 33-22-09 | Passenger Service Units | HELLA | CMM w. IPC | 15.02.94 | 1 20.07.00 | VDN-0104 | S | | GOODRICH HELLA | 3A |
| 3253-10 | 33-24-99 | Ballast Unit | DIEHL | CMM w. IPC | 20.02.95 | 2 28.09.01 | VDN-0415 | S | | | 3A |
| 2LA005113-00 | 33-26-41 | Indicator Light | HELLA | CMM w. IPC | 10.05.88 | 1 18.11.94 | VDN-0103 | S | | GOODRICH HELLA | 3A |
| 2LA006823-01 | 33-31-13 | Cargo Compartment Light | HELLA | CMM w. IPC | 01.03.00 | 2 19.03.14 | VDN-0482 | S | | GOODRICH HELLA | 3A |
| 2LA002428-00 | 33-32-01 | Light | HELLA | CMM w. IPC | 15.07.82 | 5 19.03.14 | VDN-0183 | S | | GOODRICH HELLA | 3A |
| 1X4004429-00 | 33-40-14 | Landing Light | HELLA | CMM w. IPC | 01.03.94 | 1 22.09.99 | VDN-0106 | S | | GOODRICH HELLA | 3A |
| 1X0004427-05 | 33-40-19 | Taxi Light | HELLA | CMM w. IPC | 01.01.94 | | VDN-0097 | S | | GOODRICH HELLA | 3A |
| 1XA006726/7-00 | 33-40-22 | Wing Inspection Light | HELLA | IPL | 08.02.01 | | VDN-0099 | S | | GOODRICH HELLA | 3A |
| 1XA006726/7-00 | 33-40-22 | Wing Inspection Light | HELLA | CMM w. IPC | 15.11.92 | | VDN-0099 | S | | GOODRICH HELLA | 3A |
| 1X0006678-00 | 33-40-23 | Logo Light | HELLA | CMM w. IPC | 15.11.92 | | VDN-0100 | S | | GOODRICH HELLA | 3A |
| 1X0006678-00 | 33-40-23 | Logo Light | HELLA | IPL | 10.02.01 | | VDN-0100 | S | | GOODRICH HELLA | 3A |
| 2LA004186-00 | 33-41-12 | Tail Light | HELLA | CMM w. IPC | 11.05.00 | | VDN-0187 | S | | GOODRICH HELLA | 3P |
| 02-1510-8011 | 33-49-02 | ACL-1000 Cable Assy, Model 1510 | FLIGHT COMP. | CMM w. IPC | 15.04.94 | | VDN-0092 | S | | | 3P |
| 03-1805-2001-2 | 33-49-03 | ACL-1000 Light Assy, Model 1805 | B/E Aerospace | CMM w. IPC | | 1 02.08.16 | VDN-0612 | S | | | 3A |
| 03-2901-2003/4 | 33-49-03 | ACL-1000 Light Assy, Model 2901 | FLIGHT COMP. | CMM w. IPC | 20.03.99 | 2 07.07.08 | VDN-0088 | S | | | 3A |
| 03-2700-2006 | 33-49-03 | ACL-1000 Light Assy, Model 2700 | FLIGHT COMP. | CMM w. IPC | 04.12.98 | | VDN-0089 | S | | | 3A |
| 03-1805-2001 | 33-49-03 | ACL-1000 Light Assy, Model 1805 | FLIGHT COMP. | CMM w. IPC | 15.04.94 | 2 07.11.02 | VDN-0091 | S | | | 3A |
| 03-2100-2003/4 | 33-49-03 | ACL-1000 Light Assy, Model 2100 | FLIGHT COMP. | CMM w. IPC | 15.04.94 | 3 07.07.08 | VDN-0093 | S | | | 3P |
| 03-2103-2003/4 | 33-49-03 | ACL-1000 Light Assy, Model 2103 | FLIGHT COMP. | CMM w. IPC | 15.04.99 | 2 07.07.08 | VDN-0393 | S | | | 3P |
| 04-1604-1429 | 33-49-04 | ACL-1000 Power Supply Model 1604 | B/E Aerospace | CMM w. IPC | 04.11.99 | 4 09.02.16 | VDN-0087 | S | | FLIGHT COMP. | 3A |
| 04-1504-1429 | 33-49-04 | ACL-1000 Power Supply Model 1504 | FLIGHT COMP. | CMM w. IPC | 15.04.94 | 3 23.08.04 | VDN-0090 | S | | | 3P |
| 07-2700-2000 | 33-49-07 | ACL-1000 Electronic Switch, Model 2700 | FLIGHT COMP. | CMM w. IPC | 11.03.03 | | VDN-0611 | S | | | 3A |
| | 33-50-01 | Emergency Egress Lighting Syst. | LUMINESCENT | SMIM | 30.01.88 | 6 01.05.99 | VDN-0139 | S | | | 3A |
| | 33-50-02 | Emergency Egress Lighting Syst. | LUMINESCENT | IPC | 01.05.99 | | VDN-0139 | S | | | 3A |
| 3214-30 | 33-51-07 | Battery | DIEHL | CMM w. IPC | 15.02.83 | 5 04.02.98 | VDN-0073 | S | | | 3A |
| 3214-31 | 33-51-17 | Battery | DIEHL | CMM w. IPC | 08.07.02 | 12 13.07.21 | VDN-0422 | S | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 3214-73 | 33-51-99 | Emergency Power Supply Unit | DIEHL | CMM w. IPC | 01.09.94 | 2 02.07.10 | VDN-0071 | S | | | 3A |
| 2LA006729-00 | 33-52-03 | Emergency Light | HELLA | IPL | 26.06.01 | | VDN-0101 | S | | GOODRICH HELLA | 3A |
| 2LA006729-00 | 33-52-03 | Emergency Light | HELLA | CMM w. IPC | 15.11.92 | | VDN-0101 | S | | GOODRICH HELLA | 3A |
| 0851GW / 0851GW-1 | 34-10-73 | Pitot Tube | ROSEMOUNT | CMM w. IPC | 01.09.98 | 1 15.03.00 | VDN-0085 | S | | | 3A |
| WL101AMS1 | 34-11-41 | Altimeter/Airspeed Indicator | ONTIC | CMM w. IPC | 20.11.01 | 4 02.09.16 | VDN-0420 | S | | was GE Aviation | 3A |
| 0861EF1 | 34-12-27 | Angle Of Attack Sensor | ROSEMOUNT | CMM w. IPC | 15.02.92 | | VDN-0231 | S | | | 3A |
| 7014700-XXX | 34-16-17 | AZ-840 Micro Air Data Computer | HONEYWELL | CMM w. IPC | 01.02.91 | 8 10.09.19 | A09-3435-010 | S | | formerly A09-3735-10 | 3P |
| 501-1568-10 | 34-20-51 | AI-330 Attitude Indicator | L3 COMMUNICATIONS | IOM | 31.03.00 | C 05.02.18 | TP-454 | S | | BFG AVIONICS | 3A |
| 7014332-902 | 34-24-38 | BL-870/871 Bezel Controller | HONEYWELL | CMM w. IPC | 15.05.93 | 7 29.06.20 | A09-1147-038 | S | | | 3A |
| 7014300-902 | 34-24-39 | DU-870 Display Unit | HONEYWELL | CMM w. IPC | 15.08.93 | 7 08.02.19 | A09-1147-043 | S | | merged into a single-volume | 3A |
| 7016600-901/-902 | 34-24-43 | DL-900 Data Loader | HONEYWELL | CMM w. IPC | 15.06.92 | 4 15.10.15 | A09-1147-062 | S | | | 3A |
| WL1001KCA1 | 34-25-21 | Standby Compasses | SIRS NAVIGATION | CMM w. IPC | 10.04.03 | 11 | VDN-0431 | S | | former Smiths Ind. Aero | 3A |
| HG2010AC02, AC01, AC03 | 34-26-14 | Attitude Heading Reference Unit | HONEYWELL | CMM w. IPC | 15.09.95 | 1 17.06.14 | M15-3324-002 | S | | | 3A |
| CG1042AB04 | 34-26-15 | Mode Select Unit | HONEYWELL | CMM w. IPC | 20.11.87 | 7 18.07.08 | M15-3349-006 | S | | | 3A |
| HG2001AC02 | 34-26-18 | Inertial Reference Unit | HONEYWELL | CMM w. IPC | 15.06.95 | 3 14.01.00 | M15-3343-012 | S | | | 3A |
| HG2001AC02 | 34-26-18 | Inertial Reference Unit | HONEYWELL | TR 4 | 15.03.00 | | M15-3343-012 | S | | | 3A |
| HG2001AC02 | 34-26-18 | Inertial Reference Unit | HONEYWELL | TR 6 | 07.05.02 | | M15-3343-012 | S | | | 3A |
| | 34-40-01 | TRA-45A / Terrain Display Unit / Radio Altimeter Indicator | HONEYWELL | IM | 01.02.00 | 6 01.04.10 | VDN-0478 | S | | for use with the EGPWS | 3P |
| 7008470-922 | 34-40-30 | WU-650 Receiver Transm.Antenna Vol. I | HONEYWELL | CMM w. IPC | 01.05.86 | 5 15.12.02 | A09-3941-002 | S | | Supersedes A09-3941-02 | 3P |
| 7008470-922 | 34-40-30 | WU-650 Receiver Transm.Antenna Vol. II | HONEYWELL | CMM w. IPC | 15.12.02 | | A09-3941-002 | S | | Supersedes A09-3941-02 | 3P |
| 7008470-922 | 34-40-30 | WU-650 Receiver Transm.Antenna Vol. IIIB | HONEYWELL | CMM w. IPC | 01.10.92 | 1 15.12.02 | A09-3941-002 | S | | Supersedes A09-3941-02 | 3P |
| 7008470-922 | 34-40-30 | WU-650 Receiver Transm.Antenna Vol. IIIA | HONEYWELL | CMM w. IPC | 01.10.92 | 1 15.12.02 | A09-3941-002 | S | | Supersedes A09-3941-02 | 3P |
| 7001840-932/922 | 34-42-10 | RT-300 Radio Alti. Rec.Transm. | HONEYWELL | CMM w. IPC | 01.09.10 | 9 29.03.19 | A09-3531-010 | S | | Supersedes Vol. I - III | 3A |
| 7021450-601 | 34-42-11 | Receiver Transmitter Antenna | HONEYWELL | CMM w. IPC | 15.04.97 | 3 15.05.07 | A09-3944-002 | S | | | 3A |
| 7021450-601 | 34-42-11 | Receiver Transmitter Antenna | HONEYWELL | IPC | 15.04.97 | 3 15.05.07 | A09-3944-002 | S | | | 3A |
| 7021450-601/-801 | 34-42-12 | PRIMUS 660/880 Digital Weather Radar | HOL3NEYWELL | SDIM | 20.05.96 | 9 13.10.10 | D199605000036 | S | | A09-3944-001 | 3A |
| 4066010-904/-910 | 34-43-00 | TCAS II RT-910 | L3 ACSS | SDIM | 01.06.89 | 5 06.08.14 | C15-3841-005 | S | | ACSS-L3 | 3P |
| 4066010-904 | 34-43-04 | Traff. Alert a. Collision Avoid.System Vol. 3 | HONEYWELL L3 | CMM w. IPC | 01.07.90 | 10 15.12.05 | C15-3841-007 | S | | ACSS-L3; supersedes 15-3841-07; ATA change in to 34-45-04 | 3P |
| 4066010-904 | 34-43-04 | Traff. Alert a. Collision Avoid.System Vol. 1 | HONEYWELL L3 | CMM w. IPC | 01.07.90 | 11 15.12.05 | C15-3841-007 | S | | ACSS-L3; supersedes 15-3841-07; ATA change in to 34-45-04 | 3P |
| 4066010-904 | 34-43-04 | Traff. Alert a. Collision Avoid.System Vol. 2 | HONEYWELL L3 | CMM w. IPC | 01.04.94 | 5 15.12.05 | C15-3841-007 | S | | ACSS-L3; supersedes 15-3841-07; ATA change in to 34-45-04 | 3P |
| 7517900-10001/3 | 34-43-10 | TCAS 2000 | HONEYWELL | SDIM | 20.10.97 | 3 15.11.02 | A09-3841-001 | S | | ACSS-L3 | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| 7517900-10001/3 | 34-43-10 | TCAS 2000 | L3 ACSS | TR 6 | 15.07.11 | | A09-3841-001 | S | ACSS-L3 | 3A |
| 7517900-10001/3 | 34-43-10 | TCAS 2000 | L3 ACSS | TR 3 | 03.12.09 | | A09-3841-001 | S | ACSS-L3 | 3A |
| 7517900-10001/3 | 34-43-10 | TCAS 2000 | L3 ACSS | TR 4 | 15.12.09 | | A09-3841-001 | S | ACSS-L3 | 3A |
| 7517900-10001/3 | 34-43-11 | TCAS 2000 Computer Unit Vol. III | HONEYWELL L3 | CMM w. IPC | 30.10.97 | 9 15.08.06 | A09-3841-002 | S | ACSS-L3 | 3A |
| 7517900-10001/3 | 34-43-11 | TCAS 2000 Computer Unit Vol. I | HONEYWELL L3 | CMM w. IPC | 30.10.97 | 6 15.08.06 | A09-3841-002 | S | ACSS-L3 | 3A |
| 7517900-10001/3 | 34-43-11 | TCAS 2000 Computer Unit Vol. II | HONEYWELL L3 | CMM w. IPC | 30.10.97 | 7 15.08.06 | A09-3841-002 | S | ACSS-L3 | 3A |
| 4066010-XXX | 34-45-04 | Traffic Alert and Collision Avoidance System - Volume II | L3 ACSS | CMM w. IPC | 01.07.90 | 7 15.08.18 | C15-3841-007 | S | ACSS-L3 | 3A |
| 4066010-XXX | 34-45-04 | Traffic Alert and Collision Avoidance System - Volume I | L3 ACSS | CMM w. IPC | 01.07.90 | 13 15.08.18 | C15-3841-007 | S | ACSS-L3 | 3A |
| 4066010-XXX | 34-45-04 | Traffic Alert and Collision Avoidance System - Volume III | L3 ACSS | CMM w. IPC | 01.07.90 | 12 15.08.18 | C15-3841-007 | S | ACSS-L3 | 3A |
| 965-0676-021 | 34-45-30 | Ground Proximity Warning Computer | ALLIEDSIGNAL | CMM w. IPC | 17.07.91 | 10 27.01.06 | 012-0618-001 | S | HONEYWELL | 3P |
| 965-0676-021 | 34-45-30 | Ground Proximity Warning Computer | ALLIEDSIGNAL | TR 34-16 | 22.01.07 | | 012-0618-001 | S | | 3P |
| 965-0676-021 | 34-45-30 | Ground Proximity Warning Computer | ALLIEDSIGNAL | TR 34-14 | 27.10.06 | | 012-0618-001 | S | HONEYWELL | 3P |
| 965-0676-021 | 34-45-30 | Ground Proximity Warning Computer | ALLIEDSIGNAL | TR 34-15 | 13.12.06 | | 012-0618-001 | S | HONEYWELL | 3P |
| 965-1180-/-1190-020 | 34-45-40 | Enhanced Ground Proximity Warning System EGPWS | HONEYWELL ASIG | CMM w. IPC | 09.05.00 | 19 21.09.06 | 012-0709-001 | S | | 3P |
| 69000941-10X | 34-45-72 | MKV-A Enhanced Ground Proximity Warning System | HONEYWELL | CMM w. IPL | 24.01.14 | 9 10.12.20 | D201304000065 | S | | 3P |
| 7510300-901 | 34-51-14 | AT-860 ADF Antenna Vol. II | HONEYWELL | CMM w. IPC | 30.08.00 | 2 14.09.06 | A09-3800-012 | S | Volume II | 3A |
| 7510300-901 | 34-51-14 | AT-860 ADF Antenna Vol. I | HONEYWELL | CMM w. IPC | 15.03.88 | 5 14.09.06 | A09-3800-012 | S | Volume I | 3A |
| 7510300-901 | 34-51-14 | AT-860 ADF Antenna Vol. II | HONEYWELL | TR 1 | 11.12.07 | | A09-3800-012 | S | Volume II | 3A |
| 7510100-8XX | 34-51-17 | RNZ-851 Integrated Navigation Unit | HONEYWELL | CMM w. IPC | 15.02.92 | 4 15.08.05 | A09-3800-030 | S | | 3A |
| 7013270-93X/-966 thru-988 | 34-51-24 | RM-855 Radio Management Unit | HONEYWELL | CMM w. IPC | 15.07.93 | 13 01.06.20 | A09-3800-028 | S | | 3A |
| 7510114-855/7510300-901/2 | 34-51-26 | DF-855 ADF Module and AT-860 Antenna Assy | HONEYWELL | CMM w. IPC | 30.12.01 | 2 27.07.20 | A09-3800-036 | S | | 3P |
| 7510600-801 | 34-52-05 | ML-850 MLS Receiver Vol. II | HONEYWELL | CMM w. IPC | 15.11.00 | | A09-3800-014 | S | Volume II | 3A |
| 7510600-801 | 34-52-05 | ML-850 MLS Receiver Vol. I | HONEYWELL | CMM w. IPC | 01.09.89 | 1 15.11.00 | A09-3800-014 | S | Volume I | 3A |
| HG2012GB, HG2021GD | 34-58-04 | Global Navigation Satellite Sensor Unit | HONEYWELL | TR 34-2 | 13.08.15 | | M15-3819-003 | S | | 3A |
| HG2021GB01/HG2021GDXX | 34-58-04 | Global Navigation Satellite Sensor Unit | HONEYWELL | CMM w. IPC | 15.07.94 | 4 27.04.11 | M15-3819-003 | S | | 3A |
| G7228-01/-02 | 34-60-04 | Data Loader Model No. DL-1000 | HONEYWELL | CMM w. IPC | 01.03.10 | | VDN-0010 | S | GABLES | 3A |
| G7830-02/-03 | 34-62-01 | Control Display Unit CD-830 | HONEYWELL | CMM w. IPC | 02.10.15 | | VDN-0011 | S | GABLES | 3A |
| 7022360-901/-902 | 34-63-03 | CD-815 Control Display Unit | HONEYWELL | CMM w. IPC | 30.08.99 | 1 01.09.02 | A09-1147-081 | S | | 3A |
| 7007549-906 | 34-64-02 | CD-810 Control Display Unit | HONEYWELL | CMM w. IPC | 01.02.91 | 6 28.07.15 | A09-1147-040 | S | Supersedes A09-1147-40 Vol. I + II | 3A |
| 170080-Series | 35-01-01 | Oxygen Fill Valve | B/E AERO PURITAN | CMM w. IPC | 17.12.82 | 2 20.04.05 | VDN-0438 | S | PURITAN BENNETT | 3A |
| 170017/-18/-33 | 35-10-52 | Oxygen Outlet Valve Assembly | B/E AERO PURITAN | CMM w. IPC | 15.08.86 | 3 08.05.14 | VDN-0182 | S | PURITAN BENNET | 3A |
| 174260-Series | 35-10-60 | Sweep-On 2000 and Fullface Crew Mask Assembly | B/E AERO PURITAN | CMM w. IPC | 30.12.96 | 4 01.09.09 | VDN-0439 | S | PURITAN BENNETT | 3A |
| 174260-XX | 35-11-78 | Sweep-on 2000 Crew Mask Assembly | B/E AERO PURITAN | TR-1A | 13.02.14 | | VDN-0490 | S | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 174260-XX | 35-11-78 | Sweep-on 2000 Crew Mask Assembly | B/E AERO PURITAN | CMM w. IPC | 05.02.13 | | VDN-0490 | S | | | 3A |
| 174080 Series | 35-20-96 | Oxygen Mask Assembly 174080 Series | B/E AERO PURITAN | CMM w. IPC | 31.05.99 | 2 16.07.13 | VDN-0552 | O | | PURITAN BENNETT | 3A |
| | 35-20-96 | Oxygen Mask Assembly | B/E AERO PURITAN | TR 3A | 12.08.13 | | VDN-0590 | S | | PURITAN BENNETT | 3A |
| 101013-01 | 35-21-55 | Valve Assembly, Solenoid | B/E AERO PURITAN | CMM w. IPC | 01.06.93 | | VDN-0440 | S | | PURITAN BENNETT | 3A |
| 176200-Series/-219/-250 | 35-22-02 | Oxygen Cylinder Assembly | B/E AERO PURITAN | CMM w. IPC | 27.06.03 | 2 26.06.06 | VDN-0045 | S | | PURITAN BENNETT | 3A |
| 172234-02 | 35-22-10 | Oxygen Pressure Regulator | B/E AERO PURITAN | CMM w. IPC | 15.05.04 | 1 15.05.06 | VDN-0452 | S | | PURITAN BENNETT | 3A |
| 4441019-002 | 35-22-11 | Oxygen Pressure Regulator | B/E AERO PURITAN | CMM w. IPC | 06.01.02 | | VDN-0451 | S | | PURITAN BENNETT | 3P |
| 176226-Series | 35-22-18 | Oxygen Cylinder Assembly | B/E AERO PURITAN | CMM w. IPC | 15.03.10 | | VDN-0475 | S | | PURITAN BENNETT | 3A |
| 115102 | 35-22-88 | Emergency Oxygen Container Assembly | B/E AERO PURITAN | CMM w. IPC | 13.11.09 | | VDN-0474 | S | | PURITAN BENNETT | 3A |
| 174097-88 | 35-24-04 | Oxygen Mask Assembly | B/E AERO PURITAN | CMM w. IPC | 01.11.00 | 4 02.05.23 | VDN-0110 | S | R | PURITAN BENNETT | 3A |
| 4066B000 | 36-11-02 | Non-Return Valve 2 inch (50,8 mm) | HONEYWELL NGL | MM | 10.07.92 | 1 01.07.10 | 2371 | O | | | 3P |
| 4066B000/-002 | 36-11-02 | Non-Return Valve 2 inch (50,8 mm) | HONEYWELL NGL | CMM w. IPC | 09.01.96 | 4 09.02.15 | 2372 | S | | | 3A |
| 4067B000-002/3/4/5/6 | 36-11-03 | Pressure Reducing and Shut Off Valve | HONEYWELL NGL | CMM w. IPC | 15.03.96 | 12 07.11.16 | 2385 | S | | NGL | 3A |
| 4067B000-002 | 36-11-03 | Pressure Reducing a.Shut Off Valve | NGL | MM | 07.05.92 | 2 01.07.10 | 2384 | O | | | 3P |
| 5584C000 | 36-11-04 | Over Temperature Switch | NGL | MM | 23.08.91 | | 2407 | S | | | 3A |
| 5682C000 | 36-11-05 | Over Pressure Switch | HONEYWELL | MM | 27.04.92 | 2 11.11.15 | 2373 | S | | was NGL | 3A |
| 5658C000 | 36-11-08 | Over Temperature Switch | HONEYWELL NGL | MM | 29.04.92 | 2 10.11.15 | 2374 | S | | | 3P |
| 83900-1 | 36-11-09 | Pre-Cooler | ROGERSON | CMM w. IPC | 01.07.95 | | VDN-0225 | S | | | 3P |
| 4069B000-002 | 36-11-10 | Cross Feed Valve | HONEYWELL NGL | CMM w. IPC | 12.12.95 | 6 09.02.11 | 2383 | S | | | 3A |
| 4040B000 | 36-11-11 | Non Return Valve 63,5 mm (2.5 inch) | HONEYWELL NGL | CMM w. IPC | 10.10.95 | 5 09.12.14 | 2406S | S | | NGL | 3A |
| 4040B000 | 36-11-11 | Non-Return Valve 2.5 inch (6,3 50 mm) | NGL | MM | 22.04.92 | 1 01.07.10 | 2370 | O | | | 3A |
| 4066B000-002 | 36-11-41 | Non-Return Valve, 2 inch (50.8 mm) | NGL | MM | 23.02.99 | | 2705 | O | | | 3A |
| 4066B000-002 | 36-11-41 | Non-Return Valve, 2 inch (50.8 mm) | NGL | CMM w. IPC | 04.03.99 | | 2706 | S | | | 3A |
| 4067B000-004 | 36-11-42 | Press.Reduc. And Shut-Off Valve | NGL | MM | 23.02.99 | | 2707 | O | | | 3A |
| 4067B000-004 | 36-11-42 | Press.Reduc. And Shut-Off Valve | NGL | CMM w. IPC | 23.02.99 | | 2708 | S | | | 3A |
| 785841-1 | 36-11-82 | Detection Box | INTERTECHNIQUE | CMM w. IPC | 15.01.96 | | VDN-0200 | S | | ZODIAC | 3P |
| 70290 | 38-10-37 | Faucet Assembly | ADAMS RITE | CMM w. IPC | 16.04.07 | 3 29.01.19 | VDN-0486 | S | | | 3A |
| 70428 Series | 38-10-61 | Electricla Box Assembly | ADAMS RITE | CMM w. IPC | 09.08.06 | 1 18.11.08 | VDN-0487 | S | | | 3A |
| 400500-1 | 38-11-06 | Manual Shutoff Valve | ADAMS RITE | CMM w. IPC | 01.04.73 | 7 23.03.04 | 400500 | S | | | 3A |
| 9696 Series | 38-12-34 | Faucet Assembly | ADAMS RITE | CMM w. IPC | 15.10.03 | | VDN-0489 | S | | | 3A |
| 9776-15-1 | 38-20-09 | Hands Free Electronic Faucet Assy | ADAMS RITE | CMM w. IPC | 30.12.91 | 1 22.12.97 | 9776 | S | | | 3P |
| AR9592-X/9608-X | 38-30-06 | DRAIN VALVE ASSEMBLY | ADAMS RITE | CMM w. IPC | 20.05.14 | 3 25.10.16 | VDN-0488 | S | | | 3A |
| 331-0001-01 | 38-30-08 | Waste Drain Valve | SHAW | CMM w. IPC | 15.06.95 | | 331-0001-01 | S | | | 3A |
| 0016-0015-3 | 38-32-09 | Lever Cap Assemblies | KAISER | CMM w. IPC | 01.06.84 | 5 01.02.94 | VDN-0122 | S | | | 3P |
| 14328-001/-002 | 38-35-03 | Toilet Assembly | MONOGRAM | CMM w. IPC | 30.09.91 | 3 15.02.96 | VDN-0157 | S | | | 3A |
| 2651-311-5 | 38-37-01 | Lavatory Drain Valve Assy | KAISER | CMM w. IPC | 09.09.85 | 6 15.01.90 | VDN-0121 | S | | | 3P |
| 3800498-1/-3 | 49-24-09 | Pneum.a.Shaft Power Gas Turbine GTCP36-150 Series | HONEYWELL ASIG | IRM | 02.01.88 | 33 20.02.18 | D200701000028 | S | | ALLIEDSIGNAL | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 3800498-1/-3 | 49-24-10 | APU GTCP36-150[DD] | HONEYWELL | IPC | 18.05.92 | 5 07.10.11 | VDN-0007 | S | | | 3A |
| 3800498-1/-3 | 49-24-11 | APU GTCP36-150[DD] | HONEYWELL | MM | 24.02.95 | 4 28.08.15 | VDN-0005 | S | | | 3A |
| 3800498-1/-3 | 49-24-12 | APU GTCP36-150[DD] | HONEYWELL | TR 49-3 | 25.10.01 | | VDN-0009 | S | | | 3A |
| 3800498-1/-3 | 49-24-12 | APU GTCP36-150[DD] | HONEYWELL | CMM w. IPC | 18.05.92 | 4 28.08.15 | VDN-0009 | S | | | 3A |
| 3800498-1/-3 | 49-24-12 | APU GTCP36-150[DD] | HONEYWELL | TR 49-2 | 25.10.01 | | VDN-0009 | S | | | 3A |
| 3800498-1 | 49-30-91 | Fuel Control Assembly | HONEYWELL ASIG | CMM w. IPC | 01.05.86 | 8 31.07.10 | D200402000036 | S | | ALLIEDSIGNAL | 3P |
| 3888134-5 | 49-30-93 | Normally Closed Solenoid Valve | ALLIEDSIGNAL | CMM w. IPC | 30.05.85 | 3 21.11.95 | VDN-0004 | S | | | 3P |
| 328-0040/41 | 49-32-10 | APU Panel | COBHAM | CMM w. IPC | 01.10.93 | 1 30.06.95 | VDN-0168 | S | | NEC AERO | 3A |
| 109812-7-1/-13 | 49-50-73 | Butterfly Shutoff Valve | ALLIEDSIGNAL | CMM w. IPC | 15.03.83 | 7 11.08.20 | VDN-0008 | S | | HONEYWELL | 3A |
| AR2518 | 52-50-11 | Latch Assembly | ADAMS RITE | CMM w. IPC | 16.11.70 | 2 05.07.07 | AR2518 | S | | | 3A |
| | 52-51-04 | Latch Assembly | ADAMS RITE | CMM w. IPC | 29.06.90 | 6 21.01.05 | VDN-0446 | S | | | 3A |
| SPSDO328-1/2-X-X | 56-11-81 | Front Windshield LH/RH | SULLY | CMM w. IPC | 01.01.95 | 1 01.02.01 | VDN-0241 | S | | SPS.Do328.211 | 3A |
| 001A561A0000214 | 56-13-83 | Glass Side Cockpit Window LH/RH | SULLY | CMM w. IPC | 01.10.99 | 1 01.05.01 | VDN-0240 | S | | SPS.Do328.4.1.1 | 3A |
| 001A562A0015002 | 56-21-84 | Passenger Window LH/RH | SULLY | CMM w. IPC | 01.01.95 | 1 01.10.99 | VDN-0239 | S | | SPS.Do328.6.1.0 | 3A |
| | 61-00-60 | Dual Acting Prop./Prop. Control Syst. | HARTZELL | TR-030 | 01.05.09 | | 160 | S | | | 3P |
| | 61-00-60 | Dual Acting Prop./Prop. Control Syst. | HARTZELL | TR-032 | 01.03.17 | | 160 | S | | | 3P |
| | 61-00-60 | Dual Acting Prop./Prop. Control Syst. | HARTZELL | TR-031 | 01.11.16 | | 160 | S | | | 3P |
| | 61-00-60 | Dual Acting Prop./Prop. Control Syst. | HARTZELL | TR-022 | 01.03.97 | | 160 | S | | | 3P |
| | 61-00-60 | Dual Acting Prop./Prop. Control Syst. | HARTZELL | TR-029 | 01.10.06 | | 160 | S | | | 3P |
| | 61-00-60 | Dual Acting Prop./Prop. Control Syst. | HARTZELL | TR-023 | 01.05.97 | | 160 | S | | | 3P |
| | 61-00-60 | Dual Acting Prop./Prop. Control Syst. | HARTZELL | OLMM | 01.09.93 | 4 01.02.97 | 160 | S | | | 3P |
| | 61-00-63 | Propeller Log Book | HARTZELL | LB | 01.08.93 | 2 01.06.97 | 163A | S | | | 3P |
| | 61-00-64 | IPC for Dual Acting Propeller and Propeller Control System | HARTZELL | TR-007 | 01.08.14 | | 164B | S | | | 3P |
| | 61-00-64 | IPC for Dual Acting Propeller and Propeller Control System | HARTZELL | TR-008 | 01.01.17 | | 164B | S | | | 3P |
| | 61-00-64 | IPC for Dual Acting Propeller and Propeller Control System | HARTZELL | IPC | 01.12.94 | 9 01.08.11 | 164B | S | | | 3P |
| | 61-00-65 | Illustrated Tool and Equipment Manual | HARTZELL | ITEM | 01.11.95 | 30 01.11.22 | 165A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 1 | HARTZELL | TR-045 | 01.06.22 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 7 | HARTZELL | TR-022 | 01.09.22 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 11 | HARTZELL | SPM | 01.03.93 | 37 01.02.22 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 10 | HARTZELL | SPM | 01.03.93 | 37 01.11.21 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 1 | HARTZELL | TR-048 | 01.08.22 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 9 | HARTZELL | SPM | 01.03.93 | 32 01.04.21 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 6 | HARTZELL | SPM | 01.03.93 | 36 01.06.20 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 1 | HARTZELL | TR-046 | 01.06.22 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 2 | HARTZELL | SPM | 01.03.93 | 32 01.04.20 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manuel Vol. 7 | HARTZELL | TR-023 | 01.10.22 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manuel Vol. 7 | HARTZELL | TR-024 | 01.10.22 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 1 | HARTZELL | TR-047 | 01.08.22 | | 202A | S | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | 61-01-02 | Standard Practices Manual Vol. 4 | HARTZELL | SPM | 01.03.93 | 34 01.06.22 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 8 | HARTZELL | SPM | 01.10.22 | 36 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 10 | HARTZELL | TR-010 | 01.12.21 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 3 | HARTZELL | SPM | 01.03.93 | 42 01.12.21 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 1 | HARTZELL | SPM | 01.03.93 | 61 01.11.21 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 7 | HARTZELL | SPM | 01.03.93 | 53 01.06.22 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 5 | HARTZELL | SPM | 01.03.93 | 34 01.06.22 | 202A | S | | | 3P |
| HD-E6C-3XX-XX | 61-02-59 | Application Guide | HARTZELL | AG | 01.07.02 | 82 01.11.22 | 159 | O | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-038 | 01.04.18 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | MM | 01.08.93 | 26 01.10.06 | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-031 | 01.08.11 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-027 | 01.12.06 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-035 | 01.07.15 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-029 | 01.12.07 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-039 | 01.11.20 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-036 | 01.01.17 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-032 | 01.08.11 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-034 | 01.06.13 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-033 | 01.04.12 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-030 | 01.05.11 | | 161 | S | | | 3P |
| | 61-10-73 | Composite Spinner Field Maintenance and Minor Repair Manual | HARTZELL | FMRM | 01.09.14 | 8 01.11.19 | 173 | S | | | 3P |
| | 61-13-35 | Composite Propeller Blade | HARTZELL | MM | 02.06.97 | 44 01.11.22 | 135F | S | | | 3P |
| | 61-13-70 | Composite Propeller Blade Field Maintenance and Minor Repair Manual | HARTZELL | FMRM | 01.10.13 | 18 01.09.22 | 170 | S | | | 3P |
| | 61-16-48 | Composite Spinner Maintenance Manual | HARTZELL | MM | 01.10.93 | 22 01.12.21 | 148 | S | | | 3P |
| A-5656 | 61-20-01 | Gear Pump Assy | HARTZELL | CMM w. IPC | 30.06.93 | 2 14.11.07 | WG 60063 | S | | WOODWARD | 3P |
| A-5651 | 61-20-02 | Overspeed Governor Assy | HARTZELL | CMM w. IPC | 30.06.93 | 1 15.01.97 | WG 60062 | S | | WOODWARD | 3P |
| A-5659-2 | 61-20-03 | Constant Speed Propeller Governor | HARTZELL | CMM w. IPC | 31.08.93 | 3 19.08.03 | WG 60064 | S | | WOODWARD | 3P |
| HD-E6C-3( )( ) | 61-20-62 | Propeller Control Unit | HARTZELL | MM | 01.08.93 | 15 01.01.19 | 162 | S | | | 3P |
| C-5184 | 61-21-16 | Hydraulic and Electrical Motor Assy | AERO CONTROLEX | CMM w. IPC | 15.05.97 | 3 12.08.02 | 4122-006005 | S | | | 3P |
| 001A711E0000 | 71-10-00 | Nacelle Assembly | GKN WESTL.AERO. | CMMM | 31.01.96 | 6 31.03.02 | VDN-0051 | S | | | 3P |
| 001A712A0000 | 71-20-00 | Engine Mounting Structure | GKN WESTL.AERO. | CMMM | 31.01.96 | 3 31.03.02 | VDN-0056 | S | | | 3P |
| 95218-Series | 71-20-34 | Engine Vibration Isolation System | BARRY CONTROLS | CMM w. IPC | 01.08.92 | 4 15.07.04 | VDN-0047 | S | | | 3P |
| 3041321 | 71-50-10 | Electrical Wiring Harness | PWC | ACMM | 16.08.93 | 6 24.07.15 | 3041321 | S | | | 3P |
| 001A716E1000 | 71-60-00 | Air Intake | GKN WESTL.AERO. | CMMM | 31.01.96 | 5 31.03.02 | VDN-0057 | S | | | 3P |
| 001A716E1000 | 71-60-00 | Air Intake | GKN WESTL.AERO. | OVMM | 31.01.96 | 1 31.07.98 | VDN-0336 | O | | | 3P |
| 001A717A2000 | 71-70-00 | Drain Assy, Lower Cowling | GKN WESTL.AERO. | CMMM | 31.01.96 | 4 31.03.02 | VDN-0058 | S | | | 3P |
| 3038534 | 72-00-00 | IPC for PW119B/119C | PWC | IPC | 26.04.93 | 54 18.07.22 | 3038534 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| 3040598 | 72-03-00 | Hot Section Inspection PW119B/C | PWC | HSIM | 01.10.93 | 21 06.10.06 | 3040598 | O | CD-ROM only | 3P |
| 3038533 | 72-XX-XX | Engine Manual PW119B / 119C | PWC | EM | 26.04.93 | 20 04.09.17 | 3038533 | O | CD-ROM only | 3P |
| 3038533 | 72-XX-XX | Engine Manual PW119B / 119C | PWC | TR 72-6 | 20.02.18 | | 3038533 | O | | 3P |
| 3038533 | 72-XX-XX | Engine Manual PW119B / 119C | PWC | TR 72-5 | 12.01.18 | | 3038533 | O | | 3P |
| 3072152 | 72-XX-XX | Maintenance Manual PW119B / PW119C | PWC | MM | 30.06.14 | 17 27.05.22 | 3072152 | O | | 3P |
| 585005 | 72-XX-XX | Standard Practices Manual | PWC | SPM | 01.10.66 | 130 01.12.11 | 52A138 | O | CD-ROM only | 3A |
| 3037038 | 73-10-03 | Fuel Manifold Adapter | PWC | CMM w. IPC | 27.09.89 | 8 18.07.97 | 3037038 | S | | 3P |
| 3037326 | 73-10-04 | Fuel Manifold Adapter | PWC | CMM w. IPC | 09.11.89 | 8 18.07.97 | 3037326 | S | | 3P |
| 3056640 | 73-10-05 | Fuel Manifold Adapter | PWC | CMM w. IPC | 01.03.03 | 7 22.01.16 | 3056640 | S | | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | TR 73-12 | 20.04.04 | | VDN-0192 | S | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | TR 73-13 | 01.06.05 | | VDN-0192 | S | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | CMM w. IPC | 01.05.83 | 10 28.06.02 | VDN-0192 | S | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | TR 73-8 | 15.05.95 | | VDN-0192 | S | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | TR 73-9 | 29.03.96 | | VDN-0192 | S | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | TR 73-14 | 15.09.05 | | VDN-0192 | S | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | TR 73-10 | 19.07.00 | | VDN-0192 | S | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | TR 73-11 | 18.06.03 | | VDN-0192 | S | IPC P&WC | 3P |
| 10839X | 73-10-08 | Fuel Heater | STEWART WARNER | CMM w. IPC | 15.06.92 | 6 19.01.00 | 10839 | S | IPC P&WC | 3P |
| 25910 | 73-10-08 | Ejector Pump and Tank Assy. | TRW / LUCAS | TR 73-2 | 31.03.05 | | VDN-0191 | S | IPC P&WC | 3P |
| 25910 | 73-10-08 | Ejector Pump and Tank Assy. | TRW / LUCAS | TR 73-1 | 11.02.05 | | VDN-0191 | S | IPC P&WC | 3P |
| 25910-1 to -8, 25910-09, | 73-10-08 | Ejector Pump and Tank Assy. | TRW / LUCAS | CMM w. IPC | 15.12.84 | 6 20.12.02 | VDN-0191 | S | P&WC P/N: 3033856, 3039330, 3041468, 3055635-01 | 3P |
| 26200/260 | 73-10-15 | Flow Divider and Dump Valve | TRW / LUCAS | CMM w. IPC | 31.12.92 | 3 31.05.05 | VDN-0193 | S | IPC P&WC | 3P |
| | 73-11-40 | Flexible Fuel Manifold | PWC | ACMM | 01.07.99 | 6 09.04.15 | 3043611 | S | | 3P |
| 30005-0000-41/-53/-57 | 73-20-06 | Torque Signal Conditioner Vol. I | BFG SIMMONDS | CMM w. IPC | 15.10.93 | C 30.03.99 | VDN-0441 | S | IPC P&WC | 3P |
| 30005-0000-41/-53/-57 | 73-20-06 | Torque Signal Conditioner Vol. II | BFG SIMMONDS | IPC | 30.03.99 | | VDN-0441 | S | IPC P&WC | 3P |
| 1060K | 73-21-50 | Immersion Temperatur Sensor Assembly | ROSEMOUNT | CMM w. IPC | 01.01.99 | | VDN-0190 | S | | 3A |
| 811180-X-0X,PWC3118888-0X | 73-21-71 | Electronic Engine Control EEC118-15 | HAMILTON SUND | CMM w. IPC | 01.12.92 | 13 29.07.17 | EEC118-15 | S | IPC P&WC | 3P |
| 811099-1/-3 | 73-21-74 | Drain Pressure Sensitivity Test | HAMILTON SUND | AI | 15.06.98 | | D3282-AI97166 | S | IPC P&WC | 3A |
| 811099-X/3117036-0X | 73-21-74 | Fuel Control | HAMILTON SUND | CMM w. IPC | 15.12.85 | 8 12.09.18 | JFC118-15 | S | IPC P&WC | 3P |
| 9-231-29 | 73-35-31 | Fuel Flow Transmitter | ELDEC | CMM w. IPC | 15.05.92 | 2 23.10.17 | 011-4910-702 | S | Now is CRANE | 3P |
| 3039695/3121593-01 | 74-10-58 | High Energy Ignition Unit | TRW / LUCAS | CMM w. IPC | 06.01.93 | 3 18.10.95 | VDN-0194 | S | IPC P&WC | 3P |
| 3036423 | 74-20-01 | Ignition Cables | PWC | CMM w. IPC | 30.01.87 | 3 10.12.09 | 3036423 | S | | 3P |
| 3036421 | 75-30-01 | P2.5 Check Valve | PWC | CMM w. IPC | 30.01.87 | 4 05.09.08 | 3036421 | S | | 3P |
| 3036422 | 75-30-02 | Intercompressor Bleed Valve Assy | PWC | CMM | 30.05.96 | 7 30.10.15 | 3036422 | S | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 3036422 | 75-30-02 | Intercompressor Bleed Valve Assy | PWC | CMM w. IPC | 30.01.87 | 5 18.02.10 | 3036422 | S | | | 3P |
| H019 Series | 76-10-01 | Adjustable Cam Switch Assembly | GKN WESTL.SITEC | CMM w. IPC | 01.01.00 | | VDN-0096 | S | | | 3P |
| 1606670/-80 | 76-10-08 | Control Assembly Throttle Quadrant Engine | AERO CONTROLEX | CMM w. IPC | 24.01.02 | 1 19.06.12 | VDN-0384 | S | | Now Allsafe Jungfalk | 3P |
| 190755-XXX | 76-10-61 | Engine Control Cable Assembly | MORSE | CMM w. IPC | 01.02.93 | 1 01.01.94 | 190755 | S | | | 3P |
| 250205/001-004 | 76-10-62 | Engine Control Cable Assembly | MORSE | CMM w. IPC | 01.01.94 | | VDN-0159 | S | | | 3P |
| 580-291-XXX | 76-10-63 | CONTROL CABLE ASSEMBLIES, COCKPIT AND NACELLE | Cablecraft Motion | CMM w. IPC | 20.08.15 | 1 20.08.15 | VDN-0560 | S | | | 3A |
| 3041331 | 77-10-04 | Torque Sensor | PWC | CMM w. IPC | 16.08.93 | | 3041331 | S | | | 3P |
| | 77-11-04 | Torque Probe and/or Torque Sensor | PWC | CMM w. IPC | 01.07.99 | 5 20.11.15 | 3045330 | O | | | 3P |
| 3043640 | 77-11-06 | Speed Sensors | PWC | CMM w. IPC | 01.07.99 | 4 13.06.14 | 3043640 | S | | Replaces 77-10-01/-02 | 3A |
| 3041323 | 77-20-01 | T6 Trim Cable | PWC | CMM w. IPC | 16.08.93 | | 3041323 | S | | | 3P |
| 3041332 | 77-20-02 | Immersion Thermocouples | PWC | CMM w. IPC | 15.02.96 | 3 21.07.15 | 3041332 | S | | | 3P |
| 3041327 | 77-20-05 | T6 Trim Thermocouple Electrical Cable | PWC | CMM w. IPC | 16.08.93 | 3 09.02.10 | 3041327 | S | | | 3P |
| 3041328 | 77-20-06 | Temperature Sensor | PWC | CMM w. IPC | 16.08.93 | 3 26.08.16 | 3041328 | S | | | 3P |
| 3045331 | 77-21-08 | MOT Sonsor a/o T6 Trim Thermocouple | PWC | CMM w. IPC | 01.07.99 | 1 01.09.00 | 3045331 | S | | | 3A |
| 37-035-23-000-2/-4 | 79-20-01 | Oil Cooler Assembly | BEHR | CMM w. IPC | 25.01.96 | 1 31.07.14 | VDN-0049 | S | | MAHLE | 3P |
| 3041329 | 79-30-01 | Oil Press.Differential Switch or Indicator | PWC | CMM w. IPC | 16.09.93 | 4 26.08.16 | 3041329 | S | | | 3P |
| 3041330 | 79-30-02 | Chip Detectors/Collectors a.Valves | PWC | CMM w. IPC | 18.01.95 | | 3041330 | S | | | 3P |
| 3053125 | 79-31-02 | Chip Detectors/Collectors and Valves | PWC | CMM w. IPC | 01.07.99 | 5 11.09.15 | 3053125 | S | | | 3A |
| 30VR1107 | 79-40-10 | Thermal Valve | ASG | CMM w. IPC | 01.08.96 | | VDN-0017 | S | | AEG | 3P |
| 30ZF108 | 79-40-20 | Flap Actuator for Oil Cooler | ASG | CMM w. IPC | 01.08.96 | 1 14.04.97 | VDN-0018 | S | | AEG | 3P |

# CHAPTER

# 2

# VENDOR PUBLICATIONS

## Sort Part Number

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Epoxy Adhesive 1751 B/A | 3M | SPM | 01.12.09 | | TDS 1751 B-A | S | | Supersedes Messier Dowty DCMP-156 | 3A |
| | | Adhesive Transfer Tapes with Adhesive 300 | 3M | SPM | 01.09.02 | | TDS 950 | S | | | 3A |
| | | Polyurethane Protective Tape 8672/8672 GB (Gloss black) | 3M | SPM | 01.04.13 | | TDS PPT8672_2013 | S | | | 3A |
| | 32-42-03 | Nondestructive Testing Manual with Procedures | ABSC | NTM | 18.03.94 | 1 01.03.05 | AP-763 | S | | | 3A |
| | 32-42-03 | Nondestructive Testing Manual with Procedures | ABSC | TR 32-2 | 16.05.11 | | AP-763 | S | | | 3A |
| | 52-51-04 | Latch Assembly | ADAMS RITE | CMM w. IPC | 29.06.90 | 6 21.01.05 | VDN-0446 | S | | | 3A |
| | | KLN 900 Pilot´s Guide GPS | ALLIEDSIGNAL | PG | 02.01.99 | 2 | 006-08796-0000 | O | | | 3A |
| | | KHF950/990 Pilot´s Guide for HF | ALLIEDSIGNAL | PG | 01.12.96 | | 006-18038-0000 | O | | | 3A |
| | 35-20-96 | Oxygen Mask Assembly | B/E AERO PURITAN | TR 3A | 12.08.13 | | VDN-0590 | S | | PURITAN BENNETT | 3A |
| | 30-10-31 | Black Standard Pneumatic De-Icer Installation, Maintenance and Repair Manual | BFG ICE | IM | 15.11.96 | 5 06.06.12 | VDN-0055 | S | | | 3A |
| | 30-10-70 | FASTboot Pneumatic De-Icer | BFG ICE | INSTR.M | 10.04.00 | 6 13.04.18 | VDN-0274 | S | | 74-451-XX | 3A |
| | 30-10-66 | FASTboot Silver Urethane Pneumatic De-Icer | BFG ICE | INSTAL.M | 05.03.09 | 3 11.01.19 | VDN-0550 | S | | Now is UTC Aerospace | 3A |
| | 30-10-76 | FASTboot Silver Estane Pneumatic De-Icer | BFG ICE | INSTAL.M | 07.12.99 | 8 17.10.12 | VDN-0551 | S | | | 3A |
| | | Aero-M/I Antenna TT-5006A | CHELTON ANTENNAS | IM | 04.02.05 | | 677-A00022_IM | S | | COBHAM | 3A |
| | | SwiftBroadband HLD-7260 | COBHAM | IM | 16.11.07 | 2 11.03.14 | 862-A0101_IM | S | | | 3A |
| | | Capability List (Management Manual - Appendix I) | DIEHL | CL | 19.02.10 | 23 22.07.22 | MH-000-0006 | S | | | 3A |
| | | Aircraft Tyres and Tubes | DUNLOP | GPM | 02.01.08 | | DM1172 | S | | Supersedes GSI DM1172 | 3A |
| | 20-00-02 | Aircraft Wheel Bearings | DUNLOP | GPM | 31.01.91 | | VDN-0316 | S | | | 3A |
| | 20-00-01 | NDT of Aircraft Wheels | DUNLOP | GPM | 21.05.84 | | VDN-0317 | S | | | 3A |
| | 32-41-00 | Aircraft Tyres and Tubes | DUNLOP | ACMM | | 4 01.02.17 | VDN-0553 | S | | Tire Care & Maintenace Manual | 3A |
| | | Aircraft Tire Data Book | GOOD YEAR | DB | 01.10.02 | | 700-862-931-522 | S | | | 3A |
| | 32-41-00 | Aircraft Tire Care and Maintenance | GOOD YEAR | GUIDE | 01.06.16 | | 700-862-931-538 | S | | | 3A |
| | 24-10-00 | GENERATOR DRIVES AND RELATED EQUIPMENT | HAMILTON SUND | SPM | 01.12.72 | 80 29.10.19 | SPM 24-10-00 | O | | UTC Aerospace Systems | 3P |
| | 20-00-04 | Warnings Registry (Long Version) | HAMILTON SUND | SPM | 28.10.13 | 12 05.10.18 | VDN-5025 | O | | UTC Aerospace Systems | 3A |
| | 20-00-01 | Mechanical Standard Practices | HAMILTON SUND | SPM | 26.04.07 | 18 04.02.19 | VDN-5026 | O | | UTC Aerospace Systems | 3A |
| | 20-00-02 | Electronic Standard Practices Manual | HAMILTON SUND | SPM | 26.04.07 | 29 15.11.19 | VDN-5027 | O | | UTC Aerospace Systems | 3A |
| | 61-13-35 | Composite Propeller Blade | HARTZELL | MM | 02.06.97 | 44 01.11.22 | 135F | S | | | 3P |
| | 61-16-48 | Composite Spinner Maintenance Manual | HARTZELL | MM | 01.10.93 | 22 01.12.21 | 148 | S | | | 3P |
| | 61-00-60 | Dual Acting Prop./Prop. Control Syst. | HARTZELL | TR-032 | 01.03.17 | | 160 | S | | | 3P |
| | 61-00-60 | Dual Acting Prop./Prop. Control Syst. | HARTZELL | TR-029 | 01.10.06 | | 160 | S | | | 3P |
| | 61-00-60 | Dual Acting Prop./Prop. Control Syst. | HARTZELL | OLMM | 01.09.93 | 4 01.02.97 | 160 | S | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | 61-00-60 | Dual Acting Prop./Prop. Control Syst. | HARTZELL | TR-023 | 01.05.97 | | 160 | S | | | 3P |
| | 61-00-60 | Dual Acting Prop./Prop. Control Syst. | HARTZELL | TR-031 | 01.11.16 | | 160 | S | | | 3P |
| | 61-00-60 | Dual Acting Prop./Prop. Control Syst. | HARTZELL | TR-022 | 01.03.97 | | 160 | S | | | 3P |
| | 61-00-60 | Dual Acting Prop./Prop. Control Syst. | HARTZELL | TR-030 | 01.05.09 | | 160 | S | | | 3P |
| | 61-00-63 | Propeller Log Book | HARTZELL | LB | 01.08.93 | 2 01.06.97 | 163A | S | | | 3P |
| | 61-00-64 | IPC for Dual Acting Propeller and Propeller Control System | HARTZELL | TR-007 | 01.08.14 | | 164B | S | | | 3P |
| | 61-00-64 | IPC for Dual Acting Propeller and Propeller Control System | HARTZELL | IPC | 01.12.94 | 9 01.08.11 | 164B | S | | | 3P |
| | 61-00-64 | IPC for Dual Acting Propeller and Propeller Control System | HARTZELL | TR-008 | 01.01.17 | | 164B | S | | | 3P |
| | 61-00-65 | Illustrated Tool and Equipment Manual | HARTZELL | ITEM | 01.11.95 | 30 01.11.22 | 165A | S | | | 3P |
| | 61-13-70 | Composite Propeller Blade Field Maintenance and Minor Repair Manual | HARTZELL | FMRM | 01.10.13 | 18 01.09.22 | 170 | S | | | 3P |
| | 61-10-73 | Composite Spinner Field Maintenance and Minor Repair Manual | HARTZELL | FMRM | 01.09.14 | 8 01.11.19 | 173 | S | | | 3P |
| | 30-61-80 | Propeller Ice Protection System Manual | HARTZELL | SMM | 01.07.06 | 38 01.06.22 | 180 | S | | Manual 181 & 182 & 183 included with Rev 27 | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 2 | HARTZELL | SPM | 01.03.93 | 32 01.04.20 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 4 | HARTZELL | SPM | 01.03.93 | 34 01.06.22 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 1 | HARTZELL | TR-047 | 01.08.22 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 1 | HARTZELL | TR-048 | 01.08.22 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 1 | HARTZELL | TR-045 | 01.06.22 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 10 | HARTZELL | SPM | 01.03.93 | 37 01.11.21 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 9 | HARTZELL | SPM | 01.03.93 | 32 01.04.21 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 11 | HARTZELL | SPM | 01.03.93 | 37 01.02.22 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 7 | HARTZELL | TR-022 | 01.09.22 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 1 | HARTZELL | SPM | 01.03.93 | 61 01.11.21 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manuel Vol. 7 | HARTZELL | TR-023 | 01.10.22 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 8 | HARTZELL | SPM | 01.10.22 | 36 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 3 | HARTZELL | SPM | 01.03.93 | 42 01.12.21 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 10 | HARTZELL | TR-010 | 01.12.21 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manuel Vol. 7 | HARTZELL | TR-024 | 01.10.22 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 1 | HARTZELL | TR-046 | 01.06.22 | | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 7 | HARTZELL | SPM | 01.03.93 | 53 01.06.22 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 6 | HARTZELL | SPM | 01.03.93 | 36 01.06.20 | 202A | S | | | 3P |
| | 61-01-02 | Standard Practices Manual Vol. 5 | HARTZELL | SPM | 01.03.93 | 34 01.06.22 | 202A | S | | | 3P |
| | | Manual Revision Status | HARTZELL | PI | 13.11.09 | 337 02.12.14 | VDN-0472 | O | | | 3P |
| | 23-10-09 | KHF 1050 HF Communication System | HONEYWELL | TR 23-4 | 17.07.13 | | 006-10640-0006 | S | | | 3A |
| | 23-10-09 | KHF 1050 HF Communication System | HONEYWELL | TR 23-3 | 07.03.13 | | 006-10640-0006 | S | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | 23-10-09 | KHF 1050 HF Communication System | HONEYWELL | TR 23-1 | 01.03.11 | | 006-10640-0006 | S | | | 3A |
| | | PM-CPDLC MK2 CMU | HONEYWELL | PM | 16.11.11 | A | 69001561-001 | O | | | 3P |
| | | TNL8100 GPS Navigation System ARINC CDU | HONEYWELL | PG | 29.02.96 | D 25.06.99 | 81803-01 | O | | TRIMBLE | 3P |
| | | Index of Publications | HONEYWELL | INDEX | 15.05.98 | 42 01.07.07 | A01-9000-006 | O | | | 3A |
| | | PRIMUS II Integr.Radio System | HONEYWELL | EC | 01.06.91 | | A04-3800-01-00 | O | | | 3P |
| | | Handling, Storage, Shipping Avion.Equip. | HONEYWELL | INSTR. M | 10.03.78 | 14 01.08.06 | A09-1100-001 | S | | | 3A |
| | | Stand.Rep.Procedures Avionic Equipment | HONEYWELL | SRM | 01.04.94 | 7 01.02.08 | A09-1100-004 | O | | | 3A |
| | 22-05-04 | PRIMUS 2000 Integr.Avi. Syst.Vol III | HONEYWELL | SMM | 15.03.95 | | A15-1146-054 | S | | Volume III | 3P |
| | 22-05-04 | PRIMUS 2000 Integr.Avi. Syst.Vol I | HONEYWELL | SMM | 01.11.93 | 1 15.03.95 | A15-1146-054 | S | | Volume I | 3P |
| | 22-05-04 | PRIMUS 2000 Integr.Avi. Syst.Vol II | HONEYWELL | SMM | 01.11.93 | 1 15.03.95 | A15-1146-054 | S | | Volume II | 3P |
| | 22-05-34 | PRIMUS 2000 Integr.Avi. Syst.Vol I (GAU) | HONEYWELL | SMM | 15.07.98 | | A15-1146-085 | S | | for DO328 GAU | 3P |
| | 22-05-34 | PRIMUS 2000 Integr.Avi. Syst.Vol II (GAU) | HONEYWELL | SMM | 15.07.98 | | A15-1146-085 | S | | for DO328 GAU | 3P |
| | 22-05-34 | PRIMUS 2000 Integr.Avi. Syst.Vol III (GAU) | HONEYWELL | SMM | 15.07.98 | | A15-1146-085 | S | | for DO328 GAU | 3P |
| | | Index Service Bulletins/Technical Newsletter | HONEYWELL | INDEX | 08.06.98 | 34 01.07.07 | A21-9000-002 | O | | | 3A |
| | | PRIMUS II Integr.Radio System | HONEYWELL | PM | 01.11.87 | 7 01.08.00 | A28-1146-050 | O | | | 3A |
| | | PRIMUS 2000 Integr.Avionics System | HONEYWELL | PM | 01.08.93 | 1 01.11.93 | A28-1146-086 | O | | | 3P |
| | | PRIMUS 2000 Integr.Avionics System | HONEYWELL | TR 1 | 01.10.94 | | A28-1146-086 | O | | | 3P |
| | | PRIMUS 880 Digital Weather Radar | HONEYWELL | PM | 01.09.96 | 3 01.01.06 | A28-1146-102 | O | | | 3A |
| | | PRIMUS 660 Digital Weather Radar | HONEYWELL | PM | 01.02.98 | 3 01.08.03 | A28-1146-111 | O | | | 3A |
| | | PRIMUS II Integr.Radio Syst.RM-855 RMU | HONEYWELL | PM | 01.02.99 | 3 01.10.11 | A28-1146-121 | O | | | 3A |
| | | PRIMUS 2000 Integr.Avionics Syst.w.GAU | HONEYWELL | PM | 01.03.00 | | A28-1146-139 | O | | | 3P |
| | | RNZ-850 Instal./Removal Instructions | HONEYWELL | IRI | 01.02.92 | 8 01.06.04 | A62-0096-000 | O | | | 3P |
| | | RCZ-850 Instal./Removal Instructions | HONEYWELL | IRI | 01.09.95 | 4 01.03.99 | A62-0097-000 | O | | | 3P |
| | | Tech. Pub. Index for Commercial Aviation | HONEYWELL | INDEX | 29.12.03 | | CA-INDEX | O | | | 3A |
| | | Honeywell Flight Management Systems (FMS) NZ-2000 | HONEYWELL | SIL | 10.11.10 | 2 08.08.11 | D201010000079 | O | | | 3A |
| | | Tech.Pub.Index for General Aviation | HONEYWELL | INDEX | 29.12.03 | | GA-INDEX | O | | | 3A |
| | | TRA-45A Pilot Guide / Terrain Awareness and Display System | HONEYWELL | PG | 01.03.04 | 2 | PG80-5145 | O | | EGPWS | 3P |
| | 34-40-01 | TRA-45A / Terrain Display Unit / Radio Altimeter Indicator | HONEYWELL | IM | 01.02.00 | 6 01.04.10 | VDN-0478 | S | | for use with the EGPWS | 3P |
| | | Workscope Planning Guide for 36-150 APU | HONEYWELL ASIG | WPG | 25.04.03 | | 31-16647-15 | O | | ALLIEDSIGNAL | 3A |
| | | CMM, SB, SIL Landing Gear Equipm. | HONEYWELL ASIG | INDEX | 01.03.98 | 18 31.01.06 | FORM 12-536 | O | | ALLIEDSIGNAL | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | 32-49-01 | Standard Practices Manual | HONEYWELL ASIG | SPM | 31.12.98 | 3 30.04.00 | FORM 12-622 | S | | ALLIEDSIGNAL | 3A |
| | | Traffic Alert Collision Avoid.Syst. (TCAS) | HONEYWELL L3 | PM | 01.10.90 | 4 01.09.00 | A28-1146-070 | O | | L3 | 3P |
| | | Traffic Collision Avoidance System 2000 | HONEYWELL L3 | PG | 01.09.99 | | C28-3841-005 | O | | ACCS-L3 | 3A |
| | | Pressure Transducer | KULITE | ATP | 06.09.90 | E 10.03.99 | 2952 | O | | APTE-133-1000-XXX | 3P |
| | | Oil Pressure Sensor | KULITE | ATP | 09.10.90 | G 24.04.96 | 2953 | O | | IPTE-75GF-1000-70D | 3P |
| | | Pressure Transducer | KULITE | ATP | 28.03.91 | D 24.04.96 | 2982 | O | | APTE-137-1000-200 | 3P |
| | | Low Oil Pressure Switch | KULITE | ATP | 08.07.93 | E 20.05.96 | 3104 | O | | APS-3D-1000-1000A | 3A |
| | | Underwater Locator Beacon | L3 | IOIM | 03.11.16 | | 165E5542-10 | S | | FA2100 | 3P |
| | | TCAS 2000/3000 Pilot's Guide | L3 ACSS | PG | 16.08.07 | | 8006773-001 | O | | ACSS-L3 | 3A |
| | | TCAS II / TCAS 2000 (Change 7.1) Pilot's Guide Supplement | L3 ACSS | PG | 31.10.09 | 1 15.01.12 | 8008110-001 | O | | ACSS-L3 | 3P |
| | | FA2100CVR Audio & Data Link Player Software | L3 AVIATION RECORDER | IOIM | 01.06.04 | 1 11.06.10 | 165E3596-01 | S | | | 3P |
| | | FA2100CVR Audio & Data Link Player Software Operator's Manual (v3.3) | L3 AVIATION RECORDER | OM | 14.08.14 | | 165E3596-03 | S | | Model FA2100 | 3A |
| | 25-62-01 | L3AP UNDERWATER LOCATOR BEACON | L3 AVIATION RECORDER | CMM w. IPC | 24.04.15 | 5 15.05.17 | 165E5542-00 | S | | FA2100 | 3P |
| | | Model A100S Fairchild Solid State Cockpit Voice Recorder System | L3 AVIATION RECORDER | IOIM | 01.08.93 | | FAR04611238 | S | | | 3P |
| | | Cleaning Recommendations | LANTAL | CR | 01.11.12 | | VDN-0123 | S | | | 3A |
| | | Synthetics | LANTAL | CARE INSTR. | 13.04.01 | | VDN-0297 | S | | | 3A |
| | | Wool and Wool Blends | LANTAL | CARE INSTR. | 17.11.99 | | VDN-0298 | S | | | 3A |
| | 20-00-10 | Standard Practices Manual | LIEBHERR | SPM | 30.03.88 | 3 09.12.15 | VDN-0467 | S | | LIEBHERR | 3A |
| | 33-50-01 | Emergency Egress Lighting Syst. | LUMINESCENT | SMIM | 30.01.88 | 6 01.05.99 | VDN-0139 | S | | | 3A |
| | 33-50-02 | Emergency Egress Lighting Syst. | LUMINESCENT | IPC | 01.05.99 | | VDN-0139 | S | | | 3A |
| | 32-46-35 | Standard Practices Manual | MABS | SPM | 02.07.01 | 7 16.04.21 | AP-842 | S | | ABSC | 3A |
| | | Guide for On-Line Appl. of a Repair Design Solution | MESSIER-DOWTY | SPM | 01.10.11 | 2 12.12.13 | GUIDE-CS-001 | S | | SAFRAN | 3A |
| | | CONSUMABLE MATERIALS LIST | MESSIER-DOWTY | CML | 10.11.14 | 1 19.12.14 | MBD-CML | S | | SAFRAN | 3A |
| | | Approval of Personnel for NON-Destructive Testing | MESSIER-DOWTY | SPM | 06.08.08 | 15 11.01.14 | M-DLNDT10 | S | | | 3A |
| | | Anodising of Aluminium and Aluminium Alloys | MESSIER-DOWTY | SPM | 02.07.14 | | M-DLPS102 | S | | | 3A |
| | | The Chromate Treatment of Magnesium Alloys | MESSIER-DOWTY | SPM | 01.08.06 | 6 08.01.14 | M-DLPS103 | S | | | 3A |
| | | Brush Plating | MESSIER-DOWTY | SPM | 01.03.63 | 7 08.12.14 | M-DLPS118 | S | | | 3A |
| | | The Chromium Plating of Aluminium Alloys | MESSIER-DOWTY | SPM | 01.02.63 | 4 08.12.14 | M-DLPS119 | S | | | 3A |
| | | Glass and Ceramic Bead Peening | MESSIER-DOWTY | SPM | 11.12.07 | 5 30.10.13 | M-DLPS134 | S | | | 3A |
| | | Cleaning and Preparation of Steel for Plating | MESSIER-DOWTY | SPM | 30.05.08 | 8 18.09.13 | M-DLPS207 | S | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Silver Brazing | MESSIER-DOWTY | SPM | 29.11.06 | 7 25.09.13 | M-DLPS303 | S | | | 3A |
| | | Metal Spraying | MESSIER-DOWTY | SPM | 13.11.70 | 3 18.03.14 | M-DLPS503 | S | | | 3A |
| | | Low Temperature Stoving Paint Scheme for Magnesium Alloys | MESSIER-DOWTY | SPM | 01.04.63 | 7 28.10.14 | M-DLPS602 | S | | | 3A |
| | | Air Dryling Polyurethane Paint Scheme | MESSIER-DOWTY | SPM | 02.08.14 | | M-DLPS615 | S | | | 3A |
| | | Air Drying Epoxide Paint Scheme | MESSIER-DOWTY | SPM | 05.05.14 | | M-DLPS618 | S | | | 3A |
| | | Processing requirements for Ultra High Strength Steels | MESSIER-DOWTY | SPM | 12.09.67 | 4 30.09.14 | M-DLPS914 | S | | SAFRAN | 3A |
| | | Controlled Areas for Assembly and Test | MESSIER-DOWTY | SPM | 10.12.09 | 5 04.09.13 | M-DLPS927 | S | | | 3A |
| | | Traceability and Identification of Material | MESSIER-DOWTY | SPM | 06.09.13 | 1 17.09.13 | PCD-MBD-102 | S | | | 3A |
| | | Decarburisation & Carburisation Control of Heat Treated Steel Parts | MESSIER-DOWTY | SPM | 14.04.14 | | PCS-1150 | S | | | 3A |
| | | Electrolytic Hard Chromium Plating os Steels | MESSIER-DOWTY | SPM | 23.11.05 | 5 09.07.13 | PCS-2110 | S | | SAFRAN | 3A |
| | | Top - Cot Colours of Low Voc Paint as Per PCS-2530 | MESSIER-DOWTY | SPM | 28.07.10 | 4 08.04.13 | PCS-2531 | S | | | 3A |
| | | Application of Tungsten Carbide Cobalt Chromium (4%) Coatings on Metallic Parts by High Velocity Oxygen/Fuel Process | MESSIER-DOWTY | SPM | 01.08.02 | 5 17.09.14 | PCS-2560 | S | | | 3A |
| | | Corrosion Protection of Parts by Application of Corrosion Inhibiting Compounds | MESSIER-DOWTY | SPM | 01.03.12 | 3 12.06.14 | PCS-2831 | S | | | 3A |
| | | Penetrant Inspection of Ground Chrome Plated Parts | MESSIER-DOWTY | SPM | 25.06.09 | 2 10.04.14 | PCS-3002 | S | | | 3A |
| | | Inspection of Titanium Alloy Parts | MESSIER-DOWTY | SPM | 25.06.07 | 5 11.02.14 | PCS-3601 | S | | | 3A |
| | | List of Cutting Fluids for Machinig of Metallic Parts and Coatings | MESSIER-DOWTY | SPM | 04.11.12 | 2 04.07.13 | PCS-4002 | S | | | 3A |
| | | Mechanical Finishing of HVOF Sprayed Thungsten Carbide Cobalt Chromium Coatings | MESSIER-DOWTY | SPM | 30.05.02 | 4 24.09.13 | PCS-4102 | S | | | 3A |
| | | Assembly of Bushes Using Primer Paint | MESSIER-DOWTY | SPM | 26.07.06 | 2 15.10.14 | PCS-5120 | S | | | 3A |
| | | Application of Loctite | MESSIER-DOWTY | SPM | 25.10.07 | 3 19.09.13 | PCS-5303 | S | | SAFRAN | 3A |
| | | Anti-Stone Chip Polysulphide Coating | MESSIER-DOWTY | SPM | 30.03.05 | 4 30.06.14 | PCS-7204 | S | | | 3A |
| | | Surface Compr. Stressing and Bushing Instl. | MESSIER-DOWTY | SPM | 27.03.09 | 2 30.05.12 | PCS-7500 | S | | SAFRAN | 3A |
| | 20-00-10 | Standard Practices Manual | MESSIER-DOWTY | SPM | 15.10.08 | 9 15.01.12 | VDN-0460 | S | | Supersedes CMM 31-09-01 | 3A |
| | | Engine Condition Trend Monitoring Sys. | PWC | SIL INDEX | 05.05.89 | 3 31.03.97 | | O | | | 3P |
| | 73-11-40 | Flexible Fuel Manifold | PWC | ACMM | 01.07.99 | 6 09.04.15 | 3043611 | S | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | 77-11-04 | Torque Probe and/or Torque Sensor | PWC | CMM w. IPC | 01.07.99 | 5 20.11.15 | 3045330 | O | | | 3P |
| | | Num. Index PW119B/C Engine SB | PWC | INDEX | 30.09.02 | | ABO (PW119B/C) SB | O | | | 3P |
| | | Num. Index PW119B/C Engine SPB | PWC | INDEX | 30.09.02 | | ABO (PW119B/C) SPB | O | | | 3P |
| | | Num. Index PW100 Engine SB | PWC | INDEX | 31.10.01 | | ABX (PW100) SB | O | | | 3P |
| | | Num. Index PW100 Engine SPB | PWC | INDEX | 30.04.01 | | ABX (PW100) SPB | O | | | 3P |
| | | Index of Publ. For Engine Model PW119 | PWC | INDEX | 30.04.98 | | AIP (PW119) | O | | | 3P |
| | | Numerical Index of SIL | PWC | INDEX | 17.02.03 | | COB SIL | O | | | 3A |
| | | Omnibus Index PW100Engine SB/SPB | PWC | INDEX | 30.01.98 | | VDN-0202 | O | | | 3P |
| | | Num. Index of Service Tool Bulletins | PWC | INDEX | 01.09.00 | | VDN-0206 | O | | | 3A |
| | | Publications Status Report | PWC | INDEX | 10.09.09 | | VDN-0473 | O | | | 3A |
| | | Transport Requirements | SAFT | TN | | 4 09.12.09 | CM\TranspReqs | O | | | 3A |
| | | MEMO / Dangerous Goods Transortation repuirements | SAFT | TN | 06.05.19 | | SQ-19-0166_A1_PhB | O | | | 3A |
| | | Saft Ni-Cd aviation battery storage recommendations | SAFT | TN | | 11 01.10.20 | TN1 | O | | | 3A |
| | | Allowed Temperature Tolerance during Testing | SAFT | TN | 01.01.09 | 1 01.11.18 | TN10 | O | | | 3A |
| | | Various calibrated methods to test thermistors and thermostats | SAFT | TN | 01.11.15 | | TN11 | O | | | 3A |
| | | O-ring on cells terminals | SAFT | TN | | 3 01.04.20 | TN13 | O | | | 3A |
| | | Insulation Check | SAFT | TN | | 5 01.04.20 | TN2 | O | | | 3A |
| | | Preparation before storage batteries | SAFT | TN | | 4 01.04.20 | TN3 | O | | | 3A |
| | | Saft and NiCd aircraft battery maintenance | SAFT | TN | | 3 01.08.15 | TN5 | O | | | 3A |
| | | Saft Ni-Cd Aviation Battery life | SAFT | TN | 01.03.08 | 3 01.04.20 | TN6 | O | | | 3A |
| | | End of life cells | SAFT | TN | 01.03.08 | | TN7 | O | | | 3A |
| | | Placing a battery in service | SAFT | TN | 01.10.08 | | TN8 | O | | | 3A |
| | | Torque Check | SAFT | TN | 01.03.09 | | TN9 | O | | | 3A |
| | | Aviator 200/300/350 | THRANE | UM | 13.03.12 | | 98-127719-D | S | | | 3A |
| 0016-0015-3 | 38-32-09 | Lever Cap Assemblies | KAISER | CMM w. IPC | 01.06.84 | 5 01.02.94 | VDN-0122 | S | | | 3P |
| 001A251A4400 | | Head-Up Guidance System Model 2700 | FLIGHT DYNAMICS | PG | 01.11.94 | 1 01.05.96 | 523-0809568 | S | | ROCKWELL COLLINS | 3A |
| 001A561A0000214 | 56-13-83 | Glass Side Cockpit Window LH/RH | SULLY | CMM w. IPC | 01.10.99 | 1 01.05.01 | VDN-0240 | S | | SPS.Do328.4.1.1 | 3A |
| 001A562A0015002 | 56-21-84 | Passenger Window LH/RH | SULLY | CMM w. IPC | 01.01.95 | 1 01.10.99 | VDN-0239 | S | | SPS.Do328.6.1.0 | 3A |
| 001A711E0000 | 71-10-00 | Nacelle Assembly | GKN WESTL.AERO. | CMMM | 31.01.96 | 6 31.03.02 | VDN-0051 | S | | | 3P |
| 001A712A0000 | 71-20-00 | Engine Mounting Structure | GKN WESTL.AERO. | CMMM | 31.01.96 | 3 31.03.02 | VDN-0056 | S | | | 3P |
| 001A716E1000 | 71-60-00 | Air Intake | GKN WESTL.AERO. | CMMM | 31.01.96 | 5 31.03.02 | VDN-0057 | S | | | 3P |
| 001A716E1000 | 71-60-00 | Air Intake | GKN WESTL.AERO. | OVMM | 31.01.96 | 1 31.07.98 | VDN-0336 | O | | | 3P |
| 001A717A2000 | 71-70-00 | Drain Assy, Lower Cowling | GKN WESTL.AERO. | CMMM | 31.01.96 | 4 31.03.02 | VDN-0058 | S | | | 3P |
| 011291-500 | 21-25-03 | Avionics Aft Fan | ROTRON | CMM w. IPC | 22.05.95 | 1 22.09.97 | VDN-0233 | S | | AMETEK | 3A |
| 011292-500 | 21-25-01 | EFIS Fan | ROTRON | CMM w. IPC | 01.04.95 | | VDN-0235 | S | | AMETEK | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 011389-502 | 21-51-23 | Ground Cooling Fan | ROTRON | CMM w. IPC | 15.11.94 | 2 29.04.10 | VDN-0234 | S | | AMETEK | 3A |
| 011390-500 | 21-22-01 | Recirculation Fan | AMETEK | CMM w. IPC | 22.05.95 | 5 30.04.14 | VDN-0232 | S | | ROTRON | 3A |
| 02-1510-8011 | 33-49-02 | ACL-1000 Cable Assy, Model 1510 | FLIGHT COMP. | CMM w. IPC | 15.04.94 | | VDN-0092 | S | | | 3P |
| 026-675-0 | 32-45-01 | Aircraft Tire Care & Service Manual | MICHELIN | CSM | 01.01.01 | 15.12.11 | VDN-0360 | S | | | 3P |
| 03-1805-2001 | 33-49-03 | ACL-1000 Light Assy, Model 1805 | FLIGHT COMP. | CMM w. IPC | 15.04.94 | 2 07.11.02 | VDN-0091 | S | | | 3A |
| 03-1805-2001-2 | 33-49-03 | ACL-1000 Light Assy, Model 1805 | B/E Aerospace | CMM w. IPC | | 1 02.08.16 | VDN-0612 | S | | | 3A |
| 03-2100-2003/4 | 33-49-03 | ACL-1000 Light Assy, Model 2100 | FLIGHT COMP. | CMM w. IPC | 15.04.94 | 3 07.07.08 | VDN-0093 | S | | | 3P |
| 03-2103-2003/4 | 33-49-03 | ACL-1000 Light Assy, Model 2103 | FLIGHT COMP. | CMM w. IPC | 15.04.99 | 2 07.07.08 | VDN-0393 | S | | | 3P |
| 03-2700-2006 | 33-49-03 | ACL-1000 Light Assy, Model 2700 | FLIGHT COMP. | CMM w. IPC | 04.12.98 | | VDN-0089 | S | | | 3A |
| 03-2901-2003/4 | 33-49-03 | ACL-1000 Light Assy, Model 2901 | FLIGHT COMP. | CMM w. IPC | 20.03.99 | 2 07.07.08 | VDN-0088 | S | | | 3A |
| 04-1504-1429 | 33-49-04 | ACL-1000 Power Supply Model 1504 | FLIGHT COMP. | CMM w. IPC | 15.04.94 | 3 23.08.04 | VDN-0090 | S | | | 3P |
| 04-1604-1429 | 33-49-04 | ACL-1000 Power Supply Model 1604 | B/E Aerospace | CMM w. IPC | 04.11.99 | 4 09.02.16 | VDN-0087 | S | | FLIGHT COMP. | 3A |
| 046E0828-05 | | Model A200S Memory Test EPROM | L3 AVIATION RECORDER | IOIM | 13.07.01 | | 165E2652-00 | S | | | 3P |
| 0543-284-925 | 23-30-06 | Digital Player DP 4100 | BECKER | CMM w. IPC | 15.04.05 | | VDN-0327 | S | | Supersedes TP300 | 3A |
| 0543-284-925 | 23-30-06 | Digital Player DP 4100 | BECKER | AMM | 15.06.01 | 2 15.04.05 | VDN-0328 | O | | | 3A |
| 0543-284-925 | 23-30-06 | Cardsetup Software Version 1.0 for Digital Player DP 4100 | BECKER | IOM | 01.11.02 | | VDN-0329 | O | | | 3A |
| 0543-284-925 | 23-30-06 | DP 4100 Operating Instructions | BECKER | OI | 01.04.05 | | VDN-0466 | O | | | 3A |
| 064-01072-0101 | 23-10-08 | KPA 1052 Power Amplifier | HONEYWELL BENDIX | CMM w. IPC | 30.09.03 | | 006-15641-0000 | S | | Bendix King | 3A |
| 064-01073-0102 | 23-10-09 | KHF 1050 HF Communication System | HONEYWELL | SIM | 01.03.03 | 6 01.11.07 | 006-10640-0006 | S | | Bendix King | 3A |
| 064-01073-0102 | 23-10-06 | KRX 1053 Receiver/Exciter | HONEYWELL BENDIX | CMM w. IPC | 30.09.03 | 2 06.05.11 | 006-15642-0001 | S | | Bendix King | 3A |
| 064-01073-0102 | | KHF 1050/PS440 Pilot's Guide | HONEYWELL BENDIX | PG | | 1 01.05.03 | 006-18289-0000 | O | | Bendix King | 3A |
| 064-01074-0101 | 23-10-07 | KAC 1052 Antenna Coupler | HONEYWELL BENDIX | CMM w. IPC | 26.01.04 | 1 | 006-15640-0001 | S | | Bendix King | 3A |
| 064-1015-01 | 23-20-08 | Receiver/Exciter KTR 953 | ALLIEDSIGNAL | TR 23-2 | 02.03.09 | | 006-05381-0000 | S | | Bendix King | 3A |
| 064-1015-01 | 23-20-08 | Receiver/Exciter KTR 953 | ALLIEDSIGNAL | CMM w. IPC | 30.04.95 | | 006-05381-0000 | S | | Bendix King | 3A |
| 064-1015-01 | 23-20-08 | Receiver/Exciter KTR 953 | ALLIEDSIGNAL | TR 23-1 | 20.11.08 | | 006-05381-0000 | S | | Bendix King | 3A |
| 064-1015-01 | | KHF 950 HF/SSB Communication System | BENDIX | MM w. IPL | 01.05.82 | 4 04.05.83 | 006-05190-0004 | S | | Bendix King | 3A |
| 064-1015-01 | 23-20-03 | KHF 950 HF/SSB Communication System | HONEYWELL BENDIX | SIM | 01.02.94 | 2 28.04.06 | 006-05389-0002 | S | | Bendix King | 3A |
| 07-110-9200 | | Battery Adapter P/N 07-110-9200 | DIEHL | UG | 06.12.04 | 6 18.09.17 | 0432401 | O | | | 3A |
| 07-2700-2000 | 33-49-07 | ACL-1000 Electronic Switch, Model 2700 | FLIGHT COMP. | CMM w. IPC | 11.03.03 | | VDN-0611 | S | | | 3A |
| 0851GW / 0851GW-1 | 34-10-73 | Pitot Tube | ROSEMOUNT | CMM w. IPC | 01.09.98 | 1 15.03.00 | VDN-0085 | S | | | 3A |
| 0861EF1 | 34-12-27 | Angle Of Attack Sensor | ROSEMOUNT | CMM w. IPC | 15.02.92 | | VDN-0231 | S | | | 3A |
| 0871DW1 | 30-81-17 | ICE Detector | ROSEMOUNT | CMM w. IPC | 01.11.90 | | VDN-0209 | S | | | 3A |
| 101013-01 | 35-21-55 | Valve Assembly, Solenoid | B/E AERO PURITAN | CMM w. IPC | 01.06.93 | | VDN-0440 | S | | PURITAN BENNETT | 3A |
| 103-020-0 | 24-32-16 | Hall Effect Current Sensor | THALES | TCMS | 16.11.92 | 4 02.05.13 | VDN-0313 | S | | AUXILEC | 3A |
| 103141 | 25-28-44 | QC - Wardrobe | MÜHLENBERG | CMM w. IPC | 30.01.97 | | VDN-0254 | S | | | 3A |
| 1048A0000-02/-04 | 27-50-22 | Flap Actuator | LIEBHERR | CMM w. IPC | 30.10.95 | 2 20.10.00 | VDN-0135 | S | | | 3A |
| 1049A0000-02 | 27-52-12 | Flap Valve Block | LIEBHERR | CMM w. IPC | 30.06.93 | 1 30.01.98 | VDN-0130 | S | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1050A0000-XX | 27-52-10 | Flap Control Unit | LIEBHERR | CMM w. IPC | 30.01.98 | 2 26.09.04 | VDN-0133 | S | | | 3A |
| 105146 | 25-28-20 | Foldable Trolley Stowage | MÜHLENBERG | CMM w. IPC | 25.07.95 | | VDN-0251 | S | | | 3A |
| 105148 | 25-28-40 | Galley | MÜHLENBERG | CMM w. IPC | 30.11.96 | | VDN-0253 | S | | | 3P |
| 1053A0000-02 | 27-52-18 | Flap Control Switch | LIEBHERR | CMM w. IPC | 11.12.95 | 1 30.01.98 | VDN-0131 | S | | | 3P |
| 1058A0000-03 | 27-62-16 | Roll Spoiler Actuator | LIEBHERR | CMM w. IPC | 30.09.93 | 2 28.08.19 | VDN-0136 | S | | | 3A |
| 1059A0000-02 | 27-62-10 | Ground Spoiler Actuator | LIEBHERR | CMM w. IPC | 30.09.93 | 1 30.12.99 | VDN-0116 | S | | | 3P |
| 1059A0000-03 | 27-62-11 | Ground Spoiler Actuator | LIEBHERR | CMM w. IPC | 09.09.98 | 1 15.07.14 | VDN-0117 | S | | | 3A |
| 106-000-3 | 24-22-68 | DC Bus Power Control Unit | AUXILEC | CMM w. IPC | 30.05.94 | 1 15.01.95 | VDN-0025 | S | | THALES | 3P |
| 106-000-4 | 24-22-71 | DC Bus Power Control Unit | AUXILEC | CMM w. IPC | 15.09.99 | | VDN-0028 | S | | THALES | 3A |
| 106098/106098A | 25-30-39 | AFT Galley R/H | MÜHLENBERG | CMM w. IPC | 25.06.93 | C 19.03.96 | VDN-0258 | S | | | 3P |
| 1060A0000-06 | 27-62-12 | Ground Spoiler Valve Block | LIEBHERR | CMM w. IPC | 30.06.93 | 1 30.01.98 | VDN-0137 | S | | | 3P |
| 1060K | 73-21-50 | Immersion Temperatur Sensor Assembly | ROSEMOUNT | CMM w. IPC | 01.01.99 | | VDN-0190 | S | | | 3A |
| 106100/A/B/C | 25-30-40 | AFT Galley R/H | MÜHLENBERG | CMM w. IPC | 25.06.93 | B 15.04.96 | VDN-0259 | S | | | 3A |
| 106100D, 106100L | 25-30-82 | AFT Galley R/H | MÜHLENBERG | CMM w. IPC | 15.02.00 | 2 10.10.01 | VDN-0262 | S | | | 3A |
| 106100E | 25-30-83 | Galley AFT R/H | MÜHLENBERG | CMM w. IPC | 15.02.00 | 1 10.03.00 | VDN-0263 | S | | | 3A |
| 106100F | 25-30-84 | AFT Galley R/H | MÜHLENBERG | CMM w. IPC | 15.02.00 | 2 12.12.07 | VDN-0264 | S | | | 3A |
| 106101 | 25-30-42 | Small Galley | MÜHLENBERG | CMM w. IPC | 01.08.94 | B 15.04.96 | VDN-0260 | S | | | 3A |
| 106101A | 25-30-47 | Small Galley | MÜHLENBERG | CMM w. IPC | 30.09.96 | | VDN-0261 | S | | | 3A |
| 10839X | 73-10-08 | Fuel Heater | STEWART WARNER | CMM w. IPC | 15.06.92 | 6 19.01.00 | 10839 | S | | IPC P&WC | 3P |
| 109812-7-1/-13 | 49-50-73 | Butterfly Shutoff Valve | ALLIEDSIGNAL | CMM w. IPC | 15.03.83 | 7 11.08.20 | VDN-0008 | S | | HONEYWELL | 3A |
| 110022-10 | | Baggage Net Door | ALLSAFE | CMM w. IPC | 03.07.96 | E 18.01.18 | BST-641/96 | S | | | 3A |
| 110-337 | | Emergency Locator Transmitters 406MHz | ARTEX | DOIMM | 10.12.02 | B 25.08.08 | 570-5000 | S | | ELT C406-2, C406-2HM | 3A |
| 1111C0000-01 | 27-09-50 | Solenoid Valve | LIEBHERR | CMM w. IPC | 30.09.93 | 1 02.02.18 | VDN-0469 | S | | | 3A |
| 1112-1AA | 25-11-12 | Observer Seat Model 1112 | AMI | CMM w. IPC | 01.10.93 | | VDN-0013 | S | | | 3A |
| 113197/113198 | 25-28-38 | Stowages | MÜHLENBERG | CMM w. IPC | 30.08.96 | | VDN-0252 | S | | | 3A |
| 113218 | 25-29-21 | Music Entertainment Cabinet | MÜHLENBERG | CMM w. IPC | 29.12.00 | 1 12.04.01 | VDN-0256 | S | | | 3A |
| 115102 | 35-22-88 | Emergency Oxygen Container Assembly | B/E AERO PURITAN | CMM w. IPC | 13.11.09 | | VDN-0474 | S | | PURITAN BENNETT | 3A |
| 118-000-1 | 24-35-33 | Generator Control Unit for Starter Generator | AUXILEC | CMM w. IPC | 15.11.95 | | VDN-0022 | S | | THALES | 3A |
| 118-000-2 | 24-35-30 | Generator Control Unit for Starter Generator | AUXILEC (THALES) | CMM w. IPC | 22.12.04 | | VDN-0430 | S | | AUXILEC | 3A |
| 1180002-Series | 25-10-32 | Restraint System Assembly | AM-SAFE | ACMM w. IPC | 12.10.10 | | VDN-5030 | S | | | 3A |
| 119003, 119063, 4401005 | | Protective Breathing Equipment | B/E AERO PURITAN | GUIDE | 06.04.90 | 13 21.09.21 | 2499-200 | O | | PURITAN BENNETT | 3A |
| 1234A0000-01 | 27-72-01 | Rudder Gust Damper | LIEBHERR | CMM w. IPC | 28.11.96 | | VDN-0335 | S | | | 3P |
| 14328-001/-002 | 38-35-03 | Toilet Assembly | MONOGRAM | CMM w. IPC | 30.09.91 | 3 15.02.96 | VDN-0157 | S | | | 3A |
| 147E1616-00 | | Model A200S Profiler Kit | L3 AVIATION RECORDER | IOIM | 18.07.01 | B 27.06.01 | 165E1616-00 | S | | | 3P |
| 1606670/-80 | 76-10-08 | Control Assembly Throttle Quadrant Engine | AERO CONTROLEX | CMM w. IPC | 24.01.02 | 1 19.06.12 | VDN-0384 | S | | Now Allsafe Jungfalk | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 165E1630-00 | | Portable Interface | L3 AVIATION RECORDER | OM | 01.10.98 | 1 01.05.99 | VDN-0294 | S | | | 3A |
| 165E1696-01 | | Read-Out Support Equipment RI | L3 AVIATION RECORDER | OM | 01.12.99 | | VDN-0293 | S | | | 3A |
| 170017/-18/-33 | 35-10-52 | Oxygen Outlet Valve Assembly | B/E AERO PURITAN | CMM w. IPC | 15.08.86 | 3 08.05.14 | VDN-0182 | S | | PURITAN BENNET | 3A |
| 170080-Series | 35-01-01 | Oxygen Fill Valve | B/E AERO PURITAN | CMM w. IPC | 17.12.82 | 2 20.04.05 | VDN-0438 | S | | PURITAN BENNETT | 3A |
| 1716D000-002 | 21-51-11 | Cold Air Unit | HONEYWELL NGL | CMM w. IPC | 26.05.94 | 9 06.12.16 | 2516 | S | | NGL | 3A |
| 1716D000-002 | 21-51-11 | Cold Air Unit | NGL | MM | 25.05.94 | 1 26.05.98 | 2515 | O | | | 3A |
| 172234-02 | 35-22-10 | Oxygen Pressure Regulator | B/E AERO PURITAN | CMM w. IPC | 15.05.04 | 1 15.05.06 | VDN-0452 | S | | PURITAN BENNETT | 3A |
| 174080 Series | 35-20-96 | Oxygen Mask Assembly 174080 Series | B/E AERO PURITAN | CMM w. IPC | 31.05.99 | 2 16.07.13 | VDN-0552 | O | | PURITAN BENNETT | 3A |
| 174097-88 | 35-24-04 | Oxygen Mask Assembly | B/E AERO PURITAN | CMM w. IPC | 01.11.00 | 4 02.05.23 | VDN-0110 | S | R | PURITAN BENNETT | 3A |
| 174260-Series | 35-10-60 | Sweep-On 2000 and Fullface Crew Mask Assembly | B/E AERO PURITAN | CMM w. IPC | 30.12.96 | 4 01.09.09 | VDN-0439 | S | | PURITAN BENNETT | 3A |
| 174260-XX | 35-11-78 | Sweep-on 2000 Crew Mask Assembly | B/E AERO PURITAN | CMM w. IPC | 05.02.13 | | VDN-0490 | S | | | 3A |
| 174260-XX | 35-11-78 | Sweep-on 2000 Crew Mask Assembly | B/E AERO PURITAN | TR-1A | 13.02.14 | | VDN-0490 | S | | | 3A |
| 176200-Series/-219/-250 | 35-22-02 | Oxygen Cylinder Assembly | B/E AERO PURITAN | CMM w. IPC | 27.06.03 | 2 26.06.06 | VDN-0045 | S | | PURITAN BENNETT | 3A |
| 176226-Series | 35-22-18 | Oxygen Cylinder Assembly | B/E AERO PURITAN | CMM w. IPC | 15.03.10 | | VDN-0475 | S | | PURITAN BENNETT | 3A |
| 177310 | 28-21-11 | Fuel Booster Pump | TEST-FUCHS | CMM w. IPC | 04.04.96 | 2 21.01.11 | VR 1007 | S | | | 3P |
| 17-M800-(XXX) | 31-30-01 | Digital Flight Recorder Model F800 | L3 AVIATION RECORDER | IOIM | 01.10.03 | 1 | 165E3359-00 | S | | Supersedes FAR02283174 | 3P |
| 17M800-261 | 31-30-01 | Digital Flight Recorder | L3 AVIATION RECORDER | CMM w. IPC | 01.08.88 | 2 31.01.94 | 165E0049-00 | S | | Model F800 | 3P |
| 17TES0423 | | FA2100CVR Audio & Data Link Player Software | L3 AVIATION RECORDER | IOIM | 01.06.04 | 1 01.04.07 | 165E3596-00 | S | | | 3P |
| 190755-XXX | 76-10-61 | Engine Control Cable Assembly | MORSE | CMM w. IPC | 01.02.93 | 1 01.01.94 | 190755 | S | | | 3P |
| 1C12-42 | | Centrifugal Fuel Boost Pump | PARKER | CMM w. IPC | 21.09.10 | | CM1C12-42 | S | | | 3A |
| 1C12-42 | 28-21-12 | Centrifugal Fuel Boost Pump | PARKER | CMM w. IPC | 23.05.00 | | VDN-0179 | S | | | 3P |
| 1X0004427-05 | 33-40-19 | Taxi Light | HELLA | CMM w. IPC | 01.01.94 | | VDN-0097 | S | | GOODRICH HELLA | 3A |
| 1X0006678-00 | 33-40-23 | Logo Light | HELLA | CMM w. IPC | 15.11.92 | | VDN-0100 | S | | GOODRICH HELLA | 3A |
| 1X0006678-00 | 33-40-23 | Logo Light | HELLA | IPL | 10.02.01 | | VDN-0100 | S | | GOODRICH HELLA | 3A |
| 1X4004429-00 | 33-40-14 | Landing Light | HELLA | CMM w. IPC | 01.03.94 | 1 22.09.99 | VDN-0106 | S | | GOODRICH HELLA | 3A |
| 1XA006726/7-00 | 33-40-22 | Wing Inspection Light | HELLA | IPL | 08.02.01 | | VDN-0099 | S | | GOODRICH HELLA | 3A |
| 1XA006726/7-00 | 33-40-22 | Wing Inspection Light | HELLA | CMM w. IPC | 15.11.92 | | VDN-0099 | S | | GOODRICH HELLA | 3A |
| 20040 | 24-22-66 | AC Generator | AUXILEC | CMM w. IPC | 01.10.92 | 1 02.05.00 | VDN-0023 | S | | THALES | 3P |
| 2060-5AC | 25-25-60 | Attendant Seats Model 2060 | AMI | CMM w. IPC | 15.10.93 | 5 01.05.01 | VDN-0333 | S | | | 3A |
| 20736 | 24-22-15 | Differential Protection Current Transformer | AUXILEC | TCMS | 01.06.92 | 1 16.11.92 | VDN-0448 | O | | THALES | 3P |
| 208CC02Y1 | 24-39-59 | SPST NO CONTACTOR | ZODIAC AERO ELECTRIC | ACMM w. IPC | 04.11.15 | | 208CC02Y1 | S | | | 3A |
| 2097H020900;2097P011400 | 21-34-03 | Electropneumatic Valve | LIEBHERR | CMM w. IPC | 20.11.92 | 6 15.01.06 | VDN-0125 | S | | ABG-SEMCA | 3A |
| 2099J020900;2099R011400 | 21-34-04 | Pneumatic Valve | LIEBHERR | CMM w. IPC | 01.12.92 | 6 30.05.13 | VDN-0129 | S | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 2100-1020-00 | 23-70-04 | Cockpit Voice Recorder | L3 AVIATION RECORDER | CMM w. IPC | 01.11.98 | 17 07.03.19 | 165E1689-00 | S | | Model FA2100 | 3A |
| 2100-1220-xx | | Cockpit Voice Recorder | L3 COMMUNICATIONS | IOIM | 15.03.99 | 19 04.08.15 | 165E1846-00 | O | | Model FA2100 | 3A |
| 2100-4043-00 | 31-30-03 | Flight Data Recorder | L3 AVIATION RECORDER | CMM w. IPC | 01.10.98 | 14 12.04.19 | 165E1688-00 | S | | Model FA2100 | 3A |
| 2100-4043-00 | 31-30-03 | Flight Data Recorder | L3 AVIATION RECORDER | CMM w. IPC | 01.10.98 | 12 19.02.18 | 165E1688-00 | S | | Model FA2100 | 3A |
| 219335-3/219336-2 | 28-20-06 | Fuel Jet Pumps | INTERTECHNIQUE | CMM w. IPC | 15.04.92 | 4 28.10.13 | VDN-0118 | S | | ZODIAC | 3A |
| 220GC02Y01/230GC01/-04 | 24-39-55 | DC Junction Box | ZODIAC AEROSPACE | CMM w. IPC | 15.06.94 | 8 12.05.14 | VDN-0082 | S | | | 3A |
| 22260A/E010101 | 21-34-01 | Cabin Pressure Controller | LIEBHERR | CMM w. IPC | 15.12.92 | 5 15.06.99 | VDN-0127 | S | | ABG-SEMCA | 3A |
| 22405-000-02/03/04 | 32-31-05 | Uplock Assembly | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0154 | S | | | 3P |
| 22420-000-XX | 32-11-04 | Shock Absorber | MESSIER-DOWTY | CMM w. IPC | 31.03.92 | 8 31.12.12 | VDN-0348 | S | | | 3P |
| 22445-000-00 | 32-31-07 | Unlocking Cylinder | MESSIER-DOWTY | CMM w. IPC | 30.04.92 | 3 15.07.06 | VDN-0418 | S | | ERAM | 3A |
| 22455-000-00/-1 | 32-32-00 | MLG - Assist Actuator | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0153 | S | | Supersedes 22455-000-00 | 3A |
| 22495-000-01 | 32-31-04 | NLG - Unlock Actuator | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0279 | S | | Supersedes 22495-000-00 | 3A |
| 22515/6-000-00 | 32-11-00 | Main Landing Gear | MESSIER-DOWTY | IPC | 01.05.93 | 4 29.05.09 | VDN-0419 | O | | ERAM | 3A |
| 22730/22731-000-XX | 32-00-01 | MLG - Operating Instructions | MESSIER-DOWTY | T. LEAFL. | 01.04.91 | 2 01.09.93 | VDN-0144 | O | | | 3P |
| 22730/22731-000-XX | 32-11-01 | Main - Leg | MESSIER-DOWTY | CMM w. IPC | 31.05.92 | 9 31.12.12 | VDN-0353 | S | | | 3P |
| 22760/22765-000-00 | 32-07-17 | Electrical Harness | MESSIER-DOWTY | CMM w. IPC | 31.07.98 | 1 15.07.06 | VDN-0318 | S | | | 3P |
| 22890-000-01 | 32-31-09 | Restrictor Check Valve | MESSIER-DOWTY | TDS | 31.05.93 | 1 31.01.95 | VDN-0148 | S | | | 3A |
| 22895-000-01 | 32-31-10 | Restrictor Check Valve | MESSIER-DOWTY | TDS | 31.05.93 | 1 31.01.95 | VDN-0149 | S | | | 3A |
| 22910-000-01 | 32-07-15 | Electrical Harness | MESSIER-DOWTY | CMM w. IPC | 31.07.98 | 1 15.07.06 | VDN-0289 | S | | | 3P |
| 22915-000-01 | 32-07-16 | Electrical Harness | MESSIER-DOWTY | CMM w. IPC | 31.07.98 | 1 15.07.06 | VDN-0290 | S | | | 3P |
| 23040-000-01 | 32-51-07 | Steering Control Valve | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0143 | S | | | 3A |
| 23055-000-00 | 32-07-21 | NLG - Feedback Potentiometer Harness | MESSIER-DOWTY | CMM w. IPC | 05.11.01 | 1 15.07.06 | VDN-0375 | S | | | 3A |
| 23100-000-00 /-1/-2/-3 | 32-00-02 | NLG - Operating Instructions | MESSIER-DOWTY | T. LEAFL. | 30.09.92 | 2 07.03.95 | VDN-0152 | O | | | 3P |
| 23100-000-00 /-1/-2/-3 | 32-21-00 | NLG - Shock Strut Assembly | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0481 | S | | | 3P |
| 23100-300-00-/-1-4 | 32-21-30 | NLG - Shock Strut Assembly | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0155 | S | | Supersedes 23100-300-00 | 3A |
| 23110-000-01 | 32-21-01 | Shock Absorber | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0156 | S | | | 3P |
| 23110-300-00 | 32-21-31 | Shock Absorber | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0351 | S | | | 3A |
| 23180-000-01/-02 | 32-51-08 | Electronic Control Unit | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0352 | S | | | 3A |
| 23200-000-01/02 | 32-21-16 | Brace Assy | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0347 | S | | | 3P |
| 23200-300-00/-01/-2 | 32-21-32 | NLG - Brace Assembly | MESSIER-DOWTY | CMM w. IPC | 01.03.13 | | VDN-0350 | S | | Supersedes Rev.1 May 15/1999 | 3A |
| 23265-000-00 | 32-07-28 | NLG - Uplock Electrical Harness | MESSIER-DOWTY | CMM w. IPC | 05.11.01 | 1 15.07.06 | VDN-0377 | S | | | 3P |
| 23285-000-00 | 32-07-22 | NLG - Electrical Control Harness | MESSIER-DOWTY | CMM w. IPC | 05.11.01 | 1 15.07.06 | VDN-0354 | S | | | 3P |
| 23415-000-00 | 32-07-23 | NLG - Main Electrical Harness | MESSIER-DOWTY | CMM w. IPC | 05.11.01 | 1 15.07.06 | VDN-0355 | S | | | 3P |
| 23425-000-00 | 32-07-24 | NLG - Electrical Power Harness | MESSIER-DOWTY | CMM w. IPC | 05.11.01 | 1 15.07.06 | VDN-0356 | S | | | 3P |
| 234A0101 | 21-30-05 | Filter | LIEBHERR | CMM w. IPC | 21.01.85 | 2 01.06.11 | VDN-0476 | S | | ABG-SEMCA | 3A |
| 234A0101 | 21-30-05 | Filter, Air | LIEBHERR TOUL | TCMS | 21.01.85 | 1 03.10.95 | VDN-0002 | S | | ABG-SEMCA | 3A |
| 24120-000-00 | 32-31-11 | Restrictor Check Valve | MESSIER-DOWTY | TDS | 31.05.93 | 1 31.01.95 | VDN-0151 | S | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 24125-000-00 | 32-31-06 | Actuating Cylinder | MESSIER-DOWTY | CMM w. IPC | 31.03.92 | 4 15.07.06 | VDN-0145 | S | | | 3A |
| 24260-000-00/-01/-02 | 32-11-12 | Brace Assy | MESSIER-DOWTY | CMM w. IPC | 15.09.93 | 5 31.12.12 | VDN-0147 | S | | | 3P |
| 2438 | 24-22-67 | Generator Control Unit | AUXILEC | CMM w. IPC | 30.07.92 | | VDN-0020 | S | | THALES | 3P |
| 2500-205RB | 25-60-10 | Air Aspirated Life Rafts | HOOVER INDUSTRIES | CMM w. IPC | 07.08.98 | 1 07.08.98 | VDN-0112 | S | | Models FR-25 | 3P |
| 250205/001-004 | 76-10-62 | Engine Control Cable Assembly | MORSE | CMM w. IPC | 01.01.94 | | VDN-0159 | S | | | 3P |
| 251174 | 27-70-01 | Gust Lock Control | MORSE | CMM w. IPC | 01.05.95 | 1 01.11.96 | VDN-0158 | S | | | 3P |
| 2524-519 | 25-20-97 | Fixed Dynamic Single Seat Series 1300 | B/E AERO AMP | MM w. IPL | 01.02.97 | | 4M51901 | S | | B/E AERO | 3A |
| 2524-520 | 25-20-98 | Fixed Dynamic Double Seat Series 1300 | B/E AERO AMP | MM w. IPL | 01.03.97 | | 4M52001 | S | | B/E AERO | 3A |
| 25910 | 73-10-08 | Ejector Pump and Tank Assy. | TRW / LUCAS | TR 73-2 | 31.03.05 | | VDN-0191 | S | | IPC P&WC | 3P |
| 25910 | 73-10-08 | Ejector Pump and Tank Assy. | TRW / LUCAS | TR 73-1 | 11.02.05 | | VDN-0191 | S | | IPC P&WC | 3P |
| 25910-1 to -8, 25910-09, | 73-10-08 | Ejector Pump and Tank Assy. | TRW / LUCAS | CMM w. IPC | 15.12.84 | 6 20.12.02 | VDN-0191 | S | | P&WC P/N: 3033856, 3039330, 3041468, 3055635-01 | 3P |
| 261000B | 24-23-30 | Transformer Rectifier Unit TRU - 150A1 | DITTEL | CMM w. IPC | 17.11.00 | | TRU 150 A1 | S | | | 3A |
| 2610485-1 | 32-46-03 | Nose Wheel Assembly | ALLIEDSIGNAL | CMM w. IPC | 31.08.92 | 1 30.05.97 | FORM 12-599 | S | | | 3P |
| 2610702-2/-3 | 32-46-01 | Brake Assembly | ALLIEDSIGNAL | CMM w. IPC | 31.08.92 | 8 31.01.98 | FORM 12-597 | S | | | 3P |
| 26200/260 | 73-10-15 | Flow Divider and Dump Valve | TRW / LUCAS | CMM w. IPC | 31.12.92 | 3 31.05.05 | VDN-0193 | S | | IPC P&WC | 3P |
| 2651-311-5 | 38-37-01 | Lavatory Drain Valve Assy | KAISER | CMM w. IPC | 09.09.85 | 6 15.01.90 | VDN-0121 | S | | | 3P |
| 2778-1 | 24-30-00 | Aircraft Battery | SAFT | CMM w. IPC | 01.04.95 | 1 24.04.18 | VDN-0323 | S | | | 3A |
| 2LA002428-00 | 33-32-01 | Light | HELLA | CMM w. IPC | 15.07.82 | 5 19.03.14 | VDN-0183 | S | | GOODRICH HELLA | 3A |
| 2LA004186-00 | 33-41-12 | Tail Light | HELLA | CMM w. IPC | 11.05.00 | | VDN-0187 | S | | GOODRICH HELLA | 3P |
| 2LA004626-05 | 33-11-09 | Flight Crew Reading Light | HELLA | CMM w. IPC | 10.10.95 | 1 22.01.02 | VDN-0108 | S | | GOODRICH HELLA | 3A |
| 2LA005109-Serie | 33-20-06 | Cargo Compartment Light | HELLA | CMM w. IPC | 10.05.88 | 1 18.05.95 | VDN-0107 | S | | GOODRICH HELLA | 3P |
| 2LA005113-00 | 33-26-41 | Indicator Light | HELLA | CMM w. IPC | 10.05.88 | 1 18.11.94 | VDN-0103 | S | | GOODRICH HELLA | 3A |
| 2LA005163-30 | 33-11-22 | Flight Crew Reading Light | HELLA | CMM w. IPC | 08.07.91 | 5 01.03.16 | VDN-0098 | S | | GOODRICH HELLA | 3A |
| 2LA005171-55/-60 | 33-22-08 | Reading Light | HELLA | CMM w. IPC | 01.05.95 | 1 08.08.96 | VDN-0188 | S | | GOODRICH HELLA | 3A |
| 2LA00661X-Serie | 33-22-09 | Passenger Service Units | HELLA | CMM w. IPC | 15.02.94 | 1 20.07.00 | VDN-0104 | S | | GOODRICH HELLA | 3A |
| 2LA006633-00/-01 | 33-12-06 | Dome Light | HELLA | CMM w. IPC | 29.04.94 | | VDN-0102 | S | | GOODRICH HELLA | 3A |
| 2LA006672-00 | 33-11-48 | Pedestal Light, Observer Light | HELLA | CMM w. IPC | 29.04.94 | | VDN-0105 | S | | GOODRICH HELLA | 3A |
| 2LA006729-00 | 33-52-03 | Emergency Light | HELLA | CMM w. IPC | 15.11.92 | | VDN-0101 | S | | GOODRICH HELLA | 3A |
| 2LA006729-00 | 33-52-03 | Emergency Light | HELLA | IPL | 26.06.01 | | VDN-0101 | S | | GOODRICH HELLA | 3A |
| 2LA006778-00 | 33-11-44 | Instrument Panel Light | HELLA | CMM w. IPC | 29.04.94 | 1 06.06.01 | VDN-0173 | S | | GOODRICH HELLA | 3A |
| 2LA006823-01 | 33-31-13 | Cargo Compartment Light | HELLA | CMM w. IPC | 01.03.00 | 2 19.03.14 | VDN-0482 | S | | GOODRICH HELLA | 3A |
| 30005-0000-41/-53/-57 | 73-20-06 | Torque Signal Conditioner Vol. II | BFG SIMMONDS | IPC | 30.03.99 | | VDN-0441 | S | | IPC P&WC | 3P |
| 30005-0000-41/-53/-57 | 73-20-06 | Torque Signal Conditioner Vol. I | BFG SIMMONDS | CMM w. IPC | 15.10.93 | C 30.03.99 | VDN-0441 | S | | IPC P&WC | 3P |
| 3001-01-100 | 31-33-15 | Accelerometer | AMETEK | CMM w. IPC | 01.07.86 | 6 12.12.15 | VDN-0012 | S | | PATRIOT | 3A |
| 30011-1 | 28-41-01 | Sensor, Tank Unit, Innertank | ROGERSON | CMM w. IPC | 15.07.95 | | VDN-0224 | S | | | 3A |
| 30011-2 | 28-41-02 | Sensor, Tank Unit, Outertank | ROGERSON | CMM w. IPC | 15.07.95 | | VDN-0215 | S | | | 3A |
| 30011-3 | 28-41-03 | Sensor, Tank Unit, Outertank | ROGERSON | CMM w. IPC | 15.07.95 | | VDN-0214 | S | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 30011-4 | 28-41-04 | Sensor, Tank Unit, Feeder Tank | ROGERSON | CMM w. IPC | 15.07.95 | | VDN-0216 | S | | | 3A |
| 30013 | 28-42-03 | Sensor, Fuel Level | ROGERSON | CMM w. IPC | 15.07.95 | | VDN-0217 | S | | | 3A |
| 3029B000-002 | 21-30-21 | 1/4" Non Return Valve | NGL | CMM w. IPC | 10.12.74 | 1 12.05.99 | 1372 | S | | | 3P |
| 3033125 | | PW100 S Facility Planning Manual | PWC | MANUAL | 25.01.85 | 8 28.09.95 | 3033125 | O | | | 3P |
| 3036421 | 75-30-01 | P2.5 Check Valve | PWC | CMM w. IPC | 30.01.87 | 4 05.09.08 | 3036421 | S | | | 3P |
| 3036422 | 75-30-02 | Intercompressor Bleed Valve Assy | PWC | CMM w. IPC | 30.01.87 | 5 18.02.10 | 3036422 | S | | | 3P |
| 3036422 | 75-30-02 | Intercompressor Bleed Valve Assy | PWC | CMM | 30.05.96 | 7 30.10.15 | 3036422 | S | | | 3P |
| 3036423 | 74-20-01 | Ignition Cables | PWC | CMM w. IPC | 30.01.87 | 3 10.12.09 | 3036423 | S | | | 3P |
| 3037038 | 73-10-03 | Fuel Manifold Adapter | PWC | CMM w. IPC | 27.09.89 | 8 18.07.97 | 3037038 | S | | | 3P |
| 3037326 | 73-10-04 | Fuel Manifold Adapter | PWC | CMM w. IPC | 09.11.89 | 8 18.07.97 | 3037326 | S | | | 3P |
| 3038533 | 72-XX-XX | Engine Manual PW119B / 119C | PWC | TR 72-6 | 20.02.18 | | 3038533 | O | | | 3P |
| 3038533 | 72-XX-XX | Engine Manual PW119B / 119C | PWC | EM | 26.04.93 | 20 04.09.17 | 3038533 | O | | CD-ROM only | 3P |
| 3038533 | 72-XX-XX | Engine Manual PW119B / 119C | PWC | TR 72-5 | 12.01.18 | | 3038533 | O | | | 3P |
| 3038534 | 72-00-00 | IPC for PW119B/119C | PWC | IPC | 26.04.93 | 54 18.07.22 | 3038534 | O | | | 3P |
| 3039695/3121593-01 | 74-10-58 | High Energy Ignition Unit | TRW / LUCAS | CMM w. IPC | 06.01.93 | 3 18.10.95 | VDN-0194 | S | | IPC P&WC | 3P |
| 3039739 | | Specific Operating Instr. PW119A | PWC | SOI | 27.01.92 | 1 03.04.92 | BSN 792 | O | | | 3P |
| 3040346 | | Airworthiness Limitations PW119B/C | PWC | ALM | 01.02.93 | 8 22.06.09 | 3040346 | S | | | 3P |
| 3040588 | | Specific Operating Instr. PW119B/C | PWC | SOI | 26.02.93 | 5 15.11.96 | BSN 824/878 | O | | | 3P |
| 3040589 | | Engine Module Sampling Program | PWC | MANUAL | 19.03.93 | | 3040589 | O | | | 3P |
| 3040598 | 72-03-00 | Hot Section Inspection PW119B/C | PWC | HSIM | 01.10.93 | 21 06.10.06 | 3040598 | O | | CD-ROM only | 3P |
| 3040878 | | Facility Planning Manual | PWC | FPM | 13.08.07 | | 3040878 | O | | CD-ROM only | 3A |
| 3040878 | | Facility Equipment and Planning Manual | PWC | FEPM | 30.06.96 | 7 13.08.07 | 3040878 | O | | | 3A |
| 3040879 | | PW100 Workscope Planning Guide | PWC | WPG | 04.06.99 | 23 30.06.19 | 3040879 | O | | | 3P |
| 3040888 | | Test Facility Planning Manual | PWC | TFPM | 13.05.99 | 5 15.10.05 | 3040888 | O | | CD-ROM only | 3A |
| 3041321 | 71-50-10 | Electrical Wiring Harness | PWC | ACMM | 16.08.93 | 6 24.07.15 | 3041321 | S | | | 3P |
| 3041323 | 77-20-01 | T6 Trim Cable | PWC | CMM w. IPC | 16.08.93 | | 3041323 | S | | | 3P |
| 3041327 | 77-20-05 | T6 Trim Thermocouple Electrical Cable | PWC | CMM w. IPC | 16.08.93 | 3 09.02.10 | 3041327 | S | | | 3P |
| 3041328 | 77-20-06 | Temperature Sensor | PWC | CMM w. IPC | 16.08.93 | 3 26.08.16 | 3041328 | S | | | 3P |
| 3041329 | 79-30-01 | Oil Press.Differential Switch or Indicator | PWC | CMM w. IPC | 16.09.93 | 4 26.08.16 | 3041329 | S | | | 3P |
| 3041330 | 79-30-02 | Chip Detectors/Collectors a.Valves | PWC | CMM w. IPC | 18.01.95 | | 3041330 | S | | | 3P |
| 3041331 | 77-10-04 | Torque Sensor | PWC | CMM w. IPC | 16.08.93 | | 3041331 | S | | | 3P |
| 3041332 | 77-20-02 | Immersion Thermocouples | PWC | CMM w. IPC | 15.02.96 | 3 21.07.15 | 3041332 | S | | | 3P |
| 3043340 | | CONSUMABLE MATERIALS LIST | PWC | CML | 01.03.96 | 16 02.05.06 | 3043340 | S | | | 3P |
| 3043640 | 77-11-06 | Speed Sensors | PWC | CMM w. IPC | 01.07.99 | 4 13.06.14 | 3043640 | S | | Replaces 77-10-01/-02 | 3A |
| 3045331 | 77-21-08 | MOT Sonsor a/o T6 Trim Thermocouple | PWC | CMM w. IPC | 01.07.99 | 1 01.09.00 | 3045331 | S | | | 3A |
| 3053125 | 79-31-02 | Chip Detectors/Collectors and Valves | PWC | CMM w. IPC | 01.07.99 | 5 11.09.15 | 3053125 | S | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 3056640 | 73-10-05 | Fuel Manifold Adapter | PWC | CMM w. IPC | 01.03.03 | 7 22.01.16 | 3056640 | S | | | 3P |
| 3072152 | 72-XX-XX | Maintenance Manual PW119B / PW119C | PWC | MM | 30.06.14 | 17 27.05.22 | 3072152 | O | | | 3P |
| 30874-001 | 24-34-02 | Ni-Cad-Batterie Typ SP-747 | MARATHON | CMM w. IPC | 31.03.02 | 2 07.05.04 | VDN-0428 | S | | | 3A |
| 30VR1107 | 79-40-10 | Thermal Valve | ASG | CMM w. IPC | 01.08.96 | | VDN-0017 | S | | AEG | 3P |
| 30ZF108 | 79-40-20 | Flap Actuator for Oil Cooler | ASG | CMM w. IPC | 01.08.96 | 1 14.04.97 | VDN-0018 | S | | AEG | 3P |
| 3214-30 | 33-51-07 | Battery | DIEHL | CMM w. IPC | 15.02.83 | 5 04.02.98 | VDN-0073 | S | | | 3A |
| 3214-31 | 33-51-17 | Battery | DIEHL | CMM w. IPC | 08.07.02 | 12 13.07.21 | VDN-0422 | S | | | 3A |
| 3214-73 | 33-51-99 | Emergency Power Supply Unit | DIEHL | CMM w. IPC | 01.09.94 | 2 02.07.10 | VDN-0071 | S | | | 3A |
| 3253-10 | 33-24-99 | Ballast Unit | DIEHL | CMM w. IPC | 20.02.95 | 2 28.09.01 | VDN-0415 | S | | | 3A |
| 3274-10 | 31-50-99 | Red Warning Panel | DIEHL | TR 001 | 20.11.03 | | 31-50-99_001 | S | | | 3A |
| 3274-10 | 31-50-99 | Red Warning Panel | DIEHL | CMM w. IPC | 20.03.95 | | VDN-0070 | S | | | 3A |
| 328-0010 | 31-12-13 | Ice - Fuel - Hydro Panel | COBHAM | CMM w. IPC | 01.10.93 | 1 30.06.95 | VDN-0170 | S | | NEC AERO | 3P |
| 328-0020/21 | 31-11-05 | AC/DC Panel | COBHAM | CMM w. IPC | 01.10.93 | 1 30.06.95 | VDN-0166 | S | | NEC AERO | 3A |
| 328-0030/-31 | 31-12-11 | Forward Combined Panel | COBHAM | CMM w. IPC | 01.10.93 | 2 30.04.99 | VDN-0169 | S | | NEC AERO | 3P |
| 328-0040/41 | 49-32-10 | APU Panel | COBHAM | CMM w. IPC | 01.10.93 | 1 30.06.95 | VDN-0168 | S | | NEC AERO | 3A |
| 328-0050/51/52 | 23-41-03 | Calls Panel | COBHAM | CMM w. IPC | 01.10.93 | 1 30.06.95 | VDN-0172 | S | | NEC AERO | 3A |
| 328-007XAmdtB/C /-3074 | 31-12-12 | OXYGEN/ECS Panel | COBHAM | CMM w. IPC | 01.10.93 | 2 25.06.99 | VDN-0165 | S | | NEC AERO | 3A |
| 328-0080 | 27-32-20 | Trim Panel | COBHAM | CMM w. IPC | 01.10.93 | 3 06.09.10 | VDN-0164 | S | | NEC AERO | 3A |
| 328-0090 | 31-25-01 | Reversionnary Panel | COBHAM | CMM w. IPC | 01.10.93 | 1 30.06.95 | VDN-0160 | S | | NEC AERO | 3A |
| 328-0100 | 31-12-15 | Flight Attendant Panel | COBHAM | CMM w. IPC | 01.10.93 | 4 31.07.07 | VDN-0163 | S | | NEC AERO | 3A |
| 328-0140/0160 | 27-20-11 | The Reds Test Panel 34VE | COBHAM | CMM w. IPC | 14.10.97 | 1 20.11.98 | VDN-0525 | S | | NEC AERO | 3A |
| 328-0170 | 26-10-01 | Fire Panel For Cargo Compartment | COBHAM | CMM w. IPC | 19.03.00 | 1 04.04.01 | VDN-0161 | S | | NEC AERO | 3A |
| 328-0180 | 26-10-02 | Distribution Box | COBHAM | CMM w. IPC | 07.03.00 | | VDN-0162 | S | | NEC AERO | 3A |
| 328100-1M03AMDT-A | 27-31-02 | Cable Tension Regulator (Elevator Contr.) | SARMA | CMM w. IPC | 10.07.95 | 2 29.12.00 | VDN-0197 | S | | | 3A |
| 328100-2M03AMDT-A | 27-31-02 | Cable Tension Regulator (Elevator Contr.) | SARMA | CMM w. IPC | 10.07.95 | 2 29.12.00 | VDN-0195 | S | | | 3A |
| 328300-1M02/3 | 27-11-02 | Cable Tension Regulator (Aileron Contr.) | SARMA | CMM w. IPC | 10.07.95 | 1 29.12.00 | VDN-0198 | S | | | 3A |
| 328300-2M02/3 | 27-11-02 | Cable Tension Regulator (Aileron Contr.) | SARMA | CMM w. IPC | 10.07.95 | 1 29.12.00 | VDN-0236 | S | | | 3A |
| 328-3150 | 27-60-01 | Ground Spoiler Test Panel | COBHAM | CMM w. IPC | 28.01.98 | 1 01.07.99 | VDN-0524 | S | | NEC AERO | 3A |
| 3285-10 | 30-42-02 | Windscreen Heater Control Unit | DIEHL | CMM w. IPC | 25.07.94 | 1 30.06.00 | VDN-0068 | S | | | 3P |
| 3285-50 | 30-42-03 | Control Unit, Window Heat | DIEHL | CMM w. IPC | 10.04.00 | | VDN-0229 | S | | | 3A |
| 328600 M02 | 27-31-11 | Force Detector Rod | SARMA | CMM w. IPC | 20.04.95 | 1 28.02.01 | VDN-0312 | S | | | 3A |
| 3296-30/-40 | 33-13-11 | Lighting Dimmer | DIEHL | CMM w. IPC | 15.07.96 | 3 11.03.08 | VDN-0072 | S | | | 3A |
| 330/335GA01Y01 | 24-29-55 | AC Junction Box | ECE | CMM w. IPC | 15.06.94 | 3 24.09.13 | VDN-0083 | S | | ZODIAC | 3A |
| 331-0001-01 | 38-30-08 | Waste Drain Valve | SHAW | CMM w. IPC | 15.06.95 | | 331-0001-01 | S | | | 3A |
| 33100016-1/33600042-1 | 26-22-37 | Single Outlet Fire Extinguishers | PACIFIC SCIENTIFIC | CMM w. IPC | 15.02.94 | 4 15.06.04 | VDN-0174 | S | | | 3A |
| 33500012-1/13-1 | 26-22-54 | Fire Extinguisher | PACIFIC SCIENTIFIC | CMM w. IPC | 15.06.99 | 1 15.01.05 | VDN-0281 | S | | | 3A |
| 3360 | 29-21-02 | Relief Valve and Pressure Dump | PneuDraulics | CMM w. IPC | 24.09.09 | | 06177-3360 | S | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 34200408-1 | 26-23-50 | Single Outlet Metering Fire Extinguisher | PACIFIC SCIENTIFIC | CMM w. IPC | 15.11.00 | | VDN-0280 | S | | | 3A |
| 35001016-1 | 26-20-10 | Discharge Indicator Assy | PACIFIC SCIENTIFIC | CMM w. IPC | 01.02.76 | 1 15.02.94 | VDN-0175 | S | | | 3A |
| 35303-XXX | 26-14-14 | Wire End Fittings | KIDDE-DEUGRA | CMM w. IPC | 12.02.96 | 3 03.01.13 | 514 | S | | HAMILTON SUNDSTRAND | 3A |
| 355XX-2 | 26-14-12 | Sensing Elements | KIDDE-DEUGRA | CMM w. IPC | 17.05.06 | 12 27.05.14 | 512 | S | | HAMILTON SUNDSTRAND | 3A |
| 35XXX-XXX-XXX | | Cont.Fire a.Overheat Detection Sys. | KIDDE-DEUGRA | INSTR.M | 01.11.80 | 4 15.08.96 | 505 | S | | HAMILTON SUNDSTRAND | 3A |
| 37-035-23-000-2/-4 | 79-20-01 | Oil Cooler Assembly | BEHR | CMM w. IPC | 25.01.96 | 1 31.07.14 | VDN-0049 | S | | MAHLE | 3P |
| 3759-2 | 24-30-00 | Aircraft Battery | SAFT | CMM w. IPC | 01.09.94 | | VDN-0322 | S | | | 3A |
| 3800498-1 | 49-30-91 | Fuel Control Assembly | HONEYWELL ASIG | CMM w. IPC | 01.05.86 | 8 31.07.10 | D200402000036 | S | | ALLIEDSIGNAL | 3P |
| 3800498-1/-3 | | Standard Practices Manual | HONEYWELL | SPM | 28.10.77 | 22 11.12.19 | 20-00-02-70-00-01 | S | | | 3A |
| 3800498-1/-3 | 49-24-11 | APU GTCP36-150[DD] | HONEYWELL | MM | 24.02.95 | 4 28.08.15 | VDN-0005 | S | | | 3A |
| 3800498-1/-3 | 49-24-10 | APU GTCP36-150[DD] | HONEYWELL | IPC | 18.05.92 | 5 07.10.11 | VDN-0007 | S | | | 3A |
| 3800498-1/-3 | 49-24-12 | APU GTCP36-150[DD] | HONEYWELL | TR 49-3 | 25.10.01 | | VDN-0009 | S | | | 3A |
| 3800498-1/-3 | 49-24-12 | APU GTCP36-150[DD] | HONEYWELL | CMM w. IPC | 18.05.92 | 4 28.08.15 | VDN-0009 | S | | | 3A |
| 3800498-1/-3 | 49-24-12 | APU GTCP36-150[DD] | HONEYWELL | TR 49-2 | 25.10.01 | | VDN-0009 | S | | | 3A |
| 3800498-1/-3 | 49-24-09 | Pneum.a.Shaft Power Gas Turbine GTCP36-150 Series | HONEYWELL ASIG | IRM | 02.01.88 | 33 20.02.18 | D200701000028 | S | | ALLIEDSIGNAL | 3A |
| 3888134-5 | 49-30-93 | Normally Closed Solenoid Valve | ALLIEDSIGNAL | CMM w. IPC | 30.05.85 | 3 21.11.95 | VDN-0004 | S | | | 3P |
| 3900001-101 to -109 | 29-10-29 | 3000 PSI Ribbed Shell Accumulator | PARKER | CMM w. IPC | 12.09.91 | 8 07.03.14 | VDN-0178 | S | | 3900001-101/-105/-107/-108/-109 | 3A |
| 3907B000 | 21-51-22 | Non-Return Valve | HONEYWELL NGL | CMM w. IPC | 21.10.92 | 4 01.07.10 | 2376 | S | | NGL | 3A |
| 3907B000 | 21-51-22 | Non-Return Valve 63,5 mm (2.5 in) | NGL | MM | 29.04.92 | | 2375 | O | | | 3A |
| 397.326-925/802.157-925 | 23-30-03 | Tape player TP 3100 | BECKER | IOM | 01.02.89 | | DV 32002.03 | O | | OBSOLETED | 3A |
| 3A165-0007/8-01-1 | 25-11-15 | Crew Seat | IPECO | CMM w. IPC | 05.02.07 | 4 28.08.12 | SM628 | S | | Repl. CMM 25-10-72 | 3P |
| 3A165-0007/8-01-2 | 25-11-03 | Crew Seat Assembly | IPECO | CMM w. IPC | 22.03.96 | 12 28.08.14 | SM615 | S | | | 3A |
| 3D3190-1-2 | 30-10-73 | Temperature Switch | BFG ICE | CMM w. IPC | 15.04.99 | | VDN-0282 | S | | | 3A |
| 3D3553-01 | 30-10-44 | Water Seperator | BFG ICE | CMM w. IPC | 01.02.02 | 1 25.11.19 | VDN-0426 | S | | | 3A |
| 3D3554-02 | 30-10-46 | Isolation Valve, De-Icing | BFG ICE | CMM w. IPC | 15.01.99 | | VDN-0425 | S | | | 3P |
| 3D3555-01 | 30-10-47 | Check Valve | BFG ICE | CMM w. IPC | 30.03.99 | 1 14.01.20 | VDN-0226 | S | | | 3A |
| 3D3556-01/-03 | 30-10-48 | Ejector Flow Control Valve | UTC | CMM w. IPC | 01.02.02 | 1 30.01.20 | VDN-0227 | S | | Goodrich / BFG ICE | 3A |
| 3D3557-01 | 30-10-45 | Pressure Switch | BFG ICE | CMM w. IPC | 15.12.00 | | VDN-0140 | S | | | 3A |
| 3D3573-01/-02 | 30-10-55 | PRESSURE RELIEF VALVE | BFG ICE | CMM w. IPC | 01.12.99 | | VDN-0409 | S | | | 3P |
| 3E2459-1 | 24-09-01 | Temperature Controller | BFG ICE | CMM w. IPC | 15.05.92 | | 92-32-019 | S | | | 3A |
| 40006 | 28-23-10 | Signal Processing /Refueling Panel | ROGERSON | CMM w. IPC | 15.07.95 | 1 17.11.09 | 9967-0246 | S | | | 3P |
| 400500-1 | 38-11-06 | Manual Shutoff Valve | ADAMS RITE | CMM w. IPC | 01.04.73 | 7 23.03.04 | 400500 | S | | | 3A |
| 4005842 | 22-11-51 | SB-201 Servo Drum/Housing Assy | HONEYWELL | CMM w. IPC | 15.10.73 | 6 30.08.99 | A09-1146-005 | S | | | 3A |
| 4006719-906/-910 | 22-11-50 | SM-200 Servo Drive | HONEYWELL | CMM w. IPC | 05.12.73 | 13 07.04.15 | A09-1146-004 | S | | | 3A |
| 4031B000 | 21-51-02 | Solenoid Valve | HONEYWELL NGL | CMM w. IPC | 04.02.92 | 5 11.03.11 | 2369 | S | | NGL | 3A |
| 40351 | | Application Guide Honeywell Carry-On VXP | TELEMETER ELECTRONIC | AG | 04.02.11 | | TAG-X328 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 4040B000 | 36-11-11 | Non Return Valve 63,5 mm (2.5 inch) | HONEYWELL NGL | CMM w. IPC | 10.10.95 | 5 09.12.14 | 2406S | S | | NGL | 3A |
| 4040B000 | 36-11-11 | Non-Return Valve 2.5 inch (6,3 50 mm) | NGL | MM | 22.04.92 | 1 01.07.10 | 2370 | O | | | 3A |
| 40514 | | User Guide for Honeywell Carry-On VXP | TELEMETER ELECTRONIC | UG | 04.03.11 | | TUG-X328 | O | | Chapter 1-5 | 3P |
| 4053B000 | 21-21-04 | Non-Return Valve 165 mm (6.5 in) | NGL | MM | 23.06.92 | | 2397 | O | | | 3A |
| 4053B000 | 21-21-04 | Non-Return Valve 165 mm (6.5 in) | NGL | CMM w. IPC | 11.11.92 | 1 12.12.95 | 2398 | S | | | 3A |
| 4066010-904 | 34-43-04 | Traff. Alert a. Collision Avoid.System Vol. 1 | HONEYWELL L3 | CMM w. IPC | 01.07.90 | 11 15.12.05 | C15-3841-007 | S | | ACSS-L3; supersedes 15-3841-07; ATA change in to 34-45-04 | 3P |
| 4066010-904 | 34-43-04 | Traff. Alert a. Collision Avoid.System Vol. 2 | HONEYWELL L3 | CMM w. IPC | 01.04.94 | 5 15.12.05 | C15-3841-007 | S | | ACSS-L3; supersedes 15-3841-07; ATA change in to 34-45-04 | 3P |
| 4066010-904 | 34-43-04 | Traff. Alert a. Collision Avoid.System Vol. 3 | HONEYWELL L3 | CMM w. IPC | 01.07.90 | 10 15.12.05 | C15-3841-007 | S | | ACSS-L3; supersedes 15-3841-07; ATA change in to 34-45-04 | 3P |
| 4066010-904/-910 | 34-43-00 | TCAS II RT-910 | L3 ACSS | SDIM | 01.06.89 | 5 06.08.14 | C15-3841-005 | S | | ACSS-L3 | 3P |
| 4066010-XXX | 34-45-04 | Traffic Alert and Collision Avoidance System - Volume II | L3 ACSS | CMM w. IPC | 01.07.90 | 7 15.08.18 | C15-3841-007 | S | | ACSS-L3 | 3A |
| 4066010-XXX | 34-45-04 | Traffic Alert and Collision Avoidance System - Volume I | L3 ACSS | CMM w. IPC | 01.07.90 | 13 15.08.18 | C15-3841-007 | S | | ACSS-L3 | 3A |
| 4066010-XXX | 34-45-04 | Traffic Alert and Collision Avoidance System - Volume III | L3 ACSS | CMM w. IPC | 01.07.90 | 12 15.08.18 | C15-3841-007 | S | | ACSS-L3 | 3A |
| 4066B000 | 36-11-02 | Non-Return Valve 2 inch (50,8 mm) | HONEYWELL NGL | MM | 10.07.92 | 1 01.07.10 | 2371 | O | | | 3P |
| 4066B000/-002 | 36-11-02 | Non-Return Valve 2 inch (50,8 mm) | HONEYWELL NGL | CMM w. IPC | 09.01.96 | 4 09.02.15 | 2372 | S | | | 3A |
| 4066B000-002 | 36-11-41 | Non-Return Valve, 2 inch (50.8 mm) | NGL | MM | 23.02.99 | | 2705 | O | | | 3A |
| 4066B000-002 | 36-11-41 | Non-Return Valve, 2 inch (50.8 mm) | NGL | CMM w. IPC | 04.03.99 | | 2706 | S | | | 3A |
| 4067B000-002 | 36-11-03 | Pressure Reducing a.Shut Off Valve | NGL | MM | 07.05.92 | 2 01.07.10 | 2384 | O | | | 3P |
| 4067B000-002/3/4/5/6 | 36-11-03 | Pressure Reducing and Shut Off Valve | HONEYWELL NGL | CMM w. IPC | 15.03.96 | 12 07.11.16 | 2385 | S | | NGL | 3A |
| 4067B000-004 | 36-11-42 | Press.Reduc. And Shut-Off Valve | NGL | MM | 23.02.99 | | 2707 | O | | | 3A |
| 4067B000-004 | 36-11-42 | Press.Reduc. And Shut-Off Valve | NGL | CMM w. IPC | 23.02.99 | | 2708 | S | | | 3A |
| 4068B000-002/-003 | 21-51-03 | Flow Control and Shut Off Valve | HONEYWELL NGL GL | CMM w. IPC | 18.12.95 | 9 09.08.06 | 2379 | S | | NGL | 3A |
| 4069B000-002 | 36-11-10 | Cross Feed Valve | HONEYWELL NGL | CMM w. IPC | 12.12.95 | 6 09.02.11 | 2383 | S | | | 3A |
| 4078-4 | 24-31-16 | Aircraft Battery | SAFT | CMM w. IPC | 01.02.91 | | VDN-0324 | S | | | 3A |
| 407A0104 | 21-33-05 | Air Jet Pump | LIEBHERR | CMM w. IPC | 30.06.92 | 2 31.12.12 | VDN-0132 | S | | ABG-SEMCA | 3A |
| 4100-849048 | 29-12-01 | Motor Driven Hydraulic Pump Assy | AERO CONTROLEX | CMM w. IPC | 15.08.94 | 3 15.10.02 | VDN-0003 | S | | | 3A |
| 4100-849049 | 28-09-04 | Motor Driven Hydraulic Pump Assy | AERO CONTROLEX | CMM w. IPC | 17.07.97 | 3 30.05.01 | VDN-0380 | S | | | 3A |
| 41590-200 | | Pressure compensated elbow bellows joint | PERKINELMER | GRS | 30.11.01 | | GR-0021C | O | | | 3P |
| 42086/4208601 | 29-10-50 | Electric Motor Driven Variable Delivery Hydraulic Pump | PARKER | CMM w. IPC | 01.09.93 | 1 01.03.03 | VDN-0433 | S | | | 3P |
| 4208601 | 29-10-50 | Insert facing page 118 | PARKER | TR-29-410 | 28.09.11 | | VDN-0433 | S | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 4208601 | 29-10-50 | Introduction of P/N 4208601 | PARKER | TR-29-409 | 28.09.11 | | VDN-0433 | S | | | 3A |
| 4298816/-09 | 30-41-04 | Wiper-Arm LH/RH | TELEFLEX | CMS | 01.03.92 | 1 01.07.00 | VDN-0247 | S | | ZODIAC | 3A |
| 4298823 | 30-41-05 | Wiper-Blade | TELEFLEX | CMS | 01.03.92 | 1 01.09.94 | VDN-0248 | S | | ZODIAC | 3A |
| 4327-4 | 27-31-09 | Disconnect Unit Elevator | AVIAC | CMM w. IPC | 01.06.94 | 1 01.09.99 | VDN-0038 | S | | SAGEM | 3A |
| 4328-2 | 27-11-07 | Aileron Disconnect Unit | AVIAC | CMM w. IPC | 01.06.94 | 1 15.09.99 | VDN-0037 | S | | SAGEM | 3A |
| 4330 | 27-33-02 | Stick Shaker | AVIAC | CMM w. IPC | 20.10.92 | 1 10.06.07 | VDN-0036 | S | | SAGEM | 3A |
| 4337122/38 | 30-41-03 | Motor-Converter | SAFRAN | CMM w. IPC | 31.12.91 | 5 22.08.19 | VDN-0246 | S | | Ex ZODIAC | 3A |
| 440/441TS08Y01 | 26-24-15 | Fire Panel | ECE | CMM w. IPC | 15.05.93 | 3 30.04.98 | VDN-0084 | S | | INTERTECHNIQUE | 3A |
| 4441019-002 | 35-22-11 | Oxygen Pressure Regulator | B/E AERO PURITAN | CMM w. IPC | 06.01.02 | | VDN-0451 | S | | PURITAN BENNETT | 3P |
| 453-0150 | | Emergency Locator Transmitters | ARTEX | DOIMM | 26.04.96 | G 29.08.06 | 570-1015 | S | | ELT 110-4 | 3A |
| 488-221 | | Pressure Fuel Servicing Cap | SHAW | SM | 08.05.98 | | ILS-033 | S | | | 3A |
| 4990DO-2 | 30-13-12 | Air Pressure Regulator Valve | ROGERSON | CMM w. IPC | 01.07.95 | | VDN-0219 | S | | | 3P |
| 4D2095-200/220 | 30-10-43 | Pressure Regulator/Reliever | UTC | CMM w. IPC | 01.02.02 | 2 31.08.20 | VDN-0126 | S | | Goodrich | 3P |
| 4D2185-01 | 30-10-42 | Pre-Cooler | BFG ICE | CMM w. IPC | 15.04.99 | | VDN-0120 | S | | | 3P |
| 4E2947-3 | 30-60-12 | Timer/Monitor | BFG ICE | ACMM | 01.02.01 | 1 02.09.08 | VDN-0556 | S | | | 3A |
| 500-12, 16, 27 | | MULTI FUNCTION PERSONAL LOCATOR BEACON (PLB) PERSONAL LOCATOR BEACON (PLB) | HR-SMITH | MM | | 15 20.10.14 | HRS1002-5-00 | O | | | 3A |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | TR 73-9 | 29.03.96 | | VDN-0192 | S | | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | CMM w. IPC | 01.05.83 | 10 28.06.02 | VDN-0192 | S | | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | TR 73-11 | 18.06.03 | | VDN-0192 | S | | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | TR 73-8 | 15.05.95 | | VDN-0192 | S | | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | TR 73-10 | 19.07.00 | | VDN-0192 | S | | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | TR 73-14 | 15.09.05 | | VDN-0192 | S | | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | TR 73-13 | 01.06.05 | | VDN-0192 | S | | IPC P&WC | 3P |
| 5009984 | 73-10-07 | Power Driven Rotary Pump | TRW / LUCAS | TR 73-12 | 20.04.04 | | VDN-0192 | S | | IPC P&WC | 3P |
| 501-1228-() | 24-30-04 | Emergency Power Supply JET Model PS-835 | L3 COMMUNICATIONS | IM | 01.07.94 | P 20.03.17 | TP-336 | S | | | 3A |
| 501-1228-03 | 24-30-02 | PS-835 Emergency Power Supply | L3 COMMUNICATIONS | CMM w. IPC | 01.09.95 | C, Chng4 25.07.19 | TP-329 | S | | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | PS-835 Troubleshooting Guide | L3 COMMUNICATIONS | GUIDE | 06.06.08 | | TP-607 | S | | BFG AVIONICS | 3A |
| 501-1568-() | | AI-330 Standby Attitude Indicator | L3 COMMUNICATIONS | PG | | D 05.02.18 | TP-573 | O | | | 3A |
| 501-1568-10 | 34-20-51 | AI-330 Attitude Indicator | L3 COMMUNICATIONS | IOM | 31.03.00 | C 05.02.18 | TP-454 | S | | BFG AVIONICS | 3A |
| 502745-Series | 25-24-01 | Lap Belt Assembly | AM-SAFE | CMM w. IPC | 15.05.96 | 7 12.06.12 | 502745 | S | | | 3A |
| 502879-Series | 25-22-08 | Restraint System Assembly | AM-SAFE | CMM w. IPC | 20.11.98 | 3 20.01.03 | 502879 | S | | | 3A |
| 503321-Series | 25-23-05 | Restraint System Assembly | AM-SAFE | CMM w. IPC | 27.11.98 | 3 17.01.03 | 503321 | S | | | 3A |
| 503693 Series | 25-11-16 | Restraint System Assembly | AM-SAFE | CMM w. IPC | 13.09.96 | 4 19.12.02 | 503693 | S | | | 3A |
| 504109-Series | 25-12-18 | Restraint System Assembly | AM-SAFE | CMM w. IPC | 07.06.98 | 3 09.01.03 | 504109 | S | | | 3A |
| 512XX-XXX | 26-16-10 | Terminal Lug Firewire and Accessoires | KIDDE-DEUGRA | CMM w. IPC | 04.08.93 | 09.08.11 | VDN-0381 | S | | HAMILTON SUNDSTRAND | 3A |
| 5150DO-1 | 30-13-09 | Isolation Valve | ROGERSON | CMM w. IPC | 01.07.95 | | VDN-0220 | S | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 51653-151 | 26-11-89 | Fire Detection Control Unit | KIDDE-DEUGRA | CMM w. IPC | 03.08.05 | 1 25.07.11 | VDN-0499 | S | | HAMILTON SUNDSTRAND | 3A |
| 51653-151-01 | 26-11-84 | Fire Detection Control Unit | KIDDE-DEUGRA | CMM w. IPC | 01.03.95 | | VDN-0385 | S | | HAMILTON SUNDSTRAND | 3A |
| 5382-1 | 23-30-11 | Passenger Address Amplifier | AVTECH | CMM w. IPC | 14.10.93 | 1 16.08.04 | VDN-0039 | S | | | 3A |
| 5403C000 | 21-61-06 | Duct Temperature Limiter | NGL | CMM w. IPC | 13.06.92 | | 2403 | S | | | 3A |
| 5406C000 | 21-61-03 | Temperature Controller | HONEYWELL NGL | CMM w. IPC | 17.01.96 | 4 12.10.01 | 2405 | S | | NGL | 3A |
| 5409C000 | 21-61-05 | Bay Temperature Sensor | NGL | MM | 12.05.92 | 1 07.07.08 | 2393 | S | | | 3A |
| 5410C000 | 21-61-04 | Duct Temperature Sensor | NGL | MM | 06.05.92 | 1 04.03.11 | 2381 | S | | | 3A |
| 5413C000 | 21-61-08 | Temperature Control Valve | HONEYWELL NGL | CMM w. IPC | 10.08.95 | 7 12.08.10 | 2395 | S | | NGL | 3A |
| 5483-1 | 23-30-08 | Interphone Handset/Cradle | AVTECH | CMM w. IPC | 28.02.92 | 2 01.07.05 | VDN-0041 | S | | | 3A |
| 5556C000 | 21-51-21 | Water Injector | HONEYWELL NGL | CMM w. IPC | 09.01.96 | 2 01.11.01 | 2396 | S | | NGL | 3A |
| 5570DO-3 | 30-13-11 | Water Separator | ROGERSON | CMM w. IPC | 01.07.95 | | VDN-0213 | S | | | 3P |
| 5574 | 25-10-10 | Hatrack Latch | INDRAÉRO SIREN | CMM w. IPC | 01.02.01 | 1 01.02.06 | VDN-0450 | S | | | 3A |
| 5577 | 25-10-09 | Cockpit Sliding Door Lock | INDRAÉRO SIREN | CMM w. IPC | 25.09.00 | 1 01.02.06 | VDN-0449 | S | | | 3A |
| 5584C000 | 36-11-04 | Over Temperature Switch | NGL | MM | 23.08.91 | | 2407 | S | | | 3A |
| 5586C000 | 21-51-14 | Over Temperature Switch | NGL | MM | 05.05.92 | 1 24.03.99 | 2380 | S | | | 3A |
| 5623C000 | 21-51-15 | Turbine Inlet Control Valve | NGL | CMM w. IPC | 20.10.92 | 1 17.01.96 | 2387 | S | | | 3A |
| 5658C000 | 36-11-08 | Over Temperature Switch | HONEYWELL NGL | MM | 29.04.92 | 2 10.11.15 | 2374 | S | | | 3P |
| 5677C000 | 21-51-16 | Pneumatic Temperature Sensor | NGL | MM | 09.06.92 | | 2399 | O | | | 3A |
| 5677C000/-002 | 21-51-16 | Pneumatic Temperature Sensor | HONEYWELL NGL | CMM w. IPC | 23.01.96 | 5 15.09.03 | 2400 | S | | NGL | 3A |
| 5682C000 | 36-11-05 | Over Pressure Switch | HONEYWELL | MM | 27.04.92 | 2 11.11.15 | 2373 | S | | was NGL | 3A |
| 5729C000,-002,-003 | 21-51-10 | Environmental Control Unit | NGL | MM with IPL | 14.06.94 | 1 10.01.10 | 2510 | O | | | 3P |
| 5729C000/-002 | 21-51-10 | Environmental Control Unit | HONEYWELL NGL | CMM w. IPC | 14.06.94 | 6 06.12.16 | 2511 | S | | NGL | 3A |
| 5732C000 | 21-51-15 | Turbine Inlet Control Valve | HONEYWELL NGL | CMM w. IPC | 23.05.94 | 2 19.08.04 | 2514 | S | | NGL | 3A |
| 5732C000 | 21-51-15 | Turbine Inlet Control Valve | NGL | MM | 24.05.94 | | 2513 | O | | | 3A |
| 580-291-XXX | 76-10-63 | CONTROL CABLE ASSEMBLIES, COCKPIT AND NACELLE | Cablecraft Motion | CMM w. IPC | 20.08.15 | 1 20.08.15 | VDN-0560 | S | | | 3A |
| 585005 | 72-XX-XX | Standard Practices Manual | PWC | SPM | 01.10.66 | 130 01.12.11 | 52A138 | O | | CD-ROM only | 3A |
| 5E2546/5E2547 | 30-10-19 | Elevator a. Rudder Horn Anti-Icer | BFG ICE | INSTAL.M | 07.03.06 | | VDN-0052 | O | | | 3A |
| 600100-00/-10-500 | 30-10-28 | Timer, De-Icing | TELAIR | CMS | 02.12.97 | | VDN-0245 | S | | NORD-MICRO | 3A |
| 6033-01/02-1/2/03-1 | 28-48-04 | Signal Processor and Refueling Panel Volume 1 | GE AVIATION | CMM w. IPC | 15.07.97 | 3 24.09.10 | GEK 118086 | S | | Formlerly Smiths Aerospace, then GE Aviationn, now ONTIC | 3A |
| 6033-01/02-1/2/03-1 | 28-48-04 | Signal Processor and Refueling Panel Volume 2 | GE AVIATION | CMM w. IPC | 15.07.97 | 3 24.09.10 | GEK 118101 | S | | Formlerly Smiths Aerospace, then GE Aviationn, now ONTIC | 3A |
| 6038C000-001 | 21-51-95 | Environmt.Contr.Sys.Comp.Insul.Jacket Kit | HONEYWELL NGL | CMM w. IPC | 18.10.01 | | 2780 | S | | NGL | 3A |
| 69000941-10X | 34-45-72 | MKV-A Enhanced Ground Proximity Warning System | HONEYWELL | CMM w. IPL | 24.01.14 | 9 10.12.20 | D201304000065 | S | | | 3P |
| 6900094X | | MKV-A EGPWS | HONEYWELL | IM | 14.10.13 | D 20.04.16 | PDS69000940-501 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 7001840-922/-932 | | AA-300 Radio Altimeter System | HONEYWELL | SDIM | 15.08.80 | 12 15.01.09 | A15-3321-006 | S | | consists RT-300 | 3A |
| 7001840-932/922 | 34-42-10 | RT-300 Radio Alti. Rec.Transm. | HONEYWELL | CMM w. IPC | 01.09.10 | 9 29.03.19 | A09-3531-010 | S | | Supersedes Vol. I - III | 3A |
| 7007549-906 | 34-64-02 | CD-810 Control Display Unit | HONEYWELL | CMM w. IPC | 01.02.91 | 6 28.07.15 | A09-1147-040 | S | | Supersedes A09-1147-40 Vol. I + II | 3A |
| 7008470-922 | 34-40-30 | WU-650 Receiver Transm.Antenna Vol. IIIB | HONEYWELL | CMM w. IPC | 01.10.92 | 1 15.12.02 | A09-3941-002 | S | | Supersedes A09-3941-02 | 3P |
| 7008470-922 | 34-40-30 | WU-650 Receiver Transm.Antenna Vol. IIIA | HONEYWELL | CMM w. IPC | 01.10.92 | 1 15.12.02 | A09-3941-002 | S | | Supersedes A09-3941-02 | 3P |
| 7008470-922 | 34-40-30 | WU-650 Receiver Transm.Antenna Vol. I | HONEYWELL | CMM w. IPC | 01.05.86 | 5 15.12.02 | A09-3941-002 | S | | Supersedes A09-3941-02 | 3P |
| 7008470-922 | 34-40-30 | WU-650 Receiver Transm.Antenna Vol. II | HONEYWELL | CMM w. IPC | 15.12.02 | | A09-3941-002 | S | | Supersedes A09-3941-02 | 3P |
| 7013270-93X/-966 thru-988 | 34-51-24 | RM-855 Radio Management Unit | HONEYWELL | CMM w. IPC | 15.07.93 | 13 01.06.20 | A09-3800-028 | S | | | 3A |
| 7013348-9XX | 31-40-01 | DA-800 Data Acquisition Unit | HONEYWELL | CMM w. IPC | 01.11.93 | 10 24.02.20 | M15-1147-042 | S | | | 3A |
| 7014300-902 | 34-24-39 | DU-870 Display Unit | HONEYWELL | CMM w. IPC | 15.08.93 | 7 08.02.19 | A09-1147-043 | S | | merged into a single-volume | 3A |
| 7014332-902 | 34-24-38 | BL-870/871 Bezel Controller | HONEYWELL | CMM w. IPC | 15.05.93 | 7 29.06.20 | A09-1147-038 | S | | | 3A |
| 7014700-XXX | 34-16-17 | AZ-840 Micro Air Data Computer | HONEYWELL | CMM w. IPC | 01.02.91 | 8 10.09.19 | A09-3435-010 | S | | formerly A09-3735-10 | 3P |
| 7014940-902 | 22-12-79 | IM-803 Installation Module | HONEYWELL | CMM w. IPC | 15.12.98 | 2 | A09-1147-073 | S | | Reissue | 3A |
| 7015327-901/-905 | 22-18-70 | GP-300 Guidance Panel Controller | HONEYWELL | CMM w. IPC | 01.08.91 | 4 01.12.05 | A09-1147-044 | S | | | 3A |
| 7016600-901/-902 | 34-24-43 | DL-900 Data Loader | HONEYWELL | CMM w. IPC | 15.06.92 | 4 15.10.15 | A09-1147-062 | S | | | 3A |
| 7017300-XXXXX | 22-11-95 | IC-800 Intergrated Avionics Computer | HONEYWELL | CMM w. IPC | 01.10.92 | 6 26.08.19 | A09-1147-075 | S | | Supersedes Vol. I - III | 3A |
| 7021450-601 | 34-42-11 | Receiver Transmitter Antenna | HONEYWELL | IPC | 15.04.97 | 3 15.05.07 | A09-3944-002 | S | | | 3A |
| 7021450-601 | 34-42-11 | Receiver Transmitter Antenna | HONEYWELL | CMM w. IPC | 15.04.97 | 3 15.05.07 | A09-3944-002 | S | | | 3A |
| 7021450-601/-801 | 34-42-12 | PRIMUS 660/880 Digital Weather Radar | HOL3NEYWELL | SDIM | 20.05.96 | 9 13.10.10 | D199605000036 | S | | A09-3944-001 | 3A |
| 7022360-901/-902 | 34-63-03 | CD-815 Control Display Unit | HONEYWELL | CMM w. IPC | 30.08.99 | 1 01.09.02 | A09-1147-081 | S | | | 3A |
| 7026201-8XX | 23-12-03 | Very High Frequency Data Radio Assembly | HONEYWELL | CMM w. IPC | 20.12.02 | 8 27.04.18 | A09-3829-002 | S | | | 3P |
| 7026240-90X | 23-05-04 | Mini Cabinet Assembly | HONEYWELL | CMM w. IPC | 20.12.02 | 3 24.08.11 | A09-3855-002 | S | | | 3P |
| 70290 | 38-10-37 | Faucet Assembly | ADAMS RITE | CMM w. IPC | 16.04.07 | 3 29.01.19 | VDN-0486 | S | | | 3A |
| 70428 Series | 38-10-61 | Electricla Box Assembly | ADAMS RITE | CMM w. IPC | 09.08.06 | 1 18.11.08 | VDN-0487 | S | | | 3A |
| 705000 | 29-12-02 | Hydraulic DC Standby Pump | TEST-FUCHS | CMM w. IPC | 19.09.16 | | 705000 | S | | | 3A |
| 717801-1 | 32-31-01 | Landing Gear Control Assembly | EATON | CMM w. IPC | 01.12.92 | A 01.07.95 | VDN-0081 | S | | | 3A |
| 717801-1 | 32-31-01 | LANDING GEAR CONTROL ASSEMBLY | SAFRAN | CMM w. IPC | 01.07.95 | 1 22.06.16 | VDN-0408 | S | | SAGEM | 3A |
| 72184002B | 25-33-40 | Water Heater DR40 Series | B/E AERO INVENTUM | CMM w. IPC | 01.07.91 | 17 03.06.16 | VDN-0285 | S | | B/E AERO | 3A |
| 74-20 | 26-24-05 | Halon 1/1,2/2,5 | TOTAL FEUERSCHUTZ | CMM w. IPC | 01.07.15 | | J 74/76-00 | S | | AIR TOTAL | 3A |
| 74-451-AC | 30-10-27 | Erosion Repair Kit | BFG ICE | AMR | 12.04.99 | 2 25.03.02 | VDN-0054 | O | | | 3P |
| 74-451-XX | 30-10-25 | De-Icer Patch Instructions | BFG ICE | INSTR.M | 17.10.97 | 16.05.02 | VDN-0053 | O | | | 3P |
| 7510100-8XX | 34-51-17 | RNZ-851 Integrated Navigation Unit | HONEYWELL | CMM w. IPC | 15.02.92 | 4 15.08.05 | A09-3800-030 | S | | | 3A |
| 7510114-811/901/855 | | Test Software Revision M for the DF-850/855 ADF Assembly | HONEYWELL | TB | 19.08.11 | | A45-3818-2463 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 7510114-855/7510300-901/2 | 34-51-26 | DF-855 ADF Module and AT-860 Antenna Assy | HONEYWELL | CMM w. IPC | 30.12.01 | 2 27.07.20 | A09-3800-036 | S | | | 3P |
| 7510300-901 | 34-51-14 | AT-860 ADF Antenna Vol. I | HONEYWELL | CMM w. IPC | 15.03.88 | 5 14.09.06 | A09-3800-012 | S | | Volume I | 3A |
| 7510300-901 | 34-51-14 | AT-860 ADF Antenna Vol. II | HONEYWELL | TR 1 | 11.12.07 | | A09-3800-012 | S | | Volume II | 3A |
| 7510300-901 | 34-51-14 | AT-860 ADF Antenna Vol. II | HONEYWELL | CMM w. IPC | 30.08.00 | 2 14.09.06 | A09-3800-012 | S | | Volume II | 3A |
| 7510600-801 | 34-52-05 | ML-850 MLS Receiver Vol. I | HONEYWELL | CMM w. IPC | 01.09.89 | 1 15.11.00 | A09-3800-014 | S | | Volume I | 3A |
| 7510600-801 | 34-52-05 | ML-850 MLS Receiver Vol. II | HONEYWELL | CMM w. IPC | 15.11.00 | | A09-3800-014 | S | | Volume II | 3A |
| 7510700-8XX | 23-81-01 | RCZ-8XX Integrated Comm.Unit | HONEYWELL | CMM w. IPC | 15.12.87 | 15 24.08.20 | A09-3800-015 | S | | | 3A |
| 7510733-6XX | 23-81-15 | Communication Unit ADS-B Assembly | HONEYWELL | CMM w. IPC | 02.05.12 | | D201110000060 | S | | | 3A |
| 7511001-912 | 23-81-08 | AV-850A Audio Panel | HONEYWELL | CMM w. IPC | 20.10.89 | 12 08.07.21 | A09-3800-021 | S | | Supersedes Vol. I - III | 3A |
| 7513000-802/ -836 | 23-81-07 | CD-850 Clearance Delivery Control Head | HONEYWELL | CMM w. IPC | 01.09.88 | 3 21.09.20 | A32-3800-002 | S | | | 3A |
| 7517900-10001/3 | 34-43-10 | TCAS 2000 | HONEYWELL | SDIM | 20.10.97 | 3 15.11.02 | A09-3841-001 | S | | ACSS-L3 | 3A |
| 7517900-10001/3 | 34-43-11 | TCAS 2000 Computer Unit Vol. II | HONEYWELL L3 | CMM w. IPC | 30.10.97 | 7 15.08.06 | A09-3841-002 | S | | ACSS-L3 | 3A |
| 7517900-10001/3 | 34-43-11 | TCAS 2000 Computer Unit Vol. III | HONEYWELL L3 | CMM w. IPC | 30.10.97 | 9 15.08.06 | A09-3841-002 | S | | ACSS-L3 | 3A |
| 7517900-10001/3 | 34-43-11 | TCAS 2000 Computer Unit Vol. I | HONEYWELL L3 | CMM w. IPC | 30.10.97 | 6 15.08.06 | A09-3841-002 | S | | ACSS-L3 | 3A |
| 7517900-10001/3 | 34-43-10 | TCAS 2000 | L3 ACSS | TR 4 | 15.12.09 | | A09-3841-001 | S | | ACSS-L3 | 3A |
| 7517900-10001/3 | 34-43-10 | TCAS 2000 | L3 ACSS | TR 3 | 03.12.09 | | A09-3841-001 | S | | ACSS-L3 | 3A |
| 7517900-10001/3 | 34-43-10 | TCAS 2000 | L3 ACSS | TR 6 | 15.07.11 | | A09-3841-001 | S | | ACSS-L3 | 3A |
| 76021 | | Baggage Net Freight Compartment | ALLSAFE | CMM w. IPC | 03.07.96 | F 18.01.18 | BST-639/96 | S | | | 3A |
| 779.407.925 | 23-30-03 | Tape Player | BECKER | MR | 01.09.90 | | DV 32001.04 | S | | | 3A |
| 785841-1 | 36-11-82 | Detection Box | INTERTECHNIQUE | CMM w. IPC | 15.01.96 | | VDN-0200 | S | | ZODIAC | 3P |
| 802-10-0010 | | SwiftBroadband Intermediate Gain Antenna IGA-5001 | CHELTON ANTENNAS | IM | 20.03.09 | 7 10.04.14 | 677-A0181_IM | S | | COBHAM | 3A |
| 811099-1/-3 | 73-21-74 | Drain Pressure Sensitivity Test | HAMILTON SUND | AI | 15.06.98 | | D3282-AI97166 | S | | IPC P&WC | 3A |
| 811099-X/3117036-0X | 73-21-74 | Fuel Control | HAMILTON SUND | CMM w. IPC | 15.12.85 | 8 12.09.18 | JFC118-15 | S | | IPC P&WC | 3P |
| 811180-X-0X,PWC3118888-0X | 73-21-71 | Electronic Engine Control EEC118-15 | HAMILTON SUND | CMM w. IPC | 01.12.92 | 13 29.07.17 | EEC118-15 | S | | IPC P&WC | 3P |
| 8160-121 | 24-35-32 | Starter Generator | THALES | CMM w. IPC | 01.06.92 | 3 26.04.22 | VDN-0027 | S | | AUXILEC (THALES) | 3A |
| 83900-1 | 36-11-09 | Pre-Cooler | ROGERSON | CMM w. IPC | 01.07.95 | | VDN-0225 | S | | | 3P |
| 8408/-1 | 27-22-03 | Yaw Trim Actuator | SAFRAN | CMM w. IPC | 31.01.94 | 5 09.11.11 | VDN-0035 | S | | SAGEM/AVIAC | 3A |
| 8409/-1/-2/-3 | 27-32-01 | Pitch Trim Actuator | AVIAC | CMM w. IPC | 31.12.94 | 7 09.11.11 | VDN-0034 | S | | SAGEM | 3A |
| 8410/-1 | 27-12-03 | Roll Trim Actuator | SAFRAN | CMM w. IPC | 30.12.94 | 6 29.04.11 | VDN-0033 | S | | AVIAC | 3A |
| 8428-1/-2/-3/-4 | 27-23-04 | Limiter Actuator | AVIAC | CMM w. IPC | 31.01.94 | 6 01.02.11 | VDN-0032 | S | | SAGEM | 3A |
| 8432-1 | 27-33-03 | Stick Pusher Actuator | SAGEM | CMM w. IPC | 15.03.94 | 6 08.04.19 | VDN-0031 | S | | AVIAC | 3A |
| 84400-3 | 30-13-01 | Check Valve | ROGERSON | CMM w. IPC | 01.07.95 | | VDN-0221 | S | | | 3A |
| 85000-5 | 30-13-10 | Pressure Switch | ROGERSON | CMM w. IPC | 01.07.95 | | VDN-0222 | S | | | 3P |
| 85100-3 | 30-13-06 | Ejector Flow Valve | ROGERSON | CMM w. IPC | 01.07.95 | | VDN-0223 | S | | | 3P |
| 854-301-925 | 23-30-03 | Tape Player | BECKER | CMM w. IPC | 15.01.93 | | VDN-0048 | S | | | 3A |
| 8554C000 | 21-51-12 | Dual Heat Exchanger | HONEYWELL NGL | CMM w. IPC | 27.06.92 | 8 19.01.04 | 2389 | S | | NGL | 3A |
| 8554C000 | 21-51-12 | Dual Heat Exchanger | NGL | MM | 08.05.92 | 2 10.04.95 | 2388 | O | | | 3A |
| 8555C000 | 21-51-13 | Condenser/Water Extractor | NGL | CMM w. IPC | 21.05.96 | 2 07.01.11 | 2390 | S | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 8563C000 | 21-51-13 | Condenser/Water Extractor | NGL | CMM w. IPC | 21.05.96 | 3 22.09.00 | 2512 | S | | | 3A |
| 8-700 | 31-41-00 | Proximity Sensor Electr. Unit | ELDEC | ITEM | 15.03.94 | | 011-2921-002 | O | | Now is CRANE | 3P |
| 8-700 | | Failure Indication - Quick Reference Guide | ELDEC | QRG | 16.10.00 | | QRG8-700 | S | | Now is CRANE | 3A |
| 8-700-04/-05 | 31-41-09 | Proximity Sensor Electronic Unit | CRANE | CMM w. IPC | 01.09.96 | 5 17.02.21 | 011-2910-616 | S | | was ELDEC | 3P |
| 87064/5XXX | 25-25-83 | Passenger Seat | B/E AERO BURNS | CMM w. IPC | 25.01.93 | | 25-25-083 | S | | | 3A |
| 87064/5XXX | 25-27-08 | Passenger Seat (ENGADINA) | B/E AERO BURNS | CMM w. IPC | 15.04.94 | | 25-27-008 | S | | ENGADINA | 3P |
| 87064/5XXX | 25-27-13 | Passenger Seat (AFRIMEX) | B/E AERO BURNS | CMM w. IPC | 15.04.94 | | 25-27-013 | S | | AFRIMEX | 3P |
| 87064/5XXX | 25-27-32 | Passenger Seat (ENGADINA II) | B/E AERO BURNS | CMM w. IPC | 03.02.95 | | VDN-0064 | S | | ENGADINA II | 3P |
| 87064XXX,87065XXX | 25-27-78 | JB6 SERIES COMMUTER CLASS PASSENGER SEATS FOR USAIR EXPRESS/DORNIER 328 AIRCRAFT | B/E AERO BURNS | TR 2.01 | 17.11.08 | | 25-27-078-2063 | S | | | 3A |
| 87064XXX,87065XXX | 25-27-78 | JB6 SERIES COMMUTER CLASS PASSENGER SEATS FOR USAIR EXPRESS/DORNIER 328 AIRCRAFT | B/E AERO BURNS | CMM w. IPC | 13.05.96 | 1 30.09.02 | 25-27-078-2063 | S | | | 3A |
| 87064XXX,87065XXX | 25-27-78 | JB6 SERIES COMMUTER CLASS PASSENGER SEATS FOR USAIR EXPRESS/DORNIER 328 AIRCRAFT | B/E AERO BURNS | TR 2.0 | 01.11.02 | | 25-27-078-2063 | S | | | 3A |
| 87064XXX,87065XXX | 25-27-78 | JB6 SERIES COMMUTER CLASS PASSENGER SEATS FOR USAIR EXPRESS/DORNIER 328 AIRCRAFT | B/E AERO BURNS | TR 2.02 | 14.04.16 | | 25-27-078-2063 | S | | | 3A |
| 8706XXXX | 25-40-48 | Passenger Seat (ACA) | B/E AERO BURNS | CMM w. IPC | 02.06.00 | | VDN-0042 | S | | ACA | 3A |
| 8706XXXX | 25-40-63 | Passenger Seat (OZARK) | B/E AERO BURNS | CMM w. IPC | 09.06.00 | | VDN-0043 | S | | OZARK | 3A |
| 8706XXXX | 25-40-57 | Passenger Seat (HAINAN) | B/E AERO BURNS | CMM w. IPC | 26.05.00 | | VDN-0063 | S | | HAINAN | 3A |
| 8718900X; 8719000X | 25-27-04 | Passenger Seat (HORIZON) | B/E AERO BURNS | CMM w. IPC | 08.04.94 | | VDN-0060 | S | | HORIZON | 3P |
| 8788XXXX | 25-41-51 | Passenger Seat (GROSSMANN) | B/E AERO BURNS | CMM w. IPC | 16.03.01 | | VDN-0086 | S | | GROSSMANN | 3A |
| 8788XXXX | 25-41-78 | Passenger Seat (PHILLIP MORRIS) | B/E AERO BURNS | CMM w. IPC | 03.08.01 | | VDN-0338 | S | | PHILLIP MORRIS | 3A |
| 8788XXXX | 25-40-59 | Passenger Seat (SKYWAYS) | B/E AERO BURNS | CMM w. IPC | 17.04.00 | | VDN-0339 | S | | SKYWAYS | 3A |
| 8788XXXX | 25-40-59 | Passenger Seat (SKYWAYS) | B/E AERO BURNS | TR 1.0 | 03.10.01 | | VDN-0339 | S | | SKYWAYS | 3A |
| 90002021 /-1, (2610485-1) | 32-46-37 | Nose Wheel Assy | ABSC | CMM w. IPC | 01.06.01 | 2 08.11.14 | AP-859 | S | | | 3P |
| 90002024 | 32-41-34 | Main Wheel Assy | ABSC | TR 32-4 | 03.01.07 | | AP-857 | S | | | 3P |
| 90002024 | 32-41-34 | Main Wheel Assy | ABSC | TR 32-2 | 26.10.04 | | AP-857 | S | | | 3P |
| 90002024 | 32-41-34 | Main Wheel Assy | ABSC | TR 32-3 | 08.03.06 | | AP-857 | S | | | 3P |
| 90002024 | 32-41-34 | Main Wheel Assy | ABSC | CMM w. IPC | 01.06.01 | 1 15.10.03 | AP-857 | S | | P/N 2610701-2 (HALS part) Superseded by P/N 90002024-1 (ABSC now MEGGITT) | 3P |
| 90002030 | 32-44-26 | Brake Assy | MABS | CMM w. IPC | 01.06.01 | 2 12.06.08 | AP-858 | S | | ABSC | 3P |
| 912V0201 | 21-34-02 | Manual Controller | LIEBHERR | CMM w. IPC | 01.09.92 | 3 24.11.08 | VDN-0134 | S | | ABG-SEMCA | 3P |
| 92105A010100 | 21-34-06 | Manual Indicator Module | LIEBHERR | CMM w. IPC | 02.11.92 | 1 04.03.98 | VDN-0124 | S | | ABG-SEMCA | 3A |
| 9-231-29 | 73-35-31 | Fuel Flow Transmitter | ELDEC | CMM w. IPC | 15.05.92 | 2 23.10.17 | 011-4910-702 | S | | Now is CRANE | 3P |
| 93A055-XX | 23-70-01 | CVR MIC Modules | L3 AVIATION RECORDER | CMM w. IPC | 01.05.91 | 3 01.03.04 | 165E0101-00 | S | | Model A55X | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 93A055-XX / 93A151-XX | 23-70-02 | SOLID–STATE COCKPIT VOICE RECORDER (SSCVR) | L3 AVIATION RECORDER | CMM w. IPC | 01.02.93 | 3 | 01.07.05 | 165E0948-00 | S | | Model A55X / Model A15X | 3P |
| 93A100-XX | 23-70-01 | Cockpit Voice Recorder | L3 AVIATION RECORDER | CMM w. IPC | 01.05.91 | 3 | 01.03.04 | 165E0101-00 | S | | Model A100X | 3P |
| 93A151-XX | 23-70-01 | CVR Control Units | L3 AVIATION RECORDER | CMM w. IPC | 01.05.91 | 3 | 01.03.04 | 165E0101-00 | S | | Model A15X | 3P |
| 93AXXXXX | | Cockpit Voice Recorder | L3 AVIATION RECORDER | IOIM | | 2 | 01.07.02 | 165E2807-00 | S | | Supersedes FAR02213189 | 3A |
| 947 | 24-35-34 | Ground Power Protection Unit | AUXILEC | CMM w. IPC | 15.08.92 | | | VDN-0024 | S | | THALES | 3A |
| 95218-Series | 71-20-34 | Engine Vibration Isolation System | BARRY CONTROLS | CMM w. IPC | 01.08.92 | 4 | 15.07.04 | VDN-0047 | S | | | 3P |
| 964-0465-001 | 23-20-33 | Airplane Personality Module | HONEYWELL | CMM w. IPC | 31.10.02 | | | 012-0733-001 | S | | | 3P |
| 965-0676-021 | 34-45-30 | Ground Proximity Warning Computer | ALLIEDSIGNAL | CMM w. IPC | 17.07.91 | 10 | 27.01.06 | 012-0618-001 | S | | HONEYWELL | 3P |
| 965-0676-021 | 34-45-30 | Ground Proximity Warning Computer | ALLIEDSIGNAL | TR 34-14 | 27.10.06 | | | 012-0618-001 | S | | HONEYWELL | 3P |
| 965-0676-021 | 34-45-30 | Ground Proximity Warning Computer | ALLIEDSIGNAL | TR 34-15 | 13.12.06 | | | 012-0618-001 | S | | HONEYWELL | 3P |
| 965-0676-021 | 34-45-30 | Ground Proximity Warning Computer | ALLIEDSIGNAL | TR 34-16 | 22.01.07 | | | 012-0618-001 | S | | | 3P |
| 965-0758-00X | 23-20-13 | Communications Management Unit (MK II) | HONEYWELL | CMM w. IPC | 21.02.97 | 14 | 15.05.20 | 012-0690-001 | S | | | 3P |
| 965-0976-0XX | | MK V Enhanced Ground Proximity Warning System<br>Enhanced Ground Proximity Warning System | ALLIEDSIGNAL | IDG | 01.10.99 | | | 060-4199-125 | S | | HONEYWELL | 3A |
| 965-1180-/-1190-020 | 34-45-40 | Enhanced Ground Proximity Warning System EGPWS | HONEYWELL ASIG | CMM w. IPC | 09.05.00 | 19 | 21.09.06 | 012-0709-001 | S | | | 3P |
| 9696 Series | 38-12-34 | Faucet Assembly | ADAMS RITE | CMM w. IPC | 15.10.03 | | | VDN-0489 | S | | | 3A |
| 9776-15-1 | 38-20-09 | Hands Free Electronic Faucet Assy | ADAMS RITE | CMM w. IPC | 30.12.91 | 1 | 22.12.97 | 9776 | S | | | 3P |
| 980-4700-XXX | 31-30-40 | FA2100CVR Solid State Flight Data Recorder | HONEYWELL ASIG | CMM w. IPC | 01.12.92 | 27 | 18.05.11 | 012-0650-001 | S | | ALLIEDSIGNAL | 3P |
| 980-6020-001 | 23-70-44 | Solid State Cockpit Voice Recorder | HONEYWELL ASIG | CMM w. IPC | 31.01.94 | 19 | 01.12.11 | 012-0667-001 | S | | ALLIEDSIGNAL | 3P |
| 980-6113-001 | 23-70-41 | Remote Microphone | HONEYWELL ASIG | CMM w. IPC | 10.03.89 | 3 | 14.04.98 | 012-0552-001 | S | | ALLIEDSIGNAL | 3P |
| 980-6113-001 | 23-70-41 | Remote Microphone | HONEYWELL ASIG | TR 23-01 | 01.05.00 | | | 012-0552-001 | S | | ALLIEDSIGNAL | 3P |
| 980-6113-001 | 23-70-41 | Remote Microphone | HONEYWELL ASIG | TR 23-02 | 21.08.00 | | | 012-0552-001 | S | | ALLIEDSIGNAL | 3P |
| 980-6117-005 | 23-70-43 | Microphone Monitor | ALLIEDSIGNAL | CMM w. IPC | 15.09.93 | 7 | 23.08.02 | 012-0666-001 | S | | HONEYWELL | 3P |
| 996-5106-XXX | | Equalizer-MH/C - Digital Audio Equalizer | HONEYWELL | MM | 02.12.03 | A | 19.02.04 | 763-1014-001 | S | | | 3P |
| A06 - Series | 24-09-02 | Actuator Assembly | GKN WESTL.SITEC | CMM w. IPC | 01.08.91 | 6 | 21.12.18 | A06000-07 | S | | | 3A |
| A-5651 | 61-20-02 | Overspeed Governor Assy | HARTZELL | CMM w. IPC | 30.06.93 | 1 | 15.01.97 | WG 60062 | S | | WOODWARD | 3P |
| A-5656 | 61-20-01 | Gear Pump Assy | HARTZELL | CMM w. IPC | 30.06.93 | 2 | 14.11.07 | WG 60063 | S | | WOODWARD | 3P |
| A-5659-2 | 61-20-03 | Constant Speed Propeller Governor | HARTZELL | CMM w. IPC | 31.08.93 | 3 | 19.08.03 | WG 60064 | S | | WOODWARD | 3P |
| AA-02-A | 25-34-68 | Coffee Maker | IACOBUCCI | CMM w. IPC | 22.05.00 | | | 1683 | S | | | 3A |
| AA-8 | 25-34-70 | Water Tank | IACOBUCCI | CMM w. IPC | 21.09.00 | | | 1738 | S | | | 3A |
| AC69895/69963 | 32-42-03 | Brake Metering Unit | DUNLOP | CMM w. IPC | 31.03.99 | | | VDN-0315 | S | | | 3P |
| AC69965, AC69965-2/-3 | 32-43-02 | Emergency/Park Brake Valve | MABS | CMM w. IPC | 31.10.97 | 8 | 12.03.15 | AP-2113 | S | | | 3P |
| AC70071 | 32-42-04 | Brake Metering Unit | MABS | CMM w. IPC | 15.06.01 | 4 | 12.03.15 | AP-2082 | S | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| ACM30488 | 32-43-31 | Aircraft Applicability | DUNLOP | AEM | 27.06.94 | | DM1443-47 | O | | | 3P |
| ACM30488 | 32-43-31 | Hydraulic Fuse | MABS | CMM w. IPC | 20.04.93 | 6 12.03.15 | AP-2122 | S | | | 3P |
| ACM30492 | 32-43-30 | Master Cylinder | MABS | CMM w. IPC | 25.02.93 | 2 18.04.13 | AP-2121 | S | | | 3P |
| ACM30496/30662 | 32-43-32 | Wheel Speed Transducer Installation | MABS | CMM w. IPC | 22.10.92 | 6 12.03.15 | AP-2123 | S | | | 3P |
| AE20462 | | Anti - Skid Test Set | DUNLOP | GEM | 15.04.93 | | DM1636-00 | S | | | 3A |
| AE20462 | | Interface for Anti - Skid Test Set | DUNLOP | GEM | 15.04.93 | | DM1636-01 | S | | | 3A |
| AE20464 / AE20768 | 32-43-36 | Anti-Skid Control Unit | MABS | CMM w. IPC | 09.10.92 | 4 12.03.15 | AP-2124 | S | | | 3P |
| AE20824 | 32-43-46 | Anti-Skid Conrol Unit | MABS | CMM w. IPC | 31.01.99 | 4 12.03.15 | AP-2129 | S | | | 3P |
| AL-EX15-200E-1 | 25-34-20 | Configuration for the AL-EX15-200E Espresso Coffee Maker | AEROLUX | CMM w. IPC | 30.01.00 | 2 30.10.04 | VDN-0464 | S | | Superseded by 25-34-02 | 3A |
| AL-EX15-200E-1 | 25-34-02 | AL-EX15-200E-1 Espresso Coffee Maker | AEROLUX | CMM w. IPC | 30.01.10 | 1 30.08.10 | VDN-0493 | S | | | 3A |
| AL-EX15-200E-1 | 25-34-02 | PCB Test Procedures | AEROLUX | TR25-34-02-01 | 30.03.10 | | VDN-0494 | S | | | 3A |
| AL-EX15-200E-1 | 25-34-02 | Proof Pressure Test | AEROLUX | TR25-34-02-02 | 15.11.11 | | VDN-0495 | S | | | 3A |
| AL-EX15-200E-1 | 25-34-02 | New Parts Catalogue | AEROLUX | TR25-34-02-04 | 12.02.13 | | VDN-0496 | S | | | 3A |
| AL-EX15-200E-1 | 25-34-02 | New Parts Catallog | AEROLUX | TR25-34-02-03 | 06.09.12 | | VDN-0497 | S | | | 3A |
| AL-RA15-001 | 25-34-00 | Rail Assembly | AEROLUX | CMM w. IPC | 30.03.97 | 3 30.04.04 | VDN-0465 | S | | | 3A |
| AR2518 | 52-50-11 | Latch Assembly | ADAMS RITE | CMM w. IPC | 16.11.70 | 2 05.07.07 | AR2518 | S | | | 3A |
| AR9592-X/9608-X | 38-30-06 | DRAIN VALVE ASSEMBLY | ADAMS RITE | CMM w. IPC | 20.05.14 | 3 25.10.16 | VDN-0488 | S | | | 3A |
| AR9874-3 + AR9877 Series | | Installation AR9874-3 + AR9877 Series Water System | ADAMS RITE | OM | 04.04.03 | 1 14.05.08 | AR9895-38-01 | S | | | 3A |
| AT6421R1 | 31-20-00 | Digital Chronometer Model LC-60 | ASTROTECH | CMM w. IPC | 16.11.95 | 0 17.11.99 | VDN-0019 | S | | TRANSICOIL | 3A |
| B14000 | 28-29-14 | Fuel Shut - Off Valve | GKN WESTL.SITEC | CMM w. IPC | 01.09.92 | | VDN-0095 | S | | | 3A |
| B49 - Series | 28-10-03 | Fuel Drain Valve Assy | GKN WESTL.SITEC | CMS | 01.09.92 | | VDN-0050 | S | | | 3A |
| BA21741GR-2 | 26-20-29 | Hand Fire Extinguisher 1,2kg BCF | FIRE FIGHTING ENTERP | CMM w. IPC | 01.11.92 | 6 01.01.19 | VDN-0180 | S | | PERCIVAL | 3A |
| BA23177-1 | 26-25-12 | Automatic Fire Extinguisher 0,12kg | FIRE FIGHTING ENTERP | CMM w. IPC | 01.03.93 | 8 01.01.19 | VDN-0181 | S | | PERCIVAL | 3A |
| BA24320D-1 | 26-25-36 | 0.12kg AUTO EUTECTIC FIRE EXTINGUISHER | FIRE FIGHTING ENTERP | CMM w. IPC | 01.10.02 | 8 01.03.17 | VDN-0554 | S | | PERCIVAL | 3A |
| C-5184 | 61-21-16 | Hydraulic and Electrical Motor Assy | AERO CONTROLEX | CMM w. IPC | 15.05.97 | 3 12.08.02 | 4122-006005 | S | | | 3P |
| CA-01 | 25-34-69 | Rail | IACOBUCCI | CMM w. IPC | 14.09.00 | | 1739 | S | | | 3A |
| CG1042AB04 | 34-26-15 | Mode Select Unit | HONEYWELL | CMM w. IPC | 20.11.87 | 7 18.07.08 | M15-3349-006 | S | | | 3A |
| DC24/50/1 | | Operating Instruction for Mini.Vacuum Pump | FUERGUT | OI | 26.08.02 | | VDN-0421 | O | | | 3A |
| DLH 105-210 | 25-38-26 | Hot Jug | DRIESSEN | CMM w. IPC | 05.12.97 | D 29.06.10 | VDN-0272 | S | | | 3A |
| DLH 105-210 | 25-38-26 | Hot Jug | DRIESSEN | IPC | 14.08.96 | D 29.06.10 | VDN-0272 | S | | | 3A |
| DLH 105-211 | 25-38-66 | Hot Jug | DRIESSEN | IPC | 06.07.98 | A 05.03.04 | VDN-0273 | S | | | 3P |
| DLH 105-211 | 25-38-66 | Hot Jug | DRIESSEN | CMM w. IPC | 06.07.98 | A 05.03.04 | VDN-0273 | S | | | 3P |
| DLH 1085-017 | 25-32-31 | Meal Trolley Assy | DRIESSEN | IPC | 09.08.89 | A 16.01.04 | VDN-0268 | S | | | 3A |
| DLH 1085-017 | 25-32-31 | Meal Trolley Assy | DRIESSEN | CMM w. IPC | 09.08.89 | A 16.01.04 | VDN-0268 | S | | | 3A |
| DLH 294 | 25-36-10 | Atlas Container | DRIESSEN | CMM w. IPC | 03.04.96 | E 17.06.14 | VDN-0270 | S | | | 3A |
| DLH 294 | 25-36-10 | Atlas Container | DRIESSEN | IPC | 03.04.96 | F 17.06.14 | VDN-0610 | S | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| DLH 3072 | 25-37-63 | Bar Trolley Assy | DRIESSEN | IPC | 09.03.94 | A 29.08.03 | VDN-0443 | S | | | 3P |
| DLH 3072 | 25-37-63 | Bar Trolley Assy | DRIESSEN | CMM w. IPC | 09.03.94 | B 17.03.05 | VDN-0443 | S | | | 3P |
| DP3113 (A) | | Crewmember Protective Breathing Equipment (PBE) | ESSEX | GUIDE | | 24 24.02.17 | PRM-01 | O | | | 3A |
| DTSP-400L | 24-34-00 | Aircraft Batteries | | OMM | 23.06.97 | 11 09.11.12 | VDN-0455 | S | | | 3A |
| DTSP-400L | 24-34-00 | Nickel-Cadmium Aircraft Batteries | MARATHON | OMM | 23.06.97 | 18 17.06.20 | DCR60741 | S | | | 3A |
| ELT96/97 | 25-61-02 | ELT96/ELT97 User's Manual | AIR PRECISION | USER M | 01.04.01 | 4 01.10.07 | VDN-0453 | S | | Repl. single manual of ELT96 & 97 | 3A |
| ELT96/97A2560000000 | 25-61-02 | Emergency Locator Transmitter ELT 96/97 | AIR PRECISION | CMM w. IPC | 01.05.97 | 10 01.09.16 | VDN-0275 | S | | SOCATA | 3A |
| ELT96/97A2560000000 | 25-61-02 | ELT 96 / 97 Installation Manual | AIR PRECISION | INSTAL. M | 01.04.01 | 8 01.04.15 | VDN-0442 | O | | SOCATA | 3A |
| F20/40 / F20/27 H1CT70 | | Aircraft Battery | HAWKER | OVMM | 01.01.01 | | VDN-0325 | S | | | 3A |
| FE211-002/-003/-004/-005 | 27-20-01 | Rudder Pedals Assembly | RATIER FIGEAC | CMM w. IPC | 20.12.91 | 1 03.06.96 | VDN-0211 | S | | | 3P |
| FE217-004 | 27-70-05 | Rudder Damper Assembly | RATIER FIGEAC | CMM w. IPC | 25.03.92 | 4 28.02.03 | VDN-0212 | S | | | 3P |
| FE255-000/-001 | 27-70-06 | Rudder Damper Assembly | RATIER FIGEAC | CMM w. IPC | 15.01.96 | 4 02.06.20 | VDN-0210 | S | | | 3A |
| FE309000000 | 27-20-03 | Rudder Pedals Assembly | RATIER FIGEAC | CMM w. IPC | 15.06.98 | 2 16.02.21 | VDN-0230 | S | | | 3A |
| FMZ Series | | Flight Management System Vers.4.1 | HONEYWELL | PM | 01.07.96 | | A28-1146-113 | O | | | 3P |
| FMZ Series | | Flight Management System Vers.4.8 | HONEYWELL | PM | 01.08.97 | 1 01.01.00 | A28-1146-122 | O | | | 3P |
| G7228-01 | | Data Loader 1000 | HONEYWELL | IM | 30.06.09 | | IST.G7228-01 | S | | GABLES | 3A |
| G7228-01/-02 | 34-60-04 | Data Loader Model No. DL-1000 | HONEYWELL | CMM w. IPC | 01.03.10 | | VDN-0010 | S | | GABLES | 3A |
| G7830-() | | Control Display Unit CD-830 | HONEYWELL | IM | 09.12.14 | 3 05.06.15 | IST.G7830-() | S | | GABLES | 3A |
| G7830-02/-03 | 34-62-01 | Control Display Unit CD-830 | HONEYWELL | CMM w. IPC | 02.10.15 | | VDN-0011 | S | | GABLES | 3A |
| GB2001AA1 | 21-51-24 | Check Valve | TECHNOFAN | CMM w. IPC | 01.09.00 | 1 01.01.01 | VDN-0244 | S | | | 3A |
| GC204/5(-) | 25-20-04 | Aircraft Oven Types | IPECO | CMM w. IPC | 26.07.98 | 3 23.09.02 | VDN-0429 | S | | Supersedes 25-20-01 | 3A |
| GC205CR | 25-20-17 | Aircraft Oven Types | IPECO | CMM w. IPC | 30.07.99 | 13 24.11.22 | VDN-0331 | S | | AMC INDUSTRIES | 3A |
| H019 Series | 76-10-01 | Adjustable Cam Switch Assembly | GKN WESTL.SITEC | CMM w. IPC | 01.01.00 | | VDN-0096 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-034 | 01.06.13 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-039 | 01.11.20 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-030 | 01.05.11 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | MM | 01.08.93 | 26 01.10.06 | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-032 | 01.08.11 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-038 | 01.04.18 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-027 | 01.12.06 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-031 | 01.08.11 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-033 | 01.04.12 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-029 | 01.12.07 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-035 | 01.07.15 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-10-61 | Propeller Assembly | HARTZELL | TR-036 | 01.01.17 | | 161 | S | | | 3P |
| HD-E6C-3( )( ) | 61-20-62 | Propeller Control Unit | HARTZELL | MM | 01.08.93 | 15 01.01.19 | 162 | S | | | 3P |
| HD-E6C-3XX-XX | 61-02-59 | Application Guide | HARTZELL | AG | 01.07.02 | 82 01.11.22 | 159 | O | | | 3P |
| HFE96-28 | 25-34-52 | Coffee Maker | IACOBUCCI | CMM w. IPC | 31.12.97 | B 01.09.08 | 1713 | S | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| HFE96-28 | 25-34-52 | Operating Instructions for the HFE96-28 Coffe Maker | IACOBUCCI | OI | 31.12.97 | | VDN-0470 | O | | | 3A |
| HG2001 GD03/GD20/GD40 | | HOLDERS OF THE HG2001GD03/GD20/GD40 INERTIAL REFERENCE UNIT PILOT'S GUIDE | HONEYWELL | PM | 01.09.98 | 1 01.08.10 | M28-3343-003 | O | | | 3P |
| HG2001AC02 | 34-26-18 | Inertial Reference Unit | HONEYWELL | CMM w. IPC | 15.06.95 | 3 14.01.00 | M15-3343-012 | S | | | 3A |
| HG2001AC02 | 34-26-18 | Inertial Reference Unit | HONEYWELL | TR 6 | 07.05.02 | | M15-3343-012 | S | | | 3A |
| HG2001AC02 | 34-26-18 | Inertial Reference Unit | HONEYWELL | TR 4 | 15.03.00 | | M15-3343-012 | S | | | 3A |
| HG2010AC02, AC01, AC03 | 34-26-14 | Attitude Heading Reference Unit | HONEYWELL | CMM w. IPC | 15.09.95 | 1 17.06.14 | M15-3324-002 | S | | | 3A |
| HG2012GB, HG2021GD | 34-58-04 | Global Navigation Satellite Sensor Unit | HONEYWELL | TR 34-2 | 13.08.15 | | M15-3819-003 | S | | | 3A |
| HG2021GB01/HG2021GDXX | 34-58-04 | Global Navigation Satellite Sensor Unit | HONEYWELL | CMM w. IPC | 15.07.94 | 4 27.04.11 | M15-3819-003 | S | | | 3A |
| HG2021GD04 | | Global Navigation System Sensor Unit | HONEYWELL | SIM | 21.11.08 | | D200809000030 | S | | Esterline (CMC Electronics) | 3A |
| HP1594100-1 | 29-20-01 | Dual Stage Hydraulic Hand Pump | TACTAIR | CMM w. IPC | 15.12.95 | | VDN-0243 | S | | | 3P |
| HP848800 | 32-30-02 | Landing Gear Control Valve | TACTAIR | TR 32-01 | 24.04.13 | | VDN-0242 | S | | | 3A |
| HP848800-4 | 32-30-02 | Landing Gear Control Valve | TACTAIR | CMM w. IPC | 01.08.95 | | VDN-0242 | S | | | 3A |
| Index Pub. | | History of the CMM | MESSIER-DOWTY | CMM w. IPC | 15.04.97 | 6 01.07.13 | 20269 | S | | | 3A |
| JA010001 | 25-35-36 | Hot Jug | DRIESSEN | CMM w. IPC | 26.06.95 | E 31.01.12 | VDN-0269 | S | | | 3P |
| JA010001 | 25-35-36 | Hot Jug | DRIESSEN | IPC | 26.06.95 | F 31.01.12 | VDN-0600 | S | | | 3P |
| K9321060A04, K9321062A01 | | DU-875 Display Unit | BARCO | CMM w. IPC | 15.12.09 | | K5920116-02 | S | | | 3A |
| K97-63-603P2 | 28-19-87 | Refuelling Adapter | INTERTECHNIQUE | CMM w. IPC | 15.04.92 | 2 01.10.94 | VDN-0119 | S | | ZENITH-AVIATION | 3A |
| L94E31-651 | 28-19-86 | Re- and Defuelling Valve | INTERTECHNIQUE | CMM w. IPC | 15.04.92 | 2 16.07.12 | VDN-0115 | S | | ZENITH-AVIATION | 3A |
| L98B621/-2/-6/-7 | 28-41-14 | Fuel Level Indicator | INTERTECHNIQUE | CMM w. IPC | 15.04.92 | 1 01.10.94 | VDN-0201 | S | | ZENITH-AVIATION | 3A |
| Model RH0802 | | Hydraulic Axle Jack Mod. RH0802 | HYDRO | TH | 01.09.99 | | VDN-0114 | O | | | 3A |
| Model SG103 | | Hydraulic Axle Jack Mod. SG103 | HYDRO | TH | 01.03.00 | | VDN-0113 | O | | | 3A |
| P01074-1XX | 25-60-30 | XF-35 LIFE PRESERVER | EAM | CMM | 12.02.16 | | XF-35 | S | | | 3A |
| P01400-2XX | 25-60-58 | AIC-35 LIFE PRESERVER | EAM | CMM | 15.09.15 | | AIC-35 | S | | | 3A |
| P0640-103 | 25-60-15 | Infant Life Preserver | EAM | CMM w. IPC | 20.03.87 | 9 23.05.13 | IN-V20L8 | S | | | 3A |
| P0723E105P-VARIANT | 25-60-12 | Adult/Child Life Preserver | EAM | CMM w. IPC | 26.04.88 | 10 14.12.11 | KSE-35L8 | S | | | 3A |
| PC125 | 24-20-02 | 125 VA Static Inverter | MARATHON | CMM w. IPC | 01.08.78 | 2 02.08.95 | VDN-0141 | S | | | 3P |
| PC251 | 24-20-07 | 250 VA Static Inverter | MARATHON | CMM w. IPC | 01.07.81 | 2 26.09.89 | VDN-0142 | S | | | 3A |
| PC251() Series | 24-20-32 | 300 VA Static Inverter | Avionic Instruments | CMM w. IPC | 30.04.95 | 2 14.09.07 | VDN-0642 | S | | | 3A |
| PVP 5055-00 | | Pump Valve Panel Assy | TEST-FUCHS | OI | 31.01.08 | 2 21.02.08 | VR 1013 | S | | | 3A |
| QA07376-01 / QA07770 | 29-10-76 | Pressure Sensing Valve | PALL | CMM w. IPC | 31.01.95 | 2 14.01.20 | VDN-0199 | S | | | 3P |
| QA07390 / QA07704 | 29-11-07 | Main Filter Package | PALL | CMM w. IPC | 31.01.95 | 3 12.12.16 | VDN-0006 | S | | | 3P |
| QA07770 | 29-10-78 | Pressure Sensing Valve | PALL | CMM w. IPC | 09.07.14 | | VDN-0498 | S | | | 3A |
| QAR2XX-XX-XX | 31-30-20 | microQAR (Quick ACCESS RECORDER) | L3 AVIATION RECORDER | CMM w. OIM | 31.03.03 | 7 01.02.11 | 165E2810-0 | S | | L3 | 3A |
| QB0470 | 21-02-70 | Filter Element | PALL | CMS | 27.05.94 | | VDN-0177 | S | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./DATE | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| QB0471 | 21-02-71 | Filter Element | PALL | CMS | 27.05.94 | | VDN-0176 | S | | | 3A |
| R0101A( ) | 25-60-17 | EAM-T4 LIFE RAFT | EAM | CMM | 01.09.11 | 8 01.05.14 | VDN-0570 | O | | | 3A |
| S00-0003-() | | A200S Solid State Cockpit Voice Recorder - Notification of Obsolescense | L3 AVIATION RECORDER | SIL | 20.07.06 | 1 23.08.06 | A200S SCVR 003 | O | | Model A200S | 3A |
| S100-0080-00 | 23-70-02 | FA2100CVR Solid State Cockpit Voice Recorder | L3 AVIATION RECORDER | CMM w. IPC | 01.02.93 | 3 01.07.05 | 165E0948-00 | S | | Model A100S | 3P |
| S151-0060-00 | 23-70-05 | ED-56A Control Unit, Preamplifier Module and Microphone Module | L3 AVIATION RECORDER | CMM w. IPC | 01.09.00 | 9 06.05.14 | 165E0101-00 | S | | | 3P |
| S200-0003-00/0003/90/12 | | Model A200S Solid State Cockpit Voice Recorder System | L3 AVIATION RECORDER | IOIM | 19.09.94 | 4 01.02.03 | 165E2685-00 | S | | | 3P |
| S200-0012-00 | 23-70-03 | A200S Solid State Cockpit Voice Recorder | L3 COMMUNICATIONS | CMM w. IPC | 15.02.96 | 5 01.03.05 | 165E1233-00 | S | | Model A200S | 3P |
| S4-3402000-1 | 32-43-02 | Emergency Park / Brake Valve | FWM | CMM w. IPC | 20.07.92 | 1 29.04.93 | VDN-0138 | S | | | 3P |
| S800-2000/3000-00 | 31-30-02 | FA2100CVR Solid State Flight Data Recorder | L3 AVIATION RECORDER | CMM w. IPC | 01.08.91 | 5 01.03.04 | 165E0503-00 | S | | Model F1000 | 3P |
| SD9422-01 | 26-15-01 | Ambient Smoke Detector | AOA | CMM w. IPC | 05.02.92 | 1 20.12.99 | VDN-0015 | S | | | 3A |
| SD9470-22 | 26-15-02 | Smoke Detector | AOA | CMM w. IPC | 20.12.99 | 2 05.05.04 | VDN-0014 | S | | | 3A |
| SPSDO328-1/2-X-X | 56-11-81 | Front Windshield LH/RH | SULLY | CMM w. IPC | 01.01.95 | 1 01.02.01 | VDN-0241 | S | | SPS.Do328.211 | 3A |
| SRZ-85X | | PRIMUS II SRZ-85X Integr.Radio Syst. | HONEYWELL | OIM | 10.10.87 | 16 27.07.20 | D198710000004 | O | | Supersedes A15-3800-001 | 3A |
| Suppl.for PG C28-3841-005 | | Traffic Collision Avoidance System 2000 | HONEYWELL L3 | SUPPL | 01.05.00 | 1 01.08.00 | C28-3841-006 | O | | ACCS-L3 | 3A |
| TB001016 | 25-37-63 | Atlas Trolley Assy | DRIESSEN | CMM w. IPC | 11.05.98 | | VDN-0271 | S | | | 3A |
| VD3870 | | Mixed Flow Fan | AOA | CMM w. IPC | 15.01.91 | 3 21.10.91 | VD3870 | S | | | 3A |
| WL1001KCA1 | 34-25-21 | Standby Compasses | SIRS NAVIGATION | CMM w. IPC | 10.04.03 | 11 | VDN-0431 | S | | former Smiths Ind. Aero | 3A |
| WL101AMS1 | 34-11-41 | Altimeter/Airspeed Indicator | ONTIC | CMM w. IPC | 20.11.01 | 4 02.09.16 | VDN-0420 | S | | was GE Aviation | 3A |
| WT228 | 31-50-01 | Warning/Caution Panel | AOA | CMM w. IPC | 01.03.86 | 6 09.11.98 | WT228 | S | | | 3A |
| ZCV193-4 | 27-60-06 | Valve-Double Shuttle | CIRCLE SEAL | CMM w. IPC | 17.08.94 | | ZTP-220 | S | | ZEVCO | 3P |

# CHAPTER 3

# SERVICE PUBLICATIONS

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Effect of De-/Anti-icing Fluids on Take off | 328 SSG | AOT-328-00-022 | 05.12.02 | 1 07.11.03 | AOT-328-X | S | | | 3P |
| | | Red.of Lift during T/O due to Ice on Wing | 328 SSG | AOT-328-00-023 | 24.01.06 | | AOT-328-X | S | | | 3P |
| | | Fail indicat.from Bus Power Contr.Unit | 328 SSG | AOT-328-24-006 | 14.06.94 | 2 05.07.94 | AOT-328-X | S | | | 3P |
| | | Flaps forced move down | 328 SSG | AOT-328-27-016 | 31.07.98 | 1 28.10.98 | AOT-328-X | S | | | 3P |
| | | IPC error - Poss.wrong inst.lever | 328 SSG | AOT-328-27-017 | 21.07.01 | | AOT-328-X | S | | | 3P |
| | | CAS message caused by check valve | 328 SSG | AOT-328-28-014 | 26.08.96 | 1 16.10.96 | AOT-328-X | S | | | 3P |
| | | AC Pump failure Mod. 10/20 | 328 SSG | AOT-328-29-018 | 20.09.01 | | AOT-328-X | S | | | 3P |
| | | AC Pump failure Mod. 30 | 328 SSG | AOT-328-29-019 | 20.09.01 | | AOT-328-X | S | | | 3P |
| | | Deice malefunct.with FLAPS 0° a.FLAPS12° | 328 SSG | AOT-328-30-011 | 24.01.96 | | AOT-328-X | S | | | 3P |
| | | Delimination of Wing De-Icer Boot | 328 SSG | AOT-328-30-013 | 04.04.96 | 1 19.04.96 | AOT-328-X | S | | | 3P |
| | | Mailfunct. Landing Gear Extension | 328 SSG | AOT-328-32-002 | 11.05.94 | | AOT-328-X | S | | | 3P |
| | | Suspension of European RVSM Operations | 328 SSG | AOT-328-34-021 | 11.09.02 | | AOT-328-X | S | | | 3P |
| | | Navigation - Potential interference from 5G ground stations that might impair the reliable functioning of radio altimeters | 328 SSG | AOT-328-34-024 | 21.12.21 | | AOT-328-X | S | | | 3P |
| | | All Aircraft with APU under FAA | 328 SSG | AOT-328-49-008 | 23.06.95 | | AOT-328-X | S | | | 3P |
| | | All Aircraft with APU under JAA | 328 SSG | AOT-328-49-009 | 23.06.95 | | AOT-328-X | S | | | 3P |
| | | Stabil.Leading Edges-Laminates Defect | 328 SSG | AOT-328-55-007 | 28.04.95 | 1 07.06.95 | AOT-328-X | S | | | 3P |
| | | Rudd.Spring Tabs-Impr. Balance after Paint. | 328 SSG | AOT-328-55-015 | 06.04.98 | 1 07.04.98 | AOT-328-X | S | | | 3P |
| | | Windsh.-Slight Spre-Dam.to outer face ply | 328 SSG | AOT-328-56-012 | 07.03.96 | | AOT-328-X | S | | | 3P |
| | | Propeller-Feathered/free to rotate | 328 SSG | AOT-328-61-001 | 04.03.94 | 1 15.03.94 | AOT-328-X | S | | | 3P |
| | | Unlocked transfer tube after test flight | 328 SSG | AOT-328-61-003 | 17.03.94 | 1 19.03.94 | AOT-328-X | S | | | 3P |
| | | Complied ASB A193/ASB A195 | 328 SSG | AOT-328-61-004 | 05.04.94 | | AOT-328-X | S | | | 3P |
| | | Propeller pitch lock occur during approach | 328 SSG | AOT-328-61-005 | 26.05.94 | | AOT-328-X | S | | | 3P |
| | | Occurences of a fixed pitch propeller | 328 SSG | AOT-328-61-010 | 28.09.95 | | AOT-328-X | S | | | 3P |
| | | Inspection of Control Cables | 328 SSG | ASB-328-00-011 | 04.12.95 | 2 01.08.00 | ASB-328-X | S | | | 3P |
| | | Electr.Power-Bus Power Conrol Uni | 328 SSG | ASB-328-24-005 | 08.02.95 | 1 | ASB-328-X | S | | | 3P |
| | | Inspect. of the DC Power Unit 1VE | 328 SSG | ASB-328-24-018 | 05.08.97 | | ASB-328-X | S | | | 3P |
| | | Inspection and Mod. DC Power Unit | 328 SSG | ASB-328-24-021 | 25.11.97 | | ASB-328-X | S | | | 3P |
| | | Equipment/Furnishings - Cockpit Seats -Jammed AMSAFE Restraint System | 328 SSG | ASB-328-25-040 | 02.11.16 | 2 24.05.17 | ASB-328-X | S | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Fire Protect.-Inspect.of dis.cart | 328 SSG | ASB-328-26-026 | 01.02.99 | | ASB-328-X | S | | 3P |
| | | Flight Contr. Clear Rudder Quadr. | 328 SSG | ASB-328-27-003 | 13.07.94 | | ASB-328-X | S | | 3P |
| | | Inspection elevator trim system | 328 SSG | ASB-328-27-017 | 28.07.98 | 2 | ASB-328-X | S | | 3P |
| | | Installation of an add. placard | 328 SSG | ASB-328-27-023 | 13.03.98 | | ASB-328-X | S | | 3P |
| | | Flight Controls - Inspection of roll spoiler actuator | 328 SSG | ASB-328-27-025 | 16.10.98 | 1 22.09.99 | ASB-328-X | S | | 3P |
| | | Flight Contr.- Spring Tab Bolt Insp. | 328 SSG | ASB-328-27-031 | 04.07.01 | | ASB-328-X | S | | 3P |
| | | Insp.of Rudder Spring Tab Lever Assy | 328 SSG | ASB-328-27-036 | 12.02.03 | 3 08.02.08 | ASB-328-X | S | | 3P |
| | | Inspection of the Elevator Pulley Support Bracket | 328 SSG | ASB-328-27-039 | 16.12.11 | | ASB-328-X | S | | 3P |
| | | Flight Controls - Inspection of the rudder control rod | 328 SSG | ASB-328-27-046 | 10.02.23 | | ASB-328-X | S | | 3P |
| | | Fuel - Inspection of Fuel Line Clamps | 328 SSG | ASB-328-28-041 | 14.06.16 | 2 12.12.16 | ASB-328-X | S | | 3P |
| | | Ice and Rain Protect. Inspection | 328 SSG | ASB-328-30-002 | 17.01.94 | | ASB-328-X | S | | 3P |
| | | Ice & Rain Protect. Inspection | 328 SSG | ASB-328-30-013 | 21.02.97 | 1 | ASB-328-X | S | | 3P |
| | | Ice a.Rain Protec.- De-Icer Boot Insp. | 328 SSG | ASB-328-30-029 | 30.01.01 | 1 09.02.01 | ASB-328-X | S | | 3P |
| | | Additional sealing panels 10/11VE | 328 SSG | ASB-328-31-016 | 02.04.97 | | ASB-328-X | S | | 3P |
| | | Exchange of NLG and MLG Uplocks | 328 SSG | ASB-328-32-012 | 05.12.95 | | ASB-328-X | S | | 3P |
| | | Landing Gear - Inspection of MLG bushes | 328 SSG | ASB-328-32-019 | 03.11.97 | 2 23.01.13 | ASB-328-X | S | | 3P |
| | | Landing Gear- Inspection of RIH Main Landing Gear Side Strut Pin | 328 SSG | ASB-328-32-042 | 15.12.16 | | ASB-328-X | S | | 3P |
| | | Fuselage - Top Fairing | 328 SSG | ASB-328-53-001 | 07.03.94 | 2 | ASB-328-X | S | | 3P |
| | | Fuselage - Top Fairing | 328 SSG | ASB-328-53-004 | 18.12.95 | 2 | ASB-328-X | S | | 3P |
| | | MLG Fairing Longitudinal Beam | 328 SSG | ASB-328-53-010 | 13.10.95 | | ASB-328-X | S | | 3P |
| | | Stabilizer - Rudder spring tab | 328 SSG | ASB-328-55-028 | 29.10.99 | 3 04.05.00 | ASB-328-X | S | | 3P |
| | | Add. Placards for Windshields | 328 SSG | ASB-328-56-014 | 24.05.96 | | ASB-328-X | S | | 3P |
| | | Inspect. Outer Wing Fuel Leakage | 328 SSG | ASB-328-57-020 | 28.10.97 | | ASB-328-X | S | | 3P |
| | | Wings - Insp.Lower Inner Panel f.Cracks | 328 SSG | ASB-328-57-037 | 05.05.08 | 2 20.05.08 | ASB-328-X | S | | 3P |
| | | Wings - Inspection of the X - Rod (Connecting Element Wing/Fuselage) | 328 SSG | ASB-328-57-038 | 28.10.10 | 3 24.01.14 | ASB-328-X | S | | 3P |
| | | Wings - Inspection of Roll Spoiler Bearing Arms | 328 SSG | ASB-328-57-043 | 21.09.18 | | ASB-328-X | S | | 3P |
| | | Propeller - Aux. Press. Pump Relais | 328 SSG | ASB-328-61-007 | 31.07.95 | | ASB-328-X | S | | 3P |
| | | Propeller - Hydr. Unit Forw. Spring | 328 SSG | ASB-328-61-009 | 02.11.95 | 2 | ASB-328-X | S | | 3P |
| | | Propeller - Inspection of hub | 328 SSG | ASB-328-61-027 | 24.03.99 | 1 | ASB-328-X | S | | 3P |
| | | Propeller - Thrust Bearing Race Repl. | 328 SSG | ASB-328-61-032 | 07.09.01 | | ASB-328-X | S | | 3P |
| | | Propeller - High Pressure Pump Repl. | 328 SSG | ASB-328-61-045 | 22.04.22 | | ASB-328-X | S | | 3P |
| | | Power Plant-Exchange Air Intake | 328 SSG | ASB-328-71-006 | 20.03.95 | 2 | ASB-328-X | S | | 3P |
| | | Inspection nacelle door latches | 328 SSG | ASB-328-71-008 | 11.07.96 | 1 | ASB-328-X | S | | 3P |
| | | Engine-Propeller Shaft Inspection and Replacement | 328 SSG | ASB-328-72-040 | 21.03.12 | | ASB-328-X | S | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Lubricat. Power Control Cables | 328 SSG | ASB-328-76-015 | 09.01.98 | 3 | ASB-328-X | S | | | 3P |
| | | Lubricat. Condit. Control Cables | 328 SSG | ASB-328-76-022 | 22.12.97 | | ASB-328-X | S | | | 3P |
| | | Inspect. Power Lever Cam Follower | 328 SSG | ASB-328-76-024 | 05.08.98 | 1 | ASB-328-X | S | | | 3P |
| | | Eng.Con.-Qual.issue with Eng.Con.Cabl. | 328 SSG | ASB-328-76-034 | 14.11.01 | 1 16.11.01 | ASB-328-X | S | | | 3P |
| | | ATA 57 Wings - Inspection of Landing Flap Support 2 | 328 SSG | ASB-328-57-044 | 18.02.19 | | ASB-328-X | S | | S/N 3032 - 3063 | 3P |
| | | Dornier 328 GSE Retrofit | 328 SSG | CI-328-00-015 | 15.05.96 | | CI-328-X | S | | | 3P |
| | | Dornier 328 GSE Retrofit | 328 SSG | CI-328-00-016 | 15.05.96 | | CI-328-X | S | | | 3P |
| | | Propeller Dynamic Balancing | 328 SSG | CI-328-00-017 | 05.06.96 | | CI-328-X | S | | | 3P |
| | | Operat. in Severe Icing Condition | 328 SSG | CI-328-00-018 | 13.06.96 | | CI-328-X | S | | | 3P |
| | | Dornier 328 GSE 76.4.06 Retrofit. | 328 SSG | CI-328-00-025 | 29.04.97 | | CI-328-X | S | | | 3P |
| | | Aircraft Manufacture Date | 328 SSG | CI-328-00-028 | 25.06.97 | | CI-328-X | S | | | 3P |
| | | Dornier 328 Operators Conference | 328 SSG | CI-328-00-035 | 07.07.98 | | CI-328-X | S | | | 3P |
| | | ECS Oil Contam. Prevent. Proced. | 328 SSG | CI-328-00-036 | 03.09.98 | | CI-328-X | S | | | 3P |
| | | Prev.of the inst.of uncertified A/c parts | 328 SSG | CI-328-00-068 | 20.07.01 | | CI-328-X | S | | | 3P |
| | | Global Supp. Center - Oberpfaffenhofen | 328 SSG | CI-328-00-069 | 27.08.01 | | CI-328-X | S | | | 3P |
| | | A&C Checks to LUMPD "Phase Checks" | 328 SSG | CI-328-00-071 | 31.10.01 | | CI-328-X | S | | | 3P |
| | | Customer Service Gate | 328 SSG | CI-328-00-074 | 08.01.02 | | CI-328-X | S | | | 3P |
| | | Final NTSB Rep.of Do328-100 accident | 328 SSG | CI-328-00-078 | 15.03.02 | | CI-328-X | S | | | 3P |
| | | SPR Proc.for Operator MFCR & Authority | 328 SSG | CI-328-00-081 | 23.10.02 | 1 17.08.06 | CI-328-X | S | | | 3P |
| | | Mod.resulting from SFAR 88 requirements | 328 SSG | CI-328-00-082 | 24.07.03 | | CI-328-X | S | | | 3P |
| | | Change of Company | 328 SSG | CI-328-00-084 | 01.08.03 | | CI-328-X | S | | | 3P |
| | | Compl.with Fuel Tank Safety - SFAR 88 | 328 SSG | CI-328-00-086 | 01.10.04 | 1 11.01.05 | CI-328-X | S | | | 3P |
| | | Fuel Tank Safety - SB-Kit Availability | 328 SSG | CI-328-00-091 | 02.12.05 | | CI-328-X | S | | | 3P |
| | | Change of Company and Responsibilities | 328 SSG | CI-328-00-092 | 25.08.06 | | CI-328-X | S | | | 3P |
| | | Technical Publications - Pricing Policy | 328 SSG | CI-328-00-098 | 29.06.09 | | CI-328-X | S | | | 3P |
| | | Jack Adap.,Cent.Fus.LH/RH GSE No:07.103A | 328 SSG | CI-328-07-046 | 30.10.00 | | CI-328-X | S | | | 3P |
| | | Cabin Press.Contr.System (CPCS) | 328 SSG | CI-328-21-003 | 20.01.95 | 4 25.09.01 | CI-328-X | S | | | 3P |
| | | Operat. Proced. Air Condit. Syst. | 328 SSG | CI-328-21-005 | 31.05.95 | | CI-328-X | S | | | 3P |
| | | Electric-Pneumatic Outflow Valve | 328 SSG | CI-328-21-012 | 12.12.95 | | CI-328-X | S | | | 3P |
| | | Water Dripping from Cabin Ceiling | 328 SSG | CI-328-21-021 | 28.11.96 | | CI-328-X | S | | | 3P |
| | | ECS Pack Warranty Claim Policy | 328 SSG | CI-328-21-047 | 09.02.01 | | CI-328-X | S | | | 3P |
| | | ECS Pack - Proced.to Prevent Oil Contam. | 328 SSG | CI-328-21-054 | 08.12.00 | | CI-328-X | S | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Air distribution cabin, frames 14 & 18 | 328 SSG | CI-328-21-063 | 20.04.01 | | CI-328-X | S | | 3P |
| | | Repl.of CAU tog.with Pneu.Temp.Sensor | 328 SSG | CI-328-21-070 | 27.09.01 | | CI-328-X | S | | 3P |
| | | Passenger Address Amplifier | 328 SSG | CI-328-23-019 | 03.07.96 | | CI-328-X | S | | 3P |
| | | Becker Digital Player DP 4100-005 | 328 SSG | CI-328-23-076 | 05.03.01 | | CI-328-X | S | | 3P |
| | | Engine Starting from GPU | 328 SSG | CI-328-24-006 | 18.07.95 | | CI-328-X | S | | 3P |
| | | AC Junction box P/N: 330GA01YA | 328 SSG | CI-328-24-037 | 28.09.98 | | CI-328-X | S | | 3P |
| | | AC-Generator shaft o-ring replacement | 328 SSG | CI-328-24-053 | 05.12.00 | | CI-328-X | S | | 3P |
| | | Demonstr.of Reliability of HECS & 1VE Box | 328 SSG | CI-328-24-083 | 13.11.03 | 1 19.05.04 | CI-328-X | S | | 3P |
| | | Cargo Compartm. Decompress. Panel | 328 SSG | CI-328-25-014 | 29.05.96 | 1 | CI-328-X | S | | 3P |
| | | Baggage compartm. lining repair | 328 SSG | CI-328-25-033 | 18.02.98 | | CI-328-X | S | | 3P |
| | | Bulletproof Cockpit door | 328 SSG | CI-328-25-080 | 05.06.02 | 1 20.06.02 | CI-328-X | S | | 3P |
| | | Cabin Seat Inst.in Dornier 328 Aircraft | 328 SSG | CI-328-25-097 | 18.12.08 | | CI-328-X | S | | 3P |
| | | Improved flap control unit | 328 SSG | CI-328-27-031 | 05.08.98 | | CI-328-X | S | | 3P |
| | | Autoflgt.-Autopil.servo drum mod. | 328 SSG | CI-328-27-038 | 29.10.98 | | CI-328-X | S | | 3P |
| | | Mod. Kit, Rudder Rigging Board | 328 SSG | CI-328-27-077 | 12.03.02 | | CI-328-X | S | | 3P |
| | | Amber "Fuel Feed Temp" CAS Message | 328 SSG | CI-328-28-045 | 20.07.00 | | CI-328-X | S | | 3P |
| | | Refueling Panels - Improvements | 328 SSG | CI-328-28-061 | 04.03.01 | | CI-328-X | S | | 3P |
| | | AEROQUIP Type 601 Hoses | 328 SSG | CI-328-28-088 | 19.01.05 | | CI-328-X | S | | 3P |
| | | Phase - restoration of AC Motor Pumps | 328 SSG | CI-328-29-085 | 20.08.04 | | CI-328-X | S | | 3P |
| | | Windshield Wiper | 328 SSG | CI-328-30-008 | 16.10.95 | | CI-328-X | S | | 3P |
| | | Ejector Flow Control Valve Restr. | 328 SSG | CI-328-30-010 | 17.10.95 | | CI-328-X | S | | 3P |
| | | Replacing De-Icing Components | 328 SSG | CI-328-30-022 | 27.01.97 | | CI-328-X | S | | 3P |
| | | De-Icer Boot Repairs | 328 SSG | CI-328-30-023 | 20.02.97 | 1 09.01.99 | CI-328-X | S | | 3P |
| | | Re-calibr. of press. regulator | 328 SSG | CI-328-30-026 | 27.05.97 | | CI-328-X | S | | 3P |
| | | Deicing System Improvem. Program | 328 SSG | CI-328-30-027 | 11.06.97 | | CI-328-X | S | | 3P |
| | | Propeller Heat System Reliability | 328 SSG | CI-328-30-030 | 30.06.98 | | CI-328-X | S | | 3P |
| | | Interchang.of Black a.Silver De-icer Boots | 328 SSG | CI-328-30-050 | 25.01.01 | | CI-328-X | S | | 3P |
| | | De-icer Boots - Rework to FAST boots | 328 SSG | CI-328-30-060 | 04.03.01 | | CI-328-X | S | | 3P |
| | | Elev./Rudder Anti-Ice - Ground Supp.Equip. | 328 SSG | CI-328-30-089 | 02.02.06 | | CI-328-X | S | | 3P |
| | | Eaton Lighted Push Button Switch | 328 SSG | CI-328-31-004 | 20.04.95 | | CI-328-X | S | | 3P |
| | | Cockpit Voice Rec.- Req.for JAR-OPS 1 | 328 SSG | CI-328-31-065 | 11.04.01 | | CI-328-X | S | | 3P |
| | | PSEU | 328 SSG | CI-328-32-001 | 24.02.94 | | CI-328-X | S | | 3P |
| | | Landing Gear Uplocks and Rollers | 328 SSG | CI-328-32-002 | 15.04.94 | | CI-328-X | S | | 3P |
| | | Brake Metering Unit | 328 SSG | CI-328-32-029 | 16.10.97 | | CI-328-X | S | | 3P |
| | | P/N 2610701-2 Main Gear Wheel | 328 SSG | CI-328-32-049 | 11.12.00 | | CI-328-X | S | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Landing Gear - Structural Safe-Life | 328 SSG | CI-328-32-052 | 03.04.01 | | CI-328-X | S | | | 3P |
| | | Main Landing Gear Decals | 328 SSG | CI-328-32-056 | 17.08.01 | | CI-328-X | S | | | 3P |
| | | Nose wheel - steering potentiometers | 328 SSG | CI-328-32-059 | 05.03.01 | | CI-328-X | S | | | 3P |
| | | Trouble-shooting - Nose Wheel Steer. | 328 SSG | CI-328-32-066 | 21.06.01 | | CI-328-X | S | | | 3P |
| | | New.Grd.Supp.Equip. - MLG Mount. Trolley. | 328 SSG | CI-328-32-075 | 18.02.02 | | CI-328-X | S | | | 3P |
| | | Landing Gear - Overhaul Planning | 328 SSG | CI-328-32-087 | 09.12.04 | | CI-328-X | S | | | 3P |
| | | Cabin Light Wiring | 328 SSG | CI-328-33-009 | 17.10.95 | | CI-328-X | S | | | 3P |
| | | Head Build Up in Overhead Panel | 328 SSG | CI-328-33-011 | 06.11.95 | | CI-328-X | S | | | 3P |
| | | Ballast Unit, P/N 3253-10 | 328 SSG | CI-328-33-043 | 24.05.00 | | CI-328-X | S | | | 3P |
| | | Impr. Cabin Ballast Unit P/N 3253-10 | 328 SSG | CI-328-33-064 | 30.03.01 | | CI-328-X | S | | | 3P |
| | | European Air Space - Red. Vertical Sep. | 328 SSG | CI-328-34-062 | 13.03.01 | | CI-328-X | S | | | 3P |
| | | Proposal for RVSM Certification | 328 SSG | CI-328-34-072 | 26.11.01 | 1 30.11.01 | CI-328-X | S | | | 3P |
| | | EGPWS Stand Alone - Altitude Callouts | 328 SSG | CI-328-34-090 | 17.11.05 | | CI-328-X | S | | | 3P |
| | | Mode "S" Surveillance Implementation | 328 SSG | CI-328-34-093 | 17.08.06 | 2 16.04.07 | CI-328-X | S | | | 3P |
| | | Mode "S" Surveillance Implementation | 328 SSG | CI-328-34-094 | 16.01.07 | | CI-328-X | S | | | 3P |
| | | Oxygen - Amber CAS message | 328 SSG | CI-328-35-058 | 22.02.01 | | CI-328-X | S | | | 3P |
| | | Aircraft de-icing (APU) | 328 SSG | CI-328-49-042 | 31.01.00 | | CI-328-X | S | | | 3P |
| | | APU - Insp. Repl. of Coupling Ret. Bolt | 328 SSG | CI-328-49-057 | 05.02.01 | | CI-328-X | S | | | 3P |
| | | Service Door Locking mechanism | 328 SSG | CI-328-52-013 | 14.02.96 | | CI-328-X | S | | | 3P |
| | | Limits Permissable Delamination | 328 SSG | CI-328-56-007 | 04.08.95 | 1 01.03.96 | CI-328-X | S | | | 3P |
| | | Cockpit Windshield Dome Nuts | 328 SSG | CI-328-56-020 | 03.07.96 | | CI-328-X | S | | | 3P |
| | | Cockpit Side Window Improvements | 328 SSG | CI-328-56-048 | 15.11.00 | | CI-328-X | S | | | 3P |
| | | Wing Leading Edge #2 or #3 Repl. | 328 SSG | CI-328-57-055 | 29.05.01 | | CI-328-X | S | | | 3P |
| | | Cracks in Lower Wing Panel | 328 SSG | CI-328-57-095 | 11.12.08 | | CI-328-X | S | | | 3P |
| | | Hartzell HD-SL-61-032, Prop.Vibr. | 328 SSG | CI-328-61-040 | 31.01.00 | | CI-328-X | S | | | 3P |
| | | D-5110-5 Fork Failures | 328 SSG | CI-328-61-041 | 31.01.00 | | CI-328-X | S | | | 3P |
| | | Engine Shock Absorber | 328 SSG | CI-328-71-024 | 03.03.97 | | CI-328-X | S | | | 3P |
| | | Introd. Improved engine air intake att.hardware. | 328 SSG | CI-328-71-044 | 22.06.00 | | CI-328-X | S | | | 3P |
| | | Fuel Heat.- (Stew. Warner) PN 10718 | 328 SSG | CI-328-73-067 | 24.06.01 | | CI-328-X | S | | | 3P |
| | | Trigger Switch 5JB and 15JB | 328 SSG | CI-328-74-032 | 11.12.97 | | CI-328-X | S | | | 3P |
| | | Commercial supp.prg.for Install. | 328 SSG | CI-328-76-039 | 03.12.98 | | CI-328-X | S | | | 3P |
| | | Eng.Cont.Box - Thrust Lever Guide Wear. | 328 SSG | CI-328-76-073 | 14.12.01 | | CI-328-X | S | | | 3P |
| | | Eng.Cont.Box Assy - Prod.Improvement | 328 SSG | CI-328-76-096 | 12.11.08 | | CI-328-X | S | | | 3P |
| | | Nose Landing Gear - Improvement of the NWS Feedback Potentiometer Harness | 328 SSG | EO-328-32-347 | 17.05.16 | 1 03.01.17 | EO-328-X | S | | P/N 23055-000-00, 23470-000-00 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Retrofit Mode S Transponder with EHS | 328 SSG | EO-328-34-234 | 13.11.06 | 13 25.08.11 | EO-328-X | S | | S/N 005,006,008,011,012,015,016,017,019,020,021,022,023,025,026,031,035,036,040,041,047,048,050,055,056,058,060,061,062,063,066,068,069,070,072,073,075,077,078,083,085,087,088,089,090,091,093,095,097,098,100,101,104,106,110,112,113,115,117,119 | 3P |
| | | Maint.a.funct.test for MOV-modules | 328 SSG | EO-328-30-162 | 09.11.99 | 3 23.01.01 | EO-328-X | S | | S/N 006-008,010,012-015,018,020,021,025-030,032,033,035,037-040,042,043,044,045,046,047,048,049,050,051,052,055-061,064-068,070,071,073-075,083,084,086-089,091,093,097,101,106,107,112,113 | 3P |
| | | Replace. of Fuse 2PD | 328 SSG | EO-328-24-001 | 09.12.93 | 1 | EO-328-X | S | | S/N 3005 | 3P |
| | | Installation Reinforcement Sheets | 328 SSG | EO-328-25-093 | 29.10.97 | | EO-328-X | S | | S/N 3005 | 3P |
| | | Flight Control-Replace Hydr.Tube | 328 SSG | EO-328-27-017 | 01.06.94 | 1 09.06.94 | EO-328-X | S | | S/N 3005 | 3P |
| | | Inst.of new Flight Cont.Cables & supp.Brkts. | 328 SSG | EO-328-27-185 | 17.09.01 | 2 23.01.08 | EO-328-X | S | | S/N 3005 | 3P |
| | | Autotrim Active Light | 328 SSG | EO-328-31-004 | 03.12.93 | | EO-328-X | S | | S/N 3005 | 3P |
| | | PAX Light System - Relocat. circu | 328 SSG | EO-328-33-011 | 19.04.94 | | EO-328-X | S | | S/N 3005 | 3P |
| | | GPWS | 328 SSG | EO-328-34-010 | 06.04.94 | | EO-328-X | S | | S/N 3005 | 3P |
| | | Install. Fire Access Doors | 328 SSG | EO-328-71-007 | 10.03.94 | | EO-328-X | S | | S/N 3005 | 3P |
| | | Equip./Furn.- Inst.of trolley stowage | 328 SSG | EO-328-25-252 | 16.01.09 | | EO-328-X | S | | S/N 3005, 3006, 3011, 3017, 3035, 3041, 3050, 3058, 3066, 3075, 3077, 3085, 3091, 3097 | 3P |
| | | Auto Flight - Approach mode ILS CAT II | 328 SSG | EO-328-22-026 | 13.04.95 | | EO-328-X | S | | S/N 3005, 3011, 3017 | 3P |
| | | Retrofit of Provisions of HGS | 328 SSG | EO-328-31-051 | 01.04.96 | 1 12.04.96 | EO-328-X | S | | S/N 3005, 3011, 3017 | 3P |
| | | Navigation-Steep Approach Landing | 328 SSG | EO-328-34-034 | 29.06.95 | | EO-328-X | S | | S/N 3005, 3011, 3017 | 3P |
| | | Water/Waste - Exchange Water Fauc | 328 SSG | EO-328-38-015 | 19.05.94 | 1 21.02.95 | EO-328-X | S | | S/N 3005, 3011, 3017 | 3P |
| | | Fuselage-Top Fairing Attachment | 328 SSG | EO-328-53-025 | 26.04.95 | | EO-328-X | S | | S/N 3005, 3011, 3017 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Exchange of Front Row Seats | 328 SSG | EO-328-25-070 | 20.12.96 | 1 07.05.97 | EO-328-X | S | | S/N 3005, 3011, 3017, 3022, 3023, 3036, 3041, 3046, 3053, 3054, 3062, 3063, 3066, 3069 | 3P |
| | | Install.of compl.provisions for TCAS | 328 SSG | EO-328-34-158 | 21.09.99 | 1 30.05.00 | EO-328-X | S | | S/N 3005, 3011, 3017, 3036 | 3P |
| | | Replace Electrical Wiring Harness | 328 SSG | EO-328-72-048 | 18.12.95 | | EO-328-X | S | | S/N 3005, 3011, 3017, 3036 | 3P |
| | | Installation of Ballast | 328 SSG | EO-328-53-008 | 30.03.94 | 2 21.02.95 | EO-328-X | S | | S/N 3005, 3011,3017 | 3P |
| | | Equipment/Furnishings-Retrofit | 328 SSG | EO-328-25-045 | 28.08.95 | | EO-328-X | S | | S/N 3005, 3017 | 3P |
| | | Relocat. of Oil Pressure Switch | 328 SSG | EO-328-61-075 | 28.01.97 | | EO-328-X | S | | S/N 3005, 3017 | 3P |
| | | Flight Controls-Deactiv.Spoiler | 328 SSG | EO-328-27-037 | 07.07.95 | 1 13.02.96 | EO-328-X | S | | S/N 3005,3009, 3016 | 3P |
| | | Auto Flight - Approach mode ILS CAT II | 328 SSG | EO-328-22-250 | 11.11.08 | | EO-328-X | S | | S/N 3006 | 3P |
| | | Equip./Furn.- Exchange of galley | 328 SSG | EO-328-25-246 | 11.04.08 | | EO-328-X | S | | S/N 3006 | 3P |
| | | Modification of Wiring | 328 SSG | EO-328-33-003 | 02.12.93 | | EO-328-X | S | | S/N 3006 | 3P |
| | | Installation of Protection Strip | 328 SSG | EO-328-57-005 | 28.12.93 | | EO-328-X | S | | S/N 3006 | 3P |
| | | Modific. of Galley and Toilet | 328 SSG | EO-328-25-014 | 22.04.94 | | EO-328-X | S | | S/N 3006, 3007 | 3P |
| | | Replacement of FDR | 328 SSG | EO-328-31-006 | 10.03.94 | | EO-328-X | S | | S/N 3006, 3007, 3008, 3010 | 3P |
| | | Replacem. of Fairchild Cockpit VR | 328 SSG | EO-328-23-018 | 07.06.94 | | EO-328-X | S | | S/N 3006, 3007, 3008, 3010, 3012, 3013, 3014 | 3P |
| | | GPWS - Activating of System | 328 SSG | EO-328-34-009 | 06.04.94 | 6 07.12.95 | EO-328-X | S | | S/N 3006, 3007, 3008, 3010, 3012, 3013, 3014, 3015, 3018, 3019, 3020, 3025, 3027, 3064, 3065 | 3P |
| | | Equipment-Cabin Layout 31 Pax | 328 SSG | EO-328-25-032 | 22.06.95 | | EO-328-X | S | | S/N 3006, 3007, 3008, 3010, 3012, 3013, 3014, 3015, 3020, 3029 | 3P |
| | | Equip./Furn.-Retrof.of opt.equip. | 328 SSG | EO-328-25-132 | 16.12.98 | 2 02.09.99 | EO-328-X | S | | S/N 3006, 3007, 3008, 3010, 3012, 3013, 3014, 3015, 3020, 3029, 3064, 3065 | 3P |
| | | Eq./fur.-Mod.of cab.layout | 328 SSG | EO-328-25-145 | 15.02.99 | | EO-328-X | S | | S/N 3006, 3007, 3008, 3010, 3012, 3013, 3014, 3015, 3020, 3029, 3064, 3065 | 3P |
| | | Retrofit/Reactivat.Smoke Detector | 328 SSG | EO-328-26-091 | 07.10.97 | | EO-328-X | S | | S/N 3006, 3007, 3008, 3010, 3012, 3013, 3014, 3015, 3020, 3029, 3064, 3065 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Navigat.-Inst. TCAS Computer | 328 SSG | EO-328-34-019 | 30.09.94 | 1 13.01.00 | EO-328-X | S | | S/N 3006, 3007, 3008, 3010, 3012, 3013, 3014, 3015, 3027 | 3P |
| | | Navigation - Deactivation of Steep Approach | 328 SSG | EO-328-34-136 | 21.01.99 | 2 15.01.16 | EO-328-X | S | | S/N 3006, 3007, 3008, 3010, 3012, 3013, 3014, 3015, 3064, 3065 | 3P |
| | | Equip./Furn.- Modification of ceiling Panel | 328 SSG | EO-328-25-177 | 20.09.00 | | EO-328-X | S | | S/N 3006, 3007, 3008, 3010, 3012, 3014, 3015, 3020, 3025, 3027, 3029, 3035, 3040, 3049, 3050, 3064, 3065, 3067, 3071, 3074, 3084, 3087 | 3P |
| | | Retrofit Lavatory Fire Extinguish | 328 SSG | EO-328-26-092 | 08.10.97 | | EO-328-X | S | | S/N 3006, 3007, 3008, 3010, 3064, 3065 | 3P |
| | | Navigation-Provisions for TCAS | 328 SSG | EO-328-34-021 | 17.01.95 | 1 13.01.00 | EO-328-X | S | | S/N 3006-3008, 3010, 3012-3015, 3020, 3027 | 3P |
| | | Stabilizer-Vert. Stab.Lead.Edge | 328 SSG | EO-328-55-028 | 31.05.95 | | EO-328-X | S | | S/N 3007 | 3P |
| | | Power Plant-Shock Mounts | 328 SSG | EO-328-71-029 | 10.06.95 | | EO-328-X | S | | S/N 3007 | 3P |
| | | Alternate cockp.door CASCADE cockp.door | 328 SSG | EO-328-52-241 | 03.09.07 | | EO-328-X | S | | S/N 3007, 3012, 3020, 3025, 3040, 3048, 3050, 3058, 3068, 3075 | 3P |
| | | Wiring at Relay Support 20VE | 328 SSG | EO-328-36-043 | 02.08.95 | 1 22.08.95 | EO-328-X | S | | S/N 3007, 3014 | 3P |
| | | Flight Control-Adjust.Elevat.Trim | 328 SSG | EO-328-27-016 | 28.05.94 | | EO-328-X | S | | S/N 3008 | 3P |
| | | Wing/Fuselage Connection - Brace | 328 SSG | EO-328-57-013 | 28.04.94 | | EO-328-X | S | | S/N 3008 | 3P |
| | | Prov. for Trolley Inst. in Baggag | 328 SSG | EO-328-25-012 | 28.04.94 | 1 07.07.94 | EO-328-X | S | | S/N 3009 | 3P |
| | | Retrofit of Life Vests | 328 SSG | EO-328-25-059 | 24.05.96 | | EO-328-X | S | | S/N 3009 | 3P |
| | | Fusel.- Belly Fairing - Ins.for Poss.Damage | 328 SSG | EO-328-53-194 | 09.01.02 | | EO-328-X | S | | S/N 3009, 3010, 3011, 3012, 3013, 3014, 3017, 3020, 3029, 3031, 3089 | 3P |
| | | Retrofit of Optional Equipment | 328 SSG | EO-328-00-024 | 09.03.95 | | EO-328-X | S | | S/N 3011 | 3P |
| | | Cycle Counter Engine Inlet Deice | 328 SSG | EO-328-30-044 | 02.08.95 | 2 29.08.95 | EO-328-X | S | | S/N 3011, 3017, 3030, 3032, 3033 | 3P |
| | | Equip./Furn.- Exch.of Emerg.Loc.Transm. | 328 SSG | EO-328-25-203 | 26.03.04 | 1 29.11.04 | EO-328-X | S | | S/N 3011, 3017, 3041, 3066, 3077, 3078, 3085, 3115 | 3P |
| | | Retrofit of 43 Ah Saft Batteries | 328 SSG | EO-328-24-090 | 18.09.97 | 2 23.06.15 | EO-328-X | S | | S/N 3012,3055, 3078 | 3P |
| | | Communications - Installation of KHF 1050 | 328 SSG | EO-328-23-367 | 08.04.19 | 1 23.05.19 | EO-328-X | S | | S/N 3013 | 3P |
| | | Communications - Installation of VHF Blade Antenna | 328 SSG | EO-328-23-373 | 25.10.19 | | EO-328-X | S | | S/N 3013 | 3P |
| | | Retrofit of optional equipment | 328 SSG | EO-328-25-089 | 14.08.97 | | EO-328-X | S | | S/N 3013 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Fire Protection - Deactivation of Cargo Fire Detection and Suppression System | 328 SSG | EO-328-26-315 | 15.03.13 | 1 27.03.13 | EO-328-X | S | | S/N 3013 | 3P |
| | | Landing Gears-Installation of high flotation tires | 328 SSG | EO-328-32-342 | 10.08.15 | 1 29.09.15 | EO-328-X | S | | S/N 3013 | 3P |
| | | Navigation - Retrofit of GPS (NPA) | 328 SSG | EO-328-34-311 | 28.01.14 | | EO-328-X | S | | S/N 3013 | 3P |
| | | Navigation - Installation of Dual SBAS GNSSU | 328 SSG | EO-328-34-371 | 16.12.19 | | EO-328-X | S | | S/N 3013 | 3P |
| | | Fuselage - Ballast Station on Frame 50 (Option 081K002B) | 328 SSG | EO-328-53-306 | 23.07.12 | | EO-328-X | S | | S/N 3013 | 3P |
| | | Fuselage- Ballast Station on Frame 1 (OPTION 081 K001 B) | 328 SSG | EO-328-53-307 | 27.07.12 | | EO-328-X | S | | S/N 3013 | 3P |
| | | Equipment and Furnishing - Installation of Wide Center Console (Option 251K993) | 328 SSG | EO-328-25-351 | 23.01.18 | 1 25.10.19 | EO-328-X | S | | S/N 3013, 3015, 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, 3106 | 3P |
| | | Indicating/Recording Systems - IC-810 Integrated Avionics Computer | 328 SSG | EO-328-31-348 | 27.06.18 | 1 25.10.19 | EO-328-X | S | | S/N 3013, 3015, 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, 3106 | 3P |
| | | Indicating/Recording Systems - DU-875 Enhanced Functions | 328 SSG | EO-328-31-353 | 27.06.18 | 2 20.10.20 | EO-328-X | S | | S/N 3013, 3015, 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, 3106 | 3P |
| | | Indicating/Recording Systems - Primus Elite Advanced Features | 328 SSG | EO-328-31-354 | 27.06.18 | 1 25.10.19 | EO-328-X | S | | S/N 3013, 3015, 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, 3106 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Indicating/Recording Systems - Synthetic Vision System | 328 SSG | EO-328-31-355 | 27.06.18 | 1 25.10.19 | EO-328-X | S | | S/N 3013, 3015, 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, 3106 | 3P |
| | | Navigation - Dual ADS-B Out Upgrade | 328 SSG | EO-328-34-339 | 03.12.15 | 3 25.06.21 | EO-328-X | S | | S/N 3013, 3015, 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, 3106 | 3P |
| | | Navigation - Replacement of MK VI with MKV-A EGPWS | 328 SSG | EO-328-34-350 | 27.06.18 | 2 29.10.20 | EO-328-X | S | | S/N 3013, 3015, 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, 3106 | 3P |
| | | Navigation - Installatin of FMS 2 with CD-830 | 328 SSG | EO-328-34-352 | 27.06.18 | 1 25.10.19 | EO-328-X | S | | S/N 3013, 3015, 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, 3106 | 3P |
| | | Navigation - Localizer Performance with Vertical Guidance (LPV) | 328 SSG | EO-328-34-375 | 25.02.20 | | EO-328-X | S | | S/N 3013, 3015, 3016, 3020, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, and 3106 | 3P |
| | | Indicating/Recording Systems - Removal of Provisions for Headup Guidance System | 328 SSG | EO-328-31-345 | 25.06.15 | 3 25.10.19 | EO-328-X | S | | S/N 3013, 3015, 3020 | 3P |
| | | Navigation - Replacement of Laseref III and AH-800 with Laseref IV | 328 SSG | EO-328-34-346 | 25.06.15 | 2 25.10.19 | EO-328-X | S | | S/N 3013, 3015, 3020, 3025 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Main Landing Gear - Use of Dornier 328-300 Parts on Dornier 328-100 Series MLG | 328 SSG | EO-328-32-365 | 22.06.17 | | EO-328-X | S | S/N 3013, 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3085, 3091, 3093, 3097, 3104, 3106 | 3P |
| | | Indicating/Recording System - Installation of L-3 QAR | 328 SSG | EO-328-31-341 | 24.07.15 | 3 30.08.16 | EO-328-X | S | S/N 3013, 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, 3106 | 3P |
| | | Navigation - Installation of DL-950 Data Loader | 328 SSG | EO-328-34-270 | 28.07.10 | 8 28.04.16 | EO-328-X | S | S/N 3013, 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, 3106 | 3P |
| | | Communications - Installation and Removal of HF Ferry Kit | 328 SSG | EO-328-23-301 | 24.04.12 | 2 02.08.16 | EO-328-X | S | S/N 3013, 3020, 3025, 3040 | 3P |
| | | Navigation - Retrofit of Mode S Transponders with EHS Capability | 328 SSG | EO-328-34-336 | 29.05.15 | 3 13.11.20 | EO-328-X | S | S/N 3013, 3053, 3059, 3086 | 3P |
| | | Retrofit of Optional Equipment | 328 SSG | EO-328-00-047 | 18.12.95 | | EO-328-X | S | S/N 3015 | 3P |
| | | Navigation - Retrofit of GPS NPA | 328 SSG | EO-328-34-356 | 26.04.16 | | EO-328-X | S | S/N 3015 | 3P |
| | | Navigation - Installation of 2nd SBAS GNSSU | 328 SSG | EO-328-34-382 | 25.06.21 | | EO-328-X | S | S/N 3015 | 3P |
| | | Navigation - Replacement of RMUs | 328 SSG | EO-328-34-383 | 25.06.21 | | EO-328-X | S | S/N 3015 | 3P |
| | | Communications - VDL Mode A (ACARS) | 328 SSG | EO-328-23-360 | 27.06.18 | 2 22.06.21 | EO-328-X | S | S/N 3015, 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, 3106 | 3P |
| | | Communications - Installation of FANS 1/A & PM-CPDLC | 328 SSG | EO-328-23-362 | 18.10.19 | | EO-328-X | S | S/N 3015, 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, 3106 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Navigation - Upgrade to SBAS GNSSU | 328 SSG | EO-328-34-338 | 25.06.15 | 2 22.06.21 | EO-328-X | S | | S/N 3015, 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, 3106 | 3P |
| | | Navigation - Retrofit of ADF II system | 328 SSG | EO-328-34-282 | 05.05.11 | 5 22.06.21 | EO-328-X | S | | S/N 3015, 3020, 3047, 3058, 3060, 3068, 3075 | 3P |
| | | Placards and Markings - Exterior Paint Schema for 328SSG | 328 SSG | EO-328-11-370 | 10.05.19 | | EO-328-X | S | | S/N 3015, 3061 | 3P |
| | | Plac. and Mark.- Partial Painting DAG | 328 SSG | EO-328-11-386 | 10.12.21 | | EO-328-X | S | | S/N 3015, 3061 | 3P |
| | | Fus.- Removal of option gravel protection | 328 SSG | EO-328-53-228 | 12.10.07 | | EO-328-X | S | | S/N 3016 | 3P |
| | | Navigation - Deactivation of Steep Approach | 328 SSG | EO-328-34-278 | 22.02.11 | 9 03.05.16 | EO-328-X | S | | S/N 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3095, 3097, 3104, 3106 | 3P |
| | | Placards and Markings - White Paint Scheme SNC | 328 SSG | EO-328-11-393 | 24.11.22 | | EO-328-X | S | | S/N 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, 3106 | 3P |
| | | Navigation - Installation of second SBAS GNSSU | 328 SSG | EO-328-34-349 | 27.06.18 | | EO-328-X | S | | S/N 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, 3106 | 3P |
| | | Removal of Passenger Seats | 328 SSG | EO-328-25-296 | 18.10.11 | 7 02.06.16 | EO-328-X | S | | S/N 3016, 3020, 3025, 3031, 3040, 3047, 3050, 3075, 3077, 3085, 3086, 3097 | 3P |
| | | Modification of HF-System | 328 SSG | EO-328-23-101 | 12.01.98 | 1 29.01.19 | EO-328-X | S | | S/N 3016, 3021, 3026, 3031 | 3P |
| | | Remov.of trimble GPS/Inst.GPS/NPA | 328 SSG | EO-328-34-131 | 09.09.98 | 2 21.05.01 | EO-328-X | S | | S/N 3016, 3024, 3026, 3027, 3031, 3034 | 3P |
| | | Navigation - Retrofit of ADF II / DME II system | 328 SSG | EO-328-34-283 | 30.04.11 | 3 12.05.16 | EO-328-X | S | | S/N 3016, 3025, 3026, 3031, 3040, 3050, 3077 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Auto Flight - Retrofit of CAT II Approach | 328 SSG | EO-328-22-267 | 13.08.10 | 5 28.04.16 | EO-328-X | S | | S/N 3016, 3025, 3026, 3031, 3047, 3060, 3068, 3077, 3086 | 3P |
| | | Retrofit of optional equipment | 328 SSG | EO-328-23-169 | 16.02.00 | 1 15.12.11 | EO-328-X | S | | S/N 3016, 3026, 3031 | 3P |
| | | Equip.Furn.-Exch.of frnt.row seat | 328 SSG | EO-328-25-135 | 14.01.99 | | EO-328-X | S | | S/N 3016, 3026, 3031 | 3P |
| | | Change of fuel indication lbs/kg | 328 SSG | EO-328-28-125 | 24.09.98 | 1 25.10.00 | EO-328-X | S | | S/N 3016, 3026, 3031 | 3P |
| | | Prov. for option Gravel Protect. | 328 SSG | EO-328-53-100 | 16.12.97 | | EO-328-X | S | | S/N 3016, 3026, 3031 | 3P |
| | | Retrofit of Option Gravel Protect | 328 SSG | EO-328-53-114 | 20.07.98 | 1 31.07.98 | EO-328-X | S | | S/N 3016, 3026, 3031 | 3P |
| | | Retrofit of option Gravel Protection and High Floatation Tires | 328 SSG | EO-328-53-264 | 30.07.10 | 6 18.10.21 | EO-328-X | S | | S/N 3016, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3083, 3085, 3093, 3097, 3104, 3106 | 3P |
| | | Navigation - Replacement of AH-800 with Laserref IV | 328 SSG | EO-328-34-340 | 26.11.15 | | EO-328-X | S | | S/N 3016, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, 3106 | 3P |
| | | Change of Fuel Indication from kgs to lbs | 328 SSG | EO-328-28-266 | 30.07.10 | 6 25.07.14 | EO-328-X | S | | S/N 3016, 3026, 3031, 3040,3047,3050, 3055, 3058, 3068, 3075, 3077, 3085, 3093, 3097, 3104, 3106 | 3P |
| | | Air Conditioning - Installation of Vacuum Pump | 328 SSG | EO-328-21-319 | 05.12.14 | 5 08.12.22 | EO-328-X | S | | S/N 3016, 3026, 3031, 3047, 3058, 3060, 3063, 3068, 3072, 3075, 3077 | 3P |
| | | Navigation - Inst. of provisions for TCAS | 328 SSG | EO-328-34-165 | 13.01.00 | 4 12.04.05 | EO-328-X | S | | S/N 3016, 3026, 3031, 3072 | 3P |
| | | Communication - Removal of a KHF-950 and Inst.of KHF-1050 | 328 SSG | EO-328-23-269 | 09.12.10 | 3 28.05.15 | EO-328-X | S | | S/N 3016, 3026, 3031, 3086, 3091, 3104 | 3P |
| | | Field eval. of eng. de-icer boots | 328 SSG | EO-328-30-087 | 04.09.97 | 1 16.09.97 | EO-328-X | S | | S/N 3017, 3030, 3032 | 3P |
| | | Retrofit of Optional Equipment | 328 SSG | EO-328-00-038 | 14.07.95 | 1 | EO-328-X | S | | S/N 3018 | 3P |
| | | Navigation - Retrofit of GPS Honeywell | 328 SSG | EO-328-34-224 | 18.08.05 | | EO-328-X | S | | S/N 3018 | 3P |
| | | Equip./Furn.- Modification of ceiling Panel | 328 SSG | EO-328-25-175 | 08.09.00 | 1 26.09.00 | EO-328-X | S | | S/N 3018, 3028, 3030, 3032, 3033, 3037, 3038, 3039, 3043, 3044, 3045, 3047, 3048, 3051, 3052, 3055, 3056, 3057, 3058, 3059, 3060, 3061, 3068, 3070, 3075 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Communication - Deactivation of HF 950 System | 328 SSG | EO-328-23-298 | 15.02.12 | 2 19.05.15 | EO-328-X | S | | S/N 3018, 3039, 3072, 3084, 3092, 3113 | 3P |
| | | Communication/Install. of a HF System | 328 SSG | EO-328-23-222 | 07.07.05 | 5 08.10.09 | EO-328-X | S | | S/N 3018, 3051, 3052, 3057, 3059, 3073, 3084, 3089, 3091, 3112, 3113 | 3P |
| | | Communications - Inst.of 2nd handset at galley station | 328 SSG | EO-328-23-289 | 20.06.11 | | EO-328-X | S | | S/N 3019 | 3P |
| | | Equip./Furn.- Modifications for 27 to 32 Pax Layout | 328 SSG | EO-328-25-287 | 17.06.11 | | EO-328-X | S | | S/N 3019 | 3P |
| | | De-activation of cargo fire detection and suppression system | 328 SSG | EO-328-26-295 | 22.07.11 | | EO-328-X | S | | S/N 3019 | 3P |
| | | Fuel Syst.- Change of fuel indic.from lbs to kg | 328 SSG | EO-328-28-284 | 06.06.11 | | EO-328-X | S | | S/N 3019 | 3P |
| | | Retrofit of option Logo Light | 328 SSG | EO-328-33-293 | 30.06.11 | | EO-328-X | S | | S/N 3019 | 3P |
| | | Navigation - Removal of Trimble GPS and Inst.of Honeywell GPS/NPA | 328 SSG | EO-328-34-286 | 07.06.11 | 1 06.07.11 | EO-328-X | S | | S/N 3019 | 3P |
| | | Airborne Auxiliary Power - Retrofit of APU | 328 SSG | EO-328-49-316 | 24.06.14 | 1 12.09.14 | EO-328-X | S | | S/N 3019 | 3P |
| | | Fuselage - Repl.of scuff plate at service door | 328 SSG | EO-328-53-288 | 20.06.11 | | EO-328-X | S | | S/N 3019 | 3P |
| | | Fuselage - Ice Protection Shield | 328 SSG | EO-328-53-290 | 21.06.11 | | EO-328-X | S | | S/N 3019 | 3P |
| | | Wing - Inspection of Wing Attach. | 328 SSG | EO-328-57-062 | 02.09.96 | | EO-328-X | S | | S/N 3019 | 3P |
| | | Equipment / Furnishing - Installation of Checklist Holder (Option 251K002A) | 328 SSG | EO-328-25-324 | 18.12.14 | | EO-328-X | S | | S/N 3019, 3063, 3072, 3087, 3090, 3112, 3113 | 3P |
| | | Placards and Markings - Exterior Paint Schema for Private Wings | 328 SSG | EO-328-11-372 | 21.05.19 | 1 02.07.20 | EO-328-X | S | | S/N 3019, 3063, 3072, 3087, 3090, 3112, 3113, 3117, 3119 | 3P |
| | | Placards and Markings - Decal Application on Do-328 | 328 SSG | EO-328-11-374 | 28.08.19 | 1 27.07.20 | EO-328-X | S | | S/N 3019, 3063, 3072, 3087, 3090, 3112, 3113, 3117, 3119 | 3P |
| | | Placards and Markings - Paint Scheme Without Private Wings Logo | 328 SSG | EO-328-11-387 | 26.01.22 | 1 25.02.22 | EO-328-X | S | | S/N 3019, 3063, 3072, 3087, 3090, 3112, 3113, 3117, 3119 | 3P |
| | | Placards and Markings - Exterior Paint Scheme for Private Wings | 328 SSG | EO-328-11-309 | 10.08.12 | 2 04.11.16 | EO-328-X | S | | S/N 3019, 3063, 3072, 3087, 3112, 3113, 3119 | 3P |
| | | Communications - Removal of the Pax Briefing system | 328 SSG | EO-328-23-294 | 07.06.11 | 1 08.12.14 | EO-328-X | S | | S/N 3019, 3072 | 3P |
| | | Auto Flight - Activation Approach mode ILS CAT II | 328 SSG | EO-328-22-285 | 07.06.11 | 1 21.12.11 | EO-328-X | S | | S/N 3019, 3087, 3090 | 3P |
| | | Navigation - EGPWS Altitude Callouts Menu ID 13 | 328 SSG | EO-328-34-300 | 06.07.12 | 1 01.07.20 | EO-328-X | S | | S/N 3019, 3087, 3090, 3112, 3113, 3117 | 3P |
| | | Replacement of MLG Actuators | 328 SSG | EO-328-32-049 | 09.01.96 | | EO-328-X | S | | S/N 3020 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Airborne Auxiliary Power - Retrofit of APU | 328 SSG | EO-328-49-335 | 13.05.15 | 2 25.06.15 | EO-328-X | S | | S/N 3020 | 3P |
| | | Prov. for option Gravel Protect. | 328 SSG | EO-328-53-326 | 16.01.15 | 2 29.04.16 | EO-328-X | S | | S/N 3020, 3025 | 3P |
| | | Retrofit of option Gravel Protection and High Floatation Tires | 328 SSG | EO-328-53-328 | 16.01.15 | 1 17.06.16 | EO-328-X | S | | S/N 3020, 3025 | 3P |
| | | Retrofit (Prov.cargo fire detec.& suppr.syst.) | 328 SSG | EO-328-26-245 | 01.04.08 | 4 09.04.15 | EO-328-X | S | | S/N 3020, 3025, 3035, 3040, 3047, 3048, 3050, 3058, 3060, 3068, 3075, 3086 | 3P |
| | | Communication - Inst.of a new Single KHF-1050 | 328 SSG | EO-328-23-268 | 09.12.10 | 9 02.05.16 | EO-328-X | S | | S/N 3020, 3025, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3093, 3097, 3106 | 3P |
| | | Epuipment and Furnishings - Ferry Kit Installation and Removal | 328 SSG | EO-328-25-303 | 25.05.12 | 5 04.05.18 | EO-328-X | S | | S/N 3020, 3025, 3040, 3047, 3050, 3060, 3061, 3085, 3086, 3097 | 3P |
| | | Placards and Markings - Exterior Paint Schema SNC | 328 SSG | EO-328-11-314 | 27.02.13 | 3 09.05.16 | EO-328-X | S | | S/N 3020, 3025, 3047, 3050, 3086 | 3P |
| | | Change of ELT 96 Transmitter to ELT 97 | 328 SSG | EO-328-25-262 | 28.07.10 | 6 13.11.15 | EO-328-X | S | | S/N 3020, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3093, 3104, 3106 | 3P |
| | | Fuel Syst.- Change of fuel indic.lbs to kg | 328 SSG | EO-328-28-244 | 07.02.08 | 1 26.02.08 | EO-328-X | S | | S/N 3020, 3035, 3040, 3048, 3050, 3058, 3068, 3075 | 3P |
| | | Auto Flight - Approach mode ILS CAT II | 328 SSG | EO-328-22-243 | 06.02.08 | | EO-328-X | S | | S/N 3020, 3035, 3040, 3048, 3050, 3068, 3075 | 3P |
| | | Navigation - Retrofit of GPS NPA | 328 SSG | EO-328-34-274 | 25.08.09 | 4 05.11.15 | EO-328-X | S | | S/N 3020, 3050, 3058, 3068, 3075, 3085 | 3P |
| | | Retrofit of Optional Equipment | 328 SSG | EO-328-00-054 | 17.04.96 | | EO-328-X | S | | S/N 3021 | 3P |
| | | Retrofit of optional equipment | 328 SSG | EO-328-25-179 | 07.12.00 | | EO-328-X | S | | S/N 3021 | 3P |
| | | Equip./Furn.- Retrofit 22 pax cabin layout | 328 SSG | EO-328-25-208 | 08.12.04 | 1 22.07.05 | EO-328-X | S | | S/N 3021 | 3P |
| | | TCAS with non Diversity Transpond | 328 SSG | EO-328-34-067 | 06.11.96 | | EO-328-X | S | | S/N 3021 | 3P |
| | | Retrofit of APU | 328 SSG | EO-328-49-112 | 10.07.98 | | EO-328-X | S | | S/N 3021 | 3P |
| | | Communications-CVR without Bulk | 328 SSG | EO-328-23-022 | 02.03.95 | | EO-328-X | S | | S/N 3021 and 3022 on Indian register | 3P |
| | | Navigation-GPS (Trimble) | 328 SSG | EO-328-34-023 | 03.03.95 | | EO-328-X | S | | S/N 3021, 3022 | 3P |
| | | Communication-2nd Handset Galley | 328 SSG | EO-328-23-031 | 22.06.95 | 3 09.12.05 | EO-328-X | S | | S/N 3021, 3025, 3030, 3032, 3033, 3037, 3038, 3039, 3066 | 3P |
| | | Navig.- Install.of compl.prov.for TCAS | 328 SSG | EO-328-34-178 | 30.11.00 | 1 18.01.01 | EO-328-X | S | | S/N 3021, 3026 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Change of Interior Placards | 328 SSG | EO-328-11-115 | 22.07.98 | 3 19.02.99 | EO-328-X | S | | S/N 3021, 3073 | 3P |
| | | Deactivation of steep approach | 328 SSG | EO-328-34-133 | 03.12.98 | 2 23.03.99 | EO-328-X | S | | S/N 3021, 3073 | 3P |
| | | Install.of Music entertainm.syst. | 328 SSG | EO-328-23-094 | 17.11.97 | 1 20.02.04 | EO-328-X | S | | S/N 3021, 3085 | 3P |
| | | Navigation - ILS FD/AP. | 328 SSG | EO-328-34-184 | 26.07.01 | 1 20.02.04 | EO-328-X | S | | S/N 3021, 3089, 3107 | 3P |
| | | Retrofit of Optional Equipment | 328 SSG | EO-328-00-033 | 28.06.95 | | EO-328-X | S | | S/N 3022 | 3P |
| | | Exterior Paint Scheme | 328 SSG | EO-328-11-299 | 24.02.12 | | EO-328-X | S | | S/N 3022 | 3P |
| | | Starter - Retrofit of Starter-Generator | 328 SSG | EO-328-80-183 | 06.04.01 | | EO-328-X | S | | S/N 3022 | 3P |
| | | Ejector Flow Control Valve | 328 SSG | EO-328-30-086 | 14.08.97 | | EO-328-X | S | | S/N 3022, 3023 | 3P |
| | | Approach Mode ILS CAT II | 328 SSG | EO-328-22-073 | 13.01.97 | 1 15.02.99 | EO-328-X | S | | S/N 3022, 3023, 3050 | 3P |
| | | Retrofit of optional equipment | 328 SSG | EO-328-25-176 | 13.09.00 | 2 04.04.01 | EO-328-X | S | | S/N 3022, 3023, 3053, 3062, 3069, 3083, 3086, 3088, 3098, 3104 | 3P |
| | | Retrofit of Optional Equipment | 328 SSG | EO-328-25-046 | 16.10.95 | | EO-328-X | S | | S/N 3023 | 3P |
| | | Retrofit of Optional Equipment | 328 SSG | EO-328-00-053 | 04.07.96 | 1 04.07.96 | EO-328-X | S | | S/N 3025 | 3P |
| | | Flight Controls - Activation of Ground Spoilers | 328 SSG | EO-328-27-361 | 24.06.16 | 0 03.11.16 | EO-328-X | S | | S/N 3025 | 3P |
| | | Navigation-Retrofit GPS Honeywell | 328 SSG | EO-328-34-050 | 31.01.96 | | EO-328-X | S | | S/N 3025 | 3P |
| | | Auxiliary Power Unit - Retrofit of APU | 328 SSG | EO-328-49-363 | 03.08.16 | 0 27.10.16 | EO-328-X | S | | S/N 3025 | 3P |
| | | Cabin Layout from 30Pax to 32Pax | 328 SSG | EO-328-25-039 | 17.07.95 | 1 17.04.96 | EO-328-X | S | | S/N 3025, 3035, 3040 | 3P |
| | | Navigation - AHRS 1 to IRS 1 | 328 SSG | EO-328-34-041 | 21.07.95 | 2 06.03.00 | EO-328-X | S | | S/N 3025, 3035, 3040, 3050 | 3P |
| | | Navigation - Retrofit of GPS NPA (Option 345K018A) | 328 SSG | EO-328-34-275 | 08.12.10 | 4 11.05.16 | EO-328-X | S | | S/N 3025, 3040, 3077, 3091, 3093, 3097 | 3P |
| | | Installation of Airconditioning ground supply connector | 328 SSG | EO-328-21-265 | 30.07.10 | 5 11.12.12 | EO-328-X | S | | S/N 3026, 3031, 3047, 3058, 3060, 3075, 3077, 3093, 3097, 3106 | 3P |
| | | Retrofit of optional equipment | 328 SSG | EO-328-25-166 | 19.01.00 | | EO-328-X | S | | S/N 3027 | 3P |
| | | Retrofit of Optional Equipment | 328 SSG | EO-328-00-042 | 16.01.96 | 1 16.01.96 | EO-328-X | S | | S/N 3028 | 3P |
| | | Electrical power | 328 SSG | EO-328-24-157 | 14.09.99 | | EO-328-X | S | | S/N 3028 | 3P |
| | | Equipment-Pax Door Curtin | 328 SSG | EO-328-25-027 | 23.05.95 | 1 10.11.95 | EO-328-X | S | | S/N 3030, 3032, 3033 | 3P |
| | | Equipment-Cabin Layout to 32 Pax | 328 SSG | EO-328-25-040 | 17.07.95 | | EO-328-X | S | | S/N 3030, 3032, 3033, 3037, 3038, 3039, 3043, 3044, 3045 | 3P |
| | | Placards and Markings - Change of exterior color schemes and markings | 328 SSG | EO-328-11-195 | 05.03.02 | | EO-328-X | S | | S/N 3031 | 3P |
| | | Navigation - Retrofit of GPS Honeywell | 328 SSG | EO-328-34-253 | 16.01.09 | | EO-328-X | S | | S/N 3032 | 3P |
| | | Aerodynamic Improvement | 328 SSG | EO-328-57-064 | 05.11.96 | 1 07.02.97 | EO-328-X | S | | S/N 3033, 3037, 3052, 3055, 3056, 3058 | 3P |
| | | Communic.-Cabin Briefing System | 328 SSG | EO-328-23-036 | 27.06.95 | | EO-328-X | S | | S/N 3034 | 3P |
| | | Potentiometer bracket modification | 328 SSG | EO-328-33-172 | 11.07.00 | | EO-328-X | S | | S/N 3035 | 3P |
| | | Navigation-Activating GPS Honeyw. | 328 SSG | EO-328-34-035 | 29.06.95 | | EO-328-X | S | | S/N 3035 | 3P |
| | | Equip.furn.-Chan.of int./ext.col. | 328 SSG | EO-328-11-147 | 16.03.99 | | EO-328-X | S | | S/N 3036 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Field eval.of improved sealing profiles | 328 SSG | EO-328-53-159 | 15.10.99 | | EO-328-X | S | | S/N 3036 | 3P |
| | | Retr.of Music Entert.Syst.Digit.Player | 328 SSG | EO-328-25-190 | 07.11.01 | 1 08.12.11 | EO-328-X | S | | S/N 3036, 3055, 3056 | 3P |
| | | Communication/Install.of a HF System | 328 SSG | EO-328-23-232 | 14.06.06 | | EO-328-X | S | | S/N 3039 | 3P |
| | | Navig. - Retrofit of GPS Honeywell | 328 SSG | EO-328-34-233 | 22.06.06 | | EO-328-X | S | | S/N 3039 | 3P |
| | | Stabilizer-Vert. Stab.Lead.Edge | 328 SSG | EO-328-55-030 | 21.06.95 | | EO-328-X | S | | S/N 3039 | 3P |
| | | Retrofit of APU | 328 SSG | EO-328-49-302 | 02.10.12 | | EO-328-X | S | | S/N 3040 | 3P |
| | | Fuselage - Provision for Option Gravel Protection | 328 SSG | EO-328-53-263 | 30.07.10 | 6 18.10.21 | EO-328-X | S | | S/N 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3083, 3085, 3093, 3097, 3104, 3106 | 3P |
| | | Placards and Markings - Cabin placards in English | 328 SSG | EO-328-11-305 | 23.07.12 | 1 04.03.13 | EO-328-X | S | | S/N 3040, 3047, 3050, 3060, 3085 | 3P |
| | | Navigation - Replacement of IRS 1 with AHRS 1 | 328 SSG | EO-328-34-308 | 08.08.12 | 1 11.12.12 | EO-328-X | S | | S/N 3040, 3050 | 3P |
| | | Flight Controls - Activation of Ground Spoilers | 328 SSG | EO-328-00-273 | 04.01.11 | 2 11.12.12 | EO-328-X | S | | S/N 3040, 3050, 3058 | 3P |
| | | Removal of the DOLORES system | 328 SSG | EO-328-23-180 | 14.12.00 | | EO-328-X | S | | S/N 3042, 3046 | 3P |
| | | Navig.- Install.of compl.prov.for TCAS | 328 SSG | EO-328-34-174 | 25.07.00 | 1 18.01.01 | EO-328-X | S | | S/N 3042, 3046 | 3P |
| | | Retrofit of placards a. markings | 328 SSG | EO-328-11-060 | 14.02.97 | 2 15.09.98 | EO-328-X | S | | S/N 3042, 3046, 3054, 3066, 3091, 3093, 3097, 3101 | 3P |
| | | Retrofit of life vests | 328 SSG | EO-328-25-161 | 18.11.99 | | EO-328-X | S | | S/N 3042, 3046, 3066, 3091, 3093, 3097 | 3P |
| | | Deactivation of Steep Approach | 328 SSG | EO-328-34-063 | 28.10.96 | 4 09.12.98 | EO-328-X | S | | S/N 3046, 3067, 3091, 3093 | 3P |
| | | Navigation - Retrofit of GPS Honeywell | 328 SSG | EO-328-34-212 | 09.11.04 | 1 04.04.06 | EO-328-X | S | | S/N 3047, 3051, 3052, 3055, 3057, 3059, 3061, 3070 | 3P |
| | | Fuel Syst.- Change of fuel indic.lbs to kg | 328 SSG | EO-328-28-211 | 05.11.04 | | EO-328-X | S | | S/N 3047, 3055, 3061, 3070 | 3P |
| | | Navig. - ILS Steep Approach with FD/AP | 328 SSG | EO-328-34-210 | 04.11.04 | | EO-328-X | S | | S/N 3047, 3055, 3061, 3070, 3083 | 3P |
| | | Auto Flight - Approach mode ILS CAT II | 328 SSG | EO-328-22-209 | 04.11.04 | | EO-328-X | S | | S/N 3047, 3055, 3061, 3070, 3083, 3104, 3106 | 3P |
| | | Installation of Alternate Cockpit Door | 328 SSG | EO-328-52-221 | 22.06.05 | | EO-328-X | S | | S/N 3047, 3055, 3061, 3070, 3083, 3104, 3106 | 3P |
| | | Oxygen System - Installation of 115 cu.ft Oxygen Bottle | 328 SSG | EO-328-35-344 | 16.11.15 | | EO-328-X | S | | S/N 3047, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3104 | 3P |
| | | Flight Controls - Installation of Ground Spoilers | 328 SSG | EO-328-27-279 | 20.05.11 | 2 11.12.12 | EO-328-X | S | | S/N 3047, 3060, 3068, 3075, 3077 | 3P |
| | | Retrofit of optional equipment | 328 SSG | EO-328-00-198 | 15.07.02 | | EO-328-X | S | | S/N 3049 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Change Mod 10 to Mod 20 | 328 SSG | EO-328-00-072 | 14.01.97 | 1 22.01.97 | EO-328-X | S | | S/N 3049, 3067, 3071, 3074 | 3P |
| | | Retrofit of SELCAL System | 328 SSG | EO-328-23-068 | 12.11.96 | | EO-328-X | S | | S/N 3049, 3067, 3071, 3074 | 3P |
| | | Equip./Furn.- Change to a 30 pax cab.lay. | 328 SSG | EO-328-25-229 | 30.03.06 | | EO-328-X | S | | S/N 3049, 3067, 3071, 3074 | 3P |
| | | Cabin Layout 31 Pax to 32 Pax | 328 SSG | EO-328-25-065 | 06.11.96 | | EO-328-X | S | | S/N 3049, 3071 | 3P |
| | | Fu.Sys.-Chan.of fu.ind.f.lbs to kg | 328 SSG | EO-328-28-140 | 04.02.99 | 1 10.03.99 | EO-328-X | S | | S/N 3050 | 3P |
| | | Airborne Auxiliary Power - Retrofit of APU | 328 SSG | EO-328-49-312 | 25.03.13 | | EO-328-X | S | | S/N 3050 | 3P |
| | | Equip./Furn.- Mod.for 30 Pax Layout | 328 SSG | EO-328-25-248 | 28.08.08 | 4 08.10.09 | EO-328-X | S | | S/N 3050, 3091 | 3P |
| | | Nav.-Deact.of TCASII (Opt.) | 328 SSG | EO-328-34-141 | 23.02.99 | 1 30.03.99 | EO-328-X | S | | S/N 3050, 3098 | 3P |
| | | Retrofit of a nose gear deflector kit | 328 SSG | EO-328-32-216 | 04.02.05 | 2 30.05.06 | EO-328-X | S | | S/N 3051, 3052, 3053, 3057, 3059 | 3P |
| | | Navigation - Installation of DL-950 Data Loader | 328 SSG | EO-328-34-337 | 02.06.15 | 4 13.08.18 | EO-328-X | S | | S/N 3051, 3052, 3053, 3057, 3059, 3061, 3062, 3092, 3098, 3100, 3101, 3117 | 3P |
| | | Communications - Installation of Intermediate Gain Satcom Antenna | 328 SSG | EO-328-23-369 | 17.09.19 | | EO-328-X | S | | S/N 3051, 3052, 3053, 3057, and 3059 | 3P |
| | | Navigation - Relocation of SBAS GNSS Antenna | 328 SSG | EO-328-34-368 | 29.04.19 | | EO-328-X | S | | S/N 3051, 3052, 3053, 3057, and 3059 | 3P |
| | | Fuel Syst.- Change of fuel indic.lbs to kgs | 328 SSG | EO-328-28-219 | 07.04.05 | 2 19.01.12 | EO-328-X | S | | S/N 3051, 3052, 3056, 3057, 3059, 3095 | 3P |
| | | Plac. and Mark.- Exterior Paint Scheme for EASP Air | 328 SSG | EO-328-11-385 | 15.10.21 | | EO-328-X | S | | S/N 3051, 3053, and 3059 | 3P |
| | | Retrofit of optional equipment | 328 SSG | EO-328-00-215 | 04.02.05 | 1 16.02.05 | EO-328-X | S | | S/N 3053 | 3P |
| | | New Floor betw. Galley a. Lavator | 328 SSG | EO-328-25-079 | 18.04.97 | | EO-328-X | S | | S/N 3053 | 3P |
| | | Retrofit of Optional Equipment | 328 SSG | EO-328-00-052 | 28.03.96 | | EO-328-X | S | | S/N 3053, 3063 | 3P |
| | | Installation of Name Plates | 328 SSG | EO-328-11-081 | 18.04.97 | | EO-328-X | S | | S/N 3053, 3063 | 3P |
| | | Retrofit of Placards | 328 SSG | EO-328-11-088 | 21.08.97 | | EO-328-X | S | | S/N 3053, 3063 | 3P |
| | | Fairchild Cockpit Voice Recorder | 328 SSG | EO-328-23-056 | 19.08.96 | 1 19.08.96 | EO-328-X | S | | S/N 3053, 3063 | 3P |
| | | Emergency Locator Transmitter | 328 SSG | EO-328-25-061 | 25.06.96 | | EO-328-X | S | | S/N 3053, 3063 | 3P |
| | | Modification of small Galley | 328 SSG | EO-328-25-083 | 24.06.97 | | EO-328-X | S | | S/N 3053, 3063 | 3P |
| | | Rel. of ejec. flow control valve | 328 SSG | EO-328-30-099 | 17.12.97 | 2 11.05.98 | EO-328-X | S | | S/N 3053, 3063, 3084, 3087, 3088 | 3P |
| | | Installation of Name Plates | 328 SSG | EO-328-11-080 | 18.04.97 | | EO-328-X | S | | S/N 3054, 3066 | 3P |
| | | Field eval. of de-icer boots PSA | 328 SSG | EO-328-30-120 | 04.09.98 | 1 16.10.98 | EO-328-X | S | | S/N 3055 | 3P |
| | | Auto Flight - Approach mode ILS CAT II | 328 SSG | EO-328-22-247 | 24.04.08 | | EO-328-X | S | | S/N 3056 | 3P |
| | | Navigation - Retrofit of GPS Honeywell | 328 SSG | EO-328-34-235 | 09.11.06 | | EO-328-X | S | | S/N 3056 | 3P |
| | | Auto Flight - Approach mode ILS CAT II | 328 SSG | EO-328-22-242 | 09.01.08 | | EO-328-X | S | | S/N 3058 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Plac./Mark.- Cabin placards in English | 328 SSG | EO-328-11-261 | 12.08.10 | 1 19.04.12 | EO-328-X | S | | S/N 3058, 3068, 3075, 3077, 3093, 3097, 3106 | 3P |
| | | Inst. of new Flight Cont.Cables & Brkts. | 328 SSG | EO-328-27-186 | 16.10.01 | 3 29.01.08 | EO-328-X | S | | S/N 3059 | 3P |
| | | Installation of a flashlight | 328 SSG | EO-328-25-181 | 01.02.01 | 3 13.01.22 | EO-328-X | S | | S/N 3059, 3063, 3086, 3089, 3107, 3112, 3113 | 3P |
| | | Removal of Passenger Seats | 328 SSG | EO-328-25-310 | 19.10.12 | 1 07.11.12 | EO-328-X | S | | S/N 3060 | 3P |
| | | Inst.of Repl.Flight Contr.Cabl./New Supp.Brack. | 328 SSG | EO-328-27-191 | 22.11.01 | 2 30.01.08 | EO-328-X | S | | S/N 3060 | 3P |
| | | Navig.- Retrofit of GPS Honeywell | 328 SSG | EO-328-34-225 | 15.09.05 | | EO-328-X | S | | S/N 3060 | 3P |
| | | Equipment and Furnishings - Installation of 32 Pax Life Vests (256K010C) | 328 SSG | EO-328-25-390 | 04.07.22 | 1 11.07.22 | EO-328-X | S | | S/N 3061 | 3P |
| | | Placards and Markings - Installation of interior placards in German/English | 328 SSG | EO-328-11-332 | 11.04.15 | 1 14.12.18 | EO-328-X | S | | S/N 3061, 3063 | 3P |
| | | Installation of Name Plates | 328 SSG | EO-328-11-082 | 18.04.97 | | EO-328-X | S | | S/N 3062, 3069 | 3P |
| | | 2nd Handset at Galley Station | 328 SSG | EO-328-23-107 | 08.05.98 | | EO-328-X | S | | S/N 3062, 3069 | 3P |
| | | from 31 Pax to 32 Pax | 328 SSG | EO-328-25-055 | 24.04.96 | | EO-328-X | S | | S/N 3062, 3069 | 3P |
| | | Retrofit of Life Vests | 328 SSG | EO-328-25-058 | 14.05.96 | | EO-328-X | S | | S/N 3062, 3069 | 3P |
| | | Change of placard and markings | 328 SSG | EO-328-11-152 | 26.03.99 | 4 15.06.99 | EO-328-X | S | | S/N 3062, 3069, 3098 | 3P |
| | | Communications - Removal of Cabin Briefing System (FA) | 328 SSG | EO-328-23-334 | 07.05.15 | | EO-328-X | S | | S/N 3063 | 3P |
| | | Installation new Floor Covering | 328 SSG | EO-328-25-084 | 24.06.97 | | EO-328-X | S | | S/N 3063 | 3P |
| | | Equipment / Furnishing - Layout Change 31 Pax to 32 Pax (Option 259K302) | 328 SSG | EO-328-25-333 | 15.04.15 | | EO-328-X | S | | S/N 3063 | 3P |
| | | Navigation - Retrofit of GPS Honeywell | 328 SSG | EO-328-34-280 | 07.04.11 | | EO-328-X | S | | S/N 3063 | 3P |
| | | Inspect. of Engine Control Cables | 328 SSG | EO-328-76-074 | 22.01.97 | | EO-328-X | S | | S/N 3063 | 3P |
| | | Equipment / Furnishing - Retrofit of GPS Non-Precision Approach | 328 SSG | EO-328-34-323 | 12.12.14 | 2 12.08.19 | EO-328-X | S | | S/N 3063, 3072, 3078, 3088 | 3P |
| | | Roll Spoiler Tube | 328 SSG | EO-328-29-057 | 08.05.96 | | EO-328-X | S | | S/N 3064, 3065 | 3P |
| | | Cabin Layout 32 Pax | 328 SSG | EO-328-25-066 | 06.11.96 | | EO-328-X | S | | S/N 3067 | 3P |
| | | Inst. of new Flight Cont.Cables & Brkts. | 328 SSG | EO-328-27-187 | 25.10.01 | 1 30.01.08 | EO-328-X | S | | S/N 3067 | 3P |
| | | Equip./Furn.- Exch.of Emerg.Loc.Transm. | 328 SSG | EO-328-25-204 | 22.09.04 | 1 24.11.04 | EO-328-X | S | | S/N 3070, 3100 | 3P |
| | | Change of interior markings | 328 SSG | EO-328-00-168 | 08.02.00 | | EO-328-X | S | | S/N 3072 | 3P |
| | | Communication - Installation of HF950 System | 328 SSG | EO-328-23-291 | 22.07.11 | | EO-328-X | S | | S/N 3072 | 3P |
| | | Equipment / Furnishing - Removal of Trolley Stowage (Option 253K020A) | 328 SSG | EO-328-25-320 | 03.12.14 | | EO-328-X | S | | S/N 3072 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Equipment / Furnishing - Removal of Cabin Accessible Baggage Compartment | 328 SSG | EO-328-25-321 | 03.12.14 | | EO-328-X | S | | S/N 3072 | 3P |
| | | Equipment / Furnishing - LOPA Change 31 Pax to 32 Pax Layout | 328 SSG | EO-328-25-322 | 03.12.14 | | EO-328-X | S | | S/N 3072 | 3P |
| | | Change of fuel indic.from lbs to kg | 328 SSG | EO-328-28-164 | 14.01.00 | 1 21.08.00 | EO-328-X | S | | S/N 3072, 3077 | 3P |
| | | Plac.and Mark.-Ch.of ext.cooler | 328 SSG | EO-328-11-142 | 08.02.99 | | EO-328-X | S | | S/N 3073 | 3P |
| | | Plac./Mark.-Chan.of plac.marks | 328 SSG | EO-328-11-146 | 10.03.99 | | EO-328-X | S | | S/N 3073 | 3P |
| | | Nav.-Retr.of Hon.GPS wth.opt. | 328 SSG | EO-328-34-151 | 23.03.99 | | EO-328-X | S | | S/N 3073 | 3P |
| | | Inst.of New Passenger Seat Belt | 328 SSG | EO-328-25-249 | 05.09.08 | | EO-328-X | S | | S/N 3075 | 3P |
| | | Retrofit of optional Equipment | 328 SSG | EO-328-00-111 | 08.07.98 | | EO-328-X | S | | S/N 3077 | 3P |
| | | Change of Interior Placard | 328 SSG | EO-328-11-104 | 16.04.98 | | EO-328-X | S | | S/N 3077 | 3P |
| | | Equipment / Furnishings - Retrofit of 27 pax cabin layout | 328 SSG | EO-328-25-121 | 20.08.98 | | EO-328-X | S | | S/N 3077 | 3P |
| | | Fuel Indication from lbs to kg | 328 SSG | EO-328-28-106 | 07.05.98 | | EO-328-X | S | | S/N 3077 | 3P |
| | | Lights - Removal of Recognition Lights | 328 SSG | EO-328-33-317 | 15.10.14 | | EO-328-X | S | | S/N 3077 | 3P |
| | | Communication - Removal of HF950 System | 328 SSG | EO-328-23-292 | 22.07.11 | | EO-328-X | S | | S/N 3078 | 3P |
| | | DC Junction Box 1VE | 328 SSG | EO-328-24-069 | 23.01.97 | | EO-328-X | S | | S/N 3078 | 3P |
| | | Change of Layout | 328 SSG | EO-328-25-071 | 20.12.96 | | EO-328-X | S | | S/N 3078 | 3P |
| | | Retrofit Placards + 3rd fire ext. | 328 SSG | EO-328-25-077 | 24.03.97 | | EO-328-X | S | | S/N 3078 | 3P |
| | | Change of Layout 3078 | 328 SSG | EO-328-25-078 | 24.05.97 | | EO-328-X | S | | S/N 3078 | 3P |
| | | Doors - Inspection of Passenger,Cargo and Service Doors | 328 SSG | EO-328-52-276 | 14.01.11 | | EO-328-X | S | | S/N 3079, 3080, 3081, 3082, 3092, 3103 | 3P |
| | | Retrofit of Gravel Protection | 328 SSG | EO-328-53-096 | 20.07.98 | 1 31.07.98 | EO-328-X | S | | S/N 3079, 3080, 3081, 3082, 3092, 3103 | 3P |
| | | Modification of HF-System | 328 SSG | EO-328-23-085 | 22.10.97 | 1 22.10.97 | EO-328-X | S | | S/N 3079, 3080, 3082 | 3P |
| | | Retrofit Oxygen Bottle 115 CU.FT. | 328 SSG | EO-328-35-097 | 09.12.97 | | EO-328-X | S | | S/N 3079, 3080, 3082 | 3P |
| | | Prov. for option Gravel Protect. | 328 SSG | EO-328-53-098 | 11.12.97 | 1 26.06.98 | EO-328-X | S | | S/N 3079, 3080, 3082 | 3P |
| | | Prep.of Aircraft after Long Term Stor. | 328 SSG | EO-328-10-217 | 14.03.05 | | EO-328-X | S | | S/N 3083 | 3P |
| | | Passenger Entertainment System | 328 SSG | EO-328-23-076 | 20.03.97 | | EO-328-X | S | | S/N 3083 | 3P |
| | | Equip./Furn.- Mod.for 31 to 32 Pax Layout | 328 SSG | EO-328-25-206 | 01.06.05 | 1 23.08.05 | EO-328-X | S | | S/N 3083 | 3P |
| | | Plac./Mark.-Chan.of ext.color | 328 SSG | EO-328-11-144 | 01.03.99 | 1 30.03.99 | EO-328-X | S | | S/N 3083, 3086 | 3P |
| | | Nav.-Retrof.of opt.Weat.Rad.Hon. | 328 SSG | EO-328-34-102 | 17.02.99 | 1 21.04.99 | EO-328-X | S | | S/N 3083, 3086 | 3P |
| | | Nav.-Retrof. Of GPS NPA | 328 SSG | EO-328-34-139 | 17.02.99 | | EO-328-X | S | | S/N 3083, 3086 | 3P |
| | | Fus.-Inst.of ram.light Grav.Prot. | 328 SSG | EO-328-53-143 | 16.02.99 | 1 30.03.99 | EO-328-X | S | | S/N 3083, 3086 | 3P |
| | | Navig.- Inst.of an ADF II / DME II - system | 328 SSG | EO-328-34-220 | 06.05.05 | | EO-328-X | S | | S/N 3083, 3104 | 3P |
| | | Navig.- Activating of GPS Honeywell | 328 SSG | EO-328-34-230 | 29.03.06 | | EO-328-X | S | | S/N 3084 | 3P |
| | | Retrofit of optional equipment | 328 SSG | EO-328-00-171 | 21.06.00 | | EO-328-X | S | | S/N 3084, 3087, 3088 | 3P |
| | | Retrofit of APU | 328 SSG | EO-328-49-304 | 10.10.12 | | EO-328-X | S | | S/N 3085 | 3P |
| | | Ferry Kits - Installation and Removal | 328 SSG | EO-328-00-197 | 21.03.02 | | EO-328-X | S | | S/N 3086 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Prepar.of Aircraft after Long Term Stor. | 328 SSG | EO-328-10-199 | 17.03.04 | 1 25.03.04 | EO-328-X | S | | S/N 3086 | 3P |
| | | Plac./Mark.-Chan.of ext.col.sch. | 328 SSG | EO-328-11-153 | 30.04.99 | | EO-328-X | S | | S/N 3086 | 3P |
| | | Retrofit of opt.Equipm.(Option 259K269) | 328 SSG | EO-328-25-201 | 10.05.04 | | EO-328-X | S | | S/N 3086 | 3P |
| | | Landing Gear Limitations | 328 SSG | EO-328-32-200 | 29.03.04 | 1 24.05.04 | EO-328-X | S | | S/N 3086 | 3P |
| | | Navigation - Retrofit of ADF II / DME II system | 328 SSG | EO-328-34-254 | 19.02.09 | | EO-328-X | S | | S/N 3086 | 3P |
| | | Fuselage - Provision for Gravel Protection | 328 SSG | EO-328-53-330 | 09.04.15 | | EO-328-X | S | | S/N 3086 | 3P |
| | | Fuselage - Retrofit of option Gravel Protection and High Flotation Tires | 328 SSG | EO-328-53-331 | 09.04.15 | | EO-328-X | S | | S/N 3086 | 3P |
| | | Lights - Removal of Recognition Lights | 328 SSG | EO-328-33-318 | 15.10.14 | 1 12.06.15 | EO-328-X | S | | S/N 3086, 3104 | 3P |
| | | Installation of optional equipment | 328 SSG | EO-328-00-231 | 18.05.06 | | EO-328-X | S | | S/N 3087 | 3P |
| | | Retrofit of optional equipment | 328 SSG | EO-328-00-160 | 24.11.99 | | EO-328-X | S | | S/N 3089 | 3P |
| | | Change of int. Placards a. Marks. | 328 SSG | EO-328-11-118 | 26.08.98 | | EO-328-X | S | | S/N 3089 | 3P |
| | | Auto Flight - Appr.mode ILS CAT II | 328 SSG | EO-328-22-127 | 22.10.98 | | EO-328-X | S | | S/N 3089 | 3P |
| | | Exchange of Emerg.Locator Transm. | 328 SSG | EO-328-25-167 | 21.01.00 | | EO-328-X | S | | S/N 3089 | 3P |
| | | Change of interior design | 328 SSG | EO-328-25-170 | 17.02.00 | | EO-328-X | S | | S/N 3089 | 3P |
| | | Deactiv. of TCAS II (Opt.346-002) | 328 SSG | EO-328-34-123 | 11.09.98 | | EO-328-X | S | | S/N 3089 | 3P |
| | | Placards a.Markings - New Placards | 328 SSG | EO-328-11-178 | 02.03.00 | | EO-328-X | S | | S/N 3089, 3107, 3112, 3113, 3117 | 3P |
| | | Comm.-Inst.of Music Ent.Sys.(Opt. 233-019) | 328 SSG | EO-328-00-238 | 27.08.07 | | EO-328-X | S | | S/N 3090 | 3P |
| | | Replacem.of Flight Phone Duplexer | 328 SSG | EO-328-23-095 | 07.11.97 | | EO-328-X | S | | S/N 3090 | 3P |
| | | Communications - Rem. of Flight Phone opt.231K010 | 328 SSG | EO-328-23-236 | 17.08.07 | | EO-328-X | S | | S/N 3090 | 3P |
| | | Comm.-Inst.of Music Ent.Sys.(Opt. 233-019) | 328 SSG | EO-328-23-239 | 24.08.07 | | EO-328-X | S | | S/N 3090 | 3P |
| | | Electrical Power - 230 V AC and 28 V DC Cabin Power | 328 SSG | EO-328-24-381 | 21.05.21 | | EO-328-X | S | | S/N 3090 | 3P |
| | | Equip./Furn.-Mod.for 31 to 32 Pax Layout | 328 SSG | EO-328-25-240 | 28.08.07 | | EO-328-X | S | | S/N 3090 | 3P |
| | | Equipment and Furnishing - Removal of Passenger Seats | 328 SSG | EO-328-25-359 | 11.05.16 | | EO-328-X | S | | S/N 3090 | 3P |
| | | Equipment and Furnishings - 32 Pax Cabin Layout as part of Private Wings Quick Change Medevac LOPA (Option 259K315B) | 328 SSG | EO-328-25-384 | 27.05.21 | | EO-328-X | S | | S/N 3090 | 3P |
| | | Fuel Sys.-Change of Fuel Ind.from lbs to kg | 328 SSG | EO-328-28-237 | 21.08.07 | 1 07.09.07 | EO-328-X | S | | S/N 3090 | 3P |
| | | Retrofit of option Weather Radar | 328 SSG | EO-328-34-155 | 04.08.99 | | EO-328-X | S | | S/N 3090 | 3P |
| | | Fuselage - Reinforcement of Frames to Stringer 17 | 328 SSG | EO-328-53-380 | 06.04.21 | | EO-328-X | S | | S/N 3090 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Installation of airconditioning ground supply connector | 328 SSG | EO-328-21-257 | 15.02.10 | | EO-328-X | S | | S/N 3091 | 3P |
| | | Equip./Furn.- Mod.from 30 to 31 Pax | 328 SSG | EO-328-25-251 | 17.12.08 | | EO-328-X | S | | S/N 3091 | 3P |
| | | Fuel System - Change of Fuel Indic.from kgs to lbs | 328 SSG | EO-328-28-256 | 02.10.09 | | EO-328-X | S | | S/N 3091 | 3P |
| | | Fuselage - Provision for option Gravel Protection | 328 SSG | EO-328-53-258 | 18.01.10 | | EO-328-X | S | | S/N 3091 | 3P |
| | | Fuselage - Retrofit for option Gravel Protection | 328 SSG | EO-328-53-259 | 18.01.10 | | EO-328-X | S | | S/N 3091 | 3P |
| | | Engine - Installation of Pre SB-328-72-177 engine drain lines for A/C 3091 and 3093 | 328 SSG | EO-328-72-272 | 17.11.10 | 1 14.01.11 | EO-328-X | S | | S/N 3091, 3093 | 3P |
| | | Equip./Furn.- Repl.of non-airworthy seats from MSN 3093 with airworthy seats | 328 SSG | EO-328-25-277 | 15.02.11 | | EO-328-X | S | | S/N 3093 | 3P |
| | | Retrofit of optional Equipment | 328 SSG | EO-328-25-105 | 20.04.98 | 1 19.11.98 | EO-328-X | S | | S/N 3094 | 3P |
| | | Equip./Furn.-Prov.for 24 pax cab. | 328 SSG | EO-328-25-122 | 17.11.98 | | EO-328-X | S | | S/N 3094 | 3P |
| | | Retrofit of 24 pax cabin layout | 328 SSG | EO-328-25-138 | 17.11.98 | | EO-328-X | S | | S/N 3094 | 3P |
| | | Passenger warng.light switch mod. | 328 SSG | EO-328-33-130 | 09.09.98 | | EO-328-X | S | | S/N 3094 | 3P |
| | | Lights - Removal of Logo Light | 328 SSG | EO-328-33-299 | 28.03.12 | | EO-328-X | S | | S/N 3097 | 3P |
| | | Retrofit of optional equipment | 328 SSG | EO-328-00-126 | 21.10.98 | | EO-328-X | S | | S/N 3098 | 3P |
| | | Change of int. Placards a. Marks. | 328 SSG | EO-328-11-119 | 24.08.98 | | EO-328-X | S | | S/N 3098 | 3P |
| | | Uncommanded flap retraction | 328 SSG | EO-328-27-163 | 11.01.00 | | EO-328-X | S | | S/N 3100, 3109 | 3P |
| | | Exchange of ground spoiler act. | 328 SSG | EO-328-27-137 | 25.01.99 | 1 22.06.99 | EO-328-X | S | | S/N 3101 | 3P |
| | | Inst. of Avionic Equipment | 328 SSG | EO-328-31-113 | 21.07.98 | 1 10.08.98 | EO-328-X | S | | S/N 3101 | 3P |
| | | Inst. of a WU-650 Weather Radar | 328 SSG | EO-328-34-108 | 04.05.98 | | EO-328-X | S | | S/N 3101 | 3P |
| | | Inst. of a WU-650 Weath. Rad.unit | 328 SSG | EO-328-34-124 | 11.09.98 | | EO-328-X | S | | S/N 3101 | 3P |
| | | Inst. Avionic Equipment | 328 SSG | EO-328-31-109 | 04.05.98 | | EO-328-X | S | | S/N 3103 | 3P |
| | | WU-650 Weather Radar Unit | 328 SSG | EO-328-34-110 | 17.06.98 | 1 08.09.98 | EO-328-X | S | | S/N 3103 | 3P |
| | | Prep.of Aircraft after Long Term Stor. | 328 SSG | EO-328-10-218 | 14.03.05 | | EO-328-X | S | | S/N 3104 | 3P |
| | | Equip./Furn. - Inst. of ashtrays | 328 SSG | EO-328-25-134 | 08.12.98 | | EO-328-X | S | | S/N 3104 | 3P |
| | | Equip./Furn.- Mod.for 31 to 32 Pax | 328 SSG | EO-328-25-223 | 16.09.05 | | EO-328-X | S | | S/N 3104 | 3P |
| | | Navigation - Retrofit of Honeywell WU-650 WXR | 328 SSG | EO-328-34-513 | 29.01.14 | 1 03.02.14 | EO-328-X | S | | S/N 3104 | 3P |
| | | Navig.- Activ.of ILS Steep App.with FD/AP | 328 SSG | EO-328-34-213 | 10.11.04 | | EO-328-X | S | | S/N 3104, 3106 | 3P |
| | | Retrofit of Optional Equipment | 328 SSG | EO-328-00-226 | 23.09.05 | | EO-328-X | S | | S/N 3106 | 3P |
| | | Retrofit of life vest | 328 SSG | EO-328-25-148 | 10.03.99 | | EO-328-X | S | | S/N 3106 | 3P |
| | | Installation of Avionic Equipment | 328 SSG | EO-328-31-117 | 14.08.98 | | EO-328-X | S | | S/N 3106, 3107 | 3P |
| | | Install. of WU-650 Weather Radar | 328 SSG | EO-328-34-116 | 14.08.98 | 1 08.09.98 | EO-328-X | S | | S/N 3106, 3107 | 3P |
| | | Equip./Furn.- Change 32Pax to 31Pax | 328 SSG | EO-328-25-182 | 19.02.01 | | EO-328-X | S | | S/N 3109 | 3P |
| | | Fus.- Removal of option gravel protection | 328 SSG | EO-328-53-255 | 07.05.09 | 1 09.06.09 | EO-328-X | S | | S/N 3109 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Installation of avionic equipment | 328 SSG | EO-328-31-129 | 17.12.98 | | EO-328-X | S | | S/N 3110 | 3P |
| | | Inst.of a WU-650 weath.radar unit | 328 SSG | EO-328-34-128 | 11.12.98 | | EO-328-X | S | | S/N 3110 | 3P |
| | | Equ.fur.-Inst.of int.plac./mark | 328 SSG | EO-328-11-149 | 16.03.99 | 2 01.10.99 | EO-328-X | S | | S/N 3110, 3119 | 3P |
| | | Equipment / Furnishing - Layout Change 32 Pax Layout Private Wings (Option 259K314A) | 328 SSG | EO-328-25-343 | 24.09.15 | | EO-328-X | S | | S/N 3112 | 3P |
| | | Exchange of supp. R/H wing rib13 | 328 SSG | EO-328-28-156 | 15.01.99 | | EO-328-X | S | | S/N 3112 | 3P |
| | | Commun.-Inst.of a sol.sta.cockp. | 328 SSG | EO-328-31-154 | 26.05.99 | | EO-328-X | S | | S/N 3112, 3113 | 3P |
| | | Retrofit of Optional Equipment | 328 SSG | EO-328-00-205 | 12.10.04 | | EO-328-X | S | | S/N 3117 | 3P |
| | | Retrofit of optional equipment | 328 SSG | EO-328-00-207 | 29.11.04 | | EO-328-X | S | | S/N 3117 | 3P |
| | | Compl.of 28V DC Power Outlet in Cabin | 328 SSG | EO-328-00-214 | 06.12.04 | | EO-328-X | S | | S/N 3117 | 3P |
| | | Electrical Power - Provision for 230 V AC System | 328 SSG | EO-328-24-377 | 26.06.20 | | EO-328-X | S | | S/N 3117 | 3P |
| | | Electrical Power - 230 V AC and 28 V DC Cabin Power | 328 SSG | EO-328-24-378 | 13.08.20 | 1 21.05.21 | EO-328-X | S | | S/N 3117 | 3P |
| | | Equipment and Furnishing - 32 Pax Layout as part of Private Wings Quick Change Medevac LOPA (Option 259K315A) | 328 SSG | EO-328-25-376 | 30.06.20 | | EO-328-X | S | | S/N 3117 | 3P |
| | | Equip./Furn.- Modification for 31 to 32 Pax Layout | 328 SSG | EO-328-25-281 | 15.06.11 | 1 12.01.12 | EO-328-X | S | | S/N 3119 | 3P |
| | | Navigation - Retrofit of GPS Honeywell | 328 SSG | EO-328-34-271 | 23.08.10 | | EO-328-X | S | | S/N 3119 | 3P |
| | | Ferry Kit Installation/Removal | 328 SSG | EO-328-00-002 | 05.12.94 | 5 | EO-328-X | S | | S/N All aircraft | 3P |
| | | Volcanic Ash Encounter | 328 SSG | FOI-328-00-002 | 24.07.01 | | FOI-328-X | S | | | 3P |
| | | Approach & Landing Accident Reduction. | 328 SSG | FOI-328-00-006 | 07.02.02 | | FOI-328-X | S | | | 3P |
| | | Flight Techniques - Landing - Activation of Nosewheel Steering by retarding the Condition Levers | 328 SSG | FOI-328-00-012 | 07.07.10 | | FOI-328-X | S | | | 3P |
| | | Loss of DU1 to DU3 (dark screens) | 328 SSG | FOI-328-24-009 | 07.07.05 | | FOI-328-X | S | | | 3P |
| | | Elevator Disconnect Events | 328 SSG | FOI-328-27-003 | 04.09.01 | | FOI-328-X | S | | | 3P |
| | | Airfoil De-Ice Fail Caution | 328 SSG | FOI-328-30-005 | 23.11.01 | | FOI-328-X | S | | | 3P |
| | | Landing Gear - Test DNLK | 328 SSG | FOI-328-32-011 | 01.03.07 | | FOI-328-X | S | | | 3P |
| | | Navigation - ATC Transponder Operation with ADS-B Out | 328 SSG | FOI-328-34-016 | 16.12.19 | | FOI-328-X | S | | | 3P |
| | | Navigation - EASA SIB 2013-11 ACAS II - Manoeuvres Based on Visual Acquisition of Traffic | 328 SSG | FOI-328-34-017 | 12.02.21 | | FOI-328-X | S | | | 3P |
| | | Oxygen - Risk of Fire and/or Functional Impairment on Unserviceable BE Aerospace Protective Breathing Equipment (PBE) | 328 SSG | FOI-328-35-013 | 23.06.15 | | FOI-328-X | S | | | 3P |
| | | Selection of Ground Idle/Reverse | 328 SSG | FOI-328-76-001 | 24.04.01 | 1 19.12.06 | FOI-328-X | S | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | A Complete list of Major RAS can be found in ALD (TM-ALD-010599-ALL; TM-ALD-010693-ALL) Appendix 3 & 4. If a complete list of RAS is needed, please contact Global Support Centre of Deutsche Aircraft GmbH. | 328 SSG | RAS | | | RAS-328-X | S | | | 3A |
| | | Flight Controls - Spring Tab Inspection | 328 SSG | SB-328-27-423 | 04.02.02 | | SB-328-X | S | | S/N 3001 up to and including 3119 | 3P |
| | | Wings - Ail.Trim Tab - Rep.on Trail.Edge | 328 SSG | SB-328-57-419 | 22.03.02 | | SB-328-X | S | | S/N 3001 up to and including 3119 excluding 3109, 3115, 3117 | 3P |
| | | Lights - Flight Crew Reading Lights | 328 SSG | SB-328-33-369 | 07.05.01 | | SB-328-X | S | | S/N 3003 up to and including 3119 | 3P |
| | | Deicing Syst.-Improved Configurat | 328 SSG | SB-328-30-036 | 16.06.94 | | SB-328-X | S | | S/N 3005 up to 3008 | 3P |
| | | Exchange MLG Leg Uplock Roller | 328 SSG | SB-328-32-017 | 15.03.94 | | SB-328-X | S | | S/N 3005 up to 3008 | 3P |
| | | Modific. Emerg. Gear Extens. Syst | 328 SSG | SB-328-32-018 | 17.03.94 | 2 21.08.14 | SB-328-X | S | | S/N 3005 up to 3008 | 3P |
| | | Nose Wheel Steering-Modif.Wiring | 328 SSG | SB-328-32-029 | 19.05.94 | | SB-328-X | S | | S/N 3005 up to 3008 | 3P |
| | | Modif. Baggage Door Lock Lever | 328 SSG | SB-328-52-027 | 19.05.94 | | SB-328-X | S | | S/N 3005 up to 3008 | 3P |
| | | Empennage - Tail cone drain.Impr. | 328 SSG | SB-328-53-028 | 19.05.94 | | SB-328-X | S | | S/N 3005 up to 3008 | 3P |
| | | Center Fuselage-Reinforc.Frame 24 | 328 SSG | SB-328-53-035 | 08.06.94 | | SB-328-X | S | | S/N 3005 up to 3008 | 3P |
| | | Engine Mount -Rework. Flange Hole | 328 SSG | SB-328-71-023 | 19.04.94 | | SB-328-X | S | | S/N 3005 up to 3008 | 3P |
| | | Exchange Expanding Diameter Pins | 328 SSG | SB-328-71-026 | 28.04.94 | 1 19.05.94 | SB-328-X | S | | S/N 3005 up to 3008 | 3P |
| | | Landing Gear-Hydraulic Fuse | 328 SSG | SB-328-32-048 | 11.08.94 | | SB-328-X | S | | S/N 3005 up to 3008, 3010, 3011, 3012 | 3P |
| | | Oxygen - Exchange of Shuttle Valv | 328 SSG | SB-328-35-096 | 03.04.95 | | SB-328-X | S | | S/N 3005 up to 3010 | 3P |
| | | Landing Gear-MLG Downlock Actuato | 328 SSG | SB-328-32-083 | 14.02.95 | | SB-328-X | S | | S/N 3005 up to 3013, 3015 | 3P |
| | | Landing Gear-Brake Metering Unit | 328 SSG | SB-328-32-049 | 11.08.94 | | SB-328-X | S | | S/N 3005 up to 3014 | 3P |
| | | Top Fairing-Insufficient Clearanc | 328 SSG | SB-328-53-051 | 16.08.94 | | SB-328-X | S | | S/N 3005 up to 3014 | 3P |
| | | Aircondit.-Mod. ECU Turb. Valve | 328 SSG | SB-328-21-044 | 25.09.95 | 1 | SB-328-X | S | | S/N 3005 up to 3015 | 3P |
| | | Exchange Restrictor Chek Valve | 328 SSG | SB-328-32-021 | 24.03.94 | | SB-328-X | S | | S/N 3005 up to 3015 | 3P |
| | | MLG - Removal of Wheel CAPS | 328 SSG | SB-328-32-030 | 19.05.94 | 1 25.09.95 | SB-328-X | S | | S/N 3005 up to 3015 | 3P |
| | | Landing Gear-Water Protect.Connec | 328 SSG | SB-328-32-040 | 24.06.94 | | SB-328-X | S | | S/N 3005 up to 3015 | 3P |
| | | Anti Skid Syst.-Warning Gear Tran | 328 SSG | SB-328-32-041 | 24.06.94 | | SB-328-X | S | | S/N 3005 up to 3015 | 3P |
| | | Landing Gear-Shuttle Valve Manifo | 328 SSG | SB-328-32-042 | 27.06.94 | | SB-328-X | S | | S/N 3005 up to 3015 | 3P |
| | | Landing Gear-Restrictor Valves | 328 SSG | SB-328-32-050 | 16.08.94 | | SB-328-X | S | | S/N 3005 up to 3015 | 3P |
| | | Doors - Antislip covering Steps | 328 SSG | SB-328-52-024 | 19.04.94 | | SB-328-X | S | | S/N 3005 up to 3015 | 3P |
| | | Power Plant - Mod. of Cowl. Doors | 328 SSG | SB-328-71-098 | 13.04.95 | | SB-328-X | S | | S/N 3005 up to 3015 | 3P |
| | | Ice and Rain Protection | 328 SSG | SB-328-30-111 | 21.06.95 | | SB-328-X | S | | S/N 3005 up to 3016 | 3P |
| | | Hydraulik Power-Hydr. Press. Hose | 328 SSG | SB-328-29-084 | 14.02.95 | | SB-328-X | S | | S/N 3005 up to 3019 | 3P |
| | | Wing-Exchange Leading Edge Screws | 328 SSG | SB-328-57-058 | 23.11.94 | | SB-328-X | S | | S/N 3005 up to 3019 | 3P |
| | | Engine-Replace Torque Sign. Condi | 328 SSG | SB-328-77-070 | 29.11.94 | | SB-328-X | S | | S/N 3005 up to 3020 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Propeller-Slip Ring Bonding Path | 328 SSG | SB-328-61-081 | 08.02.95 | | SB-328-X | S | | S/N 3005 up to 3021, 3024, 3028, 3030 and all spare parts on stock | 3P |
| | | Motor Converter Windshield Wiper | 328 SSG | SB-328-30-119 | 26.07.95 | | SB-328-X | S | | S/N 3005 up to 3022 | 3P |
| | | Electr. Power-DC External Power | 328 SSG | SB-328-24-108 | 23.05.95 | 1 20.06.95 | SB-328-X | S | | S/N 3005 up to 3023 | 3P |
| | | Equipm.-Exchange Hinge Bolts | 328 SSG | SB-328-25-057 | 26.01.95 | 1 | SB-328-X | S | | S/N 3005 up to 3023 | 3P |
| | | Electrical Power-Power Contr.Unit | 328 SSG | SB-328-24-061 | 03.11.94 | 1 | SB-328-X | S | | S/N 3005 up to 3024 | 3P |
| | | Electr Power-Avionic Power Supply | 328 SSG | SB-328-24-062 | 12.06.95 | 1 27.06.95 | SB-328-X | S | | S/N 3005 up to 3024 | 3P |
| | | Equipm./Furnish.-Remov. Damp.Foil | 328 SSG | SB-328-25-072 | 16.12.94 | | SB-328-X | S | | S/N 3005 up to 3024 | 3P |
| | | Flight Control-Inst.Reinforcement | 328 SSG | SB-328-27-063 | 31.01.96 | 2 | SB-328-X | S | | S/N 3005 up to 3024 | 3P |
| | | Indication - Modification of avionic power supply | 328 SSG | SB-328-31-062 | 12.06.95 | | SB-328-X | S | | S/N 3005 up to 3024 | 3P |
| | | Navigation-Inst. Isolating Diodes | 328 SSG | SB-328-34-069 | 28.11.94 | | SB-328-X | S | | S/N 3005 up to 3024 | 3P |
| | | Change Model Do 328-100 Mod.00 | 328 SSG | SB-328-00-053 | 05.09.95 | 4 | SB-328-X | S | | S/N 3005 up to 3031 | 3P |
| | | Equipment-Mod.Cup-Holder | 328 SSG | SB-328-25-054 | 16.09.94 | | SB-328-X | S | | S/N 3005 up to 3031 | 3P |
| | | Flight Controls-Hinge Fitting | 328 SSG | SB-328-27-124 | 10.08.95 | 1 11.12.95 | SB-328-X | S | | S/N 3005 up to 3031 | 3P |
| | | Water/Waste-Modif.Water Supply | 328 SSG | SB-328-38-055 | 16.09.94 | | SB-328-X | S | | S/N 3005 up to 3031 | 3P |
| | | Fuselage-Cockpit Window Side Post | 328 SSG | SB-328-53-091 | 23.03.95 | 1 10.05.95 | SB-328-X | S | | S/N 3005 up to 3031 | 3P |
| | | Fuselage-Keel Beam | 328 SSG | SB-328-53-093 | 23.03.95 | 2 02.02.96 | SB-328-X | S | | S/N 3005 up to 3031 | 3P |
| | | Floor Support Structure | 328 SSG | SB-328-53-115 | 01.12.95 | 1 24.03.97 | SB-328-X | S | | S/N 3005 up to 3031 | 3P |
| | | Oxygen - Oxygen Bottle Disch.Hose | 328 SSG | SB-328-35-039 | 24.06.94 | 1 27.07.94 | SB-328-X | S | | S/N 3005 up to 3031 with option 350-003 (Oxygen bottle 115 cuft) installed | 3P |
| | | Power Plant-Bypass Outlet Plate | 328 SSG | SB-328-71-086 | 06.03.95 | | SB-328-X | S | | S/N 3005 up to 3033 | 3P |
| | | Landing Gear-NLG/MLG Uplock | 328 SSG | SB-328-32-085 | 02.03.95 | 1 04.12.95 | SB-328-X | S | | S/N 3005 up to 3034 | 3P |
| | | Fuselage-Cockpit Cross Upper Chan | 328 SSG | SB-328-53-089 | 23.03.95 | 1 10.05.95 | SB-328-X | S | | S/N 3005 up to 3037 | 3P |
| | | MLG - Additional Jacking Point | 328 SSG | SB-328-32-117 | 24.07.95 | | SB-328-X | S | | S/N 3005 up to 3039 with a trailing arm P/N 22435-000-01/02 installed | 3P |
| | | Power Plant - Air-Intake Flange | 328 SSG | SB-328-71-082 | 16.02.95 | | SB-328-X | S | | S/N 3005 up to 3040 with air intake serial numbers 1005, 1007, 1009 to 1018, 1022, 1024, 1025, 1027, 1028, 2032, 1034, to 1037, 1040, to 1042, 1046, 1047, 1051, to 1059, 1061 to 1065, 1067 to 1086, 9001, 9005 to 9010 installed | 3P |
| | | OAT Sensor Prop. De-ice Control | 328 SSG | SB-328-30-130 | 20.10.95 | | SB-328-X | S | | S/N 3005 up to 3041 | 3P |
| | | Anti-Skid Control Unit | 328 SSG | SB-328-32-097 | 23.05.95 | 1 01.06.95 | SB-328-X | S | | S/N 3005 up to 3042 | 3P |
| | | Power Plant-Modific. Aft Cowling | 328 SSG | SB-328-71-077 | 30.01.95 | | SB-328-X | S | | S/N 3005 up to 3042 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Power Plant-Shock Mounts | 328 SSG | SB-328-71-110 | 21.06.95 | | SB-328-X | S | | S/N 3005 up to 3042 | 3P |
| | | Safety Washer Aft Shock Mounts | 328 SSG | SB-328-71-136 | 06.10.95 | | SB-328-X | S | | S/N 3005 up to 3042 | 3P |
| | | Stabilizer-Horiz.Stabil.Lead.Edge | 328 SSG | SB-328-55-103 | 31.05.95 | 2 26.07.95 | SB-328-X | S | | S/N 3005 up to 3042 with horizontal stabilizer leading edge P/N 001B551A2510002 L/H and 001B551A2510003 R/H installed | 3P |
| | | Elevator Cable Tension Regulator | 328 SSG | SB-328-27-116 | 26.09.95 | | SB-328-X | S | | S/N 3005 up to 3045 | 3P |
| | | Placard/Markings-Mark. Cargo Door | 328 SSG | SB-328-11-107 | 10.07.95 | 1 | SB-328-X | S | | S/N 3005 up to 3047 | 3P |
| | | Airc.-Mod. Access Door/Conect.Cov | 328 SSG | SB-328-21-060 | 10.10.94 | | SB-328-X | S | | S/N 3005 up to 3047 | 3P |
| | | Equipm.Furnish.-PSU Units/Channel | 328 SSG | SB-328-25-087 | 29.06.95 | 2 | SB-328-X | S | | S/N 3005 up to 3047 | 3P |
| | | Flaps-Outer Leading Edges | 328 SSG | SB-328-27-109 | 29.05.95 | | SB-328-X | S | | S/N 3005 up to 3047 | 3P |
| | | Doors-Exch. Cargo Door Lock Bolt | 328 SSG | SB-328-52-064 | 09.11.94 | 1 05.08.96 | SB-328-X | S | | S/N 3005 up to 3047 | 3P |
| | | Fuselage-Sealing and mod. Radom | 328 SSG | SB-328-53-067 | 11.11.94 | 1 10.05.95 | SB-328-X | S | | S/N 3005 up to 3047 | 3P |
| | | Fuselage-Cockpit Cross Lower Chan | 328 SSG | SB-328-53-090 | 23.03.95 | 2 03.07.95 | SB-328-X | S | | S/N 3005 up to 3047 | 3P |
| | | Engine Controls-Control Cables | 328 SSG | SB-328-76-073 | 16.12.94 | | SB-328-X | S | | S/N 3005 up to 3047 | 3P |
| | | Doors - Push-Button Latches | 328 SSG | SB-328-52-112 | 21.06.95 | | SB-328-X | S | | S/N 3005 up to 3053 | 3P |
| | | Cockpit Window Heating System | 328 SSG | SB-328-30-134 | 28.09.95 | | SB-328-X | S | | S/N 3005 up to 3056 | 3P |
| | | Proximity Switch Electrical Unit | 328 SSG | SB-328-32-143 | 01.12.95 | 3 31.07.96 | SB-328-X | S | | S/N 3005 up to 3060 | 3P |
| | | Modif. MLG Door Hinges | 328 SSG | SB-328-52-142 | 17.11.95 | | SB-328-X | S | | S/N 3005 up to 3060 | 3P |
| | | By-pass Duct Outlet | 328 SSG | SB-328-71-125 | 25.09.95 | 3 10.05.99 | SB-328-X | S | | S/N 3005 up to 3060 | 3P |
| | | Slush Protect. Covers MLG Bay | 328 SSG | SB-328-30-132 | 11.10.95 | | SB-328-X | S | | S/N 3005 up to 3063 | 3P |
| | | De-icer Aft Section Pipes | 328 SSG | SB-328-30-149 | 18.01.96 | | SB-328-X | S | | S/N 3005 up to 3063 | 3P |
| | | Reinforcement of Frame 23 | 328 SSG | SB-328-53-139 | 29.01.96 | | SB-328-X | S | | S/N 3005 up to 3063 | 3P |
| | | Exchange Auxiliary Feather Relay | 328 SSG | SB-328-61-138 | 13.11.95 | | SB-328-X | S | | S/N 3005 up to 3063 | 3P |
| | | Electrical Wiring of APU Panel | 328 SSG | SB-328-49-133 | 24.10.95 | | SB-328-X | S | | S/N 3005 up to 3063 with installed APU (option 490-001A) | 3P |
| | | Fuselage-Modif. Floor Panel | 328 SSG | SB-328-53-102 | 10.05.95 | 2 01.12.95 | SB-328-X | S | | S/N 3005 up to 3067 | 3P |
| | | Control Column Aileron Pulleys | 328 SSG | SB-328-27-137 | 09.11.95 | 1 17.10.96 | SB-328-X | S | | S/N 3005 up to 3079 | 3P |
| | | Replacem. Aileron Autopilot Cable | 328 SSG | SB-328-27-141 | 16.11.95 | 1 01.12.95 | SB-328-X | S | | S/N 3005 up to 3079 | 3P |
| | | Additional Placard | 328 SSG | SB-328-30-150 | 18.01.96 | | SB-328-X | S | | S/N 3005 up to 3079 | 3P |
| | | Doors - Pax Door Hing Slot Cover | 328 SSG | SB-328-52-128 | 28.08.95 | 1 09.02.96 | SB-328-X | S | | S/N 3005 up to 3079 | 3P |
| | | Secondary Hinge of Cargo Door | 328 SSG | SB-328-52-135 | 05.10.95 | | SB-328-X | S | | S/N 3005 up to 3079 | 3P |
| | | Fuselage - Protect. Bagage Comp. | 328 SSG | SB-328-53-127 | 28.08.95 | 1 25.01.96 | SB-328-X | S | | S/N 3005 up to 3079 | 3P |
| | | Water/Waste - Toilet Power Supply | 328 SSG | SB-328-38-151 | 20.09.96 | 1 | SB-328-X | S | | S/N 3005 up to 3079 ecept 3064, 3065 | 3P |
| | | Pneumatic-ECS flow modification | 328 SSG | SB-328-36-276 | 11.12.98 | 1 28.03.19 | SB-328-X | S | | S/N 3005 up to 3098, 3100 up to 3106, 3109,3110,3112,3113, 3115,3117,3119 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Lights - Potentiometer bracket modif. | 328 SSG | SB-328-33-348 | 08.09.00 | | SB-328-X | S | | S/N 3005 up to 3115 excluding 3007, 3035 | 3P |
| | | uninsulated bonding strap | 328 SSG | SB-328-24-320 | 23.11.99 | | SB-328-X | S | | S/N 3005 up to 3119 | 3P |
| | | Prop.- Insp.of the Pressure Switch Tube | 328 SSG | SB-328-61-326 | 10.05.00 | | SB-328-X | S | | S/N 3005 up to 3119 and all spare parts P/N 001A612A0200002 on stock, excluding A/C 3115 | 3P |
| | | Hydraulic Pow.-Main Filter Packag | 328 SSG | SB-328-29-075 | 23.01.95 | | SB-328-X | S | | S/N 3005 up to 320, 3024, 3025, 3026, 3027 | 3P |
| | | Indic./Rec.- 57 Parameter FDR | 328 SSG | SB-328-31-352 | 19.02.01 | | SB-328-X | S | | S/N 3005 up to and 3119 | 3P |
| | | Ind.& Rec.- Activation of 57 Param. (FDR) | 328 SSG | SB-328-31-354 | 07.05.01 | 1 10.08.05 | SB-328-X | S | | S/N 3005 up to and 3119 | 3P |
| | | Mod. of seal Pax. Serv.& Bagg. Door | 328 SSG | SB-328-52-312 | 20.10.99 | | SB-328-X | S | | S/N 3005 up to and 3119 | 3P |
| | | Power Plant - Insufficient clearance | 328 SSG | SB-328-72-357 | 07.03.01 | | SB-328-X | S | | S/N 3005 up to and 3119 | 3P |
| | | Flight Cont. - Spacer/Elevator (CTR) | 328 SSG | SB-328-27-329 | 30.06.00 | 1 23.11.00 | SB-328-X | S | | S/N 3005 up to and 3119, with installed CTR´s P/N 328100-1M02, P/N 328100-2M02, P/N 328100-1M03 and P/N 328100-2M03 | 3P |
| | | Fuselage - Mod. of Frame 25 | 328 SSG | SB-328-53-204 | 17.02.97 | 1 01.12.97 | SB-328-X | S | | S/N 3005 up to and includind 3016 | 3P |
| | | Fuselage-Improved Drainage | 328 SSG | SB-328-53-233 | 20.06.97 | | SB-328-X | S | | S/N 3005 up to and includind 3085 | 3P |
| | | Electrical Terminals 51VV - 56VV | 328 SSG | SB-328-24-188 | 11.09.96 | | SB-328-X | S | | S/N 3005 up to and including 3015 | 3P |
| | | GPWS-Deletion of Mode 6 Callouts | 328 SSG | SB-328-34-033 | 07.06.94 | 1 26.07.01 | SB-328-X | S | | S/N 3005 up to and including 3015, 3106 | 3P |
| | | Fuselage - Repositioning of cable bracket after modification of Frame 25 | 328 SSG | SB-328-53-551 | 29.06.16 | | SB-328-X | S | | S/N 3005 up to and including 3016 | 3P |
| | | Airfoil Protection Wiring | 328 SSG | SB-328-30-159 | 25.06.99 | 2 24.03.00 | SB-328-X | S | | S/N 3005 up to and including 3024, except 3015, 3020 | 3P |
| | | Flight Path Function | 328 SSG | SB-328-34-157 | 18.03.96 | | SB-328-X | S | | S/N 3005 up to and including 3031 | 3P |
| | | Pulley Box | 328 SSG | SB-328-76-168 | 06.05.96 | | SB-328-X | S | | S/N 3005 up to and including 3033 | 3P |
| | | Elevator - Modificat. of bonding | 328 SSG | SB-328-55-185 | 20.08.96 | 1 17.10.96 | SB-328-X | S | | S/N 3005 up to and including 3037 | 3P |
| | | Propeller Blade Overheat Protect. | 328 SSG | SB-328-30-164 | 30.04.96 | | SB-328-X | S | | S/N 3005 up to and including 3039 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Interchange. of Panel 15VE | 328 SSG | SB-328-31-161 | 18.06.96 | | SB-328-X | S | | S/N 3005 up to and including 3039 | 3P |
| | | Improved cabin light cover | 328 SSG | SB-328-25-208 | 20.02.97 | | SB-328-X | S | | S/N 3005 up to and including 3047 | 3P |
| | | Flight Controls - Drainage | 328 SSG | SB-328-27-191 | 08.10.96 | 1 18.02.97 | SB-328-X | S | | S/N 3005 up to and including 3047 | 3P |
| | | Exch. of Roll-Spoiler Control Rod | 328 SSG | SB-328-27-247 | 19.11.97 | 1 19.02.98 | SB-328-X | S | | S/N 3005 up to and including 3047 | 3P |
| | | Hydraulics - Install. of Placard | 328 SSG | SB-328-29-154 | 30.01.96 | | SB-328-X | S | | S/N 3005 up to and including 3047 | 3P |
| | | Top Fairing Attachment | 328 SSG | SB-328-53-144 | 14.12.95 | 2 18.09.96 | SB-328-X | S | | S/N 3005 up to and including 3047 | 3P |
| | | Keel Beam in MLG Bay | 328 SSG | SB-328-53-156 | 01.03.96 | 3 08.01.97 | SB-328-X | S | | S/N 3005 up to and including 3047 | 3P |
| | | Wing-Reinforcem. Flap Bearing Arm | 328 SSG | SB-328-57-071 | 30.11.94 | 5 07.11.96 | SB-328-X | S | | S/N 3005 up to and including 3047 | 3P |
| | | Mod. of Hinge at Leading Edge One | 328 SSG | SB-328-57-195 | 22.10.96 | 1 09.01.97 | SB-328-X | S | | S/N 3005 up to and including 3047 (with P/N 001 B574A1105 hinge halfs with two (2) securing pins installed) | 3P |
| | | Interchangeabil. Radio Altimeter | 328 SSG | SB-328-34-170 | 31.07.96 | | SB-328-X | S | | S/N 3005 up to and including 3050 | 3P |
| | | Fuselage - Stringers 13 and 14 | 328 SSG | SB-328-53-186 | 02.09.96 | 2 11.03.97 | SB-328-X | S | | S/N 3005 up to and including 3052 | 3P |
| | | Reinforcing Sheets at Frame 7 | 328 SSG | SB-328-53-126 | 08.05.96 | | SB-328-X | S | | S/N 3005 up to and including 3053 | 3P |
| | | Wing - Rear Spar Stringer Modif. | 328 SSG | SB-328-57-145 | 08.10.96 | | SB-328-X | S | | S/N 3005 up to and including 3053 | 3P |
| | | Center Pedestal Attachment Angles | 328 SSG | SB-328-53-092 | 23.03.95 | 3 11.06.96 | SB-328-X | S | | S/N 3005 up to and including 3054 | 3P |
| | | Foil to Refuel Panel Calibr. Plac | 328 SSG | SB-328-28-158 | 18.03.96 | | SB-328-X | S | | S/N 3005 up to and including 3063 | 3P |
| | | Reinforcement Baggage Door Frame | 328 SSG | SB-328-53-147 | 08.10.96 | | SB-328-X | S | | S/N 3005 up to and including 3063 | 3P |
| | | Reinf.Baggage and Pax Door Frames | 328 SSG | SB-328-53-148 | 08.10.96 | | SB-328-X | S | | S/N 3005 up to and including 3063 | 3P |
| | | Wing - Inner Leading Edge No. 1 | 328 SSG | SB-328-57-140 | 24.07.96 | 3 25.06.01 | SB-328-X | S | | S/N 3005 up to and including 3063 | 3P |
| | | Electric. Harness Downlock Sensor | 328 SSG | SB-328-32-163 | 17.04.96 | | SB-328-X | S | | S/N 3005 up to and including 3064 | 3P |
| | | Electric Panel 35VE a. Relay Supp | 328 SSG | SB-328-31-172 | 18.06.96 | | SB-328-X | S | | S/N 3005 up to and including 3065 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Lightweight Windshields | 328 SSG | SB-328-56-165 | 19.04.96 | 1 27.06.96 | SB-328-X | S | | S/N 3005 up to and including 3065 that are equipped with ,,lightweight" front windshields P/N 001A561A0000204 or SPS-DO-328-2-3-1 (L/H) P/N 001A561A0000205 or SPS-DO-328-1-3-1 (R/H) | 3P |
| | | Engine Controls - Leading Edge | 328 SSG | SB-328-76-189 | 13.09.96 | | SB-328-X | S | | S/N 3005 up to and including 3065, excluding 3054, 3061 | 3P |
| | | Engine Control Cables a. Fairlead | 328 SSG | SB-328-76-152 | 06.05.96 | | SB-328-X | S | | S/N 3005 up to and including 3067 ecept 3007, 3013, 3020, 3054, 3061, 3063, 3064 | 3P |
| | | Mod. of Cabin Lights Wiring | 328 SSG | SB-328-33-131 | 22.09.95 | 1 18.02.02 | SB-328-X | S | | S/N 3005 up to and including 3069 | 3P |
| | | Reinforcement Frames 24 and 26 | 328 SSG | SB-328-53-155 | 21.11.96 | | SB-328-X | S | | S/N 3005 up to and including 3069 | 3P |
| | | Torque Signal Conditioner Unit | 328 SSG | SB-328-61-173 | 19.06.96 | | SB-328-X | S | | S/N 3005 up to and including 3069 | 3P |
| | | Lights - Stairway Lights | 328 SSG | SB-328-33-190 | 25.09.96 | | SB-328-X | S | | S/N 3005 up to and including 3072 | 3P |
| | | Improvement to Rudder Drainage | 328 SSG | SB-328-55-201 | 10.01.97 | | SB-328-X | S | | S/N 3005 up to and including 3074 | 3P |
| | | Rear Spar, Cold Expansion of Hole | 328 SSG | SB-328-57-193 | 21.11.96 | | SB-328-X | S | | S/N 3005 up to and including 3075 | 3P |
| | | Waterprotect. Electrical Connect. | 328 SSG | SB-328-24-200 | 10.01.97 | | SB-328-X | S | | S/N 3005 up to and including 3079 | 3P |
| | | Panel 10/11VE Waterprotect. Cover | 328 SSG | SB-328-25-187 | 10.09.96 | | SB-328-X | S | | S/N 3005 up to and including 3079 | 3P |
| | | Fuel - Reloc.of Wiring Harn.at Ref.Panel | 328 SSG | SB-328-28-446 | 01.10.04 | | SB-328-X | S | | S/N 3005 up to and including 3079 | 3P |
| | | De-icer system improvement | 328 SSG | SB-328-30-238 | 21.10.97 | | SB-328-X | S | | S/N 3005 up to and including 3079 | 3P |
| | | Strobe/Nav. Light | 328 SSG | SB-328-33-160 | 28.03.96 | | SB-328-X | S | | S/N 3005 up to and including 3079 | 3P |
| | | Flaps Hinge Bolt at Flap Supp.3/4 | 328 SSG | SB-328-57-197 | 06.12.96 | 1 19.02.97 | SB-328-X | S | | S/N 3005 up to and including 3079 | 3P |
| | | Avionic Ventilation | 328 SSG | SB-328-21-203 | 10.01.97 | | SB-328-X | S | | S/N 3005 up to and including 3081 | 3P |
| | | Doors-Modif. Crew Hatch | 328 SSG | SB-328-52-104 | 11.05.95 | 1 06.05.96 | SB-328-X | S | | S/N 3005 up to and including 3082 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Doors - Modific. Spring Mechanism | 328 SSG | SB-328-52-210 | 12.03.97 | | SB-328-X | S | | S/N 3005 up to and including 3082 | 3P |
| | | Orifice for EFCV | 328 SSG | SB-328-30-214 | 29.04.97 | 1 19.06.97 | SB-328-X | S | | S/N 3005 up to and including 3083 | 3P |
| | | Cockpit Cross Upper Channel | 328 SSG | SB-328-53-192 | 15.10.96 | 3 05.08.97 | SB-328-X | S | | S/N 3005 up to and including 3084 | 3P |
| | | Caution Placard on CPCS-Panel | 328 SSG | SB-328-21-225 | 27.06.97 | | SB-328-X | S | | S/N 3005 up to and including 3086 | 3P |
| | | Inspect. of Double Shuttle Valve | 328 SSG | SB-328-27-236 | 19.08.97 | 1 05.11.97 | SB-328-X | S | | S/N 3005 up to and including 3086 | 3P |
| | | Cockpit Window Heating System | 328 SSG | SB-328-30-206 | 20.02.97 | 1 18.04.97 | SB-328-X | S | | S/N 3005 up to and including 3086 | 3P |
| | | Drainage at Cockpit Side Windows | 328 SSG | SB-328-56-212 | 08.04.97 | | SB-328-X | S | | S/N 3005 up to and including 3086 | 3P |
| | | Reinf. of step insert frame | 328 SSG | SB-328-52-230 | 01.10.97 | | SB-328-X | S | | S/N 3005 up to and including 3087 | 3P |
| | | Exchange Re-Circulation Fan Relay | 328 SSG | SB-328-21-218 | 02.07.97 | | SB-328-X | S | | S/N 3005 up to and including 3089 | 3P |
| | | Install. of Floor Panel Protect. | 328 SSG | SB-328-25-224 | 10.08.98 | 1 | SB-328-X | S | | S/N 3005 up to and including 3089 | 3P |
| | | Fuselage-Improved Drainage | 328 SSG | SB-328-53-244 | 29.08.97 | | SB-328-X | S | | S/N 3005 up to and including 3089 | 3P |
| | | Battery Junction Boxes 6VE a. 7VE | 328 SSG | SB-328-24-259 | 04.05.98 | | SB-328-X | S | | S/N 3005 up to and including 3091 excluding 3081, 3087, 3088 and 3089 | 3P |
| | | Jet Booster Pumps | 328 SSG | SB-328-28-211 | 26.03.97 | | SB-328-X | S | | S/N 3005 up to and including 3093 | 3P |
| | | Mod. of Pax Door Hinge | 328 SSG | SB-328-52-266 | 09.06.98 | | SB-328-X | S | | S/N 3005 up to and including 3093 | 3P |
| | | Passenger warn.light switch modif | 328 SSG | SB-328-33-271 | 17.09.98 | | SB-328-X | S | | S/N 3005 up to and including 3093 and 3095 up to and including 3111 | 3P |
| | | Adjustment of IAC mounting tray | 328 SSG | SB-328-31-287 | 28.01.99 | | SB-328-X | S | | S/N 3005 up to and including 3094 | 3P |
| | | Modification of Aft Avionic Fan | 328 SSG | SB-328-21-215 | 12.06.97 | 1 | SB-328-X | S | | S/N 3005 up to and including 3095 | 3P |
| | | Mod. of Ground Cooling Fan | 328 SSG | SB-328-21-227 | 16.07.97 | | SB-328-X | S | | S/N 3005 up to and including 3095 | 3P |
| | | Installation of additional covers | 328 SSG | SB-328-25-246 | 09.02.98 | | SB-328-X | S | | S/N 3005 up to and including 3095 | 3P |
| | | Flap Actuator Connector Bracket | 328 SSG | SB-328-27-217 | 05.05.97 | 1 11.06.97 | SB-328-X | S | | S/N 3005 up to and including 3095 | 3P |
| | | Missinst. of lockpl. RS actuator | 328 SSG | SB-328-27-263 | 29.06.98 | | SB-328-X | S | | S/N 3005 up to and including 3095 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Syst.-Pressure Dump/Relief Valve | 328 SSG | SB-328-29-205 | 12.02.97 | | SB-328-X | S | | S/N 3005 up to and including 3095 | 3P |
| | | Additional Pressure Relief Valve | 328 SSG | SB-328-30-242 | 21.08.97 | 1 15.01.99 | SB-328-X | S | | S/N 3005 up to and including 3095 | 3P |
| | | Addit. Fuse at Panels 10VE/11VE | 328 SSG | SB-328-31-226 | 16.06.97 | | SB-328-X | S | | S/N 3005 up to and including 3095 | 3P |
| | | Lights - Strobe Light Optic. Lens | 328 SSG | SB-328-33-181 | 03.09.96 | | SB-328-X | S | | S/N 3005 up to and including 3095 | 3P |
| | | Maint. switch for cabin lights | 328 SSG | SB-328-33-223 | 23.09.97 | 1 21.10.98 | SB-328-X | S | | S/N 3005 up to and including 3095 | 3P |
| | | Lights - Boarding light switch overload | 328 SSG | SB-328-33-240 | 05.12.97 | 1 06.06.01 | SB-328-X | S | | S/N 3005 up to and including 3095 | 3P |
| | | Tube with drain at discharge ind. | 328 SSG | SB-328-35-251 | 02.02.98 | | SB-328-X | S | | S/N 3005 up to and including 3095 | 3P |
| | | Doors - Outer Handle Roller | 328 SSG | SB-328-52-088 | 14.03.95 | 3 27.02.97 | SB-328-X | S | | S/N 3005 up to and including 3095 | 3P |
| | | Scuff Plate at Baggage Door | 328 SSG | SB-328-53-167 | 11.06.96 | 1 12.08.96 | SB-328-X | S | | S/N 3005 up to and including 3095 | 3P |
| | | Connect. Frame 6 to Window Side | 328 SSG | SB-328-53-178 | 21.11.96 | 1 21.01.97 | SB-328-X | S | | S/N 3005 up to and including 3095 | 3P |
| | | Connect. Frame 7 to Stringer 15RH | 328 SSG | SB-328-53-179 | 21.11.96 | | SB-328-X | S | | S/N 3005 up to and including 3095 | 3P |
| | | Overload Protect. of Switch 49KF | 328 SSG | SB-328-61-234 | 11.06.97 | 1 23.09.97 | SB-328-X | S | | S/N 3005 up to and including 3095 | 3P |
| | | Take-off Sett. CPCS Control UNIT | 328 SSG | SB-328-76-182 | 14.02.97 | | SB-328-X | S | | S/N 3005 up to and including 3095 | 3P |
| | | APU - Reinforcem. Ejector Nozzle | 328 SSG | SB-328-49-209 | 04.07.97 | | SB-328-X | S | | S/N 3005 up to and including 3095 with APU installed (option 490-001A) | 3P |
| | | Re-orientation of bleed air duct | 328 SSG | SB-328-49-199 | 30.01.97 | | SB-328-X | S | | S/N 3005 up to and including 3096 | 3P |
| | | Mod. of main landing gear strut | 328 SSG | SB-328-32-258 | 30.04.98 | | SB-328-X | S | | S/N 3005 up to and including 3097 with side brace P/N 24260-000-00 installed | 3P |
| | | Drain hole in outer wing | 328 SSG | SB-328-57-255 | 21.01.98 | | SB-328-X | S | | S/N 3005 up to and including 3098 excluding 3089 | 3P |
| | | Ligh.-Inspe.of EBS pow.supp. | 328 SSG | SB-328-33-283 | 23.11.98 | | SB-328-X | S | | S/N 3005 up to and including 3098, 3100, 3101, 3103, 3104, 3106, 3107 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | General Avionic System Upgrade | 328 SSG | SB-328-31-250 | 08.04.98 | 1 03.11.00 | SB-328-X | S | | S/N 3005 up to and including 3098, 3100, 3101, 3103, 3104, 3106, 3107, 3109, 3110 | 3P |
| | | Enh.general avionic system update | 328 SSG | SB-328-31-256 | 08.04.98 | | SB-328-X | S | | S/N 3005 up to and including 3098, 3100, 3101, 3103, 3104, 3106, 3107, 3109, 3110 | 3P |
| | | New location for FDR impact switch | 328 SSG | SB-328-31-275 | 01.09.98 | 1 15.12.00 | SB-328-X | S | | S/N 3005 up to and including 3098, 3100, 3101, 3103, 3104, 3106, 3107, 3109, 3110 | 3P |
| | | LG - Insp.& mod./Slush Pot Bay | 328 SSG | SB-328-32-332 | 04.10.00 | 1 31.10.03 | SB-328-X | S | | S/N 3005 up to and including 3098, 3100, 3101, 3103, 3104, 3106, 3107, 3109, 3110, 3112, 3113, 3115, 3117, 3119 | 3P |
| | | Ind.-Grou.wir.of pan.17VE | 328 SSG | SB-328-31-295 | 05.05.99 | | SB-328-X | S | | S/N 3005 up to and including 3098, 3100, 3101, 3104, 3106, 3106, 3107, 3109, 3110, 3112, 3113, 3115, 3117, 3119 | 3P |
| | | Ice and Rain Protection | 328 SSG | SB-328-30-231 | 02.02.99 | | SB-328-X | S | | S/N 3005 up to and including 3098, 3100, 3101, 3104, 3106, 3107 | 3P |
| | | Modificat. of CPCS control panel | 328 SSG | SB-328-21-261 | 27.01.99 | | SB-328-X | S | | S/N 3005 up to and including 3098, 3100, 3101, 3104, 3106, 3107, 3109, 3110, 3112, 3113, 3115, 3117, 3119 | 3P |
| | | Rudder torsion bar new retainer | 328 SSG | SB-328-27-298 | 26.03.99 | 1 21.11.02 | SB-328-X | S | | S/N 3005 up to and including 3098, 3100, 3101, 3104, 3106, 3107, 3109, 3110, 3112, 3113, 3115, 3117, 3119 | 3P |
| | | Pow.Plan.-Eng.Air Int.Flan.Mod. | 328 SSG | SB-328-71-296 | 25.01.99 | | SB-328-X | S | | S/N 3005 up to and including 3098, 3100, 3101, 3104, 3106, 3107, 3109, 3110, 3112, 3113, 3115, 3117, 3119 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Ice and rain protection - New orifice at the EFCV | 328 SSG | SB-328-30-274 | 11.08.98 | 1 15.01.99 | SB-328-X | S | | S/N 3005 up to and including 3098, 3100, 3103, 3104, 3106, 3107, 3109, 3110 | 3P |
| | | Modificat.of power level/Cond.Lev | 328 SSG | SB-328-76-268 | 11.08.98 | 1 09.12.98 | SB-328-X | S | | S/N 3005 up to and including 3098, 3100, 3103, 3104, 3106, 3107, 3109, 3110 | 3P |
| | | Electrical Power - Nut Replacement | 328 SSG | SB-328-24-362 | 10.01.01 | | SB-328-X | S | | S/N 3005 up to and including 3098, 3101, 3103, 3104, 3106, 3107, 3110, 3112, 3113, 3115, 3119 | 3P |
| | | Fl.Cont.-Mod.of Rud.Pe.Unit | 328 SSG | SB-328-27-270 | 23.03.99 | | SB-328-X | S | | S/N 3005 up to and including 3098, 3101, 3104, 3106, 3107, 3110 | 3P |
| | | Floor Panel Clip Nuts | 328 SSG | SB-328-53-257 | 18.03.98 | 1 03.04.00 | SB-328-X | S | | S/N 3005 up to and including 3101 | 3P |
| | | Doors - Mod.of Pax Door Hinge Supp. | 328 SSG | SB-328-52-460 | 04.02.05 | 2 01.03.12 | SB-328-X | S | | S/N 3005 up to and including 3101, 3103, 3104, 3106, 3109, 3110, 3112, 3113, 3115, 3117, 3119 | 3P |
| | | Flgt.Contr.-Missinst.of push.spac | 328 SSG | SB-328-27-279 | 17.11.98 | | SB-328-X | S | | S/N 3005 up to and including 3103 | 3P |
| | | Reinforcement of Frame 24 and 26 | 328 SSG | SB-328-53-241 | 30.03.98 | 1 20.07.01 | SB-328-X | S | | S/N 3005 up to and including 3103, excluding 3098, 3100 | 3P |
| | | Navig.- Chafing protec.for pitot lines | 328 SSG | SB-328-34-385 | 24.08.01 | | SB-328-X | S | | S/N 3005 up to and including 3107 | 3P |
| | | Guide Roller Contr.Cable Frame 15/19 | 328 SSG | SB-328-27-253 | 16.03.98 | 1 25.10.99 | SB-328-X | S | | S/N 3005 up to and including 3111 | 3P |
| | | Temperature Sensor Connector | 328 SSG | SB-328-32-273 | 03.03.98 | | SB-328-X | S | | S/N 3005 up to and including 3111 | 3P |
| | | Lights - Repl.of stairways light | 328 SSG | SB-328-33-277 | 29.09.98 | | SB-328-X | S | | S/N 3005 up to and including 3111 | 3P |
| | | Reinforcem. Wing Leading Edge | 328 SSG | SB-328-57-198 | 10.03.97 | 1 16.06.97 | SB-328-X | S | | S/N 3005 up to and including 3111 | 3P |
| | | Mod. of Engine Control Cables | 328 SSG | SB-328-76-254 | 30.06.98 | 2 29.11.99 | SB-328-X | S | | S/N 3005 up to and including 3111 | 3P |
| | | Mod. of Engine Control Cables | 328 SSG | SB-328-76-267 | 11.08.98 | 3 28.10.99 | SB-328-X | S | | S/N 3005 up to and including 3111 | 3P |
| | | Equip./Furn.-Observer seat plac. | 328 SSG | SB-328-25-281 | 30.10.98 | | SB-328-X | S | | S/N 3005 up to and including 3111 with option 110J999A installed | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Electr.Power - 12VE Panel Pow.lines | 328 SSG | SB-328-24-311 | 15.05.01 | 1 29.10.03 | SB-328-X | S | | S/N 3005 up to and including 3115 | 3P |
| | | Bracket toilet cable assy | 328 SSG | SB-328-38-294 | 10.04.99 | | SB-328-X | S | | S/N 3005 up to and including 3115 | 3P |
| | | Plac.& Mark.- Dry Nitrogen Only Mark. | 328 SSG | SB-328-11-322 | 15.05.01 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Placards & Markings - Repair & Repr. | 328 SSG | SB-328-11-361 | 10.01.01 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Air Cond.- Water in cabin | 328 SSG | SB-328-21-313 | 30.08.99 | 1 15.03.02 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Modification of recirculation fan | 328 SSG | SB-328-21-315 | 17.02.00 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Auto Flight - Improved FD/AP Control Panel | 328 SSG | SB-328-22-426 | 26.03.02 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Elec. Power - Battery Ovetheat Ind. | 328 SSG | SB-328-24-363 | 18.07.01 | 2 12.03.01 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Elec. Power - Fuel pump wiring check. | 328 SSG | SB-328-24-391 | 11.09.01 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Elec.Pow.- Rev.clamp.of altern.pow.cables | 328 SSG | SB-328-24-433 | 12.04.02 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Equipm./Furn.- New first aid kit | 328 SSG | SB-328-25-300 | 08.09.99 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Equip./Furn.- AOA Sensor Acc.Panel | 328 SSG | SB-328-25-316 | 15.02.00 | 1 09.03.17 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Equip./Furn.- Crash panel attachm. | 328 SSG | SB-328-25-375 | 18.05.01 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Equip./Furn.- Blow out panel Protection. | 328 SSG | SB-328-25-379 | 29.06.01 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Equip./Furn.- Inst.of Protection Plate | 328 SSG | SB-328-25-387 | 24.08.01 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Equipment / Furn. - Cockpit Door Stop. | 328 SSG | SB-328-25-400 | 19.10.01 | 1 25.10.01 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Equipment / Furn. - Crew Door Security Imp. | 328 SSG | SB-328-25-401 | 22.10.01 | 1 25.10.01 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Fire Protec.- Cargo Fire Supp. System | 328 SSG | SB-328-26-321 | 07.04.00 | 6 09.01.22 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Relocation of Auto Pilot Rudder Servo | 328 SSG | SB-328-27-290 | 28.07.00 | 1 08.12.00 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Relocation of Auto Pilot Aileron Servo | 328 SSG | SB-328-27-291 | 27.07.00 | 1 08.12.00 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Relocation of Auto Pilot Elevator Servo | 328 SSG | SB-328-27-292 | 27.07.00 | 1 08.12.00 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Flight Controls - Repl.of double shuttle valve | 328 SSG | SB-328-27-310 | 10.06.00 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Flight Controls - Provisioning for FDR | 328 SSG | SB-328-27-319 | 26.06.00 | 2 03.12.01 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Flight Controls - Potentiom.Lever Insp. | 328 SSG | SB-328-27-359 | 29.03.01 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Flight Contr.- Potentiom.Lever Insp. | 328 SSG | SB-328-27-364 | 26.06.01 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Inst.of Col.Ident.for Flight Contr.Cables&Op.Assys | 328 SSG | SB-328-27-436 | 29.11.02 | 3 13.03.12 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Flight Controls - Edge Protection | 328 SSG | SB-328-27-453 | 29.03.04 | 1 01.09.04 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Fl.Contr.- Rudder Spring Tab Lev.Assy | 328 SSG | SB-328-27-459 | 03.05.04 | 2 08.02.08 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Main Hydraulic Reservoir | 328 SSG | SB-328-29-302 | 13.10.99 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Hydr.Pow.- Exch.of Press.Dump & Rel.Val. | 328 SSG | SB-328-29-333 | 28.08.02 | 1 24.08.04 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Hydr.Pow.- Exch.of Hydr.Accumulators | 328 SSG | SB-328-29-443 | 11.08.04 | 1 23.03.12 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Propeller heating system | 328 SSG | SB-328-30-306 | 02.12.99 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Ice & Rain - Improved maint. to TAZ diodes. | 328 SSG | SB-328-30-415 | 04.12.01 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Ice & Rain Prot.- Insp.of TAZ-diodes/MOV | 328 SSG | SB-328-30-417 | 24.01.02 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Ice & Rain Prot.- Ice Det.Harn.Conn.-Moi.Cont. | 328 SSG | SB-328-30-448 | 13.08.03 | 2 06.07.05 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Comm.- Inst.of (CVR) with clock signal | 328 SSG | SB-328-31-318 | 28.03.01 | 2 30.10.01 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Inst.of new Impact G-switches | 328 SSG | SB-328-31-390 | 06.09.01 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Ind./Rec.- Inst.of ELT Switch Protection. | 328 SSG | SB-328-31-428 | 23.01.02 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Landing Gear - Main Landing Gear | 328 SSG | SB-328-32-344 | 27.11.00 | 1 11.06.01 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Lights - Passenger Lighted Signs | 328 SSG | SB-328-33-299 | 17.07.00 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Navigation - (RVSM) Certification. | 328 SSG | SB-328-34-413 | 14.12.01 | 1 18.11.02 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Navig.- RNZ-851 INU Glide Slope Anomaly | 328 SSG | SB-328-34-452 | 02.03.04 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Navigation - Provisions for EGPWS | 328 SSG | SB-328-34-464 | 05.08.04 | 2 15.10.04 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Doors - Mod.of Pass./Crew Door | 328 SSG | SB-328-52-381 | 11.09.01 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Fuselage - Covering/Doors | 328 SSG | SB-328-53-303 | 16.06.00 | 1 12.03.01 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Fuselage - Inst. of new Floor seal.profiles | 328 SSG | SB-328-53-383 | 22.05.01 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Insp./Rew.of Countersinks in Fuselage Skin | 328 SSG | SB-328-53-398 | 11.06.02 | 1 18.10.04 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Fuselage - RVSM Certification | 328 SSG | SB-328-53-403 | 16.10.01 | 2 13.05.03 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Fuselage - Insp. of drain installation | 328 SSG | SB-328-53-462 | 24.06.04 | 1 15.07.04 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Rudder Spring Tab - Bolt Replacement | 328 SSG | SB-328-55-351 | 10.04.01 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Stabil.- Screw Repl.in Rudder & Elev. | 328 SSG | SB-328-55-368 | 10.04.01 | 1 11.12.01 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Stabilizer - Tolerance Adj. Panel | 328 SSG | SB-328-55-370 | 11.05.01 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Stab.- Elev.Trim Tabs - Rep.on Trail.Edge | 328 SSG | SB-328-55-407 | 20.03.02 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Revised tight. torque Elev.Trim Tab | 328 SSG | SB-328-55-422 | 08.02.02 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Wing - Aileron Trim Tab Bolt Replac. | 328 SSG | SB-328-57-350 | 29.11.00 | 2 16.01.02 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Wings - Flap Inspection Holes | 328 SSG | SB-328-57-411 | 20.11.01 | 1 23.01.02 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Propellers - Inspection of Propeller hub | 328 SSG | SB-328-61-328 | 17.07.00 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Eng.Cont.- Cont. Cable Replacement | 328 SSG | SB-328-76-365 | 11.04.01 | 1 05.11.03 | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Starter - Retrofit Starter Gen. Baffle | 328 SSG | SB-328-80-378 | 13.07.01 | | SB-328-X | S | | S/N 3005 up to and including 3119 | 3P |
| | | Spr.Tab - Repair on Trailing Edge | 328 SSG | SB-328-55-307 | 01.12.99 | 1 02.03.00 | SB-328-X | S | | S/N 3005 up to and including 3119 and all spare parts, excluding spring tab S/N 1146, 9061 and up | 3P |
| | | Navigation - Activating of TCAS | 328 SSG | SB-328-34-095 | 03.04.95 | 4 26.11.00 | SB-328-X | S | | S/N 3005 up to and including 3119 with complete provisions for TCAS (option 346K008) installed | 3P |
| | | Equip./Furn.- ELT 110 syst.to ELT 96 syst. | 328 SSG | SB-328-25-466 | 17.09.04 | 1 14.01.05 | SB-328-X | S | | S/N 3005 up to and including 3119 with ELT option 256J998 installed | 3P |
| | | Equip./Furn.- ELT 96 Antenna repl. | 328 SSG | SB-328-25-386 | 17.08.01 | | SB-328-X | S | | S/N 3005 up to and including 3119 with ELT96 system installed | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | LG - Insp./Check of several LG Bolts | 328 SSG | SB-328-32-414 | 03.12.01 | 1 10.10.03 | SB-328-X | S | | S/N 3005 up to and including 3119 with threshold more than 4000FH or 24 Month since new | 3P |
| | | Flight Cont. - Spacer/Aileron Cable (CTR) | 328 SSG | SB-328-27-324 | 27.06.00 | 1 23.11.00 | SB-328-X | S | | S/N 3005 up to and including 3119, with CTR´s P/N 328300-1M01Amdt.1, P/N 328300-2M01Amdt.A installed | 3P |
| | | Repl. of Service Door Scuff Plate | 328 SSG | SB-328-53-260 | 03.03.98 | | SB-328-X | S | | S/N 3005 up to and including 3127 | 3P |
| | | Stabilizer- Replacement of Rudder fasteners | 328 SSG | SB-328-55-314 | 26.10.99 | | SB-328-X | S | | S/N 3005 up to and including 3143 | 3P |
| | | Nav.- dist.betw.co-ax.cables & APU bleedl. | 328 SSG | SB-328-34-389 | 04.09.01 | | SB-328-X | S | | S/N 3005 up to and including 3143 with installed APU | 3P |
| | | Pneum.- Repos.of the Cross Bleed Valve | 328 SSG | SB-328-36-394 | 21.09.01 | 1 10.12.01 | SB-328-X | S | | S/N 3005 up to and including 3204 | 3P |
| | | Doors - Inst.of Protect.Tape | 328 SSG | SB-328-52-392 | 11.09.01 | | SB-328-X | S | | S/N 3005 up to and inclunding 3119, excluding 3100 | 3P |
| | | Fuel vent float valve | 328 SSG | SB-328-28-309 | 27.06.99 | | SB-328-X | S | | S/N 3005 up to including 3113, excluding 3107 | 3P |
| | | Fire Prot.- Circuit Breaker Wiring Check | 328 SSG | SB-328-26-377 | 18.06.01 | | SB-328-X | S | | S/N 3005 up to including 3119 with installed option 262K004 | 3P |
| | | Uncommanded flap retraction | 328 SSG | SB-328-27-293 | 10.11.99 | | SB-328-X | S | | S/N 3005 up to including 3119, excluding 3100 and 3109 | 3P |
| | | Exchange of electrical Wires | 328 SSG | SB-328-24-001 | 06.12.93 | | SB-328-X | S | | S/N 3005, 3006 | 3P |
| | | Exchange of Double Shuttle Valve | 328 SSG | SB-328-27-002 | 06.07.94 | 3 | SB-328-X | S | | S/N 3005, 3006 | 3P |
| | | Install. Additional Fasteners | 328 SSG | SB-328-53-010 | 17.01.94 | | SB-328-X | S | | S/N 3005, 3006 | 3P |
| | | Noise reduction at main plenum | 328 SSG | SB-328-21-011 | 04.02.94 | | SB-328-X | S | | S/N 3005, 3006, 3007 | 3P |
| | | Install. Switch Rod Flight Contr. | 328 SSG | SB-328-22-006 | 20.01.94 | 1 | SB-328-X | S | | S/N 3005, 3006, 3007 | 3P |
| | | Check AC Main Pump Contr. Light | 328 SSG | SB-328-29-025 | 28.04.94 | | SB-328-X | S | | S/N 3005, 3006, 3007 | 3P |
| | | Hydr.Power-Exch. Press.Sens.Valve | 328 SSG | SB-328-29-037 | 17.07.94 | | SB-328-X | S | | S/N 3005, 3006, 3007 | 3P |
| | | Install. Addit. Pressure Regulato | 328 SSG | SB-328-30-008 | 23.12.93 | | SB-328-X | S | | S/N 3005, 3006, 3007 | 3P |
| | | Exchange Quick Release Fasteners | 328 SSG | SB-328-53-009 | 28.12.93 | | SB-328-X | S | | S/N 3005, 3006, 3007 | 3P |
| | | Vert.Stab.-Reinforcement of stringers. | 328 SSG | SB-328-55-003 | 20.12.93 | 1 13.09.94 | SB-328-X | S | | S/N 3005, 3006, 3007 | 3P |
| | | Exchange of Diagonal Brace | 328 SSG | SB-328-57-013 | 04.03.94 | | SB-328-X | S | | S/N 3005, 3006, 3007 | 3P |
| | | Wing/Fuselage Steel Nuts | 328 SSG | SB-328-57-014 | 04.03.94 | 1 30.05.94 | SB-328-X | S | | S/N 3005, 3006, 3007 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Wing-Chafing Protect.Wiring Harn. | 328 SSG | SB-328-57-038 | 24.06.94 | 1 09.02.95 | SB-328-X | S | | S/N 3005, 3006, 3007 | 3P |
| | | Inst. Low Oil Press. Sensor Ampli | 328 SSG | SB-328-61-007 | 27.12.93 | 1 05.07.94 | SB-328-X | S | | S/N 3005, 3006, 3007 | 3P |
| | | Power Plant-Mod. of Lower Cowling | 328 SSG | SB-328-71-043 | 27.06.94 | 1 08.05.95 | SB-328-X | S | | S/N 3005, 3006, 3007 | 3P |
| | | Install. Improved Oil-Coolers | 328 SSG | SB-328-79-005 | 22.12.93 | | SB-328-X | S | | S/N 3005, 3006, 3007 | 3P |
| | | Replacement of Autopilot Servo | 328 SSG | SB-328-27-019 | 21.03.94 | | SB-328-X | S | | S/N 3005, 3006, 3007, 3008 | 3P |
| | | Elevat.Horn Deice - Modif. Wiring | 328 SSG | SB-328-30-034 | 08.06.94 | | SB-328-X | S | | S/N 3005, 3006, 3007, 3008, 3009, 3010, 3011 | 3P |
| | | Modification of Wiring | 328 SSG | SB-328-34-016 | 11.03.94 | | SB-328-X | S | | S/N 3005, 3006, 3007, 3008, 3010 | 3P |
| | | Modification of Attachment | 328 SSG | SB-328-53-012 | 18.02.94 | 1 07.03.94 | SB-328-X | S | | S/N 3005, 3006, 3007, 3008, 3010 | 3P |
| | | Provisions Head up Guidance Syste | 328 SSG | SB-328-34-074 | 11.04.96 | 3 | SB-328-X | S | | S/N 3005, 3006, 3007, 3008, 3010, 3011, 3012, 3013, 3014, 3015, 3017, 3020, 3024, 3027, 3029, 3034 | 3P |
| | | Headup Guidance System-Power Supp | 328 SSG | SB-328-31-121 | 02.08.95 | 2 02.04.96 | SB-328-X | S | | S/N 3005, 3006, 3007, 3008, 3010, 3011, 3012, 3013, 3014, 3015, 3017, 3020, 3024, 3027, 3029, 3034, 3036 | 3P |
| | | Navigation - Retrofit of GPS Honeywell | 328 SSG | SB-328-34-565 | 18.10.17 | | SB-328-X | S | | S/N 3005, 3006, 3023, 3088, 3110 | 3P |
| | | MLG Longitudinal Beam | 328 SSG | SB-328-53-184 | 10.01.97 | 1 02.07.97 | SB-328-X | S | | S/N 3005, 3008, 3009, 3011 and up to and including 3079 | 3P |
| | | Wings - Insp.of Grnd.Spoiler Support Arms | 328 SSG | SB-328-57-435 | 27.06.02 | 2 06.05.03 | SB-328-X | S | | S/N 3005, 3009, 3016, 3023-3027, 3031, 3034-3036, 3040-3042, 3046, 3048-3050, 3054, 3058, 3062, 3063, 3066, 3067, 3069, 3071, 3074, 3078-3083, 3085, 3086, 3090-3098, 3100, 3101, 3103, 3104, 3106, 3107, 3109, 3110-3113, 3115, 3117, 3119 | 3P |
| | | Supp. Bracket No.8 Ground-Spoiler | 328 SSG | SB-328-57-120 | 30.11.95 | 3 29.09.98 | SB-328-X | S | | S/N 3005, 3009, 3023, 3025, 3035, 3036, 3040 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Insp./Adjust.of the Ground Spoiler | 328 SSG | SB-328-57-439 | 24.01.03 | 1 10.03.03 | SB-328-X | S | | S/N 3005, 3009, 3023-3027, 3031, 3034-3036, 3040-3042, 3046, 3048-3050, 3058, 3062, 3063, 3066, 3067, 3069, 3071, 3074, 3078-3083, 3085, 3086, 3090-3098, 3100, 3101, 3103, 3104, 3106, 3107, 3109, 3110, 3112, 3113, 3115, 3117, 3119 | 3P |
| | | Propeller - Change Sensor Tube | 328 SSG | SB-328-61-045 | 29.07.94 | | SB-328-X | S | | S/N 3006 up to 3012 | 3P |
| | | Exchange of Shock Mounts | 328 SSG | SB-328-71-004 | 22.12.93 | 2 05.04.94 | SB-328-X | S | | S/N 3006, 3007, 3008 | 3P |
| | | Exchange of Front Row Seats | 328 SSG | SB-328-25-169 | 03.06.96 | | SB-328-X | S | | S/N 3006, 3007, 3008, 3010, 3012, 3013, 3014, 3015, 3018, 3019, 3020, 3025, 3027,3028, 3029, 3030, 3032,3033, 3035, 3037,3038, 3039,3040, 3043,3044, 3045, 3047, 3048, 3050, 3051, 3052, 3055, 3056, 3057,3058, 3059,3060, 3061, 3064, 3065, 3070 | 3P |
| | | Third Nav-Unit for HGS. | 328 SSG | SB-328-34-232 | 05.11.97 | 1 | SB-328-X | S | | S/N 3006, 3007, 3008, 3010, 3012, 3013, 3014, 3015, 3020, 3024, 3027, 3029, 3034, 3049, 3064, 3065, 3067, 3071, 3074 | 3P |
| | | Equipm./Furnish.-Galley Hot Jugs | 328 SSG | SB-328-25-106 | 22.05.95 | | SB-328-X | S | | S/N 3006, 3007, 3008, 3010, 3012, 3013, 3014, 3015, 3020, 3029 with option 253K018A installed | 3P |
| | | Equipment/Furnishings - Installation of Trolly Stowage | 328 SSG | SB-328-25-550 | 02.06.16 | | SB-328-X | S | | S/N 3006, 3022, 3023, 3035, 3088, 3110 | 3P |
| | | Equipment/Furnishings - Installation of Trolley Stowage in Baggage Compartment | 328 SSG | SB-328-25-552 | 15.07.16 | | SB-328-X | S | | S/N 3006, 3022, 3023, 3035, 3088, 3110 | 3P |
| | | Navigation - Installation of SBAS GNSSU | 328 SSG | SB-328-34-560 | 23.08.17 | 2 09.03.20 | SB-328-X | S | | S/N 3006, 3035 and 3110 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Equipment-Improv. Crew Seats | 328 SSG | SB-328-25-113 | 18.09.96 | 2 | SB-328-X | S | | S/N 3006-3008, 3010, 3012-3015, 3018-3021, 3024, 3025, 3027-3030, 3032-3035, 3037-3040 | 3P |
| | | Wings - Balancing of ailerons | 328 SSG | SB-328-57-249 | 18.12.97 | 1 09.10.01 | SB-328-X | S | | S/N 3009 up to and including 3063 with aileron S/N 1009 up to 1063 installed | 3P |
| | | Inspec. of Cabin Baggage Comp. Door | 328 SSG | SB-328-25-327 | 25.07.00 | | SB-328-X | S | | S/N 3009, 3024, 3034, 3072, 3078, 3085, 3094, 3096 with option 524K001 installed | 3P |
| | | Communications - Installation of HF Wire Antenna | 328 SSG | SB-328-23-571 | 17.09.18 | 1 21.01.20 | SB-328-X | S | | S/N 3013 | 3P |
| | | Indicating/Recording Systems - Retrofit of DL-1000 Data Loader | 328 SSG | SB-328-31-546 | 28.06.17 | | SB-328-X | S | | S/N 3013, 3015, 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, 3106 | 3P |
| | | Navigation - Replacement of CD-810 with CD-830 | 328 SSG | SB-328-34-547 | 11.10.17 | 1 25.10.19 | SB-328-X | S | | S/N 3013, 3015, 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, 3106 | 3P |
| | | Navigation - Retrofit of Honeywell PRIMUS 880 Weather Radar | 328 SSG | SB-328-34-555 | 12.07.17 | 2 22.06.21 | SB-328-X | S | | S/N 3013, 3015, 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3091, 3093, 3097, 3104, 3106 | 3P |
| | | Hydraulic Power - Lockwire securing of union at tube assembly connecting to the pressure sensing valve | 328 SSG | SB-328-29-533 | 10.08.15 | 2 02.05.16 | SB-328-X | S | | S/N 3013, 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, 3106 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Doors- Improvement of Landing Light Access Door Security | 328 SSG | SB-328-52-531 | 14.08.15 | 3 13.02.19 | SB-328-X | S | | S/N 3013, 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, 3106 | 3P |
| | | HORIZON Cabin Layout 30 Passenger | 328 SSG | SB-328-25-052 | 25.08.94 | | SB-328-X | S | | S/N 3015 | 3P |
| | | Towing and Taxiing - Towbarless towing (Option 091K001) | 328 SSG | SB-328-09-572 | 07.12.18 | 1 16.12.19 | SB-328-X | S | | S/N 3015 / Certified towbarless towing vehicles: MOTOTOK Model TWIN 6500 AC-DC; LEKTRO Model AP8850SDA 120/80/50/20 [Only with aircraft ramp weight selection panel]; LEKTRO Model AP8850SDA-AL 120/80/50/20 [Only with aircraft ramp weight selection panel] | 3P |
| | | Lights - LED Navigation and Strobe Lights | 328 SSG | SB-328-33-576 | 12.08.22 | 1 20.09.22 | SB-328-X | S | | S/N 3016, 3020, 3025, 3026, 3031, 3040, 3047, 3050, 3058, 3060, 3061, 3068, 3075, 3077, 3085, 3086, 3091, 3093, 3097, 3104, 3106 | 3P |
| | | Indicating/Recording Systems - Honeywell DU-875 Software Update | 328 SSG | SB-328-31-564 | 28.02.18 | | SB-328-X | S | | S/N 3016, 3020, 3025, 3047, 3075, 3086, 3097, 3106 with Display Unit Honeywell DU-875 P/N K9321060A04 installed | 3P |
| | | Modification of Return Line | 328 SSG | SB-328-29-237 | 10.09.97 | 2 10.06.16 | SB-328-X | S | | S/N 3016, 3024, 3025, 3026, 3027, 3031, 3034, 3042, 3046, 3049, 3054, 3062, 3066, 3067, 3069, 3071, 3074, 3078, 3079, 3080, 3081, 3082, 3083, 3085, 3086 with avtive groundspoiler installed (option 040-001) | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Exchange Relief Restrictor Valve | 328 SSG | SB-328-27-243 | 23.09.97 | 2 10.06.16 | SB-328-X | S | | S/N 3016, 3024, 3025, 3026, 3027, 3031, 3034, 3042, 3046, 3049, 3054, 3062, 3066, 3067, 3069, 3071, 3074, 3078, 3079, 3080, 3081, 3082, 3083, 3085, 3086, 3090, 3091, 3092, 3093, 3094, 3095, 3096, 3097, 3098 (with installed option Groundspoiler 040-001) | 3P |
| | | Replacem. Groundspoil.Valve Block | 328 SSG | SB-328-27-228 | 22.07.97 | 2 10.06.16 | SB-328-X | S | | S/N 3016, 3024, 3025, 3026, 3027, 3031, 3034, 3042, 3046, 3049, 3054, 3062, 3066, 3067, 3069, 3071, 3074, 3078, 3079, 3080, 3081, 3083, 3085, 3086, 3090, 3091, 3092, 3093, 3094, 3095 (all a/c with installed active groundspoiler (option 040-001)) | 3P |
| | | Airb.Auxil. Power-Retrofit System | 328 SSG | SB-328-49-099 | 18.04.95 | 2 15.05.95 | SB-328-X | S | | S/N 3016, 3024, 3026, 3027, 3030, 3031, 3032, 3033 | 3P |
| | | Activation of Ground Spoilers | 328 SSG | SB-328-27-162 | 16.10.96 | 2 19.01.01 | SB-328-X | S | | S/N 3016, 3024, 3026, 3027, 3031, 3034 | 3P |
| | | Modification of return line | 328 SSG | SB-328-29-269 | 16.07.98 | | SB-328-X | S | | S/N 3016, 3024, 3027, 3031, 3034, 3042, 3046, 3049, 3054, 3062, 3066, 3067, 3069, 3071, 3074, 3078, 3079, 3080, 3081, 3082, 3083, 3085, 3086 with active groundspoiler installed (option 040-001) | 3P |
| | | Indicating/Recording Systems - Honeywell DU-875 LCD | 328 SSG | SB-328-31-534 | 20.01.16 | 2 29.11.17 | SB-328-X | S | | S/N 3019, 3026, 3031, 3040, 3050, 3058, 3060, 3068, 3077, 3085, 3091, 3093, 3104 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Navigation - Upgrade to SBAS GNSSU | 328 SSG | SB-328-34-566 | 23.03.18 | 7 09.11.20 | SB-328-X | S | | S/N 3019, 3053, 3059, 3061, 3063, 3072, 3083, 3087, 3088, 3090, 3112, 3113, 3117, 3119 | 3P |
| | | Navigation - Dual ADS-B Out Upgrade | 328 SSG | SB-328-34-567 | 23.03.18 | 7 09.11.21 | SB-328-X | S | | S/N 3019, 3053, 3059, 3061, 3063, 3072, 3083, 3087, 3088, 3090, 3112, 3113, 3117, 3119 | 3P |
| | | Navigation-Provisions for TCAS | 328 SSG | SB-328-34-065 | 09.11.94 | 1 22.01.01 | SB-328-X | S | | S/N 3022, 3023, 3024 | 3P |
| | | Communications-Cabin Briefing Sys | 328 SSG | SB-328-23-068 | 17.11.94 | | SB-328-X | S | | S/N 3024 | 3P |
| | | Equip. Furnish-Baggage Compartm. | 328 SSG | SB-328-25-066 | 10.11.94 | | SB-328-X | S | | S/N 3024 | 3P |
| | | Struct. Alternat. Hatrack Bin 5 | 328 SSG | SB-328-25-146 | 18.12.95 | | SB-328-X | S | | S/N 3025 up to 3034 | 3P |
| | | Airfoil de-ice tube | 328 SSG | SB-328-30-265 | 24.07.98 | | SB-328-X | S | | S/N 3042 up to and including 3105 | 3P |
| | | Wings - Chafing at Engine Harness | 328 SSG | SB-328-57-538 | 17.08.18 | 1 01.03.19 | SB-328-X | S | | S/N 3048-3111 | 3P |
| | | Cockpit Seat Restraint Systems | 328 SSG | SB-328-25-222 | 06.06.97 | | SB-328-X | S | | S/N 3053, 3054, 3066, 3070 with restraint systems P/N 1180002-403-100, serial numbers 0197 up to and including 0203 installed | 3P |
| | | Equipment/Furnishings - Replacement of felt material in Emergency Equipment Stowage | 328 SSG | SB-328-25-521 | 28.07.14 | | SB-328-X | S | | S/N 3053, 3063, 3078, 3094, 3096, 3100, 3117 | 3P |
| | | Equipment/Furnishing - Layout 30PAX with Quick Change Wardrobe (Option 259K311A) | 328 SSG | SB-328-25-520 | 27.08.14 | | SB-328-X | S | | S/N 3055 | 3P |
| | | Install. of a Protection Shield | 328 SSG | SB-328-52-235 | 06.05.97 | | SB-328-X | S | | S/N 3064 up to and including 3086 | 3P |
| | | Missed rivets on landing flap arm | 328 SSG | SB-328-57-239 | 07.07.97 | 1 27.02.19 | SB-328-X | S | | S/N 3064 up to and including 3086 | 3P |
| | | Exchange of Roll Spoiler Tube | 328 SSG | SB-328-29-194 | 17.10.96 | | SB-328-X | S | | S/N 3064, 3065 | 3P |
| | | Modification of power distribution logic | 328 SSG | SB-328-25-325 | 23.05.00 | | SB-328-X | S | | S/N 3078 | 3P |
| | | Equipment/Furnishings - TJS 31 PAX Cabin Layout with Hatracks (Option 259K110) | 328 SSG | SB-328-25-563 | 19.09.17 | | SB-328-X | S | | S/N 3078 | 3P |
| | | Flight Controls - Visual Insp.of flight control pulleys and cables betw.frame 25 + 26 L/H + R/H | 328 SSG | SB-328-27-498 | 15.11.11 | | SB-328-X | S | | S/N 3078 | 3P |
| | | Navigation - Removal of option (343K005A) - provisions for HGS | 328 SSG | SB-328-34-540 | 09.10.15 | 1 04.05.21 | SB-328-X | S | | S/N 3086, 3090 | 3P |
| | | Aircraft General - Change of Model Dornier 328-100 Mod. to Dornier 328-100 Mod. 10 | 328 SSG | SB-328-00-549 | 03.06.16 | | SB-328-X | S | | S/N 3087 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Fuselage - Inst. of Wedge for Light Gravel Protection | 328 SSG | SB-328-53-585 | 27.04.22 | | SB-328-X | S | | S/N 3088 | 3P |
| | | Equipment/Furnishing - LOPA Change from 32pax to 19pax | 328 SSG | SB-328-25-588 | 15.02.23 | | SB-328-X | S | | S/N 3090 | 3P |
| | | Elec.Pow.- Insp.Cable Bundle APU | 328 SSG | SB-328-24-404 | 10.12.01 | | SB-328-X | S | | S/N 3096 up to and including 3107 | 3P |
| | | Inspection of the engine control box | 328 SSG | SB-328-76-341 | 24.08.00 | | SB-328-X | S | | S/N 3098 up to and including 3119 with installed engine control box S/N 1100-1111 (P/N 001A761A1010006 or P/N 001A761A1010008) | 3P |
| | | Electrical Power - Retrofit of 40 Ah Marathon Batteries | 328 SSG | SB-328-24-509 | 19.03.13 | | SB-328-X | S | | S/N 3100 | 3P |
| | | Communications - Deactivation of Dual KHF 950 | 328 SSG | SB-328-23-512 | 19.12.13 | 1 06.03.14 | SB-328-X | S | | S/N 3109 | 3P |
| | | Installation of Alternate Cockpit Door | 328 SSG | SB-328-52-511 | 27.11.13 | | SB-328-X | S | | S/N 3109 | 3P |
| | | Elec.Pow.- Inst.of Cable Attach.Brack. | 328 SSG | SB-328-24-384 | 08.08.01 | | SB-328-X | S | | S/N 3109, 3110, 3112, 3113, 3115, 3117, 3119 | 3P |
| | | Equipment/Furnishing - LOPA Change from 32pax to 19pax | 328 SSG | SB-328-25-589 | 15.02.23 | | SB-328-X | S | | S/N 3112 | 3P |
| | | Equip./Furnish. - Music Entert. Cabinet | 328 SSG | SB-328-25-371 | 16.05.01 | | SB-328-X | S | | S/N 3115 and option 233F004 is installed | 3P |
| | | Equipment/Furnishing - LOPA Change from 32pax to 19pax | 328 SSG | SB-328-25-590 | 15.02.23 | | SB-328-X | S | | S/N 3117 | 3P |
| | | Mod. of Air Intake | 328 SSG | SB-328-71-122 | 04.10.95 | 1 10.05.99 | SB-328-X | S | | S/N Air Intakes P/N 001A716E1000000, P/N 001A716E1000002, P/N 001A716E1000004 and P/N 001A716E1000006 | 3P |
| | | Equip./Furn. - Inst.Att.Brkt. Rudder Pedal Adj. | 328 SSG | SB-328-25-388 | 18.08.01 | 1 09.04.02 | SB-328-X | S | | S/N aircraft affected from 3005 through to 3098 and 3100, 3101, 3103, 3104, 3106, 3107, 3109, 3110, 3112, 3113, 3115, 3117 including 3119 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Equip./Furn.- Inst.of a Spy Viewer | 328 SSG | SB-328-25-402 | 19.10.01 | | SB-328-X | S | | S/N aircraft affected from 3005 through to 3098 and 3100, 3101, 3103, 3104, 3106, 3107, 3109, 3110, 3112, 3113, 3115, 3117 including 3119 | 3P |
| | | Eng.Contr.- Quality issue w.Eng.Contr.cables | 328 SSG | SB-328-76-409 | 11.03.02 | 2 07.10.02 | SB-328-X | S | | S/N aircraft affected from 3005 through to 3098, 3100, 3101, 3103, 3104, 3106, 3107, 3109, 3110, 3112, 3113, 3115, 3117 including 3119, that have installed a new cable delivered after the first of June 2001. check also spare parts | 3P |
| | | Rubbing protec. for nacelle aft cowling | 328 SSG | SB-328-71-317 | 14.01.00 | | SB-328-X | S | | S/N aircraft affected from 3064 through to 3119, except 3109, 3115 and 3117 | 3P |
| | | Equip./Furn.- Removal of Door Locking device on Aircraft with Option 521K010 installed | 328 SSG | SB-328-25-492 | 18.03.10 | | SB-328-X | S | | S/N aircraft with option 521K010A Flight Compartment Door (Cascada) installed | 3P |
| | | Change of Mod. 10 to Mod. 20 | 328 SSG | SB-328-00-175 | 22.01.97 | 3 | SB-328-X | S | | S/N All | 3P |
| | | Fuel Tank Safety - SFAR88 | 328 SSG | SB-328-00-445 | 23.08.04 | 1 17.06.05 | SB-328-X | S | | S/N All | 3P |
| | | Break In Markings | 328 SSG | SB-328-11-301 | 12.10.99 | | SB-328-X | S | | S/N All | 3P |
| | | Plac. & Mark.- Main Reservoir Add. Placard. | 328 SSG | SB-328-11-340 | 16.01.01 | | SB-328-X | S | | S/N All | 3P |
| | | Plac.& Mark.- Inadvert.Open Pass.Serv.Doors | 328 SSG | SB-328-11-454 | 03.05.04 | | SB-328-X | S | | S/N All | 3P |
| | | Elec.Bond.- Exch.of wash.at wing rear spar | 328 SSG | SB-328-20-480 | 30.10.07 | | SB-328-X | S | | S/N All | 3P |
| | | Air Conditioning - HEPA Filter Element Installation Recirculation Fan System Cabin Air | 328 SSG | SB-328-21-578 | 05.07.21 | 1 18.11.21 | SB-328-X | S | | S/N All | 3P |
| | | Communications - Modification of Mode S Transponder Module | 328 SSG | SB-328-23-545 | 17.05.16 | | SB-328-X | S | | S/N All | 3P |
| | | Electr.Power - Exchange AC-Inverters | 328 SSG | SB-328-24-059 | 10.10.94 | 1 07.04.05 | SB-328-X | S | | S/N All | 3P |
| | | Elec.Syst.- El.Bond.Points APU & LH/RH Gen. | 328 SSG | SB-328-24-447 | 23.09.04 | 3 23.05.18 | SB-328-X | S | | S/N All | 3P |
| | | Electrical Power - Brush check of the starter generator using new brush gauge | 328 SSG | SB-328-24-496 | 25.02.11 | | SB-328-X | S | | S/N All | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Improved Floor Covering | 328 SSG | SB-328-25-015 | 24.02.95 | 2 | SB-328-X | S | | S/N All | 3P |
| | | Equip./Furn.- Emer.Change of ELT 110 to 97 | 328 SSG | SB-328-25-416 | 13.12.01 | 3 18.02.05 | SB-328-X | S | | S/N All | 3P |
| | | Inst.of Prot.Angle on Bagg.Comp.Part.Wall Fr.37 LH | 328 SSG | SB-328-25-427 | 23.11.01 | | SB-328-X | S | | S/N All | 3P |
| | | Equip./Furn.- Insp. of Flight Comp.Door Inst. | 328 SSG | SB-328-25-451 | 19.12.03 | | SB-328-X | S | | S/N All | 3P |
| | | Equip./Furn.- Insp.of locking device for flight comp.door | 328 SSG | SB-328-25-485 | 28.01.09 | | SB-328-X | S | | S/N All | 3P |
| | | Equip./Furn.- Inst.of Improved Door Locking device | 328 SSG | SB-328-25-491 | 18.03.10 | | SB-328-X | S | | S/N All | 3P |
| | | Rivet Test - B/E Aerospace Smoke Goggles PN 118077 | 328 SSG | SB-328-25-500 | 10.01.12 | | SB-328-X | S | | S/N All | 3P |
| | | Equipment/Furnishings - Replacement of felt material in Cockpit Stowages | 328 SSG | SB-328-25-518 | 10.07.14 | | SB-328-X | S | | S/N All | 3P |
| | | Equipment/Furnishings - Replacement of felt material in Entertainment System Cabinet | 328 SSG | SB-328-25-519 | 10.07.14 | | SB-328-X | S | | S/N All | 3P |
| | | Equipment and Furnishings - Chafing Inspection of Frame 35 | 328 SSG | SB-328-25-535 | 11.11.15 | | SB-328-X | S | | S/N All | 3P |
| | | Equipment/Furnishings - Net Anchor Plates - Change of Screw Length | 328 SSG | SB-328-25-536 | 07.09.15 | | SB-328-X | S | | S/N All | 3P |
| | | Equipment/Furnishings - Installation of new cockpit door guide rail | 328 SSG | SB-328-25-558 | 25.03.19 | | SB-328-X | S | | S/N All | 3P |
| | | ATA 256 (Emergency Equipment) - Emergency Equipment for Flight Deck PED Safety | 328 SSG | SB-328-25-574 | 15.12.20 | | SB-328-X | S | | S/N All | 3P |
| | | Equipment/Furnishings - Replacement of Crew Life Vest EAM P01074-151WC | 328 SSG | SB-328-25-582 | 26.04.21 | | SB-328-X | S | | S/N All | 3P |
| | | Fire Protection - Replacement of obsolete optional 2nd hand fire extinguisher in Cockpit and Cabin | 328 SSG | SB-328-26-523 | 30.10.14 | 1 06.06.15 | SB-328-X | S | | S/N All | 3P |
| | | Flight Contr.- Insp./Repl.rel.res.valve | 328 SSG | SB-328-27-372 | 30.05.01 | | SB-328-X | S | | S/N All | 3P |
| | | Flight Contr.- Rudder Torsion Bar Backlash | 328 SSG | SB-328-27-440 | 23.01.03 | 1 22.04.03 | SB-328-X | S | | S/N All | 3P |
| | | Flight Contr.- Insp.of Flight Contr.Tab fittings | 328 SSG | SB-328-27-483 | 30.12.08 | | SB-328-X | S | | S/N All | 3P |
| | | Flight Controls - Replacement of Flight Control Tab fittings | 328 SSG | SB-328-27-488 | 25.08.09 | | SB-328-X | S | | S/N All | 3P |
| | | Control Cable - Repl.of Flight Control and Engine Control Systems Cables | 328 SSG | SB-328-27-489 | 27.01.10 | 2 13.03.12 | SB-328-X | S | | S/N All | 3P |
| | | Fuel - Inst. of Fuel Valve Res. Beam | 328 SSG | SB-328-28-334 | 10.11.00 | 2 06.08.03 | SB-328-X | S | | S/N All | 3P |
| | | Insp.of the Fuel Jet Pumps + adjacent fuel lines | 328 SSG | SB-328-28-484 | 18.12.08 | 1 25.03.09 | SB-328-X | S | | S/N All | 3P |
| | | Fuel - Repl. of Fuel Lines | 328 SSG | SB-328-28-490 | 28.11.12 | | SB-328-X | S | | S/N All | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Fuel - Change of fuel lines within LH/RH feeder tank | 328 SSG | SB-328-28-553 | 15.05.17 | 2 18.12.19 | SB-328-X | S | | S/N All | 3P |
| | | Hydr.Power - AC motor pump retrofit | 328 SSG | SB-328-29-338 | 14.09.00 | | SB-328-X | S | | S/N All | 3P |
| | | Inspect. Engine Air-Intake Deicer | 328 SSG | SB-328-30-020 | 17.03.94 | | SB-328-X | S | | S/N All | 3P |
| | | Inspection/Exchange Deicer Boots | 328 SSG | SB-328-30-171 | 20.09.96 | | SB-328-X | S | | S/N All | 3P |
| | | Ice & Rain Prot.- Inst. of EFCV | 328 SSG | SB-328-30-335 | 13.12.00 | 1 05.10.01 | SB-328-X | S | | S/N All | 3P |
| | | Ice & Rain Prot.- Empennage de-ice Tubes | 328 SSG | SB-328-30-380 | 07.09.01 | 2 02.04.03 | SB-328-X | S | | S/N All | 3P |
| | | Insp.of Engine Air Intake De Icing System | 328 SSG | SB-328-30-432 | 26.04.02 | | SB-328-X | S | | S/N All | 3P |
| | | Modif.of Drain Caps in Fusel./Empennage | 328 SSG | SB-328-30-441 | 12.02.03 | | SB-328-X | S | | S/N All | 3P |
| | | Ice & Rain Prot.- Windshield Z-bar bonding | 328 SSG | SB-328-30-449 | 03.08.07 | | SB-328-X | S | | S/N All | 3P |
| | | Ice & Rain Prot.- Insp.of Airf.De-Icer Boots | 328 SSG | SB-328-30-472 | 22.02.05 | | SB-328-X | S | | S/N All | 3P |
| | | Ice & Rain Prot.- Insp.Elev./Rud.Anti-Icing | 328 SSG | SB-328-30-473 | 24.03.05 | 1 28.10.05 | SB-328-X | S | | S/N All | 3P |
| | | Indicating-Integr. Avionik Comp. | 328 SSG | SB-328-31-076 | 30.01.95 | | SB-328-X | S | | S/N All | 3P |
| | | Integrated Avionic Computer (IAC) | 328 SSG | SB-328-31-176 | 17.06.96 | | SB-328-X | S | | S/N All | 3P |
| | | Indic.and Rec.Syst.- Display Unit Modification | 328 SSG | SB-328-31-487 | 28.01.10 | | SB-328-X | S | | S/N All | 3P |
| | | Landing Gear - Uplocks and Roller | 328 SSG | SB-328-32-022 | 15.04.94 | | SB-328-X | S | | S/N All | 3P |
| | | Landing Gear-Exch.MLG Uplock Roll | 328 SSG | SB-328-32-031 | 08.06.94 | 1 10.06.94 | SB-328-X | S | | S/N All | 3P |
| | | Landing Gear - Adjust.MLG Uplock | 328 SSG | SB-328-32-032 | 01.06.94 | 1 10.06.94 | SB-328-X | S | | S/N All | 3P |
| | | Install. of Protective Shield | 328 SSG | SB-328-32-229 | 03.11.97 | | SB-328-X | S | | S/N All | 3P |
| | | Landing Gear - NLG Feedback Potentiometer Harn.Conn.- Moisture Cont. | 328 SSG | SB-328-32-444 | 06.08.03 | 2 20.11.12 | SB-328-X | S | | S/N All | 3P |
| | | LG - Insp./Mod.of MLG Wheel Axles | 328 SSG | SB-328-32-468 | 04.02.05 | | SB-328-X | S | | S/N All | 3P |
| | | LG - Improvement of NWS system | 328 SSG | SB-328-32-469 | 28.06.05 | 1 01.09.06 | SB-328-X | S | | S/N All | 3P |
| | | LG - Insp.of MLG side brace assy | 328 SSG | SB-328-32-476 | 05.10.06 | 1 26.10.06 | SB-328-X | S | | S/N All | 3P |
| | | Nose and MLG Definition of Restoration Tasks for Nose and MLG | 328 SSG | SB-328-32-497 | 30.04.11 | | SB-328-X | S | | S/N All | 3P |
| | | NLG - Use of Dornier 328-300 Parts on Dornier-100 NLG Series | 328 SSG | SB-328-32-506 | 24.01.13 | | SB-328-X | S | | S/N All | 3P |
| | | NLG - Replacement of Feedback Potentiometers | 328 SSG | SB-328-32-507 | 24.01.13 | | SB-328-X | S | | S/N All | 3P |
| | | Landing Gear - Inspection of Extension/Retraction Actuator Rod and Equipped End Fitting | 328 SSG | SB-328-32-510 | 04.12.13 | 2 10.01.23 | SB-328-X | S | | S/N All | 3P |
| | | Nose Landing Gear - Replacement of the NWS Feedback Potentiometer Harnass | 328 SSG | SB-328-32-542 | 14.04.16 | | SB-328-X | S | | S/N All | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Lights - Improvement of Observer Panel Lighting | 328 SSG | SB-328-33-562 | 07.05.18 | | SB-328-X | S | | S/N All | 3P |
| | | Navigation - Exch. of IRS to AHRS | 328 SSG | SB-328-34-079 | 02.02.95 | 1 11.04.95 | SB-328-X | S | | S/N All | 3P |
| | | Navigation - Exch. of IRS to AHRS | 328 SSG | SB-328-34-080 | 03.02.95 | 2 13.11.95 | SB-328-X | S | | S/N All | 3P |
| | | Nav.-ATC Transponder System 2 | 328 SSG | SB-328-34-100 | 25.01.96 | 1 | SB-328-X | S | | S/N All | 3P |
| | | Navigat.-Install Trimble GPS | 328 SSG | SB-328-34-118 | 25.07.95 | | SB-328-X | S | | S/N All | 3P |
| | | GPWS Steep Approach Landing | 328 SSG | SB-328-34-129 | 12.09.95 | 2 08.10.03 | SB-328-X | S | | S/N All | 3P |
| | | Navigation - Glide Slope Anomaly | 328 SSG | SB-328-34-442 | 24.03.03 | | SB-328-X | S | | S/N All | 3P |
| | | Navigation - Activation of EGPWS | 328 SSG | SB-328-34-465 | 08.10.04 | 4 05.05.12 | SB-328-X | S | | S/N All | 3P |
| | | Navig.- Act.FD/AP Mode ILS Steep Appr. | 328 SSG | SB-328-34-470 | 21.01.05 | 1 15.11.07 | SB-328-X | S | | S/N All | 3P |
| | | Navig.- Mod.from Non-Div.to Diversity | 328 SSG | SB-328-34-471 | 31.01.05 | 1 27.07.05 | SB-328-X | S | | S/N All | 3P |
| | | Navigation - RNZ-851 INU Glide Slope and Localizer Anomaly | 328 SSG | SB-328-34-495 | 28.10.10 | | SB-328-X | S | | S/N All | 3P |
| | | Navigation - TCAS Update for IL AD Compliance | 328 SSG | SB-328-34-501 | 16.10.12 | 1 12.08.14 | SB-328-X | S | | S/N All | 3P |
| | | Navigation - TCAS Upgrade to Change 7.1 | 328 SSG | SB-328-34-502 | 16.10.12 | 1 12.08.14 | SB-328-X | S | | S/N All | 3P |
| | | Navigation - Standby Compass: Lead and Socket Assembly Inspection | 328 SSG | SB-328-34-532 | 03.08.15 | 1 03.11.15 | SB-328-X | S | | S/N All | 3P |
| | | OXYGEN SYSTEM - Replacement of Protective Breathing Equipment (PBE) | 328 SSG | SB-328-35-543 | 16.06.16 | 1 06.06.17 | SB-328-X | S | | S/N All | 3P |
| | | Pneumatics - Inst. of PRSOV | 328 SSG | SB-328-36-336 | 14.12.00 | 3 31.07.03 | SB-328-X | S | | S/N All | 3P |
| | | ATA 50 Structure General - Marking of Components with Alternative Spare Parts | 328 SSG | SB-328-50-573 | 12.04.19 | | SB-328-X | S | | S/N All | 3P |
| | | Heat Treatment of Titanium Bolts and Sleeves | 328 SSG | SB-328-51-515 | 27.06.14 | 1 17.10.14 | SB-328-X | S | | S/N All | 3P |
| | | Doors - Inspection of PAX Door Bracket and Replacement of PAX Door Lever | 328 SSG | SB-328-52-575 | 25.10.19 | | SB-328-X | S | | S/N All | 3P |
| | | Fuselage - Insp.of the tail cone-rear part drain hole | 328 SSG | SB-328-53-494 | 04.10.10 | | SB-328-X | S | | S/N All | 3P |
| | | Fuselage - Insp. of Rivet Nuts on Scuff Plate of Service Door | 328 SSG | SB-328-53-505 | 05.03.13 | | SB-328-X | S | | S/N All | 3P |
| | | Fuselage - Skin Reinforcement of Nose Landing Gear Bay Corners | 328 SSG | SB-328-53-539 | 14.06.17 | 1 19.07.19 | SB-328-X | S | | S/N All | 3P |
| | | Fuselage - Inspection of Frame 24 & 26 | 328 SSG | SB-328-53-559 | 20.07.17 | 1 20.02.23 | SB-328-X | S | | S/N All | 3P |
| | | Fuselage - Corrosion Protection Improvement of Top Fairing 1 & 11 attachment points | 328 SSG | SB-328-53-583 | 26.10.21 | | SB-328-X | S | | S/N All | 3P |
| | | Fuselage - Replacement of Copper Bonding Plates at Frame 44/45 | 328 SSG | SB-328-53-586 | 31.08.22 | | SB-328-X | S | | S/N All | 3P |
| | | Modificat. of Rudder Spring Tab | 328 SSG | SB-328-55-264 | 09.07.98 | | SB-328-X | S | | S/N All | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Stabilizers - Elevator Drain Holes | 328 SSG | SB-328-55-450 | 14.10.03 | 1 19.11.03 | SB-328-X | S | | S/N All | 3P |
| | | Inspection of vertical stabilizer | 328 SSG | SB-328-55-477 | 13.12.06 | | SB-328-X | S | | S/N All | 3P |
| | | Stabilizers - Inspection of Rudder Tab Fixation Brackets | 328 SSG | SB-328-55-493 | 21.04.10 | | SB-328-X | S | | S/N All | 3P |
| | | Stabilizer - Inspection of Horizontal Stabilizer Support Fittings | 328 SSG | SB-328-55-527 | 29.02.16 | | SB-328-X | S | | S/N All | 3P |
| | | Stabilizer - Inspection of Horizontal Stabilizer Bearing Support Rear | 328 SSG | SB-328-55-557 | 01.09.17 | 2 24.05.18 | SB-328-X | S | | S/N All | 3P |
| | | Wings - Flaps - Insp.of flap supp.3/4 | 328 SSG | SB-328-57-479 | 11.04.07 | | SB-328-X | S | | S/N All | 3P |
| | | Wings - Cold Expansion of CAMLOC holes | 328 SSG | SB-328-57-481 | 07.05.09 | 1 15.10.09 | SB-328-X | S | | S/N All | 3P |
| | | Wings - Wing to Fuselage Connection - Replacement of composite X-rods | 328 SSG | SB-328-57-504 | 30.08.12 | 3 22.11.13 | SB-328-X | S | | S/N All | 3P |
| | | Wing - Internal Inspection of Aileron End Box | 328 SSG | SB-328-57-581 | 08.02.21 | | SB-328-X | S | | S/N All | 3P |
| | | Prop.- Insp.after long term storage | 328 SSG | SB-328-61-478 | 18.01.07 | | SB-328-X | S | | S/N All | 3P |
| | | Power Plant-Addit.Insulation | 328 SSG | SB-328-71-046 | 28.07.94 | | SB-328-X | S | | S/N All | 3P |
| | | Power Plant-Tightening Connectors | 328 SSG | SB-328-71-047 | 08.08.94 | | SB-328-X | S | | S/N All | 3P |
| | | Power Plant-Inspect. Air Intake | 328 SSG | SB-328-71-056 | 26.09.94 | | SB-328-X | S | | S/N All | 3P |
| | | Engine / Oil Tank Filler Cap Insp. | 328 SSG | SB-328-72-474 | 10.08.05 | 1 28.12.05 | SB-328-X | S | | S/N All | 3P |
| | | Engine / Prop.Shaft-Field Insp./Repl. | 328 SSG | SB-328-72-475 | 25.08.05 | | SB-328-X | S | | S/N All | 3P |
| | | Engine Fuel and Control - Fohe Pressure Switch Safety Wire Insp. | 328 SSG | SB-328-73-503 | 24.04.12 | | SB-328-X | S | | S/N All | 3P |
| | | Engine Fuel and Control - Inspection/Replacement of Fuel Oil Heat Exchanger (FOHE) | 328 SSG | SB-328-73-530 | 03.06.15 | | SB-328-X | S | | S/N All | 3P |
| | | Engine Controls - Modification of Power Lever Assembly and Introduction of Crew Aural Alerting Device | 328 SSG | SB-328-76-486 | 15.07.09 | 3 07.04.10 | SB-328-X | S | | S/N All | 3P |
| | | Engine Controls - Replacement of push-pull cables | 328 SSG | SB-328-76-514 | 13.07.15 | | SB-328-X | S | | S/N All | 3P |
| | | Engine Controls - Replacement of cam switch lock ring | 328 SSG | SB-328-76-568 | 18.04.18 | 1 22.06.18 | SB-328-X | S | | S/N All | 3P |
| | | Source Doc.of Instruction for Continued Airworthiness for Electr.Wiring Interconnection System | 328 SSG | SB-328-90-482 | 10.12.09 | | SB-328-X | S | | S/N All | 3P |
| | | General - Change of AC Power Harness Routing | 328 SSG | SB-328-90-499 | 27.03.12 | 1 21.06.12 | SB-328-X | S | | S/N All | 3P |
| | | General - Inspection of Power Wire Routing | 328 SSG | SB-328-90-528 | 06.06.16 | | SB-328-X | S | | S/N All | 3P |
| | | Wing - Allocation of S/N for Winf Leading Edge No. 2 | 328 SSG | SB-328-57-541 | 19.02.16 | | SB-328-X | S | | S/N All (Leading Edge Number Two) | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Indic./Record.- IAC Software Change Mod D | 328 SSG | SB-328-31-337 | 21.09.00 | | SB-328-X | S | | S/N All A/C with IC-800 Integrated Avionics Computer P/N 7017300-11006 or -11010 and P/N 7017300-14006 or -14010 installed | 3P |
| | | Power Plant-Repair Lower Cowling | 328 SSG | SB-328-71-101 | 08.05.95 | 2 27.08.96 | SB-328-X | S | | S/N All A/C with installed lower cowling S/N 1006 up to 1106 | 3P |
| | | Doors-Modification of Cascade Cockpit Door shape | 328 SSG | SB-328-52-548 | 09.05.16 | | SB-328-X | S | | S/N All A/C with option 521K010A | 3P |
| | | Landing Gear - NLG Potentiometer Mod. | 328 SSG | SB-328-32-393 | 28.09.01 | 1 15.11.01 | SB-328-X | S | | S/N All aircaft fitted with NLG Shock Strut Assy 23100-000 not incorporating Suffix -2 | 3P |
| | | Primus 2000 GP-300 Guidance | 328 SSG | SB-328-22-180 | 12.08.96 | | SB-328-X | S | | S/N All aircraft equipped with Honeywell GP-300 guidance and display controller P/N 7015327-901 | 3P |
| | | Primus 2000 GP-300 Guidance | 328 SSG | SB-328-22-219 | 20.05.97 | | SB-328-X | S | | S/N All aircraft equipped with Honeywell GP-300 guidance and display controller P/N 7015327-901 | 3P |
| | | Additional Toilet Door Stop | 328 SSG | SB-328-25-166 | 26.04.96 | | SB-328-X | S | | S/N All aircraft equipped with standard toilet (Option 254J999) | 3P |
| | | Ice and rain protection | 328 SSG | SB-328-30-278 | 14.09.97 | | SB-328-X | S | | S/N All aircraft excluding 3022, 3023, 3053, 3063, 3084, 3087, 3088 | 3P |
| | | Fire Protection - Fire Panel Fail Indicator | 328 SSG | SB-328-26-374 | 06.06.01 | | SB-328-X | S | | S/N All aircraft fitted with Fire Panel for the Cargo Compartment (30WB) P/N 328-0170. The affected serial numbers of the fire panel are less than or equal to 110 | 3P |
| | | Navigation - Upgr.of the TCAS II Comp. | 328 SSG | SB-328-34-353 | 14.02.01 | 1 22.03.01 | SB-328-X | S | | S/N All aircraft fitted with the TCAS II Computer P/N 4066010-904 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | NLG Shock Absorber Axle Adapter | 328 SSG | SB-328-32-213 | 16.04.97 | | SB-328-X | S | | S/N All aircraft with a NLG installed below S/N IL113 | 3P |
| | | Observer Seat Modification | 328 SSG | SB-328-25-262 | 29.06.98 | | SB-328-X | S | | S/N All aircraft with AMI Model 2060, Single Attendant Seat S/N 001 through 074 installed | 3P |
| | | Crew Seat Belt Buckle Cent. Screw | 328 SSG | SB-328-25-196 | 12.11.96 | | SB-328-X | S | | S/N All aircraft with ARC restraint P/N 1180002-403-100 S/N 0101 up to and including 0315 and 0328, 0329 installed | 3P |
| | | Equip./Furn.- Insp.of seat frame attach caps | 328 SSG | SB-328-25-412 | 21.11.02 | | SB-328-X | S | | S/N All aircraft with B/E Aerospace Pax Seats Model P/N 2524.519-.() and P/N 2524.520-() installed | 3P |
| | | Equip.-Passeng. Seat Belt Shackle | 328 SSG | SB-328-25-105 | 12.05.95 | | SB-328-X | S | | S/N All aircraft with Burns Aerospace Corporation Commuter Seat Models JB6.8-I-22 and JB6.8-2-42 passenger seats installed | 3P |
| | | Equipment-Passeng. Seat Belt | 328 SSG | SB-328-25-114 | 17.04.97 | 1 | SB-328-X | S | | S/N All aircraft with Burns Aerospace Corporation Commuter Seat Models JB6.8-I-22 and JB6.82-42 passenger seats installed. Seat serial numbers 384617 and up will not be effected | 3P |
| | | Navigation - Activ.of TCAS II Change 7 | 328 SSG | SB-328-34-360 | 14.03.01 | 1 12.06.01 | SB-328-X | S | | S/N All aircraft with complete provisions for TCAS (option 346K008) installed | 3P |
| | | Eng.Contr.- Control Cable Maintenance | 328 SSG | SB-328-76-467 | 29.09.04 | | SB-328-X | S | | S/N All aircraft with control cables from manufacturer MORSE CONTROLS LIMITED installed. Aircraft with Service Bulletin SB-328-76-365 installed are not affected | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Propeller Contr.Unit-Repl.of Fasteners | 328 SSG | SB-328-61-347 | 06.12.00 | | SB-328-X | S | | S/N All aircraft with D-119-() Propeller Control Units (PCU) S/N´s PCU-A-22 through PCU-A-42 and PCU-A-EFS 101 through PCU-A-EFS392, except those listed below | 3P |
| | | Prop.Contr.Unit-Major Periodic Insp. | 328 SSG | SB-328-61-358 | 09.01.01 | | SB-328-X | S | | S/N All aircraft with D-1199-2 Propeller Control Units, affected serial numbers are shown in table 1 of the Hartzell Propeller Inc. Service Bulletin No. HD-SB-61-025 | 3P |
| | | LG - New Emergency/Park Brake Valve | 328 SSG | SB-328-32-457 | 16.04.04 | 1 15.06.04 | SB-328-X | S | | S/N All aircraft with Dunlop emergency/park brake valve P/N AC69965-2 installed | 3P |
| | | Equip./Furn.- Install.of a new ELT ant. | 328 SSG | SB-328-25-330 | 30.03.00 | | SB-328-X | S | | S/N All aircraft with ELT110 system (option 256J998) installed | 3P |
| | | Power Plant - Eng.Aft Vibr.Isolators | 328 SSG | SB-328-71-458 | 05.03.04 | | SB-328-X | S | | S/N All aircraft with Engine Aft Vibration Isolators P/N´s 95218-22 and 95218-23 installed, including stocks/spares | 3P |
| | | Ground Spoiler Actuator | 328 SSG | SB-328-27-289 | 03.03.99 | | SB-328-X | S | | S/N All aircraft with ground spoiler actuator P/N 1059A0000-02 and spare units | 3P |
| | | Leakage and functional checks | 328 SSG | SB-328-29-220 | 20.05.97 | 2 03.03.15 | SB-328-X | S | | S/N All aircraft with ground spoiler option 040-001 | 3P |
| | | WINGS - Special Detailed Inspection of Ground Spoiler | 328 SSG | SB-328-57-537 | 19.02.16 | | SB-328-X | S | | S/N All aircraft with ground spoilers | 3P |
| | | Blade thurst bearing race replace | 328 SSG | SB-328-61-284 | 25.01.99 | | SB-328-X | S | | S/N All aircraft with HD-E6C-3B propeller assembly serial number S/N HL-334 and lower installed | 3P |
| | | Communicat.-Exchange if HF wire | 328 SSG | SB-328-23-282 | 15.01.99 | | SB-328-X | S | | S/N All aircraft with HF wire antenna option 231 K008 installed | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Fire Protec.- New improved APU fire cart. | 328 SSG | SB-328-26-342 | 02.11.00 | | SB-328-X | S | | S/N All aircraft with installed APU´s | 3P |
| | | Mod. of Data Acquisition Unit | 328 SSG | SB-328-31-123 | 09.08.95 | | SB-328-X | S | | S/N All aircraft with installed DA-800 Data Acquisition Unit P/N 7013348-903 and -913 | 3P |
| | | Communications - Pass. Entert. System | 328 SSG | SB-328-23-366 | 05.07.01 | | SB-328-X | S | | S/N All aircraft with installed Option 233-001 | 3P |
| | | Engine - Additional bonding strap. | 328 SSG | SB-328-71-297 | 30.06.99 | 2 28.08.01 | SB-328-X | S | | S/N All aircraft with installed PW119 engines | 3P |
| | | Replacem. Main Land. Gear Body | 328 SSG | SB-328-32-216 | 05.05.97 | | SB-328-X | S | | S/N All aircraft with L/H main body assy P/N 22415-000-00 S/N U1 to U12, or P/N 22415OOO-OOA S/N U13 to U15, R/H main body assy P/N 22416-000-00 S/N U1 to U12, or P/N 22416-OOO-OOA S/N U13 to U15 installed | 3P |
| | | Repl.of bushes in main body | 328 SSG | SB-328-32-245 | 30.11.98 | 2 21.11.07 | SB-328-X | S | | S/N All aircraft with L/H MLG P/N 22730-000 and P/N 22731-000 not incorporating suffix -06 | 3P |
| | | Repl.of bushes in trailing arm | 328 SSG | SB-328-32-288 | 05.07.99 | | SB-328-X | S | | S/N All aircraft with L/H MLG P/N 22730-000 and R/H P/N 22731-00 not incorporating suffix -07 | 3P |
| | | Landing Gear - Main Landing Gear | 328 SSG | SB-328-32-343 | 27.11.00 | | SB-328-X | S | | S/N All aircraft with LH MLG leg 22730-000-00 not incorporating suffix -8; RH MLG leg 22731-000-00 not incorporating suffix -8 | 3P |
| | | NLG upper brace replacement | 328 SSG | SB-328-32-207 | 20.02.97 | 1 31.07.01 | SB-328-X | S | | S/N All aircraft with NLG opper brace assembly P/N 23200-000-01 installed | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Landing Gear - NLG reloc.of Ident.Sleeve. | 328 SSG | SB-328-32-396 | 10.10.01 | | SB-328-X | S | S/N All aircraft with NLG Shock Strut Assy, Electrical control harness, Main electrical harness and Electical power herness | 3P |
| | | Swivel Joint NLG Shock Strut Assy | 328 SSG | SB-328-32-202 | 30.01.97 | | SB-328-X | S | S/N All aircraft with NLG shock strut P/N 23100-000-00 with s S/N up to and including IL104, IL107, IL108, IL109 and IL110 installed | 3P |
| | | APU - One Time Insp./Leakage Check | 328 SSG | SB-328-49-456 | 20.04.04 | | SB-328-X | S | S/N All aircraft with option 490-001 installed | 3P |
| | | Fuselage - Add.Seat Track - Fast.Rotation | 328 SSG | SB-328-53-438 | 21.02.05 | | SB-328-X | S | S/N All aircraft with option 539K001A installed | 3P |
| | | LG - Replacement of Main/Nose Gear Uplocks | 328 SSG | SB-328-32-183 | 09.10.96 | 1 17.09.09 | SB-328-X | S | S/N All aircraft with P/N 22405-000-03 MLG / NLG uplocks installed | 3P |
| | | Ice and Rain Protect.-Deicer Boot | 328 SSG | SB-328-30-094 | 24.03.95 | | SB-328-X | S | S/N All aircraft with P/N 29S-5D5240-211, 29S-5D5240-231 and 29S-5D5240-251 inlet deice boots installed | 3P |
| | | Proximity Switch Electrical Unit | 328 SSG | SB-328-32-248 | 06.11.97 | 1 22.04.98 | SB-328-X | S | S/N All aircraft with P/N 8-700-03 or 8-700-04 PSEU's installed | 3P |
| | | Propeller Control Unit (PCU) | 328 SSG | SB-328-61-221 | 22.05.97 | 1 11.06.97 | SB-328-X | S | S/N All aircraft with P/N D-1199-2 Propeller control units (PCU) (1-170A) having a S/N up to and including PCU-A-EFS379 installed | 3P |
| | | Flight Contr.- Rudder Damper Conv. | 328 SSG | SB-328-27-376 | 28.06.01 | | SB-328-X | S | S/N All aircraft with P/N FE217-004 installed | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Indic./Rec.- SwitchGuard f.Flight Att.Pan. | 328 SSG | SB-328-31-367 | 04.04.01 | | SB-328-X | S | | S/N All aircraft with panels Serial No´s 0001-0006, 0008-0010, 0012-0015, 0017, 0020-0025, 0027, 0029-0033, 0035-0040 and 0043 fitted | 3P |
| | | Engine-No. 4 Bearing Area | 328 SSG | SB-328-72-177 | 16.07.96 | | SB-328-X | S | | S/N All aircraft with PW119B (BS824)/PW119C (BS878) engines which are before and include serial number PCE-116154 but not PCE-116113 and PCE-116114 | 3P |
| | | Eng.-Repl.of oversp.govern.press. | 328 SSG | SB-328-72-280 | 09.11.98 | | SB-328-X | S | | S/N All aircraft with PW119B engines up to and including Serial No. PCE-AB0057 installed and all aircraft with PW119C engines up to and including Serial No. PCE-AZ0004 installed | 3P |
| | | Landing Gear - Shock Absorber | 328 SSG | SB-328-32-174 | 17.07.96 | | SB-328-X | S | | S/N All aircraft with shock absorber P/N 22420-000-04 or P/N 22420-000-05 installed | 3P |
| | | Power Plant-Lower/Aft Cowling | 328 SSG | SB-328-71-078 | 31.01.95 | | SB-328-X | S | | S/N All aircraft with the following lower cowlings installed: P/N 001A711A2100002 and P/N 001A711A2100004 P/N 001B711E2100000 and P/N 0018711E2100002 P/N 001A711E2100000 and P/N 001A711A2100000 | 3P |
| | | Landing Gear - Uplock | 328 SSG | SB-328-32-305 | 02.11.99 | | SB-328-X | S | | S/N All aircraft with uplock assy 22405-000-04 installed | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Mod. of Reduction Gearbox | 328 SSG | SB-328-61-252 | 10.07.97 | | SB-328-X | S | | S/N All aircraft without Hartzell Propeller Inc. Service Bulletin HD-SB-61-017 incorporated | 3P |
| | | Aircraft General - Canadian Registration | 328 SSG | SB-328-00-356 | 22.03.01 | 1 30.11.05 | SB-328-X | S | | S/N All aircrafts to be registered in Canda | 3P |
| | | Navig.- Activating of TCAS 2000 syst. | 328 SSG | SB-328-34-331 | 18.08.00 | 4 09.07.01 | SB-328-X | S | | S/N All aircrafts with complete provisions for TCAS (option 346K008) installed | 3P |
| | | Lead.Edge Nr.1 Identif.a.Interchangeab. | 328 SSG | SB-328-57-349 | 04.11.00 | 1 21.09.01 | SB-328-X | S | | S/N All leading Edge Number One | 3P |
| | | Fire Protection - Replacement of obsolete optional 2nd hand fire extinguisher in Cabin at Frame 31/32 | 328 SSG | SB-328-26-524 | 30.10.14 | 1 06.06.15 | SB-328-X | S | | S/N All Serial No.s with options 262-002A, 262-002B and 262-002C with hand fire extinguisher at Frame 31/32 installed | 3P |
| | | Landing Gear - Modification of Proximity Switch Electrical Unit (PSEU) | 328 SSG | SB-328-32-544 | 10.12.15 | | SB-328-X | S | | S/N All with PSEU P/N 8-700-04 Mod A and P/N 8-700-05 installed | 3P |
| | | Power Plant - Electr.Wiring Harness | 328 SSG | SB-328-72-153 | 25.06.96 | 1 | SB-328-X | S | | S/N engines up to and including serial numbe PCE-116160 | 3P |
| | | Fuel leakage | 328 SSG | SB-328-72-272 | 12.08.98 | | SB-328-X | S | | S/N PW119B/C engines up to and including S/N 116081 for Pratt and Whitney Canada SB PW1OO-72-21364 and PW119B/C engines up to and including S/N 116137 for Pratt and Whitney Canada SB PW1OO-72-21373 | 3P |
| | | Engine / Insp. of Second Stage Power Turbine Blades | 328 SSG | SB-328-72-580 | 11.01.21 | | SB-328-X | S | | S/N Refer to PWC SB PW100-72-21956 | 3P |
| | | Eng.Control - Missing bushes | 328 SSG | SB-328-76-286 | 22.06.99 | | SB-328-X | S | | S/N up to and including 3098, 3103 | 3P |
| | | Advance Notice of AFM Change | 328 SSG | SI-328-00-008 | 27.01.95 | 2 20.04.95 | SI-328-X | S | | | 3P |
| | | Oil Contamination of ECS | 328 SSG | SI-328-00-010 | 02.05.95 | 1 05.02.96 | SI-328-X | S | | | 3P |
| | | Go-Around and Landing Procedures | 328 SSG | SI-328-00-019 | 18.09.96 | 1 25.10.96 | SI-328-X | S | | | 3P |
| | | Erosion protection | 328 SSG | SI-328-00-032 | 27.08.97 | | SI-328-X | S | | | 3P |
| | | Pilot Info. - Selection of Ground Idle | 328 SSG | SI-328-00-067 | 18.04.00 | | SI-328-X | S | | | 3P |
| | | Aircraft exposure to volcanic ash environment | 328 SSG | SI-328-00-126 | 23.04.10 | 1 21.05.10 | SI-328-X | S | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Documents - Cancellation of SRM TR 52-017 | 328 SSG | SI-328-00-136 | 17.07.12 | | SI-328-X | S | | 3P |
| | | Equivalent Checks for LUMPD | 328 SSG | SI-328-05-108 | 24.03.03 | | SI-328-X | S | | 3P |
| | | Forward Jacking Point Plug | 328 SSG | SI-328-07-021 | 28.01.97 | | SI-328-X | S | | 3P |
| | | Return to Service | 328 SSG | SI-328-10-136 | 02.03.12 | | SI-328-X | S | | 3P |
| | | Standard Practice - Job Close-Up | 328 SSG | SI-328-20-137 | 16.12.11 | | SI-328-X | S | | 3P |
| | | Air Condit.-Impr.Sleeve Material | 328 SSG | SI-328-21-005 | 16.06.94 | | SI-328-X | S | | 3P |
| | | Air Conditioning-Sleeve Material | 328 SSG | SI-328-21-005 | 25.04.95 | | SI-328-X | S | | 3P |
| | | Ground Operat.-High Cabin Tempera | 328 SSG | SI-328-21-011 | 02.05.95 | | SI-328-X | S | | 3P |
| | | CPCS Controller | 328 SSG | SI-328-21-023 | 14.02.97 | | SI-328-X | S | | 3P |
| | | Improv.of P/N 1716D000 Cold Air | 328 SSG | SI-328-21-052 | 25.01.99 | | SI-328-X | S | | 3P |
| | | Availability of a new Cold Air Unit | 328 SSG | SI-328-21-101 | 20.02.02 | | SI-328-X | S | | 3P |
| | | Air Cond.- Flow Contr.& Shut Valve Impr. | 328 SSG | SI-328-21-111 | 10.05.05 | | SI-328-X | S | | 3P |
| | | ATA21 - Corona Virus - Cleaning Recommendations and Cabin Air Supply | 328 SSG | SI-328-21-167 | 17.03.20 | | SI-328-X | S | | 3P |
| | | ATA21 - Dry-Ice - Recommendations for calculating max allowable dry-ice load | 328 SSG | SI-328-21-169 | 27.01.21 | | SI-328-X | S | | 3P |
| | | ATA21 - Assuring Confidence in Air Travel with Dornier 328 | 328 SSG | SI-328-21-170 | 18.09.20 | | SI-328-X | S | | 3P |
| | | PRIMUS 2000 GP-300 Controller | 328 SSG | SI-328-22-016 | 02.03.96 | | SI-328-X | S | | 3P |
| | | Communic.- Com unit update | 328 SSG | SI-328-23-061 | 20.07.99 | 2 02.08.01 | SI-328-X | S | | 3P |
| | | Overheat problems DC jct. box 1VE | 328 SSG | SI-328-24-039 | 05.03.98 | | SI-328-X | S | | 3P |
| | | Servicing a. Maint. of Batteries | 328 SSG | SI-328-24-041 | 24.03.98 | 1 13.01.00 | SI-328-X | S | | 3P |
| | | Electr.Power - Modification to HECS | 328 SSG | SI-328-24-112 | 07.05.04 | 1 26.05.04 | SI-328-X | S | | 3P |
| | | Storage Requirements for Nickel-Cadmium Batteries addressing EASA SIB 2020-18 | 328 SSG | SI-328-24-171 | 04.12.20 | | SI-328-X | S | | 3P |
| | | Safety Set Screw Stowage Compartm | 328 SSG | SI-328-25-002 | 14.01.94 | | SI-328-X | S | | 3P |
| | | Eq./Fur.-Seat installation | 328 SSG | SI-328-25-059 | 10.05.99 | | SI-328-X | S | | 3P |
| | | Flight Crew Comp.Door-Sec.improv. | 328 SSG | SI-328-25-098 | 10.10.01 | | SI-328-X | S | | 3P |
| | | Equipment/Furnishings - AmSafe Seatbelts - Unapproved Parts Notification | 328 SSG | SI-328-25-153 | 27.09.16 | | SI-328-X | S | | 3P |
| | | Mod. of Fire Exting. Test Box | 328 SSG | SI-328-26-044 | 17.06.98 | | SI-328-X | S | | 3P |
| | | Improvement of P/N SD9422A0A0 | 328 SSG | SI-328-26-051 | 23.11.98 | | SI-328-X | S | | 3P |
| | | Fire Prot. - Smoke Det. Insp. | 328 SSG | SI-328-26-092 | 02.08.01 | | SI-328-X | S | | 3P |
| | | Fire Protection - Alternative Fire Extinguisher | 328 SSG | SI-328-26-125 | 09.06.10 | | SI-328-X | S | | 3P |
| | | Aviac-trim actuat. piston surface | 328 SSG | SI-328-27-017 | 12.08.96 | | SI-328-X | S | | 3P |
| | | Rudder damper data plate | 328 SSG | SI-328-27-047 | 20.10.98 | | SI-328-X | S | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Improved Elevator Trim Actuator | 328 SSG | SI-328-27-074 | 22.11.00 | | SI-328-X | S | | 3P |
| | | Replacement of groundspoiler actuator | 328 SSG | SI-328-27-080 | 19.01.01 | | SI-328-X | S | | 3P |
| | | Flight Contr.-Cable Proced. Instruc. | 328 SSG | SI-328-27-084 | 07.03.01 | | SI-328-X | S | | 3P |
| | | Flight Controls - Flap Control Unit | 328 SSG | SI-328-27-087 | 11.05.01 | | SI-328-X | S | | 3P |
| | | Flight Contr.-Potentiom.Lever Spares | 328 SSG | SI-328-27-089 | 17.08.01 | | SI-328-X | S | | 3P |
| | | Fl.Contr.- Radial Clear.for Roll Spoiler Act. | 328 SSG | SI-328-27-109 | 27.03.03 | | SI-328-X | S | | 3P |
| | | Fl.Contr.- Avail.of a new Flap Contr.Unit | 328 SSG | SI-328-27-113 | 19.08.04 | | SI-328-X | S | | 3P |
| | | Alternate Fuel Booster Pump | 328 SSG | SI-328-28-034 | 07.10.97 | | SI-328-X | S | | 3P |
| | | Ext.of Fuel Tank Safety Compl.Date | 328 SSG | SI-328-28-123 | 19.12.06 | | SI-328-X | S | | 3P |
| | | Fuel - Potential Contamination of Fuel Tanks and System | 328 SSG | SI-328-28-147 | 12.06.14 | | SI-328-X | S | | 3P |
| | | Fuel - Dornier 328-100 SAF compatibility | 328 SSG | SI-328-28-175 | 11.07.22 | | SI-328-X | S | | 3P |
| | | Blue CAS Mess.HYD MAIN PMP INOP | 328 SSG | SI-328-29-062 | 20.07.99 | | SI-328-X | S | | 3P |
| | | Hydr.Pow.- Relief Restr.Valve ZRV87xx | 328 SSG | SI-328-29-118 | 11.08.05 | | SI-328-X | S | | 3P |
| | | Hydr.Power - Non-Approved Standby DC Motor Pump | 328 SSG | SI-328-29-135 | 16.12.11 | | SI-328-X | S | | 3P |
| | | Advance Notice of AFM Change | 328 SSG | SI-328-30-007 | 27.01.95 | | SI-328-X | S | | 3P |
| | | Ejector Flow Control Valve | 328 SSG | SI-328-30-015 | 29.02.96 | 1 29.03.96 | SI-328-X | S | | 3P |
| | | Failed Propeller De-ice system | 328 SSG | SI-328-30-022 | 07.02.97 | | SI-328-X | S | | 3P |
| | | Improvem. Controller Air Intake | 328 SSG | SI-328-30-026 | 09.06.97 | | SI-328-X | S | | 3P |
| | | De-icer Boot Erosion Repair | 328 SSG | SI-328-30-028 | 23.07.97 | 1 11.12.97 | SI-328-X | S | | 3P |
| | | Ice and Rain Protection | 328 SSG | SI-328-30-040 | 02.02.98 | | SI-328-X | S | | 3P |
| | | Ice a.rain protect.-P/N 3285-10 | 328 SSG | SI-328-30-049 | 02.11.98 | | SI-328-X | S | | 3P |
| | | Alternate Intake De-ice Boot | 328 SSG | SI-328-30-055 | 09.01.99 | 1 24.01.00 | SI-328-X | S | | 3P |
| | | Installation of the FAST de-icing boots | 328 SSG | SI-328-30-066 | 14.02.00 | | SI-328-X | S | | 3P |
| | | Ice & rain - Flight through freez.drizzle | 328 SSG | SI-328-30-073 | 17.03.00 | | SI-328-X | S | | 3P |
| | | Ground Operation during heavy snowfall | 328 SSG | SI-328-30-075 | 22.11.00 | | SI-328-X | S | | 3P |
| | | Windshield Heat Control Unit | 328 SSG | SI-328-30-088 | 15.05.01 | | SI-328-X | S | | 3P |
| | | Uncommanded CAS messages | 328 SSG | SI-328-31-009 | 30.03.95 | | SI-328-X | S | | 3P |
| | | Nuisance PSEU messages | 328 SSG | SI-328-31-027 | 20.05.97 | | SI-328-X | S | | 3P |
| | | Elec.Power DC Unit 1VE, tightening torque | 328 SSG | SI-328-31-071 | 14.08.00 | | SI-328-X | S | | 3P |
| | | IC-800 Comp.- Software Change | 328 SSG | SI-328-31-079 | 22.01.01 | | SI-328-X | S | | 3P |
| | | Ind./Rec.- JAR OPS Requirement 1.715 | 328 SSG | SI-328-31-104 | 08.10.02 | | SI-328-X | S | | 3P |
| | | Indicating/Record. - IAC Interchangeability | 328 SSG | SI-328-31-115 | 04.10.04 | 1 02.11.04 | SI-328-X | S | | 3P |
| | | Indic./Rec.Syst.- DAU Troubleshooting | 328 SSG | SI-328-31-116 | 12.01.05 | | SI-328-X | S | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Indicating/Recording Systems - Loss of Display Units | 328 SSG | SI-328-31-124 | 16.09.09 | | SI-328-X | S | | 3P |
| | | Indicating and Recording - Introduction of L3 Aviation Recorders 90-Day Underwater Locator Beacon | 328 SSG | SI-328-31-158 | 08.05.18 | | SI-328-X | S | | 3P |
| | | MLG Shock Absorber | 328 SSG | SI-328-32-006 | 24.10.95 | | SI-328-X | S | | 3P |
| | | Operation of Nosewheel Steering | 328 SSG | SI-328-32-012 | 08.08.95 | | SI-328-X | S | | 3P |
| | | MLG Shock Absorber | 328 SSG | SI-328-32-014 | 26.10.95 | | SI-328-X | S | | 3P |
| | | Landing Gear - Retreaded Tyres. | 328 SSG | SI-328-32-020 | 20.11.97 | 2 10.06.99 | SI-328-X | S | | 3P |
| | | Improved brake unit | 328 SSG | SI-328-32-025 | 06.05.97 | | SI-328-X | S | | 3P |
| | | New Brake Metering Unit (BMU) | 328 SSG | SI-328-32-058 | 20.05.99 | | SI-328-X | S | | 3P |
| | | Test of landing gear in position downlock | 328 SSG | SI-328-32-073 | 30.10.00 | | SI-328-X | S | | 3P |
| | | Alternate Main Landing Gear Tires | 328 SSG | SI-328-32-082 | 02.02.01 | 2 17.04.03 | SI-328-X | S | | 3P |
| | | Main Landing Gear Downl.Assist Act. | 328 SSG | SI-328-32-083 | 02.02.01 | | SI-328-X | S | | 3P |
| | | Landing Gear - Anti Skid Cont. Unit | 328 SSG | SI-328-32-090 | 25.07.01 | | SI-328-X | S | | 3P |
| | | Landing Gear - Use of retread tires. | 328 SSG | SI-328-32-096 | 17.08.01 | | SI-328-X | S | | 3P |
| | | Landing Gear - Alternate NLG Tire | 328 SSG | SI-328-32-103 | 07.05.02 | | SI-328-X | S | | 3P |
| | | LG - Life Limitations for Dunlop BMU | 328 SSG | SI-328-32-114 | 12.11.04 | | SI-328-X | S | | 3P |
| | | Landing Gear - Insp.of aircraft tires | 328 SSG | SI-328-32-120 | 27.12.05 | | SI-328-X | S | | 3P |
| | | Landing Gear - Rod Assy NLG Door Drive | 328 SSG | SI-328-32-139 | 22.11.12 | 1 31.01.13 | SI-328-X | S | | 3P |
| | | Landing Gear - Structural Safe-Limited Parts | 328 SSG | SI-328-32-143 | 07.03.14 | 4 26.02.21 | SI-328-X | S | | 3P |
| | | LG - Cracked Sealant at MLG / NLG Bushings | 328 SSG | SI-328-32-144 | 16.12.13 | | SI-328-X | S | | 3P |
| | | Landing Gear - Main Fitting Shock Absorber Lugs - New Repair Limits | 328 SSG | SI-328-32-162 | 06.02.19 | | SI-328-X | S | | 3P |
| | | Flight Attendant Panel | 328 SSG | SI-328-33-042 | 05.05.98 | | SI-328-X | S | | 3P |
| | | Lights - Appl. of TR ALD-078. | 328 SSG | SI-328-33-100 | 05.02.02 | 1 20.07.04 | SI-328-X | S | | 3P |
| | | Navigation - Impr. TAT - Sensor | 328 SSG | SI-328-34-029 | 18.07.97 | | SI-328-X | S | | 3P |
| | | Navigat.-Improved Weather Radar | 328 SSG | SI-328-34-030 | 24.07.97 | | SI-328-X | S | | 3P |
| | | Interchangeability of Pitot Probe | 328 SSG | SI-328-34-076 | 24.11.00 | | SI-328-X | S | | 3P |
| | | Resumption of RVSM Operations | 328 SSG | SI-328-34-107 | 16.12.02 | | SI-328-X | S | | 3P |
| | | Navig.- ELS & EHS Surveillance (Euro) | 328 SSG | SI-328-34-117 | 01.03.05 | | SI-328-X | S | | 3P |
| | | Attitude Heading Ref. System (AHRS) | 328 SSG | SI-328-34-122 | 25.08.06 | | SI-328-X | S | | 3P |
| | | Navig.- ADS-B Out Mandate | 328 SSG | SI-328-34-160 | 14.01.19 | | SI-328-X | S | | 3P |
| | | Navigation - Honeywell RM-855 Mod AC for ADS-B Out | 328 SSG | SI-328-34-164 | 16.12.19 | | SI-328-X | S | | 3P |
| | | Crew Oxygen Masks | 328 SSG | SI-328-35-013 | 24.10.95 | | SI-328-X | S | | 3P |
| | | Oxygen - Overboard disch. ind.P/N 179001 | 328 SSG | SI-328-35-102 | 03.04.02 | | SI-328-X | S | | 3P |
| | | Improved pressure reducing | 328 SSG | SI-328-36-018 | 26.08.96 | | SI-328-X | S | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Improved Press.Reducing a. Shut | 328 SSG | SI-328-36-054 | 15.02.99 | | SI-328-X | S | | 3P |
| | | Pneumatic - Improved PRSOV | 328 SSG | SI-328-36-121 | 07.07.06 | | SI-328-X | S | | 3P |
| | | APU-Flameout During Ground Operat | 328 SSG | SI-328-49-024 | 17.04.97 | 1 25.09.97 | SI-328-X | S | | 3P |
| | | APU Air Intake Bellow Seal - Corr.Inst. | 328 SSG | SI-328-49-097 | 23.08.01 | | SI-328-X | S | | 3P |
| | | General Structure - Alternative Structural Spare Parts with Tartaric-Sulphuric-Acid Anodizing (TSA) | 328 SSG | SI-328-50-161 | 24.06.19 | | SI-328-X | S | | 3P |
| | | Structures General - Incorrect Torque Value in SRM 51-60-10 and 51-60-20 | 328 SSG | SI-328-51-148 | 22.08.14 | | SI-328-X | S | | 3P |
| | | Standard Practices and Structures - Repair Resin System for Wet Laminate Repairs | 328 SSG | SI-328-51-165 | 20.01.20 | | SI-328-X | S | | 3P |
| | | Red warning DOORS - Pax door link rod | 328 SSG | SI-328-52-077 | 19.12.00 | | SI-328-X | S | | 3P |
| | | Stabilizer-Balancing Proc.of the Rudder | 328 SSG | SI-328-55-106 | 29.11.02 | | SI-328-X | S | | 3P |
| | | Windows - Cockpit Side Windows | 328 SSG | SI-328-56-037 | 18.12.97 | | SI-328-X | S | | 3P |
| | | Wind.-Cockpit side windows | 328 SSG | SI-328-56-057 | 30.04.99 | | SI-328-X | S | | 3P |
| | | Windows - Interch. Front Windshield | 328 SSG | SI-328-56-081 | 24.01.01 | | SI-328-X | S | | 3P |
| | | Interch. of Solidion Side-Window | 328 SSG | SI-328-56-085 | 05.04.01 | | SI-328-X | S | | 3P |
| | | Wing - SB-328-57-140 / 57-198 | 328 SSG | SI-328-57-031 | 19.08.97 | | SI-328-X | S | | 3P |
| | | Wing - ALD Mandatory Retrofit of X-Rod Connection | 328 SSG | SI-328-57-140 | 11.12.12 | 2 10.10.14 | SI-328-X | S | | 3P |
| | | Aileron - Insprction of Aileron SN 1052 | 328 SSG | SI-328-57-152 | 30.06.16 | | SI-328-X | S | | 3P |
| | | Improved Prop. Transf. Tube Coupl | 328 SSG | SI-328-61-003 | 30.03.94 | 1 05.04.94 | SI-328-X | S | | 3P |
| | | Inspection of Blade Preload Plate | 328 SSG | SI-328-61-004 | 21.04.94 | | SI-328-X | S | | 3P |
| | | Propeller - Blade Bearing Damage | 328 SSG | SI-328-61-038 | 18.12.97 | 26.01.98 | SI-328-X | S | | 3P |
| | | Ground Operation Limitations | 328 SSG | SI-328-61-053 | 05.03.99 | | SI-328-X | S | | 3P |
| | | Inflight Dynamic Balancing | 328 SSG | SI-328-61-056 | 07.01.99 | | SI-328-X | S | | 3P |
| | | Engine Condition Trend Monitoring | 328 SSG | SI-328-71-001 | 29.12.93 | | SI-328-X | S | | 3P |
| | | Power Plant - Improved Door Strut | 328 SSG | SI-328-71-035 | 09.12.97 | | SI-328-X | S | | 3P |
| | | Eng. Air Intake Flg. Cracks/Frac. | 328 SSG | SI-328-71-045 | 03.09.98 | | SI-328-X | S | | 3P |
| | | Turb.eng.-Oil Pressure differnt. | 328 SSG | SI-328-72-050 | 09.11.98 | | SI-328-X | S | | 3P |
| | | Engine - New Engine Maintenance Manual | 328 SSG | SI-328-72-149 | 08.10.14 | | SI-328-X | S | | 3P |
| | | Power a. Condition Control Cables | 328 SSG | SI-328-76-036 | 16.12.97 | | SI-328-X | S | | 3P |
| | | Eng.Contr.-Power lev.gate designe | 328 SSG | SI-328-76-048 | 05.11.98 | | SI-328-X | S | | 3P |
| | | Eng.Contr.- Improved Heating Tubes | 328 SSG | SI-328-76-065 | 15.02.00 | | SI-328-X | S | | 3P |
| | | Improved Heating Tubes (BALCONY) | 328 SSG | SI-328-76-068 | 04.07.00 | | SI-328-X | S | | 3P |
| | | Eng.Cont.Box Ass.- Interchangeability | 328 SSG | SI-328-76-086 | 09.04.01 | | SI-328-X | S | | 3P |
| | | Engine Controls - Introduction of new Power Lever Aural Control Box (PLAC Box) | 328 SSG | SI-328-76-138 | 08.11.12 | | SI-328-X | S | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Inspection for Cracks and Wear | 328 SSG | SI-328-78-033 | 16.09.97 | | SI-328-X | S | | | 3P |
| | | Oil - Oil Leakage rev.AMM Procedure | 328 SSG | SI-328-79-105 | 06.11.02 | | SI-328-X | S | | | 3P |
| | | Engine Oil - Third Gen.Type II Turbo Oils | 328 SSG | SI-328-79-119 | 26.08.05 | | SI-328-X | S | | | 3P |
| | | Maintenance Checks - Correction of Inspection Requirements for FDI | 328 SSG | SI-328-05-145 | 20.12.13 | 1 25.04.16 | SI-328-X | S | | S/N All | 3P |
| | | Towing and Taxiing - Towbarless Towing | 328 SSG | SI-328-09-166 | 27.01.20 | | SI-328-X | S | | S/N All | 3P |
| | | Equipment/Furnishings - Emergency Equipment - Life Vests and PBE Hood | 328 SSG | SI-328-25-154 | 07.03.17 | | SI-328-X | S | | S/N All | 3P |
| | | Equipment/Furnishings - First Aid Kit | 328 SSG | SI-328-25-159 | 09.07.18 | | SI-328-X | S | | S/N All | 3P |
| | | Material Information - Repair Tape for Thermal Insulation Packages | 328 SSG | SI-328-25-163 | 07.11.19 | | SI-328-X | S | | S/N All | 3P |
| | | Fire Protection - Cabin Portable Fire Extinguisher | 328 SSG | SI-328-26-150 | 08.05.15 | | SI-328-X | S | | S/N All | 3P |
| | | Fire Protection - Mandatory Retrofit of Cargo Fire Suppression System for EASA OPS | 328 SSG | SI-328-26-173 | 15.03.22 | | SI-328-X | S | | S/N All | 3P |
| | | Hydraulic Standby DC Pump - Handling during ground operation | 328 SSG | SI-328-29-157 | 15.02.18 | | SI-328-X | S | | S/N All | 3P |
| | | Propellers - Alternative Grease | 328 SSG | SI-328-61-168 | 20.07.20 | | SI-328-X | S | | S/N All | 3P |
| SJ85XX; SJ86XX | | Polyurethane Protective Boots | 3M 3M | SPM | 01.10.07 | | TDS SJ8665 | S | | | 3A |
| | 32-44-26 | Change in Torque Value for Self-locking Nut | ABSC | SL | 24.03.03 | | 90002030-SL-1 | O | | | 3P |
| | | Use of Unauth.Parts in ABSC Wheel and Braking Assemblies | ABSC | GN | 15.01.92 | 4 24.02.97 | GN-1 | O | | | 3A |
| | | Conductivity Hardness Inspection | ABSC | SB | 17.01.00 | 2 18.06.01 | SB GS2000-1 | O | | | 3A |
| | | Standard Koenig Expander Plugs | ABSC | SB | 25.10.01 | 1 18.09.03 | SB GS2001-2 | O | | | 3A |
| | | LG - Brake Assembly - Bolts And Nuts | ABSC | SB | 10.12.01 | | SB GS2001-3 | O | | | 3A |
| | | Brake Assy - Compression Spring Testing | ABSC | SB | 18.08.03 | | SB GS2003-1 | O | | | 3A |
| | | Dry-Stripping of Paint | ABSC | SB | 04.09.01 | 5 04.09.01 | SB GS88-2 | O | | | 3A |
| | | Hardness Tests f.Forged Alum.Wheels | ABSC | SB | 15.06.92 | 5 28.03.03 | SB GS92-1 | O | | | 3A |
| 2610XXX-X | 32-4X-XX | Change in Ownership Of Do328-100 WaBP | ABSC | SL | 04.09.01 | | SL Do328-SL-1 | O | | | 3P |
| | | Wheel Inspection and Overhaul Schedules | ABSC | SL | 19.07.93 | 7 18.01.06 | SL GS-SL-36 | O | | | 3A |
| | | Timken Perform.Code 629 for Bearing Cups and Cones | ABSC | SL | 18.02.94 | 3 17.10.05 | SL GS-SL-38 | O | | | 3A |
| | | Paint Which Complies With EPA Emmision Standards | ABSC | SL | 10.10.97 | 2 26.08.05 | SL GS-SL-46 | O | | | 3A |
| | | Return Mater.Auth.Procedure (RMA) | ABSC | SL | 28.02.98 | 3 22.11.04 | SL GS-SL-47 | O | | | 3A |
| | | ABSC Internet Web Site | ABSC | SL | 15.10.98 | | SL GS-SL-49 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Usage of Adh.Bal.Weights on Nose/Main Wheel Assy | ABSC | SL | 03.10.00 | 2 10.08.06 | SL GS-SL-54 | O | | | 3A |
| | | Altern.Bearing Cone and Seals for Bearing Cone 13685 | ABSC | SL | 28.02.01 | 1 01.04.04 | SL GS-SL-55 | O | | | 3A |
| | | Effect Of Chemical Disinf.On Wheel | ABSC | SL | 22.03.01 | | SL GS-SL-56 | O | | | 3A |
| | | Altern.Bearing Cone and Seal Subassy Repl. (Code629) | ABSC | SL | 30.03.01 | 1 01.04.04 | SL GS-SL-57 | O | | | 3A |
| | | Using Tire/Wheel Balancing Material | ABSC | SL | 03.09.01 | 1 21.02.03 | SL GS-SL-58 | O | | | 3A |
| | | Purch.Info.on Special Tools for Maint.of ABSC Products | ABSC | SL | 15.03.04 | | SL GS-SL-62 | O | | | 3A |
| | | ABSC-Online Technical Publications Index | ABSC | SL | 04.06.04 | | SL GS-SL-63 | O | | | 3A |
| | | Inst. Appr.Requir.for all A/C Braking Sys.Corp.Wheel | ABSC | SL | 27.08.04 | | SL GS-SL-64 | O | | | 3A |
| AR9592, AR9608 | 38-30-06 | DRAIN VALVE ASSEMBLY | ADAMS RITE | SIL | | 2 20.06.16 | AR9592/9608-38-01 | O | | | 3A |
| AR9592-11, 9747-3 | | Water/Waste Disposal Drain Valve Assemblies Modification for Snap-Action | ADAMS RITE | SB | 24.07.95 | | SB AR9592-38-01 | O | | | 3A |
| AR9592 | | Install Improved Drain Plug Assembly | ADAMS RITE | SIL | 13.03.96 | 13.03.96 | VY420-38-01 | O | | | 3A |
| | | APU Test Cell Certification Service | ALLIEDSIGNAL | FSN | 02.01.97 | | 1176-GEN | O | | | 3A |
| 980-4700-XXX | 31-30-40 | Mod Voltage Regulator Grounding | ALLIEDSIGNAL | SB 4 | 01.02.94 | 1 18.06.98 | SB 012-0650-104 | O | | HONEYWELL | 3P |
| 980-4700-XXX | 31-30-40 | Revise FDAU Data Receiver Circuit | ALLIEDSIGNAL | SB 6 | 10.06.95 | 1 27.04.98 | SB 012-0650-106 | O | | HONEYWELL | 3P |
| 980-4700-0XX | 31-30-40 | Connector Shimming Modification | ALLIEDSIGNAL | SB 7 | 02.12.97 | | SB 012-0650-107 | O | | HONEYWELL | 3P |
| 980-4700-XXX | 31-30-40 | Current Limiting Resistor Repl. | ALLIEDSIGNAL | SB 9 | 12.08.98 | | SB 012-0650-109 | O | | HONEYWELL | 3P |
| 980-4700-001/-003 | 31-30-40 | SSFDR Conversion | ALLIEDSIGNAL | SB 12 | 15.09.99 | 1 10.09.03 | SB 012-0650-112 | O | | HONEYWELL | 3P |
| 980-6117-005 | 23-70-43 | 0dB AGC Stability Improvement | ALLIEDSIGNAL | SB 1 | 11.09.95 | | SB 012-0666-101 | O | | HONEYWELL | 3P |
| 980-6117-005 | 23-70-43 | Eliminate AGC Oscillation | ALLIEDSIGNAL | SB 5 | 06.06.96 | | SB 012-0666-105 | O | | HONEYWELL | 3P |
| 980-6020-001 | 23-70-44 | Results in Non-Resetable Bite Light | ALLIEDSIGNAL | SB 1 | 20.06.94 | | SB 012-0667-101 | O | | HONEYWELL | 3P |
| 980-6020-001 | 23-70-44 | Errors when Subjected to HF Interference | ALLIEDSIGNAL | SB 2 | 06.06.95 | 1 05.10.95 | SB 012-0667-102 | O | | HONEYWELL | 3P |
| 980-6020-001 | 23-70-44 | AMD Software Upgrade | ALLIEDSIGNAL | SB 4 | 02.12.96 | | SB 012-0667-104 | O | | HONEYWELL | 3P |
| 980-6020-001 | 23-70-44 | Controller and Software Upgrade | ALLIEDSIGNAL | SB 5 | 02.12.96 | | SB 012-0667-105 | O | | HONEYWELL | 3P |
| 980-6020-0XX | 23-70-44 | Erase Threshold and FSK Calibration | ALLIEDSIGNAL | SB 6 | 31.01.97 | | SB 012-0667-106 | O | | HONEYWELL | 3P |
| 980-6020-0XX | 23-70-44 | Connector Shimming Modification | ALLIEDSIGNAL | SB 7 | 02.12.97 | | SB 012-0667-107 | O | | HONEYWELL | 3P |
| 980-6020-0XX | 23-70-44 | Rotor Circuit Internal Clock Skew Problem | ALLIEDSIGNAL | SB 8 | 01.04.98 | | SB 012-0667-108 | O | | HONEYWELL | 3P |
| 980-6020-XXX | 23-70-44 | Current Limiting Resistor Replacement | ALLIEDSIGNAL | SB 9 | 12.08.98 | 1 26.02.99 | SB 012-0667-109 | O | | HONEYWELL | 3P |
| 980-6020-0XX | 23-70-44 | J4 Connector and Lightning Improvement | ALLIEDSIGNAL | SB 10 | 23.04.99 | | SB 012-0667-110 | O | | HONEYWELL | 3P |
| 980-6020-XXX | 23-70-44 | SSCVR Conversion | ALLIEDSIGNAL | SB 11 | 01.09.99 | 2 08.08.06 | SB 012-0667-111 | O | | HONEYWELL | 3P |
| 3800498-1 | | Repl. of Actuator Diaphragm Assembly | ALLIEDSIGNAL | SB | 19.11.93 | | SB 109812-49-6134 | O | | HONEYWELL | 3A |
| 2118330-2SER5 | | Change Identification Plate | ALLIEDSIGNAL | SB | 07.02.96 | | SB 2118330-49-4066 | O | | HONEYWELL | 3A |
| 2610701-2 | 32-46-02 | Necessity for Bead Seat NDI Insp. | ALLIEDSIGNAL | SB | 31.07.98 | 1 30.11.98 | SB 2610701-32-001 | O | | HONEYWELL | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 3800498-1 | | Change Fuel Control Assy | ALLIEDSIGNAL | SB | 05.10.95 | 2 17.06.96 | SB 3882730-49-7146 | O | | HONEYWELL | 3P |
| 3800498-1 | | Incorporate Improved Labyrinth Seal | ALLIEDSIGNAL | SB | 24.11.93 | 1 07.03.94 | SB GTCP36-49-6132 | O | | HONEYWELL | 3P |
| 3800498-1 | | Improved Igniter Plug Lead | ALLIEDSIGNAL | SB | 04.11.94 | | SB GTCP36-49-6145 | O | | HONEYWELL | 3P |
| 3800498-1 | | Compressor Seal/Ejector System | ALLIEDSIGNAL | SB | 24.02.94 | 1 02.12.94 | SB GTCP36-49-6147 | O | | HONEYWELL | 3P |
| 3800498-1 | | Compr. Inlet Hous./Planetary Gear | ALLIEDSIGNAL | SB | 02.12.94 | | SB GTCP36-49-6156 | O | | HONEYWELL | 3P |
| 3800498-1 | | Rerouting of Wiring Harness Assy | ALLIEDSIGNAL | SB | 01.02.95 | 3 24.07.96 | SB GTCP36-49-6159 | O | | HONEYWELL | 3P |
| 3800498-1 | | Repl. Fuel Control Unit | ALLIEDSIGNAL | SB | 05.10.95 | | SB GTCP36-49-6164 | O | | HONEYWELL | 3P |
| | | Repl. Electronic Control Unit | ALLIEDSIGNAL | SB | 07.02.96 | | SB GTCP36-49-7217 | O | | HONEYWELL | 3P |
| 3800498-1 | | Rotating Comp./Life Limited Comp. | ALLIEDSIGNAL | SB | 17.06.96 | 2 13.03.97 | SB GTCP36-49-7271 | O | | I N V A L I D | 3P |
| 3800498-1 | | Specific Roller Bearings | ALLIEDSIGNAL | SB | 23.10.96 | | SB GTCP36-49-7308 | O | | HONEYWELL | 3P |
| 3800498-1/-3 | | Improved Compressor Seal Assy | ALLIEDSIGNAL | SB | 11.02.98 | 3 10.12.98 | SB GTCP36-49-7346 | O | | HONEYWELL | 3A |
| 3800498-1 | | Pneum./Shaft Power Gas Turbine Eng. | ALLIEDSIGNAL | SB | 04.05.98 | | SB GTCP36-49-7367 | O | | HONEYWELL | 3P |
| | | Abrasive Media Residue Contamination | ALLIEDSIGNAL | SIL | 30.07.93 | | SIL 571 | O | | HONEYWELL | 3A |
| | | Objection to Alum.Oxide Vapor Blast | ALLIEDSIGNAL | SIL | 05.11.93 | | SIL 572 | O | | HONEYWELL | 3A |
| | | Abrasive Media Blasting For Paint Stripp. | ALLIEDSIGNAL | SIL | 10.02.94 | | SIL 576 | O | | HONEYWELL | 3A |
| | | Application of Timken Performance | ALLIEDSIGNAL | SIL | 28.04.94 | 1 30.06.94 | SIL 578 | O | | HONEYWELL | 3A |
| | | Revision of Vendor Info. in CMM's | ALLIEDSIGNAL | SIL | 03.01.95 | 1 28.02.95 | SIL 582 | O | | HONEYWELL | 3A |
| | | Expansion Plug Inst. a.Remov.Tools | ALLIEDSIGNAL | SIL | 10.02.95 | | SIL 583 | O | | | 3A |
| 2610702 | | Stator Plate Stamping | ALLIEDSIGNAL | SIL | 27.02.95 | | SIL 585 | O | | | 3P |
| | | Appearance of Spoke Windows | ALLIEDSIGNAL | SIL | 28.02.95 | | SIL 586 | O | | | 3A |
| | | Retain.Clip Weakness a.Spares Disp. | ALLIEDSIGNAL | SIL | 30.06.95 | | SIL 587 | O | | | 3A |
| | | Wheel Flange Separation | ALLIEDSIGNAL | SIL | 25.08.95 | | SIL 595 | O | | HONEYWELL | 3A |
| 2610485 | | Improved Nose Wheel Grease Seal | ALLIEDSIGNAL | SIL | 02.02.96 | | SIL 597 | O | | Bendix King | 3P |
| | | ALS Approval of Mobil Aviation Grease | ALLIEDSIGNAL | SIL | 30.11.96 | | SIL 613 | O | | | 3A |
| | | Ultrasonic Tie Bolt Inspection | ALLIEDSIGNAL | SIL | 15.12.96 | | SIL 614 | O | | HONEYWELL | 3A |
| | | TAFA Arc Jet Thermal Spray Process | ALLIEDSIGNAL | SIL | 25.02.97 | | SIL 618 | O | | | 3A |
| 2610701 | | Cracked Main Wheel Tie Bolt Nuts | ALLIEDSIGNAL | SIL | 28.02.98 | | SIL 631 | O | | HONEYWELL | 3P |
| 2610701 | 32-46-02 | Proper Heat Shield Installation | ALLIEDSIGNAL | SIL | 31.05.99 | | SIL 659 | O | | | 3P |
| | 32-49-01 | MIL-T-5544 Cancellation | ALLIEDSIGNAL | SIL | 30.06.99 | | SIL 660 | O | | | 3A |
| | 32-49-01 | Zenthane Plus Altern.Fast Cure Paint Sys. | ALLIEDSIGNAL | SIL | 30.09.99 | | SIL 667 | O | | | 3A |
| 3882730-2 | 49-30-91 | Repl. Encased Plain Seal | ALLIEDSIGNAL | SPB | 09.07.96 | | SPB 3882730-GTE1076 | O | | | 3P |
| 3882730-2 | 49-30-91 | New Identification Plate | ALLIEDSIGNAL | SPB | 19.03.98 | | SPB 3882730-GTE1145 | O | | HONEYWELL | 3P |
| 3800498-1 | 49-24-10 | Repl. Tube Assembly | ALLIEDSIGNAL | SPB | 23.08.96 | | SPB GTCP36-GTE1079 | O | | HONEYWELL | 3P |
| 3800498-1 | 49-24-10 | New Identification Plate | ALLIEDSIGNAL | SPB | 19.12.96 | | SPB GTCP36-GTE1096 | O | | HONEYWELL | 3P |
| | 49-30-91 | Spare Parts Change Notification | ALLIEDSIGNAL | SPB | 28.04.95 | | SPB GTE0504 | O | | HONEYWELL | 3P |
| 980-6020-001 | 23-70-44 | Latest Modification a.Changes to Unit | ALLIEDSIGNAL | SIL | 16.10.95 | | SSCVR-6020-23-01 | O | | HONEYWELL | 3P |
| 980-6020-001 | 23-70-44 | Changes in Self-Test Indications | ALLIEDSIGNAL | SIL | 16.10.95 | | SSCVR-6020-23-02 | O | | HONEYWELL | 3P |
| 980-4700-0XX | | Emergency Locator Beacon Identif. | ALLIEDSIGNAL | SIL | 30.04.96 | | SSFDCVR-1/96 | O | | | 3P |
| | | Technical Standing Orders Rev. | ALLIEDSIGNAL | SIL | 27.11.96 | | SSFDCVR-2/96 | O | | HONEYWELL | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1112-1AA | 25-11-12 | Improved Seatpan Latch Pin Knob | AMI | SB | 12.08.94 | | SB 1112-25-001 | O | | | 3P |
| | | Modification to Threaded Inserts on Bonded Wall Assembly | AMI | SB | 20.10.95 | | SB 2060-25-001 | O | | | 3P |
| 0150001-/1180002- | | REPLACEMENT OF ROTARY BUCKLE | AM-SAFE | ASB | 29.03.16 | 5 21.06.16 | 1150004-25-A01 | S | | | 3A |
| 3106-1-011-8012 | | Insp.of Restrain System End Release Buckle | AM-SAFE | SB | 12.09.05 | 2 16.02.06 | 50444-25-01 | O | | | 3A |
| 20040 amendment B/C | 24-22-66 | Modif.of the AC Generator 20040 | AUXILEC | SB | 01.02.99 | | SB 20040-24-001 | O | | THALES | 3P |
| 20040 amendment C/D | 24-22-66 | Modification of the AC Generator | AUXILEC | SB | 01.02.99 | | SB 20040-24-002 | O | | THALES | 3P |
| 8160-121 | 24-35-32 | Improv.in order to increase the strength of Term.Block | AUXILEC | SB | 01.02.99 | | SB 8160-121-24-001 | O | | THALES | 3A |
| 8160-121 | 24-35-32 | Modifikation of the Starter Generator | AUXILEC | SB | 01.02.99 | | SB 8160-121-24-002 | O | | DELETED | 3A |
| 8160-121 | 24-35-32 | Modifikation of the Starter Generator | AUXILEC | SB | 26.10.00 | | SB 8160-121-24-003 | O | | THALES | 3A |
| 20040 | | Product Enhancement Announcement | AUXILEC | SIL | 01.04.98 | | SIL 20040-24-01 | O | | THALES | 3A |
| | | Consumables Products | AUXILEC | SIL | 03.01.11 | | SIL 24-99-001 | O | | THALES | 3A |
| | | Electrostatic Discharge Sensitive Components | AUXILEC | SIL | 09.12.10 | | SIL 24-99-002 | O | | THALES | 3A |
| 106-000-4 | 24-22-71 | Modif. Of DC Bus Power Control Unit | AUXILEC (THALES) | SB | 25.06.02 | | SB 106-000-4-24-001 | O | | AUXILEC | 3A |
| 20040 amendment E/F | 24-22-66 | Modif.of the AC Generator 20040 | AUXILEC (THALES) | SB | 23.06.03 | | SB 20040-24-003 | O | | AUXILEC | 3P |
| 20040 | 24-22-66 | Modif.of the AC Generator 20040 | AUXILEC (THALES) | SB | 23.09.05 | 1 15.02.12 | SB 20040-24-004 | O | | AUXILEC | 3P |
| 8160-121 | 24-35-32 | Modif.of the Starter Generator 8160-121 | AUXILEC (THALES) | SB | 23.06.03 | | SB 8160-121-24-004 | O | | AUXILEC | 3A |
| 8160-121 | 24-35-32 | Overhaul of Starter Generator | AUXILEC (THALES) | SB | 21.05.03 | 1 05.11.03 | SB 8160-121-24-005 | O | | AUXILEC | 3A |
| 8160-121 | 24-35-32 | Modif.of the Starter Generator 8160-121 | AUXILEC (THALES) | SB | 22.12.04 | | SB 8160-121-24-007 | O | | AUXILEC | 3A |
| 8160-121 | 24-35-32 | Brush Check of the Starter Generator 8160-121 using new Brush Gauge P036121 | AUXILEC (THALES) | SB | 09.03.11 | | SB 8160-121-24-008 | O | | AUXILEC | 3A |
| P046363-1 | | Power PCB Z500 Replacement by P046888-1 | AUXILEC (THALES) | SIL | 18.12.14 | | SIL 118-000-1-24-001 | O | | THALES | 3A |
| 20040 | | AC Generator 20040 | AUXILEC (THALES) | SIL | 16.02.12 | | SIL 20040-24-002 | O | | AUXILEC | 3P |
| 7954A009 | | Second Source of Anti-Flash Varnish 2407-01 | AUXILEC (THALES) | SIL | 05.09.12 | | SIL 24-99-003 | O | | AUXILEC | 3A |
| 8160-121 | 24-35-32 | Starter Gen.-Brush and Bearing Replacement | AUXILEC (THALES) | SIL | 01.06.99 | 2 02.11.06 | SIL 8160-121-24-001 | O | | AUXILEC | 3A |
| 8160-121 | 24-35-32 | Starter Generat.in House Thermo-Switch Check | AUXILEC (THALES) | SIL | 19.09.03 | | SIL 8160-121-24-003 | O | | AUXILEC | 3A |
| 8160-121 | 24-35-32 | Starter Gen.-Procedure for Brush Replacement | AUXILEC (THALES) | SIL | 24.09.08 | | SIL 8160-121-24-005 | O | | AUXILEC | 3A |
| 8160-121 | 24-35-32 | Speed Sensor Tightening Procedure | AUXILEC (THALES) | SIL | 15.04.09 | 1 18.11.09 | SIL 8160-121-24-006 | O | | AUXILEC | 3A |
| 8160-121 | 24-35-32 | Packaging for Starter Generator | AUXILEC (THALES) | SIL | 15.07.09 | | SIL 8160-121-24-007 | O | | AUXILEC | 3A |
| 5382-1 | 23-30-11 | Passenger Address Amplifier | AVTECH | SB | 10.03.92 | | SB 5382-23-901 | O | | | 3A |
| 5382-1 | 23-30-11 | Passenger Address Amplifier | AVTECH | SB | 09.12.93 | | SB 5382-23-902 | O | | | 3A |
| 5382-1 | 23-30-11 | Passenger Address Amplifier | AVTECH | SB | 23.12.93 | | SB 5382-23-903 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 5382-1 | 23-30-11 | Passenger Address Amplifier | AVTECH | SB | 08.08.96 | | SB 5382-23-904 | O | | | 3A |
| 5382-1 | 23-30-11 | Passenger Address Amplifier | AVTECH | SB | 31.01.97 | | SB 5382-23-905 | O | | | 3A |
| 5382-1 | 23-30-11 | Passenger Address Amplifier | AVTECH | SB | 22.08.97 | | SB 5382-23-906 | O | | | 3A |
| 5382-1 | 23-30-11 | Passenger Address Amplifier | AVTECH | SB | 30.08.97 | | SB 5382-23-907 | O | | | 3A |
| 5483-1 | 23-30-08 | Interphone Handset | AVTECH | SB | 07.04.93 | | SB 5483-23-901 | O | | | 3A |
| 751300X-XXX | | Control Head | AVTECH | SB | 10.10.94 | 1 10.03.95 | SB 7513-34-901 | O | | | 3A |
| 5382-1 | 23-30-11 | Passenger Address Amplifier | AVTECH | SL | 16.05.00 | | SL 5382-23-501 | O | | | 3A |
| 5382-1 | 23-30-11 | Passenger Address Amplifier | AVTECH | SL | 10.06.04 | | SL 5382-23-502 | O | | | 3A |
| 2524.519/520 | 25-20-00 | Armrest Retro-Fit | B/E AERO AMP | SB | 29.10.96 | | 2524.519/520-25-01 | O | | B/E AERO | 3P |
| 2524.519/520 | 25-20-00 | Armrest Replacement | B/E AERO AMP | SB | 24.01.97 | | 2524.519/520-25-02 | O | | B/E AERO | 3P |
| 2524.519/520 | 25-20-00 | Inertia Reel Web Guide | B/E AERO AMP | SB | 10.11.97 | | 2524.519/520-25-03 | O | | B/E AERO | 3P |
| 2524.519/520 | 25-20-00 | Seats Cover / TSO Tag | B/E AERO AMP | SB | 02.04.98 | | 2524.519/520-25-04 | O | | B/E AERO | 3P |
| 2524.519/520 | 25-20-00 | Seats Cover / TSO Tag | B/E AERO AMP | SB | 28.08.98 | | 2524.519/520-25-05 | O | | B/E AERO | 3P |
| 2524-519/520A11000 | 25-20-00 | Restraint System/Seat Cover Exchange | B/E AERO AMP | SB | 09.05.00 | IR | 2524.519/520-25-14 | O | | B/E AERO | 3A |
| 2524-519/520 | 25-20-00 | DO328 Front Row Seats | B/E AERO AMP | SB | 16.08.00 | A 08.09.00 | 2524.519/520-25-20 | O | | AMP | 3A |
| 2524-519/520 | 25-20-00 | Insp.Procedure for Seat Frame attach caps | B/E AERO AMP | SB | 02.11.01 | | 2524.519/520-25-3 2 | O | | AMP | 3A |
| 2524-519/520 | 25-20-00 | Repl. Damaged Seat Frame Attach Caps | B/E AERO AMP | SB | 04.10.01 | C 12.11.01 | 2524.519/520-25-30 | O | | AMP | 3A |
| 87064/5XXX | | Add Ashtrays to Dornier Seats | B/E AERO BURNS | SB | 02.01.96 | | SB 25-20-1042 | O | | | 3A |
| 87064/5XXX | | Add Ashtrays to Dornier Seats | B/E AERO BURNS | SB | 14.03.96 | | SB 25-20-1057 | O | | | 3A |
| | | Inspection a. Repair of Fireblocking Liners | B/E AERO BURNS | SB | 30.07.98 | | SB 25-20-1223 | O | | | 3A |
| 87064/5XXX | | Convert Dornier Shipset 110 & 111 | B/E AERO BURNS | SB | 04.09.94 | | SB 25-20-1234 | O | | | 3P |
| | | Inspect and Repair Kevlar Back Diaphragms | B/E AERO BURNS | SB | 20.08.98 | | SB 25-20-1237 | O | | | 3A |
| | 25-2X-XX | Replace Literature Pocket snap with screw and Rivnut for Dornier | B/E AERO BURNS | SB | 01.09.98 | A 02.09.99 | SB 25-20-1241 | O | | | 3A |
| | | Adding Protective Clip to Dornier HCEB | B/E AERO BURNS | SB | 29.09.98 | A 22.09.99 | SB 25-20-1264 | O | | | 3A |
| 87881522 | 25-27-78 | Change Of Seat Fabric And Seat Belt | B/E AERO BURNS | SB | 23.09.99 | A 19.11.99 | SB 25-20-2063 | O | | | 3A |
| 8706XXXX | 25-40-63 | Arm Escutcheon Mod./Ashtray Removal | B/E AERO BURNS | SB | 29.03.00 | A 05.04.00 | SB 25-20-2290 | O | | OZARK | 3A |
| 87064551 | | Leather Covers | B/E AERO BURNS | SB | 13.03.01 | | SB 25-20-2303 | O | | | 3A |
| 87XXXXXX | | Dornier Conversion to Remove Ashtrays | B/E AERO BURNS | SB | 17.07.00 | | SB 25-20-2376 | O | R | | 3A |
| 870646X5,870644X5,878804X | | AWN 79 Type III Exit Rework | B/E AERO BURNS | SB | 27.07.00 | A 07.09.00 | SB 25-20-2385 | O | | | 3A |
| 87XXXXXX | | Dornier Conversion to Fabric Covers | B/E AERO BURNS | SB | 17.03.01 | | SB 25-20-2511 | O | | | 3A |
| 87064/5XXX | | Dornier Dress Cover Conversion | B/E AERO BURNS | SB | 15.01.02 | | SB 25-20-2646 | O | | | 3A |
| 8788XXXX | 25-40-49 | Dornier Ashtray Addition | B/E AERO BURNS | SB | 26.08.04 | | SB 25-20-3156 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 87065 Series | 25-27-78 | Repl.of Tolerance Legs JB6.8 Seat Assys | B/E AERO BURNS | SB | 22.06.05 | | SB 25-20-3341 | O | | Air Vallee | 3A |
| 87XXXXXX | | Repl. of seat belt shackles | B/E AERO BURNS | SB | | H 27.02.97 | SB 25-20-989 | O | | | 3A |
| | | Non Ash Escutcheons on Dornier Seats | B/E AERO BURNS | SL | 04.08.98 | A 25.08.98 | SL 98-044 | O | | | 3A |
| | | Sheet Metal Armrest on Dornier Seats | B/E AERO BURNS | SL | 06.08.98 | B 27.08.98 | SL 98-045 | O | | | 3A |
| | | Replacement of outboard struts on Dornier Seats | B/E AERO BURNS | SL | 23.09.98 | | SL 98-058 | O | | | 3A |
| 72184002B | 25-33-40 | Introd.of New Blind Cap | B/E AERO INVENTUM | SB | 16.04.02 | | SB DR-25-005 | O | | INVENTUM | 3A |
| DR40-Series | | Introduction of new Heating Cartridge | B/E AERO INVENTUM | SB | 21.11.14 | 1 14.03.17 | SB DR40-25-0006 | O | | INVENTUM | 3A |
| DR 40-Series | 25-33-40 | Modified Element Tool | B/E AERO INVENTUM | SB | 16.04.03 | 1 24.09.03 | SB-25-1014 | O | | INVENTUM | 3A |
| DR 40-Series | 25-33-40 | Introduction of a new Pressure Relief Valve | B/E AERO INVENTUM | SB | 25.07.03 | | SB-25-1018 | O | | INVENTUM | 3A |
| 72184002B | 25-33-40 | Intro.of An Improved Sub-Structure | B/E AERO INVENTUM | SB | 12.12.03 | 1 07.10.14 | SB-25-1031 | O | | INVENTUM | 3A |
| 72184002 | 25-33-40 | Installation of Washers and Rivets | B/E AERO INVENTUM | SIL | 20.07.00 | | SIL DOC-25-002 | O | | INVENTUM | 3A |
| 72184002B | 25-33-40 | Introduction of Conformal Coating | B/E AERO INVENTUM | SIL | 11.03.02 | | SIL DOC-25-012 | O | | INVENTUM | 3A |
| 72184002B | 25-33-40 | Correct Part Number in CMM | B/E AERO INVENTUM | SIL | 25.03.02 | | SIL DOC-25-019 | O | | INVENTUM | 3A |
| 72184002B | 25-33-40 | Modif.of Boiler Assemblies | B/E AERO INVENTUM | SIL | 04.01.01 | | SIL DR40-25-009 | O | | INVENTUM | 3A |
| | | Serial Number Identification | B/E AERO INVENTUM | SIL | 13.06.02 | | SIL-25-0005 | O | | INVENTUM | 3A |
| 72184002B | 25-33-40 | Restructuring Numbering Spare Parts | B/E AERO INVENTUM | SIL | 29.07.02 | | SIL-25-0012 | O | | INVENTUM | 3A |
| DR 40-Series | 25-33-40 | Intr.of approved O-Ring for Jet Breaker Set | B/E AERO INVENTUM | SIL | 03.03.03 | | SIL-25-0022 | O | | INVENTUM | 3A |
| | 25-33-40 | Part Number Change | B/E AERO INVENTUM | SIL | 06.02.03 | | SIL-25-0032 | O | | INVENTUM | 3A |
| 72184002B | 25-33-40 | Deleted Service Bulletin | B/E AERO INVENTUM | SIL | 24.11.03 | | SIL-25-0045 | O | | INVENTUM | 3A |
| DR 40-Series | 25-33-40 | Intro.of New Jet Breaker f.Water Faucet | B/E AERO INVENTUM | SL | 01.06.95 | | SL DR40-02 | O | | B/E AERO | 3A |
| DR 40-Series | 25-33-40 | New Printed Circuit Board | B/E AERO INVENTUM | SL | 01.09.97 | | SL DR40-06 | O | | INVENTUM | 3A |
| DR 40-Series | 25-33-40 | Intro.of A New O-Ring | B/E AERO INVENTUM | SL | 01.01.98 | | SL DR40-07 | O | | INVENTUM | 3A |
| 72184002B | 25-33-40 | Alternate pressure relief valve | B/E AERO INVENTUM | SL | 28.10.98 | | SL DR40-1 | O | | INVENTUM | 3A |
| 119003-11/119003-21 | | Oxygen - Crewmember Protective Breathing Equipment (PBE) -119003-11 PBE Replacement | B/E AERO PURITAN | SB | 09.11.15 | 1 12.04.16 | 119003-35-009 | O | | | 3A |
| 119003-11/119003-21 | | Oxygen - Crewmember PBE - PBE Conversion | B/E AERO PURITAN | SB | 12.04.16 | | 119003-35-010 | O | | B/E AERO | 3A |
| 119003-11 | | Risk of Fire and/or functional impairment on unserviceabel PBE | B/E AERO PURITAN | SB | 04.02.15 | | 119003-35-011 | O | | PURITAN BENNETT | 3A |
| 119003-21 | | Oxygen - Crewmember PBE - Modification of PBE bag | B/E AERO PURITAN | SB | 21.06.16 | 1 31.08.16 | 119003-35-012 | O | | PURITAN BENNETT | 3A |
| 119003-21 | | Oxygen - Crewmember Protective Breathing Equipment (PBE) - 119003-21 PBE Replacement | B/E AERO PURITAN | SB | 09.01.17 | 2 19.07.17 | 119003-35-013 | O | | PURITAN BENNETT | 3A |
| 119003-11 | | RESTORATION OF PBE PN 119003-11 BY REPLACING CANISTER ASSEMBLY | B/E AERO PURITAN | SB | 14.05.09 | | 119003-35-4 | O | | B/E AERO | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 119003-11 | | PROTECTIVE BREATHING EQUIPMENT PN 119003-11 REPLACEMENT | B/E AERO PURITAN | SB | 19.04.10 | | 119003-35-5 | O | | B/E AERO | 3A |
| 119003-XX/119063/119065 | | Proper handling of the Protective Breathing Equipment (PBE) | B/E AERO PURITAN | SIL | 24.01.02 | 2 24.10.17 | 119003-SIL-3 | O | | B/E AERO | 3A |
| 119003-11 | | Provide better access relative to useful life information for the Protective Breathing Equipment (PBE) | B/E AERO PURITAN | SIL | 05.11.02 | | 119003-SIL-4 | O | | B/E AERO | 3A |
| 119003-11 | | Additional Instructions for User of B/E Aerospace Protective Breathing Equipment (PBE) | B/E AERO PURITAN | SIL | 24.07.12 | | 119003-SIL-5 | O | | B/E AERO | 3A |
| 119003-XX | | Instructions Preventing the Use of Unserviceable B/E Aerospace (PBE) | B/E AERO PURITAN | SIL | 25.03.13 | 1 13.10.17 | 119003-SIL-6 | O | | B/E AERO | 3A |
| 119003-11/119003-21 | | Protective Breathing Equipment Part Number Supercession | B/E AERO PURITAN | SIL | 23.06.14 | 2 09.09.15 | 119003-SIL-7 | O | | B/E AERO | 3A |
| 119003-11/119003-21 | | Oxygen - Crewmember Protective Breathing Equipment (PBE) 119003-11, 119003-21 Disposal | B/E AERO PURITAN | SIL | 24.02.17 | | 119003-SIL-8 | O | | B/E AERO | 3A |
| 119003 | | Attachment of Generator Warning Label | B/E AERO PURITAN | SIL | 05.03.98 | | 2059-08 | O | | B/E AERO | 3A |
| 176XXX-XX | | New Torque Method/Leaking Regulators | B/E AERO PURITAN | SIL | 05.11.98 | | 3500-98-21 | O | | B/E AERO | 3A |
| 112052-01 | | Altitude Compensating Regulator Test Stand | B/E AERO PURITAN | TSCP | 11.09.00 | B04 10.06.06 | 962020-CP | O | | PURITAN BENNETT | 3A |
| 112052-01 | | Altitude Compensating Regulator | B/E AERO PURITAN | ATP | 30.09.91 | A07 16.10.96 | ATP-846046-01 | O | | PURITAN BENNETT | 3A |
| 118077 | | RIVET TEST - SMOKE GOGGLES | B/E AERO PURITAN | SB | 04.01.11 | 1 06.07.11 | SB 118077-35-01 | O | | B/E AERO | 3A |
| 119003 / -1/-11 | | Protective Breathing Equipment Reduction of Useful Life | B/E AERO PURITAN | SB | 06.06.02 | 3 | SB 119003-35-3 | O | | B/E AERO | 3A |
| 174XXX-XX | | Passenger Oxygen System Mask | B/E AERO PURITAN | SB | 06.09.10 | | SB 174080-35-04 | O | | PURITAN BENNETT | 3A |
| 174260-01/-14 | | Sweep-On 2000 Fullface Crew Mask Regul. | B/E AERO PURITAN | SB | 01.08.94 | | SB 174250-35-1 | O | | B/E AERO | 3A |
| 174260-Series | 35-10-60 | Align Demand Diaphr.to Prev.Lock-Up Exhal.Valve | B/E AERO PURITAN | SB | 01.08.94 | | SB 174250-35-1 | O | | PURITAN BENNETT | 3A |
| 174260-01/-14 | | Sweep-On 2000 Fullface Crew Mask Regul. | B/E AERO PURITAN | SB | 01.09.95 | | SB 174250-35-2 | O | | B/E AERO | 3A |
| 174260-Series | 35-10-60 | P/N Repl. Due to Product Improvements | B/E AERO PURITAN | SB | 01.09.95 | | SB 174250-35-2 | O | | PURITAN BENNETT | 3A |
| 174260-Series | | Oxygen Crew Mask | B/E AERO PURITAN | SB | 24.04.00 | | SB 174250-35-3 | O | | PURITAN BENNETT | 3A |
| 174690-95 | | Sweep On Mask - Locking Clip retrofit | B/E AERO PURITAN | SB | 21.04.00 | | SB 174250-35-4 | O | | PURITAN BENNETT | 3A |
| 174260-Series | | Sweep On Mask - Conversion of Part Number | B/E AERO PURITAN | SB | 14.03.03 | 1 20.10.03 | SB 174260-35-01 | O | | PURITAN BENNETT | 3A |
| C351-2000 | | Passenger Mask Series | B/E AERO PURITAN | SB | 01.07.96 | 2 25.02.98 | SB C351-2000-35-1 | O | | PURITAN BENNETT | 3A |
| 176226-77 | | PRD-Revise Setting Limit per Dot Docket | B/E AERO PURITAN | SB | 31.07.07 | 1 15.08.07 | SB PRD-35-1 | O | | B/E AERO | 3A |
| 174097-88/174485 | 35-24-04 | Maint.of TSO Passenger Oxygen Mask | B/E AERO PURITAN | SIL | 10.08.01 | 2 25.11.15 | SIL 174095-1 | O | | PURITAN BENNETT | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 174097-88/174485 | 35-24-04 | TSO Passenger Mask | B/E AERO PURITAN | SIL | 19.04.02 | | SIL 174095-2 | O | | PURITAN BENNETT | 3A |
| 174260-Series | | Fullface Mask - Face Piece Lock.Mechanism | B/E AERO PURITAN | SIL | 18.05.00 | 1 07.05.03 | SIL 174250-1 | O | | PURITAN BENNETT | 3A |
| 174260-Series | | Crew Mask-Interrupt.Transm.of Microphone | B/E AERO PURITAN | SIL | 23.01.01 | | SIL 174250-2 | O | | PURITAN BENNETT | 3A |
| 174260-Series | | Crew Mask-Upgrd.Oxygen Supply Hose Swivel | B/E AERO PURITAN | SIL | 01.08.01 | | SIL 174250-3 | O | | PURITAN BENNETT | 3A |
| All P/N | | Upgr.of Sweep-on 2000 or Fullface Oxygen Crew Mask | B/E AERO PURITAN | SIL | 12.06.02 | | SIL 174250-4 | O | | PURITAN BENNETT | 3A |
| 176226-77 | | Cylinder Assembly Identification | B/E AERO PURITAN | SIL | 04.12.02 | | SIL 176226-1 | O | | PURITAN BENNETT | 3A |
| 174260-Series | | Retro.of Adjust.Comf.Contr.Harn.Opt.to Sweep | B/E AERO PURITAN | SIL | 24.02.99 | | SIL D1014-02 | O | | PURITAN BENNETT | 3A |
| 95218-X | 71-20-34 | Engine Vibration Isolationr, Restoration Interval Sampling Program | BARRY CONTROLS | SB | 25.01.99 | 5 19.07.00 | SB DO328-71-03 | S | | Now is Hutchinson | 3P |
| | | Remplacemnet of TP3100 for DP4100 | BECKER | SIL | 25.06.02 | 1 01.01.02 | DP4100-01-2002 | O | | | 3A |
| S29S-7D5240-71 & 72 | | Ice Recognition Strip Refurbishment | BFG ICE | SNL | 13.09.03 | | SNL 03-061 | O | | S29S-7D5240-71, S29S-7D5240-72 | 3A |
| 74-451-AC | | Erosion Repair Kit | BFG ICE | SNL | 31.07.96 | 13 10.03.04 | SNL 96-033 | O | | 74-451-AC | 3A |
| | | Update on Alphasat and Beijing SAS | COBHAM | SIL | 01.07.14 | | 95-142702 | O | | | 3A |
| 811099-3/-4/-5 | 73-21-74 | Product Transition from Windsor Locks to Kansas Aviation | Collins Aerospace | SIL | 03.12.20 | 1 23.04.21 | SIL 832 | O | | | 3P |
| 22-1262183-0400 | | Switch Guard For Flight Attendant Panel | COMTRONIC | SB | 19.03.01 | | SB-328-001-A | O | | | 3A |
| 3214-30/-31 | 33-51-17 | Identification of Original Diehl Batteries | DIEHL | SIL | 09.09.01 | 2 28.04.15 | 3214-30-01/01 | O | | | 3A |
| 3214-31 | 33-51-17 | Test Prodecure Battery P/N 3214-31 | DIEHL | MI | 14.06.02 | | 321431-01/02 | O | | | 3A |
| 3214-31 | | Visual Inspection and Modification of Battery Pack | DIEHL | SB | 05.12.14 | | 3214-33-01 | O | | | 3A |
| 3214-31 | | Battery Charger EP4-025-67B | DIEHL | SIL | 14.02.03 | | 3214-33-01/03 | O | | | 3A |
| 3214-30 / 3214-31 | | Information on Battery Analyzer Cadex C7400ER-C for Batteries | DIEHL | SIL | 10.09.18 | 3 10.09.18 | 3214-33-01/04 | O | | | 3A |
| | | Storage Handling Overview for Power Supply Batteries | DIEHL | SIL | 01.03.05 | 15 10.08.21 | 3214-33-01/05 | O | | | 3A |
| 3214-30 | 33-51-07 | Battery P/N 3214-30 Mod. B Status Information | DIEHL | SIL | 15.07.87 | | 3214-33-01/87 | O | | | 3A |
| 3214 | | Modification of Pre-VSB PNR 3214-31 AMDT D to Post-VSB PNR 3214-31 AMDT E | DIEHL | SB | 23.11.17 | | 3214-33-02 | O | | | 3A |
| 3214-30 | 33-51-07 | Replacement of battery P/N 3214-30 | DIEHL | SIL | 16.01.02 | | 3214-33-02/02 | O | | | 3A |
| 3214-30 | 33-51-07 | Battery P/N 3214-30: Lifetime and Storage Time | DIEHL | SIL | 22.04.02 | | 3214-33-03/02 | O | | | 3A |
| 3214-31 | | Introduction of Amendment "B" | DIEHL | SIL | 05.12.05 | | 3214-33-06/05 | O | | | 3A |
| 3214-73 | 33-51-99 | Improvement of the Product Reliability | DIEHL | SB | 20.11.98 | 1 15.07.99 | 321473-33-01 | O | | | 3A |
| 3285-10 | 30-42-02 | Improvement of the Product Reliability | DIEHL | SB | 30.10.98 | | 3285-30-01 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Blacklisting of Microsoft Office Formats Prior to Office 2007 as Email Attachment | DIEHL | CIL | 03.04.19 | 1 | Aviation/CIL-2019-001 | O | | | 3A |
| 3214-31 | 33-51-17 | Guaranty of a Longterm Warranty for Batteries | DIEHL | CIL | 02.09.02 | 1 22.03.13 | CIL 32143X-01/02 | O | | | 3A |
| 3253-10 | 33-24-99 | Ballast Unit P/N 3253-10 | DIEHL | CIL | 20.03.01 | 1 | CIL 325310-01/01 | O | | | 3A |
| | | Step 2: Consolidation and Simplification | DIEHL | CIL | 27.09.18 | | CIL DA2018-01B | O | | | 3A |
| | | Non-approved Spare Parts in Diehl Aerospace Equipment | DIEHL | CIL | 12.03.10 | 1 07.04.10 | CIL-2010-001 | O | | | 3A |
| 3214-30/-31 | 33-51-17 | NiCd Batteries: Safety Instructions / Material Safety Data Sheet | DIEHL | SIL | 18.07.06 | 4 20.09.17 | D1347-33-001 | O | | | 3A |
| 3214-31 | 33-51-17 | Introduction of Amendment "C" for Battery | DIEHL | SIL | 16.04.12 | 1 09.08.12 | D1347-33-046 | O | | | 3A |
| | | Diehl Aerospace Customer Support Centers worldwide | DIEHL | CIL | 10.08.10 | 11 20.12.16 | DAs/CIL-2008-001 | O | | | 3A |
| | | Merger of 14 CFR Part 145 (FAA) Approvals B3WY696J and B2WY697J | DIEHL | CIL | 23.02.16 | | DAs/CIL-2016-001 | O | | | 3A |
| | | Information needed on Repair Order | DIEHL | CIL | 04.07.22 | 1 13.07.22 | DAs/CIL-2022-002 | O | | | 3A |
| | | Introduction of new representation of the CMM Part Number | DIEHL | SIL | 18.05.18 | 2 02.08.18 | DAs-VSIL-0002 | O | | | 3A |
| | | Introduction of change of surface treatment for Diehl Aerospace mechanic parts with CAGE CODE D2439 | DIEHL | SIL | 05.06.19 | | DAs-VSIL-0003 | O | | | 3A |
| | | Authorisation to assingn special serial numbers (S/N) | DIEHL | SIL | 13.12.19 | | DAs-VSIL-0004 | O | | | 3A |
| | | Customer Training Catalogue | DIEHL | SIL | 01.05.18 | | VDN-535 | O | | | 3A |
| 9-082-87 | | Repl. None Braked Castors by Braked | DRIESSEN | SL | 12.04.02 | | CASTOR-061-001 | O | | | 3A |
| AC69895 | 32-42-03 | LG - Brake Metering Unit | DUNLOP | SB | 16.05.94 | 2 10.07.95 | SB 32-1095 | O | | | 3P |
| ACM30488 | 32-43-31 | LG - Hydraulic Fuse | DUNLOP | SB | 16.05.94 | 2 22.08.94 | SB 32-1096 | O | | | 3P |
| AE20768 | 32-43-36 | Introduction of Anti - Skid Control Unit | DUNLOP | SB | 05.04.95 | | SB 32-1109 | O | | | 3P |
| AC69895 | 32-42-03 | LG - Brake Metering Unit AC69895 | DUNLOP | SB | 11.07.96 | | SB 32-1130 | O | | | 3P |
| AC69963 | 32-42-03 | Introduction of BMU AC69963 | DUNLOP | SB | 17.10.97 | 1 15.09.00 | SB 32-1131 | O | | | 3P |
| AC69963 | 32-42-03 | LG - Brake Metering Unit | DUNLOP | SB | 29.07.99 | | SB 32-1195 | O | | | 3P |
| AC69965-2 | 32-43-02 | LG - Intro.of Emergenca ParkBrake Valve | DUNLOP | SB | 29.03.04 | | SB 32-1262 | O | | | 3P |
| AC69963 | 32-42-03 | LG - Finite Life of Hous.Assy, Parts of BMU | DUNLOP | SB | 23.11.04 | | SB 32-1344 | O | | | 3P |
| AC70071 | 32-42-04 | LG - Finite Life of Hous.Assy, Parts of BMU | DUNLOP | SB | 23.11.04 | | SB 32-1345 | O | | | 3P |
| AC69965-2/-3 | 32-43-02 | LG - Finite Life of Bodies, Parts of Em.Park Brake Valve | DUNLOP | SB | 23.11.04 | | SB 32-1350 | O | | | 3P |
| AC69895 | 32-42-03 | LG - Finite Life of Var.Parts of BMU | DUNLOP | SB | 23.11.04 | | SB 32-1352 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Recomm.of Storage&Handling of unmount.Tire | DUNLOP | SIL | 20.01.03 | 1 | SIL 2003-32-001 | O | | | 3A |
| ACM30488MOD7 | 32-43-31 | Part List for MOD 7 Standard of Unit | DUNLOP | NL | 17.08.94 | | SN 32-00003 | O | | | 3P |
| AC69895 | | BMU - Intro. of Option.Parts-Mod.C2797 | DUNLOP | NL | 22.03.96 | | SN 32-00064 | O | | | 3P |
| AC69965 | | Intro. of Preliminary Maint.Data and Procedures | DUNLOP | NL | 19.03.97 | | SN 32-00139 | O | | | 3P |
| AC69963 | | Introduction of BMU AC69963 | DUNLOP | NL | 01.10.97 | | SN 32-00188 | O | | | 3P |
| AC69965 | | Intro.of Emergency/Park Valve AC69965 | DUNLOP | NL | 06.08.98 | 1 | SN 32-00189 | O | | | 3P |
| AC69965 | 32-43-02 | Emergency/Park Brake Valve | DUNLOP | NL | 06.08.98 | | SN 32-00217 | O | | | 3P |
| GENERAL | | Use of Disinfectant Chemicals | DUNLOP | NL | 22.03.01 | 1 05.04.01 | SN 32-00433 | O | | | 3A |
| AE20464/-768/-824 | | Rep. to Anti-Skid Control Unit w. Dist.Control Card PCB Assy | DUNLOP | NL | 17.11.05 | | SN 32-00748 | O | | | 3P |
| GENERAL | | Different Formats for Dunlop Stores | DUNLOP | NL | 02.09.99 | | SN GENERAL 32-00206 | O | | | 3A |
| | | ATA Spec 2000 Compliance for Part Numbers | DUNLOP (DABS) | SL | 19.03.99 | 1 05.07.09 | GS-SL-50 | O | | | 3A |
| VARIOUS | | Contamination of Carbon Heat Pack through Aircraft Washing, Aircraft De-Icing and Runway De-Icing | DUNLOP (DABS) | SIL | 30.07.09 | | SIL 32-00807 | O | | | 3A |
| P0723E105P | 25-60-12 | Optional Repair of Leaking Manifolds | EAM | SB | 07.02.94 | | SBV-25-1 | O | | | 3A |
| P0723E105P | 25-60-12 | Repl.of CO2 Inflator - Mandatory | EAM | SB | 01.10.96 | | SBV-25-2 | O | | | 3A |
| | | Discontinuation of Life Preserver Models | EAM | SIL | 07.08.15 | | SIL 25-127 | O | | | 3A |
| | | New ACR L8-4 Light Assembly | EAM | SIL | 25.02.93 | | SIL-25-103 | O | | | 3A |
| 230GC02Y03 | | DC Junction Box with APU | ECE | SB | 30.04.02 | | 230GC02Y-24-002 | O | | ZODIAC | 3A |
| 230GC02Y02 | | DC Junction Box with APU | ECE | SB | 12.05.12 | | 230GC02Y-24-003 | O | | ZODIAC | 3A |
| 8-700-/03/-04 | 31-41-09 | Proximity Sensor Electr. Unit | ELDEC | SB | 30.09.97 | 1 11.12.97 | SB8-700-31-02 | O | | Now is CRANE | 3P |
| 8-700-04/-05 | 31-41-09 | Indicating/Recording Systems - Proximity Sensor Electronic Unit 8-700-04/-05 | ELDEC | SB | 27.07.00 | 2 09.08.17 | SB8-700-31-03 | O | | Now is CRANE | 3P |
| 8-700-03/-04/-05 | 31-42-02 | Industrie Standard Specification for repairs on Printed Circuit Board | ELDEC | SIL | 17.04.12 | | SL8-700-03-01 | O | | Now is CRANE | 3A |
| 9-127/-217/-231/-802 | 73-35-31 | Fuel flow Transmitter | ELDEC | SL | 26.05.21 | | SL9-127-73-08 | O | | Now is CRANE | 3P |
| 9-231-29 | 73-35-31 | Fuel Flow Transmitter | ELDEC | SL | 28.08.97 | | SLTR9-231-73-02 | O | | Now is CRANE | 3P |
| 9-231-29 | 73-35-31 | Fuel Flow Transmitter | ELDEC | SI | 08.07.98 | | SLTR9-231-73-03 | O | | Now is CRANE | 3P |
| DU-8X5 | | On-Wing procedure for verification of F-1 Monitoring function | ESTERLINE | SB | 12.12.16 | 3 31.05.17 | SBAv-0058-03 | O | | | 3A |
| | | Cabin Portable Fire Extinguisher - Lavatory Waste Bin Fire Extinguisher | FIRE FIGHTING ENTERP | ASB | 01.01.10 | | ASB 26-115 | O | | PERCIVAL | 3A |
| | | Cabin Portable Fire Extinguisher - Lavatory Waste Bin Fire Extinguisher | FIRE FIGHTING ENTERP | ASB | 01.09.10 | | ASB 26-116 | O | | PERCIVAL | 3A |
| BA23177-1 | | Fire Extinguisher | FIRE FIGHTING ENTERP | SB | 01.11.97 | 1 01.01.98 | SB 26-110 | O | | PERCIVAL | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Cabin Portable Fire Extinguishers | FIRE FIGHTING ENTERP | SIL | 01.11.13 | | SIL 26-125 | O | | PERCIVAL | 3A |
| PAL10592/PAL10608 | | 1.5Kg Portable Fire Extinguishers | FIRE FIGHTING ENTERP | SIL | 09.05.16 | | SIL 26-128 | O | | PERCIVAL | 3A |
| | | Sale of Fuel management Business from GE Aviation to Ontic | GE AVIATION | SIL | 01.12.11 | 3 01.04.14 | GEN-37 | O | | | 3A |
| | | Update on the sale of certain legacy products by GE Aviation | GE AVIATION | SIL | 01.02.18 | | GEN-56 | O | | | 3A |
| | | Fumigation of Aircraft Tires | GOOD YEAR | SB | 16.03.01 | | GY SB 2001-32-002 | O | | | 3A |
| | 24-10-00 | Alternative to Mobil Mobilgrind 14 and Mobil Mobilmet 422 | HAMILTON SUND | AI | 21.01.16 | | D5174-AI70478 | S | | | 3A |
| | 24-10-00 | Surge Testing Electrical Windings | HAMILTON SUND | AI | 01.09.15 | | D5243-AI16891 | S | | | 3A |
| | 24-10-00 | Cold Spray | HAMILTON SUND | AI | 26.09.15 | | D5269-AI57401 | S | | | 3A |
| | 24-10-00 | SPM Marking Methods | HAMILTON SUND | AI | 20.10.15 | | D5288-AI43446 | S | | | 3A |
| 811180-X-XXX | 73-21-71 | Acceptance Criteria Correction | HAMILTON SUND | AI | 04.04.16 | | D6095-AI88106 | S | | | 3A |
| | 24-10-00 | O-ring Installation | HAMILTON SUND | AI | 14.05.19 | | D9128-AI06912 | S | | | 3A |
| 811180-5-004 | 73-21-71 | EFC-EEC118-15 Analog Board Replacement | HAMILTON SUND | SB | 20.06.14 | 1 22.04.15 | EEC118-15-73-11 | O | | IPC P&WC | 3P |
| 811180-X-XXX | 73-21-71 | ENGINE FUEL AND CONTROL - EEC118-15 ELECTRONIC ENGINE CONTROL - REPLACE OBSOLETE U9 MICROCIRCUIT | HAMILTON SUND | SB | 11.03.16 | | EEC118-15-73-14 | S | | IPC P&WC | 3P |
| 811099-1/-3 | 73-21-74 | EFC-Altern.Parts for preform.Packings | HAMILTON SUND | SB | 15.02.99 | | SB ECA-73-1 | O | | IPC P&WC | 3P |
| 811180-3-XXX | 73-21-71 | EFC-EEC118-15 Inc.of DR05 Software Config. | HAMILTON SUND | SB | 30.07.94 | | SB EEC118-15-73-1 | O | | IPC P&WC | 3P |
| 81180-6-004 | 73-21-71 | EEC118-15 Microcircuit U209 Replacement | HAMILTON SUND | SB | 11.06.14 | 1 22.04.15 | SB EEC118-15-73-13 | O | | | 3P |
| 811180-3-YYY | 73-21-71 | EFC-EEC118-15 Ident.Plate location Change | HAMILTON SUND | SB | 30.07.94 | | SB EEC118-15-73-2 | O | | IPC P&WC | 3P |
| 811180-3-YYY | 73-21-71 | EFC-EEC118-15 Power Interrupt Transist.Switch | HAMILTON SUND | SB | 15.03.95 | 1 15.05.95 | SB EEC118-15-73-3 | O | | IPC P&WC | 3P |
| 811180-X-YYY | 73-21-71 | EFC-EEC118-15 Flextape Change | HAMILTON SUND | SB | 10.02.96 | | SB EEC118-15-73-4 | O | | IPC P&WC | 3P |
| 811180-4-YYY | 73-21-71 | EFC-EEC118-15 Inc.of new digit.to analog conv. | HAMILTON SUND | SB | 31.05.96 | | SB EEC118-15-73-5 | O | | IPC P&WC | 3P |
| 811180-X-YYY | 73-21-71 | EFC-EEC118-15 Inc.of Replacement Transistor | HAMILTON SUND | SB | 30.08.97 | | SB EEC118-15-73-6 | O | | IPC P&WC | 3P |
| 811180-3-002,-003 | 73-21-71 | Eng.Contr.-Repl.digital to analog Conv. | HAMILTON SUND | SB | 30.11.99 | | SB EEC118-15-73-7 | O | | IPC P&WC | 3P |
| 811180-X-YYY | 73-21-71 | EFC-EEC118-15 New Circuit Card Assys | HAMILTON SUND | SB | 15.12.02 | 1 15.07.03 | SB EEC118-15-73-8 | O | | IPC P&WC | 3P |
| 811180-X-YYY | 73-21-71 | Suspect Multiplexers with Lot Date Code 031 | HAMILTON SUND | SB | 06.11.01 | | SB EEC118-15-73-9 | O | | IPC P&WC | 3P |
| 822823 | 73-22-10 | Electronic Engine Control EEC400-2 Incorporation of new production software | HAMILTON SUND | SB | 23.11.04 | 1 11.05.11 | SB EEC400-2-73-21 | O | | IPC P&WC | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 822410-4/-5 | 73-22-10 | Electronic Engine Control EEC400-2 New Interconnect Circuit Card Assembly | HAMILTON SUND | SB | 28.02.01 | | SB EEC400-2-73-6 | O | | IPC P&WC | 3A |
| 811099-1/-3 | 73-21-74 | EFC-Incorp.add.size Press.Valve Pistons | HAMILTON SUND | SB | 15.03.97 | 1 15.09.98 | SB JFC118-15-73-01 | O | | IPC P&WC | 3P |
| 811099-1/-3 | 73-21-74 | EFC-Incorp.of Repl.Torque Motor Filters | HAMILTON SUND | SB | 15.04.97 | 1 15.10.97 | SB JFC118-15-73-02 | O | | IPC P&WC | 3P |
| 811099-1/-3 | 73-21-74 | EFC-Incorp.of new Power Level Potentiom. | HAMILTON SUND | SB | 04.04.97 | 1 27.03.08 | SB JFC118-15-73-3 | O | | IPC P&WC | 3P |
| 811099-4 | 73-21-74 | EFC-Incorp.of new PC Set Screws | HAMILTON SUND | SB | 31.01.99 | | SB JFC118-15-73-4 | O | | IPC P&WC | 3P |
| 811099-1/-3 | 73-21-74 | EFC-Incorp.of Torque Motor Screen Test | HAMILTON SUND | SB | 15.10.99 | | SB JFC118-15-73-5 | O | | IPC P&WC | 3P |
| 811099-1/-3 | 73-21-74 | EFC-Incorp.of new Fluorocarbon Packings | HAMILTON SUND | SB | 05.06.01 | 1 03.12.01 | SB JFC118-15-73-6 | O | | IPC P&WC | 3P |
| | 24-10-00 | Surge Testing of Generator Wound Assemblies | HAMILTON SUND | SIL | 02.09.15 | | SIL 650 | O | | | 3P |
| 7863X/811099X | | Packing Replacement Recomendation for JFC118 Series Fuel Controls | HAMILTON SUND | SIL | 01.07.00 | | SIL JFC118-003A | O | | IPC P&WC | 3P |
| | | New Power Systems Onl.Doc.Web Site | HAMILTON SUND | SIL | 31.01.00 | | SIL PS-WEB-001 | O | | IPC P&WC | 3P |
| 811180-X-YYY | 73-21-71 | EEC118-15 Update | HAMILTON SUND | SIL | 27.11.96 | | SIR EEC118-15 | O | | IPC P&WC | 3P |
| 811180-5-004 | | Electronic Engine Control Update | HAMILTON SUND | SIL | 27.11.96 | | SIR EEC118-15:001 | O | | IPC P&WC | 3P |
| 811180-3-002,-003 | 73-21-71 | Transition of PWC Engine Control Product | HAMILTON SUND | SIL | 19.04.96 | | SIR GENERAL:004 | O | | IPC P&WC | 3P |
| | | Transition of PWC Engine Control Product to Long Beach | HAMILTON SUND | SIL | 19.04.96 | | SIR General-004 | O | | IPC P&WC | 3P |
| 811099-1/-3 | 73-21-74 | Incorporation of New Replaceable Torque Motor Screens | HAMILTON SUND | SIL | 12.12.97 | | SIR JFC118-002 | O | | IPC P&WC | 3P |
| 811099-1/-3 | 73-21-74 | Packing Replacement Recommendations for JFC118 Series Fuel Controls | HAMILTON SUND | SIL | 01.05.00 | | SIR JFC118-003 | O | | IPC P&WC | 3P |
| 33531C | | Propeller Governors, Pumps, and Overspeed Governors - service limits | HARTZELL | SB | 01.12.97 | | 33531C | O | | WOODWARD | 3P |
| TBO S/B-33580-M | | Time Between Overhaul Periods (TBO) | HARTZELL | SB | 01.01.82 | 12 28.02.07 | 33580M | O | | WOODWARD | 3P |
| HD-E6C-3() | | Replacement of propeller blade | HARTZELL | AD | 19.11.02 | | AD 2002-22-08 | O | | | 3P |
| HD-E6C-3() / D-5108-1 | | Reduction of hub certified service | HARTZELL | AD | 18.03.03 | | AD 2003-04-01 | O | | | 3P |
| HD-E6C-3() / D-1199-2 | | Repuirements for initial and repetitive inspections | HARTZELL | AD | 04.04.03 | | AD 2003-04-22 | O | | | 3P |
| HD-E6C-3() / D-5108-1 | | Cracks in the propeller hub. | HARTZELL | AD | 24.11.99 | | AD 99-25-05 | O | | | 3P |
| | 61-00-66 | Trinity Specialized Services/Mid America Propeller | HARTZELL | ASB | 08.03.23 | | HC-ASB-61-402 | O | | | 3P |
| | | Abnormal Vibration or Grease Leakage | HARTZELL | SL | 07.12.95 | | HC-SL-61-165 | O | | | 3P |
| | | New Fee for Parts Evaluation | HARTZELL | SL | 15.05.96 | 1 15.03.00 | HC-SL-61-172 | O | | | 3P |
| | | Introduction of Overhaul Kits | HARTZELL | SL | 10.04.01 | 2 11.11.15 | HC-SL-61-212 | O | | | 3P |
| | | Use of Porpeller Jack | HARTZELL | SL | 01.04.04 | | HC-SL-61-231 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Governor - Installation of Hartzell Propeller Inc. Governors | HARTZELL | SL | 05.11.08 | 6 16.09.20 | HC-SL-61-277 | O | | | 3P |
| | | Product Category - Lubrication Procedure | HARTZELL | SL | 01.04.14 | | HC-SL-61-343 | O | | | 3P |
| | | Propeller - NYCO GN3058 Grease | HARTZELL | SL | 06.01.20 | | HC-SL-61-366 | O | | | 3P |
| | | Propeller - Overhaul Periods and Service Life Limits for Hartzell Propeller Inc. Aviation Components - Propellers, Governors, Accumulators, and Propeller Damper Assemblies | HARTZELL | SL | 09.05.69 | 14 07.07.21 | HC-SL-61-61Y | O | | | 3P |
| | 61-00-66 | Propeller - Hub Inspection | HARTZELL | ASB | 26.02.99 | 2 19.05.14 | HD-ASB-61-021 | O | | | 3P |
| | 61-00-66 | Inspection of Propeller Hub | HARTZELL | ASB | 16.06.00 | 1 23.05.01 | HD-ASB-61-023 | O | | | 3P |
| | 61-00-66 | Propeller - Thrust Bearing Race Replacement | HARTZELL | ASB | 06.08.01 | 1 30.01.20 | HD-ASB-61-026 | O | | conj. HD-SL-61-014 | 3P |
| | 61-00-66 | Governor - High Pressure Pump Replacement | HARTZELL | ASB | 16.03.22 | | HD-ASB-61-031 | O | | | 3P |
| | | Dual Acting Propellers Service Bulletion Index | HARTZELL | SB | 16.09.22 | | HD-SB_INDEX | O | | IPC P&WC | 3P |
| | 61-00-66 | Impr. Fork, Cam Follower, Bushing Assy | HARTZELL | SB | 26.05.95 | 6 04.10.99 | HD-SB-61-005 | O | | | 3P |
| | 61-00-66 | Incorp. of SB Reference Decal | HARTZELL | SB | 15.06.95 | | HD-SB-61-008 | O | | | 3P |
| | 61-00-66 | Drive Gear Components | HARTZELL | SB | 17.05.96 | 1 22.07.96 | HD-SB-61-012 | O | | | 3P |
| | 61-00-66 | Blade - Thrust Bearing Race | HARTZELL | SB | 21.12.98 | 8 30.01.20 | HD-SB-61-014 | O | | | 3P |
| | 61-00-66 | Addition of View Port | HARTZELL | SB | 19.05.97 | | HD-SB-61-017 | O | | | 3P |
| | 61-00-66 | PCU - Repl. of NAS1352-() Fasteners | HARTZELL | SB | 06.10.00 | | HD-SB-61-024 | O | | | 3P |
| | 61-00-66 | PCU - Major Periodic Inspection | HARTZELL | SB | 17.11.00 | 1 20.12.00 | HD-SB-61-025 | O | | | 3P |
| | 61-00-66 | Coin-Tap Inspection of Blade Shank | HARTZELL | SB | 18.09.01 | | HD-SB-61-027 | O | | | 3P |
| | 61-00-66 | Propeller - Insp.After Long Term Storage | HARTZELL | SB | 01.09.06 | | HD-SB-61-028 | O | | | 3P |
| | 61-01-02 | Propeller - Hub Modification Instructions | HARTZELL | SB | 19.05.14 | 2 16.09.22 | HD-SB-61-029 | O | | | 3P |
| | 61-00-66 | Blade Retention System-Parts Replacement/Product Improvement | HARTZELL | SB | 18.07.18 | | HD-SB-61-030 | O | | | 3P |
| | 61-00-66 | PCU - Impr. Drive Gear Components | HARTZELL | ASB | 19.05.97 | | HD-SB-61-A018 | O | | | 3P |
| | | Active Service Letter Index | HARTZELL | SIL | 18.07.18 | | HD-SL_INDEX-C | O | | | 3P |
| | 61-00-66 | Propeller - Tracking of Components | HARTZELL | SIL | 22.03.95 | 2 16.08.12 | HD-SL-61-001 | O | | | 3P |
| | 61-00-66 | Balance Weight Inserts | HARTZELL | SL | 06.02.96 | | HD-SL-61-011 | O | | OBSOLETED | 3P |
| | 61-00-66 | Protective Erosion Mask | HARTZELL | SL | 04.03.96 | | HD-SL-61-012 | O | | OBSOLETED | 3P |
| | 61-00-66 | Synchronphaser Computer | HARTZELL | SL | 12.06.96 | | HD-SL-61-017 | O | | | 3P |
| | 61-00-66 | Spiner Assy - Repair of Bulkhead Nutplates | HARTZELL | SL | 03.07.96 | | HD-SL-61-018 | O | | OBSOLETED | 3P |
| | 61-00-66 | Grease Leakage | HARTZELL | SL | 04.11.96 | | HD-SL-61-023 | O | | | 3P |
| | 61-00-66 | Speed Reset Solenoid | HARTZELL | SL | 17.07.97 | | HD-SL-61-026 | O | | | 3P |
| | 61-00-66 | Hydraulic Unit - Piston Rework | HARTZELL | SL | 27.01.98 | 1 09.02.98 | HD-SL-61-028 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | 61-00-66 | Propeller - Spare Parts Release | HARTZELL | SL | 10.02.98 | | HD-SL-61-029 | O | | OBSOLETED | 3P |
| | 61-00-66 | Propeller - Serial Number Marking | HARTZELL | SL | 18.03.99 | 1 02.11.07 | HD-SL-61-030 | O | | | 3P |
| | 61-00-66 | Propeller - Spare Parts Release | HARTZELL | SL | 16.03.99 | | HD-SL-61-031 | O | | | 3P |
| | 61-00-66 | Propeller Vibration | HARTZELL | SL | 17.12.99 | 1 07.05.01 | HD-SL-61-032 | O | | | 3P |
| | 61-00-66 | Spare Parts Rel. - Blade Preload | HARTZELL | SL | 16.02.00 | 1 07.05.01 | HD-SL-61-033 | O | | OBSOLETED | 3P |
| | 61-00-66 | Installation of Protective Erosion Tape | HARTZELL | SL | 16.08.01 | | HD-SL-61-035 | O | | OBSOLETED | 3P |
| | 61-00-66 | Blade Preload | HARTZELL | SL | 15.08.01 | | HD-SL-61-036 | O | | OBSOLETED | 3P |
| | 61-00-66 | Spare Parts Release/Product Impr. | HARTZELL | SL | 19.10.01 | | HD-SL-61-038 | O | | OBSOLETED | 3P |
| | 61-00-66 | Thrust Bearing Race Replacement | HARTZELL | SL | 15.04.02 | | HD-SL-61-039 | O | | OBSOLETED | 3P |
| | 61-00-66 | Propeller - Inspection of Pitch Change Rod | HARTZELL | SL | 08.05.03 | | HD-SL-61-040 | O | | | 3P |
| | 61-00-66 | Propellers - Propeller Labels | HARTZELL | SL | 13.08.04 | 1 04.12.08 | HD-SL-61-041 | O | | | 3P |
| | 61-00-66 | Propeller - New 105030 Wear Strip and Installation Instructions | HARTZELL | SL | 17.08.11 | 3 10.12.12 | HD-SL-61-042 | O | | | 3P |
| | 61-00-66 | Propeller Control Unit - Safety Wire | HARTZELL | SL | 20.04.12 | | HD-SL-61-043 | O | | | 3P |
| | 61-00-66 | Propeller - Spare Parts Release/Product Improvement | HARTZELL | SL | 16.03.17 | | HD-SL-61-044 | O | | | 3P |
| | 61-00-66 | Propeller - Clamp Wrench TE141 | HARTZELL | SL | 09.08.17 | | HD-SL-61-045 | O | | | 3P |
| | | Summary of FAA Airworthiness Directives-Dual Acting | HARTZELL | SIL | 19.05.14 | | VDN-0485 | O | | | 3P |
| 2LA004626-05 | 33-11-09 | Flight Crew Reading Light | HELLA | SB | 30.06.00 | | SB 2LA004626-05-33-001 | O | | GOODRICH HELLA | 3A |
| | 33-31-13 | Cargo Compartment Light - Exchange of Units | HELLA | SB | 20.08.02 | | SB 2LA006823-70-33-001 | O | | GOODRICH HELLA | 3A |
| 2LA005163-30 | 33-11-22 | Flight Crew Reading Light - New Support Housing Assy | HELLA | SIL | 07.07.08 | | SIL 2LA005163-33-006 | O | | GOODRICH HELLA | 3A |
| 2LA005171-55/-60 | 33-22-08 | Internal Lightning - Reading Light Lenses | HELLA | SIL | 03.03.93 | 1 08.08.96 | SIL 2LA005171-33-001 | O | | GOODRICH HELLA | 3A |
| 7510100-VAR | | RNZ-850/851 Modification H | HONEYWELL | SB | 01.05.90 | | 21-1989-134 | O | | | 3A |
| 7510100-VAR | | RNZ-850/851 Modification J | HONEYWELL | SB | 01.05.90 | | 21-1989-135 | O | | | 3A |
| 7510100-VAR | | RNZ-850/851 Modification K | HONEYWELL | SB | 01.05.90 | | 21-1989-136 | O | | | 3A |
| 75101100-8XX | | RNZ-850/851 Modification L | HONEYWELL | SB | 01.06.90 | | 21-1989-190 | O | | | 3A |
| 7510100-VAR | | RNZ-850/851 Navigation Unit (MOD D) | HONEYWELL | SB | 22.08.89 | | 21-1989-49 | O | | | 3A |
| 7510100-VAR | | RNZ-850/851 MOD F | HONEYWELL | SB | 22.08.89 | | 21-1989-51 | O | | | 3A |
| 7510100-VAR | | RNZ-850/851 Modification G | HONEYWELL | SB | 25.09.89 | | 21-1989-96 | O | | | 3A |
| 7007549-906 | | CD-810 Modification R | HONEYWELL | SB | 03.04.91 | 1 11.11.91 | 21-1990-197 | O | | | 3A |
| 7510100-VAR | | RNZ-850/851 Modification N | HONEYWELL | SB | 20.06.90 | | 21-1990-28 | O | | | 3A |
| 7008470-XXX | | React.Override on Primus 450/650/870 | HONEYWELL | NL | 02.09.92 | 1 02.10.92 | 23-1990-06 | O | | | 3P |
| | | Gyro Handling | HONEYWELL | NL | 12.03.70 | 2 11.03.94 | 23-3000-01 | O | | | 3P |
| | | RM-855 Radio Management Unit Modification LED Backlight Assembly Replacement for Fluorescent | HONEYWELL | SB | 25.07.13 | | 7013270-23-0002 | O | | | 3A |
| 4006719-XXX | | SM-200 Conv. of Servo Drive | HONEYWELL | SB | 07.04.06 | 2 07.11.06 | A21-1146-010 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 7008470-VAR | | WU-450/650 Modif. to Impr.Quality a. Reliability | HONEYWELL | SB | 25.02.91 | 1 01.08.93 | A21-1990-102 | O | | | 3P |
| 7510100-8XX/-9XX | | RNZ-850/851 Modification S | HONEYWELL | SB | 14.06.91 | | A21-1990-200 | O | | | 3A |
| 7510100-VAR | | RNZ-850/851 Modification T | HONEYWELL | SB | 12.11.91 | | A21-1991-063 | O | | | 3A |
| 7007549-906 | | CD-810 Modification T | HONEYWELL | SB | 10.09.91 | | A21-1991-117 | O | | | 3A |
| 7001840-VAR | | WU-450/650 Modification Z | HONEYWELL | SB | 01.02.92 | 1 20.07.94 | A21-1991-131 | O | | | 3A |
| 7001840-VAR | | RT-300 Modification U | HONEYWELL | SB | 07.12.91 | 1 15.10.93 | A21-1991-180 | O | | | 3A |
| 7008470-VAR | | WU-450/650 Modif. to Better Reliability | HONEYWELL | SB | 15.05.92 | 1 01.07.94 | A21-1992-046 | O | | | 3P |
| 7510100-8XX | | RNZ-850/851 Modif. to Change VOR/ILS Softw. | HONEYWELL | SB | 16.11.92 | | A21-1992-070 | O | | | 3A |
| 7510774-901 | | XS-850 Change of Part-Number | HONEYWELL | SB | 20.11.92 | 1 01.12.93 | A21-1992-076 | O | | | 3P |
| 7510100-VAR | | RNZ-850/851 MOD F DME Interrog.Module | HONEYWELL | SB | 20.11.92 | | A21-1992-085 | O | | | 3A |
| 7001840-ALL | | RT-300 MOD V | HONEYWELL | SB | 15.12.92 | 2 13.11.08 | A21-1992-113 | O | | | 3A |
| 7510700-VAR | | RCZ-851 MOD E COM Cluster Module | HONEYWELL | SB | 20.01.93 | | A21-1992-117 | O | | | 3A |
| 7510700-802 | | RCZ-851 Change of Integr.Comm.Unit | HONEYWELL | SB | 05.02.93 | | A21-1992-129 | O | | | 3P |
| 7510700-802 | | RCZ-851 Change of Integr.Comm.Unit | HONEYWELL | SB | 05.02.93 | | A21-1992-130 | O | | | 3P |
| 7510700-802 | | RCZ-851 Change of Integr.Comm.Unit | HONEYWELL | SB | 05.02.93 | | A21-1992-131 | O | | | 3P |
| 7511001-912 | 23-81-08 | AV-850A Warning / CVR Audio Level | HONEYWELL | SB | 15.06.93 | 3 02.07.96 | A21-1992-136 | O | | | 3A |
| 7008470-ALL | | PRIMUS 450/650 Antenna (MOD AC) | HONEYWELL | SB | 28.09.93 | 1 15.08.94 | A21-1992-164 | O | | | 3P |
| 7008470-VAR | | PRIMUS 450/650 Antenna (MOD AD) | HONEYWELL | SB | 04.09.93 | 1 12.08.94 | A21-1992-165 | O | | | 3P |
| 7008470-VAR | | PRIMUS 450/650 Antenna (MOD AB) | HONEYWELL | SB | 01.08.93 | 1 10.08.94 | A21-1992-176 | O | | | 3P |
| 7008470-VAR | | PRIMUS 450/650 Antenna (RTA) | HONEYWELL | SB | 01.02.93 | 4 14.12.95 | A21-1993-009 | O | | | 3P |
| 7008470-VAR | | WU-450/650 Receiv / Transm. Antenna | HONEYWELL | SB | 11.10.93 | 1 01.02.95 | A21-1993-071 | O | | | 3P |
| 7013270-931 and -932 | | Silver Label Conversion from Red Label MOD H to Silver Label MOD A | HONEYWELL | SB | 23.07.93 | | A21-1993-080 | O | | | 3A |
| 7015327-901 | | GP-300 Change of Red Label to Silver Label | HONEYWELL | SB | 13.10.93 | | A21-1993-096 | O | | | 3A |
| 7014300-902 | | DU-870 Modif.to Repl. Non-MOD A CRT's | HONEYWELL | SB | 29.03.96 | | A21-1993-098 | O | | | 3A |
| 7511001-912 | 23-81-08 | AV-850A MOD E | HONEYWELL | SB | 30.10.93 | | A21-1993-099 | O | | | 3A |
| 7014300-902 | | DU-870 Conversion from Red to Silver Label | HONEYWELL | SB | 29.03.96 | 1 05.08.14 | A21-1993-101 | O | | | 3A |
| 7511001-912 | 23-81-08 | AV-850A Modif.to Repl.Digit.Signal Processor | HONEYWELL | SB | 30.10.93 | | A21-1993-104 | O | | | 3A |
| 7014700-9XX | | AZ-840 Conv.of DORNIER 328 Labels | HONEYWELL | SB | 15.09.93 | | A21-1993-110 | O | | | 3A |
| | | IM-803 Installation Module | HONEYWELL | SB | 14.10.94 | 1 14.10.94 | A21-1993-119 | O | | | 3P |
| 7014300-902 | | DU-870 Modif.to Better Performance | HONEYWELL | SB | 29.03.96 | | A21-1993-125 | O | | | 3A |
| 7510764-901 | | TR850 VHF Comm. Trans. Module | HONEYWELL | SB | 09.11.93 | | A21-1993-149 | O | | | 3P |
| 7510700-80X | | RCZ-851 MOD AB | HONEYWELL | SB | 09.11.93 | | A21-1993-150 | O | | | 3P |
| 7016600-902 | | DL-900 Hardware Modif. (RS-422 Interf. Perf.) | HONEYWELL | SB | 11.02.94 | | A21-1994-020 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 7017300-11000,-1/14000,-1 | 22-11-95 | MOD B; Modification to increase FGC FLASH memory and to update flight software to Dornier 328 Spec 3 | HONEYWELL | SB | 11.10.94 | | A21-1994-034 | O | | 7017300-22-2 | 3P |
| 7510700-VAR | | COMMUNICATIONS RCZ-851-Convert Integrated Comm. Unit | HONEYWELL | SB | 05.04.94 | 11 07.11.18 | A21-1994-040 | O | | | 3A |
| 7511001-912 | 23-81-08 | AV-850A Modif.to Repl.Digital a. Analog CCA's | HONEYWELL | SB | 15.09.95 | 3 04.01.01 | A21-1994-075 | O | | | 3A |
| 7016600-902 | | DL-900 Data Loader MOD B | HONEYWELL | SB | 20.05.94 | | A21-1994-090 | O | | | 3A |
| 7013270-932 | | RM-855 Software-/Harware-Update | HONEYWELL | SB | 02.09.94 | | A21-1994-094 | O | | | 3P |
| 7008470-VAR | | WU-450/650 Modif.to Modification AF | HONEYWELL | SB | 11.07.94 | | A21-1994-099 | O | | | 3P |
| 7014300-902 | | DU-870 Better Performance (MOD C) | HONEYWELL | SB | 29.03.96 | | A21-1994-119 | O | | | 3A |
| 7013348-903/-913 | | DA-800 Data Acquisition Unit | HONEYWELL | SB | 23.09.94 | | A21-1994-121 | O | | | 3P |
| 7014700-911 | | AZ-840 Micro Air Data Computer | HONEYWELL | SB | 13.09.94 | | A21-1994-123 | O | | | 3P |
| 7014300-902 | | DU-870 MOD D | HONEYWELL | SB | 07.04.96 | | A21-1994-127 | O | | | 3A |
| 7510100-VAR | | SRZ-850/851 - Conversion of any NAV Unit | HONEYWELL | SB | 26.08.94 | 3 13.09.05 | A21-1994-129 | O | | | 3A |
| 7510134-VAR | | SRZ-850/851 - Conversion of NAV Receiver | HONEYWELL | SB | 10.03.95 | 2 08.09.05 | A21-1994-131 | O | | | 3A |
| 7008470-822/-922 | | WU-450/650 MOD AG | HONEYWELL | SB | 05.09.95 | | A21-1994-160 | O | | | 3P |
| 7017300-11003 | | IC-800 Integr. Avionics Computer | HONEYWELL | SB | 09.01.95 | | A21-1995-005 | O | | | 3P |
| 7013348-903/-913 | | DA-800 Data Acquisition Unit Modification B | HONEYWELL | SB | 11.04.95 | | A21-1995-013 | O | | | 3A |
| 7511001-912 | 23-81-08 | Modif.to Audio Lockup Problems | HONEYWELL | SB | 26.09.95 | 1 31.10.95 | A21-1995-028 | O | | | 3A |
| 7513000-802 | | CD-850 Modif.to Repl. The Interconnect PCB | HONEYWELL | SB | 02.10.95 | | A21-1995-029 | O | | | 3P |
| 7014300-902 | | DU-870 Modif.to Repl.Hold-Down Assembly | HONEYWELL | SB | 28.03.96 | | A21-1995-074 | O | | | 3A |
| 751101-912 | | AV-850A Modif.to Update Software (MOD G) | HONEYWELL | SB | 31.10.95 | 1 01.03.96 | A21-1995-076 | O | | | 3A |
| 7008470-822/-922 | | WU-650 Modif.to Improve Quality a.Reliability | HONEYWELL | SB | 22.08.95 | 1 14.12.96 | A21-1995-087 | O | | | 3P |
| 7013270-932 | | Rotary Switch Mounting Upgrade | HONEYWELL | SB | 20.06.95 | | A21-1995-15 | O | | | 3A |
| 7015327-901 | | GP-300 Guidance and Display Contr. | HONEYWELL | SB | 04.03.96 | | A21-1996-011 | O | | | 3A |
| 7014300-902 | | Modification to Change Dimming Characteristics (MOD F) | HONEYWELL | SB | 20.05.96 | | A21-1996-032 | O | | | 3A |
| 7017300-11003 | | P-2000 Software Upgrade | HONEYWELL | SB | 19.06.96 | 1 11.07.96 | A21-1996-036 | O | | | 3P |
| 7015327-901 | | GP-300 Change MOD A to MOD B | HONEYWELL | SB | 29.07.96 | 1 24.09.96 | A21-1996-055 | O | | | 3A |
| 7013270-932/-934 | | RM-855 Radio Management Unit | HONEYWELL | SB | 17.12.96 | | A21-1996-108 | O | | | 3P |
| 7511001-912 | 23-81-08 | AV-850A Digtal Audio Panel | HONEYWELL | SB | 19.12.96 | 1 23.01.97 | A21-1996-118 | O | | | 3A |
| 7016600-902 | | DL-900 MOD C Software Upgrade | HONEYWELL | SB | 08.01.97 | | A21-1996-121 | O | | | 3A |
| 7017300-XXXXX | | AUTOFLIGHT-PRIMUS 2000 INTEGRATED AVIONICS SYSTEM IC-800 INTEGRATED AVIONICS COMPUTER | HONEYWELL | SB | 28.01.97 | | A21-1996-127 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 7015327-901 | | GP-300 Guidance and Display Controller | HONEYWELL | SB | 31.03.97 | | A21-1997-031 | O | | | 3A |
| 7511001-9xx | | SRZ-850/851 Integrated Radio System - MOD P - Modification to Simplify Mechanical Assembly | HONEYWELL | SB | 27.10.98 | 1 10.04.18 | A21-1997-049 | O | | | 3A |
| 7013270-XXX | | COMMUNICATIONS-PRIMUS II ® INTEGRATED RADIO SYSTEM | HONEYWELL | SB | 22.05.97 | | A21-1997-058 | O | | | 3A |
| 7510700-802 | | RCZ-850 Communic.Unit - MOD AG | HONEYWELL | SB | 26.11.97 | 1 19.05.00 | A21-1997-083 | O | | | 3P |
| 7014700-917 | | AZ-840 MICRO AIR DATA COMPUTER (MADC) | HONEYWELL | SB | 16.08.97 | | A21-1997-092 | O | | | 3A |
| 7013348-9XX | | PRIMUS 2000-DAU Conversion of P/N | HONEYWELL | SB | 12.12.97 | 2 01.06.02 | A21-1997-102 | O | | | 3P |
| 7017300-11XXX/-14XXX | | IC-800 Convert of Part-No's (MOD A) | HONEYWELL | SB | 11.05.99 | | A21-1997-103 | O | | | 3P |
| 7017300-11003/4/6 | | IC-800 Convert of Part-No's (MOD A) | HONEYWELL | SB | 07.03.98 | | A21-1997-104 | O | | | 3P |
| 7021450-401, -601, -801 | | NAVIGATION - WU-440/660/880 RECEIVER TRANSMITTER ANTENNA (RTA) - Modification (MOD) D | HONEYWELL | SB | 06.01.98 | 1 09.09.15 | A21-1997-118 | O | | | 3A |
| 7510100-XXX | | RNZ-85X/A Navigation Unit - MOD AG | HONEYWELL | SB | 24.11.97 | | A21-1997-131 | O | | | 3A |
| 7015327-901 | | GP-300 Guidance and Display Controller | HONEYWELL | SB | 19.12.97 | | A21-1997-146 | O | | | 3A |
| 7001840-922 | | RT-300 Conversion of Part-Number | HONEYWELL | SB | 08.01.98 | 1 08.09.99 | A21-1997-153 | O | | | 3P |
| 7017300-XXXXX | | AUTOFLIGHT-PRIMUS 2000 INTEGRATED AVIONICS SYSTEM IC-800 INTEGRATED AVIONICS COMPUTER | HONEYWELL | SB | 29.05.98 | | A21-1997-157 | O | | | 3A |
| 7014300-902 | | Modification to Upgrade A5 HVPS (MOD H) | HONEYWELL | SB | 13.05.98 | | A21-1998-019 | O | | | 3A |
| 7013270-XXX | | RM-855 Radio Management Unit | HONEYWELL | SB | 12.05.98 | | A21-1998-023 | O | | | 3A |
| 7014700-XXX | | AZ-840/850 MICRO AIR DATA COMPUTER | HONEYWELL | SB | 15.05.98 | | A21-1998-045 | O | | | 3A |
| 4005842-22-3 | 22-11-51 | Mod.to Replace Servo Bracket Cable Drum | HONEYWELL | SB | 29.06.98 | | A21-1998-046 | O | | | 3A |
| 7510700-802 | | Secure the Power Leads w. Lacing Tape | HONEYWELL | SB | 26.06.98 | | A21-1998-060 | O | | | 3P |
| 7017300-11XXX/-14XXX | 22-11-95 | MOD B; Installation of Software MOD B into IC-800 | HONEYWELL | SB | 01.11.99 | | A21-1998-070 | O | | 7017300-22-58 | 3P |
| 7001840-90X/-93X | | RT-300 Modif.to Repl. Downconv. CCA | HONEYWELL | SB | 07.08.98 | | A21-1998-079 | O | | | 3A |
| 7001840-922/-932 | | RT-300 Transmitter CCA if required | HONEYWELL | SB | 17.09.98 | | A21-1998-080 | O | | | 3A |
| 7017300-11XXX/-14XXX | 22-11-95 | MOD C; Software Modifiction to IC-800 | HONEYWELL | SB | 06.10.98 | | A21-1998-110 | O | | 7017300-22-39 | 3P |
| 7021450-401, -601, -801 | | NAVIGATION - RECEIVER TRANSMITTER ANTENNA (RTA) | HONEYWELL | SB | 01.09.98 | 1 09.09.15 | A21-1998-118 | O | | | 3A |
| 7013270-XXX | | NAVIGATION — PRIMUS II INTEGRATED RADIO SYSTEM — RM-855 | HONEYWELL | SB | 19.02.99 | | A21-1998-158 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 7001840-922/-932 | 34-42-10 | RT-300 Radio Altimeter Receiver-Transm. | HONEYWELL | SB | 12.05.99 | 12.05.99 | A21-1999-020 | O | | | 3A |
| 7014700-XXX | | AZ-840 MICRO AIR DATA COMPUTER | HONEYWELL | SB | 12.04.99 | 1 22.06.99 | A21-1999-043 | O | | | 3P |
| 7013348-922 | | DA-800 DATA ACQUISITION UNIT | HONEYWELL | SB | 21.06.99 | 2 30.03.00 | A21-1999-068 | O | | | 3P |
| 7017300-11120/-14120 | | IC-800 Conv.of Red Label to Silver Label | HONEYWELL | SB | 18.06.99 | | A21-1999-069 | O | | | 3P |
| 7017300-11003/4 /-14001 | | IC-800 Install.of Software MOD B | HONEYWELL | SB | 29.06.01 | | A21-1999-094 | O | | | 3P |
| 7017300-11006/-11010 | | IC-800 Modif.to Install Software MOD D | HONEYWELL | SB | 19.04.00 | | A21-1999-095 | O | | | 3P |
| 7511001-912 | 23-81-08 | AV-850A Conv.of any Dash Number | HONEYWELL | SB | 10.10.00 | 1 05.03.02 | A21-1999-107 | O | | | 3A |
| 7013270-932/-966 | | Mod.to Upgrade the Rotary Switch Assembly | HONEYWELL | SB | 03.12.99 | | A21-1999-114 | O | | | 3A |
| 7017300-XXXXX | | AUTOFLIGHT — PRIMUS 2000 INTEGRATED AVIONICS SYSTEM | HONEYWELL | SB | 16.09.99 | | A21-1999-119 | O | | | 3A |
| 4006719-XXX | | SM-200 Conv.Instr. for all Dash Numbers | HONEYWELL | SB | 10.09.99 | | A21-1999-134 | O | | | 3A |
| 7015327-901 | | GP-300 Guidance Panel Contr. | HONEYWELL | SB | 13.01.00 | | A21-1999-142 | O | | | 3A |
| 7017300-XXXXX | | AUTOFLIGHT — PRIMUS 2000 INTEGRATED AVIONICS SYSTEM | HONEYWELL | SB | 29.11.99 | | A21-1999-153 | O | | | 3A |
| 7510700-802 | | RCZ-851 Mod. to Inspect XS-852 Transponder | HONEYWELL | SB | 01.03.00 | | A21-1999-158 | O | | | 3P |
| 7017300-11XXX/-14XXX | | IC-800 Integr. Avionics Computer | HONEYWELL | SB | 30.05.00 | 1 21.07.00 | A21-2000-013 | O | | | 3A |
| 7014700-XXX | | AZ-840 MICRO AIR DATA COMPUTER | HONEYWELL | SB | 03.05.00 | | A21-2000-017 | O | | | 3A |
| 7017300-XXX | | IC-800 Integr. Avionics Computer, MOD F | HONEYWELL | SB | 18.04.00 | 1 05.01.01 | A21-2000-022 | O | | | 3A |
| 7010300-11XX | 22-11-95 | IC-800(x) Integr. Avionics Computer | HONEYWELL | SB | 07.09.00 | 1 05.01.01 | A21-2000-035 | O | | | 3A |
| 7013270-932/-966 | | RM-855 Radio Management Unit - MOD K - Secure Connectors to Reduce Probability of dispaly Outage | HONEYWELL | SB | 05.09.00 | 1 07.12.17 | A21-2000-039 | O | | | 3A |
| 7511001-912 | 23-81-08 | AV-850A Audio Control Unit | HONEYWELL | SB | 04.01.01 | | A21-2000-041 | O | | | 3A |
| 7013270-932/-966 | 34-51-24 | RM-855 Radio Management Unit - MOD L | HONEYWELL | SB | 06.12.00 | 1 21.11.17 | A21-2000-063 | O | | | 3A |
| 7016600-902 | 34-24-43 | Modif. to Eliminate Requirement | HONEYWELL | SB | 07.06.01 | | A21-2000-077 | O | | | 3A |
| 4006719-XXX | | Hardware Modification (MOD) H to SM-200 Servo Drive | HONEYWELL | SB | 27.03.02 | 1 16.03.11 | A21-2001-033 | O | | | 3A |
| 7015327-901/-905 | | GP-300 Guid.Panel Contr.-P/N-Conversion | HONEYWELL | ASB | 02.04.02 | | A21-2001-040 | O | | A L E R T | 3A |
| 7511001-912 | 23-81-08 | Impr.Unit Reliability by Repl.Switch Assy | HONEYWELL | SB | 20.03.02 | | A21-2001-054 | O | | | 3A |
| 7014300-901/-902 | | PRIMUS 2000, Install.High Voltage Power Supply with Increased High Temperature Tolerance | HONEYWELL | SB | 01.11.02 | | A21-2249-018 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 7014300-901/-902 | | PRIMUS 2000, Install.New High Voltage Power Supply (HVPS) | HONEYWELL | SB | 01.11.02 | | A21-2249-020 | O | | | 3A |
| 7014300-901/-902 | | PRIMUS 2000, Replace Existing Solid Tantalum Capacitors with a More Reliable Part | HONEYWELL | SB | 23.04.03 | 1 27.01.11 | A21-2249-021 | O | | | 3A |
| 7014300-902 | | Change Fan Speed Detect.Circ.to Prev.Fan Fail Messages | HONEYWELL | SB | 06.11.06 | | A21-2249-027 | O | | | 3A |
| 7014300-901/-902 | | Mod. MOD S, Decrease Failures That Could Cause Smoke and/or an Odor | HONEYWELL | SB | 10.10.11 | | A21-2249-030 | O | | | 3A |
| 7013270-XXX | | RM-855 RADIO MANAGEMENT UNIT - MOD N RADIO MANAGEMENT UNIT | HONEYWELL | SB | 29.09.03 | 2 05.01.18 | A21-2254-001 | O | | | 3A |
| 7013270-XXX | | NAVIGATION — PRIMUS® 1000/2000 INTEGRATED AVIONICS SYSTEM RM-855 Radio Management Unit (RMU) | HONEYWELL | SB | 28.01.04 | 2 07.12.17 | A21-2254-049 | O | | | 3P |
| 7013270-XXX | | Rm-855 Radio Management Unit (RMU) - MOD S | HONEYWELL | SB | 25.05.06 | 1 07.12.17 | A21-2254-069 | O | | | 3A |
| 7013270-801-XXX | 34-51-24 | RM-855 Radio Management Unit - MOD R | HONEYWELL | SB | 05.03.07 | 2 08.12.17 | A21-2254-079 | O | | | 3A |
| 7013270-932/-966 | | RM-855 Radio Management Unit | HONEYWELL | SB | 12.08.09 | 1 14.02.12 | A21-2254-088 | O | | | 3A |
| 7013270-XXX | | COMMUNICATIONS - RM-855 RADIO MANAGEMENT UNIT - Modification (MOD) V to RM-855 Radio Management Unit (RMU) | HONEYWELL | SB | 23.01.09 | | A21-2254-093 | O | | | 3A |
| 7013270-XXX | | NAVIGATION - RM-855 RADIO MANAGEMENT UNIT | HONEYWELL | SB | 11.04.12 | | A21-2254-112 | O | | | 3A |
| 7013270-XXX | | COMMUNICATIONS - RM-855 RADIO MANAGEMENT UNI | HONEYWELL | SB | 25.07.13 | | A21-2254-113 | O | | | 3A |
| 7013270-XXX | 34-51-24 | RM-855 Radio Management Unit - MOD AC | HONEYWELL | SB | 19.12.19 | | A21-2254-148 | O | | | 3A |
| 7013270-XXX | | NAVIGATION - RM-855 RADIO MANAGEMENT UNIT | HONEYWELL | SB | 12.12.12 | | A21-2548-005 | O | | | 3A |
| 7510700-XXX | | NV-850-Elim.Erron.Glideslope Indic. On ILS Appr. | HONEYWELL | ASB | 28.02.03 | 1 04.03.03 | A21-3816-001 | O | | A L E R T | 3P |
| 7510134-XXX | | NV-850 NAV Receiver Module - MOD T | HONEYWELL | SB | 08.07.04 | | A21-3816-003 | O | | | 3A |
| 7510700-XXX | | RNZ-851-Elim.Erron.Glideslope Indic. On ILS Appr. | HONEYWELL | ASB | 28.02.03 | | A21-3850-001 | O | | | 3P |
| 7510700-XXX | | RNZ-851-Elim.Erron.Glideslope Indic. On ILS Appr. | HONEYWELL | ASB | 11.07.03 | | A21-3850-002 | O | | | 3P |
| 7510100-XXX | | RNZ-850/851 Navigation Unit (MOD AS) | HONEYWELL | SB | 08.07.04 | | A21-3850-004 | O | | | 3A |
| 7510100-XXX | | RNZ-850/851 Navigation Unit (MOD S) | HONEYWELL | SB | 16.12.10 | | A21-3850-009 | O | | | 3A |
| 7510700-802 | | RCZ-851 Eliminat.of Dashes-Display | HONEYWELL | SB | 19.11.02 | | A21-3851-001 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 7510100-VAR | | SRZ-85X - Conv.of Integrd.Comm.Unit SRZ-85X - Conv.of Integrd.Comm.Unit | HONEYWELL | SB | 24.02.04 | 2 07.10.04 | A21-3851-004 | O | | | 3A |
| 7510100-XXX | | Rem. & Change of th XS-852E/F Mode S Transp. | HONEYWELL | ASB | 29.06.05 | 1 29.07.05 | A21-3851-005 | O | | A L E R T | 3A |
| 7510700-802 | | Install Mode S Diversity Transponder With MOD W | HONEYWELL | SB | 21.05.08 | | A21-3851-008 | O | | | 3P |
| 7510700-VAR | 23-81-01 | IdentifyInstallationofXC-833Power/ClusterAssembly | HONEYWELL | SB | 05.06.09 | | A21-3851-009 | O | | | 3A |
| 7510700-XXX | | COMMUNICATIONS - INTEGRATED COMMUNICATIONS UNIT | HONEYWELL | SB | 12.07.12 | 1 16.04.13 | A21-3851-015 | O | | | 3A |
| 7510700-XXX | | COMMUNICATIONS - RCZ-833B/E/F/G/J/K, RCZ-851B/E/F/G/J/K, RCZ-854A/E/F/G/J INTEGRATED | HONEYWELL | SB | 21.05.13 | | A21-3851-023 | O | | | 3A |
| 7021450-401, -601, -801 | | NAVIGATION - WU-440/660/880 RECEIVER TRANSMITTER ANTENNA (RTA) - Modification (MOD) V | HONEYWELL | SB | 19.12.13 | 1 24.10.18 | A21-3944-007 | O | | | 3A |
| 7017300-11XXX/-14XXX | | IC-800 Inspection for SRAM Devices & Replacement as Required | HONEYWELL | SB | 09.10.03 | 3 26.02.18 | A21-6111-002 | O | | | 3P |
| 7017300-11XXX/-14XXX | | PRIMUS 2000-ReduceFalse Engine Indication and Crew Allert System | HONEYWELL | SB | 17.09.03 | 5 07.03.18 | A21-6111-003 | O | | | 3P |
| 7017300-11XXX/-14XXX | 22-11-95 | MOD AF; Hardware Modification MOD AF to Integrated Avionics Computer (IAC) | HONEYWELL | SB | 06.10.14 | 1 30.01.17 | A21-6111-068 | O | | 7017300-22-0132 | 3A |
| 7510700-XXX | | Transp. In P-II Syst. Revert to Standby Operat.Mode | HONEYWELL | TNL | 09.12.04 | 3 18.06.07 | A23-1146-004 | O | | | 3A |
| 7008470-VAR | | Breaking VHF Communic. Squelch | HONEYWELL | NL | 10.10.96 | 2 | A23-1992-006 | O | | | 3P |
| 7008470-VAR | 34-40-00 | Primus 450/650-Sens.change after Mod. AB | HONEYWELL | NL | 11.01.93 | | A23-1993-002 | O | | | 3P |
| 7014300-9XX / 7007549-906 | | Care and Cleaning CRT Displ. Unit | HONEYWELL | SIL | 20.07.95 | | A23-1995-016 | O | | | 3A |
| 7015327-901 | | GP-300 Return To Service Procedure | HONEYWELL | NL | 22.01.97 | 1 22.09.99 | A23-1996-005 | O | | | 3A |
| 7014700-911 | | Recertif.of Honeywell MADC's | HONEYWELL | NL | 24.01.96 | 1 01.10.96 | A23-1996-01 | O | | | 3P |
| 7014700-917/-924 | | Recertif.of Part-No. 7014700-XXX MADC's | HONEYWELL | SIL | 14.11.97 | 7 30.04.12 | A23-1997-004 | O | | | 3A |
| | | Year 2000 Program Update | HONEYWELL | NL | 09.09.99 | | A23-1999-015 | O | | | 3A |
| 7017300-XXX/7013348-XXX | | IC-800/DA-800 LRU Mounting Tray Verification Tool Procedure for the Fairchild Dornier 328/428 Series Aircraft | HONEYWELL | TN | 20.09.99 | | A23-1999-016 | O | | | 3A |
| 7015541-901 | | LRU Mounting Tray Verific.Tool Procedure | HONEYWELL | NL | 20.09.99 | | A23-1999-016 | O | | IC-800/DA-800 | 3A |
| | | Year 2000 Program Office | HONEYWELL | NL | 08.03.99 | | A23-1999-04 | O | | | 3A |
| | | GV SPZ-8500 Troubleshooting Chec | HONEYWELL | TN | 02.06.00 | 1 23.09.02 | A23-2000-023 | O | | | 3A |
| 7014300-901/-902 | | Preventing Overheating of the DU-870 | HONEYWELL | NL | 24.02.06 | 1 16.03.07 | A23-2249-003 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 7510100-XXX | | Poss.Erroneous Glide Slope Ind.on RNZ-850/851 | HONEYWELL | NL | 11.01.03 | 6 17.07.03 | A23-3850-001 | O | | | 3A |
| | | Dashing of Transp.Code and/or COM Frequenzy | HONEYWELL | NL | 22.11.02 | | A23-3851-001 | O | | | 3A |
| 7021450-601 | | Unint.Change to Forced Stanby Over-Ride Rules | HONEYWELL | NL | 04.03.03 | | A23-3944-001 | O | | MOD M | 3A |
| 7021450-801/601/401 | | Primus 880/660/440 Weather Radar Fault Code 11, Magnetron Fault | HONEYWELL | TN | 05.01.03 | 3 09.06.06 | A23-3944-005 | O | | | 3A |
| | | Procedure to Improve Aircraft Ground Track for Terminal RNAV Operations | HONEYWELL | TN | 17.02.06 | | A23-6111-003 | O | | | 3A |
| 7017300-56023 | | IC-800 - Possible Flight Management Pos.Shift | HONEYWELL | NL | 02.02.07 | 1 22.02.07 | A23-6111-008 | O | | | 3P |
| 7013348 | 31-40-01 | DAU a.Fault Warning Monitor Troubleshoot. | HONEYWELL | NL | 05.09.01 | | A23-9999-0006 | O | | | 3A |
| 7015327-XXX | | Replacement of GP-300 Switch Lamps | HONEYWELL | NL | 30.11.01 | | A23-9999-0011 | O | | | 3A |
| HG2021GD02 | | Prod.Transition from GNSSU to GNSSU Mk II | HONEYWELL | NL | 10.05.03 | 1 11.05.05 | A23-9999-038 | O | | | 3A |
| 7510700-8XX | 23-81-01 | RCZ-8XX Integrated Comm.Unit | HONEYWELL | SB | 17.01.05 | 1 13.12.06 | A24-3851-001 | O | | | 3A |
| 7510700-8XX | 23-81-01 | RCZ-8XX Rem.&Change XS-852/A/E/F Mode S Transp. | HONEYWELL | SB | 27.06.05 | 2 12.12.06 | A24-3851-002 | O | | | 3A |
| 7510700-XXX | 23-XX-XX | COM Unit P/N 7510700-563/-613/-615/-624/-625/-663/-665/-675 | HONEYWELL | SB | 01.11.12 | | A24-3851-005 | O | | | 3A |
| 7510100-VAR | | SRZ-851 - Conv.of XS-852/A Mode S | HONEYWELL | SB | 24.02.04 | 2 27.10.05 | A24-3854-001 | O | | | 3A |
| 7017300-XXXXX | | IC-800(X) Integr. Avionics Computer | HONEYWELL | SB | 26.08.02 | | A24-6111-001 | O | | | 3A |
| 7017300-XXXXX | 22-11-95 | IC-800/IC-810 - Avionics Update including Primus Elite Advanced Features and FMS NZ 6.2 | HONEYWELL | SB | 21.12.17 | | A24-6111-081 | O | | | 3A |
| 7014300-901/-902 | | DU870 End-Item Test Software and Hardware Update | HONEYWELL | TB | 23.07.07 | 1 17.09.07 | A45-2249-1987 | O | | | 3A |
| 7014300-901/-902 | | DU870 - New Revision of MT7014300-101 to Address SCR's listed in Section 1B and T337467-9001 Mod B to Mod C Rework | HONEYWELL | TB | 22.10.09 | | A45-2249-2268 | O | | | 3A |
| 7014300-901/-902 | | Automatic Test Program PS7027200-901, Rev.B, used to test the DU870 Electronic Display Unit | HONEYWELL | TB | 01.08.11 | | A45-2249-2458 | O | | | 3A |
| 7510100-9XX/-7XX | | Test Software Rev. for the Honeywell RNZ-850 Nav.Unit | HONEYWELL | TB | 25.10.10 | | A45-3850-2352 | O | | | 3A |
| 7510100-XXX | | Software Rev. for the Honeywell RNZ-851 Nav.Unit | HONEYWELL | TB | 04.11.11 | | A45-3850-2475 | O | | | 3A |
| 7510700-XXX | | RCZ-8XX - New Revision of MT7510700-501 Rev. K | HONEYWELL | TB | 06.05.11 | | A45-3851-2431 | O | | | 3A |
| 7510134 | | This Test Bulletin is applicable to standardization of ITA when using EPIC CATS T336384 | HONEYWELL | TB | 29.10.10 | | A45-4424-2363 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 7510134 | | This Test Bulletin is applicable to standardization of the PRIMUS/EPIC CATS T336384 | HONEYWELL | TB | 21.01.11 | | A45-5100-2324 | O | | | 3A |
| | | Worldwide Exchange/Rental Program | HONEYWELL | BROCHURE | 01.04.01 | 20 01.01.11 | A65-8200-001 | O | | | 3A |
| | | Increased Serv.Bulletin Free-Of-Charge | HONEYWELL | NL | 12.07.94 | | C23-9000-009 | O | | | 3A |
| | | AOG Hotline Telephone Numbers | HONEYWELL | NL | 16.12.94 | 1 25.02.00 | C23-9000-012 | O | | | 3A |
| 7517900-10003 | 34-43-10 | Change 7 Summary TCAS 2000,TCAS II | HONEYWELL | NL | 04.10.99 | | C23-9000-040 | O | | | 3A |
| | | Rem.of all Integr.and Bulletins from CMM | HONEYWELL | NL | 13.07.05 | | C23-9999-042 | O | | | 3A |
| 7018879, 7017300, 7017000 | | FMS VNAV Early Descent | HONEYWELL | TN | 04.01.08 | | D200712000022 | O | | | 3A |
| | | Flight Management System (FMS) Software Versions NZ 6.1 and 6.2 | HONEYWELL | PG | 01.11.08 | 10 01.10.19 | D200802000002 | O | | | 3A |
| | | AH-800 AHRU | HONEYWELL | SIL | 07.11.08 | 2 14.06.12 | D200808000098 | O | | | 3A |
| 3882730-49-7974 | | Install Fuel Flow Deflector on the Fuel Control Differential Pressure (Delta P) Sleeve | HONEYWELL | SB | 25.02.09 | 1 10.04.09 | D200810000012 | O | | ALLIEDSIGNAL | 3P |
| | | Format changes for SB, SPB and SIL | HONEYWELL | SIL | 29.01.09 | | D200901000010 | O | | | 3A |
| 7018879/7017300 | | NZ-2000 Navigation Computer and IC-800E Integrated Avionics Computer | HONEYWELL | SIL | 08.04.09 | | D200902000024 | O | | | 3P |
| | | NZ-2000 Navigation Computer, IC-800 Integrated Avionics Computer (IAC) | HONEYWELL | SIL | 08.04.09 | | D200902000057 | O | | | 3A |
| | | Sale of Consumables Solutions Business to B/E Aerospace | HONEYWELL | SIL | 18.03.09 | | D200903000045 | O | | | 3A |
| 49-7997 | 49-XX-XX | Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines | HONEYWELL | SB | 16.09.09 | 6 05.11.21 | D200906000072 | O | | ALLIEDSIGNAL | 3A |
| | | Prompt Operational Explanation in NZ4.X, NZ5.X, and NZ6.0 Software | HONEYWELL | SIL | 15.10.09 | | D200908000055 | O | | | 3A |
| | | NZ-600/800/900 Navigation Computer | HONEYWELL | SIL | 09.06.10 | | D201006000006 | O | | | 3A |
| HG2001GD40 | | Announcing the Release of Three New Devices in Laseref IV/AH-900 Family of Reference Units | HONEYWELL | SIL | 07.04.11 | | D201009000035 | O | | | 3A |
| | | NZ-2000/FMZ-2000/PRIMUS Apex/PRIMUS EPIC Flight Management System (FMS) | HONEYWELL | SIL | 09.11.10 | 2 19.08.14 | D201010000078 | O | | | 3A |
| | | NZ-2000/NZ-2010/FMZ-2000/PRIMUS Apex/PRIMUS Epic Flight Management System (FMS | HONEYWELL | SIL | 09.11.10 | 14 14.03.14 | D201011000003 | O | | | 3A |
| 7017300-XXXXX | | IC-800/IC-810, Integrated Avionics Computer | HONEYWELL | SIL | 17.05.11 | 3 28.08.19 | D201105000003 | O | | supersedes A23-1146-009 | 3A |
| | | Approved Use of HEFA Biofuel Blends for all Honeywell Commercial APU | HONEYWELL | SIL | 07.09.11 | | D201107000024 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | APU Operations in Volcanically Active Areas | HONEYWELL | SIL | 19.08.11 | | D201107000065 | O | | | 3A |
| | 49-XX-XX | APU - Approved Oils | HONEYWELL | SB | 24.04.07 | 5 23.10.14 | D201110000029 | O | | ALLIEDSIGNAL | 3A |
| 7021450-331/401/411/421 | | Primus 331, 440, 660, 880 Receiver Transmitter Antenna (RTA). Modification | HONEYWELL | SIL | 15.11.11 | | D201111000008 | O | | | 3A |
| | | Acceptance Criteria for On-Wing Borescope Inspections | HONEYWELL | SIL | 13.01.12 | 1 14.08.12 | D201112000050 | O | | | 3A |
| HG2021GD04 | | Equipment Fault Mode Upon Date/Time Initialization | HONEYWELL | SIL | 24.05.12 | 2 21.04.15 | D201205000066 | O | | | 3A |
| 7517400-921/-922 | | PRIMUS EPIC and PRIMUS II Mode S transponders | HONEYWELL | SIL | 22.06.12 | 2 26.11.13 | D201206000008 | O | | | 3A |
| 7016600-901, -902 | | DL-900 Data Loader, PN 7016600-901, -902; Recommendations for Addressing Problems Loading Navigational Databases | HONEYWELL | SIL | 25.09.12 | | D201208000022 | O | | | 3A |
| IC-800 | | Speed Restriction Anomally | HONEYWELL | SIL | 08.02.13 | 1 15.04.13 | D201211000023 | O | | | 3A |
| 7021450-801 | | Primus 331/440/660/880 Digital Weather Radar System Identification of Unapproved Microcircuit U7 or U14 | HONEYWELL | SIL | 04.01.13 | | D201211000038 | O | | | 3A |
| IC-800 | | | HONEYWELL | SIL | 11.02.13 | | D201212000015 | O | | | 3A |
| | | NZ-2000/FMZ-2000 Flight Management System (FMS) STAR Procedure Re-Entry Anomaly | HONEYWELL | SIL | 09.04.13 | | D201302000074 | O | | | 3A |
| | | NZ-2000/FMZ-2000/PRIMUS Apex/PRIMUS EPIC Flight Management System (FMS) Incorrect Radius to Fix Waypoint Melding | HONEYWELL | SIL | 25.09.13 | | D201308000050 | O | | | 3A |
| | | Flight Management System (FMS) for the CD-830 Control Display Unit | HONEYWELL | PG | 01.03.15 | | D201308000052 | O | | | 3A |
| | | FMZ-2000 PRIMUS Apex/PRIMUS EPIC Flight Management Systems (FMS)s; Late | HONEYWELL | SIL | 20.02.14 | | D201401000013 | O | | | 3A |
| 016600-901, -902 | | Data Loader DL900 PN 7016600-901/902 End of Life | HONEYWELL | SIL | 28.05.14 | | D201405000024 | O | | | 3A |
| | | Change of Destination Not Allowed When First Leg in Missed Approach Procedure is Type ARC (AF or RF Leg) | HONEYWELL | SIL | 14.08.14 | | D201408000007 | O | | | 3A |
| | | Controller-Pilot Data Link communication (PM-CPDLC) Funtionality Issues - Protected Mode | HONEYWELL | SIL | 20.10.14 | 1 08.12.14 | D201408000057 | O | | | 3P |
| HG2021GD04 | | Space Based Augmentation System (SBAS) Global Navigation Satellite Sensor Unit (GNSSU) MKII | HONEYWELL | SIL | 05.03.15 | | D201502000082 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 3880021-2, -XX;70721587-3 | | AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Rework Fluid Pressure Regulating Valve, PN 3880021-2, -5 Through -15, and -17 to PN 70721587-3, on Multiple APUs | HONEYWELL | SB | 20.05.15 | 1 20.11.15 | D201504000034 | O | | | 3A |
| 3822101-1 | | AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Balance Repair of Compressor Rotors, PN 3822101-1, on Multiple APUs | HONEYWELL | SB | 10.07.15 | 3 27.11.17 | D201506000008 | O | | | 3A |
| FMZ-2000 | | FMS Software Version 6.1 (NZ 6.1) Uprade and Consolidation | HONEYWELL | SIL | 02.08.16 | 6 06.11.20 | D201604000032 | O | | | 3P |
| | | Integrated Avionic System for the Dornier 328 Turboprop Aircraft with Primus Elite Advanced Features Display System - Retrofit (Option) | HONEYWELL | PG | 01.05.17 | | D201605000055 | O | | | 3P |
| 69003877-501 | | CMU Mark II+ for aircraft with AOC Database P/N 69003877-501 | HONEYWELL | PG | 01.10.17 | | D201610000041 | O | | | 3P |
| 7021450-801, 7021451-XXX | | Navigation - Primus 880 Weather Radar ACT (Altitude Compensated Tilt) Function - Recommended Discontinuation of uns or use with Coution | HONEYWELL | SIL | 29.06.18 | 3 12.08.19 | D201806000021 | O | | | 3A |
| 7017300-11200 SW/-201 SW | | IC-800/IC-810 - Integr. Avionics Computer | HONEYWELL | SB | 26.02.19 | 1 30.05.19 | D201810000007 | O | | | 3A |
| 7007549 | | CD-810/CD-815 Base PN 7007549/Base PN 7022360, Obsolescence and Replacement with CD-830 Base PN G7830 | HONEYWELL | SIL | 11.12.18 | | D201811000013 | O | | | 3A |
| HG2010ACXX | | Discontinuation of Repair Support for AH-800 Attitude and Heading Reference Unit (AHRU) | HONEYWELL | SIL | 23.01.19 | 1 08.07.19 | D201901000001 | O | | | 3A |
| 69000940-1XX,69000941-1XX | | MK V EGPWS, Resident Boot to Resolve MKV-A Reset Issue | HONEYWELL | SB | 18.05.20 | | D202004000738 | O | | | 3A |
| 69000940-1XX,69000941-1XX | | MK V EGPWS, Installation of application Software Version 12 | HONEYWELL | SB | 28.09.20 | | D202009001305 | O | | | 3A |
| 7013348-922/-934 | | Data Acquisition Unit (DAU) DA-800 | HONEYWELL | SB | 24.08.99 | | M21-1147-001-00 | O | | | 3A |
| 7013348-9XX | 31-40-01 | DA-800 Modify Silver Label | HONEYWELL | SB | 15.11.99 | | M21-1147-002 | O | | | 3A |
| 7013348-918 | 31-40-01 | Data Acquisition Unit DA-800 | HONEYWELL | SB | 03.05.01 | | M21-1147-008 | O | | | 3P |
| 7013348-940 | 31-40-01 | Data Acquisition Unit DA-800 | HONEYWELL | SB | 17.10.01 | 1 11.09.03 | M21-1147-011 | O | | | 3P |
| 7013348-937 | 31-40-01 | Data Acquisition Unit DA-800 | HONEYWELL | SB | 07.12.01 | 1 01.06.02 | M21-1147-013 | O | | | 3P |
| HG2001AC02 | 34-26-18 | Modify HG2001AC02 IRU to Mod 2 | HONEYWELL | SB | 15.11.94 | 1 15.04.95 | M21-1994-052 | O | | | 3A |
| HG2010AC02 | 34-26-14 | Modif.of the HG2010AC02 AHRU,Mod 1 | HONEYWELL | SB | 15.07.96 | | M21-1996-048 | O | | | 3A |
| 7013348-9XX | 31-40-01 | DA-800 Data Acquisition Unit | HONEYWELL | NL | 19.06.00 | 1 19.10.00 | M23-1147-002 | O | | | 3A |
| 7013348-XXX | | Data Acquisition Unit (DAU) DA-800 | HONEYWELL | TN | 12.10.00 | | M23-1147-003 | O | | | 3A |
| HG2010AC02 | 34-26-14 | Attitude Heading Reference Unit | HONEYWELL | NL | 06.09.01 | | M23-3335-002 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 26006881-102 | | DC Fan Changes | HONEYWELL | NL | 04.12.98 | | M23-3341-024 | O | | | 3A |
| 26006881-102 | | DC Fan Assembly Part Number Change | HONEYWELL | NL | 04.12.98 | | M23-3341-025 | O | | | 3A |
| HG2001XX | | Inertial Reference Unit (IRU) - Attitude Heading Reference Unit (AHRS) - Global Positioning Inertial Reference Unit (GPIRU) | HONEYWELL | SIL | 06.06.00 | 4 17.12.15 | M23-3343-011 | O | | | 3A |
| HG2011AC | | Clarific.of ATA Spec.2000 Label Config.and Use | HONEYWELL | NL | 06.02.03 | 2 04.09.03 | M23-9000-002 | O | | | 3A |
| | | MKV-A Enhanced Ground Proximity Warning System (EGPWS) | HONEYWELL | PG | 01.09.13 | B 01.03.16 | PDS69000940-801 | O | | | 3P |
| 3800498-1/-3 | 49-24-10 | Replace of Compresse Seals | HONEYWELL | SB | 30.04.08 | 1 01.02.13 | SB GTCP36-49-7969 | O | | ALLIEDSIGNAL | 3P |
| K9321062A01, K9321062A11 | 34-24-39 | DU-875AF Display Unit | HONEYWELL | SB | 23.09.19 | 1 04.10.19 | SBAv644532 | S | | | 3A |
| | | Implement.of Honeywell SOAP for APU's | HONEYWELL | SIL | | 9 12.07.13 | SIL APU-49 | O | | | 3A |
| | 49-XX-XX | Aircraft De-icing and ist possible Effects on Honeywell APUs | HONEYWELL | SIL | 03.03.88 | 2 02.03.15 | SIL APU-7 | O | | | 3A |
| 3800498-1/-3 | 49-24-12 | APU GTCP36-150[DD] | HONEYWELL | SIL | 05.08.03 | 2 30.09.04 | SIL APU-78 | O | | | 3A |
| | | SpotLight Introduction | HONEYWELL | SIL | 11.06.04 | | SIL P331-177 | O | | | 3A |
| | | Aircraft Landing Systems CMM on Internet | HONEYWELL | SIL | 10.11.02 | | SIL-762 | O | | | 3A |
| 3215732-3 | 36-10-99 | DO328 Pressure Regulating and Shutoff Valve | HONEYWELL | SIL | 01.03.05 | 1 28.04.06 | SIL-VAL0013 | O | | | 3P |
| | 34-45-40 | EGPWS-Update Terr.Datab.Vers.439 | HONEYWELL ASIG | SB | 31.05.05 | 1 17.02.06 | 012-0709-137 | O | | ALLIEDSIGNAL | 3P |
| | 34-45-40 | EGPWS-Update Terr.Datab.Vers.440 | HONEYWELL ASIG | SB | 12.09.05 | 1 17.02.06 | 012-0709-139 | O | | ALLIEDSIGNAL | 3P |
| | 34-45-40 | EGPWS-Update Terr.Datab.Vers.441 | HONEYWELL ASIG | SB | 30.11.05 | 1 17.02.07 | 012-0709-141 | O | | ALLIEDSIGNAL | 3P |
| 965-1180-/-1190-020 | 34-45-36 | EGPWS-Update Terr.Datab.Vers.442 | HONEYWELL ASIG | SB | 18.01.06 | 1 17.02.06 | 012-0709-144 | O | | ALLIEDSIGNAL | 3P |
| 965-1180-/-1190-020 | 34-45-36 | EGPWS-Update Terr.Datab.Vers.443 | HONEYWELL ASIG | SB | 21.04.06 | | 012-0709-145 | O | | ALLIEDSIGNAL | 3P |
| 965-1180-/-1190-020 | 34-45-36 | EGPWS-Update Terr.Datab.Vers.444 | HONEYWELL ASIG | SB | 24.08.06 | | 012-0709-148 | O | | ALLIEDSIGNAL | 3P |
| 965-1180-/-1190-020 | 34-45-36 | EGPWS-Update Terr.Datab.Vers.445 | HONEYWELL ASIG | SB | 07.11.06 | | 012-0709-149 | O | | ALLIEDSIGNAL | 3P |
| 965-1180-/-1190-0XX | 34-45-40 | EGPWS Install. and Terrain Database and an Envelope Modulation Database | HONEYWELL ASIG | SB | 22.01.08 | 1 04.11.11 | 012-0709-156 | O | | ALLIEDSIGNAL | 3P |
| | | Format Changes for SB, SPB and SIL | HONEYWELL ASIG | SIL | 09.11.08 | | D200811000019 | O | | ALLIEDSIGNAL | 3P |
| 965-1180-/-1190-020 | 34-45-40 | MKV-Hardware Modification (MOD) 2InspectionoftheA2 Power Supply Circuit Card Assembly (CCA) | HONEYWELL ASIG | SB | 09.04.09 | 1 17.08.09 | D200902000002 | O | | ALLIEDSIGNAL | 3P |
| APU GTCP36-150[DD] | | Release of Honeywell SB GTCP36-49-7969 | HONEYWELL ASIG | SIL | 13.04.09 | | D200904000013 | O | | ALLIEDSIGNAL | 3A |
| APU GTCP36-150[DD] | | SpotLight Line Maint. Troubleshooting for BGA Propulsion and APU Products | HONEYWELL ASIG | SIL | 28.04.10 | | D200909000009 | O | | ALLIEDSIGNAL | 3A |
| 965-0676-021 | | Ground Proximity Warning System | HONEYWELL ASIG | SIL | 09.07.02 | | DISCONTINUED-EQUIP-14 | O | | ALLIEDSIGNAL | 3P |
| 965-1180-/-1190-020 | | EGPWS Terr.Datab.451 and EMD B07 for MK VI | HONEYWELL ASIG | SIL | 02.09.08 | | EGPWS MKVI-68 | O | | ALLIEDSIGNAL | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 965-0676/0976-0XX | | Recommended Maintenance | HONEYWELL ASIG | GIL | 08.06.88 | 2 17.05.00 | GPWC-ALL-34-1 | O | | ALLIEDSIGNAL | 3A |
| 965-0676-021 | | Ground Proximity Warning System | HONEYWELL ASIG | SIL | 16.01.01 | 1 12.09.01 | GPWC-ALL-34-2 | O | | ALLIEDSIGNAL | 3P |
| 965-0676-021 | | Ground Proximity Warning System | HONEYWELL ASIG | SIL | 04.04.02 | | GPWC-ALL-34-4 | O | | ALLIEDSIGNAL | 3P |
| 980-6020-XXX | 23-70-44 | SSCVR-Transp.of Underw.Acoustic Beacon | HONEYWELL ASIG | SIL | 12.02.04 | 1 18.02.05 | RECORDERS-ALL-02 | O | | ALLIEDSIGNAL | 3P |
| 980-4700-XXX | 31-30-40 | Preserv.of 25 Hours od Flight Data during Ground Check Proc. | HONEYWELL ASIG | SIL | 29.04.04 | | RECORDERS-ALL-03 | O | | ALLIEDSIGNAL | 3P |
| 980-4700-0XX | 31-30-40 | J4 Connector Improvement | HONEYWELL ASIG | SB 10 | 23.04.99 | 3 09.01.01 | SB 012-0650-110 | O | | ALLIEDSIGNAL | 3P |
| 980-4700-0XX | 31-30-40 | Repl.Two CSMU Captive Screws | HONEYWELL ASIG | SB 13 | 26.01.00 | | SB 012-0650-113 | O | | ALLIEDSIGNAL | 3P |
| 980-4700-0XX | 31-30-40 | Mod to Pull Up Write Enable Input | HONEYWELL ASIG | SB 14 | 25.08.00 | 3 11.07.01 | SB 012-0650-114 | O | | ALLIEDSIGNAL | 3P |
| 980-4700-0XX | 31-30-40 | Mod to Ensure Correct Capacitor Instal. | HONEYWELL ASIG | SB 15 | 04.05.01 | | SB 012-0650-115 | O | | ALLIEDSIGNAL | 3P |
| 980-4700-0XX | 31-30-40 | ULD Conversion for 980-4700-() | HONEYWELL ASIG | SB 16 | 20.02.02 | | SB 012-0650-116 | O | | ALLIEDSIGNAL | 3P |
| 980-4700-XXX | 31-30-40 | Mod.to Improve CSMU flexprint boot gasket | HONEYWELL ASIG | SB | 28.03.03 | 2 12.09.03 | SB 012-0650-117 | O | | ALLIEDSIGNAL | 3P |
| 980-4700-XXX | 31-30-04 | SSFDR - Ind./Rec.Sys. - Conversion of P/N | HONEYWELL ASIG | SB | 09.07.03 | | SB 012-0650-118 | O | | ALLIEDSIGNAL | 3P |
| 980-4700-XXX | 31-30-04 | SSFDR - Ind./Rec.Sys. - Conversion of P/N | HONEYWELL ASIG | SB | 10.07.03 | | SB 012-0650-119 | O | | ALLIEDSIGNAL | 3P |
| 980-6020-0XX | 23-70-44 | Repl. Two CSMU Captive Screws | HONEYWELL ASIG | SB 12 | 26.01.00 | | SB 012-0667-112 | O | | ALLIEDSIGNAL | 3P |
| 980-6020-0XX | 23-70-44 | Mod to Ensure Compliance w.ARINC 429 | HONEYWELL ASIG | SB 13 | 10.07.01 | | SB 012-0667-113 | O | | ALLIEDSIGNAL | 3P |
| 980-6020-0XX | 23-70-44 | Mod to Ensure Correct Capacitor Instal. | HONEYWELL ASIG | SB 14 | 04.05.01 | | SB 012-0667-114 | O | | ALLIEDSIGNAL | 3P |
| 980-6020-001 | 23-70-44 | ULD Conversion For 980-6020-() | HONEYWELL ASIG | SB 15 | 20.02.02 | | SB 012-0667-115 | O | | ALLIEDSIGNAL | 3P |
| 980-6020-XXX | 23-70-44 | Mod.to Improve CSMU flexprint boot gasket | HONEYWELL ASIG | SB | 28.03.03 | 3 30.01.04 | SB 012-0667-116 | O | | ALLIEDSIGNAL | 3P |
| 980-6020-XXX | 23-70-44 | SSCVR-Reduce Possibility of Liquid Intrusion | HONEYWELL ASIG | SB | 13.02.06 | | SB 012-0667-118 | O | | ALLIEDSIGNAL | 3P |
| 3800498-1 | | Repl. Spring Tension Washer | HONEYWELL ASIG | SB | 04.12.98 | 2 22.12.03 | SB 3882730-49-7416 | O | | ALLIEDSIGNAL | 3P |
| I N V A L I D | | One Time Insp./Repl.of the Coupling | HONEYWELL ASIG | SB | 20.10.99 | 2 06.11.02 | SB GTCP36-49-7540 | O | | Ref. SB GTCP36-49-7717 | 3A |
| 3800498-1/-2 | | Repl.Fuel Shutoff Solenoid Valve | HONEYWELL ASIG | SB | 14.08.02 | 2 03.08.05 | SB GTCP36-49-7691 | O | | ALLIEDSIGNAL | 3A |
| 3800498-1/-3 | 49-24-10 | Insp./Repl.of Coupling Clamp | HONEYWELL ASIG | SB | 25.09.02 | 2 17.04.03 | SB GTCP36-49-7717 | O | | ALLIEDSIGNAL | 3P |
| 3800498-1 | | Examine Fuel Control Delta-P | HONEYWELL ASIG | SB | 10.07.07 | | SB GTCP36-49-7948 | O | | ALLIEDSIGNAL | 3P |
| 3800498-1/-3 | | APU-One Time Insp./Leak Check on the Down Stream | HONEYWELL ASIG | ASB | 14.08.03 | 2 13.12.04 | SB GTCP36-49-A7758 | O | | ALLIEDSIGNAL | 3P |
| 3800498-1/-3 | | One Time Insp./Leak Check on the Down Stream Side of the APU Fuel Shutoff Valve | HONEYWELL ASIG | SB | 14.08.03 | 2 13.12.04 | SB GTCP36-49-A7758 | O | | ALLIEDSIGNAL | 3A |
| | | Using Snug-Angle Tightening Method | HONEYWELL ASIG | SIL | 15.04.96 | 4 01.08.00 | SIL 599 | O | | ALLIEDSIGNAL | 3A |
| | | Wheel Half Rebalancing Requirement | HONEYWELL ASIG | SIL | 31.01.97 | 1 31.12.99 | SIL 616 | O | | ALLIEDSIGNAL | 3A |
| | | Hard Timing Main Wheel Tie Bolt Life | HONEYWELL ASIG | SIL | 15.10.98 | 5 31.07.01 | SIL 647 | O | | ALLIEDSIGNAL | 3A |
| | 32-49-01 | Standard Practices Manual Release | HONEYWELL ASIG | SIL | 31.12.98 | 3 15.06.00 | SIL 651 | O | | ALLIEDSIGNAL | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | 32-49-01 | Steel Shot Blasting Proc.for Paint Rem. | HONEYWELL ASIG | SIL | 25.10.99 | 1 31.12.99 | SIL 668 | O | | ALLIEDSIGNAL | 3A |
| | | SB and SIL on the Internet | HONEYWELL ASIG | SIL | 20.01.00 | 1 25.10.00 | SIL 675 | O | | ALLIEDSIGNAL | 3A |
| 2610701 | 32-46-02 | New Wheel Tie Bolt Nut and Washer | HONEYWELL ASIG | SIL | 15.09.00 | 1 15.08.01 | SIL 697 | O | | ALLIEDSIGNAL | 3P |
| | | Use of BATCO Grease X-8401 #2 | HONEYWELL ASIG | SIL | 29.01.01 | 1 20.04.01 | SIL 706 | O | | ALLIEDSIGNAL | 3A |
| | | Exposure of Aircraft Wheels a.Brakes | HONEYWELL ASIG | ASIL | 10.03.01 | | SIL 710 | O | | ALLIEDSIGNAL | 3A |
| 2611178 | 32-46-02 | New Standard Wear Limits | HONEYWELL ASIG | SIL | 31.07.01 | 1 10.05.02 | SIL 721 | O | | ALLIEDSIGNAL | 3P |
| | | Appr.of Cleaning Solvent Zone Defense | HONEYWELL ASIG | SIL | 08.10.01 | | SIL 725 | O | | ALLIEDSIGNAL | 3A |
| | | APU FAME Contamination in Aviation Turbine Fuel | HONEYWELL ASIG | SIL | 18.07.08 | 2 30.11.10 | SIL APU-152 | O | | ALLIEDSIGNAL | 3A |
| | | Spotlight Troubleshooting System | HONEYWELL ASIG | SIL | 24.12.03 | 2 31.01.07 | SIL APU-83 | O | | ALLIEDSIGNAL | 3A |
| 3800498-3 | 49-24-10 | Replace the Generator Pad Seal Assembly | HONEYWELL ASIG | SPB | 21.03.07 | | SPB GTCP36-150-GTE1248 | O | | ALLIEDSIGNAL | 3A |
| 3800498-1/-3 | 49-24-10 | Repl./Interchangeable of Deswirl deflector | HONEYWELL ASIG | SPB | 19.08.02 | | SPB GTCP36-GTE1261 | O | | ALLIEDSIGNAL | 3A |
| 3800498-1/-2/-3 | 49-24-10 | Authorize the use of Ignition Unit | HONEYWELL ASIG | SPB | 27.02.03 | | SPB GTCP36-GTE1273 | O | | ALLIEDSIGNAL | 3A |
| 980-6020-001 | 23-70-44 | Rectangularly Shaped CSMU | HONEYWELL ASIG | SIL | 18.08.99 | 2 19.06.00 | SSCVR-6020-23-03 | O | | ALLIEDSIGNAL | 3P |
| 980-4700-XXX | 31-30-40 | Rectangularly Shaped CSMU | HONEYWELL ASIG | SIL | 18.08.99 | 2 30.08.00 | SSFDR-4700-31-01 | O | | ALLIEDSIGNAL | 3P |
| | | RDR 2060 Weather Radar Upgrade Program | HONEYWELL BENDIX | SB | 01.01.18 | | 2018BK-01 | O | | Bendix King | 3A |
| 4066010-904/-910 | 34-43-04 | Repair/Servicing Issues for TCAS System Products | HONEYWELL L3 | TNL | 02.02.04 | | 8000406-001 | O | | ACSS-L3 | 3P |
| 4066010-904 | | TCAS-Change Honeywell End Item Identification | HONEYWELL L3 | SB | 28.03.05 | | 8002819-001 | O | | ACSS-L3 | 3P |
| 7517900-XXXXX | 34-43-11 | TCAS 2000 Vis.Insp.1uF Ceramic Capacitors | HONEYWELL L3 | SB | 30.05.06 | | 8004958-001 | O | | ACSS-L3 | 3A |
| 7517900-XXXXX | 34-43-11 | TCAS 2000 Repl.Poer Supply CCA A4 | HONEYWELL L3 | SB | 18.05.06 | | 8005729-001 | O | | ACSS-L3 | 3A |
| 4066010-904 | 34-43-04 | Add Resistor / Capacitor Circuit | HONEYWELL L3 | SB | 15.11.95 | | C21-3841-017 | O | | L3 | 3P |
| 4066010-904 | 34-43-04 | Update Computer Unit Prod.Software | HONEYWELL L3 | SB | 20.12.93 | 1 17.02.94 | C24-3841-016 | O | | L3 | 3P |
| 4066010-904 | 34-43-04 | Install Program ATLAS | HONEYWELL L3 | SB | 04.04.94 | | C24-3841-018 | O | | L3 | 3P |
| 4066010-904 | 34-43-04 | Install Program ATLAS | HONEYWELL L3 | SB | 19.08.94 | | C24-3841-019 | O | | L3 | 3P |
| 4066010-904 | 34-43-04 | Conversion of TCAS Computer Unit | HONEYWELL L3 | SB | 23.05.96 | | C24-3841-021 | O | | L3 | 3P |
| 7517900-XXXXX | | Software Update to Upgrade the TCAS 2000 Computer | HONEYWELL L3 | SB | 31.10.00 | 3 15.07.09 | C24-3841-031 | O | | ACSS-L3 | 3A |
| 4066010-910 | 34-43-04 | Install Updated Test Program | HONEYWELL L3 | SB | 07.12.00 | | C24-3841-033 | O | | L3 | 3P |
| 1716D000-002 | 21-51-11 | Cold Air Unit - Conversion of P/N | HONEYWELL NGL | SB | 04.07.03 | | SB 1716D-21-539 | O | | NGL | 3A |
| 4068B000-002 | 21-51-03 | Flow Control and Shut Off Valve | HONEYWELL NGL | SB | 28.10.04 | | SB 4068B-21-547 | O | | NGL | 3A |
| 5729C000-002/-003 | 21-51-10 | Introduction of New Cold Air Unit | HONEYWELL NGL | SB | 10.07.01 | | SB 5729C-21-530 | O | | NGL | 3A |
| 1716D000-002 | 21-51-11 | Faulty Cold Air Units | HONEYWELL NGL | SIL | 28.09.00 | | SIL-328-001 | O | | NGL | 3A |
| | | TNL8100 Navigation Processor Unit (NPU), Part Number 80742-XX-XXXX, Software Release, System -001C. | HONEYWELL TRIMBLE | SB | 08.12.94 | | SB 80742-00-02 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | TNL8100 Navigation Processor Unit (NPU), Part Number 80742-XX-XXXX, Software Release, System -001D. | HONEYWELL TRIMBLE | SB | 08.12.94 | | SB 80742-00-03 | O | | | 3A |
| | | TNL8100 NPU Software Program 001E | HONEYWELL TRIMBLE | SB | 08.12.94 | | SB 80742-00-04 | O | | | 3A |
| | | TNL8100 NPU SOFTWARE PROGRAM 001F | HONEYWELL TRIMBLE | SB | 26.01.95 | | SB 80742-00-05 | O | | | 3A |
| | | TNL8100 Navigation Processor Unit (NPU), Part Number 80742-XX-XXXX, Software Release, System -002A | HONEYWELL TRIMBLE | SB | 22.06.95 | A 07.07.95 | SB 80742-00-06A | O | | | 3A |
| | | TNL8100 Navigation Processor Unit , Software Release, System -002E | HONEYWELL TRIMBLE | SB | 12.01.96 | A 15.08.96 | SB 80742-00-09 | O | | | 3A |
| 80742-XX-XXXX | | TNL8100 Navigation Processor Unit, Software Release, System -002F | HONEYWELL TRIMBLE | SB | 11.01.96 | A 15.08.96 | SB 80742-00-10 | O | | | 3A |
| 80742-XX-XXXX | | TNL8100 Software version -004A supersedes -0040 | HONEYWELL TRIMBLE | SB | 11.01.96 | A 15.08.96 | SB 80742-00-11 | O | | | 3A |
| 80742-XX-XXXX | | TNL8100 GPS Navigation Systems, with Multifunction Control Display Unit, A2 Oceanic System, Software Release -004B | HONEYWELL TRIMBLE | SB | 05.02.96 | A 15.08.96 | SB 80742-00-12 | O | | | 3A |
| | | TNL8100 GPS Navigation System, with ARINC CDU; Software Upgrade A1 Oceanic -003A | HONEYWELL TRIMBLE | SB | 18.04.96 | B 10.02.98 | SB 80742-00-13A | O | | | 3A |
| 80742-XX-XXXX | | TNL8100 GPS Navigation Systems, with Multifunction Control Display Unit, A2 Oceanic System, Software Release -004B | HONEYWELL TRIMBLE | SB | 15.07.96 | A 15.08.96 | SB 80742-00-14 | O | | | 3A |
| 80742-XX-004D | | Trimble 8100 GPS Navigation System with MCDU, A2 Oceanic System, Software Release -004D | HONEYWELL TRIMBLE | SB | 17.07.96 | A 15.08.96 | SB 80742-00-15 | O | | | 3A |
| | | TNL8100 NAVIGATION PROCESSOR UNIT (NPU), Release of Operating System -003B, which is Y2K-Ready | HONEYWELL TRIMBLE | SB | 14.04.99 | A 10.10.00 | SB 80742-00-20 | O | | | 3A |
| | | TNL8100 NAVIGATION PROCESSOR UNIT (NPU), Release of Operating System -002J | HONEYWELL TRIMBLE | SB | 16.02.00 | | SB 80742-00-22 | O | | | 3A |
| | | TNL8100 Navigation Processor Unit | HONEYWELL TRIMBLE | SB | 25.04.94 | | SB 80742-34-01 | O | | | 3A |
| | | TNL8100 Navigation Processor Unit | HONEYWELL TRIMBLE | SB | 25.04.94 | | SB 80742-34-02 | O | | | 3A |
| | | TNL8100 NAVIGATION PROCESSOR UNIT | HONEYWELL TRIMBLE | SB | 25.04.94 | | SB 80742-34-03 | O | | | 3A |
| | | TNL8100 Navigation System, Processor Unit | HONEYWELL TRIMBLE | SB | 25.04.94 | | SB 80742-34-04 | O | | | 3A |
| | | TNL8100 Navigation Computer Host Computer CCA | HONEYWELL TRIMBLE | SB | 28.03.95 | | SB 80742-34-05 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | TNL8100 Navigation System - ARINC Motherboard CCA, Microprocessor | HONEYWELL TRIMBLE | SB | 27.09.95 | | SB 80742-34-06 | O | | | 3A |
| | | TNL8100 Navigation Processor Unit PN 80742 ,Low Baud Rate Air Data Computer Modification | HONEYWELL TRIMBLE | SB | 10.10.95 | | SB 80742-34-09 | O | | | 3A |
| | | TNL8100 GPS Navigation System, Part Number 80742, CCA ARINC Motherbiard | HONEYWELL TRIMBLE | SB | 30.10.95 | | SB 80742-34-10 | O | | | 3A |
| | | Notification of the Availability of a Software Upgrade A1 Oceanic | HONEYWELL TRIMBLE | SIL | 01.03.96 | B 11.06.96 | SIL 80742-00-04 | O | | | 3A |
| | | Notification of the Availability of Software Upgrade A1 OCEANIC for the Trimble 8100 with ARINC Control Display Unit | HONEYWELL TRIMBLE | SIL | 01.03.96 | B 11.06.96 | SIL 80742-00-05 | O | | | 3A |
| AA-02-A | 25-34-68 | Coffee Maker | IACOBUCCI | SL | 15.09.00 | | HFE96-28B-01SL | O | | | 3A |
| HFE96-28 | | Equip.and Furn.- Galley - Coffee Maker - Repl.of the electronic connector ring nut | IACOBUCCI | SB | 12.01.09 | 1 05.10.10 | HFES-25-07SB | O | | | 3A |
| | | Coffee Maker | IACOBUCCI | SL | 04.01.10 | 1 20.01.10 | HFMM-25-06SL | O | | | 3A |
| 3LO-453/5/4.25 | | G-Switch 3LO Series | INERTIA SWITCH | TD | | | VDN-0530 | O | | FIRST INERTIA SWITCH | 3A |
| 230GC02Y02 /03 | | DC Junction Box P/N 230GC02Y02/230GC02Y03 | INTERTECHNIQUE | ASB | 24.11.97 | | ASB 230GC02Y-24-001 | O | | ZODIAC | 3A |
| L94E31-651/3L94-508 | | Fuel System - Refuelling and Defuelling Valve | INTERTECHNIQUE | SB | 23.05.12 | | L94E31-28-04 | O | | ZODIAC | 3A |
| | | Creation of a New Smoke Goggles Part Number | INTERTECHNIQUE | SB | 30.08.06 | | MXG12001-35-01 | O | | ZODIAC | 3A |
| | 28-XX-XX | Fuel Jet Boost Pump; Modification of the non-return flap valve | INTERTECHNIQUE | SB | 15.02.97 | | SB 219335-28-01 | O | | ZODIAC | 3A |
| | | AC Junction Box P/N 330GA01Y01 | INTERTECHNIQUE | SB | 07.12.98 | | SB 330GA01Y-24-001 | O | | ZODIAC | 3A |
| | 35-01-01 | Crew Oxygen Mask Regulator-Maintainability Data | INTERTECHNIQUE | SIL | 15.06.94 | 3 03.07.08 | SIL 18 | O | | ZODIAC | 3A |
| | | Inside Coating of Evacuation Systems, Non-OEM Appr.Rep.Proc. | INTERTECHNIQUE | SIL | 29.05.09 | | SIL 25-243 | O | | AIR CRUISERS | 3A |
| MC10 Series | | Oxygen-Quick Donning Mask-Regulator | INTERTECHNIQUE | SIL | 27.11.97 | 1 19.03.08 | SIL 28 | O | | C A N C E L L E D | 3A |
| | 35-01-01 | Crew Oxygen Mask Regulator-Parts Procur.Info | INTERTECHNIQUE | SIL | 06.09.04 | | SIL 59 | O | | ZODIAC | 3A |
| MSE30 Series | | Oxygen-Change of Supply Hose Protective Sleeves | INTERTECHNIQUE | SIL | 21.12.06 | 2 28.02.08 | SIL 63 | O | | ZODIAC | 3A |
| | | Verification of the Supply Hose Assembly | INTERTECHNIQUE | SIL | 08.02.08 | | SIL 69 | O | | ZODIAC | 3A |
| for PN 5500-/5600 Series | | Reduction of the Torque used to Tighten the Alternate Nut on the Handle of the On-Off Valve Assembly | INTERTECHNIQUE | SIL | 10.07.07 | | SIL-35-105 | O | | ZODIAC | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional R=Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| for PN 9700 Series | | Reduction of the Torque used to Tighten the Flange Hex Nut on the Handle of the On-Off Valve Kit | INTERTECHNIQUE | SIL | 10.07.07 | | SIL-35-106 | O | ZODIAC | 3A |
| for PN 5500T Sub Series | | New US DOT Hydrostatic Test Interval | INTERTECHNIQUE | SIL | 11.03.08 | 1 01.08.08 | SIL-35-113 | O | AVOX | 3A |
| for PN 898 Series | | New US DOT Hydrostatic Test Interval | INTERTECHNIQUE | SIL | 11.03.08 | 1 01.08.08 | SIL-35-116 | O | ZODIAC | 3A |
| for PN 9700 Series | | New US DOT Hydrostatic Test Interval | INTERTECHNIQUE | SIL | 11.03.08 | 1 01.08.08 | SIL-35-117 | O | AVOX | 3A |
| for PN 898 Series | | Cylinder and Regulator Assemblies | INTERTECHNIQUE | SIL | 01.06.07 | 3 | SIL-35-34 | O | ZODIAC | 3A |
| | | New FAA Rule for Portable Cyl.Assys | INTERTECHNIQUE | SIL | 04.01.06 | | SIL-35-51 | O | ZODIAC | 3A |
| | | New FAA Rule 5600/9800 Series and other | INTERTECHNIQUE | SIL | 20.01.06 | | SIL-35-54 | O | ZODIAC | 3A |
| | | Test Data Sheet for P/N 5500/5600 Series | INTERTECHNIQUE | SIL | 28.08.06 | | SIL-35-66 | O | ZODIAC | 3A |
| | | Test Data Sheet for P/N 9700/9800 Series | INTERTECHNIQUE | SIL | 28.08.06 | | SIL-35-67 | O | ZODIAC | 3A |
| | | Test Data Sheet for P/N 898 and 804882 Series | INTERTECHNIQUE | SIL | 29.08.06 | | SIL-35-74 | O | ZODIAC | 3A |
| | | Technical Publication Index | INTERTECHNIQUE | SIL | 31.07.00 | | SIL-46 | O | ZODIAC | 3A |
| 3A165-0007/8-01-1 | 25-10-72 | Equipment/Furnishings | IPECO | SB | 22.10.95 | | A001-25-88 | O | | 3P |
| | 25-20-17 | SIL for CMM 25-20-17 | IPECO | SIL | 14.12.17 | 2 27.04.18 | K9075-25-004 | O | | 3P |
| 3A165-0007/8-01-1 | 25-11-03 | Crew Seat | IPECO | SIL | | 1 12.01.11 | SIL 1146 | O | Pilot Seat | 3P |
| | | Hydrostatic Test and Inspection Intervals of Fire Extinguisher Containers | KIDDE-DEUGRA | SIL | 03.04.96 | 11 20.10.15 | SIL 96-2 | S | HAMILTON SUNDSTRAND | 3A |
| | | NEW UNDERWATER LOCATOR BEACON TO PROVIDE 90 DAYS OF OPERATION | L3 | SIL | 19.08.14 | | FA2100CVDR 001 | O | Model FA2100 | 3A |
| 7517900-10/55/71 | | TCAS Hardware Modification B to TCAS 2000 RT-950 | L3 ACSS | SB | 11.11.98 | 1 09.01.09 | 7517900-34-0002 | O | ACSS-L3 | 3A |
| | | C21-3841-024 Revision 01 is superseded to Revision 03 | L3 ACSS | IM | 11.11.98 | 2 31.03.09 | 7517900-34-0003 | O | ACSS-L3 | 3A |
| 9000000-XXXXX | | T2CAS and TAWS+ Computer | L3 ACSS | TNL | 03.10.11 | | 8002395-044 | O | ACSS-L3 | 3A |
| 9000000-XXXXX | | T2CAS and TAWS+ Computer | L3 ACSS | TNL | 07.11.11 | | 8002395-045 | O | ACSS-L3 | 3A |
| 9000000-XXXXX | | T2CAS and TAWS+ Computer | L3 ACSS | TNL | 07.02.12 | | 8002395-046 | O | ACSS-L3 | 3A |
| 9000000-XXXXX | | T2CAS and TAWS+ Computer | L3 ACSS | TNL | 09.04.12 | | 8002395-047 | O | ACSS-L3 | 3A |
| 9000000-XXXXX | | T2CAS and TAWS+ Computer | L3 ACSS | TNL | 08.05.12 | | 8002395-048 | O | ACSS-L3 | 3A |
| 9000000-XXXXX | | T2CAS and TAWS+ Computer | L3 ACSS | TNL | 25.06.12 | | 8002395-049 | O | ACSS-L3 | 3A |
| 9000000-XXXXX | | T2CAS and TAWS+ Computer | L3 ACSS | TNL | 02.10.12 | | 8002395-050 | O | ACSS-L3 | 3A |
| 7517900-XXXXX | 34-43-10 | TCAS 2000-Change of Product Sign.Plate to ACSS | L3 ACSS | SB | 10.02.05 | 6 30.06.11 | 8002822-001 | O | ACSS-L3 | 3A |
| 7517900-XXXXX | | Install New TCAS Product Software to Upgrade the TCAS 2000 Computer | L3 ACSS | SB | 16.07.07 | 4 28.02.10 | 8006527-001 | O | ACSS-L3 | 3A |
| 7517900-XXXXX | | A specification change in the TCAS 2000 and T2CAS Computer Units | L3 ACSS | TNL | 21.09.06 | 2 20.10.14 | 8006776-001 | O | ACSS-L3 | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 7517900-XXXXX | | Install New TCAS Product Software to Upgrade the TCAS 2000 Computer | L3 ACSS | SB | 16.07.07 | 3 30.06.09 | 8006924-001 | O | | ACSS-L3 | 3A |
| 4066010-9XX | | Announcement of Limited Service for TCAS II Computer Unit | L3 ACSS | TNL | 07.03.10 | | 8006980 | O | | ACSS-L3 | 3P |
| 7517900-XXXXX | | New Software upgrades TCAS 2000 Computer Mod. B | L3 ACSS | SB | 19.10.07 | 2 30.09.09 | 8007014-001 | O | | ACSS-L3 | 3A |
| 7517900-XXXXX | | Change Current TCAS 2000 Computer Unit Identification Label to a New ACSS Label with 2D Barcode Format | L3 ACSS | SB | 15.03.08 | 5 30.08.11 | 8007056-001 | O | | ACSS-L3 | 3A |
| 7517900-XXXXX | 34-43-11 | Change Current TCAS 2000 Computer Unit Identification Label to a New ACSS Label with 2D Barcode Format | L3 ACSS | SB | 15.03.08 | 7 15.04.14 | 8007333-001 | O | | ACSS-L3 | 3A |
| 7517900-XXXXX | | Change 7 Software Update | L3 ACSS | SB | 07.12.07 | 1 30.01.10 | 8007466-001 | O | | ACSS-L3; supersedes C24-3841-029 | 3A |
| | | Change RCZ-852 Product Identification Label to New ACSS White Polyester Label, Part No. 9000343-003 or -004 with 2D Barcode | L3 ACSS | SB | 31.03.09 | 3 15.03.14 | 8007634-001 | O | | ACSS-L3 | 3A |
| | | Accessing ACSS Test Documentation Using the ACSS Customer Support Website | L3 ACSS | TNL | 04.08.11 | | 8007635-001 | O | | ACSS-L3 | 3A |
| 7517900-55007/55009 | | Software Upgrade TCAS 2000 Computer | L3 ACSS | SB | 31.07.09 | | 8007987-001 | O | | ACSS-L3 | 3A |
| 7517900-55007 | | Software Upgrade TCAS 2000 Computer Unit, Mod. A | L3 ACSS | SB | 31.07.09 | | 8007988-001 | O | | ACSS-L3 | 3A |
| 7517900-55004 | | Software Upgrade TCAS 2000 Computer Unit, Mod. C | L3 ACSS | SB | 31.07.09 | | 8007989-001 | O | | ACSS-L3 | 3A |
| 4066010-910/7517900-XXXXX | | RT-910, RT-950/951 - Change 7.1 | L3 ACSS | TNL | 15.06.09 | C 03.08.11 | 8008040 | O | | ACSS-L3 | 3A |
| 7517900-XXXXX | | Update TCAS 2000 RT-950/-951 - Change 7.1 | L3 ACSS | SB | 15.02.10 | 1 30.10.10 | 8008086-001 | O | | ACSS-L3; superseded by 8008559-001 | 3A |
| 4066010-910/911 | | New TCAS II Change 7.1 Computer Unit | L3 ACSS | SB | 15.02.10 | 3 30.09.11 | 8008087-001 | O | | ACSS-L3, superseded by 8008558-001 | 3P |
| 7517900-XXXXX | | Change to Tear off Label Process | L3 ACSS | TNL | 31.03.10 | | 8008228 | O | | ACSS-L3 | 3A |
| 7517900-XXXXX | | Updates TCAS 2000 RT-950/-951 - Inst. of new Operational Software | L3 ACSS | SB | 12.05.10 | 2 28.06.11 | 8008229-001 | O | | ACSS-L3 | 3A |
| 4066010-910/-912 | | Updates TCAS II Computer Unit - Inst. of new Operational Software | L3 ACSS | SB | 25.05.10 | 3 15.06.14 | 8008230-001 | O | | ACSS-L3 | 3A |
| | | Change 7 Interference Limiting Airworthiness Directive FAQs | L3 ACSS | TNL | 26.08.10 | B 03.08.11 | 8008359 | O | | ACSS-L3 | 3A |
| | | Clarification of P/N Verification Steps | L3 ACSS | TNL | 31.03.11 | | 8008490 | O | | ACSS-L3 | 3A |
| 7517900-XXXXX | | TCAS 2000 Hardware Mod H - Modification Improves Reliability of Receiver CCA A5 | L3 ACSS | SB | 01.01.12 | 1 29.02.12 | 8008500-001 | O | | ACSS-L3 | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 7517900-XXXXX | | TCAS Reaction to Altitude Failures | L3 ACSS | TNL | 11.07.11 | | 8008531 | O | | ACSS-L3 | 3A |
| 7517900-XXXXX | | Update TCAS 2000 RT-951 - Change 7.1 with Altitude Correction | L3 ACSS | SB | 30.08.11 | 1 30.09.11 | 8008537-001 | O | | ACSS-L3 | 3A |
| 7517900-XXXXX | | Update TCAS 2000 RT-950 for Implementation of Interference Limiting Functionality with Altitude Correction | L3 ACSS | SB | 15.01.12 | | 8008542-001 | O | | ACSS-L3 | 3A |
| 4066010-XXX | | Navigation -Traffic Alert and collision Avoidance System -TCAS II Computer Unit | L3 ACSS | SB | 30.09.11 | 3 09.04.12 | 8008558-001 | O | | ACSS-L3 | 3A |
| 7517900-XXXXX | | Navigation -Traffic Alert and Collision Avoidance System -TCAS 2000 Computer Unit | L3 ACSS | SB | 30.08.11 | 3 09.04.12 | 8008559-001 | O | | ACSS-L3; supersedes 8008086-001 | 3A |
| 4066010-XXX | | Navigation -Traffic Alert and Collision Avoidance System -TCAS II Computer Unit | L3 ACSS | SB | 15.10.12 | 1 15.05.17 | 8008666-001 | O | | | 3A |
| 7517900-XXXXX | | Navigation -Traffic Alert and Collision Avoidance System -TCAS 2000 Computer Unit | L3 ACSS | SB | 15.11.12 | 1 16.10.14 | 8008668-001 | O | | ACSS-L3 | 3A |
| 7517900-XXXXX | | Suspect Parts Technical Newsletter | L3 ACSS | TNL | 01.02.12 | A 20.06.12 | 8008704 | O | | ACSS-L3 | 3A |
| 7517900-XXXXX | | Use of USB Adapters with ACSS PC based tools | L3 ACSS | TNL | 09.05.13 | A 25.06.13 | 8008989 | O | | ACSS-L3 | 3A |
| 7517900-XXXXX | | Use of T2CAS (EDDIT) RS-232 cable with TCAS 2000 and ATDL | L3 ACSS | TNL | 10.03.14 | | 8009165 | O | | ACSS-L3 | 3A |
| 7514217-34-0002 | 34-43-04 | Install Mod. C in Receiver Assy A5 | L3 ACSS | SB | 17.08.00 | 3 09.05.03 | C21-3841-029 | O | | L3 | 3P |
| 7517900-XXXXX | 34-43-11 | Conversion of P/N RT 950/951 | L3 ACSS | SB | 11.11.98 | 3 30.04.09 | C24-3841-024 | O | | ACSS-L3 | 3A |
| 4066010-910 | 34-43-04 | Install an Update to Change 7 Software | L3 ACSS | SB | 19.12.01 | 2 28.02.09 | C24-3841-036 | O | | L3 | 3P |
| 7517900-XXXXX | | Update to Change 7 Software to Correct Operational Software | L3 ACSS | SB | 18.12.01 | 1 15.01.10 | C24-3841-038 | O | | ACSS-L3 | 3A |
| 7517900-XXXXX | | TCAS Event Team Update | L3 ACSS | TNL | 18.01.02 | D 15.07.11 | TNL-002 | O | | ACSS-L3 | 3A |
| all P/N | 23-70-01 | Bearing Lubrication Shelf Life | L3 AVIATION RECORDER | SIL | 25.02.03 | | A100/A100A CVR 018 | O | | Model A100X | 3P |
| all P/N | 23-70-01 | Proper Inspection of Insulation Assemblies | L3 AVIATION RECORDER | SIL | 15.09.03 | | A100/A100A CVR 019 | O | | Model A100X | 3P |
| all P/N | 23-70-02 | A100S Solid State Cockpit Voice Recorder | L3 AVIATION RECORDER | SIL | 07.04.99 | | A100S SSCVR 003 | O | | Model A100S | 3P |
| S200-0003()/0012-() | | A200S Solid State Cockpit Voice Recorder - Notification of Discontinued Parts Support | L3 AVIATION RECORDER | SIL | 03.02.11 | | A200S SSCVR 004 | O | | ACSS-L3 | 3A |
| S200-00XX-XX | | A200S Solid State Cockpit Voice Recorder | L3 AVIATION RECORDER | SB | 27.04.98 | | A200S SSCVR FSB008 | O | | Model A200S | 3P |
| S200-0003-()80012-() | | A200S Solid State Cockpit Voice Recorder - Chemical Agent Resistant Clear Coating (Carc) Paint | L3 AVIATION RECORDER | SIL | 26.06.01 | 1 10.10.01 | A200S001 | O | | ACCS-L3 | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| S200-0003-()80012-() | | A200S Solid State Cockpit Voice Recorder - Chemical Agent Resistant Clear Coating | L3 AVIATION RECORDER | SIL | 26.06.01 | 1 10.10.01 | A200S002 | O | | ACCS-L3 | 3A |
| 17A180 | | Projected Shortage of reel and Tape assembly | L3 AVIATION RECORDER | SIL | 25.04.00 | 2 19.12.08 | DFR003 | O | | ACCS-L3 | 3A |
| | | Bearing Lubrication Shelf Life | L3 AVIATION RECORDER | SIL | 25.02.03 | 2 19.12.08 | DFR004 | O | | ACCS-L3 | 3A |
| S800-2000/3000-00 | 31-30-02 | Part Number Interchangeability | L3 AVIATION RECORDER | SIL | 18.02.03 | | F1000 SSFDR 004 | O | | Model F1000 | 3P |
| all P/N | | Digital Flight Recorder | L3 AVIATION RECORDER | SIL | 22.01.99 | | F800 DFR 001 | O | | Model F800 | 3P |
| all P/N | | Bearing Lubrication Shelf Life | L3 AVIATION RECORDER | SIL | 25.02.03 | | F800 DFR 004 | O | | Model F800 | 3P |
| all P/N | | DFR Power Supply Board | L3 AVIATION RECORDER | SB | 01.10.99 | | F800 DFR FSB032 | O | | Model F800 | 3P |
| | | Access to F800 CMMs, SBs, and SILs | L3 AVIATION RECORDER | SIL | 12.08.14 | | F800 DFR007 | O | | Model F800 | 3A |
| 2100-1020-00 | 23-70-04 | MOD DOT 15: Introduction of L-3AR 90-Day Underwater Locator Beacon | L3 AVIATION RECORDER | SB | 16.03.15 | 1 16.06.15 | FA2100CVDR 020 | O | | Model FA2100 | 3A |
| 2100-1020-() | 23-70-04 | Appl.of CSMU Moisture Resist.Seal&RTV Appl. | L3 AVIATION RECORDER | SIL | 25.07.03 | | FA2100CVR 018 | O | | Model FA2100CVR | 3A |
| 2100-XXX-XX | 23-70-04 | New Conformal Coating Process for Acquisition Processor Circuit Card Assembly | L3 AVIATION RECORDER | SIL | 11.03.15 | | FA2100CVR 037 | O | | Model FA2100 | 3A |
| 2100-1020-00 | 23-70-04 | Cockpit Voice Recorder | L3 AVIATION RECORDER | SB | 08.09.98 | | FA2100CVR FSB001 | O | | Model FA2100 | 3A |
| 2100-1020-00 | 23-70-04 | Enhanced Acquisition Processor | L3 AVIATION RECORDER | SB | 30.04.00 | | FA2100CVR FSB002 | O | | Model FA2100 | 3A |
| 2100-1020-00 | 23-70-04 | MOD DOT 15: Introduction of L-3AR 90-Day Underwater Locator Beacon | L3 AVIATION RECORDER | SB | 16.03.15 | | FA2100CVR SB 022 | O | | Model FA2100 | 3A |
| 2100-1020-00 | 23-70-04 | MOD DOT 15: Introduction of L-3AR 90-Day Underwater Locator Beacon | L3 AVIATION RECORDER | SB | 16.03.15 | 2 16.06.15 | FA2100CVR SB 022 | O | | Model FA2100 | 3A |
| 2100-1020-00 | 23-70-04 | Moisture-Resistant Seals | L3 AVIATION RECORDER | SB | 25.09.01 | 1 30.09.02 | FA2100CVR SB004 | O | | Model FA2100 | 3A |
| 2100-XXX-XX | 23-70-04 | New Conformal Coating Process for Acquisition Processor Circuit Card Assembly | L3 AVIATION RECORDER | SIL | 11.03.15 | | FA2100FDR 009 | O | | Model FA2100 | 3A |
| 2100-XXX-XX | | Optional RTV Applications of FA2100FDR | L3 AVIATION RECORDER | SIL | 14.10.19 | | FA2100FDR 011 | O | | Model FA2100 | 3A |
| 2100-4043-00 | 31-30-03 | Moisture-Resistant Seals | L3 AVIATION RECORDER | SB | 25.09.01 | 1 30.09.02 | FA2100FDR SB005 | O | | Model FA2100 | 3A |
| 2100-4043-00 | 31-30-03 | Incorporation of Software Revision 02 | L3 AVIATION RECORDER | SB | 02.04.02 | 1 03.10.02 | FA2100FDR SB006 | O | | Model FA2100 | 3A |
| 2100-4043-00 | 31-30-03 | MOD DOT 14: Introducton of L-3AR 90-Day Underwater Locator Beacon | L3 AVIATION RECORDER | SB | 16.03.15 | 6 21.07.17 | FA2100FDR SB024 | O | | Model FA2100 | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 2100-XXX-XX | 31-30-03 | Introduction of new Software Revision and CSMU Part Number | L3 AVIATION RECORDER | SB | 22.03.16 | 3 10.01.18 | FA2100FDR SB025 | O | | Model FA2100 | 3A |
| 2100-XXX-XX | 31-30-03 | MOD DOT 17 Introduction of new CSMU Part Number | L3 AVIATION RECORDER | SB | 15.11.17 | | FA2100FDR SB026 | O | | Model FA2100 | 3A |
| | 23-70-04 | Port.Interf.Unit-Option.Mod.for Remote Playback | L3 AVIATION RECORDER | SB | 21.07.03 | | PI SB001 | O | | Model FA2100CVR | 3A |
| QAR200-XX-XX | | Flash Card Installation Precaution | L3 AVIATION RECORDER | SIL | 01.07.05 | | QAR 001 | O | | | 3A |
| QAR2XX-XX-XX | | INTRODUCTION OF DATA SERVICES | L3 AVIATION RECORDER | SIL | 02.02.18 | | QAR 005 | O | | L3 | 3A |
| QAR2XX-XX-XX | | WINDOWS 10 COMPATIBLE GROUND STATION UTILITY SOFTWARE | L3 AVIATION RECORDER | SIL | 22.02.18 | | QAR 006 | O | | L3 | 3A |
| S800-2000/3000-00 | 31-30-02 | ROSE V 3.5 Release Notes | L3 AVIATION RECORDER | SIL | 12.09.03 | | ROSE 3.5 | O | | Model F1000 | 3P |
| | | INTRODUCTION OF L−3AR 90−DAY UNDERWATER LOCATOR BEACON INTRODUCTION OF L−3AR 90−DAY UNDERWATER LOCATOR BEACON CONVERSION KIT PN: 068E5542−00 | L3 AVIATION RECORDER | SB | 01.06.15 | 1 16.06.15 | SB L3AR-001 | O | | | 3P |
| S800-2000-00 | | User of the Model F100 Solid State Flight Data Recorder | L3 AVIATION RECORDER | SIL | 31.10.12 | | SIL F100SSFDR006 | O | | | 3A |
| | | L-3 Aviation Recorders 90-Day Beacon Retro-Fit Kits | L3 AVIATION RECORDER | SIL | 01.01.15 | 2 20.10.15 | SIL L-3AR 2015-0005 | O | | | 3P |
| all P/N | | ULB Battery Hazardous Mat.Shipm.Requirements | L3 AVIATION RECORDER | SIL | 20.11.03 | | SIL L3AR-001 | O | | ALL MODELS | 3P |
| | 31-30-20 | Introduction of 25304000-05 Memory Card | L3 AVIATION RECORDER | SB | 15.11.08 | 3 23.06.10 | uQAR SB003 | O | | L3 | 3A |
| | 31-30-20 | Introduction of Software Update Revision 05 | L3 AVIATION RECORDER | SB | 23.06.10 | | uQAR SB004 | O | | L3 | 3A |
| | 31-30-20 | Introduction of 2530400006 Memory Card and uQAR Software Change | L3 AVIATION RECORDER | SB | 09.09.10 | | uQAR SB005 (165E2810-31) | O | | L3 | 3A |
| | 31-30-20 | Introduction of MOD DOT 3 | L3 AVIATION RECORDER | SB | 26.04.11 | | uQAR SB006 | O | | L3 | 3A |
| 501-1228-03 | 24-30-02 | Inst.of PS-835A MOD 6/PS-835B MOD 7 | L3 COMMUNICATIONS | ASB | 20.05.82 | | A-SB 501-1228-7 | O | | BFG AVIONICS | 3A |
| 4066010-904 | 34-43-04 | TCAS II Computer Unit | L3 COMMUNICATIONS | SB | 17.08.00 | 1 01.12.00 | C21-3841-027 | O | | L3 | 3P |
| 4066010-904/-910 | 34-43-04 | Install Hardware Mod. a. Software Update | L3 COMMUNICATIONS | SB | 17.08.00 | 1 02.01.01 | C21-3841-028 | O | | L3 | 3P |
| 4066010-904/-910 | 34-43-04 | Install Hardware Mod. a. Software Update | L3 COMMUNICATIONS | SB | 11.12.00 | 1 05.02.01 | C24-3841-030 | O | | L3 | 3P |
| 4066010-910 | 34-43-04 | Install Updated Test Program | L3 COMMUNICATIONS | SB | 26.12.00 | | C24-3841-034 | O | | L3 | 3P |
| 4066010-910 | 34-43-04 | Install TCAS II Computer Unit | L3 COMMUNICATIONS | SB | 27.03.01 | | C24-3841-035 | O | | L3 | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 7517900-XXXXX | 34-43-10 | Detailed Explanations | L3 COMMUNICATIONS | NL | 31.05.00 | 1 11.08.00 | L23-3841-001 | O | | | 3A |
| 4066010-904 | 34-43-04 | TCAS II And TCAS 2000 Systems | L3 COMMUNICATIONS | NL | 04.10.00 | | L23-3841-002 | O | | L3 | 3P |
| 7517900-XXXXX | 34-43-10 | TCAS 2000 Change 7 Onboard Aircr.Load. | L3 COMMUNICATIONS | NL | 19.12.00 | | L23-3841-003 | O | | L3 | 3A |
| 4066010-910 | | Change 7 Software | L3 COMMUNICATIONS | NL | 17.01.01 | | L23-3841-004 | O | | | 3P |
| 501-1228-03 | 24-30-02 | Installation of MOD 1 | L3 COMMUNICATIONS | SB | 24.03.81 | B 28.02.04 | SB 501-1228-1 | O | | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | Retrofit to provide an emergency buss fuse | L3 COMMUNICATIONS | SB | 26.06.84 | C 15.05.04 | SB 501-1228-10 | O | | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | MOD to PS-835A/MOD 3 to PS-835C | L3 COMMUNICATIONS | SB | 25.02.87 | A 28.02.04 | SB 501-1228-11 | O | | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | Incorp.of MOD to prevent shorting Battery Cells | L3 COMMUNICATIONS | SB | 22.11.88 | A 20.11.03 | SB 501-1228-12 | O | | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | Add.fuse to provide protect.against improp.charging | L3 COMMUNICATIONS | SB | 23.11.88 | A 28.02.04 | SB 501-1228-13 | O | | BFG AVIONICS | 3A |
| 501-1228-04 | 24-30-02 | Incorporation of MOD 5 to PS-835D | L3 COMMUNICATIONS | SB | 17.03.97 | B 28.02.04 | SB 501-1228-14 | O | | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | Emergency Power Supply | L3 COMMUNICATIONS | SB | 15.05.03 | A 20.06.03 | SB 501-1228-15 | O | | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | Installation of MOD 2 | L3 COMMUNICATIONS | SB | 24.08.81 | B 28.02.04 | SB 501-1228-2 | O | | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | Installation of MOD 3 | L3 COMMUNICATIONS | SB | 25.08.81 | A 28.02.04 | SB 501-1228-3 | O | | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | Inst.of PS-835A MOD3/PS-835B MOD 4 | L3 COMMUNICATIONS | SB | 26.08.81 | B 28.02.04 | SB 501-1228-4 | O | | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | Inst.of PS-835A MOD4/PS-835B MOD 5 | L3 COMMUNICATIONS | SB | 16.10.85 | B 28.02.04 | SB 501-1228-5 | O | | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | Inst.of PS-835A MOD5/PS-835B MOD 6 | L3 COMMUNICATIONS | SB | 16.01.82 | D 28.02.04 | SB 501-1228-6 | O | | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | Retrofit of PS-835A/B to PS-835C/D | L3 COMMUNICATIONS | SB | 17.12.99 | B 30.01.02 | SB 501-1228-8 | O | | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | Apply MOD 7 to PS-835A/MOD 8 to PS-835B | L3 COMMUNICATIONS | SB | 26.06.84 | A 28.02.04 | SB 501-1228-9 | O | | BFG AVIONICS | 3A |
| 501-1568-10 | 34-20-27 | Attitude Indicators | L3 COMMUNICATIONS | SB | 01.09.95 | D 11.10.99 | SB 501-1568-1 | O | | BFG AVIONICS | 3A |
| 501-1568-10 | 34-20-27 | Attitude Indicators | L3 COMMUNICATIONS | SB | 14.02.97 | A 01.05.97 | SB 501-1568-2 | O | | BFG AVIONICS | 3A |
| 501-1568-10 | 34-20-27 | Attitude Indicators | L3 COMMUNICATIONS | SB | 15.12.99 | B 15.12.00 | SB 501-1568-3 | O | | BFG AVIONICS | 3A |
| 501-1568-10 | 34-20-27 | Attitude Indicators | L3 COMMUNICATIONS | SB | 15.05.01 | | SB 501-1568-5 | O | | BFG AVIONICS | 3A |
| 501-1568-10 | 34-20-27 | Attitude Indicators | L3 COMMUNICATIONS | SB | 15.05.01 | | SB 501-1568-6 | O | | BFG AVIONICS | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 501-1568-10 | 34-20-27 | Attitude Indicators | L3 COMMUNICATIONS | SB | 15.02.01 | | SB 501-1568-7 | O | | BFG AVIONICS | 3A |
| | | Cleaning and disinfecting guidance | L3 COMMUNICATIONS | SL | 01.05.20 | | SL-001 | O | | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | Repair of printed-circuit board(s) | L3 COMMUNICATIONS | SL | 17.09.70 | C 26.11.03 | SL-1 | O | | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | Provide a self-test procedure | L3 COMMUNICATIONS | SL | 05.04.88 | A | SL-105 | O | | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | Repl.Cells for Emergency Power Supplies | L3 COMMUNICATIONS | SL | 03.03.98 | A 07.08.00 | SL-109 | O | | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | Designated NOT FIELD REPARABLE Assy. | L3 COMMUNICATIONS | SL | 14.02.90 | | SL-112 | O | | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | Resistor Substitution | L3 COMMUNICATIONS | SL | 17.07.91 | A 21.10.91 | SL-114 | O | | BFG AVIONICS | 3A |
| | | Timely and Responsive Service | L3 COMMUNICATIONS | SL | 18.03.96 | A 28.03.01 | SL-126 | O | | BFG AVIONICS | 3A |
| | | Information Pertaining to EPS Installation | L3 COMMUNICATIONS | SL | 30.05.97 | A 15.03.03 | SL-136 | O | | BFG AVIONICS | 3A |
| | | Maintenance Manual Availability | L3 COMMUNICATIONS | SIL | 31.03.16 | | SL-141 | O | | | 3A |
| 501-1228-XX | 24-30-02 | Shipping Instructions For International Customers | L3 COMMUNICATIONS | SL | 24.07.19 | E | SL-261 | O | | BFG AVIONICS | 3A |
| 501-1228-XX | 24-30-02 | L3 COMMUNICATIONSShipping Instructions For International Customers | L3 COMMUNICATIONS | SL | 05.04.21 | F | SL-261 | O | | BFG AVIONICS | 3A |
| 501-1228-XX | 24-30-02 | Replacement Battery of the PS-835 | L3 COMMUNICATIONS | SL | 26.01.17 | E | SL-264 | O | | BFG AVIONICS | 3A |
| 501-1228-XX | 24-30-02 | Shelf Life - Sealed Lead Acid Batteries (Cells) | L3 COMMUNICATIONS | SL | 11.05.17 | D | SL-269 | O | | BFG AVIONICS | 3A |
| | | Literature Package Distribution | L3 COMMUNICATIONS | SL | 04.02.20 | A | SL-353 | O | | BFG AVIONICS | 3A |
| | | Index of SB, SL, SA and SM | L3 COMMUNICATIONS | SL | 15.09.98 | B 22.08.03 | SL-43 | O | | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | Replacement of the PS-823 w. PS-835 | L3 COMMUNICATIONS | SL | 01.09.81 | A 23.07.03 | SL-48 | O | | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | Moisture/Fungus proof.of BFG elect.CCA | L3 COMMUNICATIONS | SL | 06.01.86 | E 02.10.00 | SL-49 | O | | BFG AVIONICS | 3A |
| | | Index Technical Publications | L3 COMMUNICATIONS | SL | 15.09.98 | B 22.08.03 | SL-51 | O | | BFG AVIONICS | 3A |
| 501-1228-03 | 24-30-02 | Lead Acid Battery Outgassing | L3 COMMUNICATIONS | SL | 11.11.82 | D 28.02.04 | SL-64 | O | | BFG AVIONICS | 3A |
| 501-1228-XX | 24-30-02 | PS-835 ( ) - Battery Maintenance | L3 COMMUNICATIONS | SL | 01.06.84 | AD 11.04.18 | SL-80 | O | | | 3A |
| 501-1228-03 | 24-30-02 | Repl.of NiCad Battery Celles and Packs | L3 COMMUNICATIONS | SL | 05.12.91 | B 05.12.91 | SL-84 | O | | BFG AVIONICS | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 501-1228-03 | 24-30-02 | Battery Cell Tiedown Straps | L3 COMMUNICATIONS | SL | 14.12.84 | | SL-85 | O | | BFG AVIONICS | 3A |
| 1048A0000-02 | | Flap Actuator - Introduction of Spring Collar and Locking Sleeve | LIEBHERR | SB | 09.11.99 | | 1048A-27-02 | O | | | 3P |
| 1050A0000-03/-04 | | Change of Position 1 Discrete Signal | LIEBHERR | SB | 03.05.01 | | 1050A-27-01 | O | | | 3A |
| 1050A0000-03/-04 | | Flight Contr.-New Flight Data Rec.Signal | LIEBHERR | SB | 09.07.04 | | 1050A-27-02 | O | | | 3A |
| 1059A0000-02 | | Flight Control-Ground Spoiler Actuator | LIEBHERR | SB | 05.03.99 | | 1059A-27-01 | O | | | 3P |
| 1059A0000-02 | | Upgrade of Ground Spoiler Actuator | LIEBHERR | SB | 26.01.01 | 1 10.03.01 | 1059A-27-02 | O | | | 3P |
| 2097H020900 | 21-34-03 | Relief out of Low Setting | LIEBHERR | SB | 15.06.98 | | SB 2097H-21-01 | O | | ABG-SEMCA | 3A |
| 2097H020900 | 21-34-03 | Production Impr./Main Valve Red.Leakage | LIEBHERR | SB | 31.12.01 | | SB 2097H-21-02 | O | | | 3A |
| 2099J020900 | 21-34-04 | Relief out of Low Setting | LIEBHERR | SB | 31.12.01 | | SB 2099J-21-01 | O | | | 3A |
| 2099J020900 | 21-34-04 | Production Impr./Main Valve Red.Leakage | LIEBHERR | SB | 31.12.01 | | SB 2099J-21-02 | O | | | 3A |
| 22260A010101 | 21-34-01 | Improvement of The Operation | LIEBHERR | SB | 21.03.97 | 2 17.02.98 | SB 22260A-21-01 | O | | ABG-SEMCA | 3P |
| 22260A020201 | 21-34-01 | Various Hardware Modifications | LIEBHERR | SB | 29.06.99 | | SB 22260A-21-02 | O | | ABG-SEMCA | 3P |
| 22260A030201 | 21-34-01 | Backlighting Reliability/Arinc Circuit | LIEBHERR | SB | 21.01.00 | | SB 22260A-21-03 | O | | ABG-SEMCA | 3P |
| | | New AOG Fax Number | LIEBHERR | SIL | 14.02.96 | | SIL 082 | O | | | 3A |
| | | Change Of Name | LIEBHERR | SIL | 01.07.96 | | SIL 087 | O | | | 3A |
| | | Revised Telephone a.Fax Numbers | LIEBHERR | SIL | 27.11.00 | | SIL 132 | O | | | 3A |
| 2099JXXX | | Filter Plugs On Manometric Box | LIEBHERR | SIL | 01.12.95 | | SIL LS2099J-21-01 | O | | ABG-SEMCA | 3A |
| 22260A010101 | 21-34-01 | Cabin Pressure Controller - Software Initiation and Continuous Monitoring Improvements | LIEBHERR | SIL | 07.05.95 | | SIL LS22260A-21-01 | O | | ABG-SEMCA | 3P |
| 22260AXXX | 21-34-01 | Cabin Pressure Controller - Removal Raison Not confirmed Information Sheet | LIEBHERR | SIL | 10.11.95 | | SIL LS22260A-21-02 | O | | OBSOLETED | 3P |
| | | Caution Concerning Non OEM Approved Repair Stations And Part Manufacturers | LIEBHERR | SIL | 21.09.95 | | SIL\ALL\003 | O | | ABG-SEMCA | 3A |
| | | Change of E-Mail Address for Liebherr Aerospace | LIEBHERR TOUL | GIL | 12.09.06 | | GIL | O | | | 3A |
| 10839X | 73-10-08 | Fuel Oil Exchanger - Pressure Differential Switch Threaded Cap Safety Wire Insp. | MABS | SB | 15.12.11 | | 10839-73-08 | O | | | 3P |
| | | Alternate Lockwire Method for Fasteners with Recessed Heads | MABS | SL | 30.11.99 | 2 07.08.09 | GS-SL-52 | O | | | 3A |
| Repl.of Doc.-No. GS-SL-67 | | Change to MABS Paint Application Procedures | MABS | SL | 07.11.08 | | GS-SL-68 | O | | ABSC | 3A |
| DTSP-400L | 24-34-00 | Ni-Cad-Batterie Typ DTSP-400L | MARATHON | IPL | 16.07.91 | | IPL-1096 | O | | 31879-001 | 3A |
| | 24-20-XX | Electrical Power- Static Inverter - Phase Lock Testing | MARATHON | SB | 10.09.90 | | SB 091090-003 | O | | Avionics Instruments | 3A |
| PC-251-1C | 24-20-07 | Electrical Power - Static Inverter - MOD A | MARATHON | SB | 12.09.90 | | SB 091290-005 | O | | Avionics Instruments | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| PC-251-2A | 24-20-07 | Electrical Power - Static Inverter - MOD A to PC-251-2A improve reliability | MARATHON | SB | 15.09.97 | | SB 091597-022 | O | | Avionics Instruments | 3A |
| PC-251-1C (4487-4950) | 24-20-07 | Static Inverter-Damaged C7 Causing Out-Of-Spec Frequency | MARATHON | SB | 19.09.90 | | SB 091990-006 | O | | Avionics Instruments | 3A |
| | | For Repairs – Effective immediately all Flite-Tronics returned goods should be shipped to our sister location | MARATHON | SI | 20.11.06 | | VDN-0427 | O | | Avionics Instruments | 3A |
| | | SB/SL Index Do328 | MESSIER-DOWTY | SB | 30.03.95 | 4 01.02.05 | SB 800-32-000 | S | | | 3A |
| 22730/22731-000-07 | 32-11-01 | MLG - Leg / Main Body | MESSIER-DOWTY | SB | 30.05.97 | | SB 800-32-001 | O | | | 3P |
| 22730/22731-000-07 | 32-11-01 | MLG - Leg / New Jacking Point | MESSIER-DOWTY | SB | 07.07.95 | | SB 800-32-002 | O | | | 3P |
| 22730/22731-000-07 | 32-11-01 | Locking Roller of the MLG | MESSIER-DOWTY | SB | 01.10.94 | | SB 800-32-003 | O | | | 3P |
| 22890/22895-000-01 | 32-31-XX | Restrictor Check Valve | MESSIER-DOWTY | SB | 01.10.94 | | SB 800-32-004 | O | | | 3A |
| 22730/22731-000-07 | 32-11-01 | Locking Roller of the MLG | MESSIER-DOWTY | SB | 06.06.94 | | SB 800-32-006 | O | | | 3P |
| 22420-000-04 | 32-11-04 | MLG - Shock Absorber | MESSIER-DOWTY | SB | 06.11.95 | 1 30.09.96 | SB 800-32-009 | O | | | 3P |
| 22405-000-03 | 32-31-05 | M/NLG - Uplock Unit | MESSIER-DOWTY | SB | 30.03.95 | 1 07.12.95 | SB 800-32-011 | O | | | 3P |
| 22730/22731-000-04 | 32-11-01 | MLG - Shock Absorber | MESSIER-DOWTY | SB | 06.11.95 | 1 30.09.96 | SB 800-32-013 | O | | | 3P |
| 22730-/31-000 | | MLG - Main Body and Trailing Arm | MESSIER-DOWTY | SB | 18.01.99 | 1 19.07.99 | SB 800-32-014 | O | | | 3P |
| 22730/22731-000-05 | 32-11-01 | MLG - Shock Absorber | MESSIER-DOWTY | SB | 05.08.96 | | SB 800-32-015 | O | | | 3P |
| 24125-000-00 | 32-31-06 | MLG - Leg / Actuating Cylinder | MESSIER-DOWTY | SB | 12.01.96 | | SB 800-32-017 | O | | | 3A |
| 23180-000-02 | 32-51-08 | NLG - Leg / Nose Wheel Steering | MESSIER-DOWTY | SB | 23.04.96 | | SB 800-32-019 | O | | | 3A |
| 23100-000-00 | 32-21-00 | NLG - Shock Strut Assembly | MESSIER-DOWTY | SB | 12.02.97 | | SB 800-32-020 | O | | | 3P |
| 23200-000-02 | 32-21-16 | NLG - Brace Assy / Upper Brace | MESSIER-DOWTY | SB | 21.03.97 | | SB 800-32-022 | O | | | 3P |
| 22730/22731-000-XX | 32-11-01 | MLG - Leg | MESSIER-DOWTY | SB | 03.12.97 | 1 04.01.99 | SB 800-32-023 | O | | | 3P |
| 22405-000-04 | 32-31-05 | M/NLG - Uplock Unit / Locking Perform. | MESSIER-DOWTY | SB | 22.10.96 | | SB 800-32-024 | O | | | 3P |
| 24260-000-01 | 32-09-01 | MLG - Brace Assy - Unlocking Cylinder | MESSIER-DOWTY | SB | 26.05.98 | 1 03.07.98 | SB 800-32-025 | O | | | 3P |
| 23100/23110-000-00/1 | | NLG - Shock Absorber | MESSIER-DOWTY | SB | 07.05.97 | | SB 800-32-027 | O | | | 3P |
| 22730/22731-000-07 | 32-11-01 | MLG - Leg / Shot Peening | MESSIER-DOWTY | SB | 27.11.00 | | SB 800-32-028 | O | | | 3P |
| 22730/22731-000-07 | 32-11-01 | MLG - Leg / New Lubricated Bushes | MESSIER-DOWTY | SB | 19.07.99 | | SB 800-32-029 | O | | | 3P |
| 22730/22731-0/300-00 | | MLG - Legs / Universal Joint Pins Insp. | MESSIER-DOWTY | SB | 27.11.00 | | SB 800-32-031 | O | | | 3A |
| 22730/22731-000-8 | 32-11-01 | MLG - Legs / Universal Joint Pins Repl. | MESSIER-DOWTY | SB | 27.11.00 | | SB 800-32-033 | O | | | 3P |
| 22455-000-1 | 32-32-00 | MLG - Assist Actuator - Material Change | MESSIER-DOWTY | SB | 14.11.00 | | SB 800-32-034 | O | | | 3A |
| 23100-000-2/-300-4 | | NLG - Leg / Reloc.of Connector Mounting Hole | MESSIER-DOWTY | SB | 18.10.01 | | SB 800-32-036 | O | | | 3A |
| 23100/23285/23415/23425 | | NLG - Leg / Reloc.of Identification Sleeve | MESSIER-DOWTY | SB | 18.10.01 | | SB 800-32-037 | O | | | 3A |
| 22730-/31-000-00 | | MLG - Insp.of the MLG Wheel Axles | MESSIER-DOWTY | SB | 30.03.05 | 1 03.03.05 | SB 800-32-040 | O | | | 3P |
| | | NLG and MLG Definition of Restoration Tasks for the NLG and MLG | MESSIER-DOWTY | SB | 13.04.11 | | SB 800-32-045 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Nose Landing Gear | MESSIER-DOWTY | SB | 30.05.13 | | SB 800-32-046 | O | | | 3P |
| | | Nose Landing Gear Shock Strut Assembly | MESSIER-DOWTY | SB | 30.05.13 | | SB 800-32-049 | O | | | 3A |
| | | Landing Gear Repair Concessions | MESSIER-DOWTY | SL | 30.11.01 | | SL 000-32-004 | O | | | 3A |
| | | Landing Gear - New Warranty Claims Process | MESSIER-DOWTY | SL | 15.06.09 | | SL 000-32-010 | O | | | 3A |
| | | Product and Costumer Support | MESSIER-DOWTY | SL | 09.12.94 | | SL 800-32-008 | O | | | 3A |
| | | M/NLG - Parts with Limited Life | MESSIER-DOWTY | SL | 20.11.96 | | SL 800-32-021 | O | | | 3A |
| 23200-000-01 | 32-21-16 | NLG - Brace Assy | MESSIER-DOWTY | SL | 23.12.96 | | SL 800-32-026 | O | | | 3P |
| | 12-21-00 | Cleaning of the Landing Gears | MESSIER-DOWTY | SL | 20.08.99 | | SL 800-32-030 | O | | | 3A |
| 22515-000-00/22515-300-00 | 32-11-00 | Landing Gear - Introduction of Logbooks | MESSIER-DOWTY | SL | 08.06.18 | | SL 800-32-050 | O | | Now SAFRAN | 3A |
| | | Permanent Disposal of Scrap Aircraft Parts | MESSIER-DOWTY | SIL | 23.05.13 | | SL GA 32-104 | O | | | 3A |
| | | Fitting of non approved Dowty Rotol Limited parts | MESSIER-DOWTY | SL | 16.08.84 | | SL GA2 | O | | | 3A |
| | | Technical Manual Query Report | MESSIER-DOWTY | SL | 13.03.90 | | SL GA3 | O | | | 3A |
| | | Application for Concession to Repair Standard | MESSIER-DOWTY | SL | 17.04.91 | 1 10.04.96 | SL GA4 | O | | | 3A |
| 106100 | | 2. Handset for Galley | MÜHLENBERG | SB | 01.08.95 | | SB106100-25-08 | O | | DIEHL | 3A |
| 106100 | | Replacing of Ice Chest Flap | MÜHLENBERG | SB | 15.04.96 | | SB106100-54 | O | | | 3A |
| 106100X | | Installation of Handgrip | MÜHLENBERG | SB | 08.06.01 | C 07.08.01 | SB106100F25-01 | O | | | 3A |
| 113218 | 25-29-21 | Add.Doors/Cover f.Music Entertain.C. | MÜHLENBERG | SB | 14.09.00 | A 11.01.01 | SB113218-25-01 | O | | | 3A |
| 1716D000-002 | 21-51-11 | Air Conditioning - Cold Air Unit | NGL | SB | 07.01.98 | 1 11.05.99 | SB 1716D-21-500 | O | | | 3A |
| 4067B000/-002 | 36-11-03 | Introduction of Lever Assy | NGL | SB | 25.03.96 | | SB 4067B-36-116 | O | | | 3P |
| 4067B000/-001 | 36-11-03 | Introd.of Exfoliated Graphite Gaskets | NGL | SB | 12.04.96 | | SB 4067B-36-118 | O | | | 3P |
| 4067B000-002/-003 | 36-11-03 | Pressure Reducing a.Shut-Off Valve | NGL | SB | 22.12.98 | | SB 4067B-36-124 | O | | | 3P |
| 4067B000-003/-005 | 36-11-03 | Intro.of Build Standard Change Dornier 328Jet | NGL | SB | 23.08.05 | | SB 4067B-36-127 | O | | | 3A |
| 4067B000-004/-006 | 36-11-03 | Intro.of Build Standard Change Dornier 328 | NGL | SB | 23.08.05 | | SB 4067B-36-128 | O | | | 3A |
| 4068B000-002 | 21-51-03 | Flow Control and Shut Off Valve | NGL | SB | 15.07.98 | | SB 4068B-21-504 | O | | | 3A |
| 4069B000-002 | 36-11-10 | Pneumatic - Cross Feed Valve | NGL | SB | 21.07.98 | | SB 4069B-36-123 | O | | | 3A |
| 5569C035 | 21-51-10 | Introd.of Environmental Control Unit | NGL | SB | 30.06.96 | 1 02.07.96 | SB 5569C-21-479 | O | | | 3A |
| | | Non OEM Replacement Parts | PACIFIC SCIENTIFIC | SB | 06.03.98 | | SB 26-1121 | O | | | 3A |
| 33100016-1/30903870 | 26-22-37 | 328 APU Fire Extinguishing System | PACIFIC SCIENTIFIC | SB | 15.11.00 | | SB 33100016-26-1 | O | | | 3A |
| 30903870 | | Life of HTL Cartridges | PACIFIC SCIENTIFIC | SB | 15.10.73 | 2 01.06.91 | SB 83-2A | O | | | 3A |
| | | Markings on Fire Extinguishers | PACIFIC SCIENTIFIC | SIL | 15.07.94 | | SIL 26-1109 | O | | | 3A |
| | | Warning Label Halon 1301 | PACIFIC SCIENTIFIC | SIL | 15.05.95 | | SIL 26-1114 | O | | | 3A |
| | | Hydrostatic Testing Interval | PACIFIC SCIENTIFIC | SIL | 31.07.95 | | SIL 26-1115 | O | | | 3A |
| | | Use of PMA Parts | PACIFIC SCIENTIFIC | SIL | 30.08.95 | | SIL 26-1116 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Information Regarding Dot Required K Certification for Hermeticallz Sealed Fire Extinguishers | PACIFIC SCIENTIFIC | SIL | 07.11.14 | | SIL 26-1403 | O | | | 3A |
| 42086 | 29-10-50 | Electric Motor Driven Variable Delivery Hydraulic Pumps | PARKER | SB | 27.11.00 | | SB 42086-29-298 | O | | | 3P |
| 41590-200 | | Ducting Assembly - Compesated Elbow | PERKINELMER | SB | 20.11.01 | | SB 36-001 | O | | | 3P |
| | | Maint. Instructions for operation in areas containing low concentrations of volcanic ash | PWC | SI | 21.04.10 | 1 19.05.10 | 25-2010 | O | | | 3A |
| 3043515 | 72-XX-XX | Cleaning Insp. Rep. (CIR) Vol. 1-16 | PWC | CIR Manual | 31.12.95 | 33 26.10.15 | 3043515 | O | | | 3P |
| | | Insp.Tasks to Allow Return to Service of Improperly Preserved PW119B/C engines | PWC | SI | 20.06.11 | | 49-2011 | O | | | 3P |
| PW100-72-A21798 | 72-10-00 | Replacement of Propeller Shaft | PWC | ASB | 23.03.11 | 5 20.03.12 | A21798 | O | | | 3P |
| PW100-72-A21801 | | Inspection of Propeller Shaft | PWC | ASB | 12.05.11 | 1 18.05.11 | A21801 | O | | | 3P |
| PW100-72-A21802 | 72-10-00 | Replacement of Propeller Shaft | PWC | ASB | 10.05.11 | 4 16.03.12 | A21802 | O | | | 3P |
| PW100-72-A21813 | 72-10-00 | Inspection of Propeller Shaft | PWC | ASB | 08.03.12 | 3 21.03.12 | A21813 | O | | | 3P |
| 3108502-01 | | P2.5 Check Valve Assembly | PWC | CSB | 16.03.92 | | CSB 3036421-75-01 | O | | | 3P |
| 3108502-02 | | P2.5 Check Valve Assembly | PWC | CSB | 16.03.92 | | CSB 3036421-75-02 | O | | | 3P |
| 3108502-02 | 75-30-01 | P2.5 Check Valve Assembly | PWC | CSB | 18.11.96 | | CSB 3036421-75-03 | O | | | 3P |
| 3111712-01 | | Intercompressor Bleed Valve | PWC | CSB | 27.03.91 | 1 12.10.92 | CSB 3036422-75-01 | O | | | 3P |
| 3111017-01 | 75-30-04 | Intercompressor Bleed Valve | PWC | CSB | 01.06.92 | 1 12.10.92 | CSB 3036422-75-02 | O | | | 3P |
| 3111017-02 | 75-30-04 | Intercompressor Bleed Valve | PWC | CSB | 01.06.92 | 1 12.10.92 | CSB 3036422-75-03 | O | | | 3P |
| 3111017-01 | 75-30-04 | Intercompressor Bleed Valve | PWC | CSB | 12.10.92 | | CSB 3036422-75-04 | O | | | 3P |
| 3111017-01 | 75-30-04 | Intercompressor Bleed Valve | PWC | CSB | 12.10.92 | | CSB 3036422-75-05 | O | | | 3P |
| 3112824-01 | 75-30-02 | Intercompressor Bleed Valve | PWC | CSB | 12.10.92 | | CSB 3036422-75-07 | O | | | 3P |
| 3112825-03 | 75-30-02 | Intercompressor Bleed Valve | PWC | CSB | 12.10.92 | | CSB 3036422-75-08 | O | | | 3P |
| 3112825-01 | 75-30-02 | Intercompressor Bleed Valve | PWC | CSB | 12.10.92 | | CSB 3036422-75-09 | O | | | 3P |
| 3108957-01 | 75-30-02 | Intercompressor Bleed Valve | PWC | CSB | 12.10.92 | | CSB 3036422-75-10 | O | | | 3P |
| 3118778-01 | 75-30-02 | Intercompressor Bleed Valve | PWC | CSB | 14.06.93 | 3 30.11.99 | CSB 3036422-75-11 | O | | | 3P |
| 3118642-01 | 75-30-02 | Intercompressor Bleed Valve | PWC | CSB | 06.05.96 | 1 21.02.00 | CSB 3036422-75-13 | O | | | 3P |
| 3118778-01 | 75-30-02 | Intercompressor Bleed Valve | PWC | CSB | 14.02.16 | | CSB 3036422-75-14 | O | | | 3P |
| 3033339 | 74-20-01 | Ignition Cable Assembly | PWC | CSB | 22.02.93 | | CSB 3036423-74-01 | O | | | 3P |
| 3037380 | | Fuel Manifold Adapter | PWC | CSB | 18.09.91 | | CSB 3037038-73-01 | O | | | 3P |
| 3034219 | | Fuel Manifold Adapter | PWC | CSB | 09.03.92 | | CSB 3037038-73-02 | O | | | 3P |
| 3034225 | | Fuel Manifold Adapter | PWC | CSB | 09.03.92 | | CSB 3037038-73-03 | O | | | 3P |
| 3037380 | | Fuel Manifold Adapter | PWC | CSB | 09.03.92 | | CSB 3037038-73-04 | O | | | 3P |
| 3038105 | | Fuel Manifold Adapter | PWC | CSB | 21.12.92 | | CSB 3037038-73-05 | O | | | 3P |
| 3038118 | | Fuel Manifold Adapter | PWC | CSB | 13.10.92 | | CSB 3037038-73-06 | O | | | 3P |
| 3038105 | 73-10-03 | Fuel Manifold Adapter | PWC | CSB | 07.07.97 | 2 12.04.00 | CSB 3037038-73-07 | O | | | 3P |
| 3045667 | 73-10-03 | Fuel Manifold Adapter | PWC | CSB | 09.07.97 | | CSB 3037038-73-08 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 3034219 | 73-10-03 | Fuel Manifold Adapter | PWC | CSB | 01.12.99 | 1 23.04.01 | CSB 3037038-73-09 | O | | | 3P |
| 3053903-01 | 73-10-03 | Fuel Manifold Adapter | PWC | CSB | 23.04.01 | | CSB 3037038-73-10 | O | | | 3P |
| 3037381 | | Fuel Manifold Adapter | PWC | CSB | 18.09.91 | | CSB 3037326-73-01 | O | | | 3P |
| 3034215 | | Fuel Manifold Adapter | PWC | CSB | 09.03.92 | | CSB 3037326-73-02 | O | | | 3P |
| 3034731 | | Fuel Manifold Adapter | PWC | CSB | 09.03.92 | | CSB 3037326-73-03 | O | | | 3P |
| 3034729 | | Fuel Manifold Adapter | PWC | CSB | 09.03.92 | | CSB 3037326-73-04 | O | | | 3P |
| 3037381 | | Fuel Manifold Adapter | PWC | CSB | 09.03.92 | 1 08.09.04 | CSB 3037326-73-05 | O | | | 3P |
| 3038118 | | Fuel Manifold Adapter | PWC | CSB | 13.10.92 | | CSB 3037326-73-06 | O | | | 3P |
| 3038117 | | Fuel Manifold Adapter | PWC | CSB | 09.03.92 | | CSB 3037326-73-07 | O | | | 3P |
| 3038825 | | Fuel Manifold Adapter | PWC | CSB | 21.12.92 | 1 07.09.04 | CSB 3037326-73-08 | O | | | 3P |
| 3038825 | 73-10-04 | Fuel Manifold Adapter | PWC | CSB | 13.10.92 | 1 31.03.93 | CSB 3037326-73-09 | O | | | 3P |
| 3038825 | 73-10-04 | Fuel Manifold Adapter | PWC | CSB | 09.07.97 | | CSB 3037326-73-10 | O | | | 3P |
| 3038826 | 73-10-04 | Fuel Manifold Adapter | PWC | CSB | 09.07.97 | | CSB 3037326-73-11 | O | | | 3P |
| 3038826 | 73-10-04 | Fuel Manifold Adapter | PWC | CSB | 01.12.99 | 1 23.04.01 | CSB 3037326-73-12 | O | | | 3P |
| 3053917-01 | 73-10-04 | Fuel Manifold Adapter | PWC | CSB | 23.04.01 | | CSB 3037326-73-13 | O | | | 3P |
| 3037688 | 74-20-02 | Ignition Cable Assembly | PWC | CSB | 01.03.93 | | CSB 3038532-74-01 | O | | | 3P |
| 3038915 | 74-20-02 | Ignition Cable Assembly | PWC | CSB | 01.03.93 | | CSB 3038532-74-02 | O | | | 3P |
| 3056640 | 73-10-05 | Insp.of Fuel Manifold Adapter | PWC | CSB | 29.11.02 | 3 21.02.03 | CSB 3056640-73-01 | O | | | 3P |
| 3056640 | | Insp.of Fuel Manifold Adapters | PWC | CSB | 29.11.02 | 4 31.07.03 | CSB 3056640-73-01 | O | | | 3P |
| 3056640-73-03 | | Inspection / Modification of Fuel Manifold Adapters | PWC | CSB | 19.12.09 | 3 15.12.17 | CSB 3056640-73-03 | O | | | 3P |
| 3056640 | | Fuel Manifold Adapters | PWC | CSB | 20.07.12 | 3 08.01.14 | CSB 3056640-73-04 | O | | | 3P |
| 30B1704 | 75-10-10 | Modif.of Anti-Icing Solenoid Valve15 | PWC | CSB | 15.12.93 | | CSB 30B1410-75-01 | O | | | 3P |
| 30B5108-01 | 75-10-10 | Modif.of Anti-Icing Solenoid Valve | PWC | CSB | 15.11.99 | | CSB 30B1410-75-02 | O | | | 3P |
| 30B5108-01/-02 | 75-10-10 | Modif.of Anti-Icing Solenoid Valve | PWC | CSB | 15.11.99 | | CSB 30B1417-75-02 | O | | | 3P |
| 30B5108-03 | 75-10-10 | Modif.of Anti-Icing Solenoid Valve | PWC | CSB | 29.01.01 | | CSB 30B1417-75-04 | O | | | 3P |
| 30B5108-04 | 75-10-10 | Modif.of Anti-Icing Solenoid Valve | PWC | CSB | 08.07.02 | | CSB 30B1417-75-05 | O | | | 3P |
| | | Repl.of #29 Bearing and Bevel Gear | PWC | CSPN | 01.12.05 | 3 31.10.13 | CSPN 1000591 | O | | C L O S E D | 3P |
| | | No.15 Bearing Replacement | PWC | CSPN | 27.02.08 | 3 31.10.13 | CSPN 1002527 | O | | C L O S E D | 3P |
| | | Stocking Repl.of PW100 Preformed Packing | PWC | CSPN | 01.06.07 | | CSPN 1002749 | O | | | 3P |
| | | Repl. of First Stage Power Turbine Blade | PWC | CSPN | 17.04.08 | 1 29.11.13 | CSPN 1003455 | O | | C L O S E D | 3P |
| | | Repl.of Oil Filler Neck Tube Valve | PWC | CSPN | 12.05.09 | 1 13.10.13 | CSPN 1004364 | O | | C L O S E D | 3P |
| | | Replacement of Propeller Shaft | PWC | CSPN | 16.06.11 | | CSPN 1005865 | O | | | 3P |
| | | First Stage Power Turbine Blades (PT1 Blades) | PWC | CSPN | 07.11.12 | 4 02.12.13 | CSPN 1006354 | O | | | 3P |
| | | PW100 Mechanical Fuel Control Unit | PWC | CSPN | 04.06.13 | 1 22.12.16 | CSPN 1006830 | O | | | 3P |
| | | First Stage Power Turbine Blades Soft Time Replacement | PWC | CSPN | 03.10.13 | 3 06.08.14 | CSPN 1007005 | O | | | 3P |
| 3120075-02 | | Inspection Fuel Oil Heat Exchanger | PWC | CSPN | 13.05.15 | 1 17.04.17 | CSPN 1008190 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 3115601-01 | | HIGH PRESSURE TURBINE BLADE - INSPECTION/REPLACEMENT | PWC | CSPN | 04.02.16 | | CSPN 1008357 | O | | | 3P |
| PWC54613 | | Fuel Manifold Leak Check Tool | PWC | CSPN | 30.01.95 | 2 27.02.95 | CSPN A94031 | O | | | 3P |
| 3104103-01 | | First-Stage Power-Turbine Blade Repl. | PWC | CSPN | 30.09.98 | 8 20.11.06 | CSPN A95044 | O | | | 3P |
| 3120963-01 | | First-Stage Power-Turbine Blade SSR | PWC | CSPN | 01.11.95 | | CSPN A95049 | O | | | 3P |
| 3116827-01 | | Inner Front Vane-ring Air Seal | PWC | CSPN | 26.01.96 | 3 27.02.06 | CSPN A96002 | O | | | 3P |
| 3120948-01 | | Gas Generator Case Rework | PWC | CSPN | 30.01.97 | 3 05.01.01 | CSPN A97004 | O | | | 3P |
| 3121706-01 | | No. 5 Bearing Replacement | PWC | CSPN | 01.02.97 | 3 14.09.00 | CSPN A97005 | O | | | 3P |
| 3044777-01 | | Fuel Nozzle Adapter Transf. Tube Repl. | PWC | CSPN | 14.08.97 | | CSPN A97019 | O | | | 3P |
| 3121866-01 | | Oil-Pr.-Diff. Automatic-Reset Switch Repl. | PWC | CSPN | 14.09.98 | 2 05.01.01 | CSPN A98027 | O | | | 3P |
| 3112379-01 | | Outer Combus. Liner Center Cooling Ring | PWC | CSPN | 05.03.99 | 1 14.02.00 | CSPN A99003 | O | | | 3P |
| 3118148-01 | | Insulation Blankets for the P3 Venturi | PWC | CSPN | 12.08.93 | 2 26.11.97 | CSPN C93018 | O | | | 3P |
| 3118888-02 | | Upgrade Engine Control to DR005 Conf. | PWC | CSPN | 15.07.94 | 1 13.07.95 | CSPN C94018 | O | | | 3P |
| | | Life Limited History Record | PWC | SPB | 02.07.97 | | PW100 SPB 101 | O | | | 3P |
| | | Packaging Material | PWC | SPB | 08.01.98 | 1 30.10.98 | PW100 SPB 102 | O | | | 3P |
| | 24-39-55 | Chip Detector Option | PWC | SPB | 23.04.98 | 1 20.12.00 | PW100 SPB 104 | O | | | 3P |
| | | RGB-Housing-Sets Assy | PWC | SPB | 04.06.99 | | PW100 SPB 108 | O | | | 3P |
| | | Flow-Divider a.Dump-Valve Shipp.Cover | PWC | SPB | 15.03.99 | | PW100 SPB 111 | O | | | 3P |
| | | Combustion-Chamber-Inner-Liner | PWC | SPB | 18.09.00 | | PW100 SPB 112 | O | | | 3P |
| | | Introduction of Fuel Heater | PWC | SPB | 08.12.99 | 1 26.10.14 | PW100 SPB 116 | O | | | 3P |
| | | Repl.of Tube Heat Shrinkable | PWC | SPB | 21.03.00 | | PW100 SPB 119 | O | | | 3P |
| | | Low-Pressure-Diffuser-Case-Assy | PWC | SPB | 18.09.00 | | PW100 SPB 121 | O | | | 3P |
| | | Repl.of Abradable Seals | PWC | SPB | 02.03.01 | | PW100 SPB 124 | O | | | 3P |
| | | Repl.of Shipping Caps | PWC | SPB | 27.03.01 | 1 27.06.14 | PW100 SPB 126 | O | | | 3P |
| | | Repl.of Jacking Flange Insert | PWC | SPB | 18.12.01 | | PW100 SPB 127 | O | | | 3P |
| | | Repl.of Engine Shipping Container Caps | PWC | SPB | 21.09.92 | | PW100 SPB 13 | O | | | 3P |
| | | Repl.of Fuel Pump Filter Insp.Parts Kit | PWC | SPB | 11.02.02 | 2 25.11.14 | PW100 SPB 130 | O | | | 3P |
| | | Repl.of Air-Pressure-Valve-Boss Gasket | PWC | SPB | 11.03.02 | | PW100 SPB 131 | O | | | 3P |
| | | Replace of engine data plates | PWC | SPB | 12.06.02 | | PW100 SPB 132 | O | | | 3P |
| | | Repl.of Magnetic Plug Chip Detector | PWC | SPB | 25.03.03 | | PW100 SPB 133 | O | | | 3P |
| | | Intro.of No. 18 Bearing Option (IC) | PWC | SPB | 28.02.03 | | PW100 SPB 134 | O | | | 3P |
| | | Turbofan Engine-Repl.of Oil Strainer | PWC | SPB | 30.01.03 | | PW100 SPB 135 | O | | | 3P |
| | | Replacement of P2.5 Check Valve Gasket | PWC | SPB | 10.05.04 | | PW100 SPB 142 | O | | | 3P |
| | | Introduction of Oil Filter Element (IC) | PWC | SPB | 05.04.05 | | PW100 SPB 143 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Altern.Source of No.1 and 7 Bearing Option | PWC | SPB | 15.02.05 | | PW100 SPB 144 | O | | | 3P |
| | | Alt.Source of Oil Filter Element Option (IC) | PWC | SPB | 22.03.05 | | PW100 SPB 146 | O | | | 3P |
| | | Alt.Source of Fuel Filter Element Option (IC) | PWC | SPB | 09.06.05 | 2 03.04.14 | PW100 SPB 147 | O | | | 3P |
| | | Repl.of Shipping Container Steel Strapping | PWC | SPB | 14.07.05 | | PW100 SPB 148 | O | | | 3P |
| | | Repl.of No.5 Oil Bearing Nozzles | PWC | SPB | 30.08.05 | 1 09.09.05 | PW100 SPB 149 | O | | | 3P |
| | | Intro.of No.2 Bearing Housing (IC) Option | PWC | SPB | 30.08.05 | | PW100 SPB 150 | O | | | 3P |
| | | Repl.of Multiple Jet Oil Nozzle Assy | PWC | SPB | 19.09.05 | | PW100 SPB 151 | O | | | 3P |
| | | Replace of Nut Option (IC) Detail | PWC | SPB | 05.12.05 | | PW100 SPB 152 | O | | | 3P |
| | | Repl.of No. 5 Bearing Air & Oil Seal | PWC | SPB | 29.06.07 | | PW100 SPB 153 | O | | | 3P |
| | | Repl.of Fuel-Manifold-Adapter Options | PWC | SPB | 18.09.07 | 1 14.12.09 | PW100 SPB 155 | O | | | 3P |
| | | Repl.of Nut Option (IC) Deatil | PWC | SPB | 10.12.07 | 1 14.03.08 | PW100 SPB 156 | O | | | 3P |
| | | Repl.Low-Press.-Diffuser-Case Self-Locking Nuts | PWC | SPB | 21.05.08 | | PW100 SPB 157 | O | | | 3P |
| | | Intercompr. Bleed Valve Servo Filter Insp. | PWC | SPB | 23.03.92 | | PW100 SPB 16 | O | | | 3P |
| | | Introduction of Bearing Option (IC) | PWC | SPB | 05.03.09 | | PW100 SPB 161 | O | | | 3P |
| | | Replacement of Intercompressor Bleed Valve Air Filter | PWC | SPB | 15.07.09 | | PW100 SPB 162 | O | | | 3P |
| | | Introduction of Ball Bearing Option (IC) Number Revised | PWC | SPB | 09.05.09 | | PW100 SPB 163 | O | | | 3P |
| | | Replacement of Gasket | PWC | SPB | 10.07.09 | | PW100 SPB 164 | O | | | 3P |
| | | Replacement of Nut Option - Interchargeability Control (IC) Number | PWC | SPB | 16.07.09 | 2 06.12.12 | PW100 SPB 165 | O | | | 3P |
| | | Repl.of Shipping Container Shear Mounts | PWC | SPB | 01.10.09 | | PW100 SPB 166 | O | | | 3P |
| | | Introduction of Bearing | PWC | SPB | 16.11.09 | | PW100 SPB 167 | O | | | 3P |
| | | Replacement of Self Locking Nut | PWC | SPB | 10.11.09 | | PW100 SPB 168 | O | | | 3P |
| | | Introduction of Ball Bearing Option (IC) Number Revised | PWC | SPB | 09.02.10 | | PW100 SPB 169 | O | | | 3P |
| | | Part Substitution List | PWC | SPB | 24.03.11 | 2 06.11.14 | PW100 SPB 170 | O | | | 3P |
| | | Introduction of Alternate Source for Self Locking Nut | PWC | SPB | 30.11.11 | | PW100 SPB 171 | O | | | 3P |
| | | Replacement of Bus Bar | PWC | SPB | 22.08.12 | | PW100 SPB 174 | O | | | 3P |
| | | Introduction of Power Turbine Balancing Shaft Assembly (IC) | PWC | SPB | 02.11.12 | | PW100 SPB 175 | O | | | 3P |
| | | Repl. of Retaining Ring | PWC | SPB | 08.07.13 | 1 21.08.13 | PW100 SPB 178 | O | | | 3P |
| | | Introd.of Thermocouple Immersion | PWC | SPB | 07.10.91 | | PW100 SPB 2 | O | | | 3P |
| | | Power Turb.Disk Assy Counters.Tub.Rivet | PWC | SPB | 21.09.92 | | PW100 SPB 23 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | High Press.Rotor Balancing Assy No.4 | PWC | SPB | 10.08.92 | | PW100 SPB 25 | O | | | 3P |
| | | Oil Nozzle Strainer Element Assembly | PWC | SPB | 16.11.92 | 1 27.03.96 | PW100 SPB 28 | O | | | 3P |
| | | Combust. Chamber Cooling Ring | PWC | SPB | 30.11.92 | 1 26.10.95 | PW100 SPB 32 | O | | | 3P |
| | | LPT Housing Flange and Ring | PWC | SPB | 22.02.93 | 1 27.06.94 | PW100 SPB 33 | O | | | 3P |
| | | Metal Seal Ring | PWC | SPB | 14.04.93 | 5 08.10.98 | PW100 SPB 34 | O | | | 3P |
| | | Loop Cushion Clamp Assy | PWC | SPB | 19.04.93 | 4 15.02.17 | PW100 SPB 37 | O | | | 3P |
| | | Power Turbine Rotor Balancing Assy | PWC | SPB | 19.04.93 | 2 14.02.94 | PW100 SPB 39 | O | | | 3P |
| | | HPT Blade History Record | PWC | SPB | 15.11.93 | 1 28.03.94 | PW100 SPB 40 | O | | | 3P |
| | | Combust.Chamber Inner Bottom Liner | PWC | SPB | 21.06.93 | 1 03.06.94 | PW100 SPB 43 | O | | | 3P |
| | | Front Inner Vane Ring Housing Assy | PWC | SPB | 14.06.93 | | PW100 SPB 44 | O | | | 3P |
| | | Power Turbine Shaft Balancing Assy | PWC | SPB | 14.06.93 | | PW100 SPB 45 | O | | | 3P |
| | | Power Turbine Shaft Balancing Assy | PWC | SPB | 13.09.93 | | PW100 SPB 46 | O | | | 3P |
| | | Engine Ship.Container Reinforc.Corners | PWC | SPB | 12.10.93 | 1 24.02.05 | PW100 SPB 52 | O | | | 3P |
| | | Gas Generator Fireseal Supp. Ring | PWC | SPB | 20.12.93 | | PW100 SPB 53 | O | | | 3P |
| | | P2.5 and P3 Air Pressure Valve Assy | PWC | SPB | 08.04.94 | | PW100 SPB 56 | O | | | 3P |
| | | Fuel Pump Filter/Pressure Switch | PWC | SPB | 02.05.94 | | PW100 SPB 57 | O | | | 3P |
| | | Repl.of Power Turbine Blade | PWC | SPB | 29.04.94 | 3 17.10.95 | PW100 SPB 61 | O | | | 3P |
| | | Switch.Valve to Rear Inl.Case Tube Assy | PWC | SPB | 15.11.94 | 1 25.01.95 | PW100 SPB 64 | O | | | 3P |
| | | Low Pressure Diffuser Duct Assy | PWC | SPB | 20.12.94 | | PW100 SPB 65 | O | | | 3P |
| | | Oversized Selflocking Inserts | PWC | SPB | 19.04.95 | | PW100 SPB 66 | O | | | 3P |
| | | Fuel Manifold Adapt. Packings | PWC | SPB | 24.01.95 | 1 12.07.95 | PW100 SPB 67 | O | | | 3P |
| | | Introd.of Fuel Heater | PWC | SPB | 16.02.95 | | PW100 SPB 68 | O | | | 3P |
| | | Introd.of Flanged Roller Bearing Option | PWC | SPB | 08.09.92 | | PW100 SPB 7 | O | | | 3P |
| | | Intro.of Self-Locking Nut, P2.5 Check Valve Assy | PWC | SPB | 04.04.97 | 2 05.06.07 | PW100 SPB 70 | O | | | 3P |
| | | Low Pressure Turbine Stator Assy | PWC | SPB | 01.05.95 | 7 10.12.18 | PW100 SPB 72 | O | | | 3P |
| | | Dust Cap Electrical Connector | PWC | SPB | 28.02.96 | | PW100 SPB 73 | O | | | 3P |
| | | Addition of Washers | PWC | SPB | 28.11.96 | | PW100 SPB 74 | O | | | 3P |
| | | Fuel Pump Inspection Kit | PWC | SPB | 09.02.96 | | PW100 SPB 75 | O | | | 3P |
| | | Introd.of Regulating Valve Parts Kit | PWC | SPB | 27.02.96 | | PW100 SPB 77 | O | | | 3P |
| | | Counterweight Class,Power TDB Assy | PWC | SPB | 04.04.97 | | PW100 SPB 78 | O | | | 3P |
| | | Repl.of Fuel Pump | PWC | SPB | 27.10.95 | | PW100 SPB 79 | O | | | 3P |
| | | Removal of Ignition Exciter Option | PWC | SPB | 08.07.96 | | PW100 SPB 80 | O | | | 3P |
| | | Repl.of Fuel Heater Inspection Kit | PWC | SPB | 08.02.96 | | PW100 SPB 82 | O | | | 3P |
| | | Repl.of Auxiliary Tank Covers | PWC | SPB | 24.02.96 | | PW100 SPB 83 | O | | | 3P |
| | | Fuel Manifold Adapter Option | PWC | SPB | 24.04.96 | | PW100 SPB 86 | O | | | 3P |
| | | Impeller Assy,Centrifugal,High Press. | PWC | SPB | 17.05.96 | | PW100 SPB 87 | O | | | 3P |
| | | Low Press.Turbine Housing Nut Option | PWC | SPB | 05.11.96 | | PW100 SPB 90 | O | | | 3P |
| | | Bearing Spacer/Oil Slinger | PWC | SPB | 16.01.97 | | PW100 SPB 94 | O | | | 3P |
| | | Overspeed Governor Shipping Cover | PWC | SPB | 03.03.97 | | PW100 SPB 95 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Repl.of Fuel Manifold Parts Kit | PWC | SPB | 18.08.97 | | PW100 SPB 97 | O | | | 3P |
| | | Reduction Gearbox Preformed Pack. | PWC | SPB | 07.07.97 | | PW100 SPB 98 | O | | | 3P |
| | | Introduction of Tubular Rivets | PWC | SPB | 03.06.97 | 2 12.04.11 | PW100 SPB 99 | O | | | 3P |
| PW100-TP-72-1 | 72-00-00 | Approved Listing of Lubricating Oils | PWC | SB | 15.11.84 | 4 13.09.93 | SB 20001 | O | | | 3P |
| PW100-TP-72-2 | | Rotor Components - Service Life | PWC | SB | 15.11.84 | 11 13.09.93 | SB 20002 | O | | | 3P |
| PW100-TP-72-4 | 72-00-00 | Engine Fuels and Additives | PWC | SB | 15.11.84 | 4 13.09.93 | SB 20004 | O | | | 3P |
| PW100-TP-72-626 | | Cleanable Main Oil Pressure Filter | PWC | SB | 11.12.89 | | SB 20673 | O | | | 3P |
| PW100-TP-72-687 | | Borescope Insp.Criteria f.Hot Section Comp. | PWC | SB | 25.06.90 | 1 17.02.92 | SB 20845 | O | | | 3P |
| PW100-TP-72-918 | 72-01-40 | Fuel Pump Grooved Coupling | PWC | SB | 04.03.91 | 1 27.05.91 | SB 20909 | O | | | 3P |
| PW100-TP-72-865 | | High Press.Turbine Disk Balancing Assy | PWC | SB | 26.11.90 | 3 25.04.94 | SB 20918 | O | | | 3P |
| PW100-TP-72-867 | | Low Press.Turbine Stator a. Seal Assy | PWC | SB | 26.11.90 | 2 24.01.94 | SB 20927 | O | | | 3P |
| PW100-TP-72-834 | | Fuel Manifold Transf.Tubes a.Lock.Plates | PWC | SB | 12.11.90 | 1 11.02.91 | SB 20928 | O | | | 3P |
| PW100-TP-72-895 | | No.6 & 7 Bearing Housing Assy | PWC | SB | 10.06.91 | 2 28.03.94 | SB 20983 | O | | | 3P |
| PW100-72-21004 | 72-00-00 | Electr.Wiring Harness Insulating Tape | PWC | SB | 29.04.91 | 6 17.05.19 | SB 21004 | O | | | 3P |
| PW100-72-21008 | 72-xx-xx | Gas Generator Case Assy | PWC | SB | 10.06.91 | | SB 21008 | O | | | 3P |
| PW100-72-21013 | 72-xx-xx | Introd.of Fuel Heater Option | PWC | SB | 18.03.91 | 1 13.01.92 | SB 21013 | O | | | 3P |
| PW100-72-21015 | 72-xx-xx | High Press.Turbine Disk Balancing Assy | PWC | SB | 15.04.91 | 1 04.11.91 | SB 21015 | O | | | 3P |
| PW100-72-21016 | 72-03-00 | Accessory Gearbox Drive Lower Bevel | PWC | SB | 30.06.94 | 3 16.02.07 | SB 21016 | O | | | 3P |
| PW100-72-21036 | 72-11-01 | Reduction Gearbox Housing Set | PWC | SB | 08.04.91 | | SB 21036 | O | | | 3P |
| PW100-72-21039 | 72-10-00 | Reduction Gearbox Flexible Layshaft | PWC | SB | 12.08.91 | 5 31.01.00 | SB 21039 | O | | | 3P |
| PW100-72-21048 | 72-00-00 | Rear Inlet Case Assy Inserts | PWC | SB | 15.04.91 | | SB 21048 | O | | | 3P |
| PW100-72-21050 | 72-31-00 | High Press.Centrifugal Impeller Assy | PWC | SB | 27.05.91 | 4 18.11.02 | SB 21050 | O | | | 3P |
| PW100-72-21057 | 72-20-00 | Front Inlet Case Assy | PWC | SB | 21.05.91 | 4 14.05.97 | SB 21057 | O | | | 3P |
| PW100-72-21064 | 72-03-00 | Combustion Chamber Outer Liner Assy | PWC | SB | 30.05.91 | 5 28.03.00 | SB 21064 | O | | | 3P |
| PW100-72-21076 | 72-10-00 | Repl.of Layshaft Vernier Coupling | PWC | SB | 17.08.92 | 1 27.06.94 | SB 21076 | O | | | 3P |
| PW100-72-21087 | 72-00-00 | Insp.of Fuel Pump Input Shaft | PWC | SB | 13.01.92 | 11 25.06.15 | SB 21087 | O | | | 3P |
| PW100-72-21095 | 72-00-00 | Repl.of Dual Ignition Exciters | PWC | SB | 27.01.92 | 7 06.12.97 | SB 21095 | O | | | 3P |
| PW100-72-21100 | 72-01-40 | Repl.of Fuel Heater Option | PWC | SB | 10.02.92 | 3 01.05.01 | SB 21100 | O | | | 3P |
| PW100-72-21104 | 72-03-00 | Mod.of Power Turbine Stator Assy | PWC | SB | 23.03.92 | 2 08.09.94 | SB 21104 | O | | | 3P |
| PW100-72-21125 | 72-01-40 | Repl.of Fuel Pump | PWC | SB | 13.01.92 | 7 30.05.16 | SB 21125 | O | | | 3P |
| PW100-72-21142 | 72-03-00 | Turbine Interstage Case Assy | PWC | SB | 13.04.92 | 6 24.04.20 | SB 21142 | O | | | 3P |
| PW100-72-21153 | 72-20-00 | Mod.of Seal Retaining Plate Assy | PWC | SB | 09.11.92 | 1 25.05.93 | SB 21153 | O | | | 3P |
| PW100-72-21154 | 72-01-40 | Fuel Manifold Inlet Adapter Option | PWC | SB | 13.10.92 | 1 26.11.97 | SB 21154 | O | | | 3P |
| PW100-72-21158 | 72-00-41 | Fuel Manifold Adapter Locking Plates | PWC | SB | 28.04.92 | 3 31.01.97 | SB 21158 | O | | | 3P |
| PW100-72-21163 | 72-00-00 | Oil Press.Differential Autom.Reset Switch | PWC | SB | 03.08.92 | 1 25.05.93 | SB 21163 | O | | | 3P |
| PW100-72-21165 | 72-50-00 | Low Press.Rotor Balancing Assy Shaft | PWC | SB | 24.08.92 | 1 25.05.93 | SB 21165 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| PW100-72-21169 | 72-41-00 | Repl.of Gas Generator Case Assy | PWC | SB | 24.08.92 | 2 17.05.93 | SB 21169 | O | | | 3P |
| PW100-72-21171 | 72-11-80 | Reduction Gearbox Housing Set | PWC | SB | 02.01.93 | 5 01.08.11 | SB 21171 | O | | | 3P |
| PW100-72-21172 | 72-03-00 | Turbine Supp.Case Insulation Blankets | PWC | SB | 31.08.92 | | SB 21172 | O | | | 3P |
| PW100-72-21173 | 72-22-01 | Repl.of Rear Inlet Case Assy | PWC | SB | 24.08.92 | | SB 21173 | O | | | 3P |
| PW100-72-21175 | 72-03-00 | Turbine Support Case Assembly | PWC | SB | 27.07.92 | 5 11.12.97 | SB 21175 | O | | | 3P |
| PW100-72-21176 | 72-01-40 | Repl.of Fuel Heater Option | PWC | SB | 02.11.92 | | SB 21176 | O | | | 3P |
| PW100-72-21178 | | Rear Inlet Case a.Access.Gearbox Cover | PWC | SB | 28.08.92 | 2 04.06.98 | SB 21178 | O | | | 3P |
| PW100-72-21179 | 72-50-00 | Low Pressure Rotor Balancing Assy | PWC | SB | 24.08.92 | | SB 21179 | O | | | 3P |
| PW100-72-21181 | 72-22-10 | Ejector Valve Outlet Tube-To-Boss Flow | PWC | SB | 08.03.93 | | SB 21181 | O | | | 3P |
| PW100-72-21183 | 72-20-00 | Front a.Rear Inlet Case Assy | PWC | SB | 25.01.93 | 4 04.04.06 | SB 21183 | O | | | 3P |
| PW100-72-21186 | 72-01-50 | Repl.of Tube-To-Boss TEE Assy | PWC | SB | 26.04.93 | 3 28.11.94 | SB 21186 | O | | | 3P |
| PW100-72-21187 | 72-01-20 | Modif.of Igniton Cable Assy | PWC | SB | 12.11.92 | 1 01.03.93 | SB 21187 | O | | | 3P |
| PW100-72-21188 | 72-01-50 | High Pressure Impeller Seal Housing | PWC | SB | 02.11.92 | 2 27.06.94 | SB 21188 | O | | | 3P |
| PW100-72-21191 | 72-01-40 | Repl.of Flow Divider and Dump Valve | PWC | SB | 08.09.92 | 1 02.11.92 | SB 21191 | O | | | 3P |
| PW100-72-21199 | 72-02-00 | Front Inlet Case Cover Washers | PWC | SB | 30.11.92 | | SB 21199 | O | | | 3P |
| PW100-72-21200 | 72-03-00 | Gas Generator Case Assy | PWC | SB | 15.03.93 | 1 25.05.93 | SB 21200 | O | | | 3P |
| PW100-72-21205 | 72-02-00 | Modif.of Front Inlet Case Cover | PWC | SB | 18.01.93 | | SB 21205 | O | | | 3P |
| PW100-72-21206 | 72-20-00 | Modif.of Rear Inlet Case Assy | PWC | SB | 01.03.93 | 4 09.06.16 | SB 21206 | O | | | 3P |
| PW100-72-21208 | 72-40-00 | High Pressure Impeller Seal Ring | PWC | SB | 11.01.93 | | SB 21208 | O | | | 3P |
| PW100-72-21212 | 72-22-10 | Hydromechanical Fuel Control | PWC | SB | 19.04.93 | | SB 21212 | O | | | 3P |
| PW100-72-21214 | 72-50-00 | Power Turbine Disk Balancing Assy | PWC | SB | 15.03.96 | 3 30.01.06 | SB 21214 | O | | | 3P |
| PW100-72-21215 | 72-00-00 | Sealing Cap Assy No.6 a.7 Bearing Tube | PWC | SB | 15.02.93 | 1 29.03.93 | SB 21215 | O | | | 3P |
| PW100-72-21217 | 72-00-00 | Modification of Reduction Gearbox Housing Set | PWC | SB | 17.05.93 | 7 07.09.18 | SB 21217 | O | | | 3P |
| PW100-72-21219 | 72-01-10 | Torque Signal Conditioner | PWC | SB | 18.02.93 | | SB 21219 | O | | | 3P |
| PW100-72-21222 | 72-52-00 | Low Pressure Rotor Balancing Assy | PWC | SB | 08.03.93 | | SB 21222 | O | | | 3P |
| PW100-72-21224 | 72-50-00 | Low Pressure Impeller Counterweight | PWC | SB | 22.02.93 | | SB 21224 | O | | | 3P |
| PW100-72-21229 | 72-00-00 | Repl.of Igniter Cable Assy | PWC | SB | 17.05.93 | | SB 21229 | O | | | 3P |
| PW100-72-21230 | 72-00-00 | Repl.of Torque Sensor | PWC | SB | 22.03.95 | 1 12.07.95 | SB 21230 | O | | | 3P |
| PW100-72-21232 | 72-11-00 | Mod./Repl.Red.Gearbox Housing Set and Second Stage Spur Gearshaft | PWC | SB | 08.03.93 | 2 15.02.11 | SB 21232 | O | | | 3P |
| PW100-72-21233 | 72-40-00 | Modification of Combustion Chamber Small Exit Duct | PWC | SB | 23.08.93 | 4 27.10.17 | SB 21233 | O | | | 3P |
| PW100-72-21236 | 72-01-40 | Flow Divider and Dump Valve | PWC | SB | 16.02.93 | | SB 21236 | O | | | 3P |
| PW100-72-21238 | 72-53-00 | Power Turbine Stator and Shaft Assy | PWC | SB | 08.03.93 | 1 31.05.93 | SB 21238 | O | | | 3P |
| PW100-72-21241 | 72-00-00 | Rear Access.Gearbox Breather Tube Assy | PWC | SB | 08.03.93 | | SB 21241 | O | | | 3P |
| PW100-72-21242 | 72-41-03 | High Press.Turb.&Cooling Air NozzleVane | PWC | SB | 08.03.93 | | SB 21242 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| PW100-72-21243 | 72-00-00 | Sealing Cap Assy No.6a.7 Bearing Tube | PWC | SB | 29.03.93 | | SB 21243 | O | | | 3P |
| PW100-72-21245 | 72-00-41 | Repl.of Insulation Blanket Segments | PWC | SB | 12.07.93 | | SB 21245 | O | | | 3P |
| PW100-72-21251 | 72-00-00 | Repl.of Electrical Wiring Harness | PWC | SB | 22.03.93 | | SB 21251 | O | | | 3P |
| PW100-72-21252 | 72-03-00 | Low Pressure Disk Balancing Assy | PWC | SB | 03.05.93 | 1 17.01.94 | SB 21252 | O | | | 3P |
| PW100-72-21253 | 72-03-00 | No.6 Roller Bearing Option | PWC | SB | 05.04.93 | 1 01.11.93 | SB 21253 | O | | | 3P |
| PW100-72-21255 | 72-22-00 | Modif.of Rear Inlet Case Assy | PWC | SB | 27.05.93 | | SB 21255 | O | | | 3P |
| PW100-72-21256 | 72-00-00 | Repl.of Hydromechanical Fuel Control | PWC | SB | 19.04.93 | | SB 21256 | O | | | 3P |
| PW100-72-21257 | 72-10-00 | Reduction Gearbox Housing Set | PWC | SB | 31.05.93 | 1 17.12.96 | SB 21257 | O | | | 3P |
| PW100-72-21259 | 72-00-00 | No.5 Bearing Vent Tube Assy | PWC | SB | 20.09.93 | | SB 21259 | O | | | 3P |
| PW100-72-21260 | 72-00-00 | Conversion of PW119A to PW119B | PWC | SB | 25.05.93 | 1 27.04.98 | SB 21260 | O | | | 3P |
| PW100-72-21263 | 72-22-10 | Ejector Valve Outlet Tube-To-Boss Flow | PWC | SB | 17.05.93 | | SB 21263 | O | | | 3P |
| PW100-72-21264 | 72-00-00 | Intord.of T6 Trim Block Nut | PWC | SB | 17.05.93 | | SB 21264 | O | | | 3P |
| PW100-72-21267 | 72-01-30 | Introd.of Insulation Blankets | PWC | SB | 17.05.93 | 2 17.01.94 | SB 21267 | O | | | 3P |
| PW100-72-21268 | 72-01-50 | Oil Filter Housing Mounted Plug | PWC | SB | 12.07.93 | | SB 21268 | O | | | 3P |
| PW100-72-21269 | 72-00-00 | Electrical Wiring Harness Sleeves | PWC | SB | 25.05.93 | 5 13.06.16 | SB 21269 | O | | | 3P |
| PW100-72-21270 | 72-10-00 | Replacement of Starter Generator a.Hydr.Pump Plain Seals | PWC | SB | 09.05.94 | 7 11.10.17 | SB 21270 | O | | | 3P |
| PW100-72-21272 | 72-10-00 | No. 15 Bearing Keywasher | PWC | SB | 22.11.93 | | SB 21272 | O | | | 3P |
| PW100-72-21273 | 72-00-00 | Intercompressor Bleed Valve Assy | PWC | SB | 04.10.93 | 4 10.08.01 | SB 21273 | O | | | 3P |
| PW100-72-21274 | 72-01-50 | P3 Air Press.Sensing Tube Att.Clamps | PWC | SB | 14.06.93 | | SB 21274 | O | | | 3P |
| PW100-72-21277 | 72-00-53 | Repl.of Turbine Support Case Assy | PWC | SB | 11.07.94 | 3 08.08.01 | SB 21277 | O | | | 3P |
| PW100-72-21278 | 72-00-00 | Introd.of 90 Degree Angle Bracket | PWC | SB | 09.08.93 | 1 27.04.95 | SB 21278 | O | | | 3P |
| PW100-72-21279 | 72-01-50 | Scavenge Pump Housing Assy | PWC | SB | 06.12.93 | | SB 21279 | O | | | 3P |
| PW100-72-21281 | 73-21-00 | Electronic Engine Control | PWC | SB | 21.06.93 | | SB 21281 | O | | | 3P |
| PW100-72-21282 | 72-00-00 | Modif.of Negative Bus-Bar | PWC | SB | 07.09.93 | | SB 21282 | O | | | 3P |
| PW100-72-21283 | 72-00-00 | Accessory-Gearbox Breather Tube | PWC | SB | 12.07.93 | 1 04.10.93 | SB 21283 | O | | | 3P |
| PW100-72-21284 | 72-01-10 | Repl.of Torque Signal Conditioner | PWC | SB | 09.08.93 | 3 24.07.19 | SB 21284 | O | | | 3P |
| PW100-72-21286 | 72-00-41 | Replacement of Metal Seal Ring | PWC | SB | 08.11.93 | 3 18.04.17 | SB 21286 | O | | | 3P |
| PW100-72-21287 | 72-50-02 | Modif.of Turbine Support Case Assy | PWC | SB | 17.01.94 | 3 20.03.17 | SB 21287 | O | | | 3P |
| PW100-72-21288 | 72-00-00 | P3 Adapter Insulation Blanket Clamp | PWC | SB | 31.08.93 | | SB 21288 | O | | | 3P |
| PW100-72-21289 | 72-03-00 | Repl.of No. 6 Roller Bearing | PWC | SB | 02.09.93 | 1 01.11.93 | SB 21289 | O | | | 3P |
| PW100-72-21297 | 72-22-00 | Cable Support Bracket Assy | PWC | SB | 31.01.94 | | SB 21297 | O | | | 3P |
| PW100-72-21298 | 72-00-00 | Various Gaskets a.Engine Shipp.Container | PWC | SB | 12.10.93 | 4 10.06.97 | SB 21298 | O | | | 3P |
| PW100-72-21301 | 72-50-04 | Repl.of HPT Tee Shoulder Bolts | PWC | SB | 29.11.93 | | SB 21301 | O | | | 3P |
| PW100-72-21303 | 72-00-51 | HPT Disk and Rotor Balancing Assy | PWC | SB | 06.12.93 | 2 28.11.94 | SB 21303 | O | | | 3P |
| PW100-72-21305 | 72-00-00 | Sealing Cap Assy No.6 & 7 Bearing Tube | PWC | SB | 11.04.94 | 1 12.12.94 | SB 21305 | O | | | 3P |
| PW100-72-21306 | 72-20-00 | Repl.of Seal Carrier Gasket | PWC | SB | 22.11.93 | | SB 21306 | O | | | 3P |
| PW100-72-21308 | 72-03-00 | No. 5 Bearing Air and Oil Seal | PWC | SB | 17.01.94 | | SB 21308 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| PW100-72-21309 | 72-01-40 | Repl.of Flow Divider and Dump Valve | PWC | SB | 22.11.93 | 4 20.09.99 | SB 21309 | O | | | 3P |
| PW100-72-21311 | 72-20-00 | Access.Gearbox Spur Gearsh.Space Ring | PWC | SB | 23.12.93 | 6 04.05.17 | SB 21311 | O | | | 3P |
| PW100-72-21316 | 72-01-30 | Intercompr.Bleed Valve Servo Valve | PWC | SB | 24.01.94 | 5 22.07.19 | SB 21316 | O | | | 3P |
| PW100-72-21317 | 72-00-00 | Introd.of Fuel Heater Option | PWC | SB | 28.02.94 | | SB 21317 | O | | | 3P |
| PW100-72-21319 | 72-01-60 | T6 Thermocouple and Adapter | PWC | SB | 31.03.94 | 6 25.01.00 | SB 21319 | O | | | 3P |
| PW100-72-21320 | 72-00-00 | Turbine Support Case Assy Inserts | PWC | SB | 17.01.94 | 1 11.12.97 | SB 21320 | O | | | 3P |
| PW100-72-21323 | 72-10-00 | Repl.of Reduction Gearbox Input Shaft | PWC | SB | 21.03.94 | | SB 21323 | O | | | 3P |
| PW100-72-21324 | 72-00-51 | High Pressure Turbine Stubshaft | PWC | SB | 21.03.94 | 8 06.07.06 | SB 21324 | O | | | 3P |
| PW100-72-21328 | 72-50-00 | Power Turbine Disk Balancing Assy | PWC | SB | 21.04.94 | 3 14.03.05 | SB 21328 | O | | | 3P |
| PW100-72-21331 | 72-03-00 | Inner Front Vane Ring Housing Assy | PWC | SB | 15.07.94 | 3 10.12.96 | SB 21331 | O | | | 3P |
| PW100-72-21335 | 72-00-41 | Gas Generator Fireseal Supp. Ring | PWC | SB | 13.06.94 | 1 18.08.06 | SB 21335 | O | | | 3P |
| PW100-72-21336 | 72-00-00 | Repl.of Fuel Heater Option | PWC | SB | 04.06.94 | | SB 21336 | O | | | 3P |
| PW100-72-21339 | 72-30-00 | No. 4 Bearing Housing | PWC | SB | 12.05.94 | 2 28.06.01 | SB 21339 | O | | | 3P |
| PW100-72-21350 | 73-21-00 | Repl.of Electronic Engine Control | PWC | SB | 04.08.94 | 2 10.05.95 | SB 21350 | O | | | 3P |
| PW100-72-21352 | 72-00-00 | Turbine Support Case a.Metal Seal Ring | PWC | SB | 13.10.94 | 5 25.02.16 | SB 21352 | O | | | 3P |
| PW100-72-21353 | 72-01-10 | Torque Signal Conditioner Unit | PWC | SB | 26.07.94 | 2 20.12.19 | SB 21353 | O | | | 3P |
| PW100-72-21355 | 72-00-00 | Electrical Wiring Harness Clamp | PWC | SB | 07.02.95 | | SB 21355 | O | | | 3P |
| PW100-72-21356 | 72-00-41 | Gas Generator Case Assy and Bolts | PWC | SB | 18.10.94 | 1 16.05.97 | SB 21356 | O | | | 3P |
| PW100-72-21364 | 72-00-41 | Repl.of Preformed Packings | PWC | SB | 16.09.94 | 2 10.02.04 | SB 21364 | O | | | 3P |
| PW100-72-21367 | 72-03-00 | Modif.of Gas Generator Case Assy | PWC | SB | 26.01.95 | 3 04.12.18 | SB 21367 | O | | | 3P |
| PW100-72-21372 | 72-00-00 | Airframe Brackets Arrangement | PWC | SB | 09.12.94 | 1 08.08.96 | SB 21372 | O | | | 3P |
| PW100-72-21373 | 72-01-40 | Fuel Manif.Transf.Tube Lock.Plate | PWC | SB | 27.12.94 | 3 11.10.96 | SB 21373 | O | | | 3P |
| PW100-72-21374 | 72-00-21 | Repl./Rew.of Front Inlet Case Assy | PWC | SB | 10.10.94 | 2 14.03.95 | SB 21374 | O | | | 3P |
| PW100-72-21375 | 72-00-00 | Repl.of Waste Fuel Ejector | PWC | SB | 04.04.95 | | SB 21375 | O | | | 3P |
| PW100-72-21378 | 72-00-51 | Repl.of HPT Shroud Segments | PWC | SB | 31.01.95 | 1 27.02.97 | SB 21378 | O | | | 3P |
| PW100-72-21379 | 72-00-22 | Compressor Wash Nozzle | PWC | SB | 09.12.94 | 5 28.04.22 | SB 21379 | O | | | 3P |
| PW100-72-21380 | 72-50-00 | No. 5 Bearing Air and Oil Seal | PWC | SB | 16.11.94 | | SB 21380 | O | | | 3P |
| PW100-72-21381 | 72-00-21 | Front Inlet Case Assy | PWC | SB | 12.12.94 | 1 16.06.95 | SB 21381 | O | | | 3P |
| PW100-72-21382 | 72-31-00 | No. 5 Bearing Air and Oil Seal | PWC | SB | 30.11.94 | 2 22.06.99 | SB 21382 | O | | | 3P |
| PW100-72-21383 | 72-01-50 | Reduction Gearbox Oil Filter Housing | PWC | SB | 30.11.94 | 4 05.08.11 | SB 21383 | O | | | 3P |
| PW100-72-21395 | 72-03-00 | High Press.Centrifugal Impeller Assy | PWC | SB | 30.01.95 | 1 06.10.03 | SB 21395 | O | | | 3P |
| PW100-72-21403 | 72-01-50 | Red.Gearbox Scavenge Pump Housing | PWC | SB | 10.04.95 | 2 23.01.01 | SB 21403 | O | | | 3P |
| PW100-72-21404 | 72-01-10 | Electrical Wiring Harness a.Bracket | PWC | SB | 04.04.95 | 1 14.11.95 | SB 21404 | O | | | 3P |
| PW100-72-21405 | 72-03-00 | High Pressure Centrifugal Impeller | PWC | SB | 28.03.95 | 1 12.02.97 | SB 21405 | O | | | 3P |
| PW100-72-21406 | | Repl.of Keywashers | PWC | SB | 10.10.95 | 2 18.10.16 | SB 21406 | O | | | 3P |
| PW100-72-21408 | 72-00-21 | Electronic Engine Control | PWC | SB | 28.04.95 | 1 22.06.95 | SB 21408 | O | | | 3P |
| PW100-72-21410 | 72-03-00 | High Pressure Centrifugal Impeller | PWC | SB | 27.04.95 | 1 04.03.96 | SB 21410 | O | | | 3P |
| PW100-72-21412 | 72-03-00 | High Pressure Impeller Shroud Bolts | PWC | SB | 07.07.95 | | SB 21412 | O | | | 3P |
| PW100-72-21414 | 72-03-00 | High Pressure Centrifugal Impeller | PWC | SB | 29.06.95 | 1 10.02.17 | SB 21414 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| PW100-72-21416 | 72-50-02 | Fuel Drain Gasket | PWC | SB | 13.11.95 | | SB 21416 | O | | | 3P |
| PW100-72-21418 | 72-00-00 | Repl.of Ignition Exciter | PWC | SB | 29.06.95 | 1 08.02.96 | SB 21418 | O | | | 3P |
| PW100-72-21419 | 72-5X-0X | Replacement of Power Turbine Blade | PWC | SB | 21.09.95 | 5 08.05.18 | SB 21419 | O | | | 3P |
| PW100-72-21420 | 72-00-00 | Repl.of Electrical Wiring Harnes | PWC | SB | 29.05.95 | 3 02.02.96 | SB 21420 | O | | | 3P |
| PW100-72-21423 | 72-10-00 | Rework of Reduction Gearbox Mounting Pad | PWC | SB | 16.06.95 | 9 28.11.17 | SB 21423 | O | | | 3P |
| PW100-72-21424 | 72-01-40 | Repl.of Fuel Heater Thermal Element | PWC | SB | 30.08.95 | | SB 21424 | O | | | 3P |
| PW100-72-21426 | 72-31-00 | Repl.of No. 5 Bearing | PWC | SB | 17.07.95 | | SB 21426 | O | | | 3P |
| PW100-72-21427 | 72-00-00 | Introd.of Sleeve Spacers | PWC | SB | 27.07.95 | 1 14.03.96 | SB 21427 | O | | | 3P |
| PW100-72-21428 | | Repl.of Bolts | PWC | SB | 23.11.95 | | SB 21428 | O | | | 3P |
| PW100-72-21429 | 72-01-40 | Fuel Manifold Adapter Assy | PWC | SB | 18.06.96 | 3 04.12.97 | SB 21429 | O | | | 3P |
| PW100-72-21433 | 72-03-00 | Repl.of Low Pressure Diffuser Case | PWC | SB | 27.07.95 | | SB 21433 | O | | | 3P |
| PW100-72-21436 | 72-01-50 | No. 6&7 Oil Pressure Tube Clamps | PWC | SB | 29.02.96 | | SB 21436 | O | | | 3P |
| PW100-72-21438 | 72-50-00 | High Pressure Turbine Front Cover | PWC | SB | 06.09.95 | | SB 21438 | O | | | 3P |
| PW100-72-21445 | 72-01-40 | Steward Warner Fuel Heater | PWC | SB | 14.09.95 | 1 30.05.97 | SB 21445 | O | | | 3P |
| PW100-72-21446 | 72-20-00 | Accessory Drive Spur Gearshaft | PWC | SB | 15.02.96 | 4 26.11.09 | SB 21446 | O | | | 3P |
| PW100-72-21452 | 72-50-00 | Insp. of Power Turbine Blades | PWC | SB | 05.12.95 | 3 09.06.16 | SB 21452 | O | | | 3P |
| PW100-72-21453 | 7x-xx-00 | Modification of No. 4 Bearing Area | PWC | SB | 16.05.96 | 3 11.05.18 | SB 21453 | O | | | 3P |
| PW100-72-21454 | 72-20-00 | Seal Carrier Asbestos Gasket | PWC | SB | 22.02.96 | | SB 21454 | O | | | 3P |
| PW100-72-21461 | 72-01-10 | Electr.Wiring Harness Contact Enhancer | PWC | SB | 05.12.95 | 5 15.09.15 | SB 21461 | O | | | 3P |
| PW100-72-21464 | 72-00-00 | Repl.of Electrical Wiring Harness | PWC | SB | 05.02.96 | 1 07.10.96 | SB 21464 | O | | | 3P |
| PW100-72-21465 | 72-10-01 | Repl.of Accessory Drive Cover | PWC | SB | 13.02.96 | | SB 21465 | O | | | 3P |
| PW100-72-21466 | 72-00-21 | PW119C Engine To PW119B Engine | PWC | SB | 19.02.96 | 1 16.06.16 | SB 21466 | O | | | 3P |
| PW100-72-21467 | 72-03-00 | Front Inner Vane Ring Supp. Housing | PWC | SB | 10.03.97 | 2 27.08.01 | SB 21467 | O | | | 3P |
| PW100-72-21470 | 72-00-00 | Accumulator-To-Tee Vent Tube | PWC | SB | 03.04.96 | 1 27.05.96 | SB 21470 | O | | | 3P |
| PW100-72-21472 | 72-40-00 | No. 5 Flanged Roller Bearing Assy | PWC | SB | 14.05.96 | 2 25.02.99 | SB 21472 | O | | | 3P |
| PW100-72-21473 | 72-31-00 | No. 5 Flanged Roller Bearing Assy | PWC | SB | 12.06.96 | 2 25.02.99 | SB 21473 | O | | | 3P |
| PW100-72-21474 | 72-01-10 | Repl.of Torque Signal Conditioner Unit | PWC | SB | 15.03.96 | | SB 21474 | O | | | 3P |
| PW100-72-21475 | 72-20-00 | Seal Carrier Asbestos Gasket | PWC | SB | 24.02.96 | | SB 21475 | O | | | 3P |
| PW100-72-21476 | 72-20-00 | Modif.of Seal Carrier Adapter | PWC | SB | 26.03.96 | 2 29.01.04 | SB 21476 | O | | | 3P |
| PW100-72-21480 | 72-50-01 | Power Turbine Retaining Ring | PWC | SB | 08.04.96 | | SB 21480 | O | | | 3P |
| PW100-72-21481 | 72-01-50 | Main Pressure Pump Housing | PWC | SB | 16.04.96 | | SB 21481 | O | | | 3P |
| PW100-72-21482 | 72-40-00 | Oil Nozzle Strainer Element Assy | PWC | SB | 09.04.96 | | SB 21482 | O | | | 3P |
| PW100-72-21483 | 79-21-00 | Oil Pump Pressure Relief Valve Housing | PWC | SB | 16.05.96 | 1 06.01.99 | SB 21483 | O | | | 3P |
| PW100-72-21484 | 72-50-01 | Repl.of Interturbine Air Seal | PWC | SB | 07.05.96 | | SB 21484 | O | | | 3P |
| PW100-72-21485 | 72-00-31 | Repl.of P2.5 Check Valve | PWC | SB | 27.05.96 | | SB 21485 | O | | | 3P |
| PW100-72-21486 | 72-00-31 | New Intercompressor Case Assy | PWC | SB | 10.07.96 | 1 25.03.03 | SB 21486 | O | | | 3P |
| PW100-72-21489 | 72-00-00 | Reduction Gearbox Identification Plate | PWC | SB | 11.09.96 | | SB 21489 | O | | | 3P |
| PW100-72-21490 | 72-31-00 | Repl.of No. 4 Bearing Keywasher | PWC | SB | 09.07.96 | 3 10.06.97 | SB 21490 | O | | | 3P |
| PW100-72-21492 | 72-01-10 | Repl.of Engine Electronic Control | PWC | SB | 12.06.96 | 1 23.02.97 | SB 21492 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| PW100-72-21494 | 72-00-21 | PW119B Engine to PW119C Engine | PWC | SB | 28.06.96 | | SB 21494 | O | | | 3P |
| PW100-72-21495 | 72-4X-00 | Modification of Gas Generator Case | PWC | SB | 04.11.96 | 4 10.05.18 | SB 21495 | O | | | 3P |
| PW100-72-21505 | 72-10-00 | Cover Assy - Accessory Gearbox | PWC | SB | 18.09.96 | | SB 21505 | O | | | 3P |
| PW100-72-21509 | 72-4x-00 | Modificaton of Gas Generator Case | PWC | SB | 30.01.97 | 6 07.12.17 | SB 21509 | O | | | 3P |
| PW100-72-21512 | 72-10-00 | Repl. of Propeller Shaft | PWC | SB | 24.10.96 | 3 15.06.16 | SB 21512 | O | | | 3P |
| PW100-72-21516 | 72-01-40 | Repl. of Fuel Manifold Transfer Tubes | PWC | SB | 14.08.97 | | SB 21516 | O | | | 3P |
| PW100-72-21518 | 72-00-51 | HPT Stubshaft Plain Round Nut | PWC | SB | 14.11.96 | | SB 21518 | O | | | 3P |
| PW100-72-21519 | 72-00-00 | Fuel Heater w.New Thermal Element | PWC | SB | 11.11.96 | 6 11.01.16 | SB 21519 | O | | | 3P |
| PW100-72-21521 | 72-03-00 | Replacement of Bolts | PWC | SB | 30.01.97 | 1 10.05.99 | SB 21521 | O | | | 3P |
| PW100-72-21523 | 72-00-00 | Repl.of Identification Support Plate | PWC | SB | 03.03.97 | | SB 21523 | O | | | 3P |
| PW100-72-21524 | 72-20-00 | No. 2 Bearing Housing Assy | PWC | SB | 19.12.96 | 2 13.04.99 | SB 21524 | O | | | 3P |
| PW100-72-21526 | 72-10-00 | Repl.of Propeller Shaft Seal | PWC | SB | 21.10.96 | 3 28.06.00 | SB 21526 | O | | | 3P |
| PW100-72-21529 | 72-01-50 | Repl.of Oil Level Indicator | PWC | SB | 11.11.96 | | SB 21529 | O | | | 3P |
| PW100-72-21534 | 72-30-00 | Repl.of Oil Pressure Strainer Element | PWC | SB | 18.11.96 | | SB 21534 | O | | | 3P |
| PW100-72-21535 | 72-01-40 | Modif.of Fuel Manifold Adapters | PWC | SB | 06.02.97 | 10 29.02.16 | SB 21535 | O | | | 3P |
| PW100-72-21537 | 72-50-04 | HP Rotor Balancing Assy No. 5 Bearing | PWC | SB | 05.02.97 | | SB 21537 | O | | | 3P |
| PW100-72-21544 | 72-30-00 | No. 3&4 Multiple Oil Jet Nozzle Assy | PWC | SB | 16.07.97 | 2 14.03.05 | SB 21544 | O | | | 3P |
| PW100-72-21546 | 72-50-00 | NL Pulse Pick-Up Probe Packing and HP Impeller Shroud Packing | PWC | SB | 20.01.98 | 3 30.08.17 | SB 21546 | O | | | 3P |
| PW100-72-21547 | 72-01-50 | Red.Gearb.Scavenge Filter Bypass Valve | PWC | SB | 03.10.97 | | SB 21547 | O | | | 3P |
| PW100-72-21548 | 72-01-60 | T6 Thermocouple Negative Bus Bar | PWC | SB | 25.11.97 | 1 26.01.99 | SB 21548 | O | | | 3P |
| PW100-72-21549 | 72-01-40 | Fuel Manifold Drain Transfer Tube | PWC | SB | 18.09.97 | | SB 21549 | O | | | 3P |
| PW100-72-21554 | 72-50-00 | Repl.of High Pressure Turbine Stubshaft | PWC | SB | 03.10.97 | 1 29.01.98 | SB 21554 | O | | | 3P |
| PW100-72-21556 | 72-01-20 | Repl.of Igniter Plug | PWC | SB | 21.10.97 | | SB 21556 | O | | | 3P |
| PW100-72-21566 | 72-20-00 | Repl.of Front Inlet Case | PWC | SB | 11.06.98 | 1 15.11.01 | SB 21566 | O | | | 3P |
| PW100-72-21568 | 72-00-00 | Engine/Turbomach. Module Identif.Plate | PWC | SB | 02.03.98 | | SB 21568 | O | | | 3P |
| PW100-72-21571 | 72-03-00 | Repl.of.Rear Inlet Case Assy | PWC | SB | 23.03.98 | 4 06.03.17 | SB 21571 | O | | | 3P |
| PW100-72-21572 | 72-50-00 | Power Turbine Blade | PWC | SB | 19.06.98 | | SB 21572 | O | | | 3P |
| PW100-72-21573 | 72-10-02 | Repl.of Layshaft Cover | PWC | SB | 27.10.98 | | SB 21573 | O | | | 3P |
| PW100-72-21574 | 72-22-00 | Main Pressure Pump Housing Assy | PWC | SB | 02.07.98 | 2 04.09.14 | SB 21574 | O | | | 3P |
| PW100-72-21575 | 72-50-04 | High Pressure Turbine Front Cover | PWC | SB | 03.06.98 | 1 24.01.01 | SB 21575 | O | | | 3P |
| PW100-72-21576 | 72-10-00 | Modif.of Propeller Shaft | PWC | SB | 10.06.98 | 6 15.07.16 | SB 21576 | O | | | 3P |
| PW100-72-21577 | 72-01-40 | Adaper Assy,Fuel Pump-To-Rear Inlet Case | PWC | SB | 05.06.98 | 1 01.04.17 | SB 21577 | O | | | 3P |
| PW100-72-21578 | 72-50-01 | Power Turbine Balancing Shaft Assy | PWC | SB | 03.06.98 | | SB 21578 | O | | | 3P |
| PW100-72-21582 | 79-31-00 | Oil-Press.-Differ.Autom.-Reset Switch | PWC | SB | 14.09.98 | 1 24.11.98 | SB 21582 | O | | | 3P |
| PW100-72-21583 | 75-41-00 | Oversp.-Govern.Press.-Sensing Tube Assy | PWC | SB | 14.09.98 | | SB 21583 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| PW100-72-21586 | 72-20-00 | Repl.of Front Inlet Case | PWC | SB | 24.06.99 | 1 16.11.01 | SB 21586 | O | | | 3P |
| PW100-72-21587 | 72-10-02 | Repl.of Layshaft Cover | PWC | SB | 27.10.98 | | SB 21587 | O | | | 3P |
| PW100-72-21596 | 72-40-00 | Outer Combustion-Chamber-Liner-Assy | PWC | SB | 08.01.98 | 1 10.08.01 | SB 21596 | O | | | 3P |
| PW100-72-21598 | 72-40-00 | Outer Combustion-Chamber-Liner-Assy | PWC | SB | 14.01.99 | 2 15.02.00 | SB 21598 | O | | | 3P |
| PW100-72-21599 | 72-01-40 | Hydromechanical Fuel Control | PWC | SB | 01.04.99 | 1 14.04.99 | SB 21599 | O | | | 3P |
| PW100-72-21600 | 72-40-00 | Non-S./Symmetr.Gas Generator Case Assy | PWC | SB | 25.02.99 | | SB 21600 | O | | | 3P |
| PW100-72-21602 | 73-11-00 | Repl./Modif.of Fuel Pump | PWC | SB | 18.02.99 | | SB 21602 | O | | | 3P |
| PW100-72-21603 | 72-01-50 | Introd.of Oil Level Decal | PWC | SB | 15.03.99 | 3 22.01.02 | SB 21603 | O | | | 3P |
| PW100-72-21604 | 72-10-00 | Repl.of Reduction-Gearbox Input-Shaft | PWC | SB | 16.03.99 | 1 07.04.99 | SB 21604 | O | | | 3P |
| PW100-72-21605 | 72-40-00 | Combustion-Chamber-Liner-Assy | PWC | SB | 14.05.99 | 3 20.11.03 | SB 21605 | O | | | 3P |
| PW100-72-21616 | 72-11-00 | Introd.of Ground Coil Inserts | PWC | SB | 08.09.99 | 2 10.08.01 | SB 21616 | O | | | 3P |
| PW100-72-21618 | 72-50-02 | Turbine-Interstage-Case-Assy Bolts | PWC | SB | 31.08.99 | 5 08.10.19 | SB 21618 | O | | | 3P |
| PW100-72-21619 | 72-10-00 | No. 9 Bearing Key Washer | PWC | SB | 10.08.99 | 1 28.06.01 | SB 21619 | O | | | 3P |
| PW100-72-21620 | 72-40-00 | High-Press.-Turbine Vane-Ring-Segments | PWC | SB | 26.10.99 | 3 11.01.16 | SB 21620 | O | | | 3P |
| PW100-72-21621 | 72-40-00 | Repl.of Oil Nozzle Strainer Element Assy | PWC | SB | 28.07.99 | 2 19.06.16 | SB 21621 | O | | | 3P |
| PW100-72-21622 | 72-50-02 | Modification/replacement Of Power-turbine-stator Assembly (first Stage) | PWC | SB | 31.08.99 | 5 05.04.17 | SB 21622 | O | | | 3P |
| PW100-72-21623 | 72-50-02 | Turbine-Interstage-Case Assy Flange | PWC | SB | 31.08.99 | 1 09.09.10 | SB 21623 | O | | | 3P |
| PW100-72-21624 | 72-40-00 | Combustion Chamber Inner Liner Assy | PWC | SB | 26.01.00 | | SB 21624 | O | | | 3P |
| PW100-72-21628 | 72-01-50 | RGB-Scavenge-Pump Idler-Shaft | PWC | SB | 27.09.99 | 1 17.10.19 | SB 21628 | O | | | 3P |
| PW100-72-21629 | 72-40-00 | Repl.of Small Exit Duct Assy | PWC | SB | 31.01.00 | | SB 21629 | O | | | 3P |
| PW100-72-21630 | 72-01-40 | Repair of Waste Fuel Ejector | PWC | SB | 24.11.99 | | SB 21630 | O | | | 3P |
| PW100-72-21635 | 72-30-00 | Low Pressure Diffuser Case Assy | PWC | SB | 15.11.99 | 2 24.03.17 | SB 21635 | O | | | 3P |
| PW100-72-21639 | | Introduction of Corrosion Inhibitors | PWC | SB | 20.04.00 | 7 20.10.11 | SB 21639 | O | | | 3P |
| PW100-72-21641 | | Introd.of Mobil 291 Oil | PWC | SB | 03.05.00 | 4 04.07.07 | SB 21641 | O | | | 3P |
| PW100-72-21647 | 72-11-00 | Repl.of Propeller Shaft Seal | PWC | SB | 28.06.00 | | SB 21647 | O | | | 3P |
| PW100-72-21649 | 72-01-20 | Repl.of Igniter Plug | PWC | SB | 16.10.00 | 2 26.07.02 | SB 21649 | O | | | 3P |
| PW100-72-21653 | | Mod./Repl.of Electronic Engine Control | PWC | SB | 26.01.01 | 1 17.06.03 | SB 21653 | O | | | 3P |
| PW100-72-21656 | 72-50-01 | Repl.of Power Turbine Stator Assy | PWC | SB | 11.04.01 | 2 09.07.19 | SB 21656 | O | | | 3P |
| PW100-72-21657 | 72-00-00 | Repl.of Waste Fuel Ejector | PWC | SB | 27.04.01 | | SB 21657 | O | | | 3P |
| PW100-72-21659 | 72-50-02 | Low Pressure Turbine Stator | PWC | SB | 10.04.01 | 1 14.04.03 | SB 21659 | O | | | 3P |
| PW100-72-21660 | 72-50-04 | Interstage Air Seal Assy a. Abradable Seals | PWC | SB | 28.06.01 | 3 15.06.04 | SB 21660 | O | | | 3P |
| PW100-72-21662 | 72-01-04 | Repl.of Hydromechanical Fuel Control | PWC | SB | 03.08.01 | 2 16.12.04 | SB 21662 | O | | | 3P |
| PW100-72-21665 | 70-40-00 | No.5 Bearing Housing Cover Retr.Bolts | PWC | SB | 30.07.01 | | SB 21665 | O | | | 3P |
| PW100-72-21666 | 72-50-01 | Repl.of No.2 Bearing Labyrinth Seal | PWC | SB | 02.08.01 | | SB 21666 | O | | | 3P |
| PW100-72-21675 | | Repl.of Protective Cap and Plug | PWC | SB | 20.11.01 | 2 12.10.12 | SB 21675 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| PW100-72-21677 | 72-01-10 | Insp./Rep.of Electronic Eng.Control (EEC) | PWC | SB | 22.11.01 | | SB 21677 | O | | | 3P |
| PW100-72-21678 | | Repl./Modif.of Shipping Container Skid Base | PWC | SB | 16.10.02 | | SB 21678 | O | | | 3P |
| PW100-72-21679 | 72-01-50 | Intercompressor Case Drain Tube | PWC | SB | 15.01.02 | 3 11.04.16 | SB 21679 | O | | | 3P |
| PW100-72-21680 | 72-30-00 | Fluorocarbon Preformed Packing | PWC | SB | 15.01.02 | 2 02.05.17 | SB 21680 | O | | | 3P |
| PW100-72-21681 | 72-10-00 | Alternator Drive Gearshaft Plain Seal | PWC | SB | 22.03.02 | 4 31.08.18 | SB 21681 | O | | | 3P |
| PW100-72-21683 | 72-50-00 | Replacement HPT Stub Shaft | PWC | SB | 07.05.02 | 1 14.01.04 | SB 21683 | O | | | 3P |
| PW100-72-21686 | 72-01-60 | Repl.of T6 Thermocouple and Adapter | PWC | SB | 20.06.02 | 4 30.01.06 | SB 21686 | O | | | 3P |
| PW100-72-21691 | 27-30-00 | Repl.of Intercompressor Case Insert | PWC | SB | 15.01.03 | 3 12.12.06 | SB 21691 | O | | | 3P |
| PW100-72-21702 | 72-01-40 | Insp.of Fuel Pump Filter Element | PWC | SB | 11.02.04 | 1 21.07.04 | SB 21702 | O | | | 3P |
| PW100-72-21703 | 72-50-04 | Repl.of Stubshaft Retaining Nut | PWC | SB | 18.02.04 | 1 10.03.04 | SB 21703 | O | | | 3P |
| PW100-72-21706 | | Repl.of Oil Nozzle Strainer Element Assembly | PWC | SB | 10.05.04 | | SB 21706 | O | | | 3P |
| PW100-72-21713 | | Inspection of Propeller Shaft | PWC | SB | 20.12.04 | | SB 21713 | O | | | 3P |
| PW100-72-21714 | | Field Insp. And Repl.of Propeller Shaft | PWC | SB | 20.12.04 | 2 20.05.05 | SB 21714 | O | | | 3P |
| PW100-72-21718 | | Repl.of Intercompressor Bleed Valve Filt.System | PWC | SB | 02.12.05 | 1 08.08.08 | SB 21718 | O | | | 3P |
| PW100-72-21720 | | Inspection of Oil Tank Filler Cap | PWC | SB | 25.05.05 | 4 30.05.16 | SB 21720 | O | | | 3P |
| PW100-72-21721 | | Repl.of Fuel Pump Filter Element | PWC | SB | 24.08.05 | 1 03.11.05 | SB 21721 | O | | | 3P |
| PW100-72-21724 | | Insp.of Power Turbine Stator Assembly | PWC | SB | 31.10.05 | | SB 21724 | O | | | 3P |
| PW100-72-21725 | | Repl./Mod.of First Stage Power Turb.Disk Set | PWC | SB | 22.12.05 | 1 18.02.06 | SB 21725 | O | | | 3P |
| PW100-72-21729 | | Repl.of Gas Generator Case | PWC | SB | 24.08.06 | 4 07.11.08 | SB 21729 | O | | | 3P |
| PW100-72-21737 | | Repl./Mod.of Power Turb.Stator Assy | PWC | SB | 08.11.06 | 5 17.09.18 | SB 21737 | O | | | 3P |
| PW100-72-21738 | | Repl./Mod.of Bleed Valve Air Supply Tube Assy | PWC | SB | 10.11.06 | | SB 21738 | O | | | 3P |
| PW100-72-21739 | | Intro.of Metal Seal at Shaft No.6&7Bear.Hous.Assy | PWC | SB | 25.01.07 | 2 06.12.18 | SB 21739 | O | | | 3P |
| PW100-72-21740 | | Stock Repl.of Preformed Packing | PWC | SB | 28.02.07 | 3 31.05.07 | SB 21740 | O | | | 3P |
| PW100-72-21746 | | Replacement of Seal Ring, Metal | PWC | SB | 29.08.07 | 1 19.07.11 | SB 21746 | O | | | 3P |
| PW100-72-21748 | | Repl.of Interturbine Duct Insulation Blanket | PWC | SB | 18.09.07 | | SB 21748 | O | | | 3P |
| PW100-72-21755 | | Repl.of Pref.Pack.for Fluoroloy Seals P2.5Transf.Tube | PWC | SB | 20.12.07 | 3 09.06.16 | SB 21755 | O | | | 3P |
| PW100-72-21758 | 72-50-01 | Repl. of Power Turb. Balance with an improved Coating | PWC | SB | 13.12.73 | 5 25.11.13 | SB 21758 | O | | | 3P |
| PW100-72-21759 | | Repl.of Oil Tank Filler cap | PWC | SB | 21.12.07 | 1 05.02.15 | SB 21759 | O | | | 3P |
| PW100-72-21765 | | Repl.of No. 9 Bearing Keywasher | PWC | SB | 12.02.08 | 9 23.07.19 | SB 21765 | O | | | 3P |
| PW100-72-21766 | | Insp.of First Stage Power Turbine Blade | PWC | SB | 13.03.08 | 4 25.07.17 | SB 21766 | O | | | 3P |
| PW100-72-21774 | | Reduction Gearbox Firts Stage Gear - Borescope Inspection | PWC | SB | 27.01.09 | 2 06.07.09 | SB 21774 | O | | Cancellation of ModelsPW119B&C | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| PW100-72-21777 | | Repl.of HP and LP Compressor Centrifugal Impeller | PWC | SB | 04.06.09 | 9 09.10.16 | SB 21777 | O | | | 3P |
| PW100-72-21783 | | Replacement of Chip Detectors | PWC | SB | 21.10.09 | | SB 21783 | O | | | 3P |
| PW100-72-21791 | 72-01-30 | Replacement of Intercompressor Bleed Valve Assembly (HBOV) | PWC | SB | 20.10.10 | 1 08.08.16 | SB 21791 | O | | | 3P |
| PW100-72-21798 | 72-10-00 | Replacement of Propeller Shaft | PWC | SB | 23.03.11 | 2 15.06.11 | SB 21798 | O | | | 3P |
| PW100-72-21808 | 72-01-40 | Replacement of Fuel Pump | PWC | SB | 23.12.11 | 5 19.08.19 | SB 21808 | O | | | 3P |
| PW100-72-21809 | | Replacement of Power Turbine Balancing Shaft Assembly | PWC | SB | 04.01.12 | | SB 21809 | O | | | 3P |
| PW100-72-21811 | 72-01-30 | Replacement of Intercompressor Bleed Valve Assembly (IBV) | PWC | SB | 01.02.10 | 4 27.09.16 | SB 21811 | O | | | 3P |
| PW100-72-21812 | | Inspection of Fuel Oil Heat Exchanger | PWC | SB | 04.02.13 | 1 03.11.15 | SB 21812 | O | | | 3P |
| PW100-72-21816 | 72-50-02 | Replacement of Turboprop Engine Nut (IC) Otion | PWC | SB | 01.11.12 | | SB 21816 | O | | | 3P |
| PW100-72-21820 | 7X-XX-XX | Replacement of Pick-Up Probe, Pulse | PWC | SB | 04.09.12 | 1 18.07.18 | SB 21820 | O | | | 3P |
| PW100-72-21821 | 72-50-01 | Replacement of Power Turbine Balancing Shaft Assembly | PWC | SB | 01.11.12 | | SB 21821 | O | | | 3P |
| PW100-72-21823 | 72-50-01 | Repl. of First Stage Power Turbine Blades - Inspection | PWC | SB | 27.09.12 | 3 08.03.13 | SB 21823 | O | | | 3P |
| PW100-72-21825 | 72-40-00 | Inspection of Gas Generator Case Assembly | PWC | SB | 17.09.13 | 2 23.05.19 | SB 21825 | O | | | 3P |
| PW100-72-21828 | 72-XX-XX | Inspection / Replacement of Engine First Stage Power Turbine Blade | PWC | SB | 19.02.13 | 3 27.05.14 | SB 21828 | O | | | 3P |
| PW100-72-21831 | 72-50-01 | Replacement of Power Turbine Balancing Shaft Assembly (IC) | PWC | SB | 18.02.13 | | SB 21831 | O | | | 3P |
| PW100-72-21834 | 72-50-01 | Inspection / Repl. of Power Turbine Balancing Shaft | PWC | SB | 12.02.14 | 1 05.05.17 | SB 21834 | O | | | 3P |
| PW100-72-21846 | 72-00-00 | Replacement of Shipping Container Caps | PWC | SB | 07.07.14 | | SB 21846 | O | | | 3P |
| PW100-72-21853 | 72-50-01 | Replacement of Power Turbine Disk Assembly | PWC | SB | 06.11.13 | 2 18.11.15 | SB 21853 | O | | | 3P |
| PW100-72-21863 | 72-50-01 | Inpection/Replacement of First Stage Power Turbine Blades | PWC | SB | 11.07.14 | 3 07.05.18 | SB 21863 | O | | | 3P |
| PW100-72-21864 | 72-50-01 | Replacement of Power Turbine Stator Assmebly and Vane Ring | PWC | SB | 05.12.14 | 2 10.10.17 | SB 21864 | O | | | 3P |
| PW100-72-21865 | 72-5X-XX | Replacement of Power Turbine Stator Retaining Rings | PWC | SB | 17.11.14 | 4 06.10.17 | SB 21865 | O | | | 3P |
| PW100-72-21866 | 72-01-50 | Replacement of Ring Spacer | PWC | SB | 16.12.14 | 2 06.10.17 | SB 21866 | O | | | 3P |
| PW100-72-21870 | 72-5X-XX | Replacement of Power Turbine Stator Assembly | PWC | SB | 18.02.15 | 4 06.10.17 | SB 21870 | O | | | 3P |
| PW100-72-21873 | 72-4x-00 | Replacement of Gas Generator Case | PWC | SB | 30.04.15 | 2 06.10.17 | SB 21873 | O | | | 3P |
| PW100-72-21874 | 72-01-40 | Inspection/Replacement of Fuel Oil Heat Exchanger (FOHE) | PWC | SB | 13.05.15 | 5 17.01.19 | SB 21874 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| PW100-72-21876 | 72-5X-0X | Replacement of Second Stage Power Turbine Blades | PWC | SB | 24.07.15 | 3 27.10.17 | SB 21876 | O | | | 3P |
| PW100-72-21879 | 72-XX-XX | Replacement of Low Pressure Impeller Nut | PWC | SB | 16.09.15 | 1 06.10.17 | SB 21879 | O | | | 3P |
| PW100-72-21882 | 72-XX-XX | POWER TURBINE DISK ASSEMBLY - REPLACEMENT | PWC | SB | 18.11.15 | 1 03.06.21 | SB 21882 | O | | | 3P |
| PW100-72-21884 | 72-5X-0X | Replacement of Metal Seal Ring | PWC | SB | 20.10.15 | 2 06.10.17 | SB 21884 | O | | | 3P |
| PW100-72-21902 | 72-4X-00 | Replacement of Gas Generator Case Thermal Insulation Blanket Segments | PWC | SB | 21.07.16 | 3 11.12.18 | SB 21902 | O | | | 3P |
| PW100-72-21903 | 72-2X-00 | Introduction of Bearing Option (IC) | PWC | SB | 20.06.16 | 1 06.10.17 | SB 21903 | O | | | 3P |
| PW100-72-21911 | | Turboprop Engine T6 Thermocouple Trim Lug-Mounted Resistor | PWC | SB | 11.07.17 | | SB 21911 | O | | | 3P |
| PW100-72-21916 | 7X-XX-XX | Inspection/Replacement of Turboprop Engine T6 Terminal Block | PWC | SB | 29.01.19 | 1 29.03.19 | SB 21916 | O | | | 3P |
| PW100-72-21917 | 72-50-01 | Replacement/Modification of Second Stage Power Turbine (PT) Blades | PWC | SB | 15.11.17 | 7 20.03.19 | SB 21917 | O | | | 3P |
| PW100-72-21918 | 72-40-00 | Replacement of High Pressure Turbine Vane Ring Segments | PWC | SB | 20.07.18 | 6 10.02.20 | SB 21918 | O | | | 3P |
| PW100-72-21923 | 72-5x-xx | Replacement/Modification of Interstage air seals | PWC | SB | 18.06.18 | 2 15.05.19 | SB 21923 | O | | | 3P |
| PW100-72-21932 | 72-5x-xx | Replacement of LP Turbine Vane Ring | PWC | SB | 09.09.20 | 1 20.10.20 | SB 21932 | O | | | 3P |
| PW100-72-21935 | 72-3x-xx | Introd.of Low Pressure Diffuser Case (IC) | PWC | SB | 13.02.19 | | SB 21935 | O | | | 3P |
| PW100-72-21936 | 72-30-00 | Replacement of Upper Towershaft Assembly | PWC | SB | 21.02.19 | 2 12.09.19 | SB 21936 | O | | | 3P |
| PW100-72-21943 | 72-5x-xx | Replacement of Turboprop Engine No 6 Bearing Rotor Air Seal Assembly | PWC | SB | 07.06.19 | 1 24.03.20 | SB 21943 | O | | | 3P |
| PW100-72-21956 | 72-03-00 | Inspection of Second Stage Power Turbine Blades | PWC | SB | 07.12.20 | | SB 21956 | O | | | 3P |
| PW100-72-21957 | 72-30-00 | Replacement of Turboprop Engine Intercompressor and Gas Gen Case Transfer Tube | PWC | SB | 02.02.21 | 3 31.08.21 | SB 21957 | O | | | 3P |
| PW100-72-21958 | 72-50-01 | Inspection of Turboprop Engine Igniter Plug with Incorrect Terminal | PWC | SB | 25.05.21 | 1 02.06.21 | SB 21958 | O | | | 3P |
| PW100-72-21959 | 72-5X-XX | Replacement/Modification of Second Stage PT Stator Blades | PWC | SB | 25.02.21 | 4 19.08.22 | SB 21959 | O | | | 3P |
| | | Re-numbering of SIL | PWC | SIL | 02.01.95 | | SIL GEN-001 | O | | | 3A |
| | | Turbine Blade Riveting Qlty.Control | PWC | SIL | 09.03.95 | 2 22.02.99 | SIL GEN-005 | O | | | 3A |
| | | FAA STC and Similar Procedures | PWC | SIL | 30.05.95 | 3 25.04.02 | SIL GEN-013 | O | | | 3A |
| | | Material Return Requests | PWC | SIL | 23.04.96 | 2 23.11.20 | SIL GEN-015 | O | | | 3A |
| | | Basic Unplanned Removals Warranty | PWC | SIL | 01.06.95 | | SIL GEN-016 | O | | | 3A |
| | | Service Bulletin Compliance Code | PWC | SIL | 30.04.98 | | SIL GEN-018 | O | | | 3A |
| | | Vane Rings Airflow Rig Correlation | PWC | SIL | 01.08.95 | 6 27.09.21 | SIL GEN-020 | O | | | 3A |
| | | Borescope Equipment | PWC | SIL | 11.09.95 | | SIL GEN-021 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | PWC Service Tool Procurement | PWC | SIL | 28.08.95 | 11 27.04.20 | SIL GEN-022 | O | | | 3A |
| | | Install. Fuel, Oil and Pneum.Tube | PWC | SIL | 12.12.95 | 1 18.01.00 | SIL GEN-026 | O | | | 3A |
| | | P&WC´S 24-Hour Global Service | PWC | SIL | 10.04.02 | 4 12.07.13 | SIL GEN-027 | O | | | 3A |
| | | New phone-/faxnumbers for P&WC Cust.Train. | PWC | SIL | 11.09.98 | | SIL GEN-028 | O | | | 3A |
| | | Ozone Depleting Substances | PWC | SIL | 29.11.95 | | SIL GEN-029 | O | | | 3A |
| | | Amended SB Compliance Statements | PWC | SIL | 11.12.95 | 3 21.08.17 | SIL GEN-030 | O | | | 3A |
| | | Stolen Parts | PWC | SIL | 11.09.98 | 1 10.11.12 | SIL GEN-031 | O | | | 3A |
| | | Fuel Anti-Icing Additive | PWC | SIL | 05.02.96 | 1 28.03.96 | SIL GEN-032 | O | | | 3A |
| | | Hardtime Inspection intervals | PWC | SIL | 19.06.98 | 3 10.11.12 | SIL GEN-034 | O | | | 3A |
| | | Relocation of Support Offices | PWC | SIL | 26.07.96 | | SIL GEN-035 | O | | | 3A |
| | | Use of Non PWC Supported Parts | PWC | SIL | 22.10.99 | 3 10.11.12 | SIL GEN-038 | O | | | 3A |
| | | Engine Warranty and Service Polic | PWC | SIL | 10.02.98 | 1 01.03.17 | SIL GEN-039 | O | | | 3A |
| | | Fuel Nozzle Adapter Packing Lubricant | PWC | SIL | 11.09.03 | 2 | SIL GEN-040 | O | | | 3A |
| | | Ceramic Fibres | PWC | SIL | 02.09.97 | | SIL GEN-041 | O | | | 3A |
| | | Material return to PWC | PWC | SIL | 03.06.98 | 1 16.10.17 | SIL GEN-044 | O | | | 3A |
| | | Changes to Warranty Claim Process | PWC | SIL | 28.01.98 | 2 16.09.16 | SIL GEN-045 | O | | | 3A |
| | | Warranty Coverage | PWC | SIL | 26.11.98 | 2 13.09.19 | SIL GEN-049 | O | | | 3A |
| | | "Req.for Eval." for comp.exhibit.damage | PWC | SIL | 15.12.98 | | SIL GEN-050 | O | | | 3A |
| | | In Service Experience-Reliability Data | PWC | SIL | 05.02.99 | | SIL GEN-051 | O | | | 3A |
| | | Return of Defective New Material | PWC | SIL | 08.02.99 | 2 16.10.17 | SIL GEN-052 | O | | | 3A |
| | | Accessory PN Identif. And Minus Config. | PWC | SIL | 07.07.00 | | SIL GEN-053 | O | | | 3A |
| | | Availability of CAT Material | PWC | SIL | 27.04.99 | | SIL GEN-054 | O | | | 3A |
| | | Guidelines and Stand. for Util. ECTM-Software | PWC | SIL | 07.01.99 | 10 13.11.18 | SIL GEN-055 | O | | | 3A |
| | | Warranty, Commer.Claims on the Internet | PWC | SIL | 17.08.99 | 1 01.07.00 | SIL GEN-056 | O | | | 3A |
| | | Parts Substitution List (PSL) | PWC | SIL | 23.12.99 | | SIL GEN-057 | O | | | 3A |
| | | Relocation of PWC's U.K.Support Services | PWC | SIL | 30.11.99 | | SIL GEN-058 | O | | | 3A |
| | | Introduction of Life Limited Components | PWC | SIL | 03.02.00 | | SIL GEN-059 | O | | | 3A |
| | | Extranet Access for Service Bulletins | PWC | SIL | 14.02.00 | | SIL GEN-060 | O | | | 3A |
| | | Engine Related Requests | PWC | SIL | 31.03.00 | 10 25.01.21 | SIL GEN-061 | O | | | 3A |
| | | Repl.of Exxon Turbine Oil by Air BP Oils | PWC | SIL | 19.03.01 | | SIL GEN-062 | O | | | 3A |
| | | Publ.Customer Profile Change/Internet | PWC | SIL | 21.05.01 | | SIL GEN-063 | O | | | 3A |
| | | Availabilty of the Report/Index via Internet | PWC | SIL | 14.03.02 | | SIL GEN-064 | O | | | 3A |
| | | Process New Engine Accessory | PWC | SIL | 25.04.02 | | SIL GEN-065 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Modif.of Engines/Modules Shipping Cont. | PWC | SIL | 25.06.02 | | SIL GEN-066 | O | | 3A |
| | | Inst.and Insp.Engine Tube and Hardware | PWC | SIL | 03.06.02 | | SIL GEN-067 | O | | 3A |
| | | P&WC Product Maint.Training In Australia | PWC | SIL | 27.01.03 | | SIL GEN-069 | O | | 3A |
| | | Prefomed Packing - Visual Insp. Requirement | PWC | SIL | 07.03.03 | | SIL GEN-070 | O | | 3A |
| | | Relocation of P&WC Accessories Services | PWC | SIL | 27.10.03 | | SIL GEN-071 | O | | 3A |
| | | SB'S and SPB' Indices via P&WC Web Site | PWC | SIL | 15.10.04 | | SIL GEN-074 | O | | 3A |
| | | 2005 Customer Satisfaction Survey | PWC | SIL | 20.04.05 | | SIL GEN-077 | O | | 3A |
| | | Transfer of Accessory Exchange Pool Support | PWC | SIL | 17.08.06 | | SIL GEN-081 | O | | 3A |
| | | New Phone Numbers for P&WC Pub.Customer Services | PWC | SIL | 17.01.07 | 1 24.01.11 | SIL GEN-082 | O | | 3A |
| | | Change in Customer Responsibilities | PWC | SIL | 05.12.06 | 1 01.09.07 | SIL GEN-083 | O | | 3A |
| | | Parts Dstr.Center in Singapore change in Cust.Service Respons. | PWC | SIL | 21.06.07 | | SIL GEN-084 | O | | 3A |
| | | P&WC Publication Customer Service | PWC | SIL | 12.09.07 | | SIL GEN-086 | O | | 3A |
| | | Advance Notification for Customer Data Research | PWC | SIL | 06.12.07 | | SIL GEN-087 | O | | 3A |
| | | Parts Distribution Center in Australia | PWC | SIL | 20.08.08 | | SIL GEN-089 | O | | 3A |
| | | Jet Fuel Quality | PWC | SIL | 21.07.08 | | SIL GEN-091 | O | | 3A |
| | | Quality Alert - Packing AS3209-009 | PWC | SIL | 01.12.08 | | SIL GEN-092 | O | | 3A |
| | | Engine Storage and Preservation | PWC | SIL | 20.03.09 | 2 22.10.21 | SIL GEN-093 | O | | 3A |
| | | "Baseball Cap" Shipping Covers | PWC | SIL | 14.11.08 | | SIL GEN-100 | O | | 3A |
| | | Certificate of Conformity | PWC | SIL | 09.04.10 | | SIL GEN-101 | O | | 3A |
| | | PWC DPHM Solutions - Change in Customer Support Responsibility | PWC | SIL | 07.06.10 | | SIL GEN-103 | O | | 3A |
| | | Engine Operation in Volcanic Ash Conditions | PWC | SIL | 19.05.10 | 2 27.05.11 | SIL GEN-104 | O | | 3A |
| | | Diagnostics, Prognostics and Health Management ("DPHM") Package | PWC | SIL | 14.07.10 | 5 14.06.18 | SIL GEN-105 | O | | 3A |
| | | Jet Fuel Containing Fatty Acid Methyl Esters (FAME) | PWC | SIL | 24.09.10 | 2 01.11.17 | SIL GEN-108 | O | | 3A |
| | | P&WC Spare Parts Services - Change in aftermarket support responsibilities for specific Packings | PWC | SIL | 22.11.10 | 2 25.10.12 | SIL GEN-109 | O | | 3A |
| | | P&WC Customer Training collaborative agreement with FSI | PWC | SIL | 15.12.10 | 3 19.12.18 | SIL GEN-110 | O | | 3A |
| | | Operation into Radioactive Environments | PWC | SIL | 21.03.11 | | SIL GEN-112 | O | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Proper positioning of locking devices at assembly | PWC | SIL | 09.09.11 | | SIL GEN-113 | O | | | 3A |
| | | Introduction of Export Control markings on Tecnical Publication | PWC | SIL | 21.10.11 | | SIL GEN-115 | O | | | 3A |
| | | Installation of O-Ring in Oil Filter Groove | PWC | SIL | 30.11.11 | 1 19.02.13 | SIL GEN-116 | O | | | 3A |
| | | Warranty Allowance for Consumable Materials | PWC | SIL | 12.03.12 | | SIL GEN-117 | O | | | 3A |
| | | Sale of P&WC A'Asia Pty Ltd (Brisbane) to Vector Aerospace | PWC | SIL | 14.09.15 | 1 14.09.15 | SIL GEN-120 | O | | | 3A |
| | | Mobile Repair Team (MRT) | PWC | SIL | 10.09.12 | | SIL GEN-121 | O | | | 3A |
| | | Recovery Fee for Maintenance Deviation Letters | PWC | SIL | 27.08.12 | 11 29.06.22 | SIL GEN-122 | O | | | 3A |
| | | Qualified Engine Oil Analysis Laboratory List | PWC | SIL | 21.01.13 | 9 14.07.22 | SIL GEN-123 | O | | | 3A |
| | | Material Test Result Findings from Supplier: Carmel Forge | PWC | SIL | 01.03.13 | | SIL GEN-125 | O | | | 3A |
| | | Discontinued Electronic Bulletin Email Delivery Subscriptions | PWC | SIL | 02.07.13 | | SIL GEN-127 | O | | | 3A |
| | | Limited Time for Upgrade of the Data Tranmission Unit | PWC | SIL | 20.11.13 | | SIL GEN-130 | O | | | 3A |
| | | Technical Publication Revision Status | PWC | SIL | 12.11.13 | | SIL GEN-134 | O | | | 3A |
| | | Aviation Accidents / Incidents - Return to Service of affected P&WC Products and the effect on Engine Warranty and Service Policies status | PWC | SIL | 21.02.17 | 1 03.06.21 | SIL GEN-135 | O | | | 3A |
| | | Fuel Nozzle Maintenance Program | PWC | SIL | 29.05.14 | | SIL GEN-137 | O | | | 3A |
| | | Quality Alert - Elbow Tube MS9194-09 | PWC | SIL | 17.07.14 | | SIL GEN-140 | O | | | 3A |
| | | Use of Eastman Chemical Copany (ECC) turbine engine oil in PWC products | PWC | SIL | 28.11.14 | | SIL GEN-141 | O | | | 3A |
| | | Relocation of Technical and Commercial Support Office | PWC | SIL | 14.09.15 | | SIL GEN-142 | O | | | 3A |
| | | P&WC Oil Analysis Technology Trial Program | PWC | SIL | 18.08.16 | 2 09.07.18 | SIL GEN-143 | O | | | 3A |
| | | Use of Approved Fluids in the performance of Engine and Component Maintenance | PWC | SIL | 11.03.16 | | SIL GEN-145 | O | | | 3A |
| | | Transfers, Renewals, and other important navigational tools on the newly integrated MyP&WCPower Portal | PWC | SIL | 04.04.17 | | SIL GEN-148 | O | | | 3A |
| | | Submit a Request (RSVP) on My P&WC Power | PWC | SIL | 22.06.17 | 1 17.08.18 | SIL GEN-149 | O | | | 3A |
| | | AOG parts support contact information | PWC | SIL | 12.06.17 | 1 26.09.17 | SIL GEN-151 | O | | | 3A |
| | | OnSight Video (Virtual Presence) | PWC | SIL | 17.04.18 | | SIL GEN-152 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Disposition of fault Line Replaceable Units (LRU) | PWC | SIL | 09.10.18 | | SIL GEN-154 | O | | | 3A |
| | | Introduction of Hyperlinks in P&WC Service Bulletins | PWC | SIL | 14.06.19 | | SIL GEN-155 | O | | | 3A |
| | | KATHON FP 1.5 Fuel Biocide manufactured by DUPONT | PWC | SIL | 06.08.19 | 2 07.04.20 | SIL GEN-156 | O | | | 3A |
| | | Preservation - Engines Removed from Service on Temprary basis | PWC | SIL | 18.03.20 | | SIL GEN-157 | O | | | 3A |
| | | Handling of Suspected Hexavalent Chromium Residue on Engine Parts During Maintenance, Repair, and Overhaul | PWC | SIL | 20.07.20 | | SIL GEN-158 | O | | | 3A |
| | | Environmentally Assisted Cracking in Certain Aluminium Alloys | PWC | SIL | 08.07.20 | | SIL GEN-159 | O | | | 3A |
| | | Occasional Dust Plume Exposure | PWC | SIL | 30.06.20 | | SIL GEN-160 | O | | | 3A |
| | | Operations in Enviroments Affected by Wildfires, Bushfires and Forest Fires | PWC | SIL | 19.10.20 | | SIL GEN-161 | O | | | 3A |
| | | Removal of AWL Requirement to Mark Parts with Accumulated Cycles and/or Time | PWC | SIL | 03.03.21 | | SIL GEN-163 | O | | | 3A |
| | | Reminder Regarding Schedulde Maintenance Tasks at Engine Shop Visits | PWC | SIL | 23.09.22 | | SIL GEN-168 | O | | | 3A |
| | | 1st Stage Power Turbine Blade Dis | PWC | SIL | 11.11.94 | 4 18.12.14 | SIL PW100-001 | O | | C A N C E L L E D | 3P |
| | | Gas Gen.Case Drain Valve Connector | PWC | SIL | 18.06.97 | 1 05.10.07 | SIL PW100-003 | O | | | 3P |
| | | Engine Overtorque Estimation | PWC | SIL | 16.03.95 | 3 03.06.04 | SIL PW100-007 | O | | | 3P |
| | | Extended Engine service Policy (EESP) / Limited Cost Overhaul (LCO) | PWC | SIL | 13.03.95 | 7 17.09.19 | SIL PW100-008 | O | | | 3P |
| | | Fuel Heater-Fuel Inlet Temperatur | PWC | SIL | 10.08.92 | 07.03.95 | SIL PW100-010 | O | | | 3P |
| | | CPAC Software | PWC | SIL | 31.05.02 | 5 13.04.07 | SIL PW100-017 | O | | | 3P |
| | | Bearing Damage Due to Electrical Erosion | PWC | SIL | 15.12.95 | 1 07.12.99 | SIL PW100-026 | O | | | 3P |
| | | Engine Storage and Preservation | PWC | SIL | 20.04.98 | 2 29.04.09 | SIL PW100-028 | O | | | 3P |
| | | Service Policy for Repaired Parts | PWC | SIL | 11.07.96 | 7 18.05.05 | SIL PW100-029 | O | | | 3P |
| | | New Engine Serial Numbering Methodo. | PWC | SIL | 20.06.96 | 1 23.09.98 | SIL PW100-035 | O | | | 3P |
| | | Fuel Nozzle Restoration CSP | PWC | SIL | 01.01.97 | 2 30.11.01 | SIL PW100-036 | O | | E X P I R E D | 3P |
| | | Limited Cost Overhaul | PWC | SIL | 22.08.96 | | SIL PW100-041 | O | | | 3P |
| | | Applicability of Service Bulletin | PWC | SIL | 11.05.98 | 1 11.05.98 | SIL PW100-042 | O | | | 3P |
| | | Fuel Nozzle Maintenance Recommend. | PWC | SIL | 01.11.96 | 1 30.10.00 | SIL PW100-045 | O | | E X P I R E D | 3P |
| | | Fuel Heater Thermal Element | PWC | SIL | 30.05.97 | 1 30.10.00 | SIL PW100-050 | O | | E X P I R E D | 3P |
| | | TBO & HSI Contingency Extension Program | PWC | SIL | 26.05.98 | 3 31.10.13 | SIL PW100-055 | O | | C A N C E L L E D | 3P |
| | | High Pressure Turbine (HPT) Bolts | PWC | SIL | 27.10.97 | 1 23.03.07 | SIL PW100-056 | O | | C A N C E L L E D | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Impact of Engine Transfer | PWC | SIL | 27.05.98 | 2 07.12.00 | SIL PW100-057 | O | | | 3P |
| | | Service Policy and Stub Life on LCF | PWC | SIL | 10.07.98 | 3 15.02.16 | SIL PW100-064 | O | | | 3P |
| | | Harsh Environm.Operation Recomm.Pract. | PWC | SIL | 14.07.99 | | SIL PW100-067 | O | | E X P I R E D | 3P |
| | | Troubleshooting Instr.Internal Fuel Leaks | PWC | SIL | 23.08.00 | | SIL PW100-071 | O | | E X P I R E D | 3P |
| | | Borescope Training Courseware on CD-ROM | PWC | SIL | 06.10.00 | | SIL PW100-073 | O | | E X P I R E D | 3P |
| | | Stewart Warner Oil To Fuel Heaters | PWC | SIL | 07.12.00 | | SIL PW100-074 | O | | | 3P |
| | | Cating Marks on HPT Vanes | PWC | SIL | 22.12.00 | | SIL PW100-075 | O | | | 3P |
| | | Fuel Nozzle Install.w.Flexible Manif.Syst. | PWC | SIL | 16.04.01 | 1 28.11.02 | SIL PW100-077 | O | | | 3P |
| | | Accessory Gearbox Towershaft | PWC | SIL | 02.11.01 | | SIL PW100-079 | O | | | 3P |
| | | Shops for Fuel Nozzle Maintenance | PWC | SIL | 21.12.01 | | SIL PW100-084 | O | | | 3P |
| | | Clarif.of PWC Corp.'s EPP Service Policy | PWC | SIL | 01.05.02 | | SIL PW100-089 | O | | | 3P |
| | | High PressureVane Segm.Repl.Program | PWC | SIL | 02.07.02 | 1 20.11.03 | SIL PW100-090 | O | | | 3P |
| | | HPT and PT1 Turbine Blade Manufact."Dimples" | PWC | SIL | 25.09.03 | 1 02.12.08 | SIL PW100-094 | O | | | 3P |
| | | Fuel Nozzle Flexible Manifold Installation | PWC | SIL | 07.05.10 | 11 18.09.18 | SIL PW100-098 | O | | | 3P |
| | | Third Generation Typ II Turbo Oils (HTS Turbo Oils) | PWC | SIL | 18.05.05 | 1 28.03.17 | SIL PW100-101 | O | | C A N C E L L E D | 3P |
| | | PW100 Power Turbine Interstage Seal | PWC | SIL | 23.08.05 | 1 18.10.05 | SIL PW100-103 | O | | E X P I R E D | 3P |
| | | Repl. Program for #29 Bearing and Towershaft Upper Bevel Gear | PWC | SIL | 29.11.05 | 3 22.11.13 | SIL PW100-104 | O | | | 3P |
| | | PW100 Engine Power Parts Shortage | PWC | SIL | 21.12.05 | | SIL PW100-106 | O | | E X P I R E D | 3P |
| | | PW100 Engine Oil Filler and Valve Maintenance | PWC | SIL | 20.12.05 | 2 31.10.13 | SIL PW100-107 | O | | | 3P |
| | | PW100 Region.Operat.Conf.2007 & 2008 | PWC | SIL | 03.02.07 | 3 17.01.18 | SIL PW100-112 | O | | C A N C E L L E D | 3P |
| | | Fuel Manifolder Inst.and Leak Chek | PWC | SIL | 08.02.07 | 3 26.04.07 | SIL PW100-114 | O | | E X P I R E D | 3P |
| | | PW127M Introduction | PWC | SIL | 21.01.08 | | SIL PW100-116 | O | | | 3P |
| | | Bearing No. 15 Soft-time Recommendation | PWC | SIL | 25.02.08 | 1 31.10.13 | SIL PW100-118 | O | | C A N C E L L E D | 3P |
| | | P&W Initiatives for Ease of Maintenance Activities | PWC | SIL | 22.07.08 | | SIL PW100-120 | O | | E X P I R E D | 3P |
| | | Ltd. Time Offer for Eng.Conv.Power Charge Fee Discount | PWC | SIL | 29.07.08 | 3 04.11.13 | SIL PW100-123 | O | | C A N C E L L E D | 3P |
| | | PW100 Electrical Connector Maintenance | PWC | SIL | 17.11.08 | 1 18.11.08 | SIL PW100-125 | O | | | 3P |
| | | PW100 - Reconditioned Engine Support ("RES") program | PWC | SIL | 12.03.09 | 3 22.09.10 | SIL PW100-126 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Engine Accessories Maintenance Program | PWC | SIL | 08.09.09 | | SIL PW100-129 | O | | E X P I R E D | 3P |
| | | Propeller Shaft Flange Inspection | PWC | SIL | 18.09.09 | | SIL PW100-132 | O | | | 3P |
| | | PW100 Customer Web cast Technical Program Review | PWC | SIL | 21.10.09 | | SIL PW100-133 | O | | E X P I R E D | 3P |
| | | Maint. best practive Videos - PW100 connector care, and PW100 Fuel nozzle inst. and removal | PWC | SIL | 07.05.10 | 2 02.06.14 | SIL PW100-134 | O | | | 3P |
| | | Fuel Nozzle "Rigid" Manifold (Transfer Tubes) Installation | PWC | SIL | 21.09.10 | | SIL PW100-136 | O | | | 3P |
| | | Propeller Shaft crack at the No. 19 Bearing area | PWC | SIL | 21.12.10 | | SIL PW100-139 | O | | | 3P |
| | | Propeller Shaft Inspection and Replacement | PWC | SIL | 04.03.11 | 3 20.04.12 | SIL PW100-141 | O | | | 3P |
| | | Inspection Tasks to Allow Return to Service of Improperly Preserved Engines | PWC | SIL | 18.03.11 | | SIL PW100-142 | O | | | 3P |
| | | Propeller Shaft Inspection and Replacement | PWC | SIL | 03.05.11 | | SIL PW100-144 | O | | | 3P |
| | | High Pressure Turbine Bolt - Raw Material Shortage | PWC | SIL | 21.07.11 | 1 27.07.11 | SIL PW100-146 | O | | E X P I R E D | 3P |
| | | First Stage Power Turbine Blade - Maintenance Recommendation | PWC | SIL | 12.09.12 | 4 23.11.15 | SIL PW100-151 | O | | | 3P |
| | | Migration to Technical Publication Online | PWC | SIL | 07.12.12 | | SIL PW100-152 | O | | E X P I R E D | 3P |
| | | Mature Engine Commercial Initiative | PWC | SIL | 25.10.12 | | SIL PW100-153 | O | | E X P I R E D | 3P |
| | | Autofeather Control Unit Upgrade | PWC | SIL | 11.07.13 | | SIL PW100-154 | O | | | 3P |
| | | Troubleshooting Knowledgebase Updates | PWC | SIL | 26.09.13 | | SIL PW100-155 | O | | E X P I R E D | 3P |
| | | Detachment of Oil Filter integral Key washer | PWC | SIL | 07.06.13 | | SIL PW100-156 | O | | E X P I R E D | 3P |
| | | Engine Conversion Process | PWC | SIL | 28.09.18 | 1 19.10.18 | SIL PW100-158 | O | | | 3P |
| | | Fuel Nozzle and Manifolds protecting caps | PWC | SIL | 30.01.14 | | SIL PW100-160 | O | | | 3P |
| | | Recent In-Service Event Reported in August 2014 | PWC | SIL | 16.09.14 | | SIL PW100-161 | O | | | 3P |
| | | PW119B/C Engine Maintenance Manual available on line | PWC | SIL | 06.10.14 | | SIL PW100-162 | O | | | 3P |
| | | PW100 Customer Day Schedule – 2022 | PWC | SIL | 04.02.15 | 18 05.05.22 | SIL PW100-164 | O | | | 3P |
| | | PW100 Fuel Oil Heat Exchanger (FOHE) Inspection | PWC | SIL | 15.06.15 | | SIL PW100-166 | O | | | 3P |
| | | Bearing No.15 Soft-time Recommendation | PWC | SIL | 04.06.15 | | SIL PW100-168 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Use of non-approved product on PW100 Flexible Manifold | PWC | SIL | 30.06.15 | 1 01.06.16 | SIL PW100-169 | O | | | 3P |
| | | PW100 - Harsh Environment Program | PWC | SIL | 20.08.15 | 3 05.11.16 | SIL PW100-172 | O | | | 3P |
| | | PW100 Fuel Pump Delta Pressure Switch Loose Connector | PWC | SIL | 01.02.16 | | SIL PW100-174 | O | | | 3P |
| | | Disconnection of P3 supply line during compressor wash | PWC | SIL | 08.06.16 | | SIL PW100-175 | O | | | 3P |
| | | Second Stage Power Turbine (“PT2”) Blade - Eddy Current Inspection (“ECI”) and Revised Maintenance Recommendations | PWC | SIL | 28.03.17 | 1 09.08.17 | SIL PW100-185 | O | | | 3P |
| | | PW100 PMA Fuel Filter - FAA SAIB NE-17-27 | PWC | SIL | 08.11.17 | | SIL PW100-187 | O | | | 3P |
| | | Second stage power turbine blades (PT2) post SB21876 & SB21889 | PWC | SIL | 31.10.17 | 3 29.11.18 | SIL PW100-188 | O | | | 3P |
| | | Interstage Air Seals supplier change - SB21923 | PWC | SIL | 04.06.18 | 3 03.12.18 | SIL PW100-189 | O | | | 3P |
| | | Improper Repair on PW100 Rigid Fuel Nozzle | PWC | SIL | 21.11.18 | | SIL PW100-191 | O | | | 3P |
| | | PW 100 Fuel Pump Special Exchange Offer | PWC | SIL | 03.11.19 | 2 07.04.22 | SIL PW100-192 | O | | | 3P |
| | | Diagnostics, Prognostics and Health Management ("MonitorTM") Package | PWC | SIL | 28.01.20 | | SIL PW100-196 | O | | | 3P |
| | | PW 100 Rental Engine Support | PWC | SIL | 20.12.19 | | SIL PW100-198 | O | | | 3P |
| | | Second Stage Power Turbine (PT2) Blades introduced by SB12959 | PWC | SIL | 30.03.21 | 1 19.07.21 | SIL PW100-204 | O | | | 3P |
| | | PW100 Fuel Pump Filter Special Discount Offer | PWC | SIL | 06.12.21 | | SIL PW100-208 | O | | | 3P |
| | | Distribution | PWC | SIL | 21.11.22 | | SIL PW100-210 | O | | | 3P |
| | | Air Intake Case Stand - Tool Modification | PWC | SIL | 28.12.17 | | SIL PW100-768 | O | | | 3P |
| | | New Engine Serial Numbering Methodology | PWC | SIL | 20.06.96 | 2 12.03.04 | SIL PW200-004 | O | | | 3A |
| PWC31247 | | PWC31247 | PWC | TSB | 28.01.92 | | TSB PW100-0066 | O | | | 3P |
| PWC37264 | | Adapter | PWC | TSB | 30.11.90 | | TSB PW100-0087 | O | | | 3P |
| PWC37262 | | Adapter | PWC | TSB | 30.11.90 | | TSB PW100-0088 | O | | | 3P |
| PWC37626 | | Support | PWC | TSB | 12.06.91 | | TSB PW100-0090 | O | | | 3P |
| PWC37741 | | PAD | PWC | TSB | 12.06.91 | | TSB PW100-0093 | O | | | 3P |
| PWC37350 | | Puller | PWC | TSB | 07.04.92 | | TSB PW100-0094 | O | | | 3P |
| PWC37334 | | Pusher | PWC | TSB | 08.11.90 | | TSB PW100-0096 | O | | | 3P |
| PWC37349 | | Puller | PWC | TSB | 30.11.90 | | TSB PW100-0097 | O | | | 3P |
| PWC37005 | | Drift | PWC | TSB | 30.11.90 | | TSB PW100-0098 | O | | | 3P |
| PWC37030 | | Adapter | PWC | TSB | 06.12.90 | | TSB PW100-0099 | O | | | 3P |
| PWC37074 | | Plier | PWC | TSB | 30.11.90 | | TSB PW100-0100 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| PWC37585 | | Puller | PWC | TSB | 30.11.90 | | TSB PW100-0101 | O | | | 3P |
| PWC37054 | | Puller | PWC | TSB | 06.12.90 | | TSB PW100-0102 | O | | | 3P |
| PWC37574 | | Plug | PWC | TSB | 30.11.90 | | TSB PW100-0103 | O | | | 3P |
| PWC37509 | | Socket | PWC | TSB | 30.11.90 | | TSB PW100-0104 | O | | | 3P |
| PWC38080 | | Drift | PWC | TSB | 09.11.90 | | TSB PW100-0105 | O | | | 3P |
| PWC38234 | | Drift | PWC | TSB | 09.11.90 | | TSB PW100-0106 | O | | | 3P |
| PWC37151 | | Adapter | PWC | TSB | 19.12.90 | | TSB PW100-0109 | O | | | 3P |
| PWC37532 | | Riveter | PWC | TSB | 08.02.91 | | TSB PW100-0110 | O | | | 3P |
| PWC37445 | | Support | PWC | TSB | 25.01.91 | | TSB PW100-0112 | O | | | 3P |
| PWC37525 | | Wrench | PWC | TSB | 05.03.91 | | TSB PW100-0117 | O | | | 3P |
| PWC37446 | | Fixture | PWC | TSB | 12.06.91 | | TSB PW100-0118 | O | | | 3P |
| PWC38455 | | Adapter | PWC | TSB | 12.04.91 | | TSB PW100-0120 | O | | | 3P |
| PWC37319 | | Puller | PWC | TSB | 20.06.91 | | TSB PW100-0121 | O | | | 3P |
| PWC37127 | | Adapter | PWC | TSB | 30.07.91 | | TSB PW100-0122 | O | | | 3P |
| PWC37823 | | Lever | PWC | TSB | 24.07.91 | | TSB PW100-0123 | O | | | 3P |
| PWC37737 | | Fixture | PWC | TSB | 10.09.91 | | TSB PW100-0125 | O | | | 3P |
| PWC37982 | | Drift | PWC | TSB | 11.09.91 | | TSB PW100-0127 | O | | | 3P |
| PWC38131 | | Socket | PWC | TSB | 20.09.91 | | TSB PW100-0128 | O | | | 3P |
| PWC31247 | | PWC31247 | PWC | TSB | 07.04.92 | | TSB PW100-0129 | O | | | 3P |
| PWC37217 | | Puller | PWC | TSB | 12.12.91 | | TSB PW100-0130 | O | | | 3P |
| PWC37060 | | Gage | PWC | TSB | 16.12.91 | | TSB PW100-0132 | O | | | 3P |
| PWC37321 | | Puller | PWC | TSB | 07.04.92 | | TSB PW100-0133 | O | | | 3P |
| PWC37855 | | Puller | PWC | TSB | 10.01.92 | | TSB PW100-0135 | O | | | 3P |
| PWC37548 | | Drift | PWC | TSB | 07.04.92 | | TSB PW100-0136 | O | | | 3P |
| PWC37388 | | Fixture | PWC | TSB | 07.04.92 | | TSB PW100-0137 | O | | | 3P |
| PWC37732 | | Fixture | PWC | TSB | 06.04.92 | | TSB PW100-0139 | O | | | 3P |
| PWC38318 | | Bracket Assy. | PWC | TSB | 12.11.91 | | TSB PW100-0140 | O | | | 3P |
| PWC37960 | | Fixture | PWC | TSB | 31.10.91 | | TSB PW100-0142 | O | | | 3P |
| PWC37404 | | Duct Assy | PWC | TSB | 11.11.91 | | TSB PW100-0146 | O | | | 3P |
| PWC37369 | | Socket | PWC | TSB | 29.11.91 | | TSB PW100-0147 | O | | | 3P |
| PWC37277 | | Puller | PWC | TSB | 13.01.92 | | TSB PW100-0148 | O | | | 3P |
| PWC37102 | | Sling | PWC | TSB | 02.12.91 | | TSB PW100-0149 | O | | | 3P |
| PWC37486 | | Probe Assy | PWC | TSB | 13.12.91 | | TSB PW100-0153 | O | | | 3P |
| PWC37879 | | Fixture | PWC | TSB | 17.01.92 | | TSB PW100-0155 | O | | | 3P |
| PWC37880 | | Fixture | PWC | TSB | 10.01.92 | | TSB PW100-0156 | O | | | 3P |
| PWC37892 | | Plate | PWC | TSB | 07.04.92 | | TSB PW100-0157 | O | | | 3P |
| PWC37894 | | Plate | PWC | TSB | 06.04.92 | | TSB PW100-0158 | O | | | 3P |
| PWC37861 | | Protector | PWC | TSB | 10.01.92 | | TSB PW100-0159 | O | | | 3P |
| PWC38258 | | Puller | PWC | TSB | 13.12.91 | | TSB PW100-0160 | O | | | 3P |
| PWC38284 | | Template | PWC | TSB | 15.01.92 | | TSB PW100-0161 | O | | | 3P |
| PWC38296 | | Fixture | PWC | TSB | 29.01.92 | | TSB PW100-0163 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| PWC38297 | | Punch | PWC | TSB | 27.01.92 | | TSB PW100-0164 | O | | | 3P |
| PWC37811 | | PWC37811 | PWC | TSB | 06.02.92 | | TSB PW100-0165 | O | | | 3P |
| PWC37076 | | Trunnion | PWC | TSB | 16.03.92 | | TSB PW100-0167 | O | | | 3P |
| PWC37067 | | Fixture | PWC | TSB | 26.02.92 | | TSB PW100-0170 | O | | | 3P |
| PWC38407 | | Gage | PWC | TSB | 30.04.92 | | TSB PW100-0176 | O | | | 3P |
| PWC38408 | | Gage | PWC | TSB | 30.04.92 | | TSB PW100-0177 | O | | | 3P |
| PWC37324 | | Puller | PWC | TSB | 30.04.92 | | TSB PW100-0181 | O | | | 3P |
| PWC37030 | | Adapter | PWC | TSB | 30.04.92 | | TSB PW100-0182 | O | | | 3P |
| PWC54080 | | Fixture | PWC | TSB | 17.09.93 | | TSB PW100-0212 | O | | | 3P |
| PWC37102 | | Sling | PWC | TSB | 05.03.93 | | TSB PW100-0232 | O | | | 3P |
| PWC37604 | | Sling | PWC | TSB | 05.03.93 | | TSB PW100-0233 | O | | | 3P |
| PWC37981 | | Puller | PWC | TSB | 19.03.93 | | TSB PW100-0235 | O | | | 3P |
| PWC54025 | | Puller | PWC | TSB | 19.03.93 | | TSB PW100-0236 | O | | | 3P |
| PWC37837 | | Fixture | PWC | TSB | 02.06.93 | | TSB PW100-0238 | O | | | 3P |
| PWC37490 | | Crimper | PWC | TSB | 25.06.93 | | TSB PW100-0239 | O | | | 3P |
| PWC54147 | | UN-Staking Tool | PWC | TSB | 25.06.93 | | TSB PW100-0240 | O | | | 3P |
| PWC37760 | | Adapter | PWC | TSB | 14.09.93 | | TSB PW100-0242 | O | | | 3P |
| PWC37491 | | Crimper-No.4 BRG Retr.Nut Cupwasher | PWC | TSB | 12.10.93 | | TSB PW100-0246 | O | | | 3P |
| PWC54210 | | Fixture-Fuel Nozzle (Delavan) | PWC | TSB | 14.03.95 | | TSB PW100-0247 | O | | | 3P |
| PWC54209 | | Fixtrue-Lapping/Fuel Nozzle | PWC | TSB | 14.03.95 | | TSB PW100-0248 | O | | | 3P |
| PWC54240 | | Ring | PWC | TSB | 14.03.95 | | TSB PW100-0250 | O | | | 3P |
| PWC54242 | | Support | PWC | TSB | 14.03.95 | | TSB PW100-0251 | O | | | 3P |
| PWC38622 | | Support | PWC | TSB | 14.03.95 | | TSB PW100-0253 | O | | | 3P |
| PWC37459 | | Socket-HP Turbine Stubshaft Retrain. Nut | PWC | TSB | 07.05.94 | 1 | TSB PW100-0254 | O | | | 3P |
| PWC37846 | | Adapter-HP Impeller Anti-Rotation | PWC | TSB | 21.10.93 | | TSB PW100-0255 | O | | | 3P |
| PWC37167 | | Fixture-Loading, HP Impeller Assy | PWC | TSB | 21.10.93 | | TSB PW100-0256 | O | | | 3P |
| PWC54186 | | Puller-Flex HSG&No.5 BRG HSG Disassy | PWC | TSB | 14.03.95 | | TSB PW100-0257 | O | | | 3P |
| PWC54192 | | Drift-Flex HSG&No.5 BRG HSG Assy | PWC | TSB | 14.03.95 | | TSB PW100-0258 | O | | | 3P |
| PWC54198 | | Base-Flex HSG&No.5 BRG HSG Assy | PWC | TSB | 14.03.95 | | TSB PW100-0259 | O | | | 3P |
| PWC54189 | | Drift-No.5 BRG HSG&Snubber Assy | PWC | TSB | 14.03.95 | | TSB PW100-0260 | O | | | 3P |
| PWC54191 | | Drift-No.5 BRG Outer Race Installation | PWC | TSB | 14.03.95 | | TSB PW100-0261 | O | | | 3P |
| PWC54195 | | Drift-No.5 BRG Outer Race Removal | PWC | TSB | 14.03.95 | | TSB PW100-0262 | O | | | 3P |
| PWC54196 | | Base-No.5 BRG Outer Race Removal | PWC | TSB | 14.03.95 | | TSB PW100-0263 | O | | | 3P |
| PWC54184 | | Puller-No.5 BRG HSG From Gas Gen Case | PWC | TSB | 14.03.95 | | TSB PW100-0264 | O | | | 3P |
| PWC54197 | | Support-Seal&Gas Gen Case Assy Case | PWC | TSB | 14.03.95 | | TSB PW100-0265 | O | | | 3P |
| PWC54154 | | Support Ring-No.5 BRG HSG Cover Assy | PWC | TSB | 14.03.95 | | TSB PW100-0266 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| PWC54355 | | Guide-High Pressure Impeller Alignment | PWC | TSB | 14.03.95 | | TSB PW100-0267 | O | | | 3P |
| PWC54028 | | Puller-Fuel Nozzle Adapter,Transfer Tube | PWC | TSB | 14.03.95 | | TSB PW100-0268 | O | | | 3P |
| PWC54029 | | Puller-Fuel Nozzle Adapter,Transfer Tube | PWC | TSB | 14.03.95 | | TSB PW100-0269 | O | | | 3P |
| PWC54246 | | Puller-Fuel Nozzle Adapter,Transfer Tube | PWC | TSB | 14.03.95 | | TSB PW100-0270 | O | | | 3P |
| PWC54254 | | Puller-Fuel Nozzle Adapter,Transfer Tube | PWC | TSB | 14.03.95 | | TSB PW100-0271 | O | | | 3P |
| PWC54255 | | Puller-Fuel Nozzle Adapter,Transfer Tube | PWC | TSB | 14.03.95 | | TSB PW100-0272 | O | | | 3P |
| PWC37318 | | Adapter-Low Pressure Shaft Antirotation | PWC | TSB | 14.03.95 | | TSB PW100-0273 | O | | | 3P |
| PWC54082 | | Adapter-HPT Stubshaft Hardware Retainer | PWC | TSB | 14.03.95 | | TSB PW100-0276 | O | | | 3P |
| PWC37760 | | Adapter-HP Turbine Stub Shaft, Pulling | PWC | TSB | 14.03.95 | | TSB PW100-0277 | O | | | 3P |
| PWC37351 | | Fixture-Aligning HP Disk&Covers | PWC | TSB | 14.03.95 | | TSB PW100-0278 | O | | | 3P |
| PWC38395 | | Adapter-HP Turbine Stub Shaft, Pulling | PWC | TSB | 14.03.95 | | TSB PW100-0279 | O | | | 3P |
| PWC38667 | | Puller-Interstage Air Seal from HPT Disk | PWC | TSB | 14.03.95 | | TSB PW100-0280 | O | | | 3P |
| PWC37059 | | Pad-Low Pressure Shaft Air Seal | PWC | TSB | 18.03.95 | | TSB PW100-0281 | O | | | 3P |
| PWC38455 | | Adapter-High Pressure Turbine Disk Bal. | PWC | TSB | 04.11.94 | | TSB PW100-0284 | O | | | 3P |
| PWC38455-M04 | | Adapter-High Pressure Turbine Disk Bal. | PWC | TSB | 04.11.94 | | TSB PW100-0285 | O | | | 3P |
| PWC54035 | | Puller-Auxiliary Tank Cover | PWC | TSB | 14.03.95 | | TSB PW100-0287 | O | | | 3P |
| PWC54040 | | Adapter-Low Pressure Impeller Bal. | PWC | TSB | 14.03.95 | | TSB PW100-0290 | O | | | 3P |
| PWC54041 | | Pusher-LP Impeller to Balancing Adapter | PWC | TSB | 14.03.95 | | TSB PW100-0293 | O | | | 3P |
| PWC54042 | | Pusher-LP Impeller to Balancing Adapter | PWC | TSB | 14.03.95 | | TSB PW100-0294 | O | | | 3P |
| PWC37361 | | Socket-Lower Angle Drive Gear BRG Nut | PWC | TSB | 23.02.95 | | TSB PW100-0298 | O | | | 3P |
| PWC38243 | | Puller-No.13 BRG Inner Race | PWC | TSB | 18.03.95 | | TSB PW100-0299 | O | | | 3P |
| PWC37349 | | Puller-No.4 Bearing Rotor Airseal | PWC | TSB | 01.06.95 | | TSB PW100-0302 | O | | | 3P |
| PWC54633 | | Socket-Lower Angle Drive Gear BRG Nut | PWC | TSB | 29.09.97 | | TSB PW100-0303 | O | | | 3P |
| PWC38207 | | Nozzle-Engine Exhaust | PWC | TSB | 23.10.95 | | TSB PW100-0304 | O | | | 3P |
| PWC31050 | | Wrench-Nut | PWC | TSB | 29.09.97 | | TSB PW100-0305 | O | | | 3P |
| PWC37891 | | Adapter - Angle Drive Shaft Holding | PWC | TSB | 29.09.97 | | TSB PW100-0306 | O | | | 3P |
| PWC37509 | | Socket - Angle Drive Shaft Upper Nut | PWC | TSB | 29.09.97 | | TSB PW100-0307 | O | | | 3P |
| PWC37902 | | Adapter-Filter By-Pass&Press.Relief | PWC | TSB | 29.09.97 | | TSB PW100-0308 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| PWC31280-802 | | Adapter-Low Press.Turbine Disk Growth | PWC | TSB | 29.09.97 | | TSB PW100-0311 | O | | | 3P |
| PWC37807 Rev.D | | Hydraulic Pump | PWC | TSB | 12.02.98 | | TSB PW100-0312 | O | | | 3P |
| PWC37884 Rev.A | 72-30-00 | Drift, Gearshaft | PWC | TSB | 12.02.98 | | TSB PW100-0313 | O | | | 3P |
| PWC37882 Rev.B | 72-30-00 | Drift, Collar | PWC | TSB | 12.02.98 | | TSB PW100-0314 | O | | | 3P |
| PWC31247 Rev.B | 72-50-00 | Support, Rivet | PWC | TSB | 12.02.98 | | TSB PW100-0315 | O | | | 3P |
| PWC30539 Rev.E | 72-50-00 | Rivet Set | PWC | TSB | 12.02.98 | | TSB PW100-0316 | O | | | 3P |
| PWC54074 Rev.E | 72-30-00 | Crimper, No.3 Bearing Cupwasher | PWC | TSB | 12.02.98 | | TSB PW100-0318 | O | | | 3P |
| PWC43031 Rev.C | 72-50-00 | Support, Rivet | PWC | TSB | 12.02.98 | | TSB PW100-0319 | O | | | 3P |
| PWC38364 Rev.A | 72-50-00 | Balancing Adapter, LP Turbine Disk | PWC | TSB | 12.02.98 | | TSB PW100-0321 | O | | | 3P |
| PWC30304 | 72-50-00 | Rivet Set | PWC | TSB | 12.02.98 | | TSB PW100-0322 | O | | | 3P |
| PWC54001 Rev.C | 72-01-60 | Wrench | PWC | TSB | 01.03.99 | 1 01.03.99 | TSB PW100-0326 | O | | | 3P |
| PWC37732 Rev.F | 72-20-00 | Fixture, Loading | PWC | TSB | 01.03.99 | 1 01.03.99 | TSB PW100-0327 | O | | | 3P |
| PWC37373 Rev.D | 72-03-00 | Drift | PWC | TSB | 07.04.98 | | TSB PW100-0328 | O | | | 3P |
| PWC38553 Rev.C | 72-03-00 | Puller | PWC | TSB | 01.03.99 | 1 01.03.99 | TSB PW100-0329 | O | | | 3P |
| PWC54262 Rev.C | 72-50-00 | Puller, Air Seal No.2 Bearing | PWC | TSB | 15.05.98 | 1 14.05.99 | TSB PW100-0330 | O | | | 3P |
| PWC37748 Rev.D | 72-03-00 | Puller, LP Turbine Disc. | PWC | TSB | 15.05.98 | 1 14.05.99 | TSB PW100-0331 | O | | | 3P |
| PWC37834 Rev.C | 72-20-00 | Holding Fixture | PWC | TSB | 15.05.98 | | TSB PW100-0332 | O | | | 3P |
| PWC38667 Rev.E | 72-03-00 | Puller, HP Disc | PWC | TSB | 15.05.98 | | TSB PW100-0333 | O | | | 3P |
| PWC37382 Rev.B | 72-30-00 | Drift, No.28 and No.29 Bearing | PWC | TSB | 08.09.98 | | TSB PW100-0334 | O | | | 3P |
| PWC37831 Rev.D | 72-50-00 | Riverter,High Press.Imp.Balance Rivets | PWC | TSB | 08.09.98 | | TSB PW100-0335 | O | | | 3P |
| PWC37174 Rev.C | 72-50-00 | Puller, No.6 Bearing | PWC | TSB | 08.09.98 | | TSB PW100-0339 | O | | | 3P |
| PWC38350 Rev.A | 72-10-00 | Pad, Layshaft, Flexible Coupling | PWC | TSB | 08.09.98 | | TSB PW100-0340 | O | | | 3P |
| PWC38173 Rev.A | 72-00-00 | Duct Assembly, Bleed Valve | PWC | TSB | 17.02.00 | | TSB PW100-0349 | O | | | 3P |
| PWC37388 Rev.C | 72-20-00 | Fixture, Main Accessory Coupling Shaft | PWC | TSB | 14.05.99 | | TSB PW100-0369 | O | | | 3P |
| PWC37137 Rev.E | 72-00-53 | Socket, Power Turbine Nut | PWC | TSB | 27.01.00 | | TSB PW100-0371 | O | | | 3P |
| PWC37031 Rev.J | 72-20-00 | Adapter,Backlash,Fuel&Oil Pump Drives | PWC | TSB | 01.03.97 | 01.03.99 | TSB PW100-0373 | O | | | 3P |
| PWC54030 Rev.A | 72-01-10 | Tester, Continuity | PWC | TSB | 04.03.99 | | TSB PW100-0375 | O | | | 3P |
| PWC38107 Rev.D | 72-52-13 | Gage, Stretch | PWC | TSB | 15.10.98 | 2 03.06.99 | TSB PW100-0376 | O | | | 3P |
| PWC37773 Rev.A | 72-03-00 | Puller, Bearing No.28 | PWC | TSB | 01.03.99 | | TSB PW100-0378 | O | | | 3P |
| PWC37262 Rev.E | 72-50-00 | Adapter, Balancing, PT Rotor | PWC | TSB | 01.03.98 | 01.03.99 | TSB PW100-0379 | O | | | 3P |
| PWC37319 Rev.M | 72-50-00 | Puller, No. 3 Bearing Inner Race. | PWC | TSB | 01.03.98 | 01.03.99 | TSB PW100-0380 | O | | | 3P |
| PWC37838 Rev.B | 72-10-00 | Fixture, Holding, Gearshaft | PWC | TSB | 01.03.98 | 01.03.99 | TSB PW100-0389 | O | | | 3P |
| PWC38137 Rev.A | 72-10-03 | Fixture, Holding Gear | PWC | TSB | 01.03.98 | 01.03.99 | TSB PW100-0390 | O | | | 3P |
| PWC54355 Rev.B | 72-03-00 | Guide, Impeller | PWC | TSB | 01.03.98 | 01.03.99 | TSB PW100-0393 | O | | | 3P |
| PWC38316 Rev.B | 72-03-00 | Fixture, Lifting | PWC | TSB | 01.03.98 | 01.03.99 | TSB PW100-0395 | O | | | 3P |
| PWC37559 Rev.A | 72-03-00 | Puller, Bearing No.4 Outer Race | PWC | TSB | 01.03.99 | | TSB PW100-0396 | O | | | 3P |
| PWC37444 Rev.B | 72-10-00 | Fixture,Input Shaft,No.9 Bearing Retain.Nut | PWC | TSB | 01.03.98 | 01.03.99 | TSB PW100-0397 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| PWC37827 Rev.D | | Socket Nut | PWC | TSB | 14.03.95 | 1 21.01.11 | TSB PW100-286 | O | | | 3P |
| PWC37007 Rev.C | 72-20-00 | Drift,Fuel Pump Drive Shaft | PWC | TSB | 14.05.99 | | TSB PW100-400 | O | | | 3P |
| PWC37566 Rev.C | 72-11-00 | Puller, Knocker, Cover | PWC | TSB | 14.05.99 | | TSB PW100-401 | O | | | 3P |
| PWC37585 Rev.C | 72-03-00 | Puller, Seal, Breather Adapter | PWC | TSB | 14.05.98 | 14.05.99 | TSB PW100-402 | O | | | 3P |
| PWC37271 Rev.C | 72-50-00 | Puller, PT Interstage Rotor Air Seal | PWC | TSB | 14.05.99 | | TSB PW100-403 | O | | | 3P |
| PWC37056 Rev.A | 72-03-00 | Pusher | PWC | TSB | 06.08.98 | 06.08.99 | TSB PW100-404 | O | | | 3P |
| PWC37157 Rev.B | 72-03-00 | Extractor, Tube | PWC | TSB | 06.08.99 | | TSB PW100-405 | O | | | 3P |
| PWC37878 Rev.C | 72-03-00 | Fixture, Pressure, Gas Generator Case | PWC | TSB | 20.09.99 | | TSB PW100-407 | O | | | 3P |
| PWC37767 Rev.A | 72-50-00 | Support, First-Stage PT Seal Installation | PWC | TSB | 01.09.99 | | TSB PW100-409 | O | | | 3P |
| PWC37921 Rev.A | 72-02-00 | Bracket Assy. | PWC | TSB | 01.09.99 | | TSB PW100-410 | O | | | 3P |
| PWC37920 Rev.A | 72-02-00 | Bracket Assy. | PWC | TSB | 01.09.99 | | TSB PW100-411 | O | | | 3P |
| PWC38131 Rev.B | 72-11-00 | Socket, Flexible Layshaft | PWC | TSB | 01.09.99 | | TSB PW100-412 | O | | | 3P |
| PWC37235 Rev.C | 72-11-01 | Puller, No.13 & 14 Bearing Outer Race | PWC | TSB | 06.12.98 | 06.12.99 | TSB PW100-414 | O | | | 3P |
| PWC38149 Rev.B | 72-31-01 | Adapter, Anti-rotation.LP Impeller Retain.Nut | PWC | TSB | 05.12.98 | 06.12.99 | TSB PW100-415 | O | | | 3P |
| PWC37138 Rev.D | 72-03-00 | Adapter, Power Turbine Disk Anti-Rotation | PWC | TSB | 25.01.98 | 25.01.00 | TSB PW100-416 | O | | | 3P |
| PWC37853 Rev.G | 72-03-00 | Puller, HP Turbine Disk | PWC | TSB | 25.01.00 | | TSB PW100-417 | O | | | 3P |
| PWC37880 Rev.B | 72-41-10 | Fixture | PWC | TSB | 26.01.99 | 25.01.00 | TSB PW100-418 | O | | | 3P |
| PWC37894 Rev.B | 72-41-10 | Plate, Guide, Gas Generator Case | PWC | TSB | 17.02.99 | 17.02.00 | TSB PW100-419 | O | | | 3P |
| PWC38123 Rev.B | 72-11-00 | Fixture, Flexible Layshaft Loading | PWC | TSB | 17.02.00 | | TSB PW100-421 | O | | | 3P |
| PWC38132 Rev.C | 72-11-00 | Adapter,Anti-Rotation,Flex.Layshaft Loading | PWC | TSB | 17.02.99 | 17.02.00 | TSB PW100-423 | O | | | 3P |
| PWC54242 Rev.A | 72-50-00 | Support, LP Disk | PWC | TSB | 17.02.99 | 17.02.00 | TSB PW100-424 | O | | | 3P |
| PWC54100 Rev.D | 72-03-00 | Puller, PT Stator Baffle Removal | PWC | TSB | 17.02.00 | | TSB PW100-425 | O | | | 3P |
| PWC37871 Rev.B | 72-11-00 | Adapter,Vernier Coupl.Retain.Nut Anti-Rot. | PWC | TSB | 15.11.99 | 17.02.00 | TSB PW100-426 | O | | | 3P |
| PWC37815 Rev.B | 72-11-00 | Puller, Propeller Control Coupling | PWC | TSB | 17.02.00 | | TSB PW100-427 | O | | | 3P |
| PWC54912 Rev. A | 72-03-00 | Socket, LP Turbine Disk Retaining Nut | PWC | TSB | 17.02.00 | | TSB PW100-428 | O | | | 3P |
| PWC37792 Rev.C | 72-11-00 | Adapter, Input Shaft Anti-Rotation | PWC | TSB | 17.02.00 | | TSB PW100-429 | O | | | 3P |
| PWC56226 Rev. A | 72-03-00 | Pusher, Power Turbine Rotor | PWC | TSB | 19.06.00 | | TSB PW100-430 | O | | | 3P |
| PWC38389 Rev.A | 72-03-00 | Puller, Sealing Tube from Turbine Support | PWC | TSB | 17.02.00 | | TSB PW100-431 | O | | | 3P |
| PWC37342 Rev.B | 72-51-02 | Drift, No.5 Bearing Inner Race, Scoop | PWC | TSB | 15.02.95 | 17.02.00 | TSB PW100-432 | O | | | 3P |
| PWC37368 Rev.B | 72-31-05 | Fixture, Upper Angle Drive Horiz.Gear Hold. | PWC | TSB | 15.02.99 | 17.02.00 | TSB PW100-433 | O | | | 3P |
| PWC56197 Rev. B | 72-00-53 | Wrench, T6 Thermocouple | PWC | TSB | 19.06.00 | | TSB PW100-436 | O | | | 3P |
| PWC37066 Rev.B | 72-51-02 | Support, High Pressure Disk | PWC | TSB | 19.06.00 | | TSB PW100-437 | O | | | 3P |
| PWC37317 Rev.D | | Socket, Nut | PWC | TSB | 22.03.02 | | TSB PW100-448 | O | | | 3P |
| PWC38149 Rev.C | | Adapter, Shaft | PWC | TSB | 22.03.02 | | TSB PW100-449 | O | | | 3P |
| PWC38906 Rev.B | | Adapter, Cylinder | PWC | TSB | 22.03.02 | | TSB PW100-452 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| PWC54907 Rev.C | | Pusher, Gear | PWC | TSB | 14.03.02 | | TSB PW100-453 | O | | | 3P |
| PWC56316 Rev. A | | Socket, Bearing Retaining Nut | PWC | TSB | 11.03.02 | | TSB PW100-456 | O | | | 3P |
| PWC37576 Rev.E | | Cover, Blanking | PWC | TSB | 23.04.02 | | TSB PW100-457 | O | | | 3P |
| PWC37924 | | Fixture, Pressure Test, Fuel Nozzle | PWC | TSB | 26.09.02 | | TSB PW100-458 | O | | | 3P |
| PWC54209 | | Lapping Tool | PWC | TSB | 04.12.02 | | TSB PW100-460 | O | | | 3P |
| | | Support Fixture, PT Disk Balance | PWC | TSB | 06.12.02 | | TSB PW100-461 | O | | | 3P |
| | | Support, Pinion Gear | PWC | TSB | 06.01.03 | | TSB PW100-465 | O | | | 3P |
| | | Sling, Reduction Gearbox | PWC | TSB | 09.01.03 | | TSB PW100-467 | O | | | 3P |
| PWC54254 | | Puller/Pusher, Fuel Nozzle Transfer Tube | PWC | TSB | 02.04.03 | | TSB PW100-473 | O | | | 3P |
| PWC54255 | | Puller/Pusher, Fuel Nozzle Transfer Tube | PWC | TSB | 02.04.03 | | TSB PW100-474 | O | | | 3P |
| PWC54783 | | Fixture Holding, Housing | PWC | TSB | 30.04.03 | | TSB PW100-475 | O | | | 3P |
| PWC54410 | | Drift, Sleeve | PWC | TSB | 22.05.03 | | TSB PW100-476 | O | | | 3P |
| PWC38255 | 72-10-00 | Sling, Reduction Gearbox | PWC | TSB | 16.05.03 | | TSB PW100-477 | O | | | 3P |
| PWC37650 | | Adapter, RGB | PWC | TSB | 26.05.03 | | TSB PW100-479 | O | | | 3P |
| PWC54408 Rev.B | | Collar, Propshaft | PWC | TSB | 22.05.03 | | TSB PW100-480 | O | | | 3P |
| PWC54345 Rev.B | | Collar, Bench | PWC | TSB | 26.05.03 | | TSB PW100-481 | O | | | 3P |
| PWC56046 Rev. A | | Adapter, LP Rotor Assy Build Stand | PWC | TSB | 22.05.03 | | TSB PW100-482 | O | | | 3P |
| PWC56064 | | Guide, LP Rotor | PWC | TSB | 22.05.03 | | TSB PW100-483 | O | | | 3P |
| PWC56315 | | Socket | PWC | TSB | 14.07.03 | | TSB PW100-485 | O | | | 3P |
| PWC37487 | | Gage, Disk | PWC | TSB | 02.09.03 | | TSB PW100-486 | O | | | 3P |
| PWC37837 Rev.B | | Fixture, Lifting | PWC | TSB | 29.08.03 | | TSB PW100-487 | O | | | 3P |
| PWC54345 Rev.D | | Collar, Bench | PWC | TSB | 08.09.03 | | TSB PW100-488 | O | | | 3P |
| PWC54214 Rev D | | Engine Assembly Front Adapter | PWC | TSB | 17.10.03 | | TSB PW100-489 | O | | | 3P |
| PWC38570 Rev.A | | Puller, Support Housing | PWC | TSB | 20.11.03 | | TSB PW100-492 | O | | | 3P |
| PWC37175 Rev.B | | Separator, Support | PWC | TSB | 17.11.03 | | TSB PW100-493 | O | | | 3P |
| PWC37509 Rev.C | | Socket, Tower Shaft Nut | PWC | TSB | 17.11.03 | | TSB PW100-494 | O | | | 3P |
| PWC37305 Rev.H | | Sling, Reduction Gearbox | PWC | TSB | 18.11.03 | | TSB PW100-495 | O | | | 3P |
| PWC37939 | | Sling | PWC | TSB | 05.11.03 | | TSB PW100-496 | O | | | 3P |
| PWC37167 Rev.H | | Fixture, Loading, Impeller | PWC | TSB | 17.12.03 | | TSB PW100-497 | O | | | 3P |
| PWC54212 Rev.D | | Adaptor, Turbo Assy | PWC | TSB | 17.12.03 | | TSB PW100-498 | O | | | 3P |
| PWC37277 Rev.E | | Puller, P.T. Shaft Assy | PWC | TSB | 13.01.04 | | TSB PW100-499 | O | | | 3P |
| PWC54252 Rev.B | | Puller, P.T. Shaft Assy | PWC | TSB | 14.01.04 | 1 24.02.05 | TSB PW100-500 | O | | | 3P |
| PWC56098 Rev. C | | Lifting Sling, Main Engine | PWC | TSB | 17.03.04 | | TSB PW100-501 | O | | | 3P |
| PWC54213 Rev.E | | Adapter, Engine and Turbo Assy | PWC | TSB | 17.03.04 | | TSB PW100-502 | O | | | 3P |
| PWC56591 Rev. A | | Lifting Device, PT Rotor | PWC | TSB | 16.03.04 | | TSB PW100-503 | O | | | 3P |
| PWC54283 Rev.D | | Scriber, Bearing | PWC | TSB | 07.06.04 | | TSB PW100-505 | O | | | 3P |
| PWC34520 Rev.B | | Restrictor | PWC | TSB | 05.07.04 | | TSB PW100-510 | O | | | 3P |
| PWC37906 Rev.C | | Adapter | PWC | TSB | 02.08.04 | 1 17.07.14 | TSB PW100-511 | O | | | 3P |
| PWC37305 Rev.J | | Sling, Reduction Gearbox | PWC | TSB | 04.10.04 | | TSB PW100-516 | O | | | 3P |
| PWC56096 Rev. F | | Build Stand | PWC | TSB | 16.11.04 | | TSB PW100-517 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| PWC30271 Rev.E | | Spreader | PWC | TSB | 09.12.04 | | TSB PW100-518 | O | | | 3P |
| PWC32506 Rev.H | | Hydraulic Cylinder | PWC | TSB | 08.12.04 | | TSB PW100-519 | O | | | 3P |
| PWC51008 Rev.A | | Pick | PWC | TSB | 09.12.04 | | TSB PW100-520 | O | | | 3P |
| PWC64316 Rev.C | | Chisel, Rivet | PWC | TSB | 10.12.04 | | TSB PW100-521 | O | | | 3P |
| PWC38293 Rev.B | | Chisel, Rivet | PWC | TSB | 04.01.05 | 1 04.02.06 | TSB PW100-522 | O | | | 3P |
| PWC56606 Rev. B | | Cradle, Front Half Gearbox | PWC | TSB | 15.02.05 | | TSB PW100-526 | O | | | 3P |
| PWC56437 Rev. A | | Adadpter, Shaft | PWC | TSB | 17.03.05 | | TSB PW100-527 | O | | | 3P |
| PWC55933 Rev.B | | Anvil, Riveting | PWC | TSB | 07.03.05 | | TSB PW100-528 | O | | | 3P |
| PWC37488 Rev.C | | Drift, Airseal | PWC | TSB | 17.03.05 | | TSB PW100-529 | O | | | 3P |
| PWC54154 Rev.C | | Support Ring, No. 5 Brg. Cover | PWC | TSB | 12.04.05 | | TSB PW100-530 | O | | | 3P |
| PWC37446 Rev.D | | Fixture, Shaft | PWC | TSB | 16.06.05 | | TSB PW100-531 | O | | | 3P |
| PWC37701 Rev.B | | Adapter Lifting, Shaft | PWC | TSB | 20.06.05 | | TSB PW100-532 | O | | | 3P |
| PWC37912 Rev.B | | Puller, Bearing | PWC | TSB | 23.06.05 | | TSB PW100-533 | O | | | 3P |
| PWC70548 Rev.C | | Cable Assembly, DCU Adapter | PWC | TSB | 22.06.05 | | TSB PW100-534 | O | | | 3P |
| PWC30383 Rev.D | | Punch, Rivet | PWC | TSB | 20.06.05 | 1 12.01.06 | TSB PW100-535 | O | | | 3P |
| PWC51946 Rev.B | | Punch, Rivet | PWC | TSB | 20.06.05 | | TSB PW100-536 | O | | | 3P |
| PWC54147 Rev.G | | Crimper, Cupwasher | PWC | TSB | 27.06.05 | | TSB PW100-537 | O | | | 3P |
| PWC52078 Rev.C | | Rivet Support | PWC | TSB | 23.06.05 | | TSB PW100-538 | O | | | 3P |
| PWC37944 Rev.A | | Pad, Pinion Gear | PWC | TSB | 29.06.05 | | TSB PW100-539 | O | | | 3P |
| PWC54605 Rev.B | | Bridge, RGB | PWC | TSB | 30.06.05 | | TSB PW100-540 | O | | | 3P |
| PWC38020 Rev.B | | Drift, Bearing | PWC | TSB | 29.06.05 | | TSB PW100-541 | O | | | 3P |
| PWC54116 Rev.F | | Fixture, Gas Generator Case Assembly | PWC | TSB | 06.07.05 | | TSB PW100-542 | O | | | 3P |
| PWC56397 Rev. A | | Fixture, Source Control Drawing | PWC | TSB | 20.07.05 | | TSB PW100-543 | O | | | 3P |
| PWC56395 Rev. A | | Fixture, Source Control Drawing | PWC | TSB | 20.07.05 | 2 24.09.15 | TSB PW100-544 | O | | | 3P |
| PWC37929 Rev.D | | Adapter | PWC | TSB | 28.07.05 | | TSB PW100-545 | O | | | 3P |
| PWC51235 Rev.A | | Rivet Set, Blade Rivet | PWC | TSB | 22.11.05 | | TSB PW100-546 | O | | | 3P |
| PWC38292 Rev.P | | Fixture | PWC | TSB | 17.01.06 | 1 10.03.08 | TSB PW100-548 | O | | | 3P |
| PWC56634 Rev. A | | Drift, Prop Shaft | PWC | TSB | 12.05.06 | | TSB PW100-550 | O | | | 3P |
| PWC56633 Rev. A | | Drift, Prop Shaft | PWC | TSB | 12.05.06 | | TSB PW100-551 | O | | | 3P |
| PWC54746 Rev.C | | Guide, O-Ring | PWC | TSB | 02.06.06 | | TSB PW100-552 | O | | | 3P |
| PWC37577 Rev.E | | Cover, Blanking, Feathering Pump | PWC | TSB | 14.07.09 | | TSB PW100-554 | O | | | 3P |
| PWC37140 Rev.E | | Puller, PT Disc | PWC | TSB | 03.08.06 | | TSB PW100-556 | O | | | 3P |
| PWC54473 Rev.A | | Support Pinion | PWC | TSB | 04.08.06 | | TSB PW100-557 | O | | | 3P |
| PWC54489 Rev.A | | Roller Bearing Puller | PWC | TSB | 31.05.07 | | TSB PW100-559 | O | | | 3P |
| PWC51600 Rev.G | | Engine Components Stand | PWC | TSB | 07.02.07 | | TSB PW100-560 | O | | | 3P |
| PWC56178 Rev. B | | No. 3 Bearing Guide | PWC | TSB | 13.03.07 | | TSB PW100-563 | O | | | 3P |
| PWC64330 Rev.C | | Cooling Ring | PWC | TSB | 19.03.07 | | TSB PW100-564 | O | | | 3P |
| PWC38114 Rev.C | | Engine Assembly Support | PWC | TSB | 18.04.07 | | TSB PW100-565 | O | | | 3P |
| PWC38212 Rev.D | | Engine Rear Adapter | PWC | TSB | 31.05.07 | | TSB PW100-566 | O | | | 3P |
| PWC32516 Rev.B | | Hydraulic Cylinder Containment | PWC | TSB | 03.07.07 | | TSB PW100-567 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| PWC38212 Rev.D | | Engine Rear Adapter | PWC | TSB | 12.06.07 | 1 13.06.07 | TSB PW100-568 | O | | | 3P |
| PWC54746 Rev.C | | Guide | PWC | TSB | 12.06.07 | 1 15.06.07 | TSB PW100-569 | O | | | 3P |
| PWC67296 Rev.D | | Hydraulic Cylinder Containment | PWC | TSB | 13.06.07 | | TSB PW100-570 | O | | | 3P |
| PWC37806 Rev.D | | Hydraulic Cylinder Containment | PWC | TSB | 28.07.07 | | TSB PW100-571 | O | | | 3P |
| PWC56349 Rev. C | | Bearing Race Puller | PWC | TSB | 28.07.07 | | TSB PW100-572 | O | | | 3P |
| PWC54081 Rev.C | | Pusher, Stub Shaft | PWC | TSB | 13.06.07 | | TSB PW100-573 | O | | | 3P |
| PWC34300 Rev.G | | Engine Stand | PWC | TSB | 13.06.07 | | TSB PW100-574 | O | | | 3P |
| PWC56218 Rev. C | | Wrench, T& Thermocouple | PWC | TSB | 14.06.07 | | TSB PW100-575 | O | | | 3P |
| PWC90117 Rev.B | | Hydraulic Pump | PWC | TSB | 30.07.07 | | TSB PW100-576 | O | | | 3P |
| PWC32505 Rev.E | | Hydraulic Adapter | PWC | TSB | 30.07.07 | | TSB PW100-577 | O | | | 3P |
| PWC54281 Rev.C | | Stub Shaft Pusher | PWC | TSB | 14.11.07 | | TSB PW100-578 | O | | | 3P |
| PWC37949 Rev.B | | Turbine Disk Pusher | PWC | TSB | 30.07.07 | | TSB PW100-579 | O | | | 3P |
| PWC57404 Rev.B | | Lifting Bracket Rear Inlet Assermbly | PWC | TSB | 30.07.07 | | TSB PW100-580 | O | | | 3P |
| PWC56592 Rev. B | | Lifting Device Reduction Gearbox | PWC | TSB | 09.11.07 | | TSB PW100-581 | O | | | 3P |
| PWC89826 Rev.A | | Claamp - V-Band | PWC | TSB | 31.07.07 | 1 23.09.08 | TSB PW100-582 | O | | | 3P |
| PWC32610 Rev.B | | Container | PWC | TSB | 31.07.07 | | TSB PW100-583 | O | | | 3P |
| PWC86844 Rev.A | | Cylinder - Hydraulic Containment | PWC | TSB | 31.10.07 | | TSB PW100-584 | O | | | 3P |
| PWC89846 Rev.A | | Cylinder - Hydraulic Containment | PWC | TSB | 31.10.07 | | TSB PW100-585 | O | | | 3P |
| PWC38255 Rev.H | | Sling Reduction Gearbox | PWC | TSB | 02.11.07 | | TSB PW100-586 | O | | | 3P |
| PWC56255 Rev. B | | Adapter Grinding Turbine | PWC | TSB | 02.11.07 | | TSB PW100-588 | O | | | 3P |
| PWC37331 Rev.D | | Pusher | PWC | TSB | 15.01.08 | | TSB PW100-591 | O | | | 3P |
| PWC37108 Rev.J | | Support Engine Assembly | PWC | TSB | 23.11.07 | | TSB PW100-592 | O | | | 3P |
| PWC38057 Rev.C | | Fixture - Flow Nozzle | PWC | TSB | 28.11.07 | | TSB PW100-593 | O | | | 3P |
| PWC38059 Rev.C | | Fixture - Flow Nozzle | PWC | TSB | 16.11.07 | | TSB PW100-594 | O | | | 3P |
| PWC38062 Rev.C | | Fixture - Flow Nozzle | PWC | TSB | 16.11.07 | | TSB PW100-595 | O | | | 3P |
| PWC34277 Rev.D | | Support 30 Inch rail | PWC | TSB | 19.11.07 | | TSB PW100-596 | O | | | 3P |
| PWC37109 Rev.J | | Support Engine Assembly | PWC | TSB | 19.11.07 | | TSB PW100-597 | O | | | 3P |
| PWC34294 Rev.C | | Support Rail 30 Inch rail | PWC | TSB | 19.11.07 | | TSB PW100-598 | O | | | 3P |
| PWC54360 Rev.D | | Pusher HP Disc | PWC | TSB | 28.11.07 | | TSB PW100-599 | O | | | 3P |
| PWC37905 Rev.B | | Rod | PWC | TSB | 19.11.07 | | TSB PW100-600 | O | | | 3P |
| PWC89819 Rev.A | | V-Band Clamp 12 Dia V Vane Ring | PWC | TSB | 28.11.07 | 1 23.09.08 | TSB PW100-601 | O | | | 3P |
| PWC56606 Rev. C | | Container | PWC | TSB | 27.11.07 | | TSB PW100-602 | O | | | 3P |
| PWC54903 Rev.A | | Protecor | PWC | TSB | 27.11.07 | | TSB PW100-606 | O | | | 3P |
| PWC54617 Rev.A | | Filter Container | PWC | TSB | 28.11.07 | | TSB PW100-610 | O | | | 3P |
| PWC37799 Rev.A | | Inspection Manual Boroscope | PWC | TSB | 28.11.07 | | TSB PW100-611 | O | | | 3P |
| PWC89845 Rev.A | | Cylinder - Hydraulic Containment | PWC | TSB | 11.12.07 | | TSB PW100-612 | O | | | 3P |
| PWC89827 Rev.A | | V-Band Clamp 17 Dia V Vane Ring | PWC | TSB | 16.12.07 | 1 22.09.08 | TSB PW100-613 | O | | | 3P |
| PWC89829 Rev.A | | V-Band Clamp 22 Dia Vane Ring | PWC | TSB | 11.12.07 | 1 22.09.08 | TSB PW100-614 | O | | | 3P |
| PWC89837 Rev.A | | Cylinder - Hydraulic Containment | PWC | TSB | 11.12.07 | | TSB PW100-615 | O | | | 3P |
| PWC89843 Rev.A | | Hydraulic Cylinder Containment | PWC | TSB | 11.12.07 | | TSB PW100-616 | O | | | 3P |
| PWC32506 Rev.K | | Hydraulic Cylinder Containment | PWC | TSB | 11.12.07 | | TSB PW100-617 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| PWC37939 Rev.B | | Sling, P.T Rotor | PWC | TSB | 11.12.07 | | TSB PW100-618 | O | | | 3P |
| PWC37076 Rev.E | | Trunnion | PWC | TSB | 11.12.07 | | TSB PW100-619 | O | | | 3P |
| PWC56158 Rev. A | | Support | PWC | TSB | 09.01.08 | | TSB PW100-620 | O | | | 3P |
| PWC56396 Rev. C | | Master Blade | PWC | TSB | 31.12.07 | | TSB PW100-621 | O | | | 3P |
| PWC37111 Rev.C | | Adapter | PWC | TSB | 31.12.07 | | TSB PW100-623 | O | | | 3P |
| PWC37110 Rev.E | | Adapter | PWC | TSB | 31.12.07 | | TSB PW100-624 | O | | | 3P |
| PWC38001 Rev.C | | Adapter | PWC | TSB | 31.12.07 | | TSB PW100-625 | O | | | 3P |
| PWC56807 Rev..A | | Grinding Fixture | PWC | TSB | 09.01.08 | | TSB PW100-626 | O | | | 3P |
| PWC37771 Rev.A | | Nozzle Turbine Wash | PWC | TSB | 29.01.08 | | TSB PW100-627 | O | | | 3P |
| PWC89828 Rev.A | | V-Band Clamp 22 Dia Vane Ring | PWC | TSB | 18.02.08 | 1 22.09.08 | TSB PW100-628 | O | | | 3P |
| PWC38064 Rev.C | | Fixture - Flow Nuzzle | PWC | TSB | 14.01.08 | | TSB PW100-629 | O | | | 3P |
| PWC80063 Rev.B | | Trust Calibration Frame Weldment | PWC | TSB | 19.01.08 | | TSB PW100-630 | O | | | 3P |
| PWC80064 Rev.A | | Tie Rod | PWC | TSB | 19.01.08 | | TSB PW100-631 | O | | | 3P |
| PWC80044 Rev. A | | Bracket Trust Calibration | PWC | TSB | 20.01.08 | | TSB PW100-632 | O | | | 3P |
| PWC54164 Rev. C | | Base Disk | PWC | TSB | 20.01.08 | | TSB PW100-633 | O | | | 3P |
| PWC56510 Rev. A | | Master Balde | PWC | TSB | 03.02.08 | | TSB PW100-634 | O | | | 3P |
| PWC32513 Rev.F | | Trunion | PWC | TSB | 03.02.08 | | TSB PW100-635 | O | | | 3P |
| PWC32677 Rev.H | | Engine Wash | PWC | TSB | 18.02.08 | 1 14.07.09 | TSB PW100-636 | O | | | 3P |
| PWC56509 Rev. C | | Master Blade | PWC | TSB | 18.02.08 | | TSB PW100-637 | O | | | 3P |
| PWC56202 Rev. D | | Rivet Squeezer | PWC | TSB | 04.02.08 | | TSB PW100-638 | O | | | 3P |
| PWC56249 Rev. A | | Puller Turbine | PWC | TSB | 05.03.08 | | TSB PW100-639 | O | | | 3P |
| PWC59051 Rev.A1 | | Weight Attach Kit | PWC | TSB | 20.03.08 | | TSB PW100-641 | O | | | 3P |
| PWC38084 Rev.D | | Sling Inlet Case | PWC | TSB | 14.07.08 | | TSB PW100-642 | O | | | 3P |
| PWC71171 Rev.A | | Source Control | PWC | TSB | 16.07.08 | | TSB PW100-643 | O | | | 3P |
| PWC37808 Rev.A | | Gauge | PWC | TSB | 23.07.08 | | TSB PW100-644 | O | | | 3P |
| PWC64918 Rev.B | | Melting Pot Dropper | PWC | TSB | 26.07.08 | | TSB PW100-645 | O | | | 3P |
| PWC80004 Rev.C | | Bolt Share 0.312 - Engine Mount | PWC | TSB | 01.09.08 | | TSB PW100-646 | O | | | 3P |
| PWC54145 Rev.A | | Holder LP Rotor Assembly | PWC | TSB | 01.09.08 | | TSB PW100-649 | O | | | 3P |
| PWC54282 Rev.D | | Scribber Bearing | PWC | TSB | 14.09.08 | | TSB PW100-650 | O | | | 3P |
| PWC523 44 Rev.E | | Anvil Presure Settings | PWC | TSB | 25.08.08 | | TSB PW100-651 | O | | | 3P |
| PWC31892 Rev.K | | Riveting Machine | PWC | TSB | 26.08.08 | | TSB PW100-652 | O | | | 3P |
| PWC54572 Rev.C | | Fixture - Lifting Torque Shaft - Input Shaft Set | PWC | TSB | 13.10.08 | | TSB PW100-654 | O | | | 3P |
| PWC56605 Rev. B | | Assembly Drift | PWC | TSB | 13.10.08 | | TSB PW100-655 | O | | | 3P |
| PWC34200 Rev.E | | Stand Engine Assy | PWC | TSB | 13.10.08 | | TSB PW100-656 | O | | | 3P |
| PWC90203 Rev.A | | Low Temp Heat Gun | PWC | TSB | 24.09.08 | | TSB PW100-657 | O | | | 3P |
| PWC90075 Rev.C | | Low Temp Heat Gun | PWC | TSB | 24.09.08 | | TSB PW100-658 | O | | | 3P |
| PWC37471 Rev.G | | Gauge - Radius | PWC | TSB | 20.10.08 | | TSB PW100-659 | O | | | 3P |
| PWC89867 Rev.A | | DB25 To RS-232 Adapter | PWC | TSB | 20.10.08 | | TSB PW100-660 | O | | | 3P |
| PWC40600 Rev.C | | Adapter - AGB Breather | PWC | TSB | 29.10.08 | | TSB PW100-662 | O | | | 3P |
| PWC54213 Rev.F | | Adapter | PWC | TSB | 20.12.08 | | TSB PW100-663 | O | | | 3P |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| PWC56264 Rev. A | | Comparator | PWC | TSB | 29.01.09 | | TSB PW100-664 | O | | | 3P |
| PWC54934 Rev.C | | Lifting Fixture | PWC | TSB | 29.01.09 | | TSB PW100-665 | O | | | 3P |
| PWC37486 Rev.D | | Pusher - Puller | PWC | TSB | 29.01.09 | 1 31.03.09 | TSB PW100-666 | O | | | 3P |
| PWC54243 Rev.H | | Gauge - Runout Gas Gen Case | PWC | TSB | 17.02.09 | | TSB PW100-667 | O | | | 3P |
| PWC56434 Rev. A | | Lifting Bracket | PWC | TSB | 14.03.09 | | TSB PW100-668 | O | | | 3P |
| PWC41150 Rev.C | | Adapter Dyno - Torque Wrench | PWC | TSB | 04.04.09 | | TSB PW100-669 | O | | | 3P |
| PWC38081 Rev.B | | Bracket Engine Mount | PWC | TSB | 15.05.09 | | TSB PW100-673 | O | | | 3P |
| PWC56433 Rev. A | | Sling | PWC | TSB | 25.06.09 | | TSB PW100-675 | O | | | 3P |
| PWC56617 Rev. A | | Special Wrench | PWC | TSB | 27.05.09 | | TSB PW100-676 | O | | | 3P |
| PWC56433 Rev. A | | Lifting Sling | PWC | TSB | 27.05.09 | | TSB PW100-677 | O | | | 3P |
| PWC52078 Rev.D | | Support, Rivet | PWC | TSB | 09.07.09 | | TSB PW100-678 | O | | Tool replaced by PWC52838 | 3P |
| PWC37641 Rev.D | | Drift Bearing | PWC | TSB | 31.01.11 | | TSB PW100-687 | O | | | 3P |
| PWC37643 Rev.C | | Puller | PWC | TSB | 03.02.11 | | TSB PW100-688 | O | | | 3P |
| PWC40261 Rev.C | | Crimper | PWC | TSB | 03.02.11 | | TSB PW100-691 | O | | | 3P |
| PWC56591 Rev. B | | Lifting Device PT Rotor | PWC | TSB | 16.02.11 | | TSB PW100-692 | O | | | 3P |
| PWC54605 Rev.C | | Bridge - RGB | PWC | TSB | 16.02.11 | | TSB PW100-693 | O | | | 3P |
| PWC54205 Rev.B | | Rod | PWC | TSB | 16.02.11 | | TSB PW100-694 | O | | | 3P |
| PWC56249 Rev. B | | Puller - Turbine | PWC | TSB | 11.01.13 | | TSB PW100-735 | O | | | 3P |
| PWC45051 Rev. A | | Manifold | PWC | TSB | 01.10.13 | | TSB PW100-743 | O | | | 3P |
| PWC37976 Rev. F | | Probe | PWC | TSB | 10.01.14 | | TSB PW100-747 | O | | | 3P |
| | | Cooling Ring | PWC | TSB | 22.12.14 | | TSB PW100-754 | O | | | 3P |
| | | Riveter | PWC | TSB | 04.05.15 | | TSB PW100-757 | O | | | 3P |
| PWC89863 Rev. F | | Riveter | PWC | TSB | 21.05.15 | | TSB PW100-758 | O | | | 3P |
| PWC90035 | | Converter Card | PWC | TSB | 11.06.15 | | TSB PW100-759 | O | | | 3P |
| PWC54576 | | Fixture Prop Jammer | PWC | TSB | 21.12.15 | | TSB PW100-760 | O | | | 3P |
| PWC37429 | | Tool Modification | PWC | TSB | 20.01.16 | | TSB PW100-761 | O | | | 3P |
| PWC71427 | | Riveting Fixture | PWC | TSB | 13.09.16 | 1 19.01.21 | TSB PW100-763 | O | | | 3P |
| PWC71427 | | Tool Modification | PWC | TSB | 16.03.17 | | TSB PW100-767 | O | | | 3P |
| PWC45322 Rev. A | | Tool Introduction | PWC | TSB | 02.08.19 | | TSB PW100-782 | O | | PWC37370 cannot be used for POST-SB21936 | 3P |
| PWC37825 | | Tool Modification | PWC | TSB | 04.03.20 | | TSB PW100-783 | O | | | 3P |
| PWC38278 Rev. D | | Tool obsolete | PWC | TSB | 11.05.20 | | TSB PW100-784 | O | | Tool is no longer required | 3P |
| PWC89843 Rev. B | | Tool Modification | PWC | TSB | 31.07.20 | | TSB PW100-785 | O | | | 3P |
| PWC56854 Rev. A | | Sling - Inlet case | PWC | TSB | 14.09.21 | | TSB PW100-792 | O | | | 3P |
| PWC56179 Rev. F | | Regular Drift Seal | PWC | TSB | 26.05.22 | | TSB PW100-793 | O | | | 3P |
| | | Pricelist f.Commercial Publications | PWC | BROCHURE | 01.01.03 | | VDN-0203 | O | | | 3A |
| | | Customer Training | PWC | BROCHURE | 01.04.00 | | VDN-0204 | O | | | 3A |
| | | Customer Support | PWC | BROCHURE | 01.06.95 | | VDN-0205 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | P&WC Engines - Intern.Support Facilities | PWC | BROCHURE | 01.08.08 | | VDN-0207 | O | | | 3A |
| FE217-004 | 27-70-05 | Rudder Damper Conversion FE217-004 to FE255-000 | RATIER FIGEAC | SB | 20.04.01 | | SB FE217-27-01 | O | | | 3P |
| 85100-3 | 30-13-06 | Ejector Flow Valve | ROGERSON | SB | 15.12.95 | | 85100-30-01 | O | | | 3P |
| 011390-500 | 21-22-01 | Air Conditioning - Grommet | ROTRON | SB | 03.10.97 | | SB 011390500-21-1 | O | | AMETEK | 3A |
| | | CONSUMABLE MATERIALS LIST | SAFRAN | CML | | 6 08.09.20 | VDN-0410 | S | | SAFRAN LANDING SYSTEMS | 3A |
| Latch P/N 090855-002 | | Inspection and tightening of the battery box cover latch assemblies | SAFT | SB | | A 16.11.20 | SB 0516 | O | | | 3A |
| 8409/-1/-2/-3 | 27-32-01 | Modification Pitch Trim Actuator | SAGEM (AVIAC) | SB | 29.11.00 | | 8409-27-01 | O | | SAGEM | 3A |
| | | Organization Of Avionics Customer Support in Sagem SA Company | SAGEM (AVIAC) | SIL | 10.01.03 | 2 10.06.05 | SIL USC_ALL-1001 | O | | SAGEM | 3A |
| | | General Repair Procedure AVC 09 001 Application | SAGEM (AVIAC) | SIL | 18.10.08 | | SIL USC-ALL-1003 | O | | SAGEM | 3A |
| | | Tech Pub and Website Access | SAGEM (AVIAC) | SIL | 30.06.08 | 2 04.12.10 | SIL USC-ALL-1004 | O | | SAGEM | 3A |
| 001A761A1130016 | | Cable Assy Flight Hours Limitation a.Repl. | SARMA | SB | 21.01.02 | | 001A761A1130016-27-001 | O | | | 3P |
| 328100-1 M02 | | Cable Tens. Regul. Elevator Contr | SARMA | SB | 22.05.00 | | 328100-27-002 | O | | | 3A |
| 328100-1/-2 | | Cable Tension Regulator | SARMA | SB | 10.10.95 | | 328100-27-01 | O | | | 3A |
| 328300-1 M02 | | Cable Tens. Regul. Aileron Contr. | SARMA | SB | 22.05.00 | | 328300-27-001 | O | | | 3A |
| 328300-1M01MB | | Cable Tens. Regul. Aileron Contr. | SARMA | SB | 15.06.00 | | 328300-27-002 | O | | | 3A |
| 85-3864 | | Valve, Float Vent / O-Ring Replacement | SHAW | SB | 31.08.98 | | 853864-28-001 | O | | | 3A |
| | | Naviagation - Standby Compass 'Lead and socket assembly' possible insulation resistance failure | SIRS NAVIGATION | SB | | 4 09.11.15 | CE2-A26-34-001 | O | | | 3A |
| 6033-01-1 | 28-48-04 | Signal Proc.a.Refueling Panel Mod.A | SMITHS INDUSTRIES | SB | 16.03.00 | 1 22.02.01 | SB 6033-28-1 | O | | ONTIC | 3P |
| 6033-01-1 | 28-48-04 | Signal Proc.a.Refueling Panel Mod.B | SMITHS INDUSTRIES | SB | 22.02.01 | | SB 6033-28-2 | O | | ONTIC | 3P |
| 6033-01-1 | 28-48-04 | Signal Proc.a.Refueling Panel Mod.C | SMITHS INDUSTRIES | SB | 22.02.01 | | SB 6033-28-5 | O | | ONTIC | 3P |
| 6033-01/02-1/2 | 28-48-04 | Signal Proc.a.Refuel Panel Bite Error Reports | SMITHS INDUSTRIES | SIL | 01.12.00 | | SIL 28-47 | O | | ONTIC | 3A |
| WL1001KCA1 | 34-25-21 | Standby Compass.Transfer of Supp. Resp. | SMITHS INDUSTRIES | SIL | 01.06.04 | | SIL 34-47 | O | | | 3A |
| | | Change to AOG Service | SMITHS INDUSTRIES | SIL | 01.11.02 | | SIL GEN-14 | O | | | 3A |
| | | Transf.of Rep.Station from Rockford to Clearwater | SMITHS INDUSTRIES | SIL | 01.01.05 | 1 01.03.05 | SIL GEN-17 | O | | | 3A |
| | | Transf.of Rep.Station Yorba Linda to Clearwater | SMITHS INDUSTRIES | SIL | 01.01.05 | 1 01.03.05 | SIL GEN-18 | O | | | 3A |
| | | Relocation of SMITH AEROSPACE CSO | SMITHS INDUSTRIES | SIL | 28.04.02 | 1 11.11.02 | SIL-GEN-13 | O | | | 3A |
| | | Change of Name from Smith Aerosp.to GE Aviation | SMITHS INDUSTRIES | SIL | 01.10.07 | | SIL-GEN-28 | O | | GE AVIATION | 3A |
| WL101AMS1 | 34-11-01 | Altimeter/Airspeed Indicator | SMITHS INDUSTRIES | SB | 17.02.97 | 1 14.08.00 | WL101AMS-34-877 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| WL101AMS1 | 34-11-01 | Repl.of Oscillator Module | SMITHS INDUSTRIES | SB | 17.07.00 | | WL101AMS-34-879 | O | | | 3A |
| ELT96/97A2560000000 | 25-61-02 | Emergency Locator Transmitter | SOCATA | SB | 01.12.95 | | SB ELT-001 | O | | AIR PRECISION | 3A |
| 10839X | 73-10-08 | Inst.of Fixed/Sliding Sleeves, Therm.Elements | STEWART WARNER | SB | 15.10.92 | 4 19.01.00 | 10839-73-01 | O | | | 3P |
| 10839X | 73-10-08 | Fuel Heater - Rework The Mounting Feet | STEWART WARNER | SB | 15.06.94 | 2 31.10.95 | 10839-73-03 | O | | | 3P |
| 10839X | 73-10-08 | Rework of Fuel Heater Filter Can | STEWART WARNER | SB | 01.07.94 | 5 19.01.00 | 10839-73-04 | O | | | 3P |
| 10839X | 73-10-08 | One Time Insp.-Correct Caution Label/Preform.Packing | STEWART WARNER | SB | 17.08.95 | 2 19.01.00 | 10839-73-05 | O | | | 3P |
| 10839X | 73-10-08 | Fuel Haeter - Replace Thermal Elemet | STEWART WARNER | SB | 17.08.95 | 3 19.01.00 | 10839-73-06 | O | | | 3P |
| 10839X | 73-10-08 | Fuel Heater Change Thermal Element | STEWART WARNER | SB | 01.12.96 | 5 19.01.00 | 10839-73-07 | O | | | 3P |
| 4326058/65 | 30-41-03 | MOTOR-Converter LH/RH | TELEFLEX | SB | 20.10.94 | | 30-108 | O | | ZODIAC | 3P |
| 4337122/38 | 30-41-03 | MOTOR-Converter LH/RH | TELEFLEX | SB | 20.10.94 | | 30-124 | O | | ZODIAC | 3A |
| P/N 8160-121 | | Modification of Starter Generator | THALES | SB | 13.10.15 | | SB8160-121-24-009 | O | | | 3A |
| | | Consumables Obsolesence | THALES | SIL | 23.03.15 | 1 26.04.16 | SIL 24-99-005 | O | | | 3A |
| | | Publications Index | THALES | INDEX | 01.01.18 | | VDN-0477 | O | | AUXILEC | 3A |
| | 25-30-XX | Tech Pub Revision Status Index | TIA | SIL | 25.07.14 | | SL-NA-025 | S | | ZODIAC | 3A |
| 26360-1, 26370-1 | 73-10-15 | Flow Divider a.Dump Valve-New Packing | TRW / LUCAS | SB | 15.02.93 | | SB 199500-73-1 | O | | IPC P&WC | 3P |
| 26250, 26260 | 73-10-15 | Flow Div.a.Dump Valve-Impr.Manufact.Process | TRW / LUCAS | SB | 15.06.93 | | SB 199500-73-2 | O | | IPC P&WC | 3P |
| 25910-06 | 73-10-08 | EFC-Spring a.improv.Corr.Resist.Body Assy | TRW / LUCAS | SB | 30.09.91 | 1 30.05.92 | SB 25910-73-1 | O | | IPC P&WC | 3P |
| 25910-07 | 73-10-08 | EFC-Intro.of redesigned Gasket | TRW / LUCAS | SB | 17.04.95 | | SB 25910-73-3 | O | | IPC P&WC | 3P |
| 25910-5 to -8 | 73-10-08 | Ejec.Pump a.Tank Assy-Temp.Cleaning | TRW / LUCAS | SB | 26.02.99 | 1 27.10.99 | SB 25910-73-4 | O | | IPC P&WC | 3P |
| 25910-6 to -8 | 73-10-08 | Ejec.Pump a.Tank Assy-Stainl.Steel Body | TRW / LUCAS | SB | 31.03.01 | | SB 25910-73-5 | O | | IPC P&WC | 3P |
| 5009986C | 73-10-07 | EFC-Repl.of Ex.Different.Pressure Switch | TRW / LUCAS | SB | 26.02.99 | 1 30.09.99 | SB 5009986-73-4 | O | | IPC P&WC | 3P |
| 5009986C | 73-10-07 | Power Driven Rotary Fuel Pump-Outlet Filter Insp. | TRW / LUCAS | SB | 26.01.04 | 1 29.06.04 | SB 5009986-73-5 | O | | GOODRICH CONTROL SYST. | 3P |
| 26360-1 | 73-10-15 | Flow Divider & Dump Valve | TRW / LUCAS | SIL | 20.01.94 | | SIL FDPW100-1/94 | O | | IPC P&WC | 3P |
| 26360-1 | 73-10-15 | Flow Divider & Dump Valve | TRW / LUCAS | SIL | 15.06.95 | | SIL FDPW100-1/95 | O | | IPC P&WC | 3P |
| 5006488 | 73-10-07 | Support Program for Spline Insp. | TRW / LUCAS | SIL | 01.01.93 | 2 01.09.95 | SIL MFP120-1 | O | | IPC P&WC | 3P |
| 5006488 | 73-10-07 | Differential Pressure Switch Repair | TRW / LUCAS | SIL | 20.07.00 | | SIL MFP120-2 | O | | IPC P&WC | 3P |
| 25910 | 73-10-08 | CSP for Introd.of Stainless Steel Body | TRW / LUCAS | SIL | 04.10.01 | | SIL-EPT300-1 | O | | IPC P&WC | 3P |
| | | Revision Service | VARIOUS | | 31.07.08 | 179 30.05.23 | CMM-V Set | O | R | | 3A |
| | 28-XX-XX | Replacement of Dartoline SF41B | ZODIAC SERVICES | SIL | 10.10.11 | | 001-28-01 | O | | | 3A |
| | 28-XX-XX | Replacement of Deoxidine D31 | ZODIAC SERVICES | SIL | 10.05.12 | | 003-28-01 | O | | | 3A |

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | REV./Date | Doc.-No | S=Standard O=optional | R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | 28-XX-XX | Manufacture of the sealant PR-1422 is stopped in the European Union but continues in the United States | ZODIAC SERVICES | SIL | 14.05.14 | 1 | 004-28-01 | O | | | 3A |
| | 28-XX-XX | Modification of the cleaning procedure | ZODIAC SERVICES | SIL | 08.10.12 | | 005-28-01 | O | | | 3A |
| | 28-XX-XX | Product obsolescence | ZODIAC SERVICES | SIL | 09.04.13 | | 006-28-01 | O | | | 3A |
| | 28-XX-XX | Reference Change | ZODIAC SERVICES | SIL | 09.04.13 | | 007-28-01 | O | | | 3A |
| | 28-XX-XX | Replacement of Alodine 600 / 1200 / 1500 | ZODIAC SERVICES | SIL | 16.01.15 | 1 30.03.15 | 009-28-01 | O | | | 3A |
| | 30-XX-XX | Moto converter (P/N 4337122 LH and 4337138 RH) | ZODIAC SERVICES | SIL | 01.06.97 | | 30-174 | O | | | 3A |

# ANNEX

# A

# IN WORK

| PartNo | Chapter | Nomenclature | Vendor | Doc.-Title | Issue | Rev./Date | Doc.-No | S=Standard O=optional R= Revision | REMARKS | *Version |
|---|---|---|---|---|---|---|---|---|---|---|
| | TBD | | 328 SSG | FOI-328-31-014 | | | FOI-328-X | S | in work | 3P |
| | TBD | | 328 SSG | SI-328-61-155 | | | SI-328-X | S | in work | 3P |
| | TBD | | 328 SSG | SI-328-00-156 | | | SI-328-X | S | in work | 3P |
| | TBD | | 328 SSG | EO-328-34-358 | | | EO-328-X | S | in work | 3P |
| | TBD | | 328 SSG | EO-328-31-364 | | | EO-328-X | S | In work | 3P |
| | TBD | | 328 SSG | SB-328-31-556 | | | SB-328-X | S | in work | 3P |
| | TBD | | 328 SSG | SB-328-52-561 | | | SB-328-X | S | in work | 3P |