


PCK-PT/PF

PT and PF Series Power and End Termination Kit

Ordinary and Hazardous locations
Class I, Division II, Groups B, C, and D



DESCRIPTION

PCK-PT/PF allows you to make electrical connections to the PT and PF series PowerTrace constant wattage heater cable. The kit contains materials for one power termination and one end termination.

HEATER ZONE MARKERS

The heater zone markers for the PT cable are raised bumps on the cable edge. The markers on the PF cable may be raised bumps or slight depressions on the cable edge.

ITEMS REQUIRED BUT NOT SUPPLIED

- Weather-Tight Junction Box, With .75" (2cm) NPT Hubs.
- Conduit

TOOLS REQUIRED

- Crimping Tool
- Wire Stripper/Cutter
- Utility Knife
- Screw Drivers
- Needle Nose Pliers
- Adjustable Wrench
- Measuring Tape

- | | |
|-----------------------|--|
| A. Aluminum Stand Off | F. #12-10 Non-Insulated Butt Splice (2) |
| B. Silicone Tape (4) | G. Silicone End Cap .5" x 1.5" (1 x 4cm) |
| C. Silicone Sealant* | H. Stainless Steel Pipe Strap (2) |
| D. Caution Label | I. .5" x 4" Fiberglass Tape |
| E. Ring Connector | |

*California Prop 65 compliant.