

JGE INC
 5856 E Highway 12
 Aberdeen, SD 57401
 605-229-4037
 jaredgross@jgeinc.com
 www.jgeinc.com

Invoice



BILL TO
Arbor Pro Equipment Arbor PRO Equipment 38576 127th St Aberdeen, SD 57401

SHIP TO
Arbor Pro Equipment Arbor PRO Equipment 38576 127th St Aberdeen, SD 57401

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
29482	08/06/2021	\$0.00	09/05/2021	Net 30*	

AT JGE OR OFF SITE?
 JGE

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
Customer-BG56	Mustang 2109 SN#MMC02109C00802553 Hrs:830 CONCERN: NOT PULLING FUEL/WON'T START Test operation, found fuel system was not pulling fuel properly from the tank, inspect and clean all components, remove and replace fuel suction hose, install pick up screen, confirm operation.	1	440.62	440.62T
Customer-BG56	CONCERN:HYDRAULIC LEAK Replace hose on RH rear side of boom, wash oil mess, check and fill oil, test operation.	1	251.44	251.44T
Customer-BG56	CONCERN:ENGINE FAULT CODE Connect to machine with software to fault for warning light, found air intake temp sensor fault code, tested harness and all possible causes, determined sensor failure, remove and replace sensor, fault code went inactive and light went out, also check/confirm engine hours, hours on engine match hour meter.	1	318.00	318.00T
Customer-BG56	CONCERN:A/C NOT WORKING Check a/c, system was low on freon, charged freon, a/c works properly, doesn't seem to leak at this time but if system loses freon again it may require more trouble-shooting	1	81.17	81.17T
Customer-BG56	CONCERN:ENGINE BELT(S) Remove and replace dual engine belts.	1	93.03	93.03T
Customer-BG56	CONCERN:LIGHTS NOT WORKING Repair lights and make sure they all work	1	120.00	120.00T
Customer-BG56	CONCERN:LAP BAR IS LOOSE Raise cab, adjust/tighten lap bar hardware, test operation.	1	120.00	120.00T
JG55	CONCERN: STRAIGHTEN DOOR IF POSSIBLE Removed door, removed broken plexy glass, straightened frame, reinstalled door.	1	120.00	120.00T

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
INSPECTION-FULL MACHINE	COMPLETE JGE 80+ POINT INSPECTION FORM, (SAVED ON FILE) **INSPECTION DOES NOT INCLUDE ANY REPAIRS**ANY REPAIRS NEEDED WILL BE PREPARED IN ESTIMATE FORM AND PRESENTED TO CUSTOMER**	1	125.00	125.00T
ELECTRONIC TOOLING FEE	ELECTRONIC TOOLING FEE	1	60.00	60.00T
3/16 Fuel Line	3/16 Fuel Line	1	3.80	3.80T
073024	Bushing/Fuel Tank	1	1.05	1.05T
6650239	Screen, Fuel Tank	1	9.00	9.00T
139530	Light Bulb 35w	1	6.38	6.38T
184233	Strip/Trim 11.5"	1	4.93	4.93T
184867	Side Cover Ass. RT	1	133.10	133.10T
137783*	Hydraulic Hose Assembly	1	28.95	28.95
241958	Red Light	1	20.30	20.30T
9580HD	HIGH CAPACITY V-BELT	2	34.99	69.98T
2874A018	Temp Sensor	1	51.07	51.07T
2415H003	O-Ring	1	2.25	2.25T
Freight-Inbound	Inbound freight charged to customer	1	77.52	77.52T
Anti-Freeze	MOBIL PREMIUM ANTIFREEZE 50/50 RED	0.50	16.93103	8.47T
Fluid Hydraulic	MOBIL PREMIUM DTE 10 EXCEL 46	6	25.55	153.30T
Fluid Fuel Diesel	Diesel Fuel	3	4.33	12.99T
Freon	Freon per can	1	9.99	9.99T
Service MISC-1	CONSUMABLE SUPPLIES	1	46.45	46.45T
Service MISC-2	HAZ WASTE DISPOSAL	1	23.22	23.22T
	DISCLAIMER OF WARRANTIES-Due to age and or hours this machine carries no warranty coverage for failures, the only warranties applying to this repair are those of the part(s) warranty which may or may not be offered by the manufacturer of the part(s).			

SUBTOTAL	2,392.01
TAX (0%)	0.00
TOTAL	2,392.01
PAYMENT	2,392.01
BALANCE DUE	\$0.00