



VP4300 Lite 1TB/2TB Firmware Updates_ Release Note

In a recent investigation post-launch, Patriot Memory has found thermal reporting errors with the VP4300 Lite's current firmware (H230407a). These errors are incorrectly displaying higher than actual temperatures within monitoring applications while temperature and performance are within normal specs. Due to this, the Patriot Memory team has worked with the flash controller manufacturer to prepare a firmware update set to correct the thermal information passed to monitoring applications.

This error is found to occur in VP4300 Lite units with the following serial numbers:

1TB: 022305291000001-022305291000500

2TB: 022305291200001-022305291200500

For VP4300 Lite users with units featuring one of the listed serial numbers above, Patriot Memory is providing a firmware update to resolve thermal reporting errors. In order to install the new firmware update (H230407b), please visit Patriot Memory's VP4300 Lite page at <https://viper.patriotmemory.com/products/viper-vp4300lite-pcie-m-2-gen4x4-solid-state-drive>.

In addition to this, all VP4300 Lite units released outside of the listed serial numbers will have the new firmware (H230407b) installed and will not experience this problem. Patriot Memory does not recommend installing the update to any VP4300 Lite drives outside of the affected serial numbers listed.

About Patriot Memory™

Patriot Memory is a leading manufacturer of high-performance, enthusiast memory modules, SSDs, flash storage and gaming peripherals. Founded in 1985, Patriot is committed to technology innovation, customer satisfaction and providing the best price for performance on the market. Patriot products have become world-renowned for their extreme performance, reliability and innovation. Patriot sells its products through original equipment manufacturers, retailers, e-tailers and distributors throughout the world, with operations in North America, South America, Asia and Europe.