

Sensor

Weight	½ 1lb (8 oz)
Power supply	9V battery lithium
Range	up-to 1 mile away (line of site)



Installation Steps:

- 1 Connect the sensor to the instrument being monitored.
- 2 Make sure the sensor and instrument are within a 1 mile line of site range of the collector (in commercial and industrial settings range may be closer). Reading delivery will start within 24 hours.
- 2a If you would like readings to come in within 1 hour, open the unit up with a t-10 screwdriver. Remove the 9v battery from the sensor for 30 seconds and re-install. Close up the sensor enclosure.
- 3 If you have issues with readings coming into the dashboard, or if you want to ensure the units are within range of each other, please follow the “Range Check” guide.
- 4 Contact VMG for your new account site setup and to be able to login to view your readings.

You will need to provide us with:

- Sensor ID number (on the back label of the sensor starting with the letter N)
- Tank size
- Instrument type
- Product being monitored

We can create as many user logins as you like with different access levels and provide any other training needed.



VMG.us.com

NWBOC Certified

Woman Owned Business

Dave Zellen

Director of Business Development

Cell: (513) 526-9127

Dave@VMG.us.com

Mike Ahrens

Technical Lead

Office: (513) 936-5910 ext 103

Cell: 513-346-0918

Mikey@VMG.us.com