




PT-T3SL

PT and PF Series 3-Way Tee Splice Kits



GENERAL

PT-T3SL allows you to make one three-way splice to the PT and PF series Powertrace constant wattage heater cable. The splice is to be located in an appropriately rated junction box. This product has a T6 temperature rating.

HEATER ZONE MARKERS

The cable markers for the PT cable are raised bumps on the cable edge. The markers on the PF cable may be raised bumps or slight depressions on the cable edge.

ITEMS REQUIRED BUT NOT SUPPLIED

- Weather-tight junction box, with 3/4" NPT hubs.
- Silicone sealant (RTV).

TOOLS REQUIRED

- Crimping Tool
- Wire Stripper/Cutter
- Utility Knife
- Screw Drivers
- Needle Nose Pliers
- Adjustable Wrench
- Measuring Tape



CONTENTS

Quantity - Description

- 1 - Aluminum Stand-off
- 2 - Stainless Steel Pipe straps (1" - 4")*
- 3 - #12-10 Insulated 3 way butt connectors
- 3 - Silicone tape (4")
- 1 - Caution Label small

*also available in 3" - 8"