




ETK-PT/PF

PT and PF Series End Termination Kits



CONTENTS:

ETK-PT/PF (for 1 splice) includes

- 1 Silicone End Cap
- 1 - 6" Silicone Tape
- 1 - 4" Fiberglass Tape

ETK-PT/PF-5 (for 5 splices) includes:

- 5 Silicone End Cap
- 5 - 6" Silicone Tape
- 5 - 4" Fiberglass Tape

GENERAL

The ETK-PF/PT allows you to make one electrical end termination to the PT or PF series Powertrace constant wattage heater cable. The ETK-PT/PF contains materials for one end termination. The ETK-PT/PF-5 is five kits for five end terminations.

The termination can be made on the pipe for temperature ranges up to 260 oF. Higher pipe temperatures require that the termination be made off the pipe in a junction box (See items below).

HEATER ZONE MARKERS

The End Cap is typically installed 4" from a zone marker. The zone markers for the PT cable are raised bumps on the cable edge. The markers on the PF cable may be raised bumps, or slight depressions on the cable edge.

ITEMS REQUIRED IF END TERMINATION IS OFF THE PIPE

- Weather-tight junction box, 3/4" NPT hubs
- STK-AL (Stand-off)

TOOLS REQUIRED

- Wire Cutter
- Utility Knife
- Measuring Tape



WARNING: This kit and the cable used with it must be installed by a qualified electrician. All assembly, installation, and test instructions must be followed. Improper installation can result in property damage, serious injury, and/or death due to electric shock and fires.

Please call Delta-Therm Corp. at 800-526-7887 with installation or operating questions.