


Midline Tissue Damage Study of PhotonBlade vs. Other Electrosurgical Devices



Reference: Raw data from RPT 12754

Electrosurgical Device