

JGE INC
 5856 E Highway 12
 Aberdeen, SD 57401
 605-229-4037
 jaredgross@jgeinc.com
 www.jgeinc.com

Invoice



BILL TO
Arbor Pro Equipment Arbor PRO Equipment 38576 127th St Aberdeen, SD 57401

SHIP TO
Arbor Pro Equipment Arbor PRO Equipment 38576 127th St Aberdeen, SD 57401

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
30330	10/06/2021	\$0.00	11/05/2021	Net 30*	

AT JGE OR OFF SITE?
 JGE

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
Customer-BG56	NEW HOLLAND LS170 SN:168787 HRS:2825 CONCERN:MACHINE WILL NOT START Trouble-shoot and found fuel line rusted and broke in tank extracted fuel line from within tank, installed new hose, elbow, fuel line and fuel filter, treated fuel, run, check over for proper starting operation.	1	420.30	420.30T
Customer-BG56	CONCERN: LIFT PEDAL INOPERATIVE. Once machine was started, found lift pedal inoperative, heated bushings, lubed and freed pedal assembly, raised seat and found lift spool stuck on main control valve, removed spool, cleaned and inspected, reinstalled spool, run, check over for proper lift operation.	1	366.97	366.97T
Customer-BG56	CONCERN: AUX FUNCTIONS INOPERATIVE Trouble-shoot and found aux spool on control valve stuck, removed aux spool, cleaned and inspected, reinstalled spool, run, check over for proper operation.	1	210.44	210.44T
SERVICE-CYLINDER REPAIR	CONCERN:RH LIFT CYLINDER LEAK **PER CYLINDER** Wash cylinder if necessary, disassemble, wash and inspect all components and hardware, hone tube if necessary, polish rod if necessary, remove and replace seal kit and any needed components, re-assemble.	1	188.20	188.20T
Customer-BG56	CONCERN: DASH INOPERATIVE Trouble-shoot electrical system and found wiring damage behind dash, removed dash, repaired damaged wiring, reinstalled dash, run, check over for proper functions.	1	241.73	241.73T
Customer-BG56	CONCERN: HYDRAULIC LEAK Trouble-shoot and found cooler hose from control valve to cooler leaking, remove and replace hydraulic hose assembly,	1	310.86	310.86T

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
	check and filled hydraulic oil, run, check over.			
P550012	In-Line Fuel Filter	1	7.98	7.98T
820250	Fitting	1	3.61	3.61T
6598908	Elbow	1	19.87	19.87T
7-08152-1	1/4" Fuel Line	1	5.78	5.78T
073024	Bushing/Fuel Tank	1	1.05	1.05T
Freight-Inbound	Inbound freight charged to customer.	1	19.13	19.13T
Seal Kit	SEAL KIT-RH LIFT CYL	1	72.16	72.16T
10G-12FJX	Hyd Hose End	1	20.16	20.16T
10G-12FJX90S	Hyd Hose End	1	31.31977	31.32T
5/8 Hydro Hose	10M3K Mega Crimp 3000 Hydraulic Hose	4	10.76	43.04T
Fluid Hydraulic	MOBIL PREMIUM DTE 10 EXCEL 46	1.50	25.55	38.33T
Service MISC-1	CONSUMABLE SUPPLIES	1	40.02	40.02T
Service MISC-2	HAZ WASTE DISPOSAL	1	20.01	20.01T
	DISCLAIMER OF WARRANTIES-Due to age and or hours this machine carries no warranty coverage for failures, the only warranties applying to this repair are those of the part(s) warranty which may or may not be offered by the manufacturer of the part(s).			

SUBTOTAL	2,060.96
TAX (0%)	0.00
TOTAL	2,060.96
PAYMENT	2,060.96
BALANCE DUE	\$0.00